Tree No.	Botanical Name	Common Name	Caliper (cm)	Condition	High Quality Tree	High Quality Tree	Comments	To Be Preserved
1	Acer platanoides	Norway Maple	30	Dead	No	No	This tree is dead, many branches have died and fallen. This tree is a hazard.	No
2	Acer platanoides	Norway Maple	32.5	Dead	No	No	This tree is dead, many branches have died and fallen. This tree is a hazard.	No
3	Acer platanoides	Norway Maple	33	Poor	No	No	Central leader of tree is dead, there is approximately 40% die back in the canopy.	No
4	Acer platanoides	Norway Maple	32	Poor	No	No	Central leader of tree is dead, there is approximately 40% die back in the canopy.	No
5	Acer platanoides	Norway Maple	31	Moderate	No	No	Tree is in moderate condition.	No
6	Acer platanoides	Norway Maple	30	Moderate	No	No	Tree is showing approximately 20% die back in the canopy.	No
7	Acer platanoides	Norway Maple	31	Moderate	No	No	Tree is showing approximately 10% die back in the canopy, and some rot appearing at branch unions.	No

TREE INVENTORY PLAN - AERIAL PHOTOGRAPHY:

## GENERAL NOTES:

- 1) THE PROPOSED LOSS OF TURF/ TREE AREA FOR THIS DEVELOPMENT WILL BE APPROXIMATELY 326 m2.
- APPROXIMATELY 326 m2 TO BE COVERED WITH NEW HARD SURFACE

THERE IS A ROW OF SEVEN TREES ALONG THE NORTHERN PROPERTY LINE THAT WILL BE REMOVED TO ACCOMODATE THE PROPOSED BUILDING. A PORTION OF THE SOFT LANDSCAPE IS REQUIRED TO BE REMOVED. THIS IS NECESSITATED BY THE NATURE AND SCALE OF THE PROPOSED USE. THIS WILL HAVE IMPACT ON THE DRAINAGE OF THE SITE, PLEASE REFER TO THE CIVIL LOT GRADING AND DRAINAGE PLAN.

REMOVAL OF SEVEN TREES APPROVED BY ADJACENT LANDOWNER LORENZO NICOLINI, NICOLINI CONSTRUCTION; AS PER EMAIL DATED JUNE 02, 2015.

2) THE DEVELOPMENT SITE IS NOT CONSIDERED OF PRIMARY OR SUPPORTING SIGNIFICANCE AS NATURAL LANDS IN THE GREENSPACE MASTER PLAN. DUE TO THE LOW ENVIRONMENTAL VALUE OF THE SITE, IT IS NOT EXPECTED THAT FURTHER DISTURBANCE WILL SIGNIFICANTLY IMPACT THE ECOLOGICAL FUNCTION OF THE SURROUNDING AREA.

## SITE DESCRIPTION:

THE SITE IS CURRENTLY SITTING VACANT. IT IS THE FORMER AND FUTURE SITE FOR AN AUTO COLLISION CENTER, AND TIRE RETAILER. THE SITE IS RELATIVELY LEVEL WITH NO MAJOR GRADE CHANGES. ANTICIPATED ACTIVITIES ON SITE ARE THE STORAGE OF TIRES, AND EQUIPMENT ASSOCIATED WITH THE TIRE RETAILER. A MAJOR PORTION OF THE SITE IS ALSO USED FOR PARKING. THERE IS ONE (1) GROUPING OF SEVEN (7) TREES ALONG THE NORTHERN PROPERTY LINE. THE AREA SURROUNDING THIS SITE IS COMMERCIAL\LIGHT INDUSTRIAL.

## ADDITIONAL INFORMATION:

<u>OWNER:</u> <u>APPLICANT:</u>

GERRY BENSON 700 EDUCATION ROAD CORNWALL, ONTARIO K6H 6B8

OTTAWA, ONTARIO

K2G 1E3

1076 CASTLE HILL CRES. OTTAWA, ONTARIO K2C 2A8

CURRENT OFFICIAL PLAN MUNICIPAL ADDRESS: AND ZONING DESIGNATION: 1871 MERIVALE ROAD

AM10

<u>AUTHOR:</u>

K1Z 8L8

HOLZMAN CONSULTANTS INC. SHANNON HARBERS, OALA CSLA

> CSW LANDSCAPE ARCHITECTS LTD. 1960 SCOTT STREET, SUITE 200 OTTAWA, ONTARIO

--- PROPERTY LINE

PROPOSED TREES

JAMIE AVE


PROPOSED BUILDING

EXISTING TREES TO BE REMOVED

WEST HUNT CLUB RD.

LEGEND:

PROPOSED HARD SURFACES





Landscape Architecture Urban Design Site Planning Recreation and Park Planning

1960 Scott Street, Suite 200, Ottawa, Ontario K1Z 8L8 Tel: (613) 729-4536 Fax: (613) 729-3018 All measurements in millimeters unless specified otherwise.

Do not scale drawing. All drawings to be read in conjunction with written specifications. Copyright reserved. This drawing is the exclusive property of

CSW Landscape Architects Ltd. and shall not be used without the consent thereof.

This Drawing may not be used for construction until signed by the landscape architect. It is the responsibility of the contractor • check and verify all dimensions on site;

• report all errors and/or omissions to the landscape archite • comply with all pertinent codes and by-laws; • check and verify locations of all underground services with all local utilities prior to any digging.

MERIVALE AND JAMIE **AUTO GARAGE** 

1871 MERIVALE ROAD OTTAWA, ONTARIO

TREE CONSERVATION REPORT

09 SEP, 2014 TCR 01