

P.O. Box 13593, Ottawa, ON K2K 1X6 Telephone: (613) 838-5717 Website: www.ifsassociates.ca Urban Forestry & Forest Management Consulting

June 28, 2019

JB Holdings Inc. 107 Pretoria Avenue Ottawa, ON K1S 1W8 <u>Attn</u>. John Bassi – President

RE: TREE CONSERVATION REPORT FOR 24-30 PRETORIA AVENUE, OTTAWA

This report details a pre-construction Tree Conservation Report (TCR) for the above-noted property in Ottawa. The need for this TCR is related to the proposed development of the subject property. Such reports are required for all Plans of Subdivision and Site Plan Control Applications where a tree of 10 centimetres in diameter or greater is present on the property. The approval of this TCR by the City of Ottawa and the issuing of a permit by them authorize the removal of approved trees. Importantly, although this report may be used to support the application for a City tree removal permit, it does not by itself constitute permission to remove trees or begin site clearing activities. No such work should occur before a tree removal permit is issued by the City of Ottawa. In particular, permission to remove private or city owned trees adjacent to the subject properties will be required before a tree removal permit is issued.

The inventory in this report details the assessment of all individual trees on the subject, neighbouring private and adjacent City of Ottawa property. Field work for this report was completed on March 25 and June 22, 2019.

The construction proposed for the site includes a six-storey apartment building with underground parking. The foot print of building in addition to the excavation necessary for the underground parking will result in the removal of all trees currently on the subject property. All adjacent private and city owned trees will be retained. The tree preservation and protection measures cited in this report will be followed to ensure the survival of trees proposed for retention.

TREE SPECIES, CONDITION, SIZE AND STATUS

Table 1 on page 2 details the species, condition, size (diameter) and status of the individual trees on the subject, nearby private and city-owned property. Each of these trees is referenced by the numbers plotted on the accompanying tree conservation plans.



. species, conditio	m, utameter,	ownersn	ip and sta	lus of fields at 24-30 Fieldfia Avenue.
Tree Species	Condition	DBH^1	Owner	Tree Condition Notes &
	$(VP \rightarrow E)$	(cm)	-ship	Preservation Status (to be removed
				or preserved and protected)
Silver maple	Fair	110	City	Very mature; five co-dominant
(Acer				stems at 4m from grade; broad
saccharinum)				crown – slightly asymmetrical due
				to clearance pruning from house;
				good flower bud set for 2019; within
				very restricted rooting area; native
				species; to be preserved and
				protected
White spruce	Fair	16	Private	Maturing; vine growth into lower
(Picea glauca)				and mid-crown; heavy cone crop in
				2019; to be removed
Manitoba maple	Good	27	Neigh-	Mature; upright growth form;
(Acer negundo)			bour	naturalized species; to be preserved
				and protected
White elm	Fair	20	Private	Mature; divergent form towards
(Ulmus				southwest due to competition with
americana)				tree #3; native species to be
				removed
White elm	Fair	19	Private	Maturing; divergent form due to
				competition with adjacent trees; to
				be removed
White elm	Fair	17	Private	Maturing; mildly divergent form due
				to competition with adjacent trees to
				be removed
Manitoba maple	Fair	<10	Private	Immature; likely originated from
& cherry				seed (cherry likely a cultivar); to be
(Prunus spp.)				removed
Manitoba maple	Fair	21	Private	Mature; secondary stem on
				neighbouring property removed;
				embedded wire fence at base; to be
				removed
Cherry	Fair	<10	Private	Immature; to be removed
Manitoba maple	Poor	36	Private	Mature; topped at 6m; to be
				removed
Manitoba maple	Fair	98	Private	Very mature; co-dominant stems at
				2.5m; very broad crown; secondary
				lateral stem very divergent towards
				northwest; to be removed
	Tree Species Silver maple (Acer saccharinum) White spruce (Picea glauca) Manitoba maple (Acer negundo) White elm (Ulmus americana) White elm White elm White elm Manitoba maple & cherry (Prunus spp.) Manitoba maple	Tree SpeciesCondition (VP \rightarrow E)Silver maple (Acer saccharinum)FairWhite spruce (Picea glauca)FairManitoba maple (Acer negundo)GoodWhite elm (Ulmus americana)FairWhite elm (Ulmus americana)FairWhite elm (Ulmus americana)FairManitoba maple (Cherry (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (Prunus spp.)FairCherry (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (Prunus spp.)FairManitoba maple (PoorFair	Tree SpeciesCondition (VP \rightarrow E)DBH1 (cm)Silver maple (Acer saccharinum)Fair110White spruce (Picea glauca)Fair16Manitoba maple (Acer negundo)Good27White elm (Ulmus americana)Fair20White elm (Ulmus americana)Fair19White elm (Ulmus americana)Fair110Manitoba maple (Ulmus americana)Fair20White elm (Ulmus americana)Fair21Manitoba maple & Cherry (Prunus spp.)Fair21Manitoba maple & CherryFair21Cherry Manitoba maple & CherryFair<10	Tree SpeciesCondition (VP \rightarrow E)DBH1 (cm)Owner -shipSilver maple (Acer saccharinum)Fair110CityWhite spruce (Picea glauca)Fair16PrivateManitoba maple (Acer negundo)Good27Neigh- bourWhite elm (Ulmus americana)Fair20PrivateWhite elm (Ulmus americana)Fair19PrivateManitoba maple (Ulmus americana)Fair17PrivateManitoba maple (Ulmus americana)Fair21PrivateManitoba maple & cherry (Prunus spp.)Fair21PrivateManitoba maple & cherry (Prunus spp.)Fair21PrivateCherry Manitoba maple & cherryFair21PrivateCherry Manitoba maple & cherryFair<10

Table 1. Species, condition, diameter, ownership and status of trees at 24-30 Pretoria Avenue.



Table 1. Con't

12	Manitoba maple	Good	32	Private	Mature; upright growth form; to be
					removed
13	White cedar	Poor	5 avg.	Private	Immature; likely planted as a hedge;
	(Thuja				native species; to be removed
	occidentalis)				
14	Manitoba maple	Fair	64	Private	Very mature; tri-stemmed at 1m
					from grade – broad crown; to be
					removed
15	Manitoba maple	Fair	12	Neigh-	Maturing; likely originated from
			avg.	bour	seed; some stems overhanging
					property line – will have to be cut
					back; to be preserved and
					protected

¹Diameter at breast height, or 1.4m from grade.

Pictures 1 through 4 on pages 4, 5, 6 and 7 show selected trees on and adjacent to the subject property.

TREE PRESERVATION AND PROTECTION MEASURES

Preservation and protection measures intended to mitigate damage during construction will be applied for the trees to be retained adjacent to the subject property. The following measures are the minimum required by the City of Ottawa to ensure tree survival during and following construction:

- 1. Erect a fence at the critical root zone (CRZ¹) of trees;
- 2. Do not place any material or equipment within the CRZ of the tree;
- 3. Do not attach any signs, notices or posters to any tree;
- 4. Do not raise or lower the existing grade within the CRZ without approval;
- 5. Tunnel or bore when digging within the CRZ of a tree;
- 6. Do not damage the root system, trunk or branches of any tree;
- 7. Ensure that exhaust fumes from all equipment are NOT directed towards any tree's canopy.

¹ The critical root zone (CRZ) is established as being 10 centimetres from the trunk of a tree for every centimetre of trunk Diameter at breast height (DBH). The CRZ is calculated as DBH x 10 cm.

This report is subject to the attached Limitations of Tree Assessments to which the reader's attention is directed. Please do not hesitate to contact me if you have questions regarding this report.

Yours,

<u>Andrew Boyd</u>


Andrew K. Boyd, B.Sc.F, R.P.F. (#1828) Certified Arborist #ON-0496A and TRAQualified






Picture 1. Red maple (tree #1) to be preserved and protected adjacent to 24-30 Pretoria Avenue.






Picture 2. Manitoba maple (tree #11) to be removed from 24-30 Pretoria Avenue.





Picture 3. Manitoba maple (tree #14) to be removed from 24-30 Pretoria Avenue.





Picture 4. Manitoba maple grouping (#15) to be preserved and protected adjacent to 24-30 Pretoria Avenue.



LIMITATIONS OF TREE ASSESSMENTS

It is the policy of *IFS Associates Inc.* to attach the following clause regarding limitations. We do this to ensure that our clients are clearly aware of what is technically and professionally realistic in assessing trees for retention.

The information contained in this report covers only the tree(s) in question and no others. It reflects the condition of the assessed tree(s) at the time of inspection and was limited to a visual examination of the accessible portions only. *IFS Associates Inc.* has prepared this report in a manner consistent with that level of care and skill ordinarily exercised by members of the forestry and arboricultural professions, subject to the time limits and physical constraints applicable to this report. The assessment of the tree(s) presented in this report has been made using accepted arboricultural techniques. These include a visual examination of the aboveground portions of each tree for structural defects, scars, cracks, cavities, external indications of decay such as fungal fruiting bodies, evidence of insect infestations, discoloured foliage, the condition of the tree(s) and the surrounding site, and the proximity of property and people. Except where specifically noted in the report, the tree(s) examined were not dissected, cored, probed or climbed to gain further evidence of their structural condition. Also, unless otherwise noted, no detailed root collar examinations involving excavation were undertaken.

While reasonable efforts have been made to ensure that the tree(s) recommended for retention are healthy, no warranty or guarantee, expressed or implied, are offered that these trees, or any parts of them, will remain standing. This includes other trees on the property not examined as part of this assignment. It is both professionally and practically impossible to predict with absolute certainty the behaviour of any single tree or groups of trees or their component parts in all circumstances. Inevitably, a standing tree will always pose some risk. Most trees have the potential for failure in the event of adverse weather conditions, and this risk can only be eliminated through tree removal.

Notwithstanding the recommendations and conclusions made in this report, it must be realized that trees are living organisms, and their health and vigour constantly change over time. They are not immune to changes in site conditions, or seasonal variations in the weather. It is a condition of this report that *IFS Associates Inc*. be notified of any changes in tree condition and be provided an opportunity to review or revise the recommendations within this report. Recognition of changes to a tree's condition requires experience and so it is recommended that *IFS Associates Inc*. be employed to re-inspect the tree(s) with sufficient frequency to detect if conditions have changed significantly.

No responsibility is assumed for matters legal in character. Statements made to *IFS Associates Inc.* in regards to the condition or history of the tree(s) are assumed to be correct. Any and all property is assessed or evaluated as though free and clear, under responsible ownership and competent management. It is assumed that any property is not in violation of any applicable codes, ordinances, statues or other government regulations.



Neither the author of this report nor anyone else in association with *IFS Associates Inc.* shall be required to give testimony or attend court by reason of this report unless contractual arrangements are made, including payment of an additional fee for such services as described in the fee schedule and contact of engagement, or as previously accepted.

The information, recommendations and opinions expressed in this report are for the sole benefit of the client(s) named above. Possession of this report or a copy thereof does not imply right of publication or use for any purpose by any other than the person to whom it is addressed, without the prior expressly written consent of the author. Unless otherwise required by law, neither all or any part of the contents of this report, nor copy thereof, shall be conveyed by anyone, including the client, to the public through advertising, public relations, news, sales or other media, without the prior expressly written consent of the author, and especially as to value conclusions, identity of the author, or any reference to any professional society or institute or to any initialed designation conferred upon the author as stated in his qualifications.

This report and any values expressed herein represent the opinion of the author; His fee is in no way contingent upon the reporting of a specified value, a stipulated result, the occurrence of a subsequent event, nor upon any finding to be reported.

Details obtained from photographs, sketches, etc., are intended as visual aids and are not to scale. They should not be construed as engineering reports or surveys.

Although every effort has been made to ensure that this assessment is reasonably accurate, the tree(s) should be reassessed at least annually. The assessment presented in this report is valid at the time of the inspection only.

Lastly, loss or alteration of any part of this report invalidates the entire report.

