TREE CONSERVATION REPORT

APARTMENT BUILDING DEVELOPMENT

DUNBAR COURT

CITY OF OTTAWA

Prepared for:

Jane Thompson Architect Ottawa, Ontario

Prepared by:

Ruhland & Associates Limited 1750 Courtwood Crescent, Suite 200 Ottawa, ON K2C 2B5 (613) 224-4744

October 21, 2020

PROJECT INFORMATION

Project Name:	Dunbar Court				
Owner:	Nepean Housing Corporation				
Applicant:	Jane Thompson Architect Attn: Jane Thompson				
Prepared By:	Ruhland & Associates Limited, 1750 Courtwood Crescent, Suite 200, Ottawa, ON K2C 2B5 613-224-4744 Att: Marietta Ruhland				
Contractor:	Unknown at this time.				
Municipal Address:	Dunbar Court, Part 2 Plan of Lot 31, Concession 2, Geographic Township of Nepean, City of Ottawa				
Official Plan & Zoning Designations: Site Zoning as per Ottawa Zoning By-law 2008-250 Site Designation R32(708)					
Purpose for Report:	In support for an application for site plan control				
Schedule of Proposed Works: 2021-2022.					

Other Applications Affecting Subject Lands: Application for Zoning Amendment

TREE CONSERVATION REPORT

The subject site is located at 1 Dunbar Court in Ottawa, ON.

The subject lands are approximately 2 300m² 0.23 hectares (0.57 acres) in size. See Map 01 and 02 for site boundaries. It is bounded on all sides by existing residential developments. Approximately 95% of the site is affected.

The subject lands were visited by Ruhland & Associates Ltd. on November 27, 2019 and October 01, 2020.

Included in this report: 2019 aerial, 2017 City of Ottawa aerial, Map #1 – Current Vegetation, MAP #1A – Existing Vegetation Chart and City Detail for Tree Protection Notes and Details, Map #2 – Proposed Development and Conserved Vegetation Plan.

Note: locations of trees are from survey information and from field observations and aerial photographs. Status of existing vegetation was taken from field observations.

GENERAL

The subject land consists of existing townhouse residential housing, part of a larger property bounded on the north by a police station, west by retail property, south by Gibbard Ave and Ben Franklin Park West, and on the west by the Sephardi Association residential complex.

SURFACE WATER FEATURES

No water features.

STEEP SLOPES

The site has some sloping. Area outside unit 71 has a drop-off into main area of ± 1 m, slope of about 1:4.5. This slope continues round to outside unit 20. Trees 9-14 are on a minor berm outside units 2, 4, 6 & 8, ± 0.5 m height, slopes $\pm 1:8$.

WILDLIFE

No evidence of larger mammals was found on the site during any site reviews. It is expected that the normal urban wildlife is present.

SIGNIFICANT VEGETATION / SPECIES

No significant species or species at risk have been found on site during site visits.

DISTINCTIVE TREES

No distinctive trees were found on site.

VEGETATION INVENTORY

EXISTING VEGETATION

The lands consist mainly of residential yards, residential housing and lanes. Majority of lot is grassed, with planted trees, planted shrubs, and volunteer saplings and shrubs, in various conditions.

Refer to MAP #1A – Existing Vegetation Chart and Map #2 – Proposed Development and Conserved Vegetation for species, size condition and action.

AREA 1: 5 PROPOSED NEW PARKING SPACES

No trees are located within the city road allowance.

Tree 1: Norway maple (Acer platanoides),

located in the common area next to the parking across from Unit No.57.

Age: Young

Size: 25cm DBH maple

Condition: poor, crown thinning, and has a large scar from a lost branch with possible decay.

Tree 2: Blue spruce (Picea pungens) located next to Unit No.55.

Age: Young

Size: Main trunk about 16cmØ below a split about 0.5m from the ground. This appears to be a truncated leader, now grown into 2 co-dominant trunks, 13cm and 11cm DBH respectively.

Condition: good condition, needs pruning of lower branches.

AREA 2: PROPOSED NEW BUILDING, PARKING AND RECREATION SPACE:

Consists of a large grassed area, semi mature to mature trees, overgrown hedges, a several volunteer saplings, some possibly volunteer shrubs. This area also includes some shrubs and volunteer saplings within the property boundary, but on the far side of the fence between 1 Dunbar Court and 57 Bateman Drive. It is proposed that this strip of property be reclaimed by moving the fence to the property line, and that it be replanted, with due care for good trees on neighbouring 57 Bateman Drive property.

Refer to chart and MAP-01.

Tree 3: Norway maple (Acer platanoides),

Located in front of Unit 16. This appears to be a volunteer.

Age: Young Size: 13cm DBH Condition: Fair but completely unpruned, showing suckers at base

Trees 4-7: behind Units 14, 16, 18 & 20

Tree 4: <u>Scots Pine (*Pinus sylvestris*)</u> Age: Semi-mature

Size: 30cm DBH Condition: Poor. Crown very sparse, needles browning. Trees 5&6: Blue spruce (*Picea pungens*) Age: Mature Size: 25cm and 22cm DBH Condition: Good Tree 7: Norway maple (Acer platanoides) Age: Semi-mature Size: 32cm DBH Condition: Fair. Grown thinning at centre, one major branch has old tourniquet constricting it. Tree 8: Norway maple (*Acer platanoides*) Age: Semi-mature Size: 40cm DBH Condition: Excellent Trees 9 – 14: Blue spruce (Picea pungens) Age: Mature Size: 30cm, 22cm, 24cm, 23cm, 20cm, 30cm DBH Condition: Trees 9, 10, 12, 14 – Good Tree 11: Poor, very sparse, pale needles Tree 13 Poor, stunted, sparse branches Trees 15 – 17: Blue spruce (*Picea pungens*) – growing on slope Age: Mature, semi-mature Size: 30cm, 20cm and 18cm DBH Condition: Fair, slightly sparse Tree 18: Scots Pine (*Pinus sylvestris*) Age: Mature Size: 30cm DBH Condition: Poor. Sparse, browning needles Vegetation around units 14 - 20. There are some saplings in the rear yards of these units, plus a few deciduous shrubs. AREA 3: ON FENCE AND ON FAR SIDE OF FENCE BETWEEN 1 DUNBAR AND 57 BATEMAN

Trees 19, 20: <u>Blue spruce (*Picea pungens*)</u> on neighbouring property close to property line. Might interfere with new fence placement. Tree 19 ± 0.7 m from property line, tree 20 ± 1.3 m from property line

Age: Mature Size: 30cm, 25cm DBH Condition: Fair Tree 21: <u>Maidenhair tree (*Ginkgo biloba*)</u> ±2m on far side of property line. Worth realigning fence to allow to be kept.

Age: Young Size: 18cm DBH Condition: Good - weak leader

Tree 22: Red Maple (Acer rubrum) right on fenceline. Apparently volunteer,

multistem, unpruned

Age: Very young Size: Main stems: 12cm, 6cm DBH Condition: Fair, very poor form

Shrubs and saplings along fence:

6 x Sand cherry (Prunus cistena) shrubs

3 x Red Maple (Acer rubrum) sapling

1 x Norway maple (Acer platanoides)

1 x Ash (American or European) (Fraxinus) sapling

Tree 23, 24 <u>Austrian Pine (*Pinus nigra*)</u> Age: Semi-mature to mature Size: 40cm & 35cm respectively Condition: Fair to poor, crowns fairly sparse, some leaf browning.

DISTINCTIVE TREES

Distinctive trees (as described in the City of Ottawa tree bylaw 2009-200: 'means any tree with a DBH of 50 centimetres or greater').

No distinctive trees were found on site.

VEGETATION CONSERVATION

VEGETATION TO BE RETAINED

Recommended for retention are:

Area 1:

TREE 2, as this is outside the proposed new parking.

Area 2:

TREE 15 to be preserved, if feasible – to be reviewed at time of construction in regards to excavation limits or required grade changes.

AREA 3:

Trees 19, 20, and 21 are on the neighbouring property near the property line where the fence will be being relocated. It is considered worth aligning the new fence away from the property line in order to preserve these trees.

Trees 23 and 24 are on the site property. It is considered worth leaving the fence intact next to these trees in order not to disturb them.

VEGETATED AREAS TO BE REMOVED

Due to the extents of the proposed development, grade changes, retaining walls and servicing requirements, the remainder of the existing trees within the property will be removed.

Refer to 2019 aerial, 2017 City of Ottawa aerial, Map #1 – Existing Vegetation, MAP #1A – Existing Vegetation Chart & Tree Protection Detail, Map #2 – Proposed Development and Conserved Vegetation Plan

All removals to be done in accordance with the City of Ottawa tree bylaw 2009-200 and this Tree Conservation Report.

POTENTIAL IMPACTS AND MITIGATION MEASURES

POTENTIAL IMPACTS

It is noted that excavation for the development of the building, parking lot, roadways and/or sidewalks, retaining walls, new recreation areas, and servicing, does not allow for retention of trees and mitigation measures, with the exclusion of those mentioned above.

PROTECTION MEASURES

In accordance with the Municipal Trees and Natural Areas Protection By-law No. 2006 – 279, a protection fence is to be erected at vegetation that is to be preserved. Existing fencing will serve as protection fencing for vegetation on adjacent south and west properties lines. If the existing fence is to be dismantled during construction, a tree preservation fence or project hoarding is to be erected in it stead. The protection fence shall be erected as per D-01 - Tree Preservation Notes and Details. The protection fence shall be maintained throughout all phases of the development. No work is to be done within the tree protection fence.

No storage, vehicular traffic or other construction activities to take place within the treed areas.

SPECIFIC PROTECTION MEASURES

All protection measures shall follow Municipal Trees and Natural Areas Protection By-law No. 2006 – 279.

PLANTING RECOMMENDATIONS

Planting deciduous shade trees and shrubs next to the new recreation areas, and mix of deciduous and coniferous trees for screening along the replaced fence is recommended. Non-invasive, non-indigenous species will be selected where conditions are not amenable to indigenous trees.

Plantings of new deciduous and coniferous trees and shrubs will consists of indigenous (or cultivars thereof) species, suitable to the proposed site conditions.

Prepared by


Marietta Ruhland, OALA, Senior Landscape Architect Ruhland & Associates Limited October 21, 2020

2019 AERIAL



2017 City Aerial





EE	CONSERVATION REPORT
(IS	TING VEGETATION

OBER 2020	drawn by TF	project no. 19-1605	dwg. no.
10 m	checked by MR	revision no.	

PLANT ID #	SIZE DBH* / ht. (cm)	COMMON NAME	BOTANICAL NAME	DISTINCTIVE	CONDITION	COMMENTS	ACTION	RATIONALE
AREA 1								
1	25	Norway Maple	Acer plantanoides		Р	Poor, thinning, large scar @±2m - diseased?	Remove	In middle of new parking
2	13,11	Blue/Colorado Spruce	Picea pungens		G	Unpruned, split @±0.5m, leader cut?	Preserve if feasible	Review excavation limits / grade changes at time of construction
AREA 2								
3	13	Norway Maple	Acer plantanoides		F	Unpruned volunteer	Remove	In hardscape footprint
4	25	Scots Pine	Pinus sylvestris		Р	Split @±2m, very sparse	Remove	In hardscape footprint, poor condition
5	25	Blue/Colorado Spruce	Picea pungens		G		Remove	In hardscape footprint
6	22	Blue/Colorado Spruce	Picea pungens		G		Remove	In building footprint
7	32	Norway Maple	Acer plantanoides		F	Thinning centre of crown, tourniquet on major branch	Remove	In building footprint
8	40	Norway Maple	Acer plantanoides		E	-	Remove	In hardscape footprint
9	30	Blue/Colorado Spruce	Picea pungens		G		Remove	In building footprint
10	22	Blue/Colorado Spruce	Picea pungens		G		Remove	In building footprint
11	24	Blue/Colorado Spruce	Picea pungens		Р	Very sparse pale needles	Remove	In building footprint
12	23	Blue/Colorado Spruce	Picea pungens		G		Remove	In building footprint
13	20	Blue/Colorado Spruce	Picea pungens		Р	Stunted, sparse branches	Remove	In building footprint, poor condition,
14	30	Blue/Colorado Spruce	Picea pungens		G	15º slant at base	Remove	In building footprint
15	30	Blue/Colorado Spruce	Picea pungens		F	On slope	Preserve if feasible	Review excavation limits / grade changes at time of construction
16	20	Blue/Colorado Spruce	Picea pungens		F	On slope	Remove	In building footprint
17	18	Blue/Colorado Spruce	Picea pungens		F	On slope	Remove	In building footprint
18	30	Scots Pine	Pinus sylvestris		F	Sparse, browning needles, 10° slant at base	Remove	In building footprint
AREA 3								
19	30	Blue/Colorado Spruce	Picea pungens		Р	Some needle browning	Preserve	Next property, good size
20	25	Blue/Colorado Spruce	Picea pungens		G	Heavy pruning north side, some browning	Preserve	Next property, good tree
21	18,13,9	Maidenhair tree	Ginkgo biloba		G	Spindly leader, just other side of property line	Preserve	Next property, good tree
22	12,6	Red Maple	Acer rubrum		F	Volunteer, unpruned, multistem	Remove	Volunteer, poor habit, on old fence to be removed.
23	40	Austrian Pine	Pinus nigra		F	Split trunk about 2/3 up. Slight needle browning	Preserve	Fair condition, good size
24	35	Austrian Pine	Pinus nigra			Slight needle browning	Preserve	Fair condition, good size
					CONDITION			
* Diamete	er at Breast ⊦	leight			E	Tree in excellent conditon and I	nabit.	
		-			G	Tree in good condition with fair	to good habit.	
					F Tree in fair conditon showing damage or stress.			
						Tree in poor conditon with dam		

EMENTS: INTY WITHIN THE CRITICAL ROOT ZONE (CR2 = 10 TIVITY WITHIN THE CRITICAL ROOT ZONE (CR2 = 10 CRE ROOT ZONE, AND REMAIN IN PLACE UNTILE /ED BY CITY FORESTRY STAFF, FOF AL OR EQU FUMES FUMES ANY MATER TREE PROT 1. PRIOR X DIAN SURRO O O D O N N pm TREE PROTECTION FENCING -Uly TRUNK CBZ PLAN TITLE: ttawa



stamp

 TREE PROTECTION FRAMED MATERIALS (E.G. MODULOC - STEEL, PLYWOOD HOARDING, OR SNOW FENCE ON A. 2"A" WOOD FRAME) WITH DOSTS 2.4M APART, JOUCH THAT THE FENCE LOCATION CANDENG. AND LALTERED ALL SUPPORTS AND BRACING MUST BE PLACED OUTSIDE OF THE ALTERED ALL SUPPORTS AND BRACING MUST BE PLACED OUTSIDE OF THE CRZ, AND INSTALLATION MUST MINIMISE DAMAGE TO EXISTING ROOTS. (SEE DETAIL) A. THE LOCATION CANTON REDRAT AND SETALING MUST BE PLACED OUTSIDE OF THE CRZ, AND RECAUNON OF THE TREE PROTECTION FENCING MUST BE PLACED ANA ARBORIST AND DETAILED ON ANY ASSOCIATED PLANS FOR THE SITE (E.G. TREE CONSERVATION REDRAT, TREE DISCUSUE REPORT, ETC), THE PLAN AND REDRAT AND DETAILED ON ANY ASSOCIATED PLANS FOR THE SITE (E.G. TREE CONSERVATION REDRAT, TREE DISCUSUE REPORT, ETC), THE PLAN AND REDRAT AND DETAILED ON ANY ASSOCIATED PLANS FOR THE SITE (E.G. TREE CONSERVATION REDRAT, TREE DISCUSUE REPORT, ETC), THE PLAN AND REDRATING THE COMMENCEMENT OF WORK. F. THE FENCED THE PROTECTION AREA MUST BE REDUCED TO FACILITATE CONSTRUCTION, MITIGATION MASJUES MUST BE REQUCED TO FACILITATE REDRATING AND APPROVED BY CITY FORESTRY STAFF. THESE MAY INCLUDE THE PLACENTION, THE PROVED BY CITY FORESTRY STAFF. THESE MAY INCLUDE THE PLACENTION OF THE PRODECHING ON THE REQUCED TO FACILITATE REDRATING AND APPROVED BY CITY FORESTRY STAFF. THESE MAY INCLUDE THE PLACENTION, MITIGATION MASJUES MUST BE REDUCED TO FACILITATE REDRATING AND APPROVED BY CITY FORESTRY STAFF. THESE MAY INCLUDE THE PLACENTING FOR THE PROPERTRY STAFF. THESE MAY INCLUDE THE RACENTING FOR THE PRODECHING ON THE REDUCED TO FACILITATE REDRATING AND FOR AND FOR STAFF. THESE MAY INCLUDE THE RACENTING FOR THE PROPERTRY STAFF. THESE MAY INCLUDE THE RACENTING FOR THE PROPERTRY STAFF. THESE MAY INCLUDE THE RACENTING FOR THE REPRODECHING ON THE REPROVED FOR THE PLATING OVER THE RACENTING FOR THE REPROVED. WOOD CHIPS, OR STEEL PLATING OVER THE RACENTING FOR THE REPROVED FOR THE PLATING OVER THE RACENTING FOR THE PLATING FOR THE PLATING OVER THE RACENTING F	BY-LAWS ALL CITY-OWNED TREES ARE PROTECTED UNDER THE MUNICIPAL TREES AND ALL CITY-OWNED TREES ARE PROTECTION BY-LAW (2006-279). WITHIN THE URBAN AREA, NATURAL AREAS PROTECTION BY-LAW (2006-279). WITHIN THE URBAN AREA PRIVATEL-YOWNED TREES GREATER THAN 20CM DIAMETER ON LOTS 31HA, SIZE OR LESS, AND TREES GREATER THAN 10CM DIAMETER ON LOTS 31HA, ARE PROTECTED UNDER THE URBAN TREE CONSERVATION BY-LAW (2009-200).		
CRZ = DBH X IOCH MEALING CAZESTOBE MEALING CAZESTOBE CAZESTOBE MEALING CAZESTOBE MEALING CAZESTOBE MEA		Soll AND ROOT DISTURBANCE NOT PERMITTED	ACCESSIBLE FORMATS AND COMMUNICATION SUPPORTS ARE AVAILABLE, UPON REQUEST
TREE PRESERVAT PROTECTION FEN		-	DATE: FEB 2013 REV: JAN 2020 DWG No: F7
REE CONSERVATION REPO XISTING VEGETATION TREE PROTECTION D	CHART DETAIL		
	/ Inrojaat n	<u>`</u>	dwa no
OBER 2020 TF		¹⁶⁰⁵	dwg. no.

