

# **Kanata West Development Area Meander Belt Width Assessment and Erosion Analysis**


## **Feedmill Creek**

### **Draft Report**



Prepared for:  
David Schaeffer Engineering Limited  
120 Iber Road, Unit 103  
Stittsville, ON K2S 1E5

July 20, 2016  
PN16059



Report Prepared by: GEO Morphix Ltd.  
2800 High Point Drive  
Suite 100A  
Milton, ON L9T 6P4

Report Title: Kanata West Development Area Meander Belt  
Assessment and Erosion Analysis, Feedmill Creek

Project Number: PN16059

Status: Draft

Version: 1.0

First Submission Date: July 20, 2016

Prepared by: Allison Day, Jason Krompart, Emily Rick

Approved by: Paul Villard, Ph.D., P.Geo.

DRAFT



## Table of Contents

1	Introduction.....	1
2	Background Review .....	1
	2.1 Watershed Characteristics .....	1
	2.2 Reach Delineation.....	2
	2.3 Historical Assessment .....	3
3	Field Observations.....	3
	3.1 Rapid Geomorphological Assessments .....	3
	3.2 Detailed Geomorphological Assessments .....	7
4	Meander Belt Width Assessment.....	8
	4.1 Methodology .....	8
	4.2 Results and Discussion .....	9
5	Erosion Analysis.....	10
	5.1 Erosion Threshold Analysis.....	10
6	Summary and Recommendations .....	12
7	References .....	13

## List of Tables

Table 3.1. Rapid Assessment results by reach.....	4
Table 3.2. General channel characteristics by reach.....	7
Table 3.3. Bankfull parameters of the sensitive reach .....	8
Table 4.1. Meander belt width estimates for subject and reference reaches. ....	9
Table 5.1. Erosion thresholds of bed and bank materials .....	11

## Appendices

Appendix A Reach Map .....	A
Appendix B Photographic Record.....	B
Appendix C Field Observations.....	C
Appendix D Detailed Assessment Summary .....	D



## 1 Introduction

GEO Morphix Ltd. was retained by 2325483 Ontario Inc. to delineate the meander belt width and to assess and mitigate erosion potential within Feedmill Creek in the Kanata West Development Area. We understand that the valley corridor along the western boundary of the property may eventually be realigned to accommodate development activities. As such, the findings of this assessment will also inform the corridor design requirements in the case where natural corridor design is required.

The primary goal of this assessment was to determine meander belt, which may be used as the limit of development.

This assessment included the following components:

- Review available background reports and mapping (geology, topography, etc.);
- Desktop reach delineation;
- Completion of a rapid geomorphological field assessment to document channel conditions and verify the desktop assessment; and
- Review historical and recent aerial photographs to determine the limits of the meander belt width and to calculate channel migration rates, or estimate the meander belt width using models if the channel is not visible in the aerial imagery or is to be realigned.

With regards to future erosion potential, an assessment of channel sensitivity along with determination of an erosion threshold for the receiving watercourse. The goal of this component of the assessment was to characterize erosion potential in Feedmill Creek in order to help mitigate future impacts and support development of a suitable SWM plan as part of the mitigation strategy.

This component of the assessment included the following tasks:

- A desktop analysis for determining the potential zone of impact;
- Apply rapid geomorphic assessments to determine the overall stability of the receiving watercourse and to identify areas of erosion concern or at risk drainage feature based on field observations;
- A detailed geomorphic assessment of a sensitive reach, the primary objective of which is to determine the critical flow or erosion threshold; and
- Support appropriate strategies to address erosion concerns.


## 2 Background Review

### 2.1 Watershed Characteristics

Feedmill Creek originates southwest of the study area, within the Carp Valley. The creek generally flows northeast through agricultural fields, bending to the northwest and flowing along the western boundary of the subject property. It continues across Highway 417 and then flows northeast through a mix of industrial, forested and agricultural areas to its outlet at Carp River in Kanata. The study area contains a mix of the aforementioned land use types. Portions of the channel have been historically or recently straightened and others retain more natural features. Reach delineation was refined through field observation.

Channel morphology and planform are largely governed by the flow regime and the availability and type of sediments (i.e., surficial geology) within the stream corridor. Physiography, riparian vegetation and land use also physically influence the channel. These factors are explored as they





not only offer insight into existing conditions, but also potential changes that could be expected in the future as they relate to a proposed activity.

Physiographically, the majority of Feedmill Creek within the Kanata West Development Area project site overlies fine-textured glaciomarine deposits containing silt and clay with minor sand and gravel, associated with the former marine bed of the Champlain Sea. Upstream reaches of Feedmill Creek, including the northwest reach along the subject property overlies organic deposits containing peat, muck and marl. Underlying Paleozoic bedrock is exposed in localized areas and acts as a topographic control through the area (OGS, 2010).

Monthly precipitation averages at Ottawa MacDonald-Cartier Int'l A (Climate ID 6106000) range from a low of 54.3 mm in February to a high of 92.8 mm in July. During the winter months, most of the precipitation is in the form of snow. During spring, snowmelt and rain-on-snow events likely generate long-duration high flows in watercourses, which result in the most significant flows with respect to shaping the channel. Convective storms during the summer are also likely to have a role in shaping the channel, but are less significant due to the short duration of high flows.

## 2.2 Reach Delineation

Reaches are homogeneous segments of channel used in geomorphological investigations. They are studied semi-independently as each is expected to function in a manner that is at least slightly different from adjoining reaches. This allows for a meaningful characterization of a watercourse as the aggregate of reaches, or an understanding of a particular reach, for example, as it relates to a proposed activity.

Reaches are delineated based on changes in the following:

- Channel planform;
- Channel gradient;
- Physiography;
- Land cover (land use or vegetation);
- Flow, due to tributary inputs;
- Soil type and surficial geology; and
- Certain types of channel modifications by humans.

This follows scientifically defensible methodology proposed by Montgomery and Buffington (1997), Richards et al. (1997) and the Toronto and Region Conservation Authority (2004) as well as others.

Reaches were first delineated as a desktop exercise using available data and information, such as aerial photography, topographic maps, geology information, and physiography maps. These results were then verified in the field.

Five (5) reaches were delineated for Feedmill Creek including one reach (**Reach 5**) along the boundary of the subject property. Four additional reaches were defined within the length of stream downstream that was investigated as part of the assessment. These reaches were defined based on the location of road crossings as well as changes in land use, planform and gradient. Reaches were numbered from downstream to upstream to provide a geographic context. A reach map is provided in **Appendix A**.

## 2.3 Historical Assessment

## 3 Field Observations

Reach observations and channel measurements were collected on July 5<sup>th</sup> and 6<sup>th</sup>, 2016. Photographs are provided in **Appendix B** and field observations are provided in **Appendix C** for reference. Rapid geomorphological assessments for each reach were completed on July 5<sup>th</sup>, 2016. A detailed assessment for one reach was completed on July 6<sup>th</sup>, 2016.

### 3.1 Rapid Geomorphological Assessments

The rapid geomorphological assessments included the following reach observations:

- Characterization of stream form, process, and evolution using the Rapid Geomorphological Assessment (RGA) (MOE, 2003, VANR, 2007);
- Assessment of the ecological function of the watercourse using the Rapid Stream Assessment Technique (RSAT) (Galli, 1996);
- Stream classification following a modified Downs (1995) and a modified Brierley and Fryirs (2005) River Styles Classification approach;
- Reach-scale habitat sketch maps based on Newson and Newson (2000) outlining channel substrate, flow behaviour, geomorphological units, and riparian vegetation on the day;
- Instream estimates of bankfull channel dimensions;
- Bed and bank material composition and structure; and
- Georeferenced photographs to document the location of all observed erosion and infrastructure.

Five (5) reaches were defined within the study area. **Table 3.1** and **Table 3.2**, below, outline field observations for the observed reaches.

Channel instability was objectively quantified through the application of the Ontario Ministry of the Environment's (2003) Rapid Geomorphic Assessment (RGA). Observations were quantified using an index that identifies channel sensitivity based on evidence of aggradation, degradation, channel widening, and planimetric adjustment. The index produces values that indicate whether the channel is stable/in regime (score <0.20), stressed/transitional (score 0.21-0.40) or adjusting (score >0.41).

The Rapid Stream Assessment Technique (RSAT) was also employed to provide a broader view of the system and consider the ecological functioning of the watercourse (Galli, 1996). Observations were made of channel stability, channel scouring or sediment deposition, instream and riparian habitats, and water quality. The RSAT score ranks the channel as maintaining a poor (<13), fair (13-24), good (25-34) or excellent (35-42) degree of stream health.

The tributary was classified according to a modified Downs (1995) Channel Evolution Model, which describes successional stages of a channel as a result of a perturbation, namely hydromodification. Understanding the current stage of the system is beneficial as this allows one to predict how the channel will continue to evolve, or respond to an alteration to the system.


The River Styles Framework (Brierley and Fryirs, 2005) provides a geomorphic approach to examining river character, behaviour, condition and recovery potential through the identification of the Geomorphic Process Zone. Geomorphic attributes are assessed, larger scale interactions between zones are analyzed, and historical data are studied in order to understand the historical evolution and future trajectories of those reaches. This ultimately provides a physical template

for river management. A modified classification approach was applied to the study reaches. **Table 1** below summarizes the results of the rapid geomorphological assessments.

**Table 3.1. Rapid Assessment results by reach**

Reach	RGA (MOE, 2003)			RSAT (Galli, 1996)			Downs' Channel Evolution Model (1995)	River Styles Framework (Brierley and Fryirs, 2005)
	Score	Condition	Dominant Systematic Adjustment	Score	Condition	Limiting Features		
<b>1</b>	0.25	In Transition/ Stress	Aggradation	27	Good	Riparian Habitat Conditions	d - Selective deposition resulting in reduced channel width	Meandering, relatively stable, suspended load dominated, low to moderate stream power
<b>2</b>	0.28	In Transition/ Stress	Aggradation	29	Good	Riparian Habitat Conditions	d - Selective deposition resulting in reduced channel width	Meandering, relatively stable, suspended load dominated, low to moderate stream power
<b>3</b>	0.30	In Transition/ Stress	Aggradation, Widening	34	Good	Scouring /Sediment Deposition	d - Selective deposition resulting in reduced channel width	Meandering, relatively stable, suspended load dominated, moderate stream power
<b>4</b>	0.19	In Regime	Widening	27	Good	Riparian Habitat Conditions	d - Selective deposition resulting in reduced channel width	Meandering, relatively stable, suspended load dominated, low stream power
<b>5</b>	0.19	In Regime	Aggradation	23	Good	Riparian Habitat Conditions	d - Selective deposition resulting in reduced channel width	Straight, relatively stable, suspended load dominated, low stream power

**Reach 1** was classified according to the River Styles framework as a suspended load channel with a low to moderate gradient and stream power. The creek exists as a single channel and follows a meandering pattern, partially confined by valley sides both historically occurring and associated with recent development activities. A portion of the channel, mid-reach, has been recently straightened and realigned along the south valley wall; historically the entire reach has been meandering, with some meanders contacting the valley wall. A new crossing has been established along the straightened portion of the reach. Aggradation was noted throughout a substantial portion of the reach, including large sand deposits along bars, on the bed and sand deposits on top of banks. Erosion was less prominent (approximately 5-30%) and consisted mainly of undercutting, measured up to 0.33 m. Generally, bank angles ranged 30° to 90°. Riparian vegetation consisted mainly of dense grasses with shrubs along limited sections, both providing stability to channel bank material. Bank material was composed of clay to sand. Bed material ranged from clay to cobbles in riffles and from clay to silt in pools. Riffles comprised approximately 30% and pools / run features comprised approximately 70% of the length of the reach. Average




bankfull width and depth were 3.83 m and 0.89 m, respectfully. Woody debris was present in the channel and cutbank at a moderate density. The stream was clear and odourless.

According to the Downs' Model of Channel Evolution (1995), **Reach 1** was classified as "d – depositional" due to selective deposition resulting in reduced channel width. The Rapid Geomorphic Assessment produced a score of 0.25 or, "In Transition/Stress" with the dominant process being "Evidence of Aggradation" as shown by embedded riffle materials, siltation in pools, accretion of point bars and deposition in the overbank zone. The Rapid Stream Assessment Technique produced a score of 27, or "Good" with riparian habitat conditions as the limiting factor.

**Reach 2** exists as a sinuous single channel. It follows an irregularly meandering pattern, partially confined by valley sides. The meanders are smaller and less-regular than in Reach 1. Similar to Reach 1, it was classified as a suspended load channel with low to moderate gradient and stream power. Aggradation, however notable, was somewhat less-dominant a feature in this reach. Further defining this reach was exposed till along the stream bed through a large portion at the downstream end. Bank erosion and bank conditions were similar to Reach 1 with erosion approximately 5-30%, bank angles generally ranging 60° to 90° and undercuts averaging 0.28 m. Bank composition was also similar, ranging from clay to sand. Bed material ranged from clay to cobbles in riffles and clay to silt in pools with exposed till in both types of geomorphic unit. Riffles were present through approximately 20% of the reach and pools or run features were present through approximately 80% of the reach. Average bankfull width and depth were 2.83 m and 1.05 m, respectfully. Riparian vegetation consisted of dense grasses and shrubs through a limited extent of the reach. Woody debris was less commonly present in the channel and cutbank than it was in Reach 1, as was woody vegetation. Upstream of Reach 2 lie two sections running through culverts beneath on and off-ramps of Highway 417. The stream was clear and odourless.

Rapid assessment techniques produced similar results in **Reach 2** as in **Reach 1**. According to the Downs' Model of Channel Evolution (1995), Reach 2 was classified as "d – depositional" due to selective deposition resulting in reduced channel width. The Rapid Geomorphic Assessment produced a score of 0.28 or, "In Transition/Stress" with slightly less dominance on "Evidence of Aggradation" and a greater amount of "Evidence of Degradation" than Reach 1. The Rapid Stream Assessment Technique produced a score of 29, or "Good" with riparian habitat conditions as the limiting factor.

**Reach 3** was classified according to the River Styles Framework as a suspended load channel with a moderate gradient and moderate stream power. This reach flowed as a single, well-defined, meandering channel. The valley setting and meanders were generally wider than in other reaches observed however the channel still exhibited partial confinement. The channel flowed through a dense cedar forest. As such, bank material was comprised of a greater fraction of mineral soil and was stabilized by a greater proportion of tree roots as compared to other observed reaches. Also resulting from the forested surroundings was a greater amount of woody debris in the channel and on banks. Evidence of both erosion and deposition were noted throughout the reach. Bank erosion ranged approximately 30-60% with bank angles ranging 60° to 90° and undercuts ranging 0.2 to 0.5 m. Exposed roots and leaning trees were common. Bank composition ranged from clay to sand. Sand deposits were noted on outer bends, tops of banks and in pools. Bed material ranged from gravel to cobbles in riffles and from clay to sand in pools. Geomorphic units were well-developed, with riffles present along approximately 70% of the reach and pools approximately 30% of the reach. Average bankfull width and depth were 4.40 m and 0.80 m, respectfully. A length of the downstream portion flows over exposed Paleozoic bedrock. One informal farm crossing was noted. Reach 3 was the most sensitive reach observed in the study. The stream was clear and odourless.



According to the Downs' Model of Channel Evolution (1995), **Reach 3** was classified as "d – depositional" due to selective deposition resulting in reduced channel width. The Rapid Geomorphic Assessment produced a score of 0.30 or, "In Transition/Stress" with the dominant processes being "Evidence of Aggradation" and "Evidence of Widening". The Rapid Stream Assessment Technique produced a score of 34, on the high end of ranking "Good" with channel scouring / sediment deposition as the limiting factor.

**Reach 4** was classified as a suspended load channel with a low to moderate gradient and stream power according to the River Styles Framework. The observed length of reach flows through an unconfined grassy floodplain with a history of beaver activity and localized ponding. Dead trees were noted throughout the flood plain on the bank or in the channel in several locations. This reach exists as a single, well-defined channel with moderate sinuosity and irregular meanders. Average bankfull width and depth were 2.23 m and 0.88 m, respectfully. Bed and bank material ranged from clay to sand with notable sand deposits in pools. Geomorphic units were less-well developed than in downstream reaches with riffles comprising just 10% of the stream length and pools/run features the remaining 90%. Deposition in pools was noted but generally less dominant than in downstream reaches. Bank erosion was similar in extent to reaches 1 and 2, at approximately 5-30%, with bank angles ranging 60° to 90° and undercuts up to 0.33 m. The stream was clear and odourless.

According to the Downs' Model of Channel Evolution (1995), **Reach 4** was classified as "d – depositional" due to selective deposition resulting in reduced channel width. The Rapid Geomorphic Assessment produced a score of 0.19 or, "In Regime" with the dominant processes being "Evidence of Widening". The Rapid Stream Assessment Technique produced a score of 27, or "Good" with riparian habitat conditions as the limiting factor.

**Reach 5** exists as a straight single channel having been previously channelized and maintained as such. It flows along the western border of the subject property, though a predominantly grassy, unconfined, agricultural/wooded setting. According to the River Styles Framework, it was classified as a suspended load channel with low gradient and low stream power. Average bankfull width and depth were 2.30 m and 0.52 m, respectfully. Geomorphic units were nearly absent through this reach; a single riffle was noted downstream of an informal farm crossing in a short shrubby section of the channel. The remainder of the channel exists as a run feature. Bed material ranged from clay to gravel in runs and from clay to cobbles in riffles with a high degree of embeddedness. Rooted emergent vegetation and rootlets were present along a substantial extent of the reach. This reach exists within an area dominated by wetlands and organic soils. Bank erosion was under 5% in this reach with undercutting up to 0.12 m observed but generally quite low. Bank angles ranged from 60° to 90°. Deposition was noted in the channel and on top of banks.

According to the Downs' Model of Channel Evolution (1995), **Reach 5** was classified as "d – depositional" due to selective deposition resulting in reduced channel width. The Rapid Geomorphic Assessment produced a score of 0.19 or, "In Regime" with the dominant processes being "Evidence of Aggradation". The Rapid Stream Assessment Technique produced a score of 23, or "Good" with riparian habitat conditions as the limiting factor.



**Table 3.2. General channel characteristics by reach**

Reach	Average Bankfull Width (m)	Average Bankfull Depth (m)	Substrate		Valley Type	Riparian Vegetation	Notes
			Riffle	Pool			
<b>1</b>	3.83	0.89	Clay to sand, cobble	Clay to silt	Partially confined	Shrubs and grasses	Straightened section mid-reach with new crossing; over-bank and bar sand deposits common
<b>2</b>	2.83	1.05	Cobble, till	Clay to silt, till	Partially confined	Shrubs and grasses	Undercut along entire reach length; till exposed along bed
<b>3</b>	4.4	0.8	Sand to cobble, bedrock	Clay to sand, cobble	Partially confined	Continuous cedar forest	Well developed riffles and pools; reach in natural state; bedrock exposure along bed
<b>4</b>	2.23	0.88	Clay to silt	Clay to sand, cobble	Partially confined	Mainly grasses, forested areas	Geomorphic units not as well defined as downstream reaches; previous flooding in area; upstream portion not observed
<b>5</b>	2.3	0.52	Clay to cobble, rootlets	Clay to fine gravel, rootlets	Unconfined	Mainly grasses	Previously straightened channel dominated by run feature

### 3.2 Detailed Geomorphological Assessments

Following the initial rapid assessments, **Reach 3** was identified for detailed assessment. This reach was selected because it is most sensitive reaches downstream of the reach that flows along the western boundary of the subject property that may eventually be realigned to accommodate development activities. **Reach 3** was identified as 'In Transition' as a result of aggradation and widening and as such was deemed suitable for determining an appropriate erosion threshold for the upstream subject reach.

The detailed assessment was completed on July 6<sup>th</sup>, 2016 and included the following:

- Long-profile, level survey of the channel centre line;
- 8 detailed cross-sectional surveys of the watercourse;
- Detailed instream measurements at each cross-section location including bankfull channel geometry, riparian conditions, bank material, bank height/angle, and bank root density;
- Bed material sampling at each cross-section following a modified Wolman's (1954) Pebble Count Technique or substrate sample; and
- Velocity, discharge and observations of active/inactive sediment transport at select representative cross-sections.

A summary of the detailed assessment results is provided in **Appendix D**.

**Table 3.3. Bankfull parameters of the sensitive reach**

Channel parameter	Results
Measured	
Average bankfull channel width (m)	3.79
Average bankfull channel depth (m)	0.41
Bankfull channel gradient (%)	0.33
D <sub>50</sub> (mm)	< 2
D <sub>84</sub> (mm)	50.8
Manning's n roughness coefficient	0.030
Computed	
Bankfull discharge (m <sup>3</sup> /s) *	0.45
Average bankfull velocity (m/s)	0.60
Unit stream power at bankfull discharge (W/m <sup>2</sup> )	13.96
Tractive force at bankfull (N/m <sup>2</sup> )	13.24
Critical shear stress (N/m <sup>2</sup> ) **	7.02
Flow competency for D <sub>50</sub> (m/s) ***	N/A
Flow competency for D <sub>84</sub> (m/s) ***	1.20

\* Based on Manning's equation

\*\* Based on Shields diagram from Miller et al. (1997)

\*\*\* Based on Komar (1987)

Bank pins were installed on the tops of banks and erosion pins were installed for bank erosion monitoring at two representative cross sections (one riffle and one pool). Detailed measurements were taken at these two cross sections in order to establish a baseline should future monitoring activities be required. Velocity was measured at select cross sections (typically monitoring cross-sections or riffles) to provide an estimate of stream flow at the time of observations.

## 4 Meander Belt Width Assessment

### 4.1 Methodology

Most watercourses in Ontario have a natural tendency to develop and maintain a meandering planform, provided there are no spatial constraints. A meander belt width assessment estimates the lateral extent that a meandering channel has historically occupied and will likely occupy in the future. This assessment is therefore useful for determining the potential hazard to proposed activities in the vicinity of a stream.

When defining the meander belt width for a creek system, unconfined and confined systems are treated differently. Unconfined systems are those with poorly defined valleys or slopes well-outside where the channel could realistically migrate. Confined systems are those where the watercourse is contained within a defined valley, where valley wall contact is possible.

In unconfined systems, the meander belt width can be graphically defined using orthorectified aerial imagery or through survey by determining the channel centreline and the channel's central tendency (i.e. meander belt axis).

When watercourses are fully confined within a valley, an erosion setback is employed along with delineation of a stable top of slope. Stability of the valley wall should be assessed by a qualified geotechnical engineer.

Meander belt widths were estimated for two channel reaches. **Reach 5** is the reach that flows along the western boundary of the subject property and which may eventually require realignment to accommodate development activities. This reach was unconfined and previously straightened. **Reach 3** represents a reference reach located downstream exhibiting natural meandering features, indicators of sensitivity and partial confinement within a wide valley system. Both reaches exhibited defined channel banks.

**Reach 3** lies mainly within a forested area containing a high density of evergreen vegetation and as such, banks are not clearly visible in aerial photographs. **Reach 5**, as mentioned, was previously straightened. As such, empirical models were used to provide estimates of the meander belt width.

The empirical relations from Williams (1986) were modified to include channel area and width, and applied using the bankfull channel dimensions such that:

$$B_w = (18A^{0.65} + W_b) \times 1.2 \quad [\text{Eq. 1}]$$

$$B_w = (4.3W_b^{1.12} + W_b) \times 1.2 \quad [\text{Eq. 2}]$$

where  $B_w$  is meander belt width (m),  $A$  is bankfull cross-sectional area ( $\text{m}^2$ ), and  $W_b$  is bankfull channel width (m). An additional 20% buffer, or factor of safety, was applied to the computed belt width values. This addresses issues of under prediction and provides a factor of safety.

The results of these empirical models were compared with field-measured values of meander amplitude, for a reference meander within the immediate vicinity of the study area. In order to account for the active channel, the average bankfull width, as well as a 20% factor of safety was applied to this meander amplitude, similar to the empirical modelling approach.

Results of the meander belt width assessment, including the empirical modelling and desktop-based approaches are presented in **Table 4.1**.

**Table 4.1. Meander belt width estimates for subject and reference reaches.**

	Meander Belt Width Method			
	*Williams – Area (1986) (m)	*Williams – Width (1986) (m)	Reference Meander Amplitude Approach (m)	Recommended Meander Belt Width (m)
<b>Reach 3</b>	33	28	23	23
<b>Reach 5</b>	27	16	N/A	27

## 4.2 Results and Discussion

Meander belt width calculations completed in the Carp River Watershed Study (CRWS) take a very conservative approach of 20 to 40 times the bankfull width. This is substantially higher than recommended by the MNRF under their Guidelines (MNRF, 2001). To provide a more site appropriate meander belt width, a detailed assessment of the reach adjacent to the development and a downstream reference reach was completed. The assessment suggests the meander belt

widths range from 16 to 33 m (based on the reference reach). We suggest 27 m provides an adequate meander belt width for **Reach 5** adjacent to the development. This is greater than the measured meander belt width from **Reach 3** (23 m). We note that the area approach from Williams (1984) is more conservative than the width method that we usually employ, due to the uncertainty regarding a potential channel realignment. If a realignment is proposed, this can have an impact on the meander belt width, and should be refined based on the design geometry of the restored bankfull channel.

## 5 Erosion Analysis

### 5.1 Erosion Threshold Analysis

An erosion threshold can be defined as the magnitude of flow required to potentially entrain and transport channel bed and/or bank materials. Threshold targets are therefore provided to guide the design of the proposed SWMFs to ensure that natural erosion rates in the receiving watercourse are not accelerated.

The erosion threshold analysis provides a depth, velocity, or discharge at which sediments of a particular size may potentially be entrained. The results of the detailed geomorphic assessments for **Reach 3** (**Table 3.3** Error! Reference source not found.) were used to inform the erosion threshold analysis. We note that, due to natural variability of channel morphology and sediment characteristics within the reach, the computed flow characteristics only provide first approximations of erosion thresholds.

Erosion thresholds are determined using different methods that are dependent on channel and sediment characteristics. An erosion threshold, in the form of a critical discharge, was calculated based on the bed and bank materials and local channel geometry, as determined in the detailed geomorphological assessments. Theoretically, above this discharge, entrainment and transport of sediment can occur. Erosion thresholds for non-cohesive sediments may be estimated using either a shear stress or a velocity approach.

One such velocity approach follows that of Komar (1987), which is based on a velocity approach, whereby:

$$V_{cr} = 57D^{0.46} \quad [\text{Eq. 5}]$$

where  $V_{cr}$  is the critical velocity (cm/s) required to entrain a grain size of  $D$  (cm).

The velocity in an average channel cross section,  $U$ , is calculated at various depths, until the average velocity in the cross section exceeds the critical velocity of the bed materials. The velocity in the typical cross section is determined using a Manning's approach, where the Manning's  $n$  value is visually estimated, or by using the Limerinos (1970) equation:

$$n = \frac{(0.1129) R^{1/6}}{1.16 + 2.0 \log\left(\frac{R}{D_{84}}\right)} \quad [\text{Eq. 6}]$$

where  $R$  is the hydraulic radius (m) and  $D_{84}$  is the grain size at which 84% of the material is finer (m). Mathematically, the velocity,  $U$ , is calculated as:

$$U = \frac{1}{n} d^{2/3} S^{1/2} \quad [\text{Eq. 7}]$$

where  $n$  is the Manning's roughness coefficient,  $d$  is the depth (m), and  $S$  is the channel gradient. The critical discharge is then calculated using the flow area of the cross section at the depth where the average velocity in the cross section exceeds the critical velocity of the bed materials.

Determining the erosive resistance of cohesive and/or vegetated bank materials depends on a number of factors, including particle size, cohesion of bank materials, and vegetation effects due to rooting. A typical approach to determine thresholds for the banks is to use empirically derived values for various materials, such as those by Julien (1995). To estimate the erosion threshold of the channel banks, it is assumed that 75% of the bed shear stress and velocity act on the banks in a simplified cross section, following Chow (1959). In this case, as for the bed materials, flow depth is increased until the average velocity in the cross section acting on the banks exceeds the permissible velocity of the bank materials, as outlined by Julien (1995).

The results of the erosion threshold analyses are provided in **Table 5.1**.

**Table 5.1. Erosion thresholds of bed and bank materials**


<b>Erosion Thresholds (Reach 3)</b>	
<i>Bankfull Conditions</i>	
Bankfull width (m)	3.79
Maximum bankfull depth (m)	0.59
Average bankfull depth (m)	0.41
Slope (%)	0.33
Bankfull Manning's $n$	0.030
Manning's $n$ applied for erosion thresholds	0.033
Bankfull discharge ( $\text{m}^3/\text{s}$ )	1.64
Bankfull velocity (m/s)	1.05
Bankfull shear stress ( $\text{N}/\text{m}^2$ )	13.24
D50 (m) <sup>†</sup>	0.01130
<i>Erosion Threshold - Bed Materials</i>	
Critical discharge ( $\text{m}^3/\text{s}$ )	0.45
Critical velocity (m/s)*	0.60
Apparent shear stress ( $\text{N}/\text{m}^2$ )	7.02
Water depth at critical discharge (m)	0.24
<i>Erosion Threshold - Bank Materials</i>	
Critical discharge ( $\text{m}^3/\text{s}$ )	0.71
Critical velocity (m/s)**	0.53
Apparent shear stress ( $\text{N}/\text{m}^2$ )	9.38
Water depth at critical discharge (m)	0.32

\* Based on Komar (1987)

\*\* Based on Julien (1995)

† Average grain size excluding fine materials in pools to eliminate bias





The critical discharge needed to entrain the bed materials in **Reach 3** was determined to be 0.45 m<sup>3</sup>/s, based on a critical velocity of 0.60 m/s determined using Komar's (1987) method. As the bank materials in this reach consisted of a sandy loam, a permissible velocity of 0.53 m/s was used (Julien, 1995). The critical discharge for the bank materials, based on this velocity, was determined to be 0.71 m<sup>3</sup>/s. The critical discharge for the bank materials, of 0.45 m<sup>3</sup>/s, was determined to be appropriate for the reach, as it provides a conservative estimate.

It should be noted that the modelling approach applied to determine the erosion thresholds has the potential to underestimate the erosion threshold. As such, field verification is recommended. While the erosion thresholds are based on surveyed cross sections, field verification beyond the water depths on the day of the surveys have not been completed.

## 6 Summary and Recommendations

The subject reach of Feedmill Creek within the subject lands, **Reach 5**, is not confined. As such the channel can naturally migrate within its valley setting. Given this, Williams (1986) meander belt width protocol was employed. The assessment was based on a measurement of the bankfull width, and was modified to accommodate cross-sectional area. This resulted in recommendations for the meander belt width for Reach 5 of 16 m based on existing conditions, and 30 m in the event that the channel is realigned.

Rapid field assessments identified a reach of potential erosion sensitivity downstream of the proposed development. The detailed assessments were completed in one reach that was identified as sensitive and indicative of natural channel conditions. An erosion threshold was defined for the bed and banks of **Reach 3**, and a critical discharge of 0.45 m<sup>3</sup>/s was defined. We note a DRC approach is recommended in the subwatershed study to address erosion concerns. The erosion threshold can be employed in several ways to assess erosion mitigation strategies.

We trust this report meets your requirements. Should you have any questions please contact the undersigned.

Respectfully submitted,

Paul Villard Ph.D., P.Geo., CAN-CISEC  
Director, Geomorphologist

Emily Rick, B.Sc.  
Environmental Scientist

## 7 References

Brierley, G.J. and Fryiers, K.A. 2005. *Geomorphology and River Management: Applications of the River Styles Framework*. Blackwell Publishing, Oxford, UK, 398pp.

Chow, V.T. 1959. *Open channel hydraulics*. McGraw Hill, New York.

City of Ottawa. Carp River Watershed/Subwatershed Study Volume I – Main Report. Prepared by Robinson Consultants Inc. et al., 2004.

Downs, P.W. 1995. Estimating the probability of river channel adjustment. *Earth Surface Processes and Landforms*, 20: 687-705.

Environmental Canada. 2016. Canadian Climate Normals, 1981-2010 Climate Normals & Averages. [http://climate.weather.gc.ca/climate\\_normals/index\\_e.html](http://climate.weather.gc.ca/climate_normals/index_e.html) (accessed March 1, 2016).

Galli, J. 1996. *Rapid Stream Assessment Technique, Field Methods*. Metropolitan Washington Council of Governments.

Julien, P.Y., and Klaassen, G.J. 1995. Sand-dune geometry of large rivers during floods. *Journal of Hydrology*, 53, 73-84.

Komar, P.D. 1987. Selective gravel entrainment and the empirical evaluation of flow competence. *Sedimentology*, 34: 1165-1176

Ministry of Natural Resources and Forestry. 2001. *Understanding Natural Hazards*. Queen's Printer for Ontario, Ontario, Canada.

Montgomery, D.R. and Buffington, J.M. 1997. Channel-reach morphology in mountain drainage basins. *Geological Society of America Bulletin*, (109) 5: 596-611.

Ontario Geological Survey (OGS). 2010. *Surficial Geology of Southern Ontario*.

Richards, K.S., Brooks, S., Clifford, N.J., Harris, T. and Lane, S.N. 1997. Real geomorphology: theory, observation and testing. In Stoddard, D.R. (ed.), *Process and Form in Geomorphology*. London, Routledge, pp. 265-292.

Toronto and Region Conservation Authority. 2004. *Belt Width Delineation Procedures*.


Vermont Agency of Natural Resources (VANR). 2007. Step 7: Rapid Geomorphic Assessment (RGA). Phase 2 Stream Geomorphic Assessment.

Williams, G.P. 1986. River meanders and channel size. *Journal of Hydrology*, 88 (1-2): 147-164.






## **Appendix A Reach Map**





### Legend

-  Reach break
-  Watercourse
-  25 cm Contour

## REACH Delineation Feedmill Creek

Cavanagh Kanata West

GEO MORPHIX

0 100  
Metres



Imagery: Google Earth Pro, 2016.  
Reach break: GEO Morphix Ltd., 2016.  
Watercourse: MNR (2010). 25 cm Contour: DSEL (2016).





## **Appendix B**

### **Photographic Record**



Photo  
1



Reach 1 – upstream facing to run feature; grassy banks, partial confinement, undercutting on inner bank, sandy deposit out outer bank

Photo  
2



Reach 1 – upstream facing upstream of new crossing; large sandy deposit with cut face on bank



Photo  
3



Reach 2 – till on stream bed

Photo  
4



Reach 2 – upstream facing – wooded section of reach; undercut banks, woody debris; riffle feature with cobbles; embedded cobbles at downstream end; sand on bank



Photo  
5



Reach 3 – upstream facing downstream end of reach; large undercut, large sandy deposit, exposed tree roots and woody debris

Photo  
6



Reach 3 – upstream facing at downstream end of reach; riffle over exposed bedrock on bed



Photo  
7



Reach 3 – upstream facing at surveyed cross section 3 (mid-reach) - riffle feature; bed material mainly cobbles

Photo  
8



Reach 3 – downstream facing at surveyed cross-section 5 (mid-reach) – pool feature; bed material clay to sand with embedded cobbles; sand on inner bank, undercut outer bank



Photo  
9



Reach 4 - upstream facing; grassy undercut banks; silt to cobbles on bed

Photo  
10



Reach 4 - upstream facing; run feature with undercut banks and large woody debris; dead trees throughout floodplain



Photo  
11



Reach 5 - upstream facing; grassy undercut banks; run feature; clay to silt bed with rooted submergent vegetation

Photo  
12



Reach 5 - upstream facing in scrubby wooded section of reach showing bankfull dimensions and straight nature of reach; clay to cobble bed material, embeddedness



## **Appendix C**

### **Field Observations**



# General Site Characteristics

Project Code/Phase: PN 16059

Date:	<u>July 5 2016</u>	Stream/Reach:	<u>Reach 1</u>
Weather:	<u>sun/clouds 33°C</u>	Location:	<u>Feedmill Creek</u>
Field Staff:	<u>AD/ER</u>	Watershed/Subwatershed:	<u>Carp River</u>

## Features

- Reach break
- x—x Cross-section
- Flow direction
- ~ Riffle
- Pool
- ▨ Island/bar
- ||||| Eroded bank
- Undercut bank
- XXXXXX Rip rap/stabilization
- Instream log/tree
- x---x---x Fence
- Culvert
- ▨ Swamp
- ▽▽▽ Grasses
- Tree

## Flow Type

- H1 Standing water
- H2 Scarcely perceptible flow
- H3 Smooth surface flow
- H4 Upwelling
- H5 Rippled
- H6 Unbroken standing wave
- H7 Broken standing wave
- H8 Chute
- H9 Free fall


## Substrate

- S1 Silt
- S2 Sand
- S3 Gravel
- S4 Small cobble
- S5 Large cobble
- S6 Small boulder
- S7 Large boulder
- S8 Bimodal
- S9 Bedrock/till

## Other

- |    |               |     |                     |
|----|---------------|-----|---------------------|
| BM | Benchmark     | TR  | Terrace             |
| FC | Flood chute   | BOS | Bottom of slope     |
| FP | Floodplain    | TOS | Top of slope        |
| GC | Grade control | VWC | Valley wall contact |
| KP | Knick point   | WDJ | Woody debris jam    |

## Site Sketch:



Additional notes: beaver cut wood in creek · Siltation in pools

Overbank sand deposits common

rooted submergent and emergent

- realigned (straightened portion extends ups & d/s of new crossing (2014).

GEO | MORPHIX  
Geomorphology  
Earth Science  
Observations

Completed by: ER Checked by: AD

## Reach Characteristics

Project Code/Phase: pn16059

Date:	July 5, 2016	Stream/Reach:	Reach 1
Weather:	33°C, sunny	Location:	Feedmill Creek
Field staff:	ER/AD	Watershed/Subwatershed:	Carp River
UTM (Upstream)	426842.13 mE, 5016410.23 mN	UTM (Downstream)	426842.80 mE, 5016548.96 mN

Land Use (Table 1) ☐ 4 Valley Type (Table 2) ☐ 2 Channel Type (Table 3) ☐ 13 Channel Zone (Table 4) ☐ 2 Flow Type (Table 5) ☐ 1 ☐ Groundwater Evidence: \_\_\_\_\_

Riparian Vegetation				
Dominant Type: (Table 6)	Coverage: <input type="checkbox"/> None <input checked="" type="checkbox"/> Fragmented <input type="checkbox"/> Continuous	Channel widths <input type="checkbox"/> 1-4 <input checked="" type="checkbox"/> 4-10 <input type="checkbox"/> > 10	Age Class (yrs): <input type="checkbox"/> Immature (<5) <input checked="" type="checkbox"/> Established (5-30) <input type="checkbox"/> Mature (>30)	Encroachment: (Table 7) <input type="checkbox"/> 2
Species: <u>unknown</u>				

Aquatic/Instream Vegetation	
Type (Table 8)	Coverage of Reach (%)
<input type="checkbox"/> 1/2	<input type="checkbox"/> 10
Woody Debris	Density of WD:
<input checked="" type="checkbox"/> Present in Cutbank <input checked="" type="checkbox"/> Present in Channel <input type="checkbox"/> Not Present	<input type="checkbox"/> Low <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> High
	WDJ/50m: <input type="checkbox"/> 2

Water Quality
Odour (Table 16) <input type="checkbox"/> 1 very clear
Turbidity (Table 17) <input type="checkbox"/> 1 cool no substrate fouling

Channel Characteristics											
Sinuosity (Type) (Table 9)	Sinuosity (Degree) (Table 10)	Gradient (Table 11)	Number of Channels (Table 12)	Riffle Substrate	Clay/Silt	Sand	Gravel	Cobble	Boulder	Parent	Rootlets
<input type="checkbox"/> 2	<input type="checkbox"/> 2	<input type="checkbox"/> 1/2	<input type="checkbox"/> 1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Entrenchment (Table 13)	Type of Bank Failure (Table 14)	Downs's Classification (Table 15)	Pool Substrate	Bank Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> d	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Bankfull Width (m)	Bankfull Depth (m)	Wetted Width (m)	Wetted Depth (m)	Bank Angle	Bank Erosion		Notes: _____ _____ _____ _____ _____				
<input type="checkbox"/> 3.50	<input type="checkbox"/> 1.30	<input type="checkbox"/> 4.30	<input type="checkbox"/> 0.67	<input type="checkbox"/> 0-30	<input type="checkbox"/> < 5%						
<input type="checkbox"/> 3.70	<input type="checkbox"/> 0.70	<input type="checkbox"/> 0.67	<input type="checkbox"/> 0.61	<input checked="" type="checkbox"/> 30-60	<input checked="" type="checkbox"/> 5-30%						
<input type="checkbox"/> 2.30	<input type="checkbox"/> 0.30	<input type="checkbox"/> 0.15	<input type="checkbox"/> 0.30	<input checked="" type="checkbox"/> 60-90	<input type="checkbox"/> 30-60%						
Riffle/Pool Spacing (m)	% Riffles:	% Pools:	Meander Amplitude:	<input checked="" type="checkbox"/> Undercut	<input type="checkbox"/> 60-100%						
<input type="checkbox"/> 30	<input type="checkbox"/> 30	<input type="checkbox"/> 70	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>						
Pool Depth (m) (BF)	Riffle Length (m)	Undercuts (m)	Comments:	overbank + bar deposits common							
<input type="checkbox"/> 1.0 <input type="checkbox"/> 1.30 <input type="checkbox"/> 0.60 <input type="checkbox"/> 0.61	<input type="checkbox"/> 3-4	<input type="checkbox"/> 6.33									
Velocity (m/s)	Wiffle ball / ADV / Estimated										
<input type="checkbox"/> Not measured.											

Completed by: ER

Checked by: AD



## Rapid Geomorphic Assessment

Project Code/Phase: PN 16059

Date:	July 5, 2016	Stream/Reach:	Reach 1
Weather:	33°C sun/clouds	Location:	Feedmill Creek
Field Staff:	AD ER	Watershed/Subwatershed:	Cano River

Process	Geomorphic Indicator		Present?		Factor Value
	No.	Description	Yes	No	
Evidence of Aggradation (AI)	1	Lobate bar		✓	4/7
	2	Coarse materials in riffles embedded	✓		
	3	Siltation in pools	✓		
	4	Medial bars		✓	
	5	Accretion on point bars	✓		
	6	Poor longitudinal sorting of bed materials		✓	
	7	Deposition in the overbank zone	✓		
Sum of indices =			4	3	0.57

Evidence of Degradation (DI)	1	Exposed bridge footing(s)		✓	1/8
	2	Exposed sanitary / storm sewer / pipeline / etc.		N/A	
	3	Elevated storm sewer outfall(s)		✓	
	4	Undermined gabion baskets / concrete aprons / etc.		N/A	
	5	Scour pools downstream of culverts / storm sewer outlets		✓	
	6	Cut face on bar forms	✓		
	7	Head cutting due to knick point migration		✓	
	8	Terrace cut through older bar material		✓	
	9	Suspended armour layer visible in bank		✓	
	10	Channel worn into undisturbed overburden / bedrock		✓	
Sum of indices =			1	7	0.125

Evidence of Widening (WI)	1	Fallen / leaning trees / fence posts / etc.	✓		2/7
	2	Occurrence of large organic debris	✓		
	3	Exposed tree roots		✓	
	4	Basal scour on inside meander bends		✓	
	5	Basal scour on both sides of channel through riffle		✓	
	6	Outflanked gabion baskets / concrete walls / etc.		N/A	
	7	Length of basal scour >50% through subject reach		✓	
	8	Exposed length of previously buried pipe / cable / etc.		N/A	
	9	Fracture lines along top of bank		✓	
	10	Exposed building foundation		N/A	
Sum of indices =			2	5	0.29

Evidence of Planimetric Form Adjustment (PI)	1	Formation of chute(s)		✓	0/7
	2	Single thread channel to multiple channel		✓	
	3	Evolution of pool-riffle form to low bed relief form		✓	
	4	Cut-off channel(s)		✓	
	5	Formation of island(s)		✓	
	6	Thalweg alignment out of phase meander form		✓	
	7	Bar forms poorly formed / reworked / removed		✓	
Sum of indices =			0	7	0

Additional notes:

Stability Index (SI) = (AI+DI+WI+PI)/4 = 0.25

Condition	In Regime	In Transition/Stress	In Adjustment
SI score =	<input type="checkbox"/> 0.00 - 0.20	<input checked="" type="checkbox"/> 0.21 - 0.40	<input type="checkbox"/> 0.41

Completed by: AD ER Checked by: \_\_\_\_\_



# Rapid Stream Assessment Technique

Project Number: PN 16059

Date: July 5, 2016	Stream/Reach: Reach 1
Weather: Sun/clouds 33°C	Location: Feedmill Creek
Field Staff: AD ER	Watershed/Subwatershed: Carp River

Evaluation Category	Poor	Fair	Good	Excellent
Channel Stability	<ul style="list-style-type: none"> <li>&lt; 50% of bank network stable</li> <li>Recent bank sloughing, slumping or failure frequently observed</li> </ul>	<ul style="list-style-type: none"> <li>50-70% of bank network stable</li> <li>Recent signs of bank sloughing, slumping or failure fairly common</li> </ul>	<ul style="list-style-type: none"> <li>71-80% of bank network stable</li> <li>Infrequent signs of bank sloughing, slumping or failure</li> </ul>	<ul style="list-style-type: none"> <li>&gt; 80% of bank network stable</li> <li>No evidence of bank sloughing, slumping or failure</li> </ul>
	<ul style="list-style-type: none"> <li>Stream bend areas highly unstable</li> <li>Outer bank height 1.2 m above stream bank (2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang &gt; 0.8-1.0 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas unstable</li> <li>Outer bank height 0.9-1.2 m above stream bank (1.5-2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.8-0.9 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas stable</li> <li>Outer bank height 0.6-0.9 m above stream bank (1.2-1.5 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.6-0.8 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas very stable</li> <li>Height &lt; 0.6 m above stream (&lt; 1.2 m above stream bank for large mainstem areas)</li> <li>Bank overhang &lt; 0.6 m</li> </ul>
	<ul style="list-style-type: none"> <li>Young exposed tree roots abundant</li> <li>&gt; 6 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Young exposed tree roots common</li> <li>4-5 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots predominantly old and large, smaller young roots scarce</li> <li>2-3 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots old, large and woody</li> <li>Generally 0-1 recent large tree falls per stream mile</li> </ul>
	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is highly erodible material</li> <li>Plant/soil matrix severely compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly erodible material</li> <li>Plant/soil matrix compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>
	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8	<input type="checkbox"/> 9 <input checked="" type="checkbox"/> 10 <input type="checkbox"/> 11

Channel Scouring/ Sediment Deposition	<ul style="list-style-type: none"> <li>&gt; 75% embedded (&gt; 85% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>50-75% embedded (60-85% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>25-49% embedded (35-59% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Riffle embeddedness &lt; 25% sand-silt (&lt; 35% embedded for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Few, if any, deep pools</li> <li>Pool substrate composition: &gt; 81% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Low to moderate number of deep pools</li> <li>Pool substrate composition: 60-80% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Moderate number of deep pools</li> <li>Pool substrate composition: 30-59% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>High number of deep pools (&gt; 61 cm deep) (&gt; 122 cm deep for large mainstem areas)</li> <li>Pool substrate composition: &lt; 30% sand-silt</li> </ul>
	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits uncommon</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits absent</li> </ul>
	<ul style="list-style-type: none"> <li>Fresh, large sand deposits very common in channel</li> <li>Moderate to heavy sand deposition along major portion of overbank area</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits common in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits uncommon in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits rare or absent from channel</li> <li>No evidence of fresh sediment deposition on overbank</li> </ul>
	<ul style="list-style-type: none"> <li>Point bars present at most stream bends, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars common, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars few, small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input checked="" type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8

Evaluation Category	Poor	Fair	Good	Excellent
Physical Instream Habitat	<ul style="list-style-type: none"> <li>Wetted perimeter &lt; 40% of bottom channel width (&lt; 45% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 40-60% of bottom channel width (45-65% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 61-85% of bottom channel width (66-90% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter &gt; 85% of bottom channel width (&gt; 90% for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Dominated by one habitat type (usually runs) and by one velocity and depth condition (slow and shallow) (for large mainstem areas, few riffles present, runs and pools dominant, velocity and depth diversity low)</li> </ul>	<ul style="list-style-type: none"> <li>Few pools present, riffles and runs dominant. velocity and depth generally slow and shallow (for large mainstem areas, runs and pools dominant, velocity and depth diversity intermediate)</li> </ul>	<ul style="list-style-type: none"> <li>Good mix between riffles, runs and pools</li> <li>Relatively diverse velocity and depth of flow</li> </ul>	<ul style="list-style-type: none"> <li>Riffles, runs and pool habitat present</li> <li>Diverse velocity and depth of flow present (i.e., slow, fast, shallow and deep water)</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly gravel with high percentage of sand</li> <li>&lt; 5% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly small cobble, gravel and sand</li> <li>5-24% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: good mix of gravel, cobble, and rubble material</li> <li>25-49% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: cobble, gravel, rubble, boulder mix with little sand</li> <li>&gt; 50% cobble</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle depth &lt; 10 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 10-15 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 15-20 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth &gt; 20 cm for large mainstem areas</li> </ul>
	<ul style="list-style-type: none"> <li>Large pools generally &lt; 30 cm deep (&lt; 61 cm for large mainstem areas) and devoid of overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 30-46 cm deep (61-91 cm for large mainstem areas) with little or no overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 46-61 cm deep (91-122 cm for large mainstem areas) with some overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally &gt; 61 cm deep (&gt; 122 cm for large mainstem areas) with good overhead cover/structure</li> </ul>
	<ul style="list-style-type: none"> <li>Extensive channel alteration and/or point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Moderate amount of channel alteration and/or moderate increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Slight amount of channel alteration and/or slight increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>No channel alteration or significant point bar formation/enlargement</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.49:1 ≤; ≥ 1.51:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.5-0.69:1; 1.31-1.5:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.7-0.89:1; 1.11-1.3:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.9-1.1:1</li> </ul>
	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &gt; 27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 24-27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 20-24°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &lt; 20°C</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input checked="" type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8

Water Quality	<ul style="list-style-type: none"> <li>Substrate fouling level: High (&gt; 50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Moderate (21-50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Very light (11-20%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Rock underside (0-10%)</li> </ul>
	<ul style="list-style-type: none"> <li>Brown colour</li> <li>TDS: &gt; 150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Grey colour</li> <li>TDS: 101-150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Slightly grey colour</li> <li>TDS: 50-100 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Clear flow</li> <li>TDS: &lt; 50 mg/L</li> </ul>
	<ul style="list-style-type: none"> <li>Objects visible to depth &lt; 0.15 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.15-0.5 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.5-1.0 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth &gt; 1.0 m below surface</li> </ul>
	<ul style="list-style-type: none"> <li>Moderate to strong organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight to moderate organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight organic odour</li> </ul>	<ul style="list-style-type: none"> <li>No odour</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input checked="" type="checkbox"/> 8

Riparian Habitat Conditions	<ul style="list-style-type: none"> <li>Narrow riparian area of mostly non-woody vegetation</li> </ul>	<ul style="list-style-type: none"> <li>Riparian area predominantly wooded but with major localized gaps</li> </ul>	<ul style="list-style-type: none"> <li>Forested buffer generally &gt; 31 m wide along major portion of both banks</li> </ul>	<ul style="list-style-type: none"> <li>Wide (&gt; 60 m) mature forested buffer along both banks</li> </ul>
	<ul style="list-style-type: none"> <li>Canopy coverage: &lt; 50% shading (30% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 50-60% shading (30-44% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 60-79% shading (45-59% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: &gt; 80% shading (&gt; 60% for large mainstem areas)</li> </ul>
Point range	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7

Additional notes:

Total overall score (0 - 42) = 27

Ranking	Poor (<13)	Fair (13-24)	Good (25-34)	Excellent (>35)
			27	

Completed by: AD/ER Checked by: \_\_\_\_\_



# General Site Characteristics

Project Code/Phase: PN 16059

Date:	<u>July 5, 2016</u>	Stream/Reach:	<u>Reach 2</u>
Weather:	<u>Sun/clouds 33°C</u>	Location:	<u>Feedmill Creek</u>
Field Staff:	<u>AD, ER</u>	Watershed/Subwatershed:	<u>Carp River</u>

## Features

- Reach break
- ×—× Cross-section
- Flow direction
- ~ Riffle
- Pool
- ▨ Island/bar
- ▨▨▨▨▨ Eroded bank
- - - Undercut bank
- XXXXXX Rip rap/stabilization
- Instream log/tree
- ×—×—× Fence
- Culvert
- ▨ Swamp
- ▽▽▽ Grasses
- Tree

## Flow Type

- H1 Standing water
- H2 Scarcely perceptible flow
- H3 Smooth surface flow
- H4 Upwelling
- H5 Rippled
- H6 Unbroken standing wave
- H7 Broken standing wave
- H8 Chute
- H9 Free fall


## Substrate

- S1 Silt
- S2 Sand
- S3 Gravel
- S4 Small cobble
- S5 Large cobble
- S6 Small boulder
- S7 Large boulder
- S8 Bimodal
- S9 Bedrock/till

## Other

- |                  |                         |
|------------------|-------------------------|
| BM Benchmark     | TR Terrace              |
| FC Flood chute   | BOS Bottom of slope     |
| FP Floodplain    | TOS Top of slope        |
| GC Grade control | VWC Valley wall contact |
| KP Knick point   | WDJ Woody debris jam    |

## Site Sketch:



Additional notes:

undercut along entire reach  
till exposed on bed extensively, esp through d/s end of reach

GEO | MORPHIX  
 Geomorphology  
 Earth Science  
 Observations

Completed by: ER Checked by: AD

## Reach Characteristics

Project Code/Phase: ph16059

Date:	<u>July 5, 2016</u>	Stream/Reach:	<u>Reach 2</u>
Weather:	<u>sun/clouds 33°C</u>	Location:	<u>Feedmill Creek</u>
Field staff:	<u>AD, ER</u>	Watershed/Subwatershed:	<u>Carp River</u>
UTM (Upstream)	<u>426581.47 m E, 5016248.45 m N</u>	UTM (Downstream)	<u>426642.3 m E, 5016410.23 m N</u>

Land Use (Table 1) 4 Valley Type (Table 2) 2 Channel Type (Table 3) 13 Channel Zone (Table 4) 2 Flow Type (Table 5) 1 ☐ Groundwater Evidence: \_\_\_\_\_

<b>Riparian Vegetation</b> Dominant Type: (Table 6) <u>2/3</u> Coverage: <input type="checkbox"/> None <input type="checkbox"/> 1-4 <input type="checkbox"/> Immature (<5) (Table 7) Species: <u>unk</u> <input checked="" type="checkbox"/> Fragmented <input checked="" type="checkbox"/> 4-10 <input checked="" type="checkbox"/> Established (5-30) <input type="checkbox"/> Mature (>30) <input type="checkbox"/> Continuous <input type="checkbox"/> >10 Encroachment: <u>2</u>				<b>Aquatic/Instream Vegetation</b> Type (Table 8) <u>1/6</u> Coverage of Reach (%) <u>15</u> Woody Debris Density of WD: <input type="checkbox"/> Present in Cutbank <input checked="" type="checkbox"/> Low WDJ/50m: <input checked="" type="checkbox"/> Present in Channel <input type="checkbox"/> Moderate <u>1</u> <input type="checkbox"/> Not Present <input type="checkbox"/> High		<b>Water Quality</b> Odour (Table 16) <u>1</u> Turbidity (Table 17) <u>1</u>
--	--	--	--	---	--	--

Channel Characteristics											
Sinuosity (Type) (Table 9) <u>2</u>	Sinuosity (Degree) (Table 10) <u>2</u>	Gradient (Table 11) <u>1/2</u>	Number of Channels (Table 12) <u>1</u>	Clay/Silt	Sand	Gravel	Cobble	Boulder	Parent	Rootlets	
Entrenchment (Table 13) <u>1</u>	Type of Bank Failure (Table 14) <u>2</u>	Downs's Classification (Table 15) <u>2</u>		Riffle Substrate <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
				Pool Substrate <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
				Bank Material <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Bankfull Width (m)	<u>3.0</u>	<u>2.65</u>	Wetted Width (m)	<u>2.30</u>	<u>2.20</u>		Bank Angle	Bank Erosion	Notes:		
Bankfull Depth (m)	<u>1.05</u>	<u>1.05</u>	Wetted Depth (m)	<u>6.50</u>	<u>6.48</u>		<input type="checkbox"/> 0-30	<input type="checkbox"/> <5%			
Riffle/Pool Spacing (m)	<u>50</u>	% Riffles: <u>20</u>	% Pools: <u>80</u>	Meander Amplitude:		<input checked="" type="checkbox"/> 30-60	<input checked="" type="checkbox"/> 5-30%				
Pool Depth (m)	<u>0.50</u>	Riffle Length (m)	<u>3.4</u>	Undercuts (m)	<u>6.30</u>	<input checked="" type="checkbox"/> 60-90	<input type="checkbox"/> 30-60%				
Velocity (m/s)	<u>not measured</u>			Wiffle ball / ADV / Estimated		<input checked="" type="checkbox"/> Undercut	<input type="checkbox"/> 60-100%				
Comments:											

Completed by: ERChecked by: AD



## Rapid Geomorphic Assessment

Project Code/Phase: PN16059

Date:	July 5, 2016	Stream/Reach:	Reach 2
Weather:	Sun, clouds 33°C	Location:	Feedmill Creek
Field Staff:	AD, ER	Watershed/Subwatershed:	Carp River

Process	Geomorphic Indicator		Present?		Factor Value
	No.	Description	Yes	No	
Evidence of Aggradation (AI)	1	Lobate bar		✓	3/4
	2	Coarse materials in riffles embedded		✓	
	3	Siltation in pools	✓		
	4	Medial bars		✓	
	5	Accretion on point bars	✓		
	6	Poor longitudinal sorting of bed materials		✓	
	7	Deposition in the overbank zone	✓		
Sum of indices =			3	4	0.43

Evidence of Degradation (DI)	1	Exposed bridge footing(s)		N/A	2/5
	2	Exposed sanitary / storm sewer / pipeline / etc.		N/A	
	3	Elevated storm sewer outfall(s)		N/A	
	4	Undermined gabion baskets / concrete aprons / etc.		N/A	
	5	Scour pools downstream of culverts / storm sewer outlets		N/A	
	6	Cut face on bar forms	✓		
	7	Head cutting due to knick point migration		✓	
	8	Terrace cut through older bar material		✓	
	9	Suspended armour layer visible in bank		✓	
	10	Channel worn into undisturbed overburden / bedrock (+fill)	✓		
Sum of indices =			2	3	0.40

Evidence of Widening (WI)	1	Fallen / leaning trees / fence posts / etc.	✓		2/4
	2	Occurrence of large organic debris	✓		
	3	Exposed tree roots		✓	
	4	Basal scour on inside meander bends		✓	
	5	Basal scour on both sides of channel through riffle		✓	
	6	Outflanked gabion baskets / concrete walls / etc.		N/A	
	7	Length of basal scour >50% through subject reach		✓	
	8	Exposed length of previously buried pipe / cable / etc.		N/A	
	9	Fracture lines along top of bank		✓	
	10	Exposed building foundation		N/A	
Sum of indices =			2	5	0.29

Evidence of Planimetric Form Adjustment (PI)	1	Formation of chute(s)		✓	0
	2	Single thread channel to multiple channel		✓	
	3	Evolution of pool-riffle form to low bed relief form		✓	
	4	Cut-off channel(s)		✓	
	5	Formation of island(s)		✓	
	6	Thalweg alignment out of phase meander form		✓	
	7	Bar forms poorly formed / reworked / removed		✓	
Sum of indices =			0	7	0

Additional notes:

Stability Index (SI) = (AI+DI+WI+PI)/4 = 0.28

Condition	In Regime	In Transition/Stress	In Adjustment
SI score =	<input type="checkbox"/> 0.00 - 0.20	<input checked="" type="checkbox"/> 0.21 - 0.40	<input type="checkbox"/> 0.41

Completed by: AD, ER Checked by: \_\_\_\_\_

# Rapid Stream Assessment Technique

Project Number: PN 16059

Date:	July 5, 2016	Stream/Reach:	Reach 2
Weather:	Sun/Clouds 33C	Location:	Feedmill Creek
Field Staff:	ADJR	Watershed/Subwatershed:	Camp River

Evaluation Category	Poor	Fair	Good	Excellent
Channel Stability	<ul style="list-style-type: none"> <li>&lt; 50% of bank network stable</li> <li>Recent bank sloughing, slumping or failure frequently observed</li> </ul>	<ul style="list-style-type: none"> <li>50-70% of bank network stable</li> <li>Recent signs of bank sloughing, slumping or failure fairly common</li> </ul>	<ul style="list-style-type: none"> <li>71-80% of bank network stable</li> <li>Infrequent signs of bank sloughing, slumping or failure</li> </ul>	<ul style="list-style-type: none"> <li>&gt; 80% of bank network stable</li> <li>No evidence of bank sloughing, slumping or failure</li> </ul>
	<ul style="list-style-type: none"> <li>Stream bend areas highly unstable</li> <li>Outer bank height 1.2 m above stream bank (2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang &gt; 0.8-1.0 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas unstable</li> <li>Outer bank height 0.9-1.2 m above stream bank (1.5-2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.8-0.9 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas stable</li> <li>Outer bank height 0.6-0.9 m above stream bank (1.2-1.5 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.6-0.8 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas very stable</li> <li>Height &lt; 0.6 m above stream (&lt; 1.2 m above stream bank for large mainstem areas)</li> <li>Bank overhang &lt; 0.6 m</li> </ul>
	<ul style="list-style-type: none"> <li>Young exposed tree roots abundant</li> <li>&gt; 6 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Young exposed tree roots common</li> <li>4-5 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots predominantly old and large, smaller young roots scarce</li> <li>2-3 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots old, large and woody</li> <li>Generally 0-1 recent large tree falls per stream mile</li> </ul>
	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is highly erodible material</li> <li>Plant/soil matrix severely compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly erodible material</li> <li>Plant/soil matrix compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>
	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>
	Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8

Channel Scouring/ Sediment Deposition	<ul style="list-style-type: none"> <li>&gt; 75% embedded (&gt; 85% embedded for large mainstem areas)</li> <li>Few, if any, deep pools</li> <li>Pool substrate composition: &gt; 81% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>50-75% embedded (60-85% embedded for large mainstem areas)</li> <li>Low to moderate number of deep pools</li> <li>Pool substrate composition: 60-80% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>25-49% embedded (35-59% embedded for large mainstem areas)</li> <li>Moderate number of deep pools</li> <li>Pool substrate composition: 30-59% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Riffle embeddedness &lt; 25% sand-silt (&lt; 35% embedded for large mainstem areas)</li> <li>High number of deep pools (&gt; 61 cm deep) (&gt; 122 cm deep for large mainstem areas)</li> <li>Pool substrate composition: &lt; 30% sand-silt</li> </ul>
	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits uncommon</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits absent</li> </ul>
	<ul style="list-style-type: none"> <li>Fresh, large sand deposits very common in channel</li> <li>Moderate to heavy sand deposition along major portion of overbank area</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits common in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits uncommon in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits rare or absent from channel</li> <li>No evidence of fresh sediment deposition on overbank</li> </ul>
	<ul style="list-style-type: none"> <li>Point bars present at most stream bends, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars common, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars few, small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>
	Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input checked="" type="checkbox"/> 5 <input type="checkbox"/> 6



Evaluation Category	Poor	Fair	Good	Excellent
Physical Instream Habitat	<ul style="list-style-type: none"> <li>Wetted perimeter &lt; 40% of bottom channel width (&lt; 45% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 40-60% of bottom channel width (45-65% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 61-85% of bottom channel width (66-90% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter &gt; 85% of bottom channel width (&gt; 90% for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Dominated by one habitat type (usually runs) and by one velocity and depth condition (slow and shallow) (for large mainstem areas, few riffles present, runs and pools dominant, velocity and depth diversity low)</li> </ul>	<ul style="list-style-type: none"> <li>Few pools present, riffles and runs dominant, velocity and depth generally slow and shallow (for large mainstem areas, runs and pools dominant, velocity and depth diversity intermediate)</li> </ul>	<ul style="list-style-type: none"> <li>Good mix between riffles, runs and pools</li> <li>Relatively diverse velocity and depth of flow</li> </ul>	<ul style="list-style-type: none"> <li>Riffles, runs and pool habitat present</li> <li>Diverse velocity and depth of flow present (i.e., slow, fast, shallow and deep water)</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly gravel with high percentage of sand</li> <li>&lt; 5% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly small cobble, gravel and sand</li> <li>5-24% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: good mix of gravel, cobble, and rubble material</li> <li>25-49% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: cobble, gravel, rubble, boulder mix with little sand</li> <li>&gt; 50% cobble</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle depth &lt; 10 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 10-15 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 15-20 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth &gt; 20 cm for large mainstem areas</li> </ul>
	<ul style="list-style-type: none"> <li>Large pools generally &lt; 30 cm deep (&lt; 61 cm for large mainstem areas) and devoid of overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 30-46 cm deep (61-91 cm for large mainstem areas) with little or no overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 46-61 cm deep (91-122 cm for large mainstem areas) with some overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally &gt; 61 cm deep (&gt; 122 cm for large mainstem areas) with good overhead cover/structure</li> </ul>
	<ul style="list-style-type: none"> <li>Extensive channel alteration and/or point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Moderate amount of channel alteration and/or moderate increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Slight amount of channel alteration and/or slight increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>No channel alteration or significant point bar formation/enlargement</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.49:1 ≤   ≥ 1.51:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.5-0.69:1;   1.31-1.5:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.7-0.89:1;   1.11-1.3:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.9-1.1:1</li> </ul>
	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &gt; 27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 24-27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 20-24°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &lt; 20°C</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input checked="" type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8

Water Quality	<ul style="list-style-type: none"> <li>Substrate fouling level: High (&gt; 50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Moderate (21-50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Very light (11-20%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Rock underside (0-10%)</li> </ul>
	<ul style="list-style-type: none"> <li>Brown colour</li> <li>TDS: &gt; 150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Grey colour</li> <li>TDS: 101-150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Slightly grey colour</li> <li>TDS: 50-100 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Clear flow</li> <li>TDS: &lt; 50 mg/L</li> </ul>
	<ul style="list-style-type: none"> <li>Objects visible to depth &lt; 0.15 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.15-0.5 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.5-1.0 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth &gt; 1.0 m below surface</li> </ul>
	<ul style="list-style-type: none"> <li>Moderate to strong organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight to moderate organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight organic odour</li> </ul>	<ul style="list-style-type: none"> <li>No odour</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input checked="" type="checkbox"/> 8

Riparian Habitat Conditions	<ul style="list-style-type: none"> <li>Narrow riparian area of mostly non-woody vegetation</li> </ul>	<ul style="list-style-type: none"> <li>Riparian area predominantly wooded but with major localized gaps</li> </ul>	<ul style="list-style-type: none"> <li>Forested buffer generally &gt; 31 m wide along major portion of both banks</li> </ul>	<ul style="list-style-type: none"> <li>Wide (&gt; 60 m) mature forested buffer along both banks</li> </ul>
	<ul style="list-style-type: none"> <li>Canopy coverage: &lt; 50% shading (30% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 50-60% shading (30-44% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 60-79% shading (45-59% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: &gt; 80% shading (&gt; 60% for large mainstem areas)</li> </ul>
Point range	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7

Additional notes:

Total overall score (0 - 42) = 29

Ranking	Poor (<13)	Fair (13-24)	Good (25-34)	Excellent (>35)
			29	

Completed by: AD, ER Checked by: \_\_\_\_\_

# General Site Characteristics

Project Code/Phase: PV16059

Date:	<u>July 5, 2016</u>	Stream/Reach:	<u>Reach 3</u>
Weather:	<u>Mainly Sunny 33°C</u>	Location:	<u>Feedmill Creek</u>
Field Staff:	<u>AD/ER</u>	Watershed/Subwatershed:	<u>Carp River</u>

## Features

- Reach break
- x—x Cross-section
- Flow direction
- ~ Riffle
- Pool
- ▨ Island/bar
- ▨▨▨▨ Eroded bank
- - - Undercut bank
- XXXXXX Rip rap/stabilization
- Instream log/tree
- x—x—x Fence
- Culvert
- ▨ Swamp
- ▽▽▽ Grasses
- Tree

## Flow Type

- H1 Standing water
- H2 Scarcely perceptible flow
- H3 Smooth surface flow
- H4 Upwelling
- H5 Rippled
- H6 Unbroken standing wave
- H7 Broken standing wave
- H8 Chute
- H9 Free fall


## Substrate

- S1 Silt
- S2 Sand
- S3 Gravel
- S4 Small cobble
- S5 Large cobble
- S6 Small boulder
- S7 Large boulder
- S8 Bimodal
- S9 Bedrock/till

## Other

- |    |               |     |                     |
|----|---------------|-----|---------------------|
| BM | Benchmark     | TR  | Terrace             |
| FC | Flood chute   | BOS | Bottom of slope     |
| FP | Floodplain    | TOS | Top of slope        |
| GC | Grade control | VWC | Valley wall contact |
| KP | Knick point   | WDJ | Woody debris jam    |

## Site Sketch:



Additional notes:

GEO | MORPHIX

Geomorphology  
Earth Science  
Observations

Completed by: AD/ER Checked by: \_\_\_\_\_



## Reach Characteristics

Project Code/Phase: pn16059

Date:	<u>July 5, 2016</u>	Stream/Reach:	<u>Reach 3</u>
Weather:	<u>mainly sunny 33°C</u>	Location:	<u>Feedmill Creek</u>
Field staff:	<u>AD/ER</u>	Watershed/Subwatershed:	<u>Carp River</u>
UTM (Upstream)	<u>426100.42 mE, 5015886.35 mN</u>	UTM (Downstream)	<u>426344 mE, 5016093.89 mN</u>

Land Use (Table 1) 1/4 Valley Type (Table 2) 2 Channel Type (Table 3) 13 Channel Zone (Table 4) 2 Flow Type (Table 5) 1 ☐ Groundwater Evidence: \_\_\_\_\_

## Riparian Vegetation

Dominant Type: (Table 6) 1 Coverage: ☐ None ☐ 1-4 ☐ Immature (<5) ☐ Encroachment: (Table 7) 1  
 Species: cedar ☐ Fragmented ☐ 4-10 ☐ Established (5-30) ☐  
☒ Continuous ☒ > 10 ☒ Mature (>30)

## Aquatic/Instream Vegetation

Type (Table 8) 2 Coverage of Reach (%) 10  
 Woody Debris Density of WD:  
☒ Present in Cutbank ☐ Low WDJ/50m:  
☒ Present in Channel ☒ Moderate 2  
☐ Not Present ☐ High

## Water Quality

Odour (Table 16)

1

Turbidity (Table 17)

1

## Channel Characteristics

Sinuosity (Type)	Sinuosity (Degree)	Gradient	Number of Channels	Clay/Silt	Sand	Gravel	Cobble	Boulder	Parent	Rootlets
(Table 9) <u>2</u>	(Table 10) <u>2</u>	(Table 11) <u>2</u>	(Table 12) <u>1</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Entrenchment	Type of Bank Failure	Downs's Classification	Pool Substrate	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
(Table 13) <u>1</u>	(Table 14) <u>2</u>	(Table 15) <u>d</u>	Bank Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Bankfull Width (m)	<u>5.4</u>	<u>3.8</u>	<u>4.0</u>	Wetted Width (m)	<u>2.80</u>	<u>2.5</u>	<u>2.13</u>	Bank Angle	Bank Erosion	
Bankfull Depth (m)	<u>1.25</u>	<u>0.52</u>	<u>0.60</u>	Wetted Depth (m)	<u>0.60</u>	<u>0.11</u>	<u>0.19</u>	<input type="checkbox"/> 0-30	<input type="checkbox"/> < 5%	
Riffle/Pool Spacing (m)	<u>20-30</u>	% Riffles: <u>70</u>	% Pools: <u>30</u>	Meander Amplitude: <u>15</u>	<input checked="" type="checkbox"/> 30-60	<input checked="" type="checkbox"/> 5-30%	<input checked="" type="checkbox"/> 60-90	<input checked="" type="checkbox"/> 30-60%	<input type="checkbox"/> 60-100%	
Pool Depth (m)		Riffle Length (m) <u>15.70</u>	Undercuts (m) <u>0.50</u>	Comments:	<input checked="" type="checkbox"/> Undercut					
Velocity (m/s)			Wiffle ball / ADV / Estimated							

Notes:

Completed by: ER

Checked by: \_\_\_\_\_

## Rapid Geomorphic Assessment

Project Code/Phase: PIN 16059

Date:	July 5, 2016	Stream/Reach:	Reach 3
Weather:	Sun/clouds 33°C	Location:	Feedmill Creek
Field Staff:	AD, ER	Watershed/Subwatershed:	Carp River

Process	Geomorphic Indicator		Present?		Factor Value
	No.	Description	Yes	No	
Evidence of Aggradation (AI)	1	Lobate bar		✓	3/7
	2	Coarse materials in riffles embedded		✓	
	3	Siltation in pools	✓		
	4	Medial bars		✓	
	5	Accretion on point bars	✓		
	6	Poor longitudinal sorting of bed materials		✓	
	7	Deposition in the overbank zone	✓		
Sum of indices =			3	4	0.43

Evidence of Degradation (DI)	1	Exposed bridge footing(s)	N	A	2/6
	2	Exposed sanitary / storm sewer / pipeline / etc.	N	A	
	3	Elevated storm sewer outfall(s)	N	A	
	4	Undermined gabion baskets / concrete aprons / etc.	N	A	
	5	Scour pools downstream of culverts / storm sewer outlets		✓	
	6	Cut face on bar forms	✓		
	7	Head cutting due to knick point migration		✓	
	8	Terrace cut through older bar material		✓	
	9	Suspended armour layer visible in bank		✓	
	10	Channel worn into undisturbed overburden / bedrock	✓		
Sum of indices =			2	4	0.33

Evidence of Widening (WI)	1	Fallen / leaning trees / fence posts / etc.	✓		3/7
	2	Occurrence of large organic debris	✓		
	3	Exposed tree roots	✓		
	4	Basal scour on inside meander bends		✓	
	5	Basal scour on both sides of channel through riffle		✓	
	6	Outflanked gabion baskets / concrete walls / etc.	N/A		
	7	Length of basal scour >50% through subject reach		✓	
	8	Exposed length of previously buried pipe / cable / etc.	N/A		
	9	Fracture lines along top of bank		✓	
	10	Exposed building foundation	N/A		
Sum of indices =			3	4	0.43

Evidence of Planimetric Form Adjustment (PI)	1	Formation of chute(s)		✓	0
	2	Single thread channel to multiple channel		✓	
	3	Evolution of pool-riffle form to low bed relief form		✓	
	4	Cut-off channel(s)		✓	
	5	Formation of island(s)		✓	
	6	Thalweg alignment out of phase meander form		✓	
	7	Bar forms poorly formed / reworked / removed		✓	
Sum of indices =			0	7	0

Additional notes:

Stability Index (SI) = (AI+DI+WI+PI)/4 = 0.30

Condition	In Regime	In Transition/Stress	In Adjustment
SI score =	<input type="checkbox"/> 0.00 - 0.20	<input checked="" type="checkbox"/> 0.21 - 0.40	<input type="checkbox"/> 0.41

Completed by: AD/ER Checked by: \_\_\_\_\_



# Rapid Stream Assessment Technique

Project Number:

PN 16059

Date:	July 5, 2016	Stream/Reach:	Reach 3
Weather:	Sun/clouds 33°C	Location:	Feedmill Creek
Field Staff:	ADER	Watershed/Subwatershed:	Carp River

Evaluation Category	Poor	Fair	Good	Excellent
Channel Stability	<ul style="list-style-type: none"> <li>&lt; 50% of bank network stable</li> <li>Recent bank sloughing, slumping or failure frequently observed</li> </ul>	<ul style="list-style-type: none"> <li>50-70% of bank network stable</li> <li>Recent signs of bank sloughing, slumping or failure fairly common</li> </ul>	<ul style="list-style-type: none"> <li>71-80% of bank network stable</li> <li>Infrequent signs of bank sloughing, slumping or failure</li> </ul>	<ul style="list-style-type: none"> <li>&gt; 80% of bank network stable</li> <li>No evidence of bank sloughing, slumping or failure</li> </ul>
	<ul style="list-style-type: none"> <li>Stream bend areas highly unstable</li> <li>Outer bank height 1.2 m above stream bank (2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang &gt; 0.8-1.0 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas unstable</li> <li>Outer bank height 0.9-1.2 m above stream bank (1.5-2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.8-0.9 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas stable</li> <li>Outer bank height 0.6-0.9 m above stream bank (1.2-1.5 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.6-0.8 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas very stable</li> <li>Height &lt; 0.6 m above stream (&lt; 1.2 m above stream bank for large mainstem areas)</li> <li>Bank overhang &lt; 0.6 m</li> </ul>
	<ul style="list-style-type: none"> <li>Young exposed tree roots abundant</li> <li>&gt; 6 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Young exposed tree roots common</li> <li>4-5 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots predominantly old and large, smaller young roots scarce</li> <li>2-3 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots old, large and woody</li> <li>Generally 0-1 recent large tree falls per stream mile</li> </ul>
	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is highly erodible material</li> <li>Plant/soil matrix severely compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly erodible material</li> <li>Plant/soil matrix compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>
	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8	<input checked="" type="checkbox"/> 9 <input type="checkbox"/> 10 <input type="checkbox"/> 11

Channel Scouring/ Sediment Deposition	<ul style="list-style-type: none"> <li>&gt; 75% embedded (&gt; 85% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>50-75% embedded (60-85% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>25-49% embedded (35-59% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Riffle embeddedness &lt; 25% sand-silt (&lt; 35% embedded for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Few, if any, deep pools</li> <li>Pool substrate composition: &gt; 81% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Low to moderate number of deep pools</li> <li>Pool substrate composition: 60-80% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Moderate number of deep pools</li> <li>Pool substrate composition: 30-59% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>High number of deep pools (&gt; 61 cm deep) (&gt; 122 cm deep for large mainstem areas)</li> <li>Pool substrate composition: &lt; 30% sand-silt</li> </ul>
	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits uncommon</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits absent</li> </ul>
	<ul style="list-style-type: none"> <li>Fresh, large sand deposits very common in channel</li> <li>Moderate to heavy sand deposition along major portion of overbank area</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits common in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits uncommon in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits rare or absent from channel</li> <li>No evidence of fresh sediment deposition on overbank</li> </ul>
	<ul style="list-style-type: none"> <li>Point bars present at most stream bends, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars common, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars few, small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input checked="" type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8



Evaluation Category	Poor	Fair	Good	Excellent
Physical Instream Habitat	<ul style="list-style-type: none"> <li>Wetted perimeter &lt; 40% of bottom channel width (&lt; 45% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 40-60% of bottom channel width (45-65% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 61-85% of bottom channel width (66-90% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter &gt; 85% of bottom channel width (&gt; 90% for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Dominated by one habitat type (usually runs) and by one velocity and depth condition (slow and shallow) (for large mainstem areas, few riffles present, runs and pools dominant, velocity and depth diversity low)</li> </ul>	<ul style="list-style-type: none"> <li>Few pools present, riffles and runs dominant. velocity and depth generally slow and shallow (for large mainstem areas, runs and pools dominant, velocity and depth diversity intermediate)</li> </ul>	<ul style="list-style-type: none"> <li>Good mix between riffles runs and pools</li> <li>Relatively diverse velocity and depth of flow</li> </ul>	<ul style="list-style-type: none"> <li>Riffles, runs and pool habitat present</li> <li>Diverse velocity and depth of flow present (i.e., slow, fast, shallow and deep water)</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly gravel with high percentage of sand</li> <li>&lt; 5% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly small cobble, gravel and sand</li> <li>5-24% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: good mix of gravel, cobble and rubble material</li> <li>25-49% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: cobble, gravel, rubble, boulder mix with little sand</li> <li>&gt; 50% cobble</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle depth &lt; 10 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 10-15 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 15-20 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth &gt; 20 cm for large mainstem areas</li> </ul>
	<ul style="list-style-type: none"> <li>Large pools generally &lt; 30 cm deep (&lt; 61 cm for large mainstem areas) and devoid of overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 30-46 cm deep (61-91 cm for large mainstem areas) with little or no overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 46-61 cm deep (91-122 cm for large mainstem areas) with some overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally &gt; 61 cm deep (&gt; 122 cm for large mainstem areas) with good overhead cover/structure</li> </ul>
	<ul style="list-style-type: none"> <li>Extensive channel alteration and/or point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Moderate amount of channel alteration and/or moderate increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Slight amount of channel alteration and/or slight increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>No channel alteration or significant point bar formation/enlargement</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.49:1 \leq ; \geq 1.51:1</math></li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.5-0.69:1; 1.31-1.5:1</math></li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.7-0.89:1; 1.11-1.3:1</math></li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.9-1.1:1</math></li> </ul>
	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &gt; 27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 24-27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 20-24°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &lt; 20°C</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input checked="" type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8

Water Quality	<ul style="list-style-type: none"> <li>Substrate fouling level: High (&gt; 50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Moderate (21-50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Very light (11-20%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Rock underside (0-10%)</li> </ul>
	<ul style="list-style-type: none"> <li>Brown colour</li> <li>TDS: &gt; 150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Grey colour</li> <li>TDS: 101-150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Slightly grey colour</li> <li>TDS: 50-100 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Clear flow</li> <li>TDS: &lt; 50 mg/L</li> </ul>
	<ul style="list-style-type: none"> <li>Objects visible to depth &lt; 0.15 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.15-0.5 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.5-1.0 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth &gt; 1.0 m below surface</li> </ul>
	<ul style="list-style-type: none"> <li>Moderate to strong organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight to moderate organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight organic odour</li> </ul>	<ul style="list-style-type: none"> <li>No odour</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input checked="" type="checkbox"/> 8

Riparian Habitat Conditions	<ul style="list-style-type: none"> <li>Narrow riparian area of mostly non-woody vegetation</li> </ul>	<ul style="list-style-type: none"> <li>Riparian area predominantly wooded but with major localized gaps</li> </ul>	<ul style="list-style-type: none"> <li>Forested buffer generally &gt; 31 m wide along major portion of both banks</li> </ul>	<ul style="list-style-type: none"> <li>Wide (&gt; 60 m) mature forested buffer along both banks</li> </ul>
	<ul style="list-style-type: none"> <li>Canopy coverage: &lt; 50% shading (30% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 50-60% shading (30-44% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 60-79% shading (45-59% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: &gt; 80% shading (&gt; 60% for large mainstem areas)</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1	<input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> 4 <input type="checkbox"/> 5	<input checked="" type="checkbox"/> 6 <input type="checkbox"/> 7

Additional notes:

Total overall score (0 - 42) = 34

Ranking	Poor (<13)	Fair (13-24)	Good (25-34)	Excellent (>35)
			34	

Completed by: AD/ER Checked by: \_\_\_\_\_

# General Site Characteristics

Project Code/Phase: PN 16059

Date:	July 5 2016	Stream/Reach:	Reach 4
Weather:	Sun/clouds 33°C	Location:	Feedmill Creek
Field Staff:	AD ER	Watershed/Subwatershed:	Carp River

## Features

- Reach break
- x—x Cross-section
- Flow direction
- ~ Riffle
- Pool
- ▨ Island/bar
- ||||| Eroded bank
- Undercut bank
- XXXXXX Rip rap/stabilization
- Instream log/tree
- x—x—x Fence
- Culvert
- ▨ Swamp
- ▽▽▽ Grasses
- Tree

## Flow Type

- H1 Standing water
- H2 Scarcely perceptible flow
- H3 Smooth surface flow
- H4 Upwelling
- H5 Rippled
- H6 Unbroken standing wave
- H7 Broken standing wave
- H8 Chute
- H9 Free fall


## Substrate

- S1 Silt
- S2 Sand
- S3 Gravel
- S4 Small cobble
- S5 Large cobble
- S6 Small boulder
- S7 Large boulder
- S8 Bimodal
- S9 Bedrock/till

## Other

- |                  |                         |
|------------------|-------------------------|
| BM Benchmark     | TR Terrace              |
| FC Flood chute   | BOS Bottom of slope     |
| FP Floodplain    | TOS Top of slope        |
| GC Grade control | VWC Valley wall contact |
| KP Knick point   | WDJ Woody debris jam    |

## Site Sketch:



Additional notes: Tributary almost dry (source cut off)

Floodplain occupied by grasses, few shrubs and dead trees - Former Beaver dam @ d/s end of reach likely cause. Cedar forest d/s of reach and outside FP. WS extent not observed.

GEO MORPHIX  
Geomorphology  
Earth Science  
Observations

Completed by: AD Checked by: \_\_\_\_\_



## Reach Characteristics

Project Code/Phase: PN 16059

Date:	June 5, 2016	Stream/Reach:	Reach 4
Weather:	Sun/clouds 33°C	Location:	Feedmill Creek
Field staff:	AD/ER	Watershed/Subwatershed:	Carp River
UTM (Upstream)	425995.12mE, 5015614.83mN	UTM (Downstream)	426100.42mE, 5015886.35mN

Land Use (Table 1) ☐ 1/4 Valley Type (Table 2) ☐ 1 Channel Type (Table 3) ☐ 12 Channel Zone (Table 4) ☐ 2 Flow Type (Table 5) ☐ 1 ☐ Groundwater Evidence: \_\_\_\_\_

<b>Riparian Vegetation</b> Dominant Type: (Table 6) <input type="checkbox"/> 3 Coverage: <input type="checkbox"/> None <input type="checkbox"/> 1-4 <input checked="" type="checkbox"/> Immature (<5) (Table 7) Species: <input type="checkbox"/> Fragmented <input checked="" type="checkbox"/> 4-10 <input type="checkbox"/> Established (5-30) <input type="checkbox"/> Mature (>30) <input type="checkbox"/> 2 Encroachment: <input type="checkbox"/> Continuous <input type="checkbox"/> > 10 dead trees - none alive		<b>Aquatic/Instream Vegetation</b> Type (Table 8) <input type="checkbox"/> 2 Coverage of Reach (%) <input type="checkbox"/> 5 Woody Debris Density of WD: <input checked="" type="checkbox"/> Present in Cutbank <input type="checkbox"/> Low WDJ/50m: <input checked="" type="checkbox"/> Present in Channel <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> 2 <input type="checkbox"/> Not Present <input type="checkbox"/> High		<b>Water Quality</b> Odour (Table 16) <input type="checkbox"/> 1 Turbidity (Table 17) <input type="checkbox"/> 1
--	--	---	--	--

<b>Channel Characteristics</b>											
Sinuosity (Type) (Table 9) <input type="checkbox"/> 1	Sinuosity (Degree) (Table 10) <input type="checkbox"/> 2	Gradient (Table 11) <input type="checkbox"/> 1/2	Number of Channels (Table 12) <input type="checkbox"/> 1	Clay/Silt <input checked="" type="checkbox"/>	Sand <input type="checkbox"/>	Gravel <input type="checkbox"/>	Cobble <input type="checkbox"/>	Boulder <input type="checkbox"/>	Parent <input type="checkbox"/>	Rootlets <input type="checkbox"/>	
Entrenchment (Table 13) <input type="checkbox"/> 1	Type of Bank Failure (Table 14) <input type="checkbox"/> 2	Downs's Classification (Table 15) <input type="checkbox"/> d	Riffle Substrate <input checked="" type="checkbox"/>	Pool Substrate <input checked="" type="checkbox"/>	Bank Material <input checked="" type="checkbox"/>						
Bankfull Width (m) <input type="checkbox"/> 2.35 <input type="checkbox"/> 2.10	Wetted Width (m) <input type="checkbox"/> 1.70 <input type="checkbox"/> 1.78	Bank Angle <input type="checkbox"/> 0-30 <input type="checkbox"/> 30-60 <input checked="" type="checkbox"/> 60-90 <input checked="" type="checkbox"/> Undercut	Bank Erosion <input type="checkbox"/> <5% <input checked="" type="checkbox"/> 5-30% <input type="checkbox"/> 30-60% <input type="checkbox"/> 60-100%								
Bankfull Depth (m) <input type="checkbox"/> 0.33 <input type="checkbox"/> 0.92	Wetted Depth (m) <input type="checkbox"/> 0.29 <input type="checkbox"/> 0.18	Riffle/Pool Spacing (m) <input type="checkbox"/>	% Riffles: <input type="checkbox"/> 10 % Pools: <input type="checkbox"/> 90 Meander Amplitude: <input type="checkbox"/>								
Pool Depth (m) <input type="checkbox"/>	Riffle Length (m) <input type="checkbox"/> 4 Undercuts (m) <input type="checkbox"/> 6.05 <input type="checkbox"/> 0.24	Velocity (m/s) <input type="checkbox"/>	Wiffle ball / ADV / Estimated <input type="checkbox"/>								
Comments: beaver chewed wood geomorph units not as present											
Notes: Stream flowing											

Completed by: ER Checked by: \_\_\_\_\_



## Rapid Geomorphic Assessment

Project Code/Phase: AV16059

Date:	July 5, 2016	Stream/Reach:	Reach 4
Weather:	Sun/clouds 33°C	Location:	Feedmill Creek
Field Staff:	AD, ER	Watershed/Subwatershed:	Carp River

Process	Geomorphic Indicator		Present?		Factor Value
	No.	Description	Yes	No	
Evidence of Aggradation (AI)	1	Lobate bar		✓	2/6
	2	Coarse materials in riffles embedded		N/A	
	3	Siltation in pools	✓		
	4	Medial bars		✓	
	5	Accretion on point bars		✓	
	6	Poor longitudinal sorting of bed materials	✓		
	7	Deposition in the overbank zone		✓	
Sum of indices =			2	4	0.33

Evidence of Degradation (DI)	1	Exposed bridge footing(s)		N/A	9.5
	2	Exposed sanitary / storm sewer / pipeline / etc.		N/A	
	3	Elevated storm sewer outfall(s)		N/A	
	4	Undermined gabion baskets / concrete aprons / etc.		N/A	
	5	Scour pools downstream of culverts / storm sewer outlets		N/A	
	6	Cut face on bar forms		✓	
	7	Head cutting due to knick point migration		✓	
	8	Terrace cut through older bar material		✓	
	9	Suspended armour layer visible in bank		✓	
	10	Channel worn into undisturbed overburden / bedrock		✓	
Sum of indices =			0	5	0

Evidence of Widening (WI)	1	Fallen / leaning trees / fence posts / etc.	✓		3/4
	2	Occurrence of large organic debris	✓		
	3	Exposed tree roots	✓		
	4	Basal scour on inside meander bends		✓	
	5	Basal scour on both sides of channel through riffle		✓	
	6	Outflanked gabion baskets / concrete walls / etc.		N/A	
	7	Length of basal scour >50% through subject reach		✓	
	8	Exposed length of previously buried pipe / cable / etc.		N/A	
	9	Fracture lines along top of bank		✓	
	10	Exposed building foundation		N/A	
Sum of indices =			3	4	0.43

Evidence of Planimetric Form Adjustment (PI)	1	Formation of chute(s)		✓	0/7
	2	Single thread channel to multiple channel		✓	
	3	Evolution of pool-riffle form to low bed relief form		✓	
	4	Cut-off channel(s)		✓	
	5	Formation of island(s)		✓	
	6	Thalweg alignment out of phase meander form		✓	
	7	Bar forms poorly formed / reworked / removed		✓	
Sum of indices =			0	7	0

Additional notes:

Stability Index (SI) = (AI+DI+WI+PI)/4 = 0.19

Condition	In Regime	In Transition/Stress	In Adjustment
SI score =	<input checked="" type="checkbox"/> 0.00 - 0.20	<input type="checkbox"/> 0.21 - 0.40	<input type="checkbox"/> 0.41

Completed by: AD/ER Checked by: \_\_\_\_\_

# Rapid Stream Assessment Technique

Project Number: PN 16059

Date: July 5, 2016	Stream/Reach: Reach 4
Weather: Sun/clouds 33°C	Location: Feedmill Creek
Field Staff: AD, ER	Watershed/Subwatershed: Camp River

Evaluation Category	Poor	Fair	Good	Excellent
Channel Stability	<ul style="list-style-type: none"> <li>&lt; 50% of bank network stable</li> <li>Recent bank sloughing, slumping or failure frequently observed</li> </ul>	<ul style="list-style-type: none"> <li>50-70% of bank network stable</li> <li>Recent signs of bank sloughing, slumping or failure fairly common</li> </ul>	<ul style="list-style-type: none"> <li>71-80% of bank network stable</li> <li>Infrequent signs of bank sloughing, slumping or failure</li> </ul>	<ul style="list-style-type: none"> <li>&gt; 80% of bank network stable</li> <li>No evidence of bank sloughing, slumping or failure</li> </ul>
	<ul style="list-style-type: none"> <li>Stream bend areas highly unstable</li> <li>Outer bank height 1.2 m above stream bank (2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang &gt; 0.8-1.0 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas unstable</li> <li>Outer bank height 0.9-1.2 m above stream bank (1.5-2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.8-0.9 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas stable</li> <li>Outer bank height 0.6-0.9 m above stream bank (1.2-1.5 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.6-0.8 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas very stable</li> <li>Height &lt; 0.6 m above stream (&lt; 1.2 m above stream bank for large mainstem areas)</li> <li>Bank overhang &lt; 0.6 m</li> </ul>
	<ul style="list-style-type: none"> <li>Young exposed tree roots abundant</li> <li>&gt; 6 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Young exposed tree roots common</li> <li>4-5 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots predominantly old and large, smaller young roots scarce</li> <li>2-3 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots old, large and woody</li> <li>Generally 0-1 recent large tree falls per stream mile</li> </ul>
	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is highly erodible material</li> <li>Plant/soil matrix severely compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly erodible material</li> <li>Plant/soil matrix compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>
	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8	<input type="checkbox"/> 9 <input checked="" type="checkbox"/> 10 <input type="checkbox"/> 11

Channel Scouring/ Sediment Deposition	<ul style="list-style-type: none"> <li>&gt; 75% embedded (&gt; 85% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>50-75% embedded (60-85% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>25-49% embedded (35-59% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Riffle embeddedness &lt; 25% sand-silt (&lt; 35% embedded for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Few, if any, deep pools</li> <li>Pool substrate composition: &gt; 81% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Low to moderate number of deep pools</li> <li>Pool substrate composition: 60-80% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Moderate number of deep pools</li> <li>Pool substrate composition: 30-59% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>High number of deep pools (&gt; 61 cm deep) (&gt; 122 cm deep for large mainstem areas)</li> <li>Pool substrate composition: &lt; 30% sand-silt</li> </ul>
	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits uncommon</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits absent</li> </ul>
	<ul style="list-style-type: none"> <li>Fresh, large sand deposits very common in channel</li> <li>Moderate to heavy sand deposition along major portion of overbank area</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits common in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits uncommon in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits rare or absent from channel</li> <li>No evidence of fresh sediment deposition on overbank</li> </ul>
	<ul style="list-style-type: none"> <li>Point bars present at most stream bends, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars common, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars few, small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input checked="" type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8



Evaluation Category	Poor	Fair	Good	Excellent
Physical Instream Habitat	<ul style="list-style-type: none"> <li>Wetted perimeter &lt; 40% of bottom channel width (&lt; 45% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 40-60% of bottom channel width (45-65% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 61-85% of bottom channel width (66-90% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter &gt; 85% of bottom channel width (&gt; 90% for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Dominated by one habitat type (usually runs) and by one velocity and depth condition (slow and shallow) (for large mainstem areas, few riffles present, runs and pools dominant, velocity and depth diversity low)</li> </ul>	<ul style="list-style-type: none"> <li>Few pools present, riffles and runs dominant, velocity and depth generally slow and shallow (for large mainstem areas, runs and pools dominant, velocity and depth diversity intermediate)</li> </ul>	<ul style="list-style-type: none"> <li>Good mix between riffles, runs and pools</li> <li>Relatively diverse velocity and depth of flow</li> </ul>	<ul style="list-style-type: none"> <li>Riffles, runs and pool habitat present</li> <li>Diverse velocity and depth of flow present (i.e., slow, fast, shallow and deep water)</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly gravel with high percentage of sand &lt; 5% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly small cobble, gravel and sand</li> <li>5-24% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: good mix of gravel, cobble, and rubble material</li> <li>25-49% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: cobble, gravel, rubble, boulder mix with little sand</li> <li>&gt; 50% cobble</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle depth &lt; 10 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 10-15 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 15-20 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth &gt; 20 cm for large mainstem areas</li> </ul>
	<ul style="list-style-type: none"> <li>Large pools generally &lt; 30 cm deep (&lt; 61 cm for large mainstem areas) and devoid of overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 30-46 cm deep (61-91 cm for large mainstem areas) with little or no overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 46-61 cm deep (91-122 cm for large mainstem areas) with some overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally &gt; 61 cm deep (&gt; 122 cm for large mainstem areas) with good overhead cover/structure</li> </ul>
	<ul style="list-style-type: none"> <li>Extensive channel alteration and/or point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Moderate amount of channel alteration and/or moderate increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Slight amount of channel alteration and/or slight increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>No channel alteration or significant point bar formation/enlargement</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.49:1 \leq</math>; <math>\geq 1.51:1</math></li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.5-0.69:1</math>; <math>1.31-1.5:1</math></li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.7-0.89:1</math>; <math>1.11-1.3:1</math></li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.9-1.1:1</math></li> </ul>
	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &gt; 27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 24-27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 20-24°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &lt; 20°C</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input checked="" type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8

Water Quality	<ul style="list-style-type: none"> <li>Substrate fouling level: High (&gt; 50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Moderate (21-50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Very light (11-20%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Rock underside (0-10%)</li> </ul>
	<ul style="list-style-type: none"> <li>Brown colour</li> <li>TDS: &gt; 150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Grey colour</li> <li>TDS: 101-150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Slightly grey colour</li> <li>TDS: 50-100 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Clear flow</li> <li>TDS: &lt; 50 mg/L</li> </ul>
	<ul style="list-style-type: none"> <li>Objects visible to depth &lt; 0.15 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.15-0.5 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.5-1.0 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth &gt; 1.0 m below surface</li> </ul>
	<ul style="list-style-type: none"> <li>Moderate to strong organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight to moderate organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight organic odour</li> </ul>	<ul style="list-style-type: none"> <li>No odour</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input checked="" type="checkbox"/> 8

Riparian Habitat Conditions	<ul style="list-style-type: none"> <li>Narrow riparian area of mostly non-woody vegetation</li> </ul>	<ul style="list-style-type: none"> <li>Riparian area predominantly wooded but with major localized gaps</li> </ul>	<ul style="list-style-type: none"> <li>Forested buffer generally &gt; 31 m wide along major portion of both banks</li> </ul>	<ul style="list-style-type: none"> <li>Wide (&gt; 60 m) mature forested buffer along both banks</li> </ul>
	<ul style="list-style-type: none"> <li>Canopy coverage: &lt; 50% shading (30% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 50-60% shading (30-44% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 60-79% shading (45-59% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: &gt; 80% shading (&gt; 60% for large mainstem areas)</li> </ul>
Point range	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7

Additional notes:

Total overall score (0-42) = 27

Ranking	Poor (<13)	Fair (13-24)	Good (25-34)	Excellent (>35)
			27	

Completed by: AD/ER Checked by: \_\_\_\_\_

Evaluation Category	Poor	Fair	Good	Excellent
Physical Instream Habitat	<ul style="list-style-type: none"> <li>Wetted perimeter &lt; 40% of bottom channel width (&lt; 45% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 40-60% of bottom channel width (45-65% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 61-85% of bottom channel width (66-90% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter &gt; 85% of bottom channel width (&gt; 90% for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Dominated by one habitat type (usually runs) and by one velocity and depth condition (slow and shallow) (for large mainstem areas, few riffles present, runs and pools dominant, velocity and depth diversity low)</li> </ul>	<ul style="list-style-type: none"> <li>Few pools present, riffles and runs dominant, velocity and depth generally slow and shallow (for large mainstem areas, runs and pools dominant, velocity and depth diversity intermediate)</li> </ul>	<ul style="list-style-type: none"> <li>Good mix between riffles, runs and pools</li> <li>Relatively diverse velocity and depth of flow</li> </ul>	<ul style="list-style-type: none"> <li>Riffles, runs and pool habitat present</li> <li>Diverse velocity and depth of flow present (i.e., slow, fast, shallow and deep water)</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly gravel with high percentage of sand &lt; 5% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly small cobble, gravel and sand</li> <li>5-24% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: good mix of gravel, cobble, and rubble material</li> <li>25-49% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: cobble, gravel, rubble, boulder mix with little sand</li> <li>&gt; 50% cobble</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle depth &lt; 10 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 10-15 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 15-20 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth &gt; 20 cm for large mainstem areas</li> </ul>
	<ul style="list-style-type: none"> <li>Large pools generally &lt; 30 cm deep (&lt; 61 cm for large mainstem areas) and devoid of overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 30-46 cm deep (61-91 cm for large mainstem areas) with little or no overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 46-61 cm deep (91-122 cm for large mainstem areas) with some overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally &gt; 61 cm deep (&gt; 122 cm for large mainstem areas) with good overhead cover/structure</li> </ul>
	<ul style="list-style-type: none"> <li>Extensive channel alteration and/or point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Moderate amount of channel alteration and/or moderate increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Slight amount of channel alteration and/or slight increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>No channel alteration or significant point bar formation/enlargement</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.49:1 ≤ ; ≥ 1.51:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.5-0.69:1; 1.31-1.5:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.7-0.89:1; 1.11-1.3:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.9-1.1:1</li> </ul>
	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &gt; 27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 24-27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 20-24°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &lt; 20°C</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input checked="" type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8

Water Quality	<ul style="list-style-type: none"> <li>Substrate fouling level: High (&gt; 50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Moderate (21-50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Very light (11-20%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Rock underside (0-10%)</li> </ul>
	<ul style="list-style-type: none"> <li>Brown colour</li> <li>TDS: &gt; 150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Grey colour</li> <li>TDS: 101-150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Slightly grey colour</li> <li>TDS: 50-100 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Clear flow</li> <li>TDS: &lt; 50 mg/L</li> </ul>
	<ul style="list-style-type: none"> <li>Objects visible to depth &lt; 0.15 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.15-0.5 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.5-1.0 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth &gt; 1.0 m below surface</li> </ul>
	<ul style="list-style-type: none"> <li>Moderate to strong organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight to moderate organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight organic odour</li> </ul>	<ul style="list-style-type: none"> <li>No odour</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input checked="" type="checkbox"/> 8

Riparian Habitat Conditions	<ul style="list-style-type: none"> <li>Narrow riparian area of mostly non-woody vegetation</li> </ul>	<ul style="list-style-type: none"> <li>Riparian area predominantly wooded but with major localized gaps</li> </ul>	<ul style="list-style-type: none"> <li>Forested buffer generally &gt; 31 m wide along major portion of both banks</li> </ul>	<ul style="list-style-type: none"> <li>Wide (&gt; 60 m) mature forested buffer along both banks</li> </ul>
	<ul style="list-style-type: none"> <li>Canopy coverage: &lt; 50% shading (30% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 50-60% shading (30-44% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 60-79% shading (45-59% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: &gt; 80% shading (&gt; 60% for large mainstem areas)</li> </ul>
Point range	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7

Additional notes:	Total overall score (0-42) = 27			
	Ranking	Poor (<13)	Fair (13-24)	Good (25-34)
				27

Completed by: AD/ER Checked by: \_\_\_\_\_



# General Site Characteristics

Project Code/Phase: PN16059

Date:	July 5, 2016	Stream/Reach:	Reach 5
Weather:	Sunny 33°C	Location:	Feedmill Creek
Field Staff:	AD, ER	Watershed/Subwatershed:	Carp River

## Features

- Reach break
- × × Cross-section
- Flow direction
- ~ Riffle
- Pool
- ▨ Island/bar
- ▨ Eroded bank
- - - Undercut bank
- XXXXXX Rip rap/stabilization
- Instream log/tree
- × × × × Fence
- Culvert
- ▨ Swamp
- ▽ ▽ ▽ Grasses
- Tree

## Flow Type

- H1 Standing water
- H2 Scarcely perceptible flow
- H3 Smooth surface flow
- H4 Upwelling
- H5 Rippled
- H6 Unbroken standing wave
- H7 Broken standing wave
- H8 Chute
- H9 Free fall


## Substrate

- S1 Silt
- S2 Sand
- S3 Gravel
- S4 Small cobble
- S5 Large cobble
- S6 Small boulder
- S7 Large boulder
- S8 Bimodal
- S9 Bedrock/till

## Other

- |    |               |     |                     |
|----|---------------|-----|---------------------|
| BM | Benchmark     | TR  | Terrace             |
| FC | Flood chute   | BOS | Bottom of slope     |
| FP | Floodplain    | TOS | Top of slope        |
| GC | Grade control | VWC | Valley wall contact |
| KP | Knick point   | WDJ | Woody debris jam    |

## Site Sketch:



Additional notes:

straightened channel  
more encroachment than d/s reaches

GEO MORPHIX  
Geomorphology  
Earth Science  
Observations

Completed by: AD, ER Checked by: \_\_\_\_\_

## Reach Characteristics

Project Code/Phase: pn16059

Date:	<u>July 5, 2016</u>	Stream/Reach:	<u>Reach 5</u>
Weather:	<u>mainly sunny, 33°C</u>	Location:	<u>Feedmill Creek</u>
Field staff:	<u>AD ER</u>	Watershed/Subwatershed:	<u>Carp River</u>
UTM (Upstream)	<u>426383.46mE, 5015021.22mN</u>	UTM (Downstream)	<u>4255980.34mE, 5015484.58mN</u>

Land Use (Table 1) 2/4 Valley Type (Table 2) 1 Channel Type (Table 3) 11 Channel Zone (Table 4) 2 Flow Type (Table 5) 1 ☐ Groundwater Evidence: \_\_\_\_\_

<b>Riparian Vegetation</b> Dominant Type: (Table 6) <u>3</u> Coverage: <input type="checkbox"/> None <input type="checkbox"/> 1-4 <input checked="" type="checkbox"/> Immature (<5) (Table 7) Species: <u>Mixed/unknown</u> <input type="checkbox"/> Fragmented <input checked="" type="checkbox"/> 4-10 <input type="checkbox"/> Established (5-30) <u>2</u> <input checked="" type="checkbox"/> Continuous <input type="checkbox"/> >10 <input type="checkbox"/> Mature (>30)		<b>Aquatic/Instream Vegetation</b> Type (Table 8) <u>2</u> Coverage of Reach (%) <u>50</u> Woody Debris Density of WD: <input type="checkbox"/> Present in Cutbank <input checked="" type="checkbox"/> Low WDJ/50m: <input type="checkbox"/> Present in Channel <input type="checkbox"/> Moderate <u>0</u> <input checked="" type="checkbox"/> Not Present <input type="checkbox"/> High	<b>Water Quality</b> Odour (Table 16) <u>1</u> Turbidity (Table 17) <u>1</u>
--	--	---	--

<b>Channel Characteristics</b> Sinuosity (Type) (Table 9) <u>1</u> Sinuosity (Degree) (Table 10) <u>1</u> Gradient (Table 11) <u>1</u> Number of Channels (Table 12) <u>1</u> <u>RVN</u> Entrenchment (Table 13) <u>1</u> Type of Bank Failure (Table 14) <u>2</u> Downs's Classification (Table 15) <u>d</u> <u>Pool</u> Substrate <input checked="" type="checkbox"/> Riffle Substrate <input checked="" type="checkbox"/> Bankfull Width (m) <u>RVN</u> <u>2.0</u> <u>RVN</u> <u>2.40</u> <u>RVN</u> <u>2.50</u> Wetted Width (m) <u>RVN</u> <u>1.60</u> <u>RVN</u> <u>1.80</u> <u>RVN</u> <u>1.65</u> Bank Angle <input type="checkbox"/> 0-30 <input checked="" type="checkbox"/> <5% Bankfull Depth (m) <u>0.54</u> <u>0.61</u> <u>0.42</u> Wetted Depth (m) <u>0.17</u> <u>0.20</u> <u>0.27</u> <input type="checkbox"/> 30-60 <input type="checkbox"/> 5-30% Riffle/Pool Spacing (m) <u>NA</u> % Riffles: <u>5</u> % Pools: <u>95</u> (Run) Meander Amplitude: <u>0.12</u> <input checked="" type="checkbox"/> 60-90 <input type="checkbox"/> 30-60% Pool Depth (m) <u>0.28</u> Riffle Length (m) <u>0.12</u> Undercuts (m) <u>0.12</u> Comments: <u>-all runs (one small riffle)</u> <input checked="" type="checkbox"/> Undercut <input type="checkbox"/> 60-100% Velocity (m/s) <u>not measured</u> Wiffle ball / ADV / Estimated <u>-embedded</u>												<b>Notes:</b> <u>-straightened</u> <u>-flowing</u>
--	--	--	--	--	--	--	--	--	--	--	--	--

Completed by: ER Checked by: \_\_\_\_\_



## Rapid Geomorphic Assessment

Project Code/Phase: PV 16059

Date:	<u>July 5, 2016</u>	Stream/Reach:	<u>Reach 5</u>
Weather:	<u>mainly sunny 33°C</u>	Location:	<u>Feedmill Creek</u>
Field Staff:	<u>AD, ER</u>	Watershed/Subwatershed:	<u>Carp River</u>

Process	Geomorphic Indicator		Present?		Factor Value
	No.	Description	Yes	No	
Evidence of Aggradation (AI)	1	Lobate bar		✓	4/7
	2	Coarse materials in riffles embedded	✓		
	3	Siltation in pools	✓		
	4	Medial bars		✓	
	5	Accretion on point bars		✓	
	6	Poor longitudinal sorting of bed materials	✓		
	7	Deposition in the overbank zone	✓		
Sum of indices =			4	3	0.57

Evidence of Degradation (DI)	1	Exposed bridge footing(s)		N/A	0/8
	2	Exposed sanitary / storm sewer / pipeline / etc.		✓	
	3	Elevated storm sewer outfall(s)		✓	
	4	Undermined gabion baskets / concrete aprons / etc.		N/A	
	5	Scour pools downstream of culverts / storm sewer outlets		✓	
	6	Cut face on bar forms		✓	
	7	Head cutting due to knick point migration		✓	
	8	Terrace cut through older bar material		✓	
	9	Suspended armour layer visible in bank		✓	
	10	Channel worn into undisturbed overburden / bedrock		✓	
Sum of indices =			0	8	0

Evidence of Widening (WI)	1	Fallen / leaning trees / fence posts / etc.		✓	1/6
	2	Occurrence of large organic debris	✓		
	3	Exposed tree roots		✓	
	4	Basal scour on inside meander bends		✓	
	5	Basal scour on both sides of channel through riffle		✓	
	6	Outflanked gabion baskets / concrete walls / etc.		N/A	
	7	Length of basal scour >50% through subject reach		✓	
	8	Exposed length of previously buried pipe / cable / etc.		N/A	
	9	Fracture lines along top of bank		✓	
	10	Exposed building foundation		N/A	
Sum of indices =			1	6	0.17

Evidence of Planimetric Form Adjustment (PI)	1	Formation of chute(s)		✓	0/7
	2	Single thread channel to multiple channel		✓	
	3	Evolution of pool-riffle form to low bed relief form		✓	
	4	Cut-off channel(s)		✓	
	5	Formation of island(s)		✓	
	6	Thalweg alignment out of phase meander form		✓	
	7	Bar forms poorly formed / reworked / removed		✓	
Sum of indices =			0	7	0

Additional notes:

Stability Index (SI) = (AI+DI+WI+PI)/4 = 0.19

Condition	In Regime	In Transition/Stress	In Adjustment
SI score =	<input checked="" type="checkbox"/> 0.00 - 0.20	<input type="checkbox"/> 0.21 - 0.40	<input type="checkbox"/> 0.41

Completed by: AD/ER Checked by: \_\_\_\_\_

# Rapid Stream Assessment Technique

Project Number:

PN 16059

Date:	July 5 2016	Stream/Reach:	Reach 5
Weather:	Sunny 33°C	Location:	Feedmill Creek
Field Staff:	ADER.	Watershed/Subwatershed:	Carp River

Evaluation Category	Poor	Fair	Good	Excellent
Channel Stability	<ul style="list-style-type: none"> <li>&lt; 50% of bank network stable</li> <li>Recent bank sloughing, slumping or failure frequently observed</li> </ul>	<ul style="list-style-type: none"> <li>50-70% of bank network stable</li> <li>Recent signs of bank sloughing, slumping or failure fairly common</li> </ul>	<ul style="list-style-type: none"> <li>71-80% of bank network stable</li> <li>Infrequent signs of bank sloughing, slumping or failure</li> </ul>	<ul style="list-style-type: none"> <li>&gt; 80% of bank network stable</li> <li>No evidence of bank sloughing, slumping or failure</li> </ul>
	<ul style="list-style-type: none"> <li>Stream bend areas highly unstable</li> <li>Outer bank height 1.2 m above stream bank (2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang &gt; 0.8-1.0 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas unstable</li> <li>Outer bank height 0.9-1.2 m above stream bank (1.5-2.1 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.8-0.9 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas stable</li> <li>Outer bank height 0.6-0.9 m above stream bank (1.2-1.5 m above stream bank for large mainstem areas)</li> <li>Bank overhang 0.6-0.8 m</li> </ul>	<ul style="list-style-type: none"> <li>Stream bend areas very stable</li> <li>Height &lt; 0.6 m above stream (&lt; 1.2 m above stream bank for large mainstem areas)</li> <li>Bank overhang &lt; 0.6 m</li> </ul>
	<ul style="list-style-type: none"> <li>Young exposed tree roots abundant</li> <li>&gt; 6 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Young exposed tree roots common</li> <li>4-5 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots predominantly old and large, smaller young roots scarce</li> <li>2-3 recent large tree falls per stream mile</li> </ul>	<ul style="list-style-type: none"> <li>Exposed tree roots old, large and woody</li> <li>Generally 0-1 recent large tree falls per stream mile</li> </ul>
	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is highly erodible material</li> <li>Plant/soil matrix severely compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly erodible material</li> <li>Plant/soil matrix compromised</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>	<ul style="list-style-type: none"> <li>Bottom 1/3 of bank is generally highly resistant plant/soil matrix or material</li> </ul>
	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally trapezoidally-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>	<ul style="list-style-type: none"> <li>Channel cross-section is generally V- or U-shaped</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8	<input type="checkbox"/> 9 <input checked="" type="checkbox"/> 10 <input type="checkbox"/> 11

Channel Scouring/ Sediment Deposition	<ul style="list-style-type: none"> <li>&gt; 75% embedded (&gt; 85% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>50-75% embedded (60-85% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>25-49% embedded (35-59% embedded for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Riffle embeddedness &lt; 25% sand-silt (&lt; 35% embedded for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Few, if any, deep pools</li> <li>Pool substrate composition: &gt; 81% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Low to moderate number of deep pools</li> <li>Pool substrate composition: 60-80% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>Moderate number of deep pools</li> <li>Pool substrate composition: 30-59% sand-silt</li> </ul>	<ul style="list-style-type: none"> <li>High number of deep pools (&gt; 61 cm deep) (&gt; 122 cm deep for large mainstem areas)</li> <li>Pool substrate composition: &lt; 30% sand-silt</li> </ul>
	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits common</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits uncommon</li> </ul>	<ul style="list-style-type: none"> <li>Streambed streak marks and/or "banana"-shaped sediment deposits absent</li> </ul>
	<ul style="list-style-type: none"> <li>Fresh, large sand deposits very common in channel</li> <li>Moderate to heavy sand deposition along major portion of overbank area</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits common in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits uncommon in channel</li> <li>Small localized areas of fresh sand deposits along top of low banks</li> </ul>	<ul style="list-style-type: none"> <li>Fresh, large sand deposits rare or absent from channel</li> <li>No evidence of fresh sediment deposition on overbank</li> </ul>
	<ul style="list-style-type: none"> <li>Point bars present at most stream bends, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars common, moderate to large and unstable with high amount of fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>	<ul style="list-style-type: none"> <li>Point bars few, small and stable, well-vegetated and/or armoured with little or no fresh sand</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input checked="" type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8



Evaluation Category	Poor	Fair	Good	Excellent
Physical Instream Habitat	<ul style="list-style-type: none"> <li>Wetted perimeter &lt; 40% of bottom channel width (&lt; 45% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 40-60% of bottom channel width (45-65% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter 61-85% of bottom channel width (66-90% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Wetted perimeter &gt; 85% of bottom channel width (&gt; 90% for large mainstem areas)</li> </ul>
	<ul style="list-style-type: none"> <li>Dominated by one habitat type (usually runs) and by one velocity and depth condition (slow and shallow for large mainstem areas, few riffles present, runs and pools dominant, velocity and depth diversity low)</li> </ul>	<ul style="list-style-type: none"> <li>Few pools present, riffles and runs dominant, velocity and depth generally slow and shallow (for large mainstem areas, runs and pools dominant, velocity and depth diversity intermediate)</li> </ul>	<ul style="list-style-type: none"> <li>Good mix between riffles, runs and pools</li> <li>Relatively diverse velocity and depth of flow</li> </ul>	<ul style="list-style-type: none"> <li>Riffles, runs and pool habitat present</li> <li>Diverse velocity and depth of flow present (i.e., slow, fast, shallow and deep water)</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly gravel with high percentage of sand</li> <li>&lt; 5% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: predominantly small cobble, gravel and sand</li> <li>5-24% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: good mix of gravel, cobble, and rubble material</li> <li>25-49% cobble</li> </ul>	<ul style="list-style-type: none"> <li>Riffle substrate composition: cobble, gravel, rubble, boulder mix with little sand</li> <li>&gt; 50% cobble</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle depth &lt; 10 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 10-15 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth 15-20 cm for large mainstem areas</li> </ul>	<ul style="list-style-type: none"> <li>Riffle depth &gt; 20 cm for large mainstem areas</li> </ul>
	<ul style="list-style-type: none"> <li>Large pools generally &lt; 30 cm deep (&lt; 61 cm for large mainstem areas) and devoid of overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 30-46 cm deep (61-91 cm for large mainstem areas) with little or no overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally 46-61 cm deep (91-122 cm for large mainstem areas) with some overhead cover/structure</li> </ul>	<ul style="list-style-type: none"> <li>Large pools generally &gt; 61 cm deep (&gt; 122 cm for large mainstem areas) with good overhead cover/structure</li> </ul>
	<ul style="list-style-type: none"> <li>Extensive channel alteration and/or point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Moderate amount of channel alteration and/or moderate increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>Slight amount of channel alteration and/or slight increase in point bar formation/enlargement</li> </ul>	<ul style="list-style-type: none"> <li>No channel alteration or significant point bar formation/enlargement</li> </ul>
	<ul style="list-style-type: none"> <li>Riffle/Pool ratio <math>0.49:1 \leq</math>; <math>\geq 1.51:1</math></li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.5-0.69:1; 1.31-1.5:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.7-0.89:1; 1.11-1.3:1</li> </ul>	<ul style="list-style-type: none"> <li>Riffle/Pool ratio 0.9-1.1:1</li> </ul>
NA	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &gt; 27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 24-27°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature 20-24°C</li> </ul>	<ul style="list-style-type: none"> <li>Summer afternoon water temperature &lt; 20°C</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input checked="" type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8

Water Quality	<ul style="list-style-type: none"> <li>Substrate fouling level: High (&gt; 50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Moderate (21-50%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Very light (11-20%)</li> </ul>	<ul style="list-style-type: none"> <li>Substrate fouling level: Rock underside (0-10%)</li> </ul>
	<ul style="list-style-type: none"> <li>Brown colour</li> <li>TDS: &gt; 150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Grey colour</li> <li>TDS: 101-150 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Slightly grey colour</li> <li>TDS: 50-100 mg/L</li> </ul>	<ul style="list-style-type: none"> <li>Clear flow</li> <li>TDS: &lt; 50 mg/L</li> </ul>
	<ul style="list-style-type: none"> <li>Objects visible to depth &lt; 0.15 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.15-0.5 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth 0.5-1.0 m below surface</li> </ul>	<ul style="list-style-type: none"> <li>Objects visible to depth &gt; 1.0 m below surface</li> </ul>
	<ul style="list-style-type: none"> <li>Moderate to strong organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight to moderate organic odour</li> </ul>	<ul style="list-style-type: none"> <li>Slight organic odour</li> </ul>	<ul style="list-style-type: none"> <li>No odour</li> </ul>
Point range	<input type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2	<input type="checkbox"/> 3 <input type="checkbox"/> 4	<input type="checkbox"/> 5 <input checked="" type="checkbox"/> 6	<input type="checkbox"/> 7 <input type="checkbox"/> 8

Riparian Habitat Conditions	<ul style="list-style-type: none"> <li>Narrow riparian area of mostly non-woody vegetation</li> </ul>	<ul style="list-style-type: none"> <li>Riparian area predominantly wooded but with major localized gaps</li> </ul>	<ul style="list-style-type: none"> <li>Forested buffer generally &gt; 31 m wide along major portion of both banks</li> </ul>	<ul style="list-style-type: none"> <li>Wide (&gt; 60 m) mature forested buffer along both banks</li> </ul>
	<ul style="list-style-type: none"> <li>Canopy coverage: &lt; 50% shading (30% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 50-60% shading (30-44% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: 60-79% shading (45-59% for large mainstem areas)</li> </ul>	<ul style="list-style-type: none"> <li>Canopy coverage: &gt; 80% shading (&gt; 60% for large mainstem areas)</li> </ul>
Point range	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2 <input type="checkbox"/> 3	<input type="checkbox"/> 4 <input type="checkbox"/> 5	<input type="checkbox"/> 6 <input type="checkbox"/> 7

Additional notes:

Total overall score (0-42) = 23

Ranking	Poor (<13)	Fair (13-24)	Good (25-34)	Excellent (>35)
			23	

Completed by: AD/ER Checked by: \_\_\_\_\_



## **Appendix D**

### **Detailed Assessment Summary**



## Detailed Geomorphological Assessment Summary


<b>Project Number:</b>	PN16059	<b>Date:</b>	July 6, 2016
<b>Client:</b>	DSEL	<b>Length Surveyed (m):</b>	104.1
<b>Location:</b>	Feedmill Creek	<b># of Cross-Sections:</b>	8

Reach Characteristics			
<b>Drainage Area:</b>	Not measured	<b>Dominant Riparian Vegetation Type:</b>	Cedar forest
<b>Geology/Soils:</b>	Glaciolacustrine	<b>Extent of Riparian Cover:</b>	Continuous
<b>Surrounding Land Use:</b>	Industrial/forest	<b>Width of Riparian Cover:</b>	> 10 channel widths
<b>Valley Type:</b>	Partially confined	<b>Age Class of Riparian Vegetation:</b>	Mature (>30 years)
<b>Dominant Instream Vegetation Type:</b>	Rooted submergent	<b>Extent of Encroachment into Channel:</b>	No encroachment
<b>Portion of Reach with Vegetation:</b>	10%	<b>Density of Woody Debris:</b>	Moderate

Hydrology			
<b>Measured Discharge (m<sup>3</sup>/s):</b>	#DIV/0!	<b>Calculated Bankfull Discharge (m<sup>3</sup>/s):</b>	1.64
<b>Modelled 2-year Discharge (m<sup>3</sup>/s):</b>	Not modelled	<b>Calculated Bankfull Velocity (m/s):</b>	1.05
<b>Modelled 2-year Velocity (m/s):</b>	Not modelled		

Profile Characteristics	
<b>Bankfull Gradient (%):</b>	0.33
<b>Channel Bed Gradient (%):</b>	0.17
<b>Riffle Gradient (%):</b>	2.63
<b>Riffle Length (m):</b>	8.13
<b>Riffle-Pool Spacing (m):</b>	17.54

Planform Characteristics	
<b>Sinuosity:</b>	1.83
<b>Meander Belt Width (m):</b>	Not measured
<b>Radius of Curvature (m):</b>	Not measured
<b>Meander Amplitude (m):</b>	Not measured
<b>Meander wavelength (m):</b>	Not measured



Bank Characteristics							
	Minimum	Maximum	Average		Minimum	Maximum	Average
Bank Height (m):	0.25	0.65	0.38				
Bank Angle (deg):	30	90	65	Torvane Value (kg/cm²):		Not measured	
Root Depth (m):	0.05	0.30	0.18	Penetrometer Value (kg/cm³):		Not measured	
Root Density (%):	4	35	17	Bank Material (range):		Clay to sand	
Bank Undercut (m):	0.00	0.28	0.04				


## Cross-Sectional Characteristics

	Minimum	Maximum	Average
Bankfull Width (m):	3.33	4.69	3.79
Average Bankfull Depth (m):	0.32	0.54	0.41
Bankfull Width/Depth (m/m):	6	13	10
Wetted Width (m):	2.05	3.34	2.59
Average Water Depth (m):	0.06	0.32	0.15
Wetted Width/Depth (m/m):	6	52	24
Entrenchment (m):	Not measured		
Entrenchment Ratio (m/m):	Not measured		
Maximum Water Depth (m):	0.08	0.40	0.22
Manning's <i>n</i> :	0.030		



Photograph at cross section 4 (looking downstream)

## Representative Cross-Section # 4



## Substrate Characteristics

### Particle Size (mm)

<b>D<sub>10</sub> :</b>	<2
<b>D<sub>50</sub> :</b>	<2
<b>D<sub>84</sub> :</b>	50.8

### Subpavement:

Gravel, cobble

### Particle shape:

Subangular

### Embeddedness (%):

10 - 100%


### Particle range (riffle):

Sand to cobble

### Particle Range (pool):

Clay to cobble

## Cumulative Particle Size Distribution





Channel Thresholds			
<b>Flow Competency (m/s):</b>		<b>Tractive Force at Bankfull (<math>\text{N/m}^2</math>):</b>	13.24
for $D_{50}$ :	N/A	<b>Tractive Force at 2-year flow (<math>\text{N/m}^2</math>):</b>	Not modelled
for $D_{84}$ :	1.20	<b>Critical Shear Stress (<math>D_{50}</math>) (<math>\text{N/m}^2</math>):</b>	N/A
<b>Unit Stream Power at Bankfull (<math>\text{W/m}^2</math>):</b>			13.96

## General Field Observations

### Channel Description

Reach 3 follows a meandering path within a continuous cedar forest. The reach is partially confined, has a moderate gradient and a meander amplitude of approximately 15 m. Riffles and pools are well-developed. Some riffles within the reach but outside of the surveyed extent were much longer than those surveyed. Bed substrate ranged from clay to large cobbles. Sand deposits were noted on meander bends. Bank angles ranged from 60 to 90° with undercuts up to 0.5 m but typically in the range of 0.20 m. Bank erosion was 30-60%. Most banks were well supported by both fine and large woody root matrix. Woody debris was frequently encountered in the channel.

### Cross Section 6 - Looking Downstream

