

CARLETON CONDOMINIUM PLAN 252  
PIN 1 5 2 5 2 - 0 0 0 1 1 0 - 0 1 0 5



**Notes & Legend**

Symbol	Description
—	Survey Monument Planted
—	Survey Monument Found
—	Standard Iron Bar
—	Short Standard Iron Bar
—	Concrete Pin
—	Iron Bar Found
(WIT)	Witness
—	Maintenance Hole (Storm Sewer)
—	Maintenance Hole (Sanitary)
—	Maintenance Hole (Unidentified)
—	Valve Chamber (Watermain)
—	Underground Storm Sewer
—	Underground Sanitary Sewer
—	Underground Water
—	Catch Basin
—	Ball Terminal Box
—	Cable Terminal Box
—	Sign
—	Light Standard
—	Flag Pole
—	Wooden Retaining Wall
—	Chain Link Fence
—	Diameter
—	Location of Elevations
—	Location of Elevations (Top of Wall)
—	Location of Elevations (Top of Curt)
—	Deciduous Tree
—	Coniferous Tree
—	Fire Hydrant
—	Water Valve
—	Top of Grate
—	Canal
—	Invert
—	Property Line
—	Edge of Asphalt

Bearings are astronomic.

SITE AREA = 29273 m<sup>2</sup>

**ELEVATION NOTES**

- Elevations shown are referred to geoidic datum.
- It is the responsibility of the user of this information to verify that the job benchmark has not been altered or disturbed and that its relative elevation and description agrees with the information shown on this drawing.

**UTILITY NOTES**

- This drawing cannot be accepted as acknowledging all of the utilities and it will be the responsibility of the user to contact the respective utility authorities for confirmation.
- Only visible surface utilities were located.
- A field location of underground plant by the pertinent utility authority is mandatory before any work involving breaking ground, probing, excavating etc.
- Water main and Inverts are taken from Camming-Cocksack Associates Ltd. Drawing No. 3222-102 dated April 1977.