patersongroup

Consulting Engineers

October 25, 2021 File: PE4387-LET.02 154 Colonnade Road South Ottawa, Ontario Canada, K2E 7J5 Tel: (613) 226-7381 Fax: (613) 226-6344

Day & Ross Transportation Group 398 Main Street

Geotechnical Engineering Environmental Engineering Hydrogeology Geological Engineering Materials Testing Building Science

Hartland, New Brunswick E7P 1C6

www.patersongroup.ca

Subject: Response to City Comments

Re: Phase I ESA (Report PE4387-1)

5510 Boundary Road Ottawa, Ontario

Dear Sir/Madame,

Paterson Group (Paterson) has prepared this letter in response to the comment issued by the City of Ottawa (City) regarding the 5494 and 5510 Boundary Road, Ottawa, Ontario. Specifically, the responses addressed herein pertain to the comments about the Phase I Environmental Site Assessment Report (Comments 1 through 16).

Phase I ESA Comments

City Comment 1.

The Executive Summary in the Phase I ESA report refers to a Phase II ESA to confirm a non-APEC. A copy of the report needs to be submitted.

Paterson's Response 1.

Please refer to the attached Phase I ESA revised report (PE4387-1R), for clarification as well as the Phase II ESA/Fill Quality Assessment Report (PE4387-LET.01R)

City Comment 2.

It is not clear why the APEC was reviewed when Table 1 declares that there are no APECs.

Paterson's Response 2.

Please refer to the attached Phase I ESA revised report (PE4387-1R), for clarification regarding the non-APEC.

Ottawa North Bav

It should be noted that the Phase I ESA investigation identified fill material as a PCA. Paterson conducted a subsurface program to assess the quality of fill material, which has been addressed in the Phase II ESA report, appended to this letter.

City Comment 3.

Please change references MOECC to MECP in the reports.

Paterson's Response 3.

Please refer to the attached Phase I ESA revised report (PE4387-1R) and Fill Quality Assessment (PE4387-LET.01R) Reports for the amended changes.

City Comment 4.

An interview with someone familiar with the history of the site is required for Section 5.0.

Paterson's Response 4.

Mr. Michel Pilon (5510 Boundary Road) and Mr. Lesile Kern (5494 Boundary Road) were considered in Section 5.0, based on their knowledge of the Phase I Property. As discussed in the revised Phase I ESA report, the previous landowners (Pomerleau Excavation Ltd. and Mr. Lesile Kern) have owned the property for at least 20 years. The previous landowners (prior to Pomerleau Excavation and Mr. Kern) are not known and as such, any information not discussed in Section 5.0 dating back to 2001 is not available.

City Comment 5.

The comments of the first paragraph below the heading "Site Features" on page 12 require more discussion.

Paterson's Response 5.

Please refer to the attached Phase I ESA Revised (PE4387-1R) for amended changes.

City Comment 6.

The comments of the first paragraph below the heading "7. Land Use History" on page 1 require more discussion.

Paterson's Response 6.

Please refer to the attached Phase I ESA revised report (PE4387-1R) for amended changes.

File: PE4387-LET.02

City Comment 7.

The Phase II ESA is discussed in Section 7.1, page 16, however, it is not provided and as such, it cannot be verified.

Paterson's Response 7.

Please refer to the attached Phase II ESA (PE4387-LET.01).

City Comment 8.

The fill material is Section 7.2 needs to be discussed further.

Paterson's Response 8.

Please refer to the attached Phase I ESA revised report (PE4387-1R) for amended changes as well as the Phase II ESA report.

City Comment 9.

The variety of the independent sources need to be stated at the end of Section 7.2 (page 19) and verified.

Paterson's Response 9.

Please refer to the attached Phase I ESA Revised (PE4387-1R) for amended changes.

City Comment 10.

The statement 'down-gradient,' used variously in the report requires multiple bases to support rational.

Paterson's Response 10.

Based on a "Geological, Hydrogeology and Geotechnical Report, Capital Region Resource Recovery Centre (CRRRC)," prepared by Golder Associates, dated December 2014. The groundwater in the area flows in a northeasterly direction. The topography in the immediate area confirms the groundwater flows in the directions specified above.

City Comment 11.

It is suggested that the septic system be added to the recommendations.

Paterson's Response 11.

The septic system is not relevant to the finding of the Phase I ESA.

File: PE4387-LET.02

City Comment 12.

Photograph 3 (Appendix 1) is of concern.

Paterson's Response 12.

The fill and demolition debris on-site has been discussed and addressed by the subsurface investigation (Phase II ESA) to assess the quality of the fill material. Please refer to the attached Phase II ESA (PE4387-LET.01).

City Comment 13.

Photograph 6 (Appendix 1) is of concern.

Paterson's Response 13.

It is our opinion that the steel remnants are not considered a potential environmental concern to the Phase I Property.

City Comment 14.

Photograph 7 (Appendix 1) is of concern.

Paterson's Response 14.

It is our opinion that the construction waste bin is not considered a potential environmental concern to the Phase I Property.

City Comment 15.

Photograph 12 (Appendix 1) is of concern.

Paterson's Response 15.

It is our opinion that the 2-storey residential dwelling is not considered a potential environmental concern to the Phase I Property.

City Comment 16.

Photograph 14 (Appendix 1) shows a septic system that was not given a condition assessment.

Paterson's Response 16.

The condition of the septic system is not relevant to the findings of the Phase I ESA.

Day & Ross Page 5

File: PE4387-LET.02

We trust this information satisfies your requirements.

Paterson Group Inc.

Mandy Witteman, B.Eng., M.A.Sc.

Mark D'Arcy, P.Eng., QPESA



Attachment:

- ☐ Phase I ESA Report Revised (PE4387-1R)
- ☐ Fill Quality Assessment Report (Phase II ESA)

Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

Materials Testing

Building Science

patersongroup

Phase I Environmental Site Assessment

5494 and 5510 Boundary Road Ottawa, Ontario

Prepared For

Day & Ross

Paterson Group Inc.

Consulting Engineers 154 Colonnade Road South Ottawa (Nepean), Ontario Canada K2E 7J5

Tel: (613) 226-7381 Fax: (613) 226-6344 www.patersongroup.ca October 20, 2021

Report: PE4387-1R



TABLE OF CONTENTS

EXEC	UTIVE	SUMMARY	.ii	
1.0	INTRO	DUCTION	1	
2.0	PHAS	PHASE I PROPERTY INFORMATION2		
3.0	SCOPE OF INVESTIGATION			
4.0	RECO	RDS REVIEW	4	
		General		
Fire Insurance Plans			4	
	4.2	Environmental Source Information	6	
	4.3	Physical Setting Sources	9	
5.0	INTER	VIEWS	1	
6.0	SITE F	RECONNAISSANCE	2	
	6.1	General Requirements	2	
	6.2	Specific Observations at Phase I Property	2	
7.0	REVIE	W AND EVALUATION OF INFORMATION	5	
	7.1	Land Use History´	5	
	7.2	Conceptual Site Model´	7	
8.0		CONCLUSION		
9.0	STATE	EMENT OF LIMITATIONS2	21	
10.0	REFE	RENCES2	22	
Figure Figure Drawi	ing PE₄			
	of Appe ndix 1	Plan of Subdivision Aerial Photographs Site Photographs		
Арреі	ndix 2	MECP Freedom of Information Search MECP Water Well Records TSSA Correspondence TSSA Reports City of Ottawa HLUI Search		

Appendix 3 Qualifications of Assessors



EXECUTIVE SUMMARY

Assessment

A Phase I – Environmental Site Assessment was carried out for the properties addressed 5494 and 5510 Boundary Road, in the City of Ottawa, Ontario. The purpose of this environmental assessment was to research the past and current use of the Phase I Property and Study Area and identify any environmental concerns with the potential to impact the subject property.

Based on a review of available historical sources, the subject site, addressed 5494 Boundary Road was first developed in 1979 with the current homestead. The subject site addressed 5510 Boundary Road was first developed in the early 1960's with what appears be a homestead. However, in the late 1990's the property was redeveloped and stripped of any structures. Based on aerial photographs, sand was excavated from 5510 Boundary Road and subsequently infilled. Paterson completed a fill quality assessment to address fill material on-site. The laboratory results identified PHC and/or PAH impacted fill material on the Phase I Property, which were considered to be the result of asphaltic concrete in the fill. Recommendations have been provided in the Phase II ESA letter report.

Historical research indicates that the surrounding properties, although many still vacant lots, have been used for light to medium industrial purposes with some residential use. Five (5) potentially contaminating activities (PCAs) were identified on the surrounding lands to the east, across Boundary Road. Based on the separation distance and/or orientation (down-gradient) from the subject property, these PCAs are considered to pose very low risk to the Phase I Property, and therefore are not considered to represent APECs.

Following the historical review, a site assessment was conducted for the Phase I Property and surrounding lands. Current use of the subject property and surrounding lands are considered to pose low risk for reasons previously discussed. Based on the above information, it is our opinion that no further work is required for the Phase I Property at this time.

Recommendations

It is expected that the residential dwelling addressed 5494 Boundary Road will be demolished during future site redevelopment.





5494 and 5510 Boundary Road Ottawa, Ontario

In addition, if the domestic well is not to be used in the future then it should be abandoned according to Ontario Regulation 903. Further information can be provided upon request in this regard.



5494 and 5510 Boundary Road Ottawa, Ontario

1.0 INTRODUCTION

At the request of Avenue 31 Capital Inc., acting on behalf of Day & Ross, Paterson Group (Paterson) conducted a Phase I - Environmental Site Assessment (Phase I ESA) for the Phase I Properties addressed 5510 and 5494 Boundary Road, in the City of Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the Phase I Property (5510 and 5494 Boundary Road) and Phase I Study Area and to identify any environmental concerns with the potential to have impacted the subject properties.

Paterson was engaged to conduct this Phase I ESA by Mr. Michel Pilon of Avenue 31 Capital Inc. Mr. Pilon can be reached by telephone at (613) 850-3132.

This report has been prepared specifically and solely for the above noted project which is described herein. It contains all of our findings and results of the environmental conditions at this site.

This Phase I ESA report has been prepared in under the supervision of a Qualified Person (QP_{ESA}), general accordance with the requirements of Ontario Regulation 153/04 as amended by O.Reg. 269/11 (Environmental Protection Act), and also complies with the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.



2.0 PHASE I PROPERTY INFORMATION

Addresses: 5494 Boundary Road and 5510 Boundary Road, in

Ottawa, Ontario.

Legal Description: Part of Lot 1, Concession 9, Ottawa River Front

Gloucester Township, in the City of Ottawa, Ontario.

Property Identification

Number (PIN): 04324-0161, 04324-0177 and 04324-0178

Location: The Phase I Property is situated on the east side of

Boundary Road, just south of Highway 417, in the City of Ottawa, Ontario. Refer to Figure 1 – Key Plan for

the site location.

Latitude and Longitude: 45°20′ 18″ N, 75° 26′ 33.8″ W;

45°20' 24" N, 75° 26' 30" W

Site Description:

Configuration: Rectangular (approximate)

Site Area: 8.45 ha (approximate)

Zoning: RH1 – Rural Heavy Industrial Zone (5510 Boundary

Road)

RU – Rural Countryside Zone (5494 Boundary Road)

Current Use: The parcel of land, addressed 5510 Boundary Road is

undeveloped land that has been used as a fill handling site. The other parcel of land addressed 5494

Boundary Road is used as a residential property.

Services: The Phase I Property is situated in a privately serviced

area.

0, 2021 Page 2



3.0 SCOPE OF INVESTIGATION

e scope of work for this Phase I – Environmental Site Assessment was as ows:
Determine the historical activities on the subject site and study area by conducting a review of readily available records, reports, photographs, plans, mapping, databases and regulatory agencies;
Investigate the existing conditions present at the subject site and study area by conducting site reconnaissance;
Conduct interviews with persons knowledgeable of current and historic operations on the subject property, and if warranted, neighbouring properties;
Present the results of our findings in a comprehensive report in general accordance with the requirements of Ontario Regulation 269/11 amending O.Reg. 153/04 made under the Environmental Protection Act and in compliance with the requirements of CSA Z768-01;
Provide a preliminary environmental site evaluation based on our findings;
Provide preliminary remediation recommendations and further investigative work if contamination is suspected or encountered.



4.0 RECORDS REVIEW

4.1 General

Phase I ESA Study Area Determination

A radius of approximately 250 m was determined to be appropriate as a Phase I ESA study area for this assignment. Properties outside the 250 m radius are not considered to have impacted the subject land, based on their significant distance from the site.

First Developed Use Determination

Based on a review of historical information, the northern portion of the Phase I Property addressed 5494 Boundary Road was originally developed with a single-family dwelling circa late 1970s. The southern portion of the Phase I Property addressed 5510 Boundary Road was originally developed with a single-family dwelling circa early 1960s.

Fire Insurance Plans

Fire insurance plans are not available for the Phase I Property or Study Area.

City of Ottawa Street Directories

City directories for the Phase I Property and Study Area were reviewed at the National Archives, in approximate 10-year intervals, from 1986 through 2011.

The portion of the Phase I Property addressed 5510 Boundary Road has never been developed and is unlisted. The second subject property addressed 5494 Boundary Road has been listed as residential since 1980.

Based on a review of the City directories, five (5) off-site potentially contaminating activities (PCAs) were identified, as presented in Table 1. All of the PCAs are situated to the east across Boundary Road. Based on information in our files (as discussed later), the groundwater flows eastward in this area. Given the nature of the PCAs and their distances and/or downgradient locations with respect to the subject land, none of the PCAs are considered to represent an area of potential environmental concern (APEC) on the site. The PCAs that have been identified are presented on Drawing PE4387-2 – Surrounding Land Use Plan.



Table 1: City Directories – PCAs in Phase I Study Area				
Address	Listed Activity	Years Listed	Approximate Distance / Orientation from Site	APEC (Y/N)
Boundary Road				
5425, 5455	Pomerleau Sand and Topsoil Yard	1992-2011	28 m NE	Z
	Pomerleau Excavations			
5507	Rene`s Steel & Welding Inc. metal works	1992-2011	20 m SE	N
	Luso Gas	1995-2005		
5495	PK Auto Repair	1996-1998	20 m E	N
	Car Guarantiers (Auto repair)	1998-2011		
Indcum Road				
145	Power Asphalt Corporation (Lumber handling facility)	1992-2011	50 m E	N
140	Western Signs and Line Painting	2000-2011	130 m SE	Ν

It should be noted that while some of the PCA properties are quite close to the subject site; they are downgradient relative to the Phase I Property, and as such, they are not considered to represent APECs on the Phase I Property.

Engineering Reports

The following report was reviewed for this assessment:

"Volume III: Geological, Hydrogeology and Geotechnical Report, Capital Region Resource Recovery Centre (CRRRC)," prepared by Golder Associates, dated December 2014.

The proposed CRRC is situated east, surrounding the aforementioned PCA properties. Based on the extensive investigation work, the groundwater flow of the various aquifers has been determined to be to the east and northeast direction.



Plan of Subdivision

A Plan has been prepared by Hachard Engineering, dated July 12, 2018 and was reviewed as part of this assessment. The plan depicts the Phase I Property in its current configuration with a proposed development plan.

4.2 Environmental Source Information

Environment Canada

A search of the National Pollutant Release Inventory (NPRI) was conducted electronically on July 13, 2018. No properties within the Phase I Study Area were listed in the NPRI database.

Ministry of Environment, Climate Change and Parks (MECP) Instruments

A request was submitted to the MECP Freedom of Information office for information with respect to certificates of approval, permits to take water, certificates of property use or any other similar MECP issued instruments for the site. At the time of issuing this report, a response from the MECP had been received. A copy of the response is provided in Appendix 2.

MECP Coal Gasification Plant Inventory

The Ontario Ministry of Environment and Climate Change document titled "Municipal Coal Gasification Plant Site Inventory, 1991" was reviewed to reference the locations of former plants with respect to the site. No coal gasification plants were identified in the Phase I Study Area.

MECP Incident Reports

A request was submitted to the MECP Freedom of Information office for information with respect to records concerning environmental incidents, orders, offences, spills, discharges of contaminants or inspections maintained by the MECP for the site or adjacent properties. At the time of issuing this report, a response from the MECP had not been received. Any pertinent information will be forwarded to the client upon receipt. A copy of the request form is provided in Appendix 2.



MECP Waste Management Records

A request was submitted to the MECP Freedom of Information office for information with respect to waste management records. At the time of issuing this report, a response from the MECP had not been received. Any pertinent information will be forwarded to the client upon receipt. A copy of the request form is provided in Appendix 2.

MECP Submission

A request was submitted to the MECP Freedom of Information office for information with respect to reports related to environmental conditions for the property. At the time of issuing this report, a response from the MECP had not been received. Any pertinent information will be forwarded to the client upon receipt. A copy of the request form is provided in Appendix 2.

MECP Brownfields Environmental Site Registry

A search of the MECP Brownfields Environmental Site Registry (ESR) was conducted as part of this assessment for the site, neighbouring properties and the general area of the site. No Records of Site Condition (RSCs) were filed for the Phase I Property. There are no RSCs listed for properties within the Phase I Study Area.

MECP Waste Disposal Site Inventory

The Ontario Ministry of Environment and Climate Change document titled "Waste Disposal Site Inventory in Ontario, 1991" was reviewed as part of the historical research. This document includes all recorded active and closed waste disposal sites, industrial manufactured gas plants and coal tar distillation plants in the Province of Ontario. No records were listed for the Phase I Property or for properties within the Phase I Study Area.

Areas of Natural Significance

A search for areas of natural significance and features within the Phase I study area was conducted on the web site of the Ontario Ministry of Natural Resources and Forestry (MNRF) on July 13, 2018. No areas of natural significance were identified on the Phase I Property or within the Phase I Study Area.



City of Ottawa Landfill Document

The document entitled "Old Landfill Management Strategy, Phase I – Identification of Sites, City of Ottawa", was reviewed. No landfill sites were identified within the Phase I Study Area.

PCB Inventory

A search of national PCB waste storage sites was conducted. No PCB waste storage sites were identified on the Phase I Property or within the Phase I Study Area.

Technical Standards and Safety Authority (TSSA)

The TSSA, Fuels Safety Branch in Toronto was contacted electronically on July 13, 2018 to inquire about current and former underground storage tanks, spills and incidents for the site and neighbouring properties. Two addresses, 5495 and 5425 Boundary Road, east of the subject site, were identified in the TSSA records.

The property addressed 5495 Boundary Road was listed as a former gas station and auto repair shop and registered as having two expired gas pumps and one active gas pump.

The other property addressed 5425 Boundary Road is listed as the Pomerleau Sand and Topsoil Yard and Excavation and registered as having multiple active fuel tanks. Both properties have been identified as PCAs in the Phase I ESA Study Area, however they are not considered to represent APECs on the Phase I Property based on the nature of their business and/or their down gradient location.

A full report has been requested for the two (2) aforementioned addresses. A full report was received from the TSSA on September 26, 2018. According to the reports, the retail fuel outlet at 5425 Boundary Road has been active since 1985. No infractions associated with this property were identified during the review of these reports.

According to the TSSA reports, the private fuel station located at 5495 Boundary Road reported as being in non-compliance from 2001 to 2006 as the ancillary equipment associated with the private fuel station did not meet the current standards at that time. It was reported in 2011 that the license to operate was cancelled, followed by non-compliance orders from 2013 to 2018 due to the abandonment of the UST containing fuel on-site. No other pertinent information was provided in these reports.



As previously discussed in this report, this property is not considered to pose a risk to the Phase I Property due to its downgradient orientation. A copy of the TSSA reports is provided in Appendix 2.

City of Ottawa Historical Land Use Inventory (HLUI)

A requisition form was sent to the City of Ottawa to request information from the City's Historical Land Use Inventory (HLUI 2005) database for the Phase I Property. Based on the City of Ottawa's HLUI report, previously identified PCAs were also listed in the HLUI. A copy of the HLUI report is provided in Appendix 2.

4.3 Physical Setting Sources

Aerial Photographs

Historical air photos from the National Air Photo Library were reviewed in approximate ten (10) year intervals. The review period dates to the first available air photos for the sites. Based on the review, the following observations have been made:

1945	The Phase I Property appears as a vacant parcel of land. The surrounding properties are generally vacant, undeveloped lands with occasional farmsteads.
1965	The Phase I Property appears to have been developed, with three (3) structures visible in the south east part of the subject property. They appear to be a house, a garage and a shed. The surrounding area appears unchanged from the previous photograph.
1976	Highway No. 417 is visible further to the north. No significant changes are apparent to the Phase I Property and the surrounding lands.
1991	More development is noticeable north of the subject property; a combination of industrial and residential properties. A residential dwelling is apparent in the north east part of the Phase I Property. Changes are apparent east of the subject property as well, with what appears to be a new roadway and pre-development (excavation) activities.
1999	Demolition in the of the previously existing residential home in the south east corner of the subject site has occurred and sand is being





	excavated from the southern portion of the site. No significant changes to the adjacent lands immediately to the north, east and south have occurred.
2002	Further excavation and some fill placement has occurred on sire, while some dump truck trailers are being stored on the southern part of the site. Lands further to the northeast have been developed for commercial / industrial purpose.
2011	Further excavation of the native sand has occurred on site and these areas are filled with shallow groundwater. Lands further to the east have been developed for commercial / industrial purpose.
2017	The majority of the subject site, not including 5494 Boundary Road, has been excavated and backfilled with imported fill. Some stockpiles of soil are present on site along with some limited construction materials.

The surrounding properties are depicted as the last aerial photograph. Laser copies of selected aerial photographs reviewed are included in Appendix 1.

Topographic Maps

Topographic information was obtained from Natural Resources Canada – The Atlas of Canada website. The topographic maps indicate that the elevation of the Phase I Property is approximately 77 m above sea level. The regional topography slopes towards the north to Mer Bleue Provincial Park Wetland, approximately 5km away from the Phase I Property. An illustration of the referenced topographic map is presented on Figure 2 – Topographic Map, which is included in Appendix 1.

Physiographic Maps

A Physiographic Map was reviewed from the Natural Resources Canada – The Atlas of Canada website, as a part of this assessment. According to the publication and mapping, the site is situated within the St. Lawrence Lowlands, Till Plains (Drumlinized) physiographic region. According to the mapping description provided: "The lowlands are plain-like areas that were all affected by the Pleistocene glaciations and are therefore covered by surficial deposits and other features associated with the ice sheets." The Phase I Property is in the Central St. Lawrence Lowland, "where the land is rarely more than 150 m above sea level, except for the Monteregion Hills, which consist of intrusive igneous rocks."



Geological Maps

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, the bedrock in the area of the Phase I Property consists of shale of the Carlsbad Formation. Overburden of the subject property reportedly consists mostly of nearshore marine sediments of deltaic and estuarian deposits. The south part of the subject property consists of offshore marine deposits of clay and silt, with a drift thickness ranging from approximately 15 to 50 m below grade.

Water Well Records

A search of the MECPs web site for all drilled well records within 250 m of the Phase I Property was conducted on July 13, 2018. Based on the search results, no wells were identified on the Phase I Property. Three (3) mix-use, domestic and commercial wells were present in the Phase I Study Area, located at 100 Entrepreneur Road (1 domestic/commercial use well); 145 Indcum Road (1 domestic use well); and, 120 Indcum Road (1 commercial use well).

Water Bodies and Areas of Natural Significance

No bodies of water or areas of natural significances (ANSI) were present on the Phase I Property or are known to exist within the Phase I Study Area. Mer Bleue Provincial Park Wetland is the closest water body at approximately 5 km to the north of the Phase I Property.

5.0 INTERVIEWS

Property Owner Representative

Mr. Michel Pilon, representing the current owner, Day and Ross Transportation Group, as well as Mr. Lesile Kern, the previous owner of 5494 Boundary Road was considered for this interview based on their knowledge of the Phase I Property.

5510 Boundary Road was previously owned by Pomerleau Excavation Ltd. Pomerleau Excavation has owned the property for more than 15 years, during which the site was used for aggregate extraction purposes.

5494 Boundary Road was owned by Mr. Kern since 2001. According to Mr. Kern, the property has always been used for residential purpose since its firs developed use, circa 1979. Mr. Kern is unaware of any potential environmental concerns on the Phase I Property or within the Phase I Study Area.



Any other pertinent information obtained during the interviews have been included in the relevant sections of this report.

6.0 SITE RECONNAISSANCE

6.1 General Requirements

Two site visits were conducted by personnel from the Environmental Division of Paterson Group. The site visit for the vacant parcel of land, located at 5510 Boundary Road was conducted on July 16, 2018.

The site visit for the residential property, located at 5494 Boundary Road was conducted on July 26, 2018. In addition to the Phase I Property, the uses of neighbouring properties within the Phase I Study Area were also assessed at the time of the site visits.

6.2 Specific Observations at Phase I Property

Buildings and Structures

No buildings or permanent structures existed on the southern portion of the Phase I Property (5510 Boundary Road) at the time of the site assessment.

A single-family residential dwelling has been situated on the northern portion of the Phase I Property (5494 Boundary Road) since 1979. The Phase I Property is depicted on Drawing PE4387-1 – Site Plan, in the Figures section of this report.

Underground Utilities

The Phase I Property is situated in a privately serviced area.

Site Features

The majority of the Phase I Property is not developed with any buildings or permanent structures, except the northeast portion of the subject property (5494 Boundary Road).

The vacant portion of the subject site (5510 Boundary Road) is covered with some gravel, low vegetation and stockpiles of fill material. The vacant lot appears to have been stripped entirely of vegetation at one point in time. A small excavator was located in the central-west portion of the property.

Phase I - Environmental Site Assessment



5494 and 5510 Boundary Road Ottawa, Ontario

Stockpiles of native and non-native fill material, broken concrete, gravel and topsoil, construction material (manhole pipes, and rusted metalworks) and a waste storage container were present on the southwestern portion of the subject property. It appeared however, that no waste was or had been generated on this portion of the Phase I Property. Drainage on the vacant portion of the Phase I Property consists primarily of surficial infiltration. No evidence of surficial staining was observed; however, evidence of stagnant water was observed along the northwest part of the vacant lot (5510 Boundary Road) at the time of the site visit.

The northeastern portion of the Phase I Property (5494 Boundary Road) is occupied by a two (2) storey, red-brick building with a concrete foundation and a shingled roof., constructed circa 1979. The residential dwelling is on a heavily treed lot with a gravel laneway fronting onto Boundary Road.

No signs of above ground or underground fuel storage tanks were observed at the time of the site visit. One pole-mounted transformer was identified on the northern property boundary. A private sewage system and well was observed on the central-west part of the residential property. Site photographs of each parcel of land are provided in Appendix 1.

Drainage on the northeastern portion of the Phase I Property consists primarily of surficial infiltration. No evidence of surficial staining or ponded water was observed at the time of the site visit.

No evidence of recent excavation was observed on the Phase I Property. No evidence of current or former railway or spur lines on the subject land was observed at the time of the site visit. The above-noted site features are shown on Drawing PE4387-1 - Site Plan.

Interior Assessment

As mentioned previously, only one building is presently on the Phase I Property, a 2-storey residential dwelling located on the northeast corner, addressed 5494 Boundary Road. A general description of the building interior follows:

The floors throughout the building consisted of laminate, hardwood, ceramic tiling and concrete (basement).
The walls consisted of drywall, some brick and concrete (basement).
The ceilings were finished with drywall and ceiling stipple.
Lighting throughout the building was provided by incandescent fixtures.



5494 and 5510 Boundary Road Ottawa, Ontario

The building is currently heated with an oil burning furnace. The above ground storage tank (AST manufactured in 2005) with a capacity of 950 L is located in the northeast part of the basement, partitioned from the furnace room (west part of the basement). The furnace is fed through an above ground line via the AST. Some staining was observed on the concrete floor next to the oil line between the partition and the furnace, however, no oil odour was noted. It is expected that the staining is moisture.

Chemical storage on site was limited to cleaning and maintenance products for domestic use.

A sump was located in the basement – no water or odour was observed at the time of site assessment.

Hazardous Building Materials

Based on the age of the residential dwelling addressed 5494 Boundary Road (1979), possible asbestos-containing materials (ACMs) observed during the site visit included possible drywall joint compound and stippled plaster. The potential ACMs were observed to be in good condition at the time of the site visit.

Based on the age of the building, lead-based paint may be present beneath more recent paints or on any original or older painted surfaces. Painted surfaces were generally observed to be in good condition throughout the structure at the time of the site visit.

Urea Formaldehyde Foam Insulation (UFFI) was not identified during the site visit.

Ozone-depleting substances (ODSs) noted at the time of the site visit included an A/C portable unit and a fire extinguisher.

Older PCB-containing light ballasts are considered to have by now been replaced with PCB-free ballasts.

No evidence of mould or water damage was observed on the interior of the subject structure.



Phase I Study Area

An inspection of the neighbouring properties was conducted from publicly accessible roadways at the time of the site inspection. Land use adjacent to the Phase I Property was as follows:

North –	Treed lot, followed by a residential dwelling;
South -	Treed lot, followed by Mitch Owens Road;
East –	Boundary Road, followed by a former gas station / auto repair
	garage and an excavation & materials company;
West -	Vacant lot, followed by treed land.

Current lands within the Phase I Study Area are vacant or used for light to heavy industrial purposes. Five (5) PCAs were identified within the Phase I Study Area at the time of the site assessment and are consistent with the PCAs listed in Table 1.

Surrounding land use and PCAs within the Phase I Study Area are presented on Drawing PE4387-2 – Surrounding Land Use Plan.

7.0 REVIEW AND EVALUATION OF INFORMATION

7.1 Land Use History

The Phase I Property is comprised of two (2) parcels of land: a vacant lot, addressed 5510 Boundary Road, and a residential lot, addressed 5494 Boundary Road.

The property addressed 5510 Boundary Road has been a vacant treed lot that was first developed as a residential dwelling between 1945 to 1950's. In the mid 1990's the structures / buildings on the property were demolished. The property since then has been excavated for aggregate extraction purposes and then infilled and used to handle fill material since 1999.

The property addressed 5494 Boundary Road has been a vacant treed lot that was first developed in 1979 with the exisiting 2-storey residential dwelling.

Based on the historical use of the Phase I Property, the first developed use was residential followed by commercial/light-industrial uses in the mid-1990s.



The intended use of the Phase I Property is commercial; therefore, a Record of Site Condition (RSC) is not required.

The following identified an on-site PCA, as per Table 2, O.Reg. 153/04 as

Potentially Contaminating Activities (PCAs)

amended by O.Reg. 269/11, and applicable item number: ☐ Item 30: "Importation of Fill Material of Unknown Quality" — this PCA was identified to have occurred on the subject property (5510 Boundary Road). While the fill placed on the subject site would typically be an APEC, a fill quality assessment was subsequently completed by Paterson to determine the quality of the fill material. The results of the fill quality assessment identifed PHC and/or PAH impact on the Phase I Property, which is likely a result of asphaltic concrete in the fill material. Reference should be made to the Phase II ESA report for details of the fill assessment, including recommendations to address the impacted fill material. Since the quality of the fill material has been addressed, this former activity is not considered to be an APEC on the Phase I Property. The following identified off-site PCAs within the Study Area, as per Table 2, O.Reg. 153/04 as amended by O.Reg. 269/11, and applicable item number: ☐ Item 28: "Gasoline and Associated Products Storage in Fixed Tanks" – this PCA was identified to have occurred on 5495 Boundary Road (former retail fuel outlet) and on 5425 Boundary Road (Pomerleau Sand and Topsoil Yard); ☐ Item 34: "Metal Fabrication" – this PCA was identified to have potentially occurred on 5507 Boundary Road (Rene's Steel & Welding Inc.); ☐ Item 39: "Paints Manufacturing, Processing and Bulk Storage" – this PCA was identified to have potentially occurred on 140 Indcum Road (Western Signs and Line Painting);

☐ Item 52: "Storage, maintenance, fuelling and repair of equipment, vehicles, and materials used to maintain transportation systems" — this PCA was identified to

☐ Item 59: "Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products" — this PCA was identified to have potentially

have occurred on 5495 Boundary Road (Car Guarantiers);

occurred on 145 Indcum Road (Power Asphalt Corporation).



Five (5) off-site PCAs have been identified east and southeast of subject property. Based on the groundwater direction (the groundwater flows east, away from the Phase I Property) and, as a result these off-site PCAs are not considered to represent APECs on the Phase I Property. These PCAs are depicted in green on Drawing PE4387-2 – Surrounding Land use Plan.

Areas of Potential Environmental Concern (APECs)

Based on the above mentioned findings, there are no APECs on the Phase I Property.

Contaminants of Concern

The contaminants of concern on the Phase I Property are PHCs and PAHs in the fill material, as identified in the fill quality assessment report.

7.2 Conceptual Site Model

Existing Buildings and Structures

A residential dwelling is the only structure on the site located on the north east corner of the Phase I Property.

Fill Material

Based on the Phase II ESA, the quality of the fill material has been addressed.

Geological and Hydrogeological Setting

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, the bedrock in the area of the Phase I Property consists of shale of the Carlsbad Formation. The reported overburden thickness of the Phase I Property ranges from 25 to 50 m below grade, consisting mostly of nearshore marine sediments of deltaic and estuarian deposits. A small part of the subject property in the south consists of an overburden thickness of 15 to 25 m below grade, consisting of offshore marine deposits of clay.

The regional topography slopes towards the northeastern direction. The regional groundwater flows in an easterly direction.



Water Bodies

There are no bodies of water on the Phase I Property. The closest water body is the Mer Bleue Provincial Park Wetland, approximately 5 km north of the Phase I Property.

Areas of Natural Significance

No areas of natural significance were identified on the Phase I Property or on other properties within the Phase I Study Area.

Drinking Water Wells

One drinking water well was located on the Phase I Property. Three (3) mixed-use, domestic and commercial wells were identified in the Phase I Study Area, located at 100 Entrepreneur Road (1 domestic/commercial use well); 145 Indcum Road (1 domestic use well); and, 120 Indcum Road (1 commercial use well).

Neighbouring Land Use

Neighbouring land use in the Phase I Study Area is primarily light to medium industrial use with occasional vacant land, residential and commercial land. Land use in the surrounding area is presented on Drawing PE4387-2 - Surrounding Land Use Plan.

Potentially Contaminating Activities and Areas of Potential Environmental Concern

The former PCA on the subject property had been assessed, and thus, is no longer an APEC. Additional PCAs were identified within the Phase I Study Area, however these activities were not considered to represent APECs on the Phase I Property based on their respective separation distances and/or orientations with respect to the Phase I Property.

Assessment of Uncertainty and/or Absence of Information

The information available for review as part of the preparation of this Phase I ESA is considered to be sufficient to conclude that there are no areas of potential environmental concern on the subject site.

A variety of independent sources were consulted and verified as part of this assessment, and as such, the conclusions of this report are not affected by uncertainty which may be present with respect to the individual sources.



8.0 CONCLUSION

Assessment

A Phase I – Environmental Site Assessment was carried out for the properties addressed 5494 and 5510 Boundary Road, in the City of Ottawa, Ontario. The purpose of this environmental assessment was to research the past and current use of the Phase I Property and Study Area and identify any environmental concerns with the potential to impact the subject property.

Based on a review of available historical sources, the subject site, addressed 5494 Boundary Road was first developed in 1979 with the current homestead. The subject site addressed 5510 Boundary Road was first developed in the early 1960's with what appears be a homestead. However, in the late 1990's the property was redeveloped and stripped of any structures. Based on aerial photographs, sand was excavated from 5510 Boundary Road and subsequently infilled. Paterson completed a fill quality assessment to address fill material onsite. The laboratory results identified PHC and/or PAH impacted fill material on the Phase I Property, which were considered to be the result of asphaltic concrete in the fill. Recommendations have been provided in the Phase II ESA letter report.

Historical research indicates that the surrounding properties, although many still vacant lots, have been used for light to medium industrial purposes with some residential use. Five (5) potentially contaminating activities (PCAs) were identified on the surrounding lands to the east, across Boundary Road. Based on the separation distance and/or orientation (down-gradient) from the subject property, these PCAs are considered to pose very low risk to the Phase I Property, and therefore are not considered to represent APECs.

Following the historical review, a site assessment was conducted for the Phase I Property and surrounding lands. Current use of the subject property and surrounding lands are considered to pose low risk for reasons previously discussed. Based on the above information, it is our opinion that no further work is required for the Phase I Property at this time.

Recommendations

It is expected that the residential dwelling addressed 5494 Boundary Road will be demolished during future site redevelopment.





5494 and 5510 Boundary Road Ottawa, Ontario

In addition, if the domestic well is not to be used in the future then it should be abandoned according to Ontario Regulation 903. Further information can be provided upon request in this regard.

Report: PE4387-1R October 20, 2021



9.0 STATEMENT OF LIMITATIONS

This Phase I - Environmental Site Assessment report has been prepared under the supervision of a Qualified Person (QP_{ESA}), in general accordance with O.Reg. 153/04 as amended by O.Reg. 269/11, and meets the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

Should any conditions be encountered at the subject site and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Day & Ross. Permission and notification from Day & Ross and Paterson Group will be required to release this report to any other party.

Paterson Group Inc.

Mandy Witteman, B.Eng., M.A.Sc

Mark S. D'Arcy, P.Eng., QPESA

Report Distribution:

- Day & Ross
- Paterson Group Inc.





10.0 REFERENCES

Federal Records

Air photos at the Energy Mines and Resources Air Photo Library.

National Archives.

Maps and photographs (Geological Survey of Canada surficial and subsurface).

Natural Resources Canada – The Atlas of Canada.

Environment Canada, National Pollutant Release Inventory.

PCB Waste Storage Site Inventory.

Provincial Records

MECP Freedom of Information and Privacy Office.

MECP Municipal Coal Gasification Plant Site Inventory, 1991.

MECP document titled "Waste Disposal Site Inventory in Ontario".

MECP Brownfields Environmental Site Registry.

Office of Technical Standards and Safety Authority, Fuels Safety Branch.

MNRF Areas of Natural Significance.

MECP Water Well Inventory.

Chapman, L.J., and Putnam, D.F., 1984: 'The Physiography of Southern Ontario, Third Edition', Ontario Geological Survey Special Volume 2.

Municipal Records

City of Ottawa Document "Old Landfill Management Strategy, Phase I -

Identification of Sites", prepared by Golder Associates, 2004.

The City of Ottawa Historical Land Use Inventory.

Intera Technologies Limited Report "Mapping and Assessment of Former Industrial Sites, City of Ottawa", 1988.

The City of Ottawa eMap website.

Local Information Sources

Previous Engineering Reports.

Plan of Subdivision, Hatchard Engineering (July 12, 2018)

Public Information Sources

Google Earth.

Google Maps/Street View.

FIGURES

FIGURE 1 – KEY PLAN

FIGURE 2 – TOPOGRAPHIC MAP

DRAWING PE4387-1 – SITE PLAN

DRAWING PE4387-2 – SURROUNDING LAND USE PLAN




FIGURE 1 KEY PLAN







FIGURE 2 TOPOGRAPHIC MAP

patersongroup _








APPENDIX 1

PLAN OF SUBDIVISION


AERIAL PHOTOGRAPHS

SITE PHOTOGRAPHS



AERIAL PHOTOGRAPH 1945

patersongroup _____



AERIAL PHOTOGRAPH 1965

patersongroup _____




AERIAL PHOTOGRAPH 1976

patersongroup



AERIAL PHOTOGRAPH 1991

patersongroup ___



AERIAL PHOTOGRAPH 1999

patersongroup _____



AERIAL PHOTOGRAPH 2002

patersongroup _____



AERIAL PHOTOGRAPH 2011

patersongroup ____



AERIAL PHOTOGRAPH 2017

patersongroup ____

5510 and 5494 Boundary Road, Ottawa, ON

August 15, 2018



Photograph 1: View of the north east corner of the vacant portion of the subject site, looking onto the Boundary Road and the adjacent property (former gas station).



Photograph 2: View along the south end of thevacant lot, looking south west from Boundary Road.



Photograph 3: View of the north east part of the vacant lot, looking towards to the residential portion of the subject site.



Photograph 4: View of the eastern portion of the vacant lot, taken from the west end of the site, looking towards Boundary Road.



Photograph 5: View of the central north west part of the vacant lot, looking north.



Photograph 6: View of the central south part of the subject site, looking south.

Site Photographs

PE4387

5510 and 5494 Boundary Road, Ottawa, ON

August 15, 2018



Photograph 7: View of the south west corner of the subject property, looking west.



Photograph 8: View of the north west corner of the vacant lot, looking north.



Photograph 9: View of the central south part of the vacant lot, looking south west.



Photograph 10: View of the former gas station, across Boundary Road, taken from the vacant lot.



Photograph 11: View of the east portion of the residential lot, looking onto Boundary Road (east).



Photograph 12: Front view of the residential dwelling on the residential lot.



Photograph 13: View of the front yard (east part) of the residential property.



Photograph 14: View of the septic system, located on the north side of the residential dwelling.

APPENDIX 2

MECP FREEDOM OF INFORMATION SEARCH REQUEST

MECP WATER WELL RECORDS

TSSA RESPONSE

TSSA REPORTS

HISTORICAL LAND USE INVENTORY (HLUI)

Ministry of the Environment, Conservation and Parks

Freedom of Information and

Protection of Privacy Office

Ministère de l'Environnement, de la Protection de la nature et des

Bureau de l'accès à l'information et de la protection de la vie privée

40 St. Clair Avenue West

Toronto ON M4V 1M2 Tel: (416) 314-4075

12th Floor

12" étage 40, avenue St. Clair ouest Toronto ON M4V 1M2 Tél.: (416) 314-4075



August 16, 2018

Mandy Witteman Paterson Group Inc. 154 Colonnade Road Ottawa, ON K3E 7J5

Dear Mandy Witteman:

RE: Freedom of Information and Protection of Privacy Act Request

Our File #: A-2018-04784, Your Reference #: PE4387

This letter is in response to your request made pursuant to the Freedom of Information and Protection of Privacy Act relating to 5510, 5494 Boundary Road, Carlsbad Springs.

After a thorough search of the Ministry's Ottawa District Office, Investigations and Enforcement Branch, Environmental Assessment and Permissions Branch, Environmental Monitoring and Reporting Branch, Sector Compliance Branch and Safe Drinking Water Branch, records were located in response to your request. It is my decision to provide partial access to the attached information as identifying information pertaining to private individuals has been removed to protect privacy (Section 21(1)(f) of the Act).

In accordance with Section 57 of the Freedom of Information and Protection of Privacy Act, detailed below are our charges:

•	Search Time 1 hour @ \$30/hour	9.	\$	30.00
•	Copying 21 pages @ \$0.20/page		\$	4.20
	Delivery		\$	3.00
•	Total			37.20
•	Deposit Received		- \$	30.00
•	BALANCE WAIVED (NOT REQUIRED)		\$	7.20

You may request a review of my decision by contacting the Information and Privacy Commissioner/Ontario, 2 Bloor Street East, Suite 1400, Toronto, ON M4W 1A8 (800-387-0073 or 416-326-3333). Please note that there is a \$25.00 fee and you only have 30 days from receipt of this letter to request a review.

If you have any questions regarding this matter, please contact Katie Tudor at katie.tudor@ontario.ca.

Yours truly

Janet Dadufalza FOI Manager

Attachments

Pages 3 to / à 8 are not relevant sont non pertinentes

Ontario

Ministry of the **Environment**

| central site | Feedback | search | site map | français |

8 Search Coor Menagoraph * | Company Mgmt - | Manifels | She Data - | Help | Logouit HOME AR WATER VAND ABOUT US NEWS & PUBLICATIONS Administration

Generator Details

Registration/Notification Number

Legal Company Name

R.W. Tomlinson Ltd. Primary Name:

Company Operating Name

R.W. Tomlinson Ltd. **Mailing Address** Primary Name:

5597 Power Road

Division Building:

Address Line 1:

Town/City:

Otterva

OTTAWA CARLTON (RM) ×

County: (if outside Ontario)

County: (if inside Ontario)

Province/State (Linside Canada/US) ONTARIO

Province / State (If outside Conada / US)

K1G 3N4

Postal Code / Zip Code:

ΑN NA

Post Box Number,

Address Line 2:

Z Z

Division Name:

٧X

Division Name:

Cunada

Site Location

Country:

This should be the street address of the site that is being registered. You are required to register each site that generates hazardous waste separately. ¥ Division Building:

Post Box Number:

5510 Boundary Road

Address Line 1: Address Line 2:

Province / State (If inside Canada / Postal Code / Zip Code: OTTAWA CARLTON (RM)

Ottawa

Town/City:

Ϋ́Z

ONTARIO K4B 1P6

Province / State (If oatside Canada / US)

Y.

Country:

Conada

Y.

County: (if outside Ontario) County: (if inside Ontario)



Ministry of the Environment Ministère de l'Environnement

Compliance Summary Inspection Report

Client:	Pomerleau Ltd. Mailing Address: 5425 Boundary Rd, Ottawa, Ontario, Canada, K4B 1P6 Physical Address: 5425 Boundary Rd, Ottawa, City, Ontario, Canada Telephone. (613)822-1211 Client #: 6619-8ATHQV, Client Type: Corporation						
Inspection Site Address:	District Office: Ottawa GeoReference: ,	y Rd, Ottawa, City, K0A 1K0	,Latitude: , Longitude:				
Contact Name:	Regent Pomerleau	Title:	Owner				
Contact Telephone:	(613)822-1211 ext	Contact Fax:					
Last Inspection Date:	81	=:					
Inspection Start Date:	2014/05/12	Inspection Finish Date:	2014/05/12				
Region:	Eastern						

1.0 INTRODUCTION

see attached POEC inspection

2.0 INSPECTION OBSERVATIONS

see attached POEC inspection

2.1 AREA OF FOCUS

This inspection is being conducted under the following Ministry of Environment program(s) and/or activities:

Properties of Environmental Concern

Specifics:

2.2 COMPLIANCE OVERVIEW

Specifics:

See warnings under section 6.0 below. See attached POEC inspection.

3.0 REVIEW OF PREVIOUS NON-COMPLIANCE ISSUES

7.0 INCIDENT REPORT

Not Applicable

8.0 ATTACHMENTS

Pomerleau Ltd May 12 2014.doc

PREPARED BY:

Environmental Officer:

Name:

District Office:

Date:

Signature

Lance Larkin

Ottawa District Office

2014/05/13

REVIEWED BY:

District Supervisor.

Name:

District Office:

Date:

Jena Leavoy

Ottawa District Office

2014/05/28

Signature:

Gara Comey

File Storage Number:

SI OT OT BO 100

Note:

This inspection report does not in any way suggest that there is or has been compliance with applicable legislation and regulations as they may apply to this facility. It is, and remains, the responsibility of the owner and/or the operating authority to ensure compliance with all applicable legislative and regulatory requirements.

SAC Action Class:	Poliution Incident Reports (PIRs) and "Other" calls
Non-Standard Procedure:	No
ERP Call-out Initiated:	No

Client(s)

Site(s)

Site Details

Vacant Land<UNOFFICIAL>

Address: Lot: , Part: , Vacant land on Boundary road, south off Hwy 17, Carlsdad Springs, Ottawa, City,

District Office: Ottawa

+ + + +

5510 Boundary Road<UNOFFICIAL>

Address: Lot: , Part: , 5510 Boundary Road, Ottawa, City, District Office: Ottawa

Incident Information

Incident Summary:	TIPS; Drain All trucks dumping >200 loads on vacant land cannot be longer than 60 characters
Incident Description:	Celler reports Drain All trucks are known for illegal dumping in the vacant land south of a gas station located on Boundary Rd (South of Hwy 417). The caller estimates >200 loads have been dumped this year alone. The trucks are always Drain All. Many people are aware of this. The caller could not give any more details on the location. The caller just saw a truck now, and reports dumping takes place during the day and night. The caller has not personally observed dumping, but reports others have. He reports the area is easy to find if you park at the gas station and walk south. Caller wished to remain anonymous.
	Lt Dec 20, 2012 - I checked previous IRs. I called previous complainant, in the said that Drain-Ali was dumping cutting water from pavement. Caller said he's been to the site, 5588 Boundary Road. Caller said he saw Drain-All on Dec 19th, 2012 at 6 p.m. He said they go to the site 3x per day. Rheal Detaquis was dealing with this originally. Nothing in writting found from Rheal Delaquis Regent Pomerleau Ltd. or Drain-All.
	16:05 - I called Drain-All and spoke to Frank Cardinali (President). He said they have trucks that do vacuum excavation. He mentioned there's no financial gain for them to dump any contaminated mud slurry. He said if there slurry is deemed "filt" it will go to Pomerleau on boundary road, 5425 Boundary. He believed they are stockpilling the material. Mr. Cardinali said they have sampled material in the past. A visual check is used and drivers are trained in Reg. 347. He said that he was confident that if I sampled no contaminants of concern would be detected. He mentioned there's more of a financial gain for them to take the material to their transfer station. He mentioned that Officer Rheat Delaquis was dealing with Dave Elsie. He explained that the mud slurry is generated by cutting into soil to create gas mains and bell wire mains. He said that workers are always looking a where they are cutting. Any sheen would be visible. He mentioned that abnormalities have been discovered and when that happens, they manage the material as contaminated material. He said the material wouldn't pass the slump test.
	Jan 8, 2013 - I drove by 5425 Boundary Road, Pomerleau Sand & Gravel. Three seconds down the road, was 5588 Boundary Road. The metal swing gate was open and it was snow covered. Doesn't appear that the gate was ever closed this winter. The inner roadway leading to the back of the property had been plowed recently. There was a roto screener equipment near the entrance to the right. The site was snow covered. There were three or four large piles of what I could see was soil. Some of the soil was exposed it looked like it was there for some time due to snow cover. There was one Hitachi front loader parked near the piles. There were a few piles of industrial size metal I beems. There were about 6 large metal tanks (~30,000 litre capacity) stored on the property. They were on their sides. They seemed empty to me as scrap metal. There were no flowing watercourses in the vicinity of the site, however it was difficult to see due to winter conditions. I drove to the back

s.21

	nud - inert fill_Mar2001 (2).	pdf					
		irinii nii irini	46.00	enini enin	inini in ininini		
Date & Time of Incident	Incident Date Confirm 2012/12/19	nation? Estimat	ed				
Source Type:				Sector Type:			1000
Nearest Watercourse:				Watershed Code:	ategory		
Environmental Impact:	Possible						
Nature of Impact:							
incident Cause:				Incident Reas	on:		
Damaged Party:	No					7/	
	-8302	Contaminant	s Tab	le			
Contaminant N	ame	Code	UN#	# Limit	Quantity	[units]	[freq]
	-						
Controller of Material: Estimated Clean Up Cost:				Owner of Mate Who Cleaned			
			_				
% Clean Up:	%		Agencies Involved:				
production and the second	PREMISERATOR PROPERTY AND ADDRESS OF	100000000000000000000000000000000000000		aracasasa	A CONTRACTOR OF THE PERSON OF	STATE OF THE STATE OF	energy market
	natement						
oluntary / Mandatory Ab						entre de la regional de la composition della com	
		O Yes		● No		O To be det	ermined
oluntary / Mandatory Ab Is there Voluntary Abatem /oluntary / Mandatory Com Type Parent RefNo Work So	ent Activity?	163	Date		inList	○ To be det	ermined .
Is there Voluntary Abatem /oluntary / Mandatory Com Type Parent RefNo Work St ffence(s)	ent Activity? ppliance Items ummary (may be truncate	163	Date		inList	O To be det	ermined :
Is there Voluntary Abatem	ent Activity? ppliance Items ummary (may be truncate	163	Date		inList	O To be det	ermined

MUD - Inert Fill

Question:

Does clean mud or muddy water meet the inert fill definition in Reg. 347, (i.e.

exempt from Part V)?

Reg. Reference:

O. Reg. 347, (Waste Management) definitions, Section 3(1) (Exemptions)

Background:

Mud and muddy water are generated from the drilling of wells, directional boring activities, construction activities, etc. On occasion the mud and muddy water from these activities needs to be removed.

Regulation 347 defines "inert fill" as "earth or rock fill or waste of a similar nature that contains no putrescible materials or soluble or decomposable chemical substances".

If it is known or can reasonably be expected to be known that the mud and muddy water is otherwise not contaminated, then the Ministry does not need to regulate this off-site disposal activity. The Ministry can deal with "may impair" and "adverse effect" issues under the appropriate legislation if the situation arises.

The intent of the legislation is not to capture clean mud and muddy water as waste. Under Reg. 347 "drilling fluids and produced wastes associated with the exploration, development or production of crude oil or natural gas" are explicitly excluded from the definition of "liquid industrial waste". Therefore, clean mud and muddy water from other similar activities, should also be excluded from this definition.

Response:

Clean mud and muddy water are essentially earth mixed with varying amounts of water. Since the definition of inert fill includes earth, than mud and muddy water can be considered inert fill making them exempt from Part V.

1.0 Introduction:

The purpose of this inspection was to assess the Site's compliance with the requirements of the Ontario Environmental Protection Act (EPA) and the Ontario Water Resources Act (OWRA). A walkabout of the site was conducted to assess waste management requirements and potential for adverse effects. No non-compliance issues were identified.

The Site is zoned Rural Heavy Industrial and is located across from an industrial area located west of highway 417 and Carlsbad Springs.



Pomerleau Ltd. (the Company) operates a sand and gravel operation at 5425 Boundary Road, just east of the subject Site. The Company's headquarters is located there as well.

2.0 Inspection Observations:

The Site is primarily used for the temporary storage of recycled material such as asphalt and concrete. As per a review of historical aerial photos crushed stone and likely other

Does the owner/operator have a history of non-compliance with environmental legislation or activities that had the potential or caused an adverse effect in the past? ☐ Yes ☒ No Specifics:									
2.2 Abandoned or Derelict:	2.2 Abandoned or Derelict:								
Which of the following best describes the property? Abandoned Derelict Idle What is the legal description of the site and what are its area boundaries? (If municipal address is unavailable or insufficient to accurately describe the site, please give a description of the site area, e.g. Roadway boundaries). Specifics: 5510 Boundary Road, Ottawa, K0A 1K0 (Concession 9, South Part, Lot 1) and PIN No. 043240177 (Concession 9, Part Lot 1 of Gloucester Part 2, 4R13964).									
locked buildings, evidence of forced entry breach. Could the problem potentially pose a ☐ Yes ☐ No	Is the site secure? (Please indicate if the site is occupied 24/7, fenced, locked gates, locked buildings, evidence of forced entry, etc. List information if there has been a breach. Could the problem potentially pose a risk to human health or the environment?) Yes No Specifics: The main swing gate was locked.								
During the time of the inspection can the effect related to the site condition? ☐ Yes ☒ No ☐ Unknown Specifics:	inspector observe any potential or adverse								
	er or operator ceased operations on the site or closed the site, resulting in a potential or								
From the inspection observations is further decommissioning/site closure work or compliance activities required to ameliorate any potential or adverse effect(s)? Yes No Specifics:									
2.3 Chemical and Waste Storage:	*								
Are there volumes of chemicals or waste nenvironmental concern? Yes No Potential List:	Are there volumes of chemicals or waste materials stored at the site that would be of environmental concern? Yes X No Potential								
Chemicals or Waste	Estimated Volume								
	· .								

Yes, known and confirmed adverse effect Potential (Ministry review still in not started or in progress)									
N/A									
What are the contaminants of concern for each affected media and highest concentrations? (Indoor soil vapour could also be listed) List: NA									
Contaminant of Concern	nant of Concern Groundwater Soil/Sediment concentrations concentrations								
extent of the contami indicate if the contami Specifics: N/A	ation is readily available nants of concern found ination is moving, the se	I in the sub surface, on the surce, if it is an ongoin	on or off-site? (please g source, etc,)						
Is the site located in Records of Site Condi ☐ Yes ☒ No Specifics:	n an area of natural stition?	significance as define	d in O.Reg. 153/04,						
been attributed by the	ors that are associated site? of receptors, estimated	·							
Has there been a remedial action plan/risk assessment designed to mitigate the associated adverse effect or potential for an adverse effect on and off site contamination found on and/or off the site? ☐ Yes ☐ No ☒ No, not required Specifics:									
Does the plan adequately address the adverse effect or potential for an adverse effect? Yes No Specifics: N/A									
2.5 Overlapping wi	th Other Program A	reas:	÷.						
Is the inspection performed with another overlapping inspection media? Yes No (list the common media) If yes, provide reference? (Additional inspection forms may be filled out related to other program areas for the site if there is an overlap. Please copy significant information from other inspections reports where applicable and vice versa). Specifics:									

6.0 Other Inspection Findings

These are inspection findings, which are not classified under the site categories and may often involve other programs areas. This may often involve inspection findings that are not under Ministry jurisdiction but are potential issues and concerns that need to be made to the appropriate jurisdictional agency. Where the Environmental Officer can, for example, identify a contravention of a Ministry requirement which in itself may not trigger a "Program Priority", but may still require some action from the owner/operating authority. The Environmental Officer may also include suggested actions to be taken.

- The Company should be mindful that any water taking greater than 50,000 litres per day requires a Permit To Take Water under the OWRA. Should water takings occur at the site, the company should track the volumes of water removed from the site.
- The Company should be mindful that Section 53 of the OWRA requires approval prior to using, operating, establishing, altering, extending or replacing new or existing sewage works.

7.0 Actions Required

9 A EO Basammandad Casa Eila Managaman

Use the Compliance Guidelines and the Delivery Strategies to determine appropriate procedure for ensuring that full and timely compliance is achieved.

N/A

0.0 EO Recommended Case i lie management
☑ Site requires no further action
Site inventory for prioritization exercise required
Level 1 - Case Files Managed Within the District
Level 2 - Case Files Managed Between Two Districts in the Same Region-
Coordinated Approach
Level 3 - Case Files Managed Over Multiple Districts / Regions or Provincially
Significant

Note:

This inspection report does not in any way suggest that there is or has been compliance with applicable legislation and regulations as they may apply to this facility. It is, and remains, the responsibility of the owner and/or the operating authority to ensure compliance with all applicable legislative and regulatory requirements.

			Code:	
			UN No.:	
			Code : 6	
			UN No.:	
			Code:	
			Code:	
			Waste GenNum :	
			Waste GenNum :	
Carried out by:	- 176.5			
[v] Owner	[N] Othe	r		
	Estimate	ed Cost:		
/al Given Under				- 1
Regulation	362 [v]	Manifest No.		
			Code:	
			Code :	
			Code:	
Nature of Ir	mpact:			_
			Code :	
1				
roller):				
150			Code :	
	[v] Owner val Given Under Regulation Nature of in	[v] Owner [N] Other Estimate val Given Under Regulation 362 [v] Nature of impact:	[v] Owner [N] Other Estimated Cost: val Given Under Regulation 362 [v] Manifest No. Nature of impact:	UN No.: Code: UN No.: Code: Code: Code: Waste GenNum: Waste GenNum: Waste GenNum: Estimated Cost: //al Given Under Regulation 362 [v] Manifest No. Code: Code: Code: Code: Code: Code:

		a sandanas () ja	٠.			ĝ.		
পি Ontario	Ministry of	Well Tag N····	non oticker and pri	nt number,below)			Well R	ecord
W Gritano	the Environment	Jane, 1			Regulation 903	3 Ontario	Water Reso	ources Act
Instructions for Comp	 etina Form	A 01	1415	The state of the s	*	K.,	page _	of
	ce of Ontario only. This		· · · · · · · · · · · · · · · · · · ·	I document Pla	ı ease retain for futur	ு e refere	nce.	fy. The
 All Sections must be 	completed in full to avoi	d delays in process	ing. Further i	nstructions and	l explanations are ava	ailable or	n the back of	this form.
Questions regarding	completing this applicati	on can be directed to	o the Water	Well Managem	nent Coordinator at	416-23	5-6203.	*
Please print clearly in	ents shall be reported blue or black ink only.	to 1/10" of a metro	e	2	Ministry Us	e Only	,i	
Well Owner's Informat	457	Vell Information	MUN	000000	ONOF	1	LOT	02
RR#/Street Number/Name	50M-136 PA	BLK1 C	Permer	lon (at	taway At	7-3	RPSOI	76120
	Rd Carllad	S	City/Town/VI			artment/E	Block/Tract et	C.
GPS Reading NAD	Zone Easting	Northing	Unit Make/M	odel Mode	of Operation: Und	lifferentiate	d — ever	aged
Log of Overburden an	18 465747	5010 69 3	Magel	lan	Diffe	erentiated,	specify	1 1
	· · · · · · · · · · · · · · · · · · ·	Other Materials		General	I Description		Depth	Metres
General Coldur Most com	mon material	Other Materials		General	Description		From	То
Brann San	dy sent of	Lacry		7 75		Augustina - martina - mart	0	5_
grey clay	<u> </u>			LARVANIA MARTINI MARTI			5	15
blue els			AANNA WANTO PART .				15	95
que land	pon ora	/					95	109
any roa	4						109	110
73							•	
							1	
			,				<u> </u>	
					. /		/	
Hole Diameter		Construction Re	cord		Tes	t of Wel	l Yield	
Depth Metres Diam	ter Inside	Wall	Depth	Metres	Pumping test method			ecovery
From To Centim	tres diam Mate	แห่งเลาอยู่อ	From	To	Sub.	1 (ater Level Time Metres min	Water Level Metres
0 110 6"	centimetres	centimetres	110111		Pump intake set at -	Static 2		277
		Casing		***	(metres)		70 1	a.65
	6 / Plastic Galvanize	Fibreglass	in de la companya de La companya de la companya de	1001	(litres/min) (/1		, , ,	0,03
Water Record	Galvanize	diff 188	+ 0	77	Duration of pumping	2 2	70 2!	2.64
Water found Kind of Wat		Fibreglass	<u>.</u>	<u> </u>	hrs + min		70	3 (3
m Fresh Sulp	I lorned lumi	Concrete			of pumping	3 3	. 70 3	2.63
Gas Salty Min	erals Galvanize	d			Recommended pump	4 2	72 4	2.62
m Fresh Sulp	dhur. II	Fibreglass			type. Shallow Seep			
Gas Salty Min	erals Plastic Galvanize				Recommended pump depth. 50 metres	5 3	. 72 5	0.61
Other:	T	Screen			Recommended pump	10 🗟	72 10	2.60
Gas Salty Min	arale Outoido		·	T	rate. (litres/min)	15 🗸	74 15	à.60
Other:	diam Plastic	Fibreglass Slot No.			If flowing give rate -	20 🞝	74 20	2.60
After test of well yield, water w	as Galvanize	' I			(litres/min)	25 2 30 2	75 25 75 30	3.60
Other, specify		No Casing or Sc	reen		ued, give reason.	40 🕽	75 30	3.60
	Open hole					50 2	76 50	2.60
Chlorinated Yes No	Open note	•	<u> </u>			60	.77 60	2.60
	<u> </u>		Abandonment		Location (
Depth set at Metres Material a	nd type (bentonite slurry, neat ce		me Placed ic metres)	In diagram below Indicate north by	show distances of well for	om réad,	lot line, and bu	ilding.
0 30	a sout.	4	lag.	NW.	.	أحنيا		
			T	'	Bulch	P	and the second	
	No.			3	16		A State Marian College Harry States	
				8		\mathbf{A}		
			<u> </u>	1 1		لب		. [
	Method of Constructi	on,.	j.	4				
Table Tabl		iamond [Digging	1 3	1 parking	<i>t</i>	· A	1
Rotary (conventional) Ai	,	etting \ Priving	Other	1 3			m.	
	Water Use		2 **	1				
		ublic Supply [Other		end	tum :	IR di.	
		lot used\`/ cooling & air conditioning		Audit No.	A O A P P Dai	te Well Co	mpleted	
	Final Status of Well				124//	g.	00 4	05 2D
Water Supply Rechar	Y		loned, (Other)	Was the well own	nor o imprinadors	te Delivere	d YYYY	MM DD
		ewatering eplacement well		package delivered			1004	05 127
Well	Contractor/Technician Ir	formation			Ministry Us			
Name of Well Contractor	ati	Well Contractor's	Licence No.	Data Source	Co	ntractor	517	1
Business Address (street name,	number, city etc.)	<u> </u>		Date Received	YYYY MM DD Dat	te of Inspe	ction YYYY	MM DD
Carrelman a	nt	1,50,00	S 4 4 1	AUG 1	8 2004			
Name of Well Technician (last na	ame, first name)	Well Technician's		Remarks	We	ell Record	Number	
Signature of Technician/Contrac	br :	Date Submitted YYY	Y MM DD	1		11	53487	76
x Maure C		1004	Well Own	er's Con	Code 5		st disponible	
0506E (09/03)	Contractor's Co	py Ministry's Copy	│	era cob X	Cente n	omule e	or aroportible	он пануаі8
						~		
	I		Ī					

(V) OI	ntario	Ministr the En	y of vironment	Well Ta	i g Number (Pla	ce sticker and o	rint number below)	Regulation	n 903 Ontari		Record
Instructions	s for Compl	eting Fo	m		A05	393	6			page	<u>ك</u> of <u>ح</u>
For useAll SectionQuestionAll metron	in the Provin ons must be	ce of Oni complete completin	ario only. The din full to aving this application of the reporte	oid delay: ation can d to 1/10	nent is a perm s in processin be directed	nanent leg ang. Further to the Wa	al document. P	Please retain for to d explanations are Desk (Toll Free) Ministry	e available o	n the back o	f this form.
	'o losowooti		-			MUN	C	ON		LOT	
F 7											
OTTA	WH - C	2, 4,	muriicipanty)	00.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0.4.0.0		amb	enlan	d	2	Concession	
RR#/Street Nu	mber/Name	n				City/Town/V	jilage Spad-		ompartment/E $CR - C$		tc.
GPS Reading	NAD 8 3		asting 165723		thing 020642	Unit Make/N	Model Mode	of Operation:	Undifferentiated,	ed GAVe	raged
Log of Over	burden and	Bedroc	(Materials	(see ins	tructions)	1112					
General Colour	#") #	non materia	1	Other Ma	aterials			al Description		Depth From	Metres To
Brown	81	ay_					<u>5 o</u>	K T		0	0.90
Ked	61	<u> </u>					<u>50</u>	F. T.		0.90	3,63
Grey	Crisi	10/						2+	, , , , , , , , , , , , , , , , , , ,	30.30	30.30
Grey.	SHI	PLE					Por	0 u 5	VI.	31.51	32.42
	ALE IS CONTROL OF THE PARTY OF										
							The state of the s				· · · · · · · · · · · · · · · · · · ·
Hole I	Diameter			Cons	struction Reco	ord	4		Test of Wel	l Yield	
· · · · · · · · · · · · · · · · · · ·	etres Diamet	msic	Mot	erial	Wall	Depth	Metres	Pumping test me		Down F	Recovery
	57 20,3	Centime	'	- 1 - 1	thickness centimetres	From	То	Submencib Pump intake set	le min 1	Metres min	Metres
					Casing			(metres) 9,0	7 Level X	.89	3.04
		15.5		Fibreglass Concrete	0,48	0	31.51	(litres/min)	50	20 1	2,89
Water Water found at Metres	Record Kind of Wate		Galvaniz	ed	- , , ,		37,37	Duration of pumpi	- 1 - 13	17 2	
1 (20)	Fresh Sulph		Steel Plastic	Fibreglass				Final water level	end o 2	,12 3	
Gas Other:	Salty Miner	als	Galvaniz					of pumping 3.0		10 4	1
	Fresh Sulph		Steel	Fibreglass				type. Zhallow Recommended po	Deep		
Gas Other:	Salty Miner	als	Galvaniz					depth. 9 , 69 me	etres	10 5	
	Fresh Sulph	******	de 🗀		Screen			Recommended purate. 4/5,5 (litres/min)	10 3. 15 3.	0 f 10 0 y 15	
Other:		diar	J Sieei L	Steel Fibreglass Slot No. Plastic Concrete				If flowing give rate	20 3	04 20	
After test of well Clear and se		5	Galvaniz	Galvanized				(litres/min) If pumping discont ued, give reason.	25 <u>3</u> , in- 30 2	04 25	
Other, specif	y			No Casing or Screen				ued, give reason.	40 3,	04 40	
Chlorinated 📑	Yes No	15.5	5 A open ho	le		31,51	32,42		50 3. 60 3.	64 50 64 60	
	Plugging and			Annula		andonment			on of Well		
Depth set at - Me	o Iviateriai arii			, neat cement slurry) etc. Volume Placed (cubic metres)			In diagram below show distances of well from road, lot line, and buil Indicate north by arrow.				ilding.
0 7,5	5 (62)	npn	t	rest	120	K_{S}	-	17	wy	7//	THE RESERVE THE PROPERTY OF TH
								\overline{a}			
		The state of the s						5 5			
		Method	of Construct	ion				2			
Cable Tool		ary (air)		Diamond		Digging			~ 1		,
Rotary (conve	, ===	percussion ng		Jetting Driving		Other			wdco	1 m - 5	Ź,
mestic	∏Indu		ater Use	Public Supp	lv	Other		R	endce		
Stock	Con	nmercial licipal		Not used	ir conditioning	Other			TISI	nétre	
		Final	Status of We		Conditioning		Audit No.	71657	Date Well Co	' YYYY	MM DD 04 26
Water Supply Observation w	Recharg rell Abandor	e well ied, insufficie		Unfinished Dewatering	Abando	ned, (Other)	Was the well ow package delivered		Date Delivere	2007	MM DD
Test Hole	Abandon	ed, poor qua		Replacemer				Ministry	Use Only		
Name of Well Co			// 0	// We	ell Contractor's L	cence No.	Data Source		Contractor	000	3
Business Address	s (street name, n		۶)	ing	600	2	Date Received	YYYY MM DD	Date of Inspec	ction _{YYYY}	MM DD
Name of Well Tec	P - 5 + chnician (last nam	ne, first name	•	- 02 We	ell Technician's L		MAY 0 Remarks	9 200/	Well Record I	Number	
Signature of Tech	5 / € nnician/Contracto	5 n d	y ras	- Dat	e Submitted YYYY	S MM DD					
0506E (08/2006)	· //	ng'			2007	0426			to format	nt dinn ''- '	on france
U0/2006)					Winist	y's Copy	7	Cei	tte formule es	ы иівропівіе	ын ıғапçаis

Well ID Number: 7266180 Well Audit Number: *Z197003* Well Tag Number: *A131930*

This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	100 ENTREPRENEUR CRESCENT
Township	CUMBERLAND TOWNSHIP
Lot	024
Concession	CON 11
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	OTTAWA
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 465761.00 Northing: 5020502.00
Municipal Plan and Sublot Number	
Other	_

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To
BRWN	LOAM			0 m	.2 m
GREY	CLAY			.2 m	2.75 m
GREY	CLAY			2.75 m	4 m
BLUE	CLAY			4 m	7 m

Annular Space/Abandonment Sealing Record

Depth	Depth	Type of Sealant Used (Material and Type)	Volume
From	To		Placed
0 m	2.5 m	ELASTIC CLAY	

Method of Construction & Well Use

Method of Construction	Well Use
Digging	Commercia
	Domestic

Status of Well

Water Supply

Construction Record - Casing

Inside	Open Hole or material	Depth	Depth
Diameter		From	To
	PLASTIC	0 m	7.5 m

Construction Record - Screen

Outside Diameter Material Depth Depth From To 0 m 3 m

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 6667

Results of Well Yield Testing

CLEAR
N

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind
	Fresh

Hole Diameter

Depth From	Depth To	Diameter		
0 m	3 m	6 m		
3 m	5 m	4 m		
5 m	7 m	4 m		

Audit Number: Z197003

Date Well Completed: March 23, 2015

Date Well Record Received by MOE: July 11, 2016

Updated: June 28, 2018 Rate <u>Rate</u> Share <u>facebook twitter Print</u>

Mandy Witteman

From: Public Information Services <publicinformationservices@tssa.org>

Sent: July-16-18 3:45 PM **To:** Mandy Witteman

Subject: RE: Search Records Request (PE4387)

Good afternoon Mandy,

Thank you for your request for confirmation of public information.

I have searched the below noted addresses and I have located the following record:

Inst	Context	Address	City	Province	Postal	Status
Number					Code	
9189889	FS GASOLINE STATION - SELF SERVE	5495 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	EXPIRED
9995453	FS GASOLINE STATION - FULL SERVE	5495 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	EXPIRED
10092079	FS GASOLINE STATION - FULL SERVE	5495 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active
11292691	FS LIQUID FUEL TANK	5495 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active
11292649	FS LIQUID FUEL TANK	5495 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active
11292671	FS LIQUID FUEL TANK	5495 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active
11292709	FS LIQUID FUEL TANK	5495 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active
11571736	FS LIQUID FUEL TANK	5495 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active
9310504	FS PRIVATE FUEL OUTLET - SELF SERVE	5425 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active
10901268	FS LIQUID FUEL TANK	5425 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active
10901283	FS LIQUID FUEL TANK	5425 BOUNDARY RD	CUMBERLAND	ON	K4B 1P6	Active

11372189	FS LIQUID FUEL	5425	CUMBERLAND	ON	K4B 1P6	Active	
	TANK	BOUNDARY					
		RD					

For a further search in our archives or for copies of documents, please complete our release of public information form found at https://www.tssa.org/en/about-tssa/release-of-public-information.aspx? mid =392 and email the completed form to publicinformationservices@tssa.org or through mail along with a fee of \$56.50 (including HST) per location. The fee is payable with credit card (Visa or MasterCard) or with a Cheque made payable to TSSA.

Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Kind regards,

Yalini

From: Mandy Witteman < MWitteman@Patersongroup.ca>

Sent: July 13, 2018 2:03 PM

To: Public Information Services < publicinformationservices@tssa.org>

Subject: Search Records Request (PE4387)

Good afternoon,

Could you please complete a search of your records for underground/aboveground storage tanks, historical spills or other incidents/infractions for the following addresses in the City of Ottawa:

Boundary Rd: #5494, 5495, 5485, 5510, 5507 and 5425

Indcum Rd: 145, 120, and 140

Thank you very much!

Best Regards,

Mandy Witteman

patersongroup

solution oriented engineering

154 Colonnade Road South Ottawa, Ontario, K2E 7J5 Tel: (613) 226-7381 Ext. 339

Fax: (613) 226-6344

Email: mwitteman@patersongroup.ca

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise

protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.





www.tssa.org

26 September 2018

Mandy Witterman PATTERSON GROUP 154 Colonnade Road OTTAWA ON K2E 7J5

Subject: 5425 Boundary Road, Cumberland

Your File No.: PE4387 SR No.: 2368706

Dear Madam/Sir:

We are in receipt of your correspondence wherein you requested information regarding the above noted subject.

A search of our records produced the attached Fuels Safety documents.

The Technical Standards and Safety Act and associated regulations do not require the registration of private fuel outlets. Nor does it require that any documentation on these facilities be submitted to or reviewed or approved by TSSA. As a result, TSSA has limited information on these facilities. TSSA cautions that any information provided may be inaccurate, incomplete or out of date.

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.


Trusting the attached satisfies your request; however, should you have any questions, please contact Public Information at publicinformationservices@tssa.org.

Yours truly,

Yalini Kanagendran

Public Information Services

Yalini Kanagendran



Installed Date	06-JUL-1990 Ins	stalled Time 0:00
Time format is HH24:MM		
	Change in installed date does no	ot change contract date.
Туре	✓ Go	
Order		
Sales Order Number	S	Sales Order Date
Sales Order Line		
Purchase Order Number		Agreement Name
Item Flags		
	✓ BOM Enabled	
	☑ IB Trackable	Inventory Trackable
	✓ Sellable	☐ Shippable
Item Views		
	☐ Merchant	Customer
Descriptive Flexfields		
Context Value	FS Facility	<u> </u>
	Select Context Value and click 'C	Go' to show relevant fields.
Facility Type 2		9
Facility Type 3		<u> </u>
Total Capacity - Liquid Fuel Tanks (L)	49900	
. , , ,		
Total Capacity - Propane Tank s (USWG)		
* Previous Facility Type		9
Previous Instance Number		<u> </u>
Item Instances Home	Profile Sign Out Help	



📅 Navigator 🙀 Favorites Home Logout Preferences Help

Other Item

Transaction

<u>History</u> <u>Item Instance</u> <u>History</u>

Contracts

Orders and

Relationship

Graphically

OMS Orders

Directives

View

<u>Orders</u>

Instance Details

Operating Units

Service Requests

Item Instance | Counters | Mass Update | Item Instances | Systems | Transactions

Item Instances | Systems | Harisactions

Item Instance: Item Instance > Item Instance Search >

View: Item Instance: 10901268

Item **FS LIQUID FUEL TANK** System

Item Description FS Liquid Fuel Tank Owner REGENT POMERLEAU LTD

Account Number 145486

General Location Associations Configuration Counters Notes

External Reference New Version Label
Organization TSSA Item Master Last Version Label 1

Revision Creation Date **06-Jul-1990 00:00:00**

Instance Name Status Active

Quantity 1 Install Date 06-Jul-1990 00:00:00

UOM Each Expiration Date

UOMEachExpiration DateItem Instance TypeShipped On DateItem ConditionReturn By Date

Accounting Classification Customer Product Actual Return Date

Operational Status Code Not Used

■ Show Additional Attributes

Hide Instance Flex Fields

Fuel Type1 Diesel

Fuel Type2 Fuel Type3

Capacity (L) **22700**

Tank Material Fiberglass (FRP)

Fiberglass (FRP)

Tank Type Single Wall UST

Single Wall UST

FS Corrosion Protection **Fiberglass**

Fiberglass

Overfill Protection Type

Installation Year 1992

ULC Standard Manufacturer Model

Serial Number

Description UNDERGROUND

TANK

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help



👚 Navigator 🖳 Favorites

Home Logout Preferences Help

Other Item

History Item Instance History

Contracts

Orders and

Graphically

OMS Orders

Directives

<u>Orders</u>

<u>Transaction</u>

Instance Details

Operating Units

Service Requests

View Relationship

Item Instance Counters Mass Update

Item Instances Systems Transactions

Item Instance: Item Instances > Item Instance Search >

View: Item Instance: 10901283

Item FS LIQUID FUEL TANK System

Item Description FS Liquid Fuel Tank Owner REGENT POMERLEAU LTD

Account Number 145486

General Location Associations Configuration Counters Notes

External Reference New Version Label
Organization TSSA Item Master Last Version Label 1

Revision Creation Date **06-Jul-1990 00:00:00**Instance Name Status **Active**

Quantity 1 Status Active

UOM Each Expiration Date

Item Instance Type Shipped On Date

Item Condition Return By Date
Accounting Classification Customer Product Actual Return Date

Operational Status Code Not Used

⊞ Show Additional Attributes

Hide Instance Flex Fields

Fuel Type1 **Diesel**

Diesel

Fuel Type2 Fuel Type3

Capacity (L) **13600**

Tank Material Fiberglass (FRP)

Fiberglass (FRP)

Tank Type Single Wall UST

Single Wall UST

FS Corrosion Protection **Fiberglass**

Fiberglass

Overfill Protection Type

Installation Year 1985

ULC Standard Manufacturer Model Serial Number

Description UNDERGROUND

TANK

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help



navigator 🦣 Favorites

Home Logout Preferences Help

Item Instance Counters Mass Update

Item Instances Systems Transactions

Item Instance: Item Instances > Item Instance Search >

View: Item Instance: 11372189

Item **FS LIQUID FUEL TANK** System

Item Description FS Liquid Fuel Tank Owner REGENT POMERLEAU LTD

Account Number 145486

General Location Associations Configuration Counters Notes

External Reference New Version Label
Organization TSSA Item Master Last Version Label 1

Revision Creation Date 06-Jul-1990 00:00:00

Instance Name Status Active

Quantity 1 Install Date 06-Jul-1990 00:00:00

UOM Each Expiration Date

Item Instance Type
Item Condition

Each

Expiration Date
Shipped On Date
Return By Date

Accounting Classification Customer Product Actual Return Date

Operational Status Code Not Used

Item Instance
History

History
Operating Units
Contracts

Other Item

History

<u>Transaction</u>

Instance Details

Orders
Service Requests
Orders and

<u>Directives</u> <u>View Relationship</u> Graphically

Graphically OMS Orders

Hide Instance Flex Fields

Show Additional Attributes

Fuel Type1 **Diesel**

Diesel

Fuel Type2 Fuel Type3

Capacity (L) **13600**

Tank Material Fiberglass (FRP)

Fiberglass (FRP)

Tank Type Single Wall UST

Single Wall UST

FS Corrosion Protection **Fiberglass**

Fiberglass

Overfill Protection Type

Installation Year 1985

ULC Standard Manufacturer Model

Serial Number

Description UNDERGROUND

TANK

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help



14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario M8X 2X4

Fuel Safety Inspection Report

Ph - (416) 734-3300, Fax - (416) 231-1626 Toll - 1-877-682-8772

1 Report Number: FS-2002-0001361

Technical Standards and Safety Act, 2000 2 File Number: FS PIN 2002-01361 3 Location Address 4 License/Serial Number 5 Job Type Inspection Date Periodic Inspection (FS) **5425 BOUNDARY RD** 0001028875-C Mar 06, 2006

CUMBERLAND TWP, ON K4B 1P6 CANADA 7 Facility Type

Gasoline Station - Self Serve

8 Client **REGENT POMERLEAU LTD 5425 BOUNDARY RD CUMBERLAND, ON K4B 1P6**

1.1.4.

The Facility/Equipment is inspected in accordance with Ontario's Technical Standards & Safety Act and the appropriate regulations and codes. When an Inspector's order is issued, time limits for compliance reflect the severity of the violation and serve to avoid disruption of service. In the interim period the recipient must ensure that additional precautions are taken for safe use.

10 Code 11 9 Order Compliance Order Issued To No. Section Date LFHC 4.5.1.8. Apr 22, 2006 No corrosion protection and/or does not meet standard - Steel piping and vent lines in direct contact with backfill shall be provided with corrosion protection in accordance with ULC Standard S603.1 or with an impressed current cathodic protection system. LFHC 2.3.1.3. Record of corrosion test missing/test failed Apr 22, 2006 - The corrosion protection system for an underground storage tank system shall be tested and certified in writing to be in working order by a professional engineer or by a person with qualifications approved by the Director, at intervals exceeding two (2) years. The record of testing and certification shall be retained in accordance with sections 1.1.3 and

INSPECTION NOTE: ON SITE TO INSPECT PFO INSPECTORS INSTRUCTIONS ISSUED.

- * Note: This report is eligible for the Voluntary Compliance option. Should you choose to exercise it, please adhere to the following procedure:
- 1. All Inspectors orders appearing on the inspection report must be complied with.
- 2. The recipient must complete the Voluntary Compliance Option box. After complying with the above conditions, this inspection report must be returned directly to TSSA head office via fax or mail, by the last compliance date appearing on the inspection report.
- 3. Should TSSA fail to receive the Voluntary Compliance Form by the compliance date, an inspector will re-inspect and bill at double our normal rate.

For more information please contact TSSA at the number above or toll-free at 1-877-682-8772. It is an offence to knowingly make a false statement or to furnish false information under the Act, the Regulations or a Ministers order. (Technical Standards and Safety Act, 2000; Sect 37)

X Yes No	*Please, refer to guidelines						
pection report have been completed.	I hereby confirm that all the Inspector's orders, appearing on this inspection report have been completed.						
Print Name Client Signature							
	Client Signatur						

David Norman (613) 284-8296 Inspector Inspector Fax Number



FS 09181/(12/99)

Inspector's Report - Part A

Issued under Ontario's Energy Act and/or Gasoline Handling Act

-	-	
Re	port	Nο
, 10	port	140

E-053220

PLEA					PRINT				0 557 52 0
Location Inspected	Location Inspected				Owner's Name)			
O. n. core	^ ()								
Address Address					Address				
5425 BOWNDARYRD					Address				
City/town	City/town								
20000000					City/town				
Postal Code	Postal Code Tel. No.				De stal O. A.				
	K4B-186	822 12			Postal Code			Т	el. No.
Operator's Name	N40-166	822 12	/ (Fuel Constinu				
Sporator o Hamo	- 1 t/				Fuel Supplier			C	City
Licence No.									
0001028	875								
Contractor					Registration N	•			
					negistration N	0.			
		r							
OPERATION/SUB	LOC TYPE	POP DEN	FUEL		CLASS	REASO	N	TRIGGER	ACTION
20	02	01	DIESEL		03	26		02	
ACT	REG	DURATION	TRAVEL		BILLABLE	BILL		OCC RATE	CAUSE
ISSA	217 02	1.5	0		1.5	(1) 2	3	OOO HATE	CAUSE
CON FACT	OCC DATE	OCC TIME	FIELD 1		SITE REM	Yes	COM	PLETED?	Yes
						□ No			□ No
Investigation/Au	dit/Occurrence Su	ummary			-	0			2
		ON	SITE T	<u>ں</u>	INSPEC	TITR	IVATI	E FUEL F	ACICITY
ALL IN C	OM PCIANCE	AT IN	me of	-	MSP RCT 100				. 0
				-					
1 0	11								
NOTE POSTAL	CODE								
Equipment/Applia	ince/Component				Equipment/Ap	nlianos/C	omnon	ant	
Туре	ince/component					риансе/С	ompon	ient	
Турс			-		Туре				
Description					Description				
						AD	DSRSA		No
Manufacturer					Manufacturer	STANDAM	-11/1	ETYAUT	*
Model		Serial No.			Model	PREC	EIVE	D TO	- 120 - 120
Wodel					Model		0 7 2	002 Serial	No.
Material		2000			Material	MAY	U 1 L	UUL	
					1	-		TV S	14
Material Fuel Input Rating MAY Fuel Input Rating				Fuel Input Ration PORATE SERVICES DIVISION					
Date of Manufacture						PORATE	SERVIC	ESU	2.10
Date of Manufacture					Date of Manufac	ture			
Installation Date					Installation Date				å
					motalitation Bate			2	*
Supply Pressure Manifold Pressure				Ì	Supply Pressure			Manifold Press	sure
	As a not-for-profit regulatory authority, the Technical Standards and Safety Authority operates on a cost recovery basis.								
As a not-for-p	rotit regulatory au	athority, the Tec	hnical Stand	arc	is and Safety A	uthority o	perates	s on a cost recov	ery basis.
Cliento Pierra				sue	ed for this activ	11			
Client's Signature		Inspecto	k's Name			Badge	#	Date of Ins	spection

Badge #

Les demandes d'une version française du présent document seront prises en considération.

Date of Inspection 2002 05 02

Inspector's Name



Ministry of Consumer and Commercial Relations

Ministère de la Consommation et du Commerce Technical Standards Division Division des normes techniques 'rspection and breement anch Direction de l'inspection et de l'application des mesures législatives

Rapport de l'inspecteur/inspectrice

Part A/Partie A

Report #/Nº de rapport :

D- 17482

D

ì	Lacation Income at all	111000000000			001 -	5	1	232		×=		
	Location Inspected/	Pome	-52 L	All	DATA	EN.		Owner's Na	me / N	Nom du/de la prop		
	Address/Adresse				A STATE OF THE PARTY OF THE PAR			Address/Ad	resse			
8	City/town/Ville Cum Bermula Twp						, as soon releases					
	City/town/Ville	umber	1.00	D =	-CUP			City/town/V	ille			
	Total Cook Cook Poolar						F	Postal Code	e/Code	e postal		Tel.No. /Nº de tél.
1	Contator's Name (No	om de la personne re		h.l.			L	F 10 "				
	Operator's Name/No	om de la personne re	esponsai	ole				Fuel Suppli	er/Fou	rnisseur de coml	oustible	City/Ville
	Licence #/№ de permis							PE-	Tle	CAN AL) A 5	TRUP
	Contractor/Entrepreneur							Registration	ı #/Nº	d'inscription		
	OPERATION/ACTIVITÉ	SUB TYPE/ SOUS-TYPE	LOC TY TYPE D	PE/ DE LIEU	POP DENS/ DENS. DE POP	9		FUEL/ COMBUSTIBL	B (EL	CLASS/ CATEGORIE	REASON/ RAISON	TRIGGER/ MOTIVÉ PAR :
	ACTION/ MESURES PRISES	ACTLOI G +1 A	/	GLEMENT 143	DURATION/ DURÉE)	Ì	BILLABLE/ A FACTURER		TRAVEL/ DÉPLACEMENT	BILL Y/N FACTURER (O/N)	
	DAMAGE/ DOMMAGES	OCC RATE/ GRAV. DE L'ACC.	CAUSE		CON FACT/ FACT. CONTR.		Ì	OCC DATE/ DATE DE L'AC	CC.	OCC TIME/ HEURE DE L'ACC.	MANDATED Y/N MANDAT (0/N)	
	FIELD 1/ DOMAINE 1	CALL/ INTERVENTION	CONSUI	LT. (O/N)	SITE REM YA	'N)/N)						F/U REQ'D? Y/N SUIVI REQUIS? (O/N)
	Comments/Remarques											
	Phease	Amar	00	46A	LESS.							
-												
L												
E	quipment/Applian				/Composant		E	quipment/	Applia	ance/Compone	nt / Matériel/App	areil/Composant
	Туре/Туре		Code/C	ode	-		Type/Type Code/Code					
	Description/Descripti	on					Description/Description					
	Manufacturer/Fabrica	ant					Manufacturer/Fabricant					
	Model/Modèle	Sei	rial #/Nº	de série			Model/Modèle Serial #/N° de série					
	Material/Matériel						١	Material/Mat	ériel	THEC	FIVED	
	Corrosion Protection	Protection contre la	corrosio	'n						on/Protection con	=	
	Fuel Input Rating/Débit de combustible					F	Fuel Input Ra	ating/[Dépit de AMGust	1995 Gelei		
	Capacity/Capacité				(Capacity/Cap	pacité	Technical St	andards Division			
	Installation Date/Date	d'installation					li	nstallation D	ate/Date	ate d'installation		
L	Manufacture Date/Date de fabrication				N	Manufacture	Date/	Date de fabrication	n			
	Supply Pressure/ Pression d'alimentation		old Press on d'adn				F	Supply Press Pression d'al	sure/ imenta		Manifold Pressure/ Pression d'admissi	
1	Client's Signature / Sig	nature du client/de la	cliente	Inspector's	Name / Nom de	e l'in:				Badge #/Nº d'ins		
	Sergo ERIC								Date of Inspecti Date de l'inspec	on/	Y/A M/M D/J S 0 7 2 6	
_	2200					_			III.III.			



Technica Standards Division

Division des normes techniques

Inspection and Enforcement Branch

Direction de l'inspection et de l'application des mesures législatives Inspector's Intions/Orders
Directives et ordres de l'inspecteur/inspectrice
Part B/Partie B

Report #/N° de rapport :

D17482

00097089

Date: 1995 07 26

Location Address (No HH's) Adresse du lieu inspecté (pas de RR) Superinte de l'europélivré à Position/Fonction KOA (KO)								
Issued To/Déli		E POMER	vea u	1	Position/Fonction	K	OAIKO	
Mailing Address/Adresse postale								
Your attention Ces ordres ou	Your attention is required pursuant to: Act Ces ordres ou directives vous sont donnés en vertu: Act de la Loi Regulation du Règlement 5 2 4 3							
Licence # Nº de permis	EX 27 8 2010	xpiry/Expiration Registration # Nº d' inscription	Expir	y/Expiration	Certificate # Nº de certificat		Expiry/Expiration	
CALL/INTERVENTION	ACTION/MESURES PRISES	DURATION/DURÉE	BILLABLE/À FACTURER	TRAVEL/DÉPL	ACEMENT	BILL Y/N / F	FACTURER (O/N)	
Order #/ N° de l'ordre	Section/ Article	You are here Vous deve	eby instructed to correct the z rectifier l'infraction ou le	ne following s infraction:	infraction(s)/ s suivantes.		Compliance Date/ Date limite d'exécution	
1	8612)	NA. NTA. J				<u> </u>		
		LENKTH C	F 6 N F -	0 6 6	on so hit care A	31	. ,	
		RETCACTOR	1 6 00	KTDR	COLLETTE		Aug 11/95	
	G	LE LLACTOR	1 4.0 101	id ca	3 WITHE)CCI,	149	
	<15. Vh. Vh. Vh. Vh. Vh. Vh. Vh. Vh. Vh. Vh	FROUDE PR	5766	0.4	1 1 1 1 1 1 1		/	
	0 0 100/07/07/07/07/07/07/07/07/07/07/07/07/0	100116	SIECTION 1	(,0)(V (MANIC			
		FOR VENT					Aug 11/95	
5	195 10 IVO	Collect Le	CoLour	(C).	D = 0		1	
>	GE 15 (1/6)	Coered he	AKINDIE	SEL	DISLEMSE	-6	Aug 1/95	
=								
			14					
				_				
				1.				
				/s				
			<u> </u>					
Received By: Reçu par : (e	(print) n lettres moulées	SERGE.	Inspector: (print) Inspecteur(trice)	: (en lettre	s moulées)		9 4	
Position:/Fon			Signature :	, ,			5	
Signature:		Sergol		Inspector's Badge#: Nº d'insigne de l'inspecteur(trice) :				
			-			Page_	of/de	



345 Carlingview Drive Toronto, Ontario M9W 6N9 Tel.: 416.734.3300 Fax: 416.231.1626 Toll Free: 1.877.682.8772

www.tssa.org

26 September 2018

Mandy Witterman PATTERSON GROUP 154 Colonnade Road OTTAWA ON K2E 7J5

Subject: 5495 Boundary Road, Cumberland

Your File No.: PE4387 SR No.: 2368706

Dear Madam/Sir:

We are in receipt of your correspondence wherein you requested information regarding the above noted subject.

A search of our records produced the attached Fuels Safety documents.

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.


Trusting the attached satisfies your request; however, should you have any questions, please contact Public Information at publicinformationservices@tssa.org.

Yours truly,

Yalini Kanagendran


Public Information Services

Yalini Kanagendran




	Installe Tim	
Time format is HH24:MM	1111	ie
	Change in installed date does not change	contract date.
Туре	∨ Go	
Order		
Sales Order Number	Sales Orde Dai	
Sales Order Line		
Purchase Order Number	Agreemei Nam	
Item Flags		
	☑ BOM Enabled	
	☑ IB Trackable	☐ Inventory Trackable
	✓ Sellable	Shippable
Item Views		
	☐ Merchant	Customer
Descriptive Flexfields		
Context Value	FS Facility	
	Select Context Value and click 'Go' to show	w relevant fields.
Facility Type 2		9
Facility Type 3		
,	400000	
Total Capacity - Liquid Fuel Tanks (L)	109200	
Total Capacity - Propane Tank s (USWG)	0	
* Previous Facility Type		•
Previous Instance Number		

Item Instances Home Profile Sign Out Help



Installed Date	03-JUN-1993	Installed Time 0:00
Time format is HH24:MM		
	Change in installed date do	oes not change contract date.
Туре	∨ Go	
Order	r	
Sales Order Number		Sales Order Date
Sales Order Line		
Purchase Order Number		Agreement Name
Item Flags	r	
	☑ BOM Enabled	
	✓ IB Trackable	☐ Inventory Trackable
	✓ Sellable	☐ Shippable
Item Views		
	☐ Merchant	✓ Customer
Descriptive Flexfields	r	
Context Value	FS Facility	4
		l click 'Go' to show relevant fields.
Facility Type 2		
racincy Type 2		
Facility Type 3		•
Total Capacity - Liquid Fuel Tanks (L)		
Total Capacity - Propane Tank s (USWG)		
* Previous Facility Type		
Frevious Facility Type		
Previous Instance Number		•
Item Instances Home	Profile Sign Out Help	



Installed Date	06-JUN-1989	Installed Time 0:00
Time format is HH24:MM		
	Change in installed date d	oes not change contract date.
Туре	∨ Go	
Order	r	
Sales Order Number		Sales Order Date
Sales Order Line		
Purchase Order Number		Agreement Name
Item Flags	r	
	☑ BOM Enabled	
	✓ IB Trackable	☐ Inventory Trackable
	✓ Sellable	☐ Shippable
Item Views		
	☐ Merchant	✓ Customer
Descriptive Flexfields	r	
Context Value	FS Facility	Q
		l click 'Go' to show relevant fields.
Facility Type 2		
Facility Type 3		•
Total Capacity - Liquid Fuel Tanks (L)		
Total Capacity - Propane Tank s (USWG)		
		_
* Previous Facility Type		4
Previous Instance Number		
		*
Item Instances Home	Profile Sign Out Help	
itelli ilistalices Hollie	r rome olgir out Help	



🟗 Navigator 🙀 Favorites Home Logout Preferences Help

Other Item
Instance Details

Transaction

<u>Item Instance</u> <u>History</u> <u>Operating Units</u>

History

Contracts

Orders and

Relationship

Graphically

OMS Orders

Directives

View

<u>Orders</u>

Service Requests

 Item Instance
 Counters
 Mass Update

 Item Instances
 Systems
 Transactions

Item Instance: Item Instance > Item Instance Search >

View: Item Instance: 11292691

Item **FS LIQUID FUEL** System

TANK Owner ANIVIC ENTREPRISE INC O/A

Item Description FS Liquid Fuel LUSO GAS

Tank Account Number 15988

General Location Associations Configuration Counters Notes

External Reference New Version Label
Organization TSSA Item Master Last Version Label 1

Revision Creation Date 19-Jul-2000 20:15:15

Instance Name Status Active

Quantity **1** Install Date **03-Jun-2009 00:00:00**

UOM **Each** Expiration Date Item Instance Type Item Condition Return By Date

Accounting Classification Customer Product Actual Return Date

Operational Status Code Not Used

☐ Hide Instance Flex Fields

☐ Show Additional Attributes

Fuel Type1 Diesel
Fuel Type2
Fuel Type3

Capacity (L) **25000**Tank Material **Steel**Steel

Tank Type Single Wall UST

Sacrificial anode

FS Corrosion Protection Sacrificial anode

Overfill Protection Type

Installation Year ULC Standard

Manufacturer Model Serial Number

Description 2009VBS

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help



🟗 Navigator 🙀 Favorites Home Logout Preferences Help

Other Item Instance Details

Transaction

Item Instance
History
Operating Units

Service Requests Orders and

View Relationship

<u>History</u>

<u>Contracts</u>

Directives

Graphically

OMS Orders

<u>Orders</u>

Item Instance Counters Mass Update

Item Instances Systems Transactions

Item Instance: Item Instances > Item Instance Search >

View: Item Instance: 11292709

Item **FS LIQUID FUEL** System

TANK Owner ANIVIC ENTREPRISE INC O/A
Item Description FS Liquid Fuel LUSO GAS

Tank Account Number 15988

General Location Associations Configuration Counters Notes

External Reference New Version Label
Organization TSSA Item Master Last Version Label 1

Revision Creation Date 19-Jul-2000 20:15:15

Instance Name Status Active

Quantity **1** Install Date **03-Jun-2009 00:00:00**

UOM **Each** Expiration Date
Item Instance Type
Item Condition Return By Date

Accounting Classification **Customer Product** Actual Return Date

Operational Status Code Not Used

■ Hide Instance Flex Fields

Fuel Type1 Gasoline

Gasoline

Fuel Type2

Fuel Type3
Capacity (L) 15000
Tank Material

Tank Material Steel

Tank Type Single Wall UST

Single Wall UST

FS Corrosion Protection Sacrificial anode

Sacrificial anode

Overfill Protection Type

Installation Year 1989

ULC Standard Manufacturer Model Serial Number

Serial Number

Description 2009VBS ETHANOL

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help



Navigator Favorites Home Logout Preferences Help

> **Other Item Instance Details**

Transaction

Item Instance <u>History</u> **Operating Units**

Service Requests Orders and

View Relationship

<u>History</u>

<u>Contracts</u>

Directives

Graphically

OMS Orders

<u>Orders</u>

Item Instance Counters Mass Update **Item Instances** | Systems | Transactions

Item Instance: Item Instance > Item Instance Search >

View: Item Instance: 11292649

Item FS LIQUID FUEL System

TANK Owner ANIVIC ENTREPRISE INC O/A Item Description FS Liquid Fuel **LUSO GAS**

Account Number 15988 **Tank**

General Location Associations Configuration Counters Notes

External Reference New Version Label Organization TSSA Item Master Last Version Label 1

Revision Creation Date 19-Jul-2000 20:15:15

Instance Name Status Active

Quantity 1 Install Date 03-Jun-2009 00:00:00

UOM Each **Expiration Date** Item Instance Type Shipped On Date Item Condition Return By Date

Accounting Classification Customer Product Actual Return Date

Operational Status Code Not Used

■ Show Additional Attributes Hide Instance Flex Fields

Fuel Type1 Gasoline

Fuel Type2

Fuel Type3

Capacity (L) 35000 Tank Material Steel

Tank Type Single Wall UST Single Wall UST

FS Corrosion Protection Sacrificial anode

Sacrificial anode

Overfill Protection Type

Installation Year 1989

ULC Standard Manufacturer Model Serial Number

Description 2009VBS REGULAR

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help



> Other Item Instance Details

Transaction

Item Instance
History
Operating Units

Service Requests Orders and

View Relationship

<u>History</u>

<u>Contracts</u>

Directives

Graphically

OMS Orders

<u>Orders</u>

Item Instance Counters Mass Update

Item Instances Systems Transactions

Item Instance: Item Instances > Item Instance Search >

View: Item Instance: 11292671

Item **FS LIQUID FUEL** System

TANK Owner ANIVIC ENTREPRISE INC O/A
Item Description FS Liquid Fuel LUSO GAS

Tank Account Number 15988

General Location Associations Configuration Counters Notes

External Reference New Version Label
Organization TSSA Item Master Last Version Label 1

Revision Creation Date 19-Jul-2000 20:15:15

Instance Name Status Active

Quantity 1 Install Date 03-Jun-2009 00:00:00

UOM Each Expiration Date
Item Instance Type
Item Condition Return By Date

Accounting Classification
Customer Product
Actual Return Date

Operational Status Code Not Used

■ Hide Instance Flex Fields

■ Show Additional Attributes

Fuel Type1 Gasoline

Gasoline

Fuel Type2

Fuel Type3

Capacity (L) **25000**Tank Material **Steel**

Steel

Tank Type Single Wall UST

Single Wall UST

FS Corrosion Protection Sacrificial anode

Sacrificial anode

Overfill Protection Type

Installation Year 1989

ULC Standard Manufacturer

Model

Serial Number

Description 2009VBS REGULAR

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help



> Other Item Instance Details

Transaction

Item Instance
History
Operating Units

Service Requests Orders and

View Relationship

<u>History</u>

<u>Contracts</u>

Directives

Graphically

OMS Orders

<u>Orders</u>

Item Instance Counters Mass Update

Item Instances Systems Transactions

Item Instance: Item Instances > Item Instance Search >

View: Item Instance: 11571736

Item **FS LIQUID FUEL** System

TANK Owner ANIVIC ENTREPRISE INC O/A
Item Description FS Liquid Fuel LUSO GAS

Tank Account Number 15988

General Location Associations Configuration Counters Notes

External Reference New Version Label
Organization TSSA Item Master Last Version Label 1

Revision Creation Date 19-Jul-2000 20:15:15

Instance Name Status Active

Quantity 1 Install Date 03-Jun-2009 00:00:00

UOM **Each** Expiration Date
Item Instance Type
Item Condition Expiration Date
Return By Date

Accounting Classification
Customer Product
Actual Return Date

Operational Status Code Not Used

■ Hide Instance Flex Fields

■ Show Additional Attributes

Fuel Type1 Gasoline

Gasoline

Fuel Type2
Fuel Type3
Capacity (L) 9200
ank Material Steel

Tank Material Steel

Steel

Tank Type **Double Wall UST**

Double Wall UST

FS Corrosion Protection Sacrificial anode

Sacrificial anode

Overfill Protection Type

Installation Year 1998

ULC Standard Manufacturer Model

Serial Number

Description 2009VBS REGULAR

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help



345 Carlingview Drive Toronto, Ontario M9W 6N9 Toll free 1-877-682-8772 www.tssa.org

FS Inspection Report

Service Request #	1704554
Inspection Report #	7325211

Inspection Address: 5495 BOUNDARY RD CUMBERLAND; ON	Reference Number(s):	Inspection Completion Date: SEP 06, 2018
CA K4B 1P6	Facility Type: FS Gasoline Station - Full Serve	Equipment Type:
Customer Name and Address: ANIVIC ENTREPRISE INC O/A LUSO GAS	Task Type: FS-Follow up LF Inspect	
5495 BOUNDARY RD CUMBERLAND;ON CA K4B 1P6	The facility/equipment is inspected in accordance with Ontario's Technical Standards & Safety Act and the appropriate regulations and codes. When an Inspector's order is issued, time limits for compliance reflect the severity of the violation and serve to avoid disruption of service.	

Orders Issued To: PERSONS ON SITE

Line	Reference and Order(s)	Compliance Date
74034 2-2	Liquid Fuels Handling Code 2007. 2.4.2.1 Where an underground storage tank is out of service for 2 years or more, the owner of the tank system or the owner of the property on which the tank is located shall remove the tank from the ground. THIS SITE HAS NOT BEEN IN USE FOR MORE THAN 2 YEARS TAKES MUST BE REMOVED.	OCT 05, 2018
74034 2-3	Liquid Fuels Handling Code 2007. 8.3.1 Where an underground storage tank(s) has been removed permanently and the property no longer maintains any fuel storage equipment or tank systems, the owner or operator of the facility, the owner or operator of the storage tank systems, or the owner of the property on which the equipment is installed, as the case may be, shall: (a) submit an assessment report to TSSA that delineates the full extent of any petroleum product that has escaped into the environment or inside a building both on site and, where necessary and practical, off site; and (b) immediately notify the Ontario Ministry of the Environment in accordance with the Environmental Protection Act, as amended, and the Ontario Water Resources Act, as amended. This report shall be submitted electronically to: fssubmissions@tssa.org or shall be mailed to:Technical Standards and Safety Authority3300 Bloor Street14th Floor, Centre TowerToronto, Ontario, M8X 2X4NOTE: All submissions MUST be accompanied by a completed Environmental Review Services Form. If the form is incomplete the report will not be reviewed and the file will not be closed. Copies of the form are available at http://www.tssa.org/regulated/fuels/fuelsForms.aspTSSA does not consider the matter resolved and the file closed until written correspondence from the TSSA engineering department has been provided upon review of the report submission.	OCT 05, 2018
74034 2-4	Technical Standards and Safety Act. 37 (1) - Offences Every person who, (a) contravenes or fails to comply with any provision of this Act, the regulations or a Minister's order; (b) knowingly makes a false statement or furnishes false information under this Act, the regulations or a Minister's order; (c) contravenes or fails to comply with a term or condition of an authorization; (d) contravenes or fails to comply with an order or requirement of a director or an inspector, or obstructs an inspector, is guilty of an offence and on conviction is liable to a fine of not more than \$50,000 or to imprisonment for a term of not more than one year, or to both, or, if the person is a body corporate, to a fine of not more than \$1,000,000. 2000, c. 16, s. 37 (1); 2009, c. 28, s. 14 (1). NOTE: In a site inspection done on September 5, 2018 at 5495 Boundry Road in Cumberland of the former Luso Gas station it has revealed that the site is closed. The fuel tanks still remain on site and have not been removed and it in not clear if the fuel has been removed from the tanks.	OCT 05, 2018
	Pursuant to my authority under section 21(2) of the Technical Standards and Safety Act, 2000, S.O. 2000, as the (person, corporation, company, party) with the authority to correct the contravention, I order you to have a persons qualified remove the fuel tanks and complete the Environmental Assessment report by the compliance date as given.	

Customer Signature & Position / Date:		Inspector Name: Hutchinson, Mark	Inspector Contact Number: 613-537-9963
Report Received By:	Customer Contact	Inspector Email:	Inspector Fax:
	Number:	mhutchinson@tssa.org	613-537-5236



345 Carlingview Drive Toronto, Ontario M9W 6N9 Toll free 1-877-682-8772 www.tssa.org

FS Inspection Report

Service Request #	1704554
Inspection Report #	7325211

Inspection Address: 5495 BOUNDARY RD CUMBERLAND; ON	Reference Number(s):	Inspection Completion Date: SEP 06, 2018
CA K4B 1P6	Facility Type: FS Gasoline Station - Full Serve	Equipment Type:
Customer Name and Address: ANIVIC ENTREPRISE INC O/A LUSO GAS	Task Type: FS-Follow up LF Inspect	
5495 BOUNDARY RD CUMBERLAND; ON CA K4B 1P6	The facility/equipment is inspected in accordance with Ontario's Technical Standards & Safety Act and the appropriate regulations and codes. When a Inspector's order is issued, time limits for compliance reflect the severity of the violation and serve to avoid disruption of service.	

Issued on September 6, 2018	

Task Notes

In a site inspection done on September 5, 2018 at 5495 Boundry Road in Cumberland of the former Luso Gas station it has revealed that the site is

The fuel tanks still remain on site and have not been removed and it in not clear if the fuel has been removed from the tanks.

The site has provided NO information to our office as requested.

NEW orders have been issued

ALL INSTRUCTIONS MUST BE COMPLETED BY THE DUE DATE AND SENT TO TSSA OR A BILLABLE FOLLOW UP INSPECTIONS WILL APPLY.

THIS REPORT IS FOR NON COMPLIANCE AUDIT. INSPECTOR HAS ISSUED TIME SENSITIVE INSTRUCTIONS.

TSSA's time involved with this inspection will be billed to the above named client in the form of cost recovery fees by authority of Section 19 of the TSSAct, 2011 and according to TSSA billing policy.

Pursuant to my authority under section 21 of the TSSAct, 2011, you are hereby ordered to comply with the above orders forthwith.

Customer Signature & Position / Date:		Inspector Name: Hutchinson, Mark	Inspector Contact Number: 613-537-9963
Report Received By:	Customer Contact	Inspector Email:	Inspector Fax:
	Number:	mhutchinson@tssa.org	613-537-5236



345 Carlingview Drive Toronto, Ontario M9W 6N9 Toll free 1-877-682-8772 www.tssa.org

FS Inspection Report

Service Request #	1704554
Inspection Report #	5834284

Inspection Address: 5495 BOUNDARY RD CUMBERLAND; ON	Reference Number(s):	Inspection Completion Date: OCT 07, 2015
CA K4B 1P6	Facility Type: FS Gasoline Station - Full Serve	Equipment Type:
Customer Name and Address: ANIVIC ENTREPRISE INC O/A LUSO GAS	Task Type: FS-Periodic LF Inspection	
5495 BOUNDARY RD CUMBERLAND;ON CA K4B 1P6	The facility/equipment is inspected in accordance with Ontario's Tec Standards & Safety Act and the appropriate regulations and codes. V Inspector's order is issued, time limits for compliance reflect the seve the violation and serve to avoid disruption of service.	

Orders Issued To: PERSONS ON SITE

Line	Reference and Order(s)	Compliance Date
74034 2-2	Liquid Fuels Handling Code 2007. 2.4.2.1 Where an underground storage tank is out of service for 2 years or more, the owner of the tank system or the owner of the property on which the tank is located shall remove the tank from the ground. THIS SITE HAS NOT BEEN IN USE FOR MORE THAN 2 YEARS TAKES MUST BE REMOVED.	JUN 23, 2018
74034 2-3	Liquid Fuels Handling Code 2007. 8.3.1 Where an underground storage tank(s) has been removed permanently and the property no longer maintains any fuel storage equipment or tank systems, the owner or operator of the facility, the owner or operator of the storage tank systems, or the owner of the property on which the equipment is installed, as the case may be, shall: (a) submit an assessment report to TSSA that delineates the full extent of any petroleum product that has escaped into the environment or inside a building both on site and, where necessary and practical, off site; and (b) immediately notify the Ontario Ministry of the Environment in accordance with the Environmental Protection Act, as amended, and the Ontario Water Resources Act, as amended. This report shall be submitted electronically to: fssubmissions@tssa.org or shall be mailed to:Technical Standards and Safety Authority3300 Bloor Street14th Floor, Centre TowerToronto, Ontario, M8X 2X4NOTE: All submissions MUST be accompanied by a completed Environmental Review Services Form. If the form is incomplete the report will not be reviewed and the file will not be closed. Copies of the form are available at http://www.tssa.org/regulated/fuels/fuelsForms.aspTSSA does not consider the matter resolved and the file closed until written correspondence from the TSSA engineering department has been provided upon review of the report submission.	JUN 23, 2018

Task Notes

FIND ATTACHED YOUR COPY OF THE THEL SAFETY INSPECTION ON OCT 7 2015. SHOULD YOU HAVE ANY QUESTIONS ABOUT THIS REPORT, CONTACT DAVID NORMAN AT 613-2977422

If you have questions regarding your invoice, when received, contact TSSA billing department by telephone at 1-877-682-TSSA (8772)or customerservices@tssa.org

TRAVEL, SITE INSPECTION DOCUMENTATION AND REPORT PREPARATION BILLED IN ACCORDANCE WITH TSSA POLICY

This inspector has no control over billing.

ON SITE FOR REGULAR AUDIT. SITE OUT OF SERVICE FOR 2 PLUS YEARE ORDERS TO REMOVE TANKS LINES AND COMPLETE AN ENVIRONMENTAL

INSPECTOR HAS ISSUED TIME SENSITIVE INSTRUCTIONS.

THIS IS ASSIGNED AS A FS Declaration of Compliance AND MUST BE FILED OUT AND SENT IN TO ADDRESS OR FAX AT BOTTOM OF FORM.

ALL INSTRUCTIONS MUST BE COMPLETED BY THE DUE DATE AND SENT TO TSSA OR A BILLABLE FOLLOW UP INSPECTIONS

Customer Signature & Position / Date:		Inspector Name:	Inspector Contact Number:
		Norman, David	613-284-8284
Report Received By:	Customer Contact	Inspector Email:	Inspector Fax:
	Number:	DNorman@tssa.org	613-284-8296



345 Carlingview Drive Toronto, Ontario M9W 6N9 Toll free 1-877-682-8772 www.tssa.org

FS Inspection Report

Service Request #	1704554
Inspection Report #	5834284

613-284-8284

Inspector Fax:

	,	,	
Inspection Address:	Reference Number(s):	Inspection Completion Date:	
5495 BOUNDARY RD		OCT 07, 2015	
CUMBERLAND;ON			
CA K4B 1P6	Facility Type:	Equipment Type:	
CA K4D II 0	FS Gasoline Station -		
	Full Serve		
Customer Name and Address:	Task Type:		
ANIVIC ENTREPRISE INC O/A LUSO GAS	FS-Periodic LF Inspection		
5495 BOUNDARY RD	The facility/equipment is inspected in accordance with Ontario's Technical		
CUMBERLAND;ON	Standards & Safety Act and the appropriate regulations and codes. When an		
,	Inspector's order is issued, time limits for compliance reflect the severity of		
CA K4B 1P6	the violation and serve to avoid disruption of service.		
	the violation and serve to avoid	distuption of service.	

WILL APPLY.

YOU ARE ORDERED TO COMPLY WITH THE ABOVE INSTRUCTIONS BY COMPLIANCE DATE AS PER Section 19 of the TSSAct, 2000!

ALL PETROLEUM WORK TO BE COMPLETED BY A LICENSED PETROLEUM MECHANIC!

Every person who,(a) contravenes or fails to comply with any provision of this Act, the regulations or a Minister's order;(b) knowingly makes a false statement or furnishes false information under this Act, the regulations or a Minister's order;(c) contravenes or fails to comply with a term or condition of an authorization;(d) contravenes or fails to comply with an order or requirement of an inspector or obstructs an inspector, is guilty of an offence and on conviction is liable to a fine of not more than \$50,000 or to imprisonment for a term of not more than one year, or to both, or, if the person is a body corporate, to a fine of not more than \$1,000,000.(Technical Standards and Safety Act, 2000, Section 37 (1))

Standard Notes

This Inspection Report contains Inspector's Orders with a compliance date(s) and is eligible for Declaration of Compliance. Documented proof that the order(s) have been complied with before the compliance date must be submitted to TSSA This documented proof shall include, but is not limited to, any of the following where applicable: Photocopies of Licenses, Certificates, Registrations, Invoices, and/or Work Orders, Photographs, and Name, Certificate number, and Signature (where applicable) of the person who has performed the corrective action.

YOU MUST EXERCISE THIS OPTION TO AVOID A FOLLOW UP INSPECTION AND THE ASSOCIATED FEES WHICH WILL RESULT. Reporting requirements are as follows:

1. All Inspector's Orders (directives) appearing on the inspection report must be complied with.

Customer Signature & Position / Date:	Inspector Name:	Inspector Contact Number:	
Submission: Send an EMAIL (dcreporting@tssa.org) or FAX (416-734-6242) complete with the following information 1. The Service Request number from the Inspection Report as the Subject line. 2. A copy of the Inspection Report with the Declaration of Compliance portion completed and attached.			
It is an offence to knowingly make a false statement or to furnish false information Standards and Safety Act, 2000; sect. 37.	under The Act, the regulations of	r a ministers order; Technical	
Contact Email Address Contact Phone N	umber		
SignatureDate			
Title			
Printed Name			
I, the undersigned hereby declare that all orders on this Inspection Report have been	n complied with.		
Declaration of Compliance			
2. A person who has legal signing authority on behalf of the Owner or User must of via EMAIL or FAX on or before the last compliance date appearing on the inspect Note: Declaration of Compliance is subject to an audit process which may result in	on report.	liance and submit this to TSSA	

Number: DNorman@tssa.org 613-284-8296
As a not-for-profit regulatory authority, TSSA operates on a cost recovery basis. An Invoice will be issued for the Total Charges Incurred.

(Note: This is not an invoice)

Norman, David

Inspector Email:

Report Received By:

Customer Contact



345 Carlingview Drive Toronto, Ontario M9W 6N9 Toll free 1-877-682-8772 www.tssa.org

FS Inspection Report

Service Request #	1704554
Inspection Report #	5834284

Inspection Address: 5495 BOUNDARY RD CUMBERLAND; ON	Reference Number(s):	Inspection Completion Date: OCT 07, 2015	
CA K4B 1P6	Facility Type: FS Gasoline Station - Full Serve	Equipment Type:	
Customer Name and Address: ANIVIC ENTREPRISE INC O/A LUSO GAS	Task Type: FS-Periodic LF Inspection		
5495 BOUNDARY RD CUMBERLAND; ON CA K4B 1P6	The facility/equipment is inspected in accordance with Ontario's Technical Standards & Safety Act and the appropriate regulations and codes. When an Inspector's order is issued, time limits for compliance reflect the severity of the violation and serve to avoid disruption of service.		

For more information please contact TSSA at 416-734-3599 or email dcreporting@tssa.org	

Other Charges Detail			
Date	Activity	Qty	Comments
OCT 07, 2015	Billing	1	

Customer Signature & Position / Date:		Inspector Name: Norman, David	Inspector Contact Number: 613-284-8284
Report Received By:	Customer Contact	Inspector Email:	Inspector Fax:
	Number:	DNorman@tssa.org	613-284-8296



14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario M8X 2X4 Toll free 1-877-682-8772 Fax (416) 231-1626 www.tssa.org

FS Inspection Report

Service Request #	988630
Inspection Report #	4233977

Inspection Address: 5495 BOUNDARY RD CUMBERLAND; ON	Reference Number(s):	Inspection Completion Date: JAN 21, 2013	
CA K4B 1P6	Facility Type: FS Gasoline Station - Full Serve	Equipment Type:	
Customer Name and Address: ANIVIC ENTREPRISE INC O/A LUSO GAS	Task Type: FS-Shutdown LF Inspect		
5495 BOUNDARY RD CUMBERLAND;ON CA K4B 1P6	The facility/equipment is inspected in accordance with Ontario's Technical Standards & Safety Act and the appropriate regulations and codes. When an Inspector's order is issued, time limits for compliance reflect the severity of the violation and serve to avoid disruption of service.		

Orders Issued To: ANIVIC ENTREPRISE INC O/A LUSO GAS

Line	Reference and Order(s)	Compliance Date
62721	Liquid Fuels Handling Code 2007. 2.4.2.1	APR 30, 2013
9-1	Where an underground storage tank is out of service for 2 years or more, the owner of the tank system or the owner of the property on which the tank is located shall remove the tank from the ground. 8.3.1	111 10 30, 2013
	Where an underground storage tank(s) has been removed	
	permanently and the property no longer maintains any fuel storage equipment or tank systems, the owner or operator of the facility, the	
	owner or operator of the storage tank systems, or the owner of the	
	property on which the equipment is installed, as the case may be,	
	shall	
	(a) submit an assessment report to TSSA that delineates the full	
	extent of any petroleum product that has escaped into the	
	environment or inside a building both on site and, where	
	necessary and practical, off site; and	
	(b) immediately notify the Ontario Ministry of the Environment in	
	accordance with the Environmental Protection Act, as amended,	
	and the Ontario Water Resources Act, as amended.	
	THE REPORT MUST MEET THE CRITERIA AS SET FORTH IN TSSA Environmental Management Protocol for Operating Fuel	
	Handling Sites in Ontario	
	. THE REPORT SHALL BE SENT TO TSSA WEST TOWER 14Th FLOOR ENVIRONMENTAL OFFICE,	
	3300 BLOOR STREET WEST TORONTO, ONTARIO M8X 2X4 OR E-MAIL TO fssubmissions@tssa.org	

Task Notes			
FIND ATTACHED YOUR COPY OF THE FUEL S	AFETY INSPECTION ON JAN	21 2013. SHOULD YOU H.	AVE ANY QUESTIONS,
CONTACT DAVID NORMAN AT 613-2977422		D. E. E.O. I. O.V. I.I. D. I.I. D. I.I.	
ALL INSTRUCTIONS MUST BE COMPLETED BY	Y THE DUE DATE OR BILLA	BLE FOLLOW UP INSPECT	TIONS WILL APPLY.
ATTEND SITE RE SHUTDOWN ORDER RE SITE	OUT OF SERVICE MORE TH	AN 2 YEARS AS PER ORD	DERS ALL PETROLEUM
EQUIPMENT MUST BE REMOVED	TOO I OF BERVICE MORE III	IIV 2 TEMOS. TISTER ORD	ERS TEETETROEECW
YOU ARE ORDERED TO COMPLY WITH THE A	BOVE INSTRUCTIONS BY CO	OMPLIANCE DATE!	
ALL DETROLEUM WORK TO DE COMPLETED I	DV A LICENSED DETROLEUR	AMEGHANIGI	
ALL PETROLEUM WORK TO BE COMPLETED I	BY A LICENSED PETROLEUM	I MECHANIC!	
"TO BE COMPLETED: BY PETROLEUM MECHANIC DEFICIENCY ORDER # EG 1 2 COMPLETED: ,			
PRINT NAME:, SIGN			
CERTIFICATE #:,			
CERTIFICATE # .			
Customer Signature & Position / Date:		Inspector Name:	Inspector Contact Number:
Castomer Signature to 1 option, 2 and		Norman, David	613-284-8284
Report Received By:	Customer Contact	Inspector Email:	Inspector Fax:
	Number:	DNorman@tssa.org	613-284-8296



14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario M8X 2X4 Toll free 1-877-682-8772 Fax (416) 231-1626 www.tssa.org

FS Inspection Report

Service Request #	988630
Inspection Report #	4233977

Inspection Address:	Reference Number(s):	Inspection Completion Date:				
5495 BOUNDARY RD		JAN 21, 2013				
CUMBERLAND;ON						
CA K4B 1P6	Facility Type:	Equipment Type:				
	FS Gasoline Station -					
	Full Serve					
Customer Name and Address:	Task Type:					
ANIVIC ENTREPRISE INC O/A LUSO GAS	FS-Shutdown LF Inspect					
5495 BOUNDARY RD		cted in accordance with Ontario's Technical				
CUMBERLAND;ON		e appropriate regulations and codes. When an				
CA K4B 1P6		e limits for compliance reflect the severity of				
	the violation and serve to avoid	the violation and serve to avoid disruption of service.				
COMPANY'S NAME:"						
Standard Notes						
Standard Proces						
to, any of the following where applicable: Photocopies of License Name, Certificate number, and Signature (where applicable) of the YOU MUST EXERCISE THIS OPTION TO AVOID A FOLLOW Reporting requirements are as follows; 1. All Inspector's Orders (directives) appearing on the inspection of 2. A person who has legal signing authority on behalf of the Owne via EMAIL or FAX on or before the last compliance date appearing Note: Declaration of Compliance is subject to an audit process who Declaration of Compliance	1. All Inspector's Orders (directives) appearing on the inspection report must be complied with. 2. A person who has legal signing authority on behalf of the Owner or User must complete the Declaration of Compliance and submit this to TS via EMAIL or FAX on or before the last compliance date appearing on the inspection report. Note: Declaration of Compliance is subject to an audit process which may result in additional inspection fees. Declaration of Compliance 1. the undersigned hereby declare that all orders on this Inspection Report have been complied with.					
Title						
Signature	Date					
Contact Email Address	Contact Phone Number					
It is an offence to knowingly make a false statement or to furnish Standards and Safety Act, 2000; sect. 37.	false information under The Act, the	e regulations or a ministers order; Technical				
Submission: Send an EMAIL (dcreporting@tssa.org) or FAX (416-231-5435) 1. The Service Request number from the Inspection Report as the 2. A copy of the Inspection Report with the Declaration of Comp	Subject line.					
For more information please contact TSSA at 416-734-3599 or email dcreporting@tssa.org						

_			Labour Detail			
Date Activity Hours Comments						
JAN 21, 2013	Inspection	2	INSPECT FACILITY PREPAR	E AND MAIL ORDERS		
Customer Signature & Position / Date:			Inspector Name: Norman, David	Inspector Contact Number: 613-284-8284		
Report Receive	ed By:		Customer Contact	Inspector Email:	Inspector Fax:	
			Number:	DNorman@tssa.org	613-284-8296	



14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario M8X 2X4 Toll free 1-877-682-8772 Fax (416) 231-1626 www.tssa.org

FS Inspection Report

Service Request #	988630
Inspection Report #	4233977

Inspection Address:	Reference Number(s):	Inspection Completion Date:
5495 BOUNDARY RD		JAN 21, 2013
CUMBERLAND;ON		•
CA K4B 1P6	Facility Type:	Equipment Type:
CA K4D II 0	FS Gasoline Station -	
	Full Serve	
Customer Name and Address:	Task Type:	
ANIVIC ENTREPRISE INC O/A LUSO GAS	FS-Shutdown LF Inspect	
5495 BOUNDARY RD	The facility/equipment is inspec	eted in accordance with Ontario's Technical
CUMBERLAND;ON	Standards & Safety Act and the	e appropriate regulations and codes. When an
,	Inspector's order is issued, time	e limits for compliance reflect the severity of
CA K4B 1P6	the violation and serve to avoid	disruption of service.

JAN 21, 2013 Travel	1.5	TRAVEL TO SITE 92
---------------------	-----	-------------------

Customer Signature & Position / Date:		Inspector Name: Norman, David	Inspector Contact Number: 613-284-8284
Report Received By:	Customer Contact	Inspector Email:	Inspector Fax:
	Number:	DNorman@tssa.org	613-284-8296



14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario M8X 2X4 Toll free 1-877-682-8772 Fax (416) 231-1626 www.tssa.org

FS Inspection Report

Service Request #	82486
Inspection Report #	2143661

Inspection Address:	Reference Number(s):	Inspection Completion Date:				
5495 BOUNDARY RD		JUN 14, 2011				
CUMBERLAND;ON		,				
CA K4B 1P6	Facility Type:	Equipment Type:				
CA KAD II U	FS Gasoline Station -					
	Full Serve					
Customer Name and Address:	Task Type:					
ANIVIC ENTREPRISE INC O/A LUSO GAS	FS-Periodic LF Inspection					
5495 BOUNDARY RD		eted in accordance with Ontario's Technical				
CUMBERLAND;ON		e appropriate regulations and codes. When an				
CA K4B 1P6	Inspector's order is issued, time	Inspector's order is issued, time limits for compliance reflect the severity of				
CA K4D IFU	the violation and serve to avoid disruption of service.					

Task Notes
SITE NOT IN OPERATION CANCEL LICENCE

Standard Notes

TSSA inspected the above mentioned location and did not find any non-compliances at the time of inspection.

Customer Signature & Position / Date:		Inspector Name: Norman, David	Inspector Contact Number: 613-284-8284
Report Received By:	Customer Contact	Inspector Email:	Inspector Fax:
-	Number:	DNorman@tssa.org	613-284-8296

www.tssa.org

14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario M8X 2X4 Ph - (416) 734-3300, Fax - (416) 231-1626 Toll - 1-877-682-8772

Fuel Safety Inspection Report

1 Report Number: FS-2002-0010608 Technical Standards and Safety Act, 2000 2 File Number: FS PIN 2002-10608 3 Location Address 4 License/Serial Number 5 Job Type Inspection Date Periodic Inspection (FS) **5495 BOUNDARY RD** 0076536275-C Mar 06, 2006 **CUMBERLAND, ON K4B 1P6 CANADA** 7 Facility Type **Gasoline Station - Full Serve** The Facility/Equipment is inspected in accordance with Ontario's Technical Standards 8 Client ANIVIC ENTREPRISE INC O/A LUSO GAS & Safety Act and the appropriate regulations and codes. When an Inspector's order is **5495 BOUNDARY RD** issued, time limits for compliance reflect the severity of the violation and serve to avoid

CUMBERLAND, ON K4B 1P6 disruption of service. In the interim period the recipient must ensure that additional precautions are taken for safe use. 11 10 Code Order Compliance Order Issued To No. Section Date LFHC 2.3.1.3. Apr 15, 2006 Record of corrosion test missing/test failed - The corrosion protection system for an underground storage tank system shall be tested and certified in writing to be in working order by a professional engineer or by a person with qualifications approved by the Director, at intervals exceeding two (2) years. The record of testing and certification shall be retained in accordance with sections 1.1.3 and 1.1.4. **OVER DUE** LFHC 4.5.1.8. No corrosion protection and/or does not meet standard Apr 15, 2006 - Steel piping and vent lines in direct contact with backfill shall be provided with corrosion protection in accordance with ULC Standard S603.1 or with an impressed current cathodic protection system.

LFHC 1.1.5. Unapproved hoses and nozzels Apr 15, 2006

- Equipment installed at a facility or on a tank vehicle shall be approved and installed in accordance with the requirements of this Document and the manufacturer's instructions, and shall be appropriate for the service for which it is intended. PUMP 4

INSPECTION NOTE: ON SITE TO INSPECT FACILITY INSPECTORS INSTRUCTIONS ISSUED.

- * Note: This report is eligible for the Voluntary Compliance option. Should you choose to exercise it, please adhere to the following procedure:
- 1. All Inspectors orders appearing on the inspection report must be complied with.
- 2. The recipient must complete the Voluntary Compliance Option box. After complying with the above conditions, this inspection report must be returned directly to TSSA head office via fax or mail, by the last compliance date appearing on the inspection report.
- 3. Should TSSA fail to receive the Voluntary Compliance Form by the compliance date, an inspector will re-inspect and bill at double our normal rate.

For more information please contact TSSA at the number above or toll-free at 1-877-682-8772. It is an offence to knowingly make a false statement or to furnish false information under the Act, the Regulations or a Ministers order. (Technical Standards and Safety Act, 2000; Sect 37)

13 Total Time 2	14 Travel Time 0.5	15 Billable Hours 0	16 Additional Charges			
Voluntary 0	Compliance Option* - Eligible? X	Yes No	*Please, refer to guidelines			
I hereby confirm that all the Inspector's orders, appearing on this inspection report have been completed.						
Print Name Client Signature						
David Names (649) 994 9995						

David Norman (613) 284-8296 Inspector Inspector Fax Number



Inspector's Report - Part A

Issued under Ontario's Energy Act and/or Gasoline Handling Act

Report No.

E- 051805

			PLEASI	<i>E r</i>	PHINI				
Location Inspected					Owner's Name	Э			
Address BOUNDARY RD.					Address				
City/town					City/town				
Cumpie LAN Postal Code K48-1P6	613	Tel. No. 822 186	3		Postal Code			Т	el. No.
Operator's Name MORRIS CH					Fuel Supplier			C	ity
Licence No.									
Contractor				1	Registration N	0.			
OPERATION/SUB	LOC TYPE	POP DEN	FUEL		CLASS	REASON		TRIGGER	ACTION
10	02	01	GAS		03	26		01	O/
ACT	REG	DURATION	TRAVEL	T	BILLABLE	BILL		OCC RATE	CAUSE
GHA	521 93	2	•5		1.5	1 2 3		02	0.1002
CON FACT	OCC DATE	OCC TIME	FIELD 1		SITE REM			PLETED? 2566/	☐ Yes ☐ No
Investigation/Aud	dit/Occurrence Su	ımmary							_
ON SIT	e To Ins	PECT FUEL	FACILITY	1	INSPE	CTORS	I	NSTRUCTION	2
Issuio				7					
			17						
Equipment/Applia	nce/Component				Equipment/Ap	opliance/Comp	on	ent	£ 0
Туре					Туре				
Description	r.				Description				
Manufacturer					Manufacturer			201	7 47
Model Serial No. Material Fuel Input Rating			-	ı	Model STANDARDS & SAFETY Serial No.				No.
Material NPR 2 4 23					Material APR 1 6 2001				
Fuel Input Rating					Fuel Input Rating		-6.1		
Date of Manufacture					Date of Manufac	ture FUELS SA		5 Dillieign	
Installation Date					Installation Date)	10.00		ä
Supply Pressure	M	lanifold Pressure			Supply Pressure			Manifold Press	sure
As a not-for-profit regulatory authority, the Technical Standards and Safety Authority operates on a cost recovery basis. An invoice will be issued for this activity.									

FS 09181 (12/99)

Client's Signature

Les demandes d'une version française du présent document seront prises en considération.

Date of Inspection

Badge #

Inspector's Name



Inspector's Instructions/Orders Peport No. Part B Feositions Part B

00759639

E051805

Issued under Onta	Date:	2001		02						
Location Address (I	H 2				Υ	M	D			
		DOUNDARY	RD COMBERGAND	1248-190	2					
Issued To		N.		Position						
MORRIS CHAMOUN										
Mailing Address										
LUSO GAS 5495 BOUNDARY RD CUMBERLAND K4B-196										
Your attention is requested oursuant to:										
	<u> </u>		GHA		521/93)				
Licence #	Expiry	Registration #	Expiry	Certificate #		Expiry				
00765362	25 2002 013/	1 5								
		2.5								
	P H H									

Order #	Section	You are hereby instructed to correct the following infraction(s)		Compliance Date
	5 (34)	Pursuant to the gasoline handling code 521 [93] The corrosion protection system for an underground storage tank system shall be tested and certified in writing to the owner to be in working order by a person certified by NACE or an engineer at intervals not exceeding 2 years and the record of testing and certification shall be retained by the owner.	/	May 24 2001
2	5(51)(8)11	EVERY COMMON HEADER AND EVERY INDIVIDUAL VENT PIPE NOT CONNECTED INTO A COMMON HEADER SHALL: BE FIRMLY SUPPORTED AND PROTECTED.		May 24 2001
3	8 (46)	THERE SHALL BE PROVIDED AT EVERY FACILITY: A MINIMUM OF 2 FIRE EXTINGUISHERS WHICH ARE LOCATED SO AS TO BE READILY ACCESSIBLE AND WHICH ARE MAINTAINED TO HAVE AN EFFECTIVE TOTAL RATING EQUIVALENT TO AT LEAST 20-BC		APRIL 20 200/

Received By: (print) Morris С на моск	Inspector: (print)
Position:	Signature:
Signature: 49.2	Inspector's Badge #:

FS 09221 (09/98)

/ of /



Ministry of Consumer and Commercial Relations Ministère de la Consommation et du Commerce

Division des normes techniques

Technical Standards Division Ction and Enforcement Branch

Direction de l'inspection et de l'application des mesures législatives

Inspector Report #/Nº de rapport Rapport de l'inspecteur/inspectrice Part A/Partie A

D- 14471

Location inspected/	Lieu inspecte				Owner's Name /	Nom du/de la pro	priétaire	
DRI	deanne				ALRES	TO BE	14005	
Address/Adresse					Address/Adresse	9	271200	
54	195 Bo	HORDARY	80.			Same.	ş.	
City/town/Ville					City/town/Ville	9 14000		
Postal Code/Code	UM BERLA		/N° de tél.		Postal Code/Cod	le nostal		Tel.No. /Nº de tél.
Kor	KO	822			1 Ostal Oode, Coc	ie postai		rei.No. /N° de tel.
	om de la personne re	esponsable		. 4	Fuel Supplier/Fo	urnisseur de com	bustible	City/Ville
TON	Y CHAN	NouN		j	OSer		도로부 "	
Licence #/Nº de per	mis 7642	£654-3			& DS	unnow	6 0	There
Contractor/Entrepre				1,0	Registration #/Nº	d'inscription		
							c ×	
OPERATION/ACTIVITÉ	SUB TYPE/ SOUS-TYPE	LOC TYPE/ TYPE DE LIEU	POP DENS/ DENS. DE PGP.		FUEL/ COMBUSTIBLE	CLASS/ CATEGORIE	REASON/	TRIGGER/ MOTIVÉ PAR :
10		07_	05		COMBOSTIBLE	O	RAISON	O/
ACTION/ MESURES PRISES	ACT/LOI	REG/RÈGLEMENT	DURATION/	-	BILLABLE/	TŖAVEL/	BILL Y/N	
MESONES PRISES	alea	52193	DURÉE / C)	À FACTURER	DÉPLACEMENT	FACTURER, (O/N)	
DAMAGE/ DOMMAGES	OCC RATE/ GRAV. DE L'ACC.	CAUSE/CAUSE	CON FACT/ FACT, CONTR.		OCC DATE/ DATE DE L'ACC.	OCC TIME/ HEURE DE L'ACC.	MANDALED Y/N	
	CHANNE ENGO.		TAOT. CONTIN.		DATE DE LACC.	HEUNE DE L'ACC.	MANDAT (O/N)	
FIELD 1/ DOMAINE 1	CALL/ INTERVENTION	CONSULT Y/N CONSULT. (O/N)	SITE REM Y/N REMÉDIER (O/I	I N)				F/U REQ'D? Y/N SUIVI REQUIS? (O/N)
	0	N	N					N
Comments/Remarqu	les							
	6.1							
							8	*
Equipment/Applian	ce/Component /l	Matériel/Appareil	Composant		Fauinment/Appli	anco/Compone	nt / Matérial/Ann	pareil/Composant
Type/Type		Code/Code	/ED	ſ	Type/Type	arke/compone	Code/Code	Jaren/Composant
Description/Descripti	00	7 1 km 50 km 1		1	December 10	toutou		
Description/Descripti	OII	AUG 2 6 1	996 \		Description/Descri	OF CONSUMER	1	
Manufacturer/Fabrica	ant				Manufacturer/Fab	ricant RELATIONS		
Model/Modèle	Ser	Technical Standard rial #/Nº de série	s Division	ŀ	Model/Modèle	AFETY BRANCH	Serial #/Nº de s	Árin
	EV				SEP	2 0 1996	Serial #/N- de s	ene
Material/Matériel	" The "	¥			Material/Matériel			
Corrosion Protection	Protection contre la	corrosion		ŀ	Corrosion Protecti	on/Protection con	tre la corrosion	
Fuel Input Rating/Dé	hit do combustible			-	F. II.			
Tuel imput Hating/De	on de combustible				Fuel Input Rating/	Debit de combust	ible	
Capacity/Capacité				Ī	Capacity/Capacité			
Installation Date/Date	d'installation			ŀ	Installation Date/D	ate d'installation		
Manufacture D. L. D.	to do fall to the							
Manufacture Date/Da	tie de raprication				Manufacture Date	/Date de fabrication	on	7.7
Supply Pressure/ Pression d'alimentation		ld Pressure/ on d'admission			Supply Pressure/ Pression d'aliment		Manifold Pressure/	
Client's Signature / Sig		16	Name / Nom de l	l'ins	specteur/inspectrice	Badge #/Nº d'ins	Pression d'admissione	On
		-					1-21,	1
TANIOSELIA	ucti7	5	Ic he	1	NN	Date of Inspection Date de l'inspec	on/ tion 199	6 08 B
09181(10/94)				10	Hond Office			1

Head Office



Technical Standards Division

Division des normes techniques

Inspection and Enforcement Branch Direction de l'inspection et de l'application des mesures législatives

Inspector's Instr Directives et ordres de l'inspecteur/inspectrice Part B/Partie B

ons/Orders Report #/N° de rapport :

D, 4471

T ASSESSED TO THE PARTY OF THE			A .	
1.2		3417006	Date: 190	
		391 1000	Y/A	M/M D/J
Location Address (No RR's) Adresse du lieu inspecté (pas de RR)	1	BOUNDARY R	1	two two.
Issued To/Délivré à			Position/Fonction	
ALBERTO	BELLIOUS		OWNER.	
Mailing Address/Adresse postale				
Your attention is required pursuant to	:	Act	Regulation	
Ces ordres ou directives vous sont do	nnés en vertu :	de la Loi G LA	du Règlem	ent 521/93
	Expiration Registration #	Expir	/Expiration Certificate #	Expiry/Expiration
Nº de permis	Nº d' inscription		Nº de certificat	
CALL/INTERVENTION ACTION/MESURES PRISES	DURATION/DURÉE	BILLABLE/A FACTURER	TRAVEL/DÉPLACEMENT	BILL Y/N / FACTURER (O/N)
			_	

Order #/ Nº de l'ordre	Section/ Article	You are hereby instructed to correct the following infraction(s)/ Vous devez rectifier l'infraction ou les infractions suivantes.	Compliance Date/ Date limite d'exécution
2	ACTIG)	RENCO DE OVERDUE LICENDE	Aug 23/91
	(ixa)		1 2/11
7	REG(10)	- POST LICENCE INV & CONSPICUOUS	
		PLACE AT THE PLACE OF BUSINESS	Se073019
Y			
. 3			
Received By:	(print)	Inspector: (print)	1

Reçu par : (en lettres moulées) Tanios Chamoun. Inspecteur(trice): (en lettres moulées) Position:/Fonction: Signature: 1 40 Inspector's Badge#: Signature: Nº d'insigne de l'inspecteur(trice) :

of/de



Ministry of Consumer and Commercial Relations Ministère de

la Consommation et du Commerce

Technical Standards Division Division des normes

techniques

Inspection and Enforcement Branch

Rapport de l'inspecteur/inspectrice Direction de l'inspection et de l'application des mesures législatives UCI = 5 1885 Part A/Partie A

Inspector's Report / Report #/Nº de rapport :

17474

Location Inspected/Lieu inspecté				Owner's Name / Nom du/de la propriétaire					
De	Deumono				AUBERTO BOULHOS				
Address/Adresse	Address/Adresse			T	Address/Adresse				
SHGS	5 Boun	DARY R	D. a			Sam	6		
City/town/Ville	UMBERW				City/town/Ville				
Postal Code/Code p	oostal	Tel.No./	/Nº de tél.		Postal Code/Code	e postal		Tel.No. /Nº de tél.	
	om de la personne re	872:	1865		5.10 5.45				
	TONY CHONOUN				Fuel Supplier/Fournisseur de combustible City/Ville				
Licence #/Nº de per	mis 90764265	543			Down	drown	JT	TALLA	
	Contractor/Entrepreneur				Registration #/Nº				
OPERATION/ACTIVITÉ	SUB TYPE/ SOUS-TYPE	LOC TYPE/ TYPE DE LIEU	POP DENS/ DENS. DE POP.	- 1	FUEL/ COMBUSTIBLE	CLASS/ CATEGORIE	REASON/ RAISON	TRIGGER/ MOTIVÉ PAR :	
Ollo	<u> </u>	02	05	- 1	GAS/DIEL	03	2-6	02	
ACTION/ MESURES PRISES	ACTILOI G + A	REG/REGLEMENT	DURATION/ DURÉE	5	BILLABLE/ A FACTURER	TRAVEL/ DEPLACEMENT	BILL Y/N FACTURER (O/N)		
DAMAGE/ DOMMAGES	OCC RATE/ GRAV. DE L'ACC.	CAUSE/CAUSE	CON FACT/ FACT, CONTR.		OCC DATE/ DATE DE L'ACC.	OCC TIME/ HEURE DE L'ACC.	MANDATED Y/N MANDAT (O/N)		
FIELD 1/ DOMAINE 1	CALL/ INTERVENTION	CONSULT Y/N CONSULT. (O/N)	SITE REM Y/N REMEDIER (O/N	N)				F/U REQ'D? Y/N SUIVI REQUIS? (O/N)	
Comments/Remarques									
	- VI	200	8						
						V			
		Y							
Equipment/Applian	ce/Component / I	Matériel/Appareil	/Composant	E	quipment/Applia	ance/Compone	nt / Matériel/App	pareil/Composant	
Type/Type		Code/Code		1 4	Type/Type		Code/Code		
Description/Descripti	on			1	Description/Description				
Manufacturer/Fabrica	ant			ı	Manufacturer/Fabricant				
Model/Modèle	Sei	rial #/Nº de série		١	Model/Modèle Serial #/Nº de série				
Material/Matériel				N	Material/Matériel	REC	EIVED		
Corrosion Protection	Protection contre la	corrosion		(Corrosion Protection	Protection con	te laggresion		
Fuel Input Rating/Dé	bit de combustible			F	Fuel Input Rating/Debit de combustible Technical Standards Division				
Capacity/Capacité				Capacity/Capacité					
Installation Date/Date	d'installation			li	nstallation Date/D	ate d'installation			
Manufacture Date/Da	ate de fabrication			N	Manufacture Date/	Date de fabrication	on		
Supply Pressure/ Pression d'alimentation		on d'admission		S	Supply Pressure/ Pression d'aliment		Manifold Pressure/ Pression d'admissi		
Client's Signature / Sig	nature du client/de la	cliente Inspector's	Name / Nom de l'			Badge #/Nº d'ins			
- Projusehi	amour	GO	il he	W^	11	Date of Inspecti Date de l'inspec		VIA M/M D/J 107 24	



Location Address (No RR's)

Adresse du lieu inspecté (pas de RR)

Technical Standards Division

Division des normes techniques

Inspection and Enforcement Branch Direction de l'Inspection et de l'application des mesures législatives

Inspector's Instructions/Orders Report #/Nº de rapport : Directives et ordres de l'inspecteur/inspectrice Part B/Partie B

\$ 5495 BOUNDARY RDO, CUNSCRINDS

Issued To/Déli		nonous	Position/Fonction (\(\sigma \sigma \cdot\) \(\lambda \cdot\)	/ P				
Mailing Addres	Mailing Address/Adresse postale							
		nt donnés en vertu : de la	a Loi G L A Regulation du Règle					
Licence # Nº de permis €0	076 Ex	piry/Expiration, Registration # N° d' inscription	Expiry/Expiration Certificate # Nº de certificat	/Expiry/Expiration				
CALLINTERVENTION	ACTION/MESURES PRISES	DURATION/DURÉE BILLA	ABLE/À FACTURER TRAVEL/DÉPLACEMENT	BILL Y/N / FACTURER (O/N)				
	2= .	1						
Order #/ Nº de l'ordre	Section/ Article	You are hereby in Vous devez rec	nstructed to correct the following infraction(s)/ tifier l'infraction ou les infractions suivantes.	Compliance Date/ Date limite d'exécution				
1 1/2	5 (40/d)	Et CONCILL 72	YRS AND METERS BAILY	in i				
	\		THE REPOWIPENISTED THE	7				
per returning	-/ \//\			7				
	2 (2 1/ 1/11)	PROTECT YOUTS	TACKS FROM IMPORTIN					
	1	ALL DUES LONG	T-MANUS.	Aug 4/95				
3	8/27	POST AS SIGN S	LOWING THE TYPES OF	7				
			VERS THAT MAY BE FILLED	Augylas				
8								
6-9	8(28)		MOCTANE RATINGS IN	A- /				
		LOCATION VISISI	LE TO THE PUBLIC	Auc. 4/9:				
5	265							
	5 (23)	CNSCISE THAT A	IFF - SUKS TONE PO LOG	1) Rug 4/93.				
6	5 (34)	LIGUE CORROSIO	1 profectionsystem res	TICIO AMG 4/95				
<u>—,</u>	8(40)	Penling 118 TEEN	1 FMERGENCY PROCEDURE	/				
- A			EIEES ILCAKS, SPILLS A					
		EXPLOSIONS		Rug 4/95				
8	8 ((1)		ALL STORE ARE TEAM	ICD				
			NSIGN A RECORD THAT	Aug 4/as				
		THEY TRAVE BY	(EN (EA-INCI)	0				
Received By: Reçu par : (e	(print) n lettres moulées	TAnioschamoun.	Inspector: (print) Inspecteur(trice) : (en lettres moulées)	-Rickenson				
Position:/Fon		inger.	Signature:	LINO				
Signature :	Janies ch		Inspector's Badge#: Nº d'insigne de l'inspecteur(trice):	154				
				Page of/de				

Ministry of Technical Fuels Inspector's					
Consumer and Standards Safety Instructions					
Commercial					
Ontario Relations					
To Jan D. Par mars to Aug o					
TOP CIL RESOURCES (S) HILL. 19 90					
24 BENTLEY AVE					
NEPSAN ONTRES KOE 6T8 10/3					
Your attention is required pursuant to					
Energy Act Gasoline Handling Act					
Propane Gasoline Fuel Oil					
Natural Gas Utilization ☐ Transmission and Distribution ☐					
Regulation 439/80 AS AMENDED BY 67/89					
You are hereby instructed to correct the infractions noted					
TE: TOP SOP 5495 BOUNDRY PO CUMBERSAND					
(D) SECT. 7 (19) EVERY VENT SHOW					
(a) HAVE A INCATURAL-PRINT HOOD					
(b) TERMINATE IN OPEN AIR NOT					
LESS THIN 12' FER CLASS I PRODUCTS					
(c) BE FIRMLY SUPPORTED AND					
Rosemo					
(2) SECT 7 (32) (B) ALL FILL PIPES OF ALL UNDER-					
-GROUND STORAGE TANKS SHALL BE					
ASRMANENTLY MARKED TO INDICATE					
THE PRODUCT IN EACH TANK.					
(33) THESE MARKINES SHALL CON-					
-FORM TO THE REQUIREMENTS					
B P - 5 OF SECT 5 (47) 8/48) GHA					
(3) SECT 8 (17) FIXED DISPENSING EQUIPMENT					
S'HALL BE INSTALLED					
(B) AT A DISTANCE OF AT KEAST					
(DIESCL PUMP MOVE PUMP BE PROVINE					
GERICE CODY					
Received by To be completed by Inspector Copy					
Bround Day Trice					
10 know (19 / 2					
09181 (02/85) Signature Signature					

Ministry of		Fuels	Insp	ector's			
Commerci	District	Safety Branch		uctions			
Ontario Relations	ai						
Ticiations				- 1			
TO TOP OIL	KESMOCES K	(m)	AIL 1	19 90			
24 Bears	Name		7100	_ 19 20			
Alexand	Address	-					
	VATAREO	_	Pu#2 of 3	?			
Your attention is required pur			0				
Ene	rgy Act		Gasoline Handling A	Act 🗎			
Propane	Gasoline 🗆		Fuel Oil				
Natural Gas Ut	ilization	Transmis	ssion and Distribution				
Regulation 4/39/80	AS AMENDED I	By 671	89				
You are	hereby instructed to con	rrect the infra	actions noted				
ME: TOP STOP	5495 Box	nory A	B Combach	90			
- D (=	() =						
(4) SEG 7 (8		1	K MONITORI	NG			
COLL			WRIDEN				
CERT	THICHTON T		the CATHODIC				
. 1101	ECHON 15 F	orgi	FUN STONAL				
(5) Sec. 8 (28	1) No Parn	SHALL	DISPERISE O	elasi			
1 " II PRODUCT UNITESS HE ISNE IS							
A COMPERANT TRAINED EMPLOYES OF							
THE OWNER OR OPERATOR AS THE							
en	SE MAY BE	BNE	ALL "SELF	-			
Sie	eve " SIENA	1ck 5	HAN BE REI	noved			
PRIO	R TO OPER	antes.					
- ALL	WORK TO PO	NERM	TO THE 6.	4. ACT			
	MED OUT B	4 11.	REGISTERAD 6	Asoleve			
Common							
	OFFICE COPY		: W				
/ Received by	To be completed b	ov	Inspector	Сору			
Transt	The Completion of		FisHER				
2 Almand	Aug o	_	11/	2			
00191 (72/95) Signature	AUG 8 1	9 20		2			

Ministry of Consumer	and Standards	Fuels Safety		ector's			
Commerc	ial Division	Branch	Instr	ructions			
Ontario Relations	9 1	()					
To 100 On 1	PESOURCES AT	1	Pepr. 27	_ 19 90			
24 BENTL	Address.	4 - 1 1					
MEDEAN	Chansel 1		1				
Your attention is required pur	suant to	675	19/3				
	rgy Act		Gasoline Handling A	Act 4			
Propane	Gasoline 🗷		Fuel Oil 🗆				
Natural Gas Ut	ilization	Transmission	and Distribution	1			
Regulation 439/80 A	AMERDED B	4 67/99	7	100			
You are	hereby instructed to corr	rect the infractio	ns noted				
ME: TOP STOP	5495 BOO	spy Rs	Cumbicula	500			
10 P (a)		/					
(1) Let 7 (19)	EVERY VE	NT JUHALL		15 5 501			
(4	1	ATHER PRO					
	TERMINATE		AIR NOT	- less			
Propuer	FOR CLASS I	: / /2	DA PLASS II	S .			
Or 1 (c)	BE FRANKY 3	5, 100 in the	1.06	· 2			
JE SEET 7(32)(B) Au FILL	Pipes	OF UNIVER	Samo			
STORAL	STORAGE TANKS STANKS BE PERMINATELY						
Od MARK	TO TO ho	icare 7	The Phoous				
DO IN EA	CH TANK						
(W) (33)	THESE MAN	enings S	HALL PON	FORM			
TO 71	HE REGURAM	15145 OF	SEC 51	47:48			
0 Sei 8 (17)	FIXED D	SPENSING	EGUPM	ENT			
5/1	THE BE INSI	ALLRD,	AT A DIS	ANCE			
() Con 2 (5) 5	Firem Mu	PRATY 1	ents.				
den Pon	TIDE CURITED			LARS			
CM740010	PROTECTION 15		EINCHUNA,	THE			
11.27.7.1	LOCATION COPY		cero monsy	1			
Received by	To be completed by		Inspector	Сору			
hount below)0 Part	> J.	EISHER				
March 1 1100	SEE VAGETE 19	1	19	3			
09181 (02/85) Signature	43	1/	Signature				

Ministry of Consumer and Standards Safety Division Branch Ontario Relations To Ministry of Consumer and Standards Safety Division Branch To Manager Address Addr	Inspector's Instructions
Your attention is required pursuant to	3
	Handling Act
	uel Oil 🗆
Natural Gas Utilization Transmission and Dist	
Deculation 1/3 @ /c	
You are hereby instructed to correct the infractions noted	
H3 TOP STOP 5495 BOD DOLLO	Per Deals S
The state of the constraint of the	DM BORLETTO
(5) Sect 8(29) 16 PERSON THOU D.	COCAS =
CLASS 1: TI PADRILLES DAL	ess Hetsu
15 A COMPATENT TRAINER	Endlover
OF THE OWNER OR DEFERENCE	o se
THE CASE MAY BE AND THE	SELE
SERVE" SIGNAGE SHOW BE	REMAITED
FORTHWITH.	
WILL WERK TO CONFORM TO	ME
GASOMAN HANDLING ACT ! PODE A	ns 85
MY CARRIED OUT BY A REGIS	meres
A BASONNE CONTINCTOR	
14/4	
1 62.	
1.0	
Received by To be completed by Inspector	
Received by To be completed by Inspector	Сору
majort Il X O V. FSH	3/
09181 (02/85) Signature 5 19%	3
09181 (02/85) Signature Signature	



File Number: D06-03-18-0029

August 1, 2018

Mandy Witteman Paterson Group 154 Colonnade Rd S Ottawa, ON K2E 7S8

Sent via email [mwitteman@patersongroup.ca]

Dear Ms. Witteman,

Re: Information Request

5510 Boundary Road & 5494 Boundary Road, Ottawa, Ontario ("Subject

Properties")

Internal Department Circulation

The Planning, Infrastructure and Economic Development Department has the following information in response to your request for information regarding the Subject Properties:

Disposals & Environmental Remediation – The subject properties are within 500 M of a former landfill known as Cu-01, located near the intersection of Devine Road and Frontier Road. The City's Environmental Remediation Unit has no information on the current environmental conditions of this former landfill as the site is under private ownership. The City's Environmental Remediation Unit has no other record of environmental contamination information for the subject properties or on rights of way or other city-owned properties adjacent to the subject properties.

Search of Historical Land Use Inventory

This acknowledges receipt of the signed Disclaimer regarding your request for information from the City's Historical Land Use Inventory (HLUI 2005) database for the Subject Properties.

A search of the HLUI database revealed the following information:

There are no activities associated with the Subject Properties.

Shaping our future together
Ensemble, formons notre avenir

City of Ottawa Planning, Infrastructure and Economic Development Department

110 Laurier Avenue West, 4th Floor Ottawa, ON K1P 1J1 Tel: (613) 580-2424 ext. 14743 Fax: (613) 560-6006 www.ottawa.ca Ville d'Ottawa Services de la planification, de l'infrastructure et du développement économique

110, avenue Laurier Ouest, 4e étage Ottawa (Ontario) K1P 1J1 Tél.: (613) 580-2424 ext. 14743 Télé: (613) 560-6006 www.ottawa.ca The HLUI database was also searched for activity associated with properties located within 50m of the Subject Properties. The search revealed the following:

• There are 10 activities associated with properties located within 50m of the Subject Properties: Activity Numbers 4727, 6485, 11564, 11569, 11873, 11499, 6225, 3101, 7603 and 11227.

A site map has been included to show the location of the Subject Properties as well as the location of all the activities noted above.

Additional information may be obtained by contacting:

Ontario's Environmental Registry

The Environmental Registry found at http://www.ebr.gov.on.ca/ERS-WEB-External/ contains "public notices" about environmental matters being proposed by all government ministries covered by the Environmental Bill of Rights. The public notices may contain information about proposed new laws, regulations, policies and programs or about proposals to change or eliminate existing ones. By using keys words i.e. name of proponent/owner and the address one can ascertain if there is any information on the proponent and address under the following categories: Ministry, keywords, notice types, Notice Status, Acts, Instruments and published date (all years).

The Ontario Land Registry Office

Registration of real property is recorded in the Ontario Land Registry Office through the Land Titles Act or the Registry Act. Documents relating to title and other agreements that may affect your property are available to the public for a fee. It is recommended that a property search at the Land Registry Office be included in any investigation as to the historic use of your property. The City of Ottawa cannot comment on any documents to which it is not a party.

Court House 161 Elgin Street 4th Floor Ottawa ON K2P 2K1 Tel: (613) 239-1230

Fax: (613) 239-1422

Please note, as per the HLUI Disclaimer, that the information contained in the HLUI database has been compiled from publicly available records and other sources of information. The HLUI may contain erroneous information given that the records used as sources of information may be flawed. For instance, changes in municipal addresses over time may introduce error. Accordingly, all information from the HLUI database is provided on an "as is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in responding to the request.

Furthermore, the HLUI database and the results of this search in no way confirm the presence or absence of contamination or pollution of any kind. This information is provided on the assumption that it will not be relied upon by any person for any purpose whatsoever. The City of Ottawa denies all liability to any persons attempting to rely on any information provided from the HLUI database.

Please note that in responding to your request, the City of Ottawa does not guarantee or comment on the environmental condition of the Subject Property. You may wish to contact the Ontario Ministry of Environment and Climate Change for additional information.

If you have any further questions or comments, please contact Melanie Vivian at 613-580-2424 ext. 14743 or HLUI@ottawa.ca

Sincerely,

Melanie Vivian


Per:

Michael Boughton, MCIP, RPP Senior Planner Development Review East Planning Services Planning, Infrastructure and Economic Development Department

MB/ MV

Attach: 5

cc: File no. D06-03-18-0029





Report:

RPTC_OT_DEV0122

Run On:

01 Aug 2018 at: 10:03:28

HLUI ID: __670IIU

AREA (Square Metres): 8713.438

Study YearPINMulti-NAICMultiple Activities1998145580041YN

Υ

Activity ID: 4727 Multiple PINS:

PIN Certainty: 1 Previous Activity ID(s): 6485

Related PINS: 145580048

Name: EASTERN ROOFING OTTAWA LIMITED

Address: 150 INDCUM ROAD,

Facility Type: Structural and Related Work

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1: MCBED1996

HL References 2:

HL References 3: 2005 Select Phone

NAICS	SIC
238150	423
238160	0
238170	0
238140	423
238160	423
238390	0
238310	423

Company Name Year of Operation

Eastern Roofing Ottawa Ltd. c. 1996
EASTERN ROOFING OTTAWA LIMITED c. 2005

EASTERN ROOFING OTTAWA LIMITED c. 2001

MAP Report Ver: 1 Page 1 of 1



Report: Run On: RPTC_OT_DEV0122

01 Aug 2018 at: 10:04:56

HLUI ID: __679BQI

AREA (Square Metres): 4224.057

Multiple Activities Study Year PIN **Multi-NAIC** 145580038 2005

Activity ID: 11564 Multiple PINS: Ν

PIN Certainty:

Previous Activity ID(s):

Related PINS:

145580038

Name:

RENE STEEL INC.

Address:

5507 BOUNDARY ROAD,

Facility Type:

Other Metal Fabricating Industries

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

2005 Select Phone HL References 3:

NAICS

SIC

332314

0

Company Name

Year of Operation

RENE STEEL INC.

c. 2005

MAP Report Ver: 1 Page 1 of 3



HLUI ID: __679BQI

AREA (Square Metres): 4224.057

Report: RPTC_OT_DEV0122

Run On: 01 Aug 2018 at: 10:04:56

Study Year PIN Multi-NAIC Multiple Activities 145580038 Y Wultiple Activities

Activity ID: 11569 Multiple PINS: N

PIN Certainty: 1 Previous Activity ID(s):

Related PINS: 145580038

Name: RENE'S WELDING INC.

Address: 5507 BOUNDARY ROAD, CARLSBAD SPRINGS

Facility Type: Site Work

Comments 1:

Comments 2:

Generator Number:

Storage Tanks: HL References 1:

HL References 2:

HL References 3: 2001 Employment Survey

NAICS SIC

238390 0

Company Name Year of Operation

RENE'S WELDING INC. c. 2001

MAP Report Ver: 1 Page 2 of 3



HLUI ID: __679BQI

AREA (Square Metres): 4224.057

Report: RPTC_OT_DEV0122

Run On: 01 Aug 2018 at: 10:04:56

Study Year PIN Multi-NAIC Multiple Activities 145580038 Y Wultiple Activities

Activity ID: 11873 Multiple PINS: N

PIN Certainty: 1 Previous Activity ID(s):

Related PINS: 145580038

Name: ROTHSAY LAURENCO
Address: 5507 BOUNDARY ROAD,
Facility Type: Waste Materials, Wholesale

Comments 1: Comments 2:

Generator Number:
Storage Tanks:

HL References 1: HL References 2:

HL References 3: 2005 Select Phone

NAICS SIC 418190 0

Company Name Year of Operation

ROTHSAY LAURENCO c. 2005

MAP Report Ver: 1 Page 3 of 3



Report:

RPTC_OT_DEV0122

Run On:

01 Aug 2018 at: 10:05:49

HLUI ID: __670HA2

AREA (Square Metres): 3041.364

Study YearPINMulti-NAICMultiple Activities1998145580037YY

·

Activity ID: 11499 Multiple PINS: N

PIN Certainty: 1 Previous Activity ID(s): 6225

Related PINS: 145580037

Name: PK AUTO IMPORT AND DOMESTIC SALES AND SERVICE

Address: 5495 BOUNDARY ROAD, CUMBERLAND

Facility Type: Motor Vehicle Repair Shops

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1: MCBED1996

HL References 2: HL References 3:

NAICS SIC 811119 635 811112 635 811121 635

Company Name Year of Operation

PK Auto Import and Domestic Sales and Service c. 1996

MAP Report Ver: 1 Page 1 of 3



Study Year

1998

CITY OF OTTAWA

HLUI ID: __670HA2

AREA (Square Metres): 3041.364

Report: RPTC_OT_DEV0122

Run On: 01 Aug 2018 at: 10:05:49

PIN Multi-NAIC Multiple Activities 145580037 Y Y

Activity ID: 3101 Multiple PINS: N

PIN Certainty: 1 Previous Activity ID(s):

Related PINS: 145580037

Name:CAR GUARANTIERSAddress:5495 BOUNDARY ROAD,Facility Type:Motor Vehicles, Wholesale

Comments 1: Comments 2:

Generator Number:
Storage Tanks:

HL References 1: HL References 2:

HL References 3: 2005 Select Phone

NAICS SIC 811111 0

Company Name Year of Operation

CAR GUARANTIERS c. 2005

MAP Report Ver: 1 Page 2 of 3



Study Year

1998

CITY OF OTTAWA

HLUI ID: __670HA2

AREA (Square Metres): 3041.364

Report: RPTC_OT_DEV0122

Run On: 01 Aug 2018 at: 10:05:49

PIN Multi-NAIC Multiple Activities
145580037 Y Multiple Activities

Activity ID: 7603 Multiple PINS: N

PIN Certainty: 1 Previous Activity ID(s):

Related PINS: 145580037

Name: RICHMOND GLEN ESTATES LIMITED

Address: 5495 BOUNDARY ROAD, CUMBERLAND

Facility Type: Gasoline Service Stations

Comments 1: Comments 2:

Generator Number: Storage Tanks: HL References 1: HL References 2:

HL References 3: 2005 Property Assessment

NAICS SIC447110 0
447190 0

Company Name Year of Operation

RICHMOND GLEN ESTATES LIMITED c. 2005

LUOSO GAS c. 2001

LUOSO GAS c. 2005

MAP Report Ver: 1 Page 3 of 3



Report:

RPTC_OT_DEV0122

Run On:

01 Aug 2018 at: 10:07:17

HLUI ID: __6790IX

AREA (Square Metres): 410976.930

 Study Year
 PIN
 Multi-NAIC
 Multiple Activities

 2005
 145580031
 Y
 N

Activity ID: 11227 Multiple PINS: Y

PIN Certainty: 1 Previous Activity ID(s):

Related PINS: 145580031

Name: R. POMERLEAU LIMITED

Address: 5425 BOUNDARY ROAD, CUMBERLAND TOWNSHIP

Facility Type: Site Work

Comments 1:

Comments 2:

Generator Number: ON2049900

Storage Tanks:

HL References 1:

HL References 2:

HL References 3: 2003 PID

NAICS SIC

238990 0 238910 0

Company Name Year of Operation

R. POMERLEAU LIMITED c. 2003

MAP Report Ver: 1 Page 1 of 1

APPENDIX 3

QUALIFICATIONS OF ASSESSORS

Mandy Witteman, B.Eng., M.A.Sc.



POSITION

Intermediate Environmental Engineer

EDUCATION

Carleton University
M.A.Sc., Environmental Engineering, 2013
B.Eng., Environmental Engineering, 2008

MEMBERSHIPS & AWARDS

Ontario Professional Engineers Association (EIT) NSERC Industry R&D Scholarship

EXPERIENCE

2018 - Present

Paterson Group Inc.

Consulting Engineers
Geotechnical and Environmental Division
Environmental Engineer

2014 - 2015

Thurber Engineering Limited

Oil Sand Tailings Group Tailings Engineer

2009 - 2014

Carleton University

Department of Civil & Environmental Engineering Research Engineer, Research Assistant & Teaching Assistant

2008 - 2009

SLR Consulting Limited

Contaminated Sites
Junior Environmental Engineer

SELECTED LIST OF PROJECTS

Phase I & II Environmental Site Assessments – NRC, Kingston Remediation – National Capital Region, Saskatchewan Multi-lift and dry-stacking pilot programs – Northern Alberta Polymer amended oil sand tailings – Northern Alberta Hydraulic cut-off wall – Allen, Saskatchewan Cemented paste backfill systems – Northern Ontario

Mark S. D'Arcy, P. Eng.

patersongroup

Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

Materials Testing

Building Science

Archaeological Services

POSITION

Associate and Supervisor of the Environmental Division Senior Environmental/Geotechnical Engineer

EDUCATION

Queen's University, B.A.Sc.Eng, 1991 Geotechnical / Geological Engineering

MEMBERSHIPS

Ottawa Geotechnical Group Professional Engineers of Ontario

EXPERIENCE

1991 to Present

Paterson Group Inc.

Associate and Senior Environmental/Geotechnical Engineer Environmental and Geotechnical Division Supervisor of the Environmental Division

SELECT LIST OF PROJECTS

Mary River Exploration Mine Site - Northern Baffin Island

Agricultural Supply Facilities - Eastern Ontario

Laboratory Facility – Edmonton (Alberta)

Ottawa International Airport - Contaminant Migration Study - Ottawa

Richmond Road Reconstruction - Ottawa

Billings Hurdman Interconnect - Ottawa

Bank Street Reconstruction - Ottawa

Environmental Review - Various Laboratories across Canada - CFIA

Dwyer Hill Training Centre - Ottawa

Nortel Networks Environmental Monitoring - Carling Campus - Ottawa

Remediation Program - Block D Lands - Kingston

Investigation of former landfill sites - City of Ottawa

Record of Site Condition for Railway Lands - North Bay

Commercial Properties - Guelph and Brampton

Brownfields Remediation - Alcan Site - Kingston

Montreal Road Reconstruction - Ottawa

Appleford Street Residential Development - Ottawa

Remediation Program - Ottawa Train Yards

Remediation Program - Bayshore and Heron Gate

Gladstone Avenue Reconstruction – Ottawa

Somerset Avenue West Reconstruction - Ottawa

patersongroup

Consulting Engineers

154 Colonnade Road South Ottawa, Ontario Canada, K2E 7J5 Tel: (613) 226-7381

Fax: (613) 226-6344

Geotechnical Engineering Environmental Engineering Hydrogeology Geological Engineering Materials Testing Building Science

www.patersongroup.ca

October 20, 2021 File: PE4387-LET.01R

Day & Ross

Transportation Group 398 Main Street Hartland, New Brunswick E7P 1C6

Subject: Fill Quality Assessment

Phase II Environmental Site Assessment

5510 Boundary Road Ottawa, Ontario

Dear Sir/Madame,

As requested, Paterson Group (Paterson) conducted a Phase II Environmental Site Assessment (ESA) to assess the fill material placed on the subject land. Based on a Phase I ESA completed by Paterson in conjunction with this study, it was determined that the land was excavated as an aggregate source and subsequent infilling of the site has taken place, with the majority of the excavated area having now been backfilled. This letter contains a summary of our findings with regard to the quality of the above noted fill material.

Field Findings/Observations

The Phase II ESA consisted primarily of a test pit excavation program, which was carried out on August 1, 2018. At that time, twelve (12) test pits were excavated through the fill layer and representative fill and native soil samples were recovered from the test pits. Four (4) boreholes were also placed on site, one of which (BH4) was completed with a groundwater monitoring well.

No obvious odours or staining were noted during the excavation of the test pits, however, minor amounts of brick, asphaltic concrete, concrete, wood and insulation were present in the fill material, which ranged in thickness from 1.4 to 3.2m below grade. The native soils encountered below the fill consisted of fine sands and silty clays. No evidence of impact was observed in the native soils, or the groundwater that was encountered in the test pits.

Ottawa North Bay

The recovered soil samples were subjected to a vapour screening survey which did not identify the potential for significant volatile contamination.

Analytical Test Results

Six (6) fill samples were submitted to Paracel Laboratories in Ottawa for petroleum hydrocarbons (PHC, Fractions 2 to 4), metals and polycyclic aromatic hydrocarbons (PAHs). The test results are presented in Tables 1 through 3 below, along with the MECP Table 2 industrial coarse grained soil standards. A copy of the certificate of analysis is attached to this letter.

Table 1 - Analytical Test Results PHC (F ₂ -F ₄)						
Parameter	MDL (µg/g)	Soil Sample (µg/g) August 1, 2018 TP2 G1	MECP Table 2 Standards Commercial Coarse (μg/g)			
F ₂ (C ₁₀ -C ₁₆)	4	11	230			
F ₃ (C ₁₆ -C ₃₄)	8	347	1,700			
F ₄ (C ₃₄ -C ₅₀)	6	875	3,300			
F ₄ (gravimetric)	50	6,590	3,300			
□ nd ·	L - Method Detect - not detected abo <u>d</u> - Value exceeds		•			

The PHC heavy Fraction 4 concentration exceeds the selected Ontario Ministry of Conservation and Parks (MECP) Table 2 Commercial Standard. The remaining PHC concentrations comply with the standards.

All PHC concentrations exceed the MECP Table 1 typical Ontario background standards, which are commonly used to assess the quality of fill for off-site disposal.

Parameter	MDL (µg/g)	Soil Samples (μg/g) August 1, 2018						MECP Table 2 Standards
		TP2 G1	TP4 G2	TP5 G2	TP7 G1	TP8 G1	TP11 G1	Commercial Coarse (µg/g)
Antimony	1	nd	nd	nd	nd	nd	nd	40
Arsenic	1	2.6	1.9	1.3	2.6	1.7	1.9	18
Barium	1	67.5	96.6	168	112	152	128	670
Beryllium	0.5	nd	nd	nd	nd	nd	nd	8
Boron (total)	5	11.1	nd	nd	nd	nd	nd	120
Cadmium	0.5	nd	nd	nd	nd	nd	nd	1.9
Chromium	5	15.8	26.9	43.0	32.8	32.0	47.0	160
Cobalt	1	4.9	6.4	10.6	7.9	7.5	10.0	80
Copper	5	14.0	18.5	20.7	23.5	17.9	29.0	230
Lead	1	30.9	47.7	22.7	26.5	37.2	26.8	120
Molybdenu	1	nd	nd	nd	nd	nd	nd	40
Nickel	5	14.3	16.2	25.1	20.0	18.1	28.8	270
Selenium	1	nd	nd	nd	nd	nd	nd	5.5
Silver	0.3	nd	nd	nd	nd	nd	nd	40
Thallium	1	nd	nd	nd	nd	nd	nd	3.3
Uranium	1	nd	nd	nd	nd	nd	nd	33
Vanadium	10	33.2	30.6	42.6	34.4	33.9	39.7	86
Zinc	20	58.4	63.4	61.6	50.9	69.0	79.0	340

All of the metal results comply with the selected MECP Table 2 standards. All of the metals results also comply with the MECP Table 1 background standards.

Table 3 - Analytical	Test Results
PAHs	

Parameter	MDL (µg/g)	Soil Samples (µg/g) August 1, 2018			MECP Table 2 Standards
		TP2 G1	TP4 G2	TP5 G2	Commercial Coarse (μg/g)
Acenaphthene	0.05	0.07	0.09	0.03	21
Acenaphthylene	0.05	0.07	0.06	nd	0.15
Anthracene	0.05	0.21	0.21	0.06	0.67
Benzo[a]anthracene	0.05	0.51	0.46	0.14	0.96
Benzo[a]pyrene	0.05	0.47	0.46	0.21	0.3
Benzo[b]fluoranthene	0.05	<u>1.24</u>	<u>1.05</u>	0.19	0.96
Benzo[ghi]perylene	0.05	0.34	0.31	0.26	9.6
Benzo[k]fluoranthene	0.05	0.67	0.59	0.10	0.96
Chrysene	0.05	0.56	0.45	0.14	9.6
Dibenzo[a,h]anthracene	0.05	0.09	0.09	0.06	0.1
Fluoranthene	0.05	1.26	1.0	0.29	9.6
Fluorene	0.05	0.07	0.06	nd	62
Indeno[1,2,3-cd]pyrene	0.05	0.30	0.31	0.24	0.76
1-Methylnaphthalene	0.05	0.02	0.03	nd	30
2-Methylnaphthalene	0.05	0.03	0.03	nd	30
Naphthalene	0.05	0.04	0.05	nd	9.6
Phenanthrene	0.05	0.67	0.69	0.19	12
Pyrene	0.05	0.99	0.86	0.25	96

Notes:

MDL - Method Detection Limit

nd - not detected above the MDL

□ Bold - Value exceeds selected MECP Standard

Parameter	MDL (µg/g)		Samples (ugust 1, 20	MECP Table 2 Standards	
		TP7 G1	TP8 G1	TP11 G1	Commercial Coarse (µg/g)
Acenaphthene	0.05	0.02	nd	nd	21
Acenaphthylene	0.05	nd	nd	nd	0.15
Anthracene	0.05	0.07	nd	0.07	0.67
Benzo[a]anthracene	0.05	0.15	0.04	0.13	0.96
Benzo[a]pyrene	0.05	0.18	0.06	0.15	0.3
Benzo[b]fluoranthene	0.05	0.16	0.07	0.15	0.96
Benzo[ghi]perylene	0.05	0.18	0.09	0.22	9.6
Benzo[k]fluoranthene	0.05	0.10	0.3	0.08	0.96
Chrysene	0.05	0.20	0.05	0.12	9.6
Dibenzo[a,h]anthracene	0.05	0.05	nd	0.05	0.1
Fluoranthene	0.05	0.26	0.07	0.17	9.6
Fluorene	0.05	nd	nd	nd	62
Indeno[1,2,3-cd]pyrene	0.05	0.16	0.07	0.17	0.76
1-Methylnaphthalene	0.05	nd	0.02	nd	30
2-Methylnaphthalene	0.05	nd	0.03	nd	30
Naphthalene	0.05	0.02	0.02	0.01	9.6
Phenanthrene	0.05	0.17	0.04	0.21	12
Pyrene	0.05	0.26	0.07	0.14	96

Several parameter concentrations in Samples TP2 G1 and TP4 G2 exceed the selected Table 2 standards, while the results from the remaining samples are in compliance with these standards.

Parameter results from Samples TP2 G1, TP4 G2 and TP5 G2 exceed the Table 1 standards, while the remaining sample results comply with the Table 1 standards.

Groundwater

A groundwater sample was collected from the monitoring well installed in BH4 and submitted for PHCs and volatile organic compound (VOC) analysis. The results of the analytical testing and the selected MECP standards are presented in Tables 4 and 5. A copy of the laboratory certificate of analysis is attached to this report.

Table 4 Analytical Test Results - Groundwater PHCs (Fractions 1 to 4)							
Damanastan	MDL	Groundwater Sample (ug/L)	MECP Table 2				
Parameter	(ug/L)	BH4-GW1	Commercial Standards (ug/L)				
F1 PHCs (C ₆ -C ₁₀)	25	nd	750				
F2 PHCs (C ₁₀ -C ₁₆)	100	nd	150				
F3 PHCs (C ₁₆ -C ₃₄)	100	nd	500				
F4 PHCs (C ₃₄ -C ₅₀)	100	nd	500				
Notes: MDL - Method Detection Limit nd - Not Detected (< MDL)							

The PHC results comply with the MECP Table 2 standards.

		Groundwater Sample	MECP Table 2 Commercial Standards (µg/L)	
Parameter	MDL	August 8, 2018		
	(ug/L)	BH4-GW1		
Acetone	5.0	nd	2,700	
Benzene	0.5	nd	5	
Bromodichloromethane	0.5	nd	16	
Bromoform	0.5	nd	25	
Bromomethane	0.5	nd	0.89	
Carbon Tetrachloride	0.2	nd	0.79	
Chlorobenzene	0.5	nd	30	
Chloroform	0.5	nd	2.4	
Dibromochloromethane	0.5	nd	25	
Dichlorodifluoromethane	1.0	nd	590	
1,2-Dichlorobenzene	0.5	nd	3	
1,3-Dichlorobenzene	0.5	nd	59	
1,4-Dichlorobenzene	0.5	nd	1	
1,1-Dichloroethane	0.5	nd	5	
1,2-Dichloroethane	0.5	nd	1.6	
1,1-Dichloroethylene	0.5	nd	1.6	
cis-1,2-Dichloroethylene	0.5	nd	1.6	
trans-1,2-Dichloroethylene	0.5	nd	1.6	
1,2-Dichloropropane	0.5	nd	5	
1,3-Dichloropropene	0.5	nd	0.5	
Ethyl benzene	0.5	nd	2.4	
Ethylene dibromide	0.5	nd	0.2	
Hexane	1.0	nd	51	
Methyl Ethyl Ketone	5.0	nd	1,800	
Methyl Isobutyl Ketone	5.0	nd	640	
Methyl tert-butyl ether	2.0	nd	15	
Methylene Chloride	5.0	nd	50	
Styrene	0.5	nd	5.4	
1,1,1,2-Tetrachloroethane	0.5	nd	1.1	
1,1,2,2-Tetrachloroethane	0.5	nd	1	
Tetrachloroethylene	0.5	nd	1.6	
Toluene	0.5	nd	24	
1,1,1-Trichloroethane	0.5	nd	200	
1,1,2-Trichloroethane	0.5	nd	4.7	
Trichloroethylene	0.5	nd	1.6	
Trichlorofluoromethane	1.0	nd	150	
Vinyl Chloride	0.5	nd	0.5	
Xylenes	0.5	nd	300	

The VOC results comply with the MECP Table 2 standards.

Assessment

Twelve (12) test pits were excavated through the fill layer and representative fill and native soil samples were recovered from the test pits. No obvious odours or staining were noted during the excavation of the test pits, however, minor amounts of brick, asphaltic concrete, concrete, wood and insulation were present in the majority of the test pits. A significant amount of asphaltic concrete was present in Test Pit 4. The fill layer ranged in thickness from 1.4 to 3.2m below grade. No evidence of impact was observed in the native soils, or the groundwater that was encountered in the test pits

Six (6) samples of the fill material were submitted to Paracel Laboratories for petroleum hydrocarbons (PHC, Fractions 2 to 4), metals and/or polycyclic aromatic hydrocarbons (PAHs). The test results were compared to the MECP Table 2 industrial coarse grained soil standards, which were considered appropriate for the intended use of the land. The PHC F4 concentration and 2 PAH parameter concentrations in Test Pit 2 exceeded the selected standards, as did 2 PAH parameter concentrations in Test Pit 4. These concentrations are considered to be a result of asphaltic concrete being present in the fill material. The remainder of the test results were in compliance with the selected standards for the subject property.

The results were also compared to the MECP Table 1 typical Ontario background standards, which are commonly used to assess the quality of fill for off-site disposal purposes. A comparison of the test data to these standards indicates that the same soil samples from TP2 and TP4 have numerous PAH parameters that exceed the standards, in addition to the sample from TP5. The remaining test results are in compliance with the Table 1 standards.

A groundwater sample was collected from the monitoring well installed in BH4 and submitted for PHC and VOC analyses. No parameters were detected above the laboratory detection limits. The water results comply with the selected site standards.

Conclusion/Recommendations

Based on our findings, it is evident that some of the fill on site has concentrations of petroleum hydrocarbons and/or PAHs above the selected MECP Standards. The PAHs are considered likely to be a result of the asphaltic concrete fragments observed in the fill. The test pits where the contaminants were identified were also the test pits where the greatest amount of demolition debris was observed. These test pits were generally situated in the southern portion of the property, which was the first portion of the site to be back filled.

The impacted fill (and fill containing demolition debris) is not considered to pose a risk to the intended use of the land, however, it is recommended that any fill with contaminant concentration in excess of the Table 2 standards or containing significant demolition debris should be removed from the site during redevelopment. Based on the limited nature of our investigation, an accurate determination of the impacted fill cannot be made at this time.

Given that the site is slated for development, it should be noted that any fill that has to be taken off site for construction purposes has to comply with the appropriate standards for the selected destination site and cannot contain non-inert materials, such as the construction/demolition debris observed in a significant number of the test pits, if it is goig anywhere but an approved waste disposal facility.

Statement of Limitations

A soils investigation of this nature is a limited sampling program. Should any conditions at the site be encountered which differ from those at the test locations, we request that we be notified immediately in order to permit reassessment of our recommendations/conclusions.

The present report applies only to the project described in this document. Use of this report for purposes other than those described herein or by person(s) other than Day & Ross, or their agents, without review by this firm for the applicability of our recommendations to the altered use of the report, is prohibited.

Paterson Group Inc.



Mark S. D'Arcy, P.Eng.

Attachments

Laboratory Certificates of Analysis

Report Distribution

- ☐ Day & Ross (1 copy and electronic copy)
- ☐ Paterson Group (1 copy)



300 - 2319 St. Laurent Blvd Ottawa, ON, K1G 4J8 1-800-749-1947 www.paracellabs.com

Certificate of Analysis

Paterson Group Consulting Engineers

154 Colonnade Road South

Nepean, ON K2E 7J5 Attn: Mark D'Arcy

Client PO: 24819 Project: PE4387 Custody: 44358

Report Date: 13-Aug-2018 Order Date: 8-Aug-2018

Order #: 1832245

This Certificate of Analysis contains analytical data applicable to the following samples as submitted:

Paracel ID	Client ID
1832245-01	TP2-G1
1832245-02	TP4-G2
1832245-03	TP5-G2
1832245-04	TP7-G1
1832245-05	TP8-G1
1832245-06	TP11-G1

Approved By:

Mark Froto

Mark Foto, M.Sc. Lab Supervisor



Order #: 1832245

Certificate of Analysis

Client: Paterson Group Consulting Engineers

Order Date: 8-Aug-2018

Client PO: 24819

Report Date: 13-Aug-2018

Order Date: 8-Aug-2018

Project Description: PE4387

Analysis Summary Table

Analysis	Method Reference/Description	Extraction Date	Analysis Date
PHC F4G (gravimetric)	CWS Tier 1 - Extraction Gravimetric	13-Aug-18	13-Aug-18
PHCs F2 to F4	CWS Tier 1 - GC-FID, extraction	9-Aug-18	10-Aug-18
REG 153: Metals by ICP/MS, soil	EPA 6020 - Digestion - ICP-MS	10-Aug-18	10-Aug-18
REG 153: PAHs by GC-MS	EPA 8270 - GC-MS, extraction	9-Aug-18	13-Aug-18
Solids, %	Gravimetric, calculation	10-Aug-18	10-Aug-18



Order #: 1832245

Report Date: 13-Aug-2018

Certificate of Analysis **Client: Paterson Group Consulting Engineers**

Order Date: 8-Aug-2018

Client PO: 24819 **Project Description: PE4387**

	Client ID: Sample Date: Sample ID:	TP2-G1 08/01/2018 09:00 1832245-01	TP4-G2 08/01/2018 09:00 1832245-02	TP5-G2 08/01/2018 09:00 1832245-03	TP7-G1 08/01/2018 09:00 1832245-04
	MDL/Units	Soil	Soil	Soil	Soil
Physical Characteristics					
% Solids	0.1 % by Wt.	90.6	91.4	83.0	91.1
Metals					,
Antimony	1.0 ug/g dry	<1.0	<1.0	<1.0	<1.0
Arsenic	1.0 ug/g dry	2.6	1.9	1.3	2.6
Barium	1.0 ug/g dry	67.5	96.6	168	112
Beryllium	0.5 ug/g dry	<0.5	<0.5	<0.5	<0.5
Boron	5.0 ug/g dry	11.1	<5.0	<5.0	<5.0
Cadmium	0.5 ug/g dry	<0.5	<0.5	<0.5	<0.5
Chromium	5.0 ug/g dry	15.8	26.9	43.0	32.8
Cobalt	1.0 ug/g dry	4.9	6.4	10.6	7.9
Copper	5.0 ug/g dry	14.0	18.5	20.7	23.5
Lead	1.0 ug/g dry	30.9	47.7	22.7	26.5
Molybdenum	1.0 ug/g dry	<1.0	<1.0	<1.0	<1.0
Nickel	5.0 ug/g dry	14.3	16.2	25.1	20.0
Selenium	1.0 ug/g dry	<1.0	<1.0	<1.0	<1.0
Silver	0.3 ug/g dry	<0.3	<0.3	<0.3	<0.3
Thallium	1.0 ug/g dry	<1.0	<1.0	<1.0	<1.0
Uranium	1.0 ug/g dry	<1.0	<1.0	<1.0	<1.0
Vanadium	10.0 ug/g dry	33.2	30.6	42.6	34.4
Zinc	20.0 ug/g dry	58.4	63.4	61.6	50.9
Hydrocarbons					
F2 PHCs (C10-C16)	4 ug/g dry	11	-	-	-
F3 PHCs (C16-C34)	8 ug/g dry	347	-	-	-
F4 PHCs (C34-C50)	6 ug/g dry	875 [1]	-	-	-
F4G PHCs (gravimetric)	50 ug/g dry	6590	-	-	-
Semi-Volatiles					
Acenaphthene	0.02 ug/g dry	0.07	0.09	0.03	0.02
Acenaphthylene	0.02 ug/g dry	0.07	0.06	<0.02	<0.02
Anthracene	0.02 ug/g dry	0.21	0.21	0.06	0.07
Benzo [a] anthracene	0.02 ug/g dry	0.51	0.46	0.14	0.15
Benzo [a] pyrene	0.02 ug/g dry	0.47	0.46	0.21	0.18
Benzo [b] fluoranthene	0.02 ug/g dry	1.24	1.05	0.19	0.16
Benzo [g,h,i] perylene	0.02 ug/g dry	0.34	0.31	0.26	0.18
Benzo [k] fluoranthene	0.02 ug/g dry	0.67	0.59	0.10	0.10
Chrysene	0.02 ug/g dry	0.56	0.45	0.14	0.20



Order #: 1832245

Report Date: 13-Aug-2018

Order Date: 8-Aug-2018

Certificate of Analysis

Client: Paterson Group Consulting Engineers

Client PO: 24819 **Project Description: PE4387**

	Client ID: Sample Date: Sample ID:	TP2-G1 08/01/2018 09:00 1832245-01	TP4-G2 08/01/2018 09:00 1832245-02	TP5-G2 08/01/2018 09:00 1832245-03	TP7-G1 08/01/2018 09:00 1832245-04
	MDL/Units	Soil	Soil	Soil	Soil
Dibenzo [a,h] anthracene	0.02 ug/g dry	0.09	0.09	0.06	0.05
Fluoranthene	0.02 ug/g dry	1.26	1.00	0.29	0.26
Fluorene	0.02 ug/g dry	0.07	0.06	<0.02	<0.02
Indeno [1,2,3-cd] pyrene	0.02 ug/g dry	0.30	0.31	0.24	0.16
1-Methylnaphthalene	0.02 ug/g dry	0.02	0.03	<0.02	<0.02
2-Methylnaphthalene	0.02 ug/g dry	0.03	0.03	<0.02	<0.02
Methylnaphthalene (1&2)	0.04 ug/g dry	0.05	0.06	<0.04	<0.04
Naphthalene	0.01 ug/g dry	0.04	0.05	<0.01	0.02
Phenanthrene	0.02 ug/g dry	0.67	0.69	0.19	0.17
Pyrene	0.02 ug/g dry	0.99	0.86	0.25	0.26
2-Fluorobiphenyl	Surrogate	85.0%	111%	95.0%	96.3%
Terphenyl-d14	Surrogate	78.5%	96.7%	82.9%	77.9%



Certificate of Analysis

Client: Paterson Group Consulting Engineers

Client PO: 24819

Report Date: 13-Aug-2018 Order Date: 8-Aug-2018 **Project Description: PE4387**

	Client ID:	TP8-G1	TP11-G1	-	-
	Sample Date:	08/01/2018 09:00	08/01/2018 09:00	-	-
	Sample ID:	1832245-05	1832245-06	-	-
Physical Characteristics	MDL/Units	Soil	Soil	-	-
% Solids	0.1 % by Wt.	90.9	85.6	_	
Metals	011 /0 Dy 1111	90.9	65.0	-	-
Antimony	1.0 ug/g dry	<1.0	<1.0	_	-
Arsenic	1.0 ug/g dry	1.7	1.9	-	-
Barium	1.0 ug/g dry	152	128	-	-
Beryllium	0.5 ug/g dry	<0.5	<0.5	-	-
Boron	5.0 ug/g dry	<5.0	<5.0	-	-
Cadmium	0.5 ug/g dry	<0.5	<0.5	-	-
Chromium	5.0 ug/g dry	32.0	47.0	-	-
Cobalt	1.0 ug/g dry	7.5	10.0	-	-
Copper	5.0 ug/g dry	17.9	29.0	-	-
Lead	1.0 ug/g dry	37.2	26.8	-	-
Molybdenum	1.0 ug/g dry	<1.0	<1.0	-	-
Nickel	5.0 ug/g dry	18.1	28.8	-	-
Selenium	1.0 ug/g dry	<1.0	<1.0	-	-
Silver	0.3 ug/g dry	<0.3	<0.3	-	-
Thallium	1.0 ug/g dry	<1.0	<1.0	-	•
Uranium	1.0 ug/g dry	<1.0	<1.0	-	-
Vanadium	10.0 ug/g dry	33.9	39.7	-	-
Zinc	20.0 ug/g dry	69.0	79.0	-	-
Semi-Volatiles					
Acenaphthene	0.02 ug/g dry	<0.02	<0.02	-	-
Acenaphthylene	0.02 ug/g dry	<0.02	<0.02	-	-
Anthracene	0.02 ug/g dry	<0.02	0.07	-	-
Benzo [a] anthracene	0.02 ug/g dry	0.04	0.13	-	-
Benzo [a] pyrene	0.02 ug/g dry	0.06	0.15	-	-
Benzo [b] fluoranthene	0.02 ug/g dry	0.07	0.15	-	-
Benzo [g,h,i] perylene	0.02 ug/g dry	0.09	0.22	-	-
Benzo [k] fluoranthene	0.02 ug/g dry	0.03	0.08	-	-
Chrysene	0.02 ug/g dry	0.05	0.12	-	-
Dibenzo [a,h] anthracene	0.02 ug/g dry	<0.02	0.05	-	-
Fluoranthene	0.02 ug/g dry	0.07	0.17	-	-
Fluorene	0.02 ug/g dry	<0.02	<0.02	-	-
Indeno [1,2,3-cd] pyrene	0.02 ug/g dry	0.07	0.17	-	-
1-Methylnaphthalene	0.02 ug/g dry	0.02	<0.02	-	-



Report Date: 13-Aug-2018

Certificate of Analysis **Client: Paterson Group Consulting Engineers**

Order Date: 8-Aug-2018 Client PO: 24819 **Project Description: PE4387**

	Client ID: Sample Date: Sample ID: MDL/Units	08/01/2018 09:00	TP11-G1 08/01/2018 09:00 1832245-06 Soil	- - - -	- - - -
2-Methylnaphthalene	0.02 ug/g dry	0.03	<0.02	-	-
Methylnaphthalene (1&2)	0.04 ug/g dry	0.05	<0.04	-	-
Naphthalene	0.01 ug/g dry	0.02	0.01	-	-
Phenanthrene	0.02 ug/g dry	0.04	0.21	-	-
Pyrene	0.02 ug/g dry	0.07	0.14	-	-
2-Fluorobiphenyl	Surrogate	93.5%	107%	-	-
Terphenyl-d14	Surrogate	85.5%	77.1%	-	-



Order #: 1832245

Report Date: 13-Aug-2018 Order Date: 8-Aug-2018

Client: Paterson Group Consulting EngineersOrder Date: 8-Aug-2018Client PO: 24819Project Description: PE4387

Method Quality Control: Blank

Antimony ND 1.0 ug/g Arsenic ND 1.0 ug/g Barium ND 1.0 ug/g Beryllium ND 0.5 ug/g Boron ND 5.0 ug/g Cadmium ND 5.0 ug/g Chromium ND 5.0 ug/g Cobalt ND 1.0 ug/g Copper ND 5.0 ug/g Lead ND 1.0 ug/g Molybdenum ND 1.0 ug/g Nickel ND 5.0 ug/g Selenium ND 1.0 ug/g Silver ND 0.3 ug/g Thallium ND 1.0 ug/g Vanadium ND 10.0 ug/g Vanadium ND 10.0 ug/g	Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
FŽ PHCS (C10-C16) ND 4 ug/g 73 PHCS (C16-C34) ND 8 ug/g F4 PHCS (C34-C50) ND 6 ug/g F4 PHCS (C34-C50) ND 50 ug/g Antimony ND 1.0 ug/g Antimony ND 1.0 ug/g Barium ND 1.0 ug/g Barium ND 0.5 ug/g Boron ND 5.0 ug/g Boron ND 5.0 ug/g Commin ND 5.0 ug/g Cromium ND 5.0 ug/g Cromorium ND 5.0 ug/g Cropper ND 1.0 ug/g Copper ND 1.0 ug/g Molydenum ND 1.0 ug/g Molydenum ND 1.0 ug/g Selenium ND 1.0 ug/g Selenium ND 1.0										
F3 PHCs (G16-G34)				ug/g						
F4 PHCs (G34-C50)										
Metals ND 50 ug/g Antimony ND 1.0 ug/g Arsenic ND 1.0 ug/g Barium ND 1.0 ug/g Beryllium ND 0.5 ug/g Boron ND 5.0 ug/g Cadmium ND 0.5 ug/g Chromium ND 5.0 ug/g Corpor ND 1.0 ug/g Copper ND 1.0 ug/g Copper ND 1.0 ug/g Molydednum ND 1.0 ug/g Molydednum ND 1.0 ug/g Molydednum ND 1.0 ug/g Selenium ND 1.0 ug/g Selenium ND 1.0 ug/g Vanadium ND 1.0 ug/g Vanadium ND 1.0 ug/g Vanadium ND 1.0 ug/g		ND								
Metals Antimony ND 1.0 ug/g Arsenic ND 1.0 ug/g Barium ND 1.0 ug/g Beryllium ND 0.5 ug/g Boron ND 5.0 ug/g Cadmium ND 0.5 ug/g Chromium ND 5.0 ug/g Chromium ND 5.0 ug/g Chromium ND 5.0 ug/g Copper ND 1.0 ug/g Lead ND 1.0 ug/g Molybdenum ND 1.0 ug/g Mickel ND 1.0 ug/g Selenium ND 1.0 ug/g Silver ND 0.3 ug/g Thallium ND 1.0 ug/g Uranium ND 1.0 ug/g Vanadium ND 10.0 ug/g Zinc ND 0.02 ug/g<										
Antimory ND	,			0.0						
Arsenic		ND	1.0	ug/a						
Barium	•									
Beryllium										
Boron										
Cadmium										
Chromium										
Cobat										
Copper										
Lead ND										
Molybdenum ND 1.0 ug/g Nickel ND 5.0 ug/g Selenium ND 1.0 ug/g Silver ND 0.3 ug/g Thallium ND 1.0 ug/g Uranium ND 1.0 ug/g Vanadium ND 10.0 ug/g Zinc ND 10.0 ug/g Semi-Volatiles ND 0.02 ug/g Acenaphthene ND 0.02 ug/g Acenaphthene ND 0.02 ug/g Acenaphthylene ND 0.02 ug/g Acenaphthylene ND 0.02 ug/g Benzo [a] anthracene ND 0.02 ug/g Benzo [a] prene ND 0.02 ug/g Benzo [a] fluoranthene ND 0.02 ug/g Benzo [a] fluoranthene ND 0.02 ug/g Benzo [a] fluoranthene ND 0.02 ug/g										
Nicke										
Selenium										
Silver										
Thallium										
Uranium										
Vanadium Zinc ND ND 20.0 ug/g ug/g Semi-Volatiles Acenaphthene ND 0.02 ug/g Acenaphthylene ND 0.02 ug/g Anthracene ND 0.02 ug/g Benzo [a] anthracene ND 0.02 ug/g Benzo [a] pyrene ND 0.02 ug/g Benzo [b] fluoranthene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g I-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene ND 0.02 ug/g Methylnaphthalene ND 0.04 ug/g Methylnaphthalene ND 0.04 ug/g ND 0.05 ug/g ND 0.06 ug/g ND 0.07 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>										
Semi-Volatiles										
Acenaphthene										
Acenaphthene ND 0.02 ug/g Acenaphthylene ND 0.02 ug/g Anthracene ND 0.02 ug/g Benzo [a] anthracene ND 0.02 ug/g Benzo [a] pyrene ND 0.02 ug/g Benzo [b] fluoranthene ND 0.02 ug/g Benzo [g,h,i] perylene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g I-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene ND 0.02 ug/g Methylnaphthalene ND 0.04 ug/g ND 0.01 ug/g ND 0.02 ug/g <		ND	20.0	ug/g						
Acenaphthylene ND 0.02 ug/g Anthracene ND 0.02 ug/g Benzo [a] anthracene ND 0.02 ug/g Benzo [a] pyrene ND 0.02 ug/g Benzo [b] fluoranthene ND 0.02 ug/g Benzo [g,h,i] perylene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g I-Methylnaphthalene ND 0.02 ug/g Wethylnaphthalene ND 0.02 ug/g Methylnaphthalene ND 0.04 ug/g ND 0.01 ug/g ND 0.02 ug/g ND 0.02 ug/g ND </td <td></td>										
Anthracené ND 0.02 ug/g Benzo [a] anthracene ND 0.02 ug/g Benzo [a] pyrene ND 0.02 ug/g Benzo [g,h,i] perylene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Naphthalene ND 0.04 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140				ug/g						
Benzo [a] anthracene ND 0.02 ug/g Benzo [a] pyrene ND 0.02 ug/g Benzo [b] fluoranthene ND 0.02 ug/g Benzo [g,h,i] perylene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140	Acenaphthylene			ug/g						
Benzo [a] pyrene ND 0.02 ug/g Benzo [b] fluoranthene ND 0.02 ug/g Benzo [g,h,i] perylene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Benzo [a] pyrene ND 0.02 ug/g Benzo [b] fluoranthene ND 0.02 ug/g Benzo [g,h,i] perylene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140	Benzo [a] anthracene			ug/g						
Benzo [b] fluoranthene ND 0.02 ug/g Benzo [g,h,i] perylene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140	Benzo [a] pyrene	ND	0.02							
Benzo [g,h,i] perylene ND 0.02 ug/g Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140		ND	0.02							
Benzo [k] fluoranthene ND 0.02 ug/g Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140		ND	0.02							
Chrysene ND 0.02 ug/g Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140	Benzo [k] fluoranthene	ND								
Dibenzo [a,h] anthracene ND 0.02 ug/g Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Fluoranthene ND 0.02 ug/g Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Fluorene ND 0.02 ug/g Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Indeno [1,2,3-cd] pyrene ND 0.02 ug/g 1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
1-Methylnaphthalene ND 0.02 ug/g 2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
2-Methylnaphthalene ND 0.02 ug/g Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Methylnaphthalene (1&2) ND 0.04 ug/g Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Naphthalene ND 0.01 ug/g Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Phenanthrene ND 0.02 ug/g Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Pyrene ND 0.02 ug/g Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
Surrogate: 2-Fluorobiphenyl 1.20 ug/g 89.7 50-140										
			0.02			90 7	EO 140			
Surrogate. rerpnenyr-a14 1.34 ug/g 101 50-140										
	Surrogate: Terphenyl-d14	1.34		ug/g		101	50-140			



Certificate of Analysis

Client: Paterson Group Consulting Engineers

Report Date: 13-Aug-2018

Order Date: 8-Aug-2018

Client PO: 24819 Project Description: PE4387

Method Quality Control: Duplicate

Analyta		Reporting		Source		%REC		RPD	
Analyte	Result	Limit	Units	Result	%REC	Limit	RPD	Limit	Notes
Hydrocarbons									
F2 PHCs (C10-C16)	ND	4	ug/g dry	ND				30	
F3 PHCs (C16-C34)	ND	8	ug/g dry	ND				30	
F4 PHCs (C34-C50)	ND	6	ug/g dry	ND				30	
Metals									
Antimony	ND	1.0	ug/g dry	ND				30	
Arsenic	1.6	1.0	ug/g dry	1.8			12.2	30	
Barium	60.3	1.0	ug/g dry	58.2			3.5	30	
Beryllium	0.6	0.5	ug/g dry	0.5			20.3	30	
Boron	10.2	5.0	ug/g dry	10.0			1.4	30	
Cadmium	ND	0.5	ug/g dry	ND			0.0	30	
Chromium	16.4	5.0	ug/g dry	15.9			2.6	30	
Cobalt	4.6	1.0	ug/g dry	4.6			0.7	30	
Copper	8.1	5.0	ug/g dry	8.0			1.0	30	
Lead	29.1	1.0	ug/g dry	29.6			1.8	30	
Molybdenum	ND	1.0	ug/g dry	ND			0.0	30	
Nickel	12.4	5.0	ug/g dry	11.9			3.7	30	
Selenium	ND	1.0	ug/g dry	1.0			0.0	30	
Silver	ND	0.3	ug/g dry	ND			0.0	30	
Thallium	ND	1.0	ug/g dry	ND			0.0	30	
Uranium	ND	1.0	ug/g dry	ND			0.0	30	
Vanadium	19.5	10.0	ug/g dry	19.4			0.0	30	
Zinc	73.5	20.0	ug/g dry	75.5			2.7	30	
Physical Characteristics			-9.9,						
% Solids	90.4	0.1	% by Wt.	92.7			2.5	25	
Semi-Volatiles									
Acenaphthene	ND	0.02	ug/g dry	ND				40	
Acenaphthylene	ND	0.02	ug/g dry	ND				40	
Anthracene	ND	0.02	ug/g dry	ND			0.0	40	
Benzo [a] anthracene	ND	0.02	ug/g dry	ND				40	
Benzo [a] pyrene	ND	0.02	ug/g dry	ND				40	
Benzo [b] fluoranthene	ND	0.02	ug/g dry	ND				40	
Benzo [g,h,i] perylene	ND	0.02	ug/g dry	ND				40	
Benzo [k] fluoranthene	ND	0.02	ug/g dry	ND			0.0	40	
Chrysene	ND	0.02	ug/g dry	ND				40	
Dibenzo [a,h] anthracene	ND	0.02	ug/g dry	ND				40	
Fluoranthene	ND	0.02	ug/g dry	ND			0.0	40	
Fluorene	ND	0.02	ug/g dry	ND				40	
Indeno [1,2,3-cd] pyrene	ND	0.02	ug/g dry	ND				40	
1-Methylnaphthalene	ND	0.02	ug/g dry	ND				40	
2-Methylnaphthalene	ND	0.02	ug/g dry	ND				40	
Naphthalene	ND	0.01	ug/g dry	ND				40	
Phenanthrene	ND	0.02	ug/g dry	ND				40	
Pyrene	ND	0.02	ug/g dry	ND			0.0	40	
Surrogate: 2-Fluorobiphenyl	0.931	0.02	ug/g dry		63.8	50-140	0.0		
Surrogate: Terphenyl-d14	0.930		ug/g dry		63.7	50-140			



Report Date: 13-Aug-2018

Certificate of Analysis

Client: Paterson Group Consulting Engineers

Order Date: 8-Aug-2018 Client PO: 24819 **Project Description: PE4387**

Method Quality Control: Spike

Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
Hydrocarbons									
F2 PHCs (C10-C16)	124	4	ug/g	ND	129	60-140			
F3 PHCs (C16-C34)	315	8	ug/g	ND	134	60-140			
F4 PHCs (C34-C50)	167	6	ug/g	ND	112	60-140			
F4G PHCs (gravimetric)	930	50	ug/g		93.0	80-120			
Metals									
Antimony	37.9		ug/L	ND	75.9	70-130			
Arsenic	39.1		ug/L	ND	76.8	70-130			
Barium	66.6		ug/L	23.3	86.5	70-130			
Beryllium	44.4		ug/L	ND	88.5	70-130			
Boron	44.2		ug/L	ND	80.5	70-130			
Cadmium	37.7		ug/L	ND	75.3	70-130			
Chromium	50.8		ug/L	6.4	88.8	70-130			
Cobalt	45.2		ug/L	1.8	86.6	70-130			
Copper	46.5		ug/L	ND	86.7	70-130			
Lead	56.2		ug/L	11.9	88.6	70-130			
Molybdenum	38.6		ug/L	ND	76.7	70-130			
Nickel	48.3		ug/L	ND	87.1	70-130			
Selenium	38.7		ug/L	ND	76.6	70-130			
Silver	38.0		ug/L	ND	75.9	70-130			
Thallium	45.8		ug/L	ND	91.4	70-130			
Uranium	45.0		ug/L	ND	89.7	70-130			
Vanadium	52.5		ug/L	ND	89.5	70-130			
Zinc	66.6		ug/L	30.2	72.7	70-130			
Semi-Volatiles									
Acenaphthene	0.198	0.02	ug/g	ND	108	50-140			
Acenaphthylene	0.175	0.02	ug/g	ND	95.8	50-140			
Anthracene	0.186	0.02	ug/g	ND	102	50-140			
Benzo [a] anthracene	0.176	0.02	ug/g	ND	96.3	50-140			
Benzo [a] pyrene	0.193	0.02	ug/g	ND	106	50-140			
Benzo [b] fluoranthene	0.216	0.02	ug/g	ND	118	50-140			
Benzo [g,h,i] perylene	0.170	0.02	ug/g	ND	93.3	50-140			
Benzo [k] fluoranthene	0.200	0.02	ug/g	ND	110	50-140			
Chrysene	0.210	0.02	ug/g	ND	115	50-140			
Dibenzo [a,h] anthracene	0.185	0.02	ug/g	ND	102	50-140			
Fluoranthene	0.187	0.02	ug/g	ND	103	50-140			
Fluorene	0.192	0.02	ug/g	ND	105	50-140			
Indeno [1,2,3-cd] pyrene	0.198	0.02	ug/g	ND	108	50-140			
1-Methylnaphthalene	0.229	0.02	ug/g	ND	126	50-140			
2-Methylnaphthalene	0.225	0.02	ug/g	ND	123	50-140			
Naphthalene	0.212	0.01	ug/g	ND	116	50-140			
Phenanthrene	0.203	0.02	ug/g	ND	111	50-140			
Pyrene	0.193	0.02	ug/g	ND	106	50-140			
Surrogate: 2-Fluorobiphenyl	1.46		ug/g		100	50-140			



Order #: 1832245

Report Date: 13-Aug-2018 Order Date: 8-Aug-2018 **Project Description: PE4387**

Client: Paterson Group Consulting Engineers

Client PO: 24819

Qualifier Notes:

Sample Qualifiers:

1: GC-FID signal did not return to baseline by C50

Sample Data Revisions

None

Work Order Revisions / Comments:

None

Other Report Notes:

n/a: not applicable ND: Not Detected

MDL: Method Detection Limit

Source Result: Data used as source for matrix and duplicate samples

%REC: Percent recovery. RPD: Relative percent difference.

Soil results are reported on a dry weight basis when the units are denoted with 'dry'. Where %Solids is reported, moisture loss includes the loss of volatile hydrocarbons.

CCME PHC additional information:

- The method for the analysis of PHCs complies with the Reference Method for the CWS PHC and is validated for use in the laboratory. All prescribed quality criteria identified in the method has been met.
- F1 range corrected for BTEX.
- F2 to F3 ranges corrected for appropriate PAHs where available.
- The gravimetric heavy hydrocarbons (F4G) are not to be added to C6 to C50 hydrocarbons.
- In the case where F4 and F4G are both reported, the greater of the two results is to be used for comparison to CWS PHC criteria.



Paracel ID: 1832245



Head Office 319 St. Laurent Blvd. a, Ontario K1G 4J8 30-749-1947 acel@paracellabs.com

Chain of Custody
(Lab Use Only)

Nº 44358

Page / of /

Client Name: Potarson Grov	0		Project	Reference:	PE 4	38	7				Turnar	ound Tir	nez	
Contact Name: Potarson Gro-	V		Quote #							□ Day		2	3 Day	
Address:			PO#	248	319					□ 2 Day		K	Regular	
11/-020/			Email A	Address						Date Rec	mirad:		· ·	
Telephone: 226-7381		en (h.)		owe manage	D COME D	erm (e.c.	\ D	CFD (Conitant)				Other:		
Criteria: 10 O. Reg. 153/04 (As Amended) Table						SUB (510)	m) U	SUD (Sautary)				round		-
Matrix Type: S (Soil/Sed.) GW (Ground Water) SW (Surface Water	SS (Storm S	anitary Se	wer) P (Paint) A (Air) O (O	ther)				Requi	red Analy	ses	_		
Paracel Order Number:	xir	Air Volume	of Containers	Sample	Taken	cPtals	SHAS	- F4						
Sample ID/Location Name	Matrix	Air	lo #	Date	Time	H	K	12						
1 TP2-G1	5	4		Aug 1/18		V	~	/		1X12	oml	jar +	1250	ul
2 TP4-62	5			0,,		1	/			250	onl	Jay		
3 TP5-G2	2			0		1	1			2	LXIA	omi	ign	
4 TP7-61	S			11		1	1							
5 TP8-61	S			li		1	/							
6 TP11-61	S			11		/	V			,	V			
7											A			_
8														
9														_
10														
Conuments:								1			Metho	od of Delive	P.	
Relinquished By (Sign):		ed by Dri	1	Jeans.		ved at Lab	lay	In .		Venticality	Se	2	- (s'n	4
Relinquished By (Print):	Date/T	ime 🙋	8/	08/18 3	30 Date	Finac 8	18/1	6 4	74	Date/Time: pH Verified	dug	5/10	9.4	X
Date Time: A 15 8 2818.	Tempe	rature.		C	T. Temp	erature: Q(14		N. N.	pri venned	THO			
Chain of Custody (Blank) - Rev 0.4 Feb 2016														



300 - 2319 St. Laurent Blvd Ottawa, ON, K1G 4J8 1-800-749-1947 www.paracellabs.com

Certificate of Analysis

Paterson Group Consulting Engineers

154 Colonnade Road South Nepean, ON K2E 7J5 Attn: Mark D'Arcy

Client PO: 24870 Project: PE4387 Custody: 118614

Report Date: 14-Aug-2018 Order Date: 8-Aug-2018

Order #: 1832249

This Certificate of Analysis contains analytical data applicable to the following samples as submitted:

Paracel ID Client ID 1832249-01 BH4-GW1

Approved By:

Mark Foto

Mark Foto, M.Sc. Lab Supervisor



Certificate of Analysis

Client: Paterson Group Consulting Engineers

Order Date: 8-Aug-2018

Client PO: 24870

Report Date: 14-Aug-2018

Order Date: 8-Aug-2018

Project Description: PE4387

Analysis Summary Table

Analysis	Method Reference/Description	Extraction Date	Analysis Date
PHC F1	CWS Tier 1 - P&T GC-FID	10-Aug-18	10-Aug-18
PHCs F2 to F4	CWS Tier 1 - GC-FID, extraction	9-Aug-18	9-Aug-18
REG 153: VOCs by P&T GC/MS	EPA 624 - P&T GC-MS	10-Aug-18	10-Aug-18



Certificate of Analysis

Client: Paterson Group Consulting Engineers

Client PO: 24870 Projec

Report Date: 14-Aug-2018 Order Date: 8-Aug-2018 **Project Description: PE4387**

	Cample Date.	08/08/2018 09:00			
	Sample Date: Sample ID:	1832249-01	-	-	-
	MDL/Units	Water	-	-	-
Volatiles	-				
Acetone	5.0 ug/L	<5.0	-	-	-
Benzene	0.5 ug/L	<0.5	-	-	-
Bromodichloromethane	0.5 ug/L	<0.5	-	-	-
Bromoform	0.5 ug/L	<0.5	-	-	-
Bromomethane	0.5 ug/L	<0.5	-	-	-
Carbon Tetrachloride	0.2 ug/L	<0.2	-	-	-
Chlorobenzene	0.5 ug/L	<0.5	-	-	-
Chloroform	0.5 ug/L	<0.5	-	-	-
Dibromochloromethane	0.5 ug/L	<0.5	-	-	-
Dichlorodifluoromethane	1.0 ug/L	<1.0	-	-	-
1,2-Dichlorobenzene	0.5 ug/L	<0.5	-	-	-
1,3-Dichlorobenzene	0.5 ug/L	<0.5	-	-	-
1,4-Dichlorobenzene	0.5 ug/L	<0.5	-	-	-
1,1-Dichloroethane	0.5 ug/L	<0.5	-	-	-
1,2-Dichloroethane	0.5 ug/L	<0.5	-	-	-
1,1-Dichloroethylene	0.5 ug/L	<0.5	-	-	-
cis-1,2-Dichloroethylene	0.5 ug/L	<0.5	-	-	-
trans-1,2-Dichloroethylene	0.5 ug/L	<0.5	-	-	-
1,2-Dichloropropane	0.5 ug/L	<0.5	-	-	-
cis-1,3-Dichloropropylene	0.5 ug/L	<0.5	-	-	-
trans-1,3-Dichloropropylene	0.5 ug/L	<0.5	-	-	-
1,3-Dichloropropene, total	0.5 ug/L	<0.5	-	-	-
Ethylbenzene	0.5 ug/L	<0.5	-	-	-
Ethylene dibromide (dibromoethan	0.2 ug/L	<0.2	-	-	-
Hexane	1.0 ug/L	<1.0	-	-	-
Methyl Ethyl Ketone (2-Butanone)	5.0 ug/L	<5.0	-	-	-
Methyl Isobutyl Ketone	5.0 ug/L	<5.0	-	-	-
Methyl tert-butyl ether	2.0 ug/L	<2.0	-	-	-
Methylene Chloride	5.0 ug/L	<5.0	-	-	-
Styrene	0.5 ug/L	<0.5	-	-	-
1,1,1,2-Tetrachloroethane	0.5 ug/L	<0.5	-	-	-
1,1,2,2-Tetrachloroethane	0.5 ug/L	<0.5	-	-	-
Tetrachloroethylene	0.5 ug/L	<0.5	-	-	-
Toluene	0.5 ug/L	<0.5	-	-	-
1,1,1-Trichloroethane	0.5 ug/L	<0.5	-	-	-



Report Date: 14-Aug-2018

Order Date: 8-Aug-2018

Certificate of Analysis

Client: Paterson Group Consulting Engineers

Client PO: 24870 Project Description: PE4387

Client ID:		-	-	-
•		-	-	-
Sample ID:	1832249-01	-	-	-
MDL/Units	Water	-	-	-
0.5 ug/L	<0.5	-	-	-
0.5 ug/L	<0.5	-		-
1.0 ug/L	<1.0	-	-	-
0.5 ug/L	<0.5	-	-	-
0.5 ug/L	<0.5	-	-	-
0.5 ug/L	<0.5	-	-	-
0.5 ug/L	<0.5	-	-	-
Surrogate	92.5%	-	-	-
Surrogate	122%	-	-	-
Surrogate	99.6%	-	-	-
25 ug/L	<25	-	-	-
100 ug/L	<100	-	-	-
100 ug/L	<100	-	-	-
100 ug/L	<100	-	-	-
	Sample Date: Sample ID: MDL/Units 0.5 ug/L 0.5 ug/L 1.0 ug/L 0.5 ug/L 0.5 ug/L 0.5 ug/L Surrogate Surrogate Surrogate Surrogate Surrogate Surrogate Surrogate 100 ug/L 100 ug/L	Sample Date: Sample ID: 08/08/2018 09:00 MDL/Units 08/08/2018 09:00 MDL/Units Water 0.5 ug/L <0.5	Sample Date: Sample ID: 1832249-01 MDL/Units 0.5 ug/L <0.5	Sample Date: 08/08/2018 09:00 - - Sample ID: 1832249-01 - - MDL/Units Water - - 0.5 ug/L <0.5



Order #: 1832249

Report Date: 14-Aug-2018 Order Date: 8-Aug-2018

Client: Paterson Group Consulting EngineersOrder Date: 8-Aug-2018Client PO: 24870Project Description: PE4387

Method Quality Control: Blank

Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
Hydrocarbons									
F1 PHCs (C6-C10)	ND	25	ug/L						
F2 PHCs (C10-C16)	ND	100	ug/L						
F3 PHCs (C16-C34)	ND	100	ug/L						
F4 PHCs (C34-C50)	ND	100	ug/L						
Volatiles			•						
Acetone	ND	5.0	ug/L						
Benzene	ND	0.5	ug/L						
Bromodichloromethane	ND	0.5	ug/L						
Bromoform	ND	0.5	ug/L						
Bromomethane	ND	0.5	ug/L						
Carbon Tetrachloride	ND	0.2	ug/L						
Chlorobenzene	ND	0.5	ug/L						
Chloroform	ND	0.5	ug/L						
Dibromochloromethane	ND	0.5	ug/L						
Dichlorodifluoromethane	ND	1.0	ug/L						
1,2-Dichlorobenzene	ND	0.5	ug/L						
1,3-Dichlorobenzene	ND	0.5	ug/L						
1,4-Dichlorobenzene	ND	0.5	ug/L						
1,1-Dichloroethane	ND	0.5	ug/L						
1,2-Dichloroethane	ND	0.5	ug/L						
1,1-Dichloroethylene	ND	0.5	ug/L						
cis-1,2-Dichloroethylene	ND	0.5	ug/L						
trans-1,2-Dichloroethylene	ND	0.5	ug/L						
1,2-Dichloropropane	ND	0.5	ug/L						
cis-1,3-Dichloropropylene	ND	0.5	ug/L						
trans-1,3-Dichloropropylene	ND	0.5	ug/L						
1,3-Dichloropropene, total	ND	0.5	ug/L						
Ethylbenzene	ND	0.5	ug/L						
Ethylene dibromide (dibromoethane	ND	0.2	ug/L						
Hexane	ND	1.0	ug/L						
Methyl Ethyl Ketone (2-Butanone)	ND	5.0	ug/L						
Methyl Isobutyl Ketone	ND	5.0	ug/L						
Methyl tert-butyl ether	ND	2.0	ug/L						
Methylene Chloride	ND	5.0	ug/L						
Styrene	ND	0.5	ug/L						
1,1,1,2-Tetrachloroethane	ND	0.5	ug/L						
1,1,2,2-Tetrachloroethane	ND	0.5	ug/L						
Tetrachloroethylene	ND	0.5	ug/L						
Toluene	ND	0.5	ug/L						
1,1,1-Trichloroethane	ND	0.5	ug/L						
1,1,2-Trichloroethane	ND	0.5	ug/L						
Trichloroethylene	ND	0.5	ug/L						
Trichlorofluoromethane	ND	1.0	ug/L						
Vinyl chloride	ND	0.5	ug/L						
m,p-Xylenes	ND	0.5	ug/L						
o-Xylene	ND	0.5	ug/L						
Xylenes, total	ND	0.5	ug/L						
Surrogate: 4-Bromofluorobenzene	81.8		ug/L		102	50-140			
Surrogate: Dibromofluoromethane	83.8		ug/L		105	50-140			
Carrogato: Bibromonacromothano									



Report Date: 14-Aug-2018

Certificate of Analysis

Client: Paterson Group Consulting Engineers

Client: Paterson Group Consulting Engineers
Order Date: 8-Aug-2018
Client PO: 24870
Project Description: PE4387

Method Quality Control: Duplicate

Analyte	Result	Reporting Limit	ما اما ا	Source	0/ DEC	%REC	RPD	RPD Limit	Notes
, mary co	Kesuit	LIIIIII	Units	Result	%REC	Limit	KPD	Limit	notes
Hydrocarbons									
F1 PHCs (C6-C10)	ND	25	ug/L	ND				30	
Volatiles									
Acetone	7.14	5.0	ug/L	7.64			6.8	30	
Benzene	7.14 ND	0.5	ug/L ug/L	7.04 ND			0.0	30	
Bromodichloromethane	1.45	0.5		1.43			1.4	30	
Bromoform	ND	0.5	ug/L	ND			1.4	30	
Bromomethane	ND ND	0.5	ug/L	ND ND				30	
			ug/L						
Carbon Tetrachloride	ND	0.2	ug/L	ND				30	
Chlorobenzene	ND	0.5	ug/L	ND			0.4	30	
Chloroform	3.33	0.5	ug/L	3.25			2.4	30	
Dibromochloromethane	0.88	0.5	ug/L	0.87			1.1	30	
Dichlorodifluoromethane	ND	1.0	ug/L	ND				30	
1,2-Dichlorobenzene	ND	0.5	ug/L	ND				30	
1,3-Dichlorobenzene	ND	0.5	ug/L	ND				30	
1,4-Dichlorobenzene	ND	0.5	ug/L	ND				30	
1,1-Dichloroethane	ND	0.5	ug/L	ND				30	
1,2-Dichloroethane	ND	0.5	ug/L	ND				30	
1,1-Dichloroethylene	ND	0.5	ug/L	ND				30	
cis-1,2-Dichloroethylene	ND	0.5	ug/L	ND				30	
trans-1,2-Dichloroethylene	ND	0.5	ug/L	ND				30	
1,2-Dichloropropane	ND	0.5	ug/L	ND				30	
cis-1,3-Dichloropropylene	ND	0.5	ug/L	ND				30	
trans-1,3-Dichloropropylene	ND	0.5	ug/L	ND				30	
Ethylbenzene	ND	0.5	ug/L	ND				30	
Ethylene dibromide (dibromoethane	ND	0.2	ug/L	ND				30	
Hexane	ND	1.0	ug/L	ND				30	
Methyl Ethyl Ketone (2-Butanone)	ND	5.0	ug/L	ND			0.0	30	
Methyl Isobutyl Ketone	ND	5.0	ug/L	ND				30	
Methyl tert-butyl ether	ND	2.0	ug/L	ND				30	
Methylene Chloride	ND	5.0	ug/L	ND				30	
Styrene	135	0.5	ug/L	130			3.6	30	
1,1,1,2-Tetrachloroethane	ND	0.5	ug/L	ND				30	
1,1,2,2-Tetrachloroethane	ND	0.5	ug/L	ND				30	
Tetrachloroethylene	ND	0.5	ug/L	ND				30	
Toluene	ND	0.5	ug/L	ND				30	
1,1,1-Trichloroethane	ND	0.5	ug/L	ND				30	
1,1,2-Trichloroethane	ND	0.5	ug/L	ND				30	
Trichloroethylene	ND	0.5	ug/L	ND				30	
Trichlorofluoromethane	ND	1.0	ug/L	ND				30	
Vinyl chloride	ND	0.5	ug/L	ND				30	
m,p-Xylenes	ND ND	0.5	ug/L	ND				30	
o-Xylene	ND	0.5	ug/L	ND				30	
Surrogate: 4-Bromofluorobenzene	96. <i>4</i>	0.5	ug/L ug/L	ND	120	50-140		30	
•									
Surrogate: Dibromofluoromethane	97.7		ug/L		122	50-140			
Surrogate: Toluene-d8	79.5		ug/L		99.3	<i>50-140</i>			



Order #: 1832249

Report Date: 14-Aug-2018 Order Date: 8-Aug-2018

Client: Paterson Group Consulting Engineers Client PO: 24870 **Project Description: PE4387**

Method Quality Control: Snike

Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
Hydrocarbons									
F1 PHCs (C6-C10)	1820	25	ug/L		91.0	68-117			
F2 PHCs (C10-C16)	1780	100	ug/L		111	60-140			
F3 PHCs (C16-C34)	5050	100	ug/L		129	60-140			
F4 PHCs (C34-C50)	3140	100	ug/L		127	60-140			
Volatiles									
Acetone	96.5	5.0	ug/L	7.64	88.8	50-140			
Benzene	51.8	0.5	ug/L	ND	130	50-140			
Bromodichloromethane	49.0	0.5	ug/L	1.43	119	50-140			
Bromoform	49.7	0.5	ug/L	ND	124	50-140			
Bromomethane	49.2	0.5	ug/L	ND	123	50-140			
Carbon Tetrachloride	48.8	0.2	ug/L	ND	122	50-140			
Chlorobenzene	41.6	0.5	ug/L	ND	104	50-140			
Chloroform	46.8	0.5	ug/L	3.25	109	50-140			
Dibromochloromethane	51.0	0.5	ug/L	0.87	125	50-140			
Dichlorodifluoromethane	50.4	1.0	ug/L	ND	126	50-140			
1,2-Dichlorobenzene	46.8	0.5	ug/L	ND	117	50-140			
1,3-Dichlorobenzene	46.7	0.5	ug/L	ND	117	50-140			
1,4-Dichlorobenzene	46.8	0.5	ug/L	ND	117	50-140			
1,1-Dichloroethane	51.5	0.5	ug/L	ND	129	50-140			
1,2-Dichloroethane	42.9	0.5	ug/L	ND	107	50-140			
1,1-Dichloroethylene	40.7	0.5	ug/L	ND	102	50-140			
cis-1,2-Dichloroethylene	50.5	0.5	ug/L	ND	126	50-140			
trans-1,2-Dichloroethylene	43.1	0.5	ug/L	ND	108	50-140			
1,2-Dichloropropane	50.1	0.5	ug/L	ND	125	50-140			
cis-1,3-Dichloropropylene	46.0	0.5	ug/L	ND	115	50-140			
trans-1,3-Dichloropropylene	47.7	0.5	ug/L	ND	119	50-140			
Ethylbenzene	44.1	0.5	ug/L	ND	110	50-140			
Ethylene dibromide (dibromoethane	47.4	0.2	ug/L	ND	119	50-140			
Hexane	43.1	1.0	ug/L	ND	108	50-140			
Methyl Ethyl Ketone (2-Butanone)	135	5.0	ug/L	ND	135	50-140			
Methyl Isobutyl Ketone	134	5.0	ug/L	ND	134	50-140			
Methyl tert-butyl ether	99.2	2.0	ug/L	ND	99.2	50-140			
Methylene Chloride	42.4	5.0	ug/L	ND	106	50-140			
Styrene	167	0.5	ug/L	130	92.0	50-140			
1,1,1,2-Tetrachloroethane	50.5	0.5	ug/L	ND	126	50-140			
1,1,2,2-Tetrachloroethane	45.2	0.5	ug/L	ND	113	50-140			
Tetrachloroethylene	46.0	0.5	ug/L	ND	115	50-140			
Toluene	42.1	0.5	ug/L	ND	105	50-140			
1,1,1-Trichloroethane	41.7	0.5	ug/L	ND	104	50-140			
1,1,2-Trichloroethane	48.0	0.5	ug/L	ND	120	50-140			
Trichloroethylene	46.8	0.5	ug/L	ND	117	50-140			
Trichlorofluoromethane	45.0	1.0	ug/L	ND	112	50-140			
Vinyl chloride	50.5	0.5	ug/L	ND	126	50-140			
m,p-Xylenes	95.9	0.5	ug/L	ND	120	50-140			
o-Xylene	48.8	0.5	ug/L	ND	122	50-140			
Surrogate: 4-Bromofluorobenzene	65.2		ug/L		81.5	50-140			



Certificate of Analysis

Client: Paterson Group Consulting Engineers

Order Date: 8-Aug-2018

Client PO: 24870

Project Description: PE4387

Qualifier Notes:

None

Sample Data Revisions

None

Work Order Revisions / Comments:

None

Other Report Notes:

n/a: not applicable ND: Not Detected

MDL: Method Detection Limit

Source Result: Data used as source for matrix and duplicate samples

%REC: Percent recovery. RPD: Relative percent difference.

CCME PHC additional information:

- The method for the analysis of PHCs complies with the Reference Method for the CWS PHC and is validated for use in the laboratory. All prescribed quality criteria identified in the method has been met.
- F1 range corrected for BTEX.
- F2 to F3 ranges corrected for appropriate PAHs where available.
- The gravimetric heavy hydrocarbons (F4G) are not to be added to C6 to C50 hydrocarbons.
- In the case where F4 and F4G are both reported, the greater of the two results is to be used for comparison to CWS PHC criteria.



LABORATORIES LTD.

Paracel ID: 1832249

Head Office 300-2319 St. Laurent Blvd. Ottawa, Ontario K1G 4J8

p: 1-800-749-1947 e: paracel@paracellabs.com Chain of Custody (Lab Use Only)

Nº 118614

Page L of L

Client Name: PATCRSON		Project Reference: PE4367											Turnaround Time:						
Contact Name: MARLY D'ARLY Address: 54 Colonnact Telephone: 13-226-734 Criteria: 00, Reg. 153/04 (As Amended) Table 0 RSC Filing 00, Reg. 558/0					Quote #											ay		□3 Day	y
					Email Address: Andress: Onter someron D. Co.										□ 2 Day Date Required:			∠ Regular	
Cate and 15 0 Page 157/04 (Ac	Amandadi Table 3 FIR	SC Filine D	O. Reg	558/00	DPW00 DC	CME II SU	B (Sto	m)	DS	UB (Sanita	ary)	Municipali	ty:			ther:		113
Matrix Type: S (Soil/Sed.) GW (Grou								uire											
Paracel Order Number: 1832249		rix	Air Volume	of Containers	Sample Taken		s F1-F4+BTEX	9	8	Metals by ICP			B (HWS)						
Sample ID/Loc	eation Name	Matrix	Air	to #	Date	Time	PHCs	VOCs	PAHs	Meta	#	Crv	E .						_
1 Bitit-GWI		bu		3	Aug 8/15		X	X				4						_	_
2					11				Ц		Н	4	_	_				-	_
3							+			L	H	+			_		_	\dashv	
4							+		_		Н	+		-		-		+	_
5				-			+	_	_	-	Н	+	-		-		-	-	
6		-	_	-			+	_	_	-	Н	+						+	
7		-	_	-			+	-		-		+						+	
8							+					+	1					\forall	
9							+				Н								
Comments:																-	of Deliver)
Relinquished By (Sign):	B.		-	ver/Depo	1 COUSE		ved at L	ab:	a		L	-		1	10	Se	7		
Relinquished By (Print): MIK	EB	Date/Tin	ne: Of	3/08	3/18 3	30 Date	Time: crature:	8/	10	180 °C		4:	25	pH Ven	- 1	hus	(19)	504	
Date/Time:		Tempera	nanc.			Total Total			V	-	-					1			