

June 7, 2024 FINAL

Windmill Development Group 150 Elgin Street, Suite 1000 Ottawa, ON K2P 1L4

Re: Phase One Environmental Site Assessment Update

384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario

Pinchin File: 341532

Pinchin Ltd. (Pinchin) is pleased to provide the findings of our Phase One Environmental Site Assessment (ESA) Update to Windmill Development Group (Client) for the property described as 384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario (Phase One Property or Site).

#### 1.0 BACKGROUND

This Phase One ESA Update has been prepared by Pinchin for the Client as an update to a Phase One ESA dated September 23, 2022 completed for the Phase One Property. The Phase One Property and Phase One Study Area are shown on Figure 2 (all figures are provided in Appendix I).

Pinchin previously prepared the following relevant reports for Client:

 "Phase One Environmental Site Assessment, 384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario" and dated September 23, 2022 (2022 Pinchin Phase One ESA Report).

At the time of the above-noted assessments, the Phase One Property was developed with a two-storey community building (Site Building).

Based on information obtained during the 2022 Pinchin Phase One ESA, two potentially contaminating activities (PCAs) were identified at the Phase One Property (i.e., on-Site) and 29 PCAs were identified within the Phase One Study Area outside of the Phase One Property (i.e., off-Site). Of the on and off-Site PCAs, none were considered to result in areas of potential environmental concern (APECs) at the Phase One Property given no evidence of spills or historical spills (i.e., staining) observed in the vicinity of the transformers and no issues of potential environmental concern (i.e., spills) were noted for the transformers within the Environmental Risk Information Services report and any maintenance/ environmental issues associated with the transformers would be the responsibility of Hydro Ottawa; no spills, evidence of historical spills (i.e., staining) or floor drains observed in the boiler room and vicinity of the historical on-Site aboveground storage tank (AST); the impacts of creosote or chromated copper arsenate (CCA) typically being minor, localized, and near the surface; polychlorinated biphenyls (PCBs) being highly immobile in soils and immiscible in water; the distance between these properties and the Phase One property; and the inferred groundwater flow direction. Based on these findings, nothing was

June 7, 2024 Pinchin File: 341532

FINAL

identified that is likely to have resulted in impacts to the soil and/or groundwater at the Phase One Property and would require the completion of a Phase Two ESA. As such, it is Pinchin's opinion that the Phase One Property is suitable for the purpose of filing a rezoning application with the City of Ottawa based only on the completion of this Phase One ESA report.

Pinchin conducted the 2022 Pinchin Phase One ESA Report in accordance with Part VII and Schedule D of the Province of Ontario's *Environmental Protection Act R.S.O. 1990, c. E.19* and *Ontario Regulation 153/04: Records of Site Condition – Part XV.1 of the Act*, and last amended by Ontario Regulation 274/20 on July 1, 2020 (O. Reg. 153/04). The purpose of the Phase One ESA was to assess the potential presence of environmental impacts at the Phase One Property due to activities at and near the Phase One Property.

The 2022 Pinchin Phase One ESA Report was conducted at the request of the Client as a condition for a rezoning application with the City of Ottawa.

The purposes of this Phase One ESA Update were to:

- Assess whether any new APECs or PCAs exist at the Phase One Property or Phase One Study Area;
- Provide a revised table and figures summarizing PCAs identified in the Phase One Study
   Area; and
- Provide a revised Phase One Conceptual Site Model (Phase One CSM) following further consideration of potential exposure pathways and ecological receptors.

The Phase One ESA Update constitute the Phase One ESA reporting requirements necessary to support a rezoning application for the Site in accordance with O. Reg. 153/04. An update must be prepared if a Phase One ESA report is more than 18 months old prior to filing a rezoning application.

# 2.0 SCOPE OF WORK

The scope of work for this Update Phase One ESA was consistent with O. Reg. 153/04 in support of the Client's rezoning application and was comprised of a Site reconnaissance. The Site reconnaissance comprised of a visual assessment of the Phase One Property and the surrounding properties within the Phase One Study Area (from publicly-accessible areas) including any associated buildings and/or facilities for the purpose of identifying the presence of potentially contaminating activities (PCAs).

Furthermore, Pinchin conducted an interview with the current Site owner to determine if any current or historical operations have caused a concern with respect to the environmental condition of the Phase One Property and the surrounding properties within the Phase One Study Area.

© 2024 Pinchin Ltd. Page 2 of 10

# June 7, 2024 Pinchin File: 341532 FINAL

# 2.1 Written Description of Investigation

# 2.2.1 Summary of Site Reconnaissance

Pinchin formerly completed a Site inspection and a review of surrounding properties within the Phase One Study Area from publicly accessible locations on August 31, 2022 as part of the original Phase One ESA. The initial Site reconnaissance was completed by Pinchin personnel, under the supervision of Pinchin's Qualified Person (QP) overseeing this project. The Phase One Study Area is outlined on Figure 3.

As part of this Update Phase One ESA, Mr. Alex Kelly of Pinchin completed an additional Site reconnaissance on May 27, 2024 under supervision of Pinchin's QP for this project. The Site reconnaissance was documented with notes and photographs. Photographs of some of the features noted during the Site reconnaissance are attached in Appendix II.

The results of the subsequent Site reconnaissance indicated that no substantial changes have been observed to have occurred on the Phase One Property or on the surrounding properties located within the Phase One Study Area from the time of the initial Site reconnaissance that would result in potential subsurface impacts at the Phase One Property. As such, no additional PCAs or APECs, beyond the PCAs identified in the initial Phase One ESA, have been identified.

### 3.0 REVIEW AND EVALUATION OF INFORMATION

### 3.1 First Developed Use Determination

The first developed land use of the Phase One Property is defined by O. Reg. 153/04 to be the earlier of:

- The first use of a Phase One Property in or after 1875 that resulted in the development of a building or structure on the property; and
- The first potentially contaminating use or activity on the Phase One Property.

A review of the aerial photographs, Fire Insurance Plans (FIPs), an interview with the Site Representative and an exterior plaque observed during the Site reconnaissance, determined that the original portion of the Site Building was constructed in approximately the early 1900's, with an addition constructed along the northwest elevation of the original portion of the Site Building in approximately 1910. In the 1928 aerial photograph and 1922 FIP reviewed by Pinchin, a building that was similar in size and configuration the present-day Site Building was evident on the Phase One Property. Therefore, it is Pinchin's opinion that the first developed use of the Phase One Property was in the early 1900's.

The Site Building is currently occupied by the Ottawa Korean Community Church as a church. The FIPs for the Phase One Property indicated that the Site Building was historically occupied by Bell Street

© 2024 Pinchin Ltd. Page 3 of 10

384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario Windmill Development Group

June 7, 2024 Pinchin File: 341532 FINAL

Methodist Church in 1915 and 1922, and Bell Street United Church in 1948 and 1963. Therefore, the Site Building has historically been occupied as a church.

The date of the first developed use of the Phase One Property was determined through a review of FIPs, aerial photographs, an exterior plaque and information from the Site Representative. No other information was reviewed by Pinchin during the records review, or obtained during the Site reconnaissance or interviews which would have resulted in a different interpretation of the date of first developed use of the Phase One Property.

# 3.2 Potentially Contaminating Activities

### 3.2.1 On-Site PCAs

Pinchin's investigation of the Phase One Property during the previous Phase One ESA identified the following on-Site PCAs that were considered to represent APECs at the Phase One Property:

- PCA-1: Item 28: Gasoline and Associated Products Storage in Fixed Tanks fill/vent pipes indicative of an AST were observed within the boiler room and exterior to the west elevation of the Site Building during Pinchin's Site reconnaissance. In addition, equipment observed within the boiler room indicated that an oil-fired boiler system was formerly present within the Site Building; and
- PCA-2: Item 55: Transformer Manufacturing, Processing and Use a pole-mounted oilcooled transformer is located adjacent to the north elevation of the Site Building.

No substantive changes were observed to have been made to the Phase One Property from the time of the initial Site reconnaissance that would result in potential subsurface impacts and, as such, no additional on-Site PCAs have been identified as part of this Update Phase One ESA.

The locations of the on-Site PCAs are shown on Figure 3.

#### 3.2.2 Off-Site PCAs

29 PCAs were identified within the Phase One Study Area outside of the Phase One Property (i.e., off-Site). Of the off-Site PCAs, none were considered to result in APECs at the Phase One Property:

- PCA-3: Item 46: Rail Yards, Tracks and Spurs the Canada Atlantic Railway was located approximately 30 m south of the Phase One Property in the 1895-1948 FIPs. In addition, a former railyard presumably associated with the Canadian Atlantic Railway was located approximately 80 m south of the Phase One Property in the 1895-1948 FIPs;
- PCA-4: Item 37: Operation of Dry Cleaning Equipment (where chemicals are used) –
   Trans Dry Cleaning was listed at 219 Bell Street North in the 2000 city directory;

© 2024 Pinchin Ltd. Page 4 of 10



384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario Windmill Development Group

June 7, 2024 Pinchin File: 341532 FINAL

- PCA-5: Other the property located at 10 Orangeville Street was identified within the National PCB Inventory database search results. This property was identified as having stored PCBs or PCB-containing equipment (including transformers, capacitors, ballasts, soil and free liquids;
- PCA-6: Item 10: Commercial Autobody Shops White Truck Sale Ottawa Ltd. and an automotive repair/servicing facility were located at 520 Bronson Avenue in the 1948 and 1963 FIPs;
- PCA-7: Other the property located at 555 Booth Street was identified within the National PCB Inventory database search results. This property was identified as having stored PCBs or PCB-containing equipment (including transformers, capacitors, ballasts, soil and free liquids;
- PCA-8: Item 10: Commercial Autobody Shops Green's Garage and Holliday Auto (i.e., automotive repair/servicing facilities;
- PCA-9: Other the property located at 605 Bronson Avenue was identified within the National PCB Inventory database search results and within the Ontario Inventory of PCB Storage Sites database. This property was identified as having stored PCBs or PCB-containing equipment (including transformers, capacitors, ballasts, soil and free liquids) within the Phase One Study Area; however, PCBs are highly immobile in soils and immiscible in water. Item 28: Gasoline and Associated Products Storage in Fixed Tanks the property located at 275 Chamberlain Avenue was identified within the chemical or fuel storage tank databases search results. This property was listed in these databases as an institutional building with associated underground storage tanks (USTs)). It should be noted that 605 Bronson Avenue and 275 Chamberlain Avenue are the same property;
- PCA-10: Item 28: Gasoline and Associated Products Storage in Fixed Tanks the
  property located at 470 Bronson Avenue was identified within the chemical or fuel
  storage tank databases search results. This property was listed in these databases as an
  RFO with associated USTs; and
- PCAs-11-31: Item 55: Transformer Manufacturing, Processing and Use a total of 36 pole-mounted oil-cooled transformers are located within 250 m of the Phase One Property.

No substantive changes were observed to have been made to the Phase One Study Area from the time of the initial Site reconnaissance that would result in potential subsurface impacts and, as such, no additional on-Site PCAs have been identified as part of this Update Phase One ESA.

The locations of the off-Site PCAs are shown on Figure 3.

© 2024 Pinchin Ltd. Page 5 of 10

June 7, 2024 Pinchin File: 341532

**FINAL** 

#### 3.3 Areas of Potential Environmental Concern

No APECs as defined by O. Reg. 153/04 were identified by Pinchin at the Phase One Property.

# 3.4 Updated Phase One Conceptual Site Model

A conceptual site model (CSM) was created to provide a summary of the findings of the Update Phase One ESA. The Phase One CSM is summarized in Figures 1 through 3, which illustrate the following features within the Phase One Study Area, where present:

- Existing buildings and structures;
- Water bodies located in whole or in part within the Phase One Study Area;
- Areas of natural significance located in whole or in part within the Phase One Study Area;
- Drinking water wells located at the Phase One Property;
- Land use of adjacent properties;
- Roads within the Phase One Study Area;
- PCAs within the Phase One Study Area, including the locations of tanks; and
- APECs at the Phase One Property.

The following provides a narrative summary of the Updated Phase One CSM:

- The Phase One Property consists of one legal lot situated at the municipal addresses of 384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario, which is currently owned by The Ottawa Korean Community Church. The Phase One Property is located immediately south of Arlington Avenue, approximately 50 metres (m) southwest of the intersection of Arlington Avenue and Cambridge Street North in Ottawa, Ontario. The Phase One Property is presently developed with a two-storey community building (Site Building). There is no record of industrial use or of a commercial use (e.g., garage, bulk liquid dispensing facility or dry cleaner) that would require classifying the Phase One Property as an enhanced investigation property;
- The nearest surface water body is the Ottawa River located approximately 1.5 kilometres northwest of the Phase One Property at an elevation of approximately 53 m above mean sea level;
- No areas of natural significance were identified within the Phase One Study Area;
- No drinking water wells were located on the Phase One Property;

© 2024 Pinchin Ltd. Page 6 of 10



384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario Windmill Development Group

June 7, 2024 Pinchin File: 341532 FINAL

- The adjacent and surrounding properties in the vicinity of the Site consist of commercial and residential land uses. The properties located north of the Phase One Property consist of residential dwellings, multi-tenant residential buildings and associated roadways; the properties located east of the Phase One Property consist of multi-tenant residential buildings, residential dwellings, commercial buildings and associated roadways; the properties located south of the Phase One Property consist of residential dwellings and associated roadways to beyond 200 m from the Phase One Property; and the properties located west of the Phase One Property consist of multi-tenant residential buildings, an automotive repair/servicing facility and associated roadways to beyond 200 m from the Phase One Property;
- Two PCAs were identified at the Phase One Property (i.e., a former on-Site heating oil AST; and one pole-mounted oil-cooled transformer located adjacent to the north elevation of the Site Building). 29 PCAs were identified within the Phase One Study Area:
  - A former railway line located approximately 30 m south of the Phase One Property and a former railyard located approximately 80 m south of the Phase One Property in the 1895-1948 FIPs;
  - A dry-cleaning facility located approximately 45 m north of the Phase One
     Property in the 2000 city directory;
  - Three properties identified in the PCB inventory database search located approximately 100 m southwest, 150 m southwest and 200 m southeast of the Phase One Property, respectively;
  - A former automotive repair/servicing facility located approximately 120 m northeast of the Phase One Property in the 1948 and 1963 FIPs;
  - An active automotive repair/servicing facility located approximately 150 m west of the Phase One Property since approximately 1966;
  - Two properties identified in the chemical or fuel storage tank databases search results as having USTs, located approximately 200 m southeast and 200 m northeast of the Phase One property, respectively; and
  - A total of 36 pole-mounted oil-cooled transformers located within 250 m of the Phase One Property.

© 2024 Pinchin Ltd. Page 7 of 10

384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario Windmill Development Group

June 7, 2024 Pinchin File: 341532 FINAL

However, no evidence of spills or historical spills (i.e., staining) observed in the vicinity of the transformers and no issues of potential environmental concern (i.e., spills) were noted for the transformers within the ERIS report and any maintenance/environmental issues associated with the transformers would be the responsibility of Hydro Ottawa. Based on the above-noted information, as well as no spills, evidence of historical spills (i.e., staining) or floor drains observed in the boiler room and vicinity of the historical on-Site AST; the impacts of creosote or CCA typically being minor, localized, and near the surface; PCBs being highly immobile in soils and immiscible in water; the distance between these properties and the Phase One property; and the inferred groundwater flow direction, it is Pinchin's opinion that these PCAs do not represent areas of potential environmental concern for the Phase One Property. Based on these findings, nothing was identified that is likely to have resulted in impacts to the soil and/or groundwater at the Phase One Property and would require the completion of a Phase Two ESA. As such, it is Pinchin's opinion that the Phase One Property is suitable for the purpose of filing a rezoning application with the City of Ottawa based only on the completion of this Phase One ESA report;

- Underground utilities at the Phase One Property provide potable water, natural gas, electrical, telephone, cable and sewer services to the Site Building. These services enter the Site Building through subsurface conduits, with the exception of a pressurized natural gas line, which connects to meters located along the exterior of the Site Building;
- The Phase One Property and the surrounding properties located within the Phase One Study Area are located within alluvial deposits consisting of stratified gravel, sand, silt and clay. Bedrock is expected to consist of sedimentary rocks consisting of limestone, dolomite, shale, argillite, sandstone, quartzite, and/or grit; and
- The Phase One Property is relatively flat. Local groundwater flow is inferred to be to the northwest, based on the nearest surface water body.

There were no deviations from the Phase One ESA requirements specified in O. Reg. 153/04 or absence of information that have resulted in uncertainty that would affect the validity of the Phase One CSM.

© 2024 Pinchin Ltd. Page 8 of 10

June 7, 2024 Pinchin File: 341532

FINAL

#### 4.0 CONCLUSIONS

Pinchin conducted this Phase One ESA Update in order to satisfy the requirements of O. Reg. 153/04. No additional PCAs or APECs beyond that which was previously identified in the 2022 Pinchin Phase One ESA.

The conclusions of this Phase One ESA Update represent the best judgment of the assessor and QP based on the conditions of the Phase One Property observed since completion of the 2022 Pinchin Phase One ESA Report. The combined 2022 Pinchin Phase One ESA Report and the Phase One ESA Update constitute the Phase One ESA reporting requirements necessary to support a rezoning application for the Site in accordance with O. Reg. 153/04.

The Update Phase One ESA of the property located at 384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario has been conducted in accordance with O. Reg. 153/04, under the supervision of a QP.

### 5.0 TERMS AND LIMITATIONS

This Phase One ESA Update was performed in order to identify potential issues of environmental concern associated with the Phase One Property located at 384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario (Phase One Property) since the time of the initial Site reconnaissance on August 31, 2022. This Phase One ESA Update was performed in general compliance with currently acceptable practices for environmental site investigations, and specific client requests, as applicable to this Phase One Property.

This report was prepared for the exclusive use of Windmill Development Group, subject to the terms, conditions and limitations contained within the duly authorized work plan for this project. Any use which a third party makes of this report, or any reliance on or decisions to be made based on it, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted.

If additional parties require reliance on this report, written authorization from Pinchin will be required. Such reliance will only be provided by Pinchin following written authorization from the Client. Pinchin disclaims responsibility of consequential financial effects on transactions or property values, or requirements for follow-up actions and costs. No other warranties are implied or expressed. Furthermore, this report should not be construed as legal advice. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law.

© 2024 Pinchin Ltd. Page 9 of 10



384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario Windmill Development Group

June 7, 2024 Pinchin File: 341532 FINAL

The information provided in this report is based upon analysis of available documents, records and drawings, and personal interviews. In evaluating the Site, Pinchin has relied in good faith on information provided by other individuals noted in this report. Pinchin has assumed that the information provided is factual and accurate. In addition, the findings in this report are based, to a large degree, upon information provided by the current owner/occupant. Pinchin accepts no responsibility for any deficiency, misstatement or inaccuracy contained in this report as a result of omissions, misinterpretations or fraudulent acts of persons interviewed or contacted, or contained in reports that were reviewed.

Pinchin makes no other representations whatsoever, including those concerning the legal significance of its findings, or as to other legal matters touched on in this report, including, but not limited to, ownership of any property, or the application of any law to the facts set forth herein. With respect to regulatory compliance issues, regulatory statutes are subject to interpretation and these interpretations may change over time.

We trust that the information provided in this report meets your current requirements. If you have any questions or concerns, please do not hesitate to contact the undersigned.

### Pinchin Ltd.

Prepared by: Reviewed by:

Alex Kelly, M.Sc.
Project Coordinator
613.223.0668
akelly@pinchin.com

Scott Mather, P.Eng., QP<sub>ESA</sub> Director, Eastern Ontario 613.851.4098 smather@pinchin.com

Encl: Appendix I – Figures


Appendix II – Photographs


\\pinchin.com\Ott\Job\341000s\0341532.000 Windmill,Arlington&Bell,Ottawa,EDR,SAONE\Deliverables\341532 Phase One ESA Update Arlington Ave and Bell St N Ottawa ON.doc

Template: Phase I ESA Stage 1 PSI Update Report Template, EDR, June 6, 2023

© 2024 Pinchin Ltd. Page 10 of 10

APPENDIX I Figures







APPENDIX II Photographs

Appendix II Pinchin File: 341532 FINAL



Photo 1 – Site Building (northwest elevation).



Photo 2 – Site Building (northeast elevation).

© 2024 Pinchin Ltd. Page 1 of 4

Appendix II Pinchin File: 341532 FINAL



Photo 3 – Site Building (southeast elevation).



Photo 4 – Site Building (southwest elevation).

© 2024 Pinchin Ltd. Page 2 of 4

384 Arlington Avenue and 241 Bell Street North, Ottawa, Ontario Photographs

Appendix II Pinchin File: 341532 FINAL



Photo 5 – Property located northwest of the Site.



Photo 6 – Property located northeast of the Site.

© 2024 Pinchin Ltd. Page 3 of 4

Appendix II Pinchin File: 341532 FINAL



Photo 7 – Property located southeast of the Site.



Photo 8 – Property located southwest of the Site.

© 2024 Pinchin Ltd. Page 4 of 4