

315-321 CHAPEL STREET - ALL SAINTS

Project Location: 315-321 Chapel Street

A LOOK INSIDE

Here is what you will ind in this document:

1 PROJECT DESCRIPTION

5 Rendering

02 DESIGN DIRECTIVES

- **7** ZBLA PH1 Pre-Consultation Comments
- **10** ZBLA PH2 Pre-Consultation Comments
- 13 ZBLA PH3 Pre-Consultation Comments
- **14** SPC PH1 Pre-Consultation Comments
- 17 Responses to UDRP Comments
- **21** Responses to Round 3 SPC Comments

03 SITE, CONTEXT, AND ANALYSIS

- **29** Surrounding site context
- **30** Perspective images to and / or from the site
- 32 Built and natural heritage assets on and adjacent area

04 DESIGN RESEARCH

36 Design evolution

05 APPENDIX

- **45** Site Plan
- **46** Landscape Plan
- 49 Building Elevations of the proposed building
- 53 Floor Plans of the proposed building

PROJECT DESCRIPTION

Project Rendering





DESIGN DIRECTIVES

• Compiled comments received to date related to Urban Design and Architecture







315 + 321 Chapel Street Responses to ZBLA Pre-Consultation Phase 1 Comments August 23, 2023

No.	Comment	Response
1	Heritage	
1.1	Treatment of the apse. The initial package sent by the applicant included a proposal to remove the roof of the apse. The applicant clarified that this is not an intention anymore. The entire apse wall will remain and will be exposed both to the interior lobby and from the exterior. The applicant is still working with structural engineers to comply with Building Code and build in a way that the fire wall does not rely on the existing apse roof (potential additional structure around). The roof won't necessarily be visible form hotel site as a result of this intervention, but the intention is to keep the stone wall visible.	Agreed.
1.2	Lobby facing Blackburn Avenue Previous proposal had the visibility from Laurier, and the applicant confirmed that this visibility will be maintained with the revised proposal.	Acknowledged.
1.3	Process Heritage application will have to go to Planning and Housing Committee and City Council. Heritage Impact Assessment is required, both for the impacts and changes to the church building and impact on the Russel Range HCD. Plus, the strip of land along Blackburn Avenue (portion of 321 Chapel): the plan has a note about lot consolidations and severances need to be accompanied by Heritage Impact Assessment. The Heritage Impact Assessment should speak to this too. It all can be combined in one document.	Acknowledged, a Heritage Impact Assessment (HIA) has been prepared and is included as part of this submission.
2.1	Urban Design UDRP	The project team attended UDRP on July 7, 2023.
	The subject site is within Design Priority Corridor, and attendance to UDRP is required.	The project team attended est to en early 1, 2020.
2.2	Question why the hotel use was restricted in the first place From the City perspective, the building was intended to provide community hub functions on the ground and up to fourth floor.	Acknowledged.
2.3	Transition to the south It was advised to be cautious on how the building is getting pushed towards the south with the revised design as presented, including the very large balconies. Transition to the south and to the existing neighbourhood in the south was really important during the first zoning amendment. It's going to be a sensitive issue and perhaps some design mitigation of this impact will be required.	We have maintained the massing of the zoning in that area save for the structure and green roofed section over the parking ramp. The balconies on the South façade are within the zoning requirements. Shape and size is still under consideration and these comments will be considered during any revisions.
2.4	Design Brief Design Brief will be required. It is a separate submission from the UDRP submission.	A Design Brief has been prepared and is included as part of this submission.



No.	Comment	Response
3	Planning	
3.1	Question why the community hub on ground-level floors is not part of the revised proposal. The applicant anticipates developing the site with mass timber construction and it is not feasible anymore to provide community space with anticipated construction model, sustainability and heritage considerations. The synergy between the restaurant, the hotel, micro-mobility as a hub (conference spaces etc.), small retail/commerce, condos, and using the existing church as a community space provides better feasibility model for the project to move forward.	Acknowledged.
3.2	Transition to the south It was advised to explore how south façade and especially balconies can work better as a transition to the neighbouring low-rise residential properties to the south.	We have maintained the massing of the zoning in that area save for the structure and green roofed section over the parking ramp. The balconies on the South façade are within the zoning requirements. The balcony guards are in keeping with the heritage nature of the neighbourhood, favouring pickets over a more transparent glass guard. This will aid with any privacy concerns for neighbouring properties. Shape and size is still under consideration and these comments will be considered during any revisions.
3.3	Portion of property at 321 Chapel Street How this strip will be developed? Will it be maintained as a landscaped buffer? Or will it be included as part of the building? The building won't be extended but it helps to plan the parking garage and opens more of the ground floor for other functions. It will be partially ramp for driving down and closer to Chapel Street it will be a landscaped area. It was advised to avoid more impact on the neighbouring property along Blackburn.	The building will not be extended further into the newly acquired strip of land save for the parking ramp and the roof over the ramp. Careful attention was paid when designing the roof of the ramp to avoid increasing impacts to 14 Blackburn Avenue. The southwest corner of the lot will be softly landscaped and will include a path for exiting the building.
3.4	Rooftop Amenity There is a precedent in the city where the rooftop amenity area was provided and wasn't calculated as an additional storey towards a building height. It was advised to keep it at a minimum, however, and to evaluate it from a streetview perspective. As seen from perspective views, there is also a canopy extent over the amenity area and potentially there will be an elevator runover. Keeping the height at street level as nine stroreys is what the City will be looking at and evaluating the impact of the relief. Will the area of the outdoor rooftop amenity be increased? The applicant confirmed that there is a slight increase of this rooftop amenity area. Will it be used as for hotel use or for residential use? The applicant would like to maintain the flexibility. Some restrictions may apply for hotel use in terms of hours of operation, but more information will be provided by City staff.	Currently, the intent is to utilize the roof for resident amenity space, both indoor and outdoor. The terrace area does not extend beyond the required zoning boundaries. The outdoor terrace area and interior amenity space will not be visible from street level. The Planning Rationale provides a detailed discussion of relief required for the ZBLA, including permitted projections above the height limit.
3.5	Reduction in parking compared with the initial proposal Though the parking garage is being reduced compared with the initial proposal, the applicant has confirmed that the proposal is compliant with parking requirements of the Zoning By-law.	During the initial pre-consultation meeting, the project team indicated that they were investigating ways to provide the minimum parking rate for the development. However, following refinements to the design, including application of vehicle turning radii templates and refinements to the structural requirements, such as locating structural supports, the required parking minimum could not be accommodated. Therefore, a reduction in the required visitor parking rate has been included in the list of requested relief as part of the Zoning Bylaw Amendment.
3.6	Rooftop Amenity follow-up question It was advised to keep it as small as possible. Also, information provided that in zoning provisions it will be limited to the area, to the use, and to the square footage of the interior space.	Interior rooftop amenity space will be kept to a minimum (small kitchenette/dining room, washrooms)



No.	Comment	Response
7	Urban Design	
	The site is within a Design Priority Area and the proposal is subject to review by the City's Urban Design Review Panel prior to the application being deemed complete. Please contact udrp@ottawa.ca for details on submission requirements and scheduling.	Acknowledged and actioned.
	We appreciate the presentation material provided at the Pre-consultation meeting and have the following design comments: - We recommend additional exterior detail be provided for the UDRP meeting. - We recommend caution be taken regarding the relationship of the southern facade to the residential neighbourhood to the south, including the overhanging balconies. - We recommend the project team review the UDRP recommendations from Dec, 2017 as many of the issues remain relevant.	Acknowledged and actioned.
	A scoped Design Brief is a required submittal (and separate from any UDRP submission) for all Site Plan/Re-zoning applications. Please see the Design Brief Terms of Reference provided and consult the City's website for details regarding the UDRP schedule. - Note. The Design Brief submittal should have a section which addresses these pre-consultation comments.	Acknowledged and actioned. Design Brief is being prepared for our ZBLA submission.







315 + portion of 321 Chapel Street Responses ZBLA Pre-Consultation Phase 2 Comments November 21, 2023

No.	Comment	Response	
	Planning		
1	Policy 128) in Section 4.7.8 – Building Heights of the Central and East Downtown Core Secondary Plan:	Acknowledged and agreed that an OPA is not required.	
	128) Within the Sandy Hill Character Area, any maximum building heights permitted in the Zoning By-law that exceed the heights indicated on Schedule B as of the date of adoption of this Secondary Plan will continue to apply. Any increases beyond these maximum heights will require an Official Plan Amendment.		
	Since there is no additional storey proposed and there is a sufficient planning rationale for the over 2 metres increase in height, we can consider the policy 128) in Secondary Plan as met and there is no need for an OPA.		
2	Transition to the South: • Please, further integrate the parking garage access ramp into the building mass and shift away from the neighbouring building to the south. Incorporate a landscape buffer along the southern property line to mitigate impacts to the low-rise residential to the south, specifically the two-storey building directly abutting the site.	The driveway/ramp to parking has been moved further North and now accommodates a 2m walkway using pavers between properties. The garage door is hidden below grade and guard rails surrounding the ramp opening will be in keeping with the architectural expression of the building. A landscaped area at the Southwest corner of the property integrates bike storage into the area.	
	• The previous comments/concerns with regards to the southern balconies are not accommodated. Are balconies compliant with the Zoning By-law (Section 65)?	Balconies have been redesigned to ensure compliance with Section 65. Balconies project no more than 2 metres from the building face and are more than 1 metre from the property line, consistent with table 65(6)(c) of the Zoning By-law. As described in the Planning Rationale, relief is sought from Section 65 for the balconies located on the corner side yard (Blackburn Avenue) as they project to within 0 metres of the property line.	
	• Currently, the two trees proposed in the landscaped area to the south are covered with the canopy/structure over the parking ramp access. Additionally, the parking garage extends to the south with a setback of 2 metres from the new property line. How will this impact the survivability of the trees that are being proposed?	The two proposed trees are considered small trees and full shade tolerant. The plant bed where these trees are planted is open toward the east and will have a fair amount of light in the morning. As well, the planting bed is irrgated.	
		An active entrance to Laurier Avenue is provided, with an entrance to the lobby and amenity area provided via the	
	reconfiguration for the visitor bicycle parking rack, and opening the corner portion of the ground floor for continuous visibility of the apse along Laurier Avenue from the east. Laurier Avenue East is defined as a minor corridor in the Official Plan: On Downtown Core Minor Corridors, all buildings shall have active entrances facing the Minor Corridor, regardless of use. (Policy 4 in Section 5.1.4).	both guests and residents.	
		Exterior bicycle parking has been re-arranged; the bicycle parking rack has been downsized and five (5) convenient bicycle parking spaces are now provided at each of the lobby entrances.	
		The visitor bicycle parking is being rearraged to be more welcoming on this facade. There is no other practical location for the stairway considering the required stepbacks in the building in coordination with the parking garage (the stair either ends up in a stepback or in the drive aisle).	
	 Landscape Plan and Site Plan MLA and encroachment agreement required for the stairs, sidewalk material, and street furniture and fixed landscape located in the ROW. Further discussion will be required with respect to the extent of the encroachment. 	Noted.This would be applicable at a future Site Plan Control application.	
	Widen walkway connections from ground floor units to the street (Blackburn Avenue) to a min of 1.5 metres.	It is our understanding that the 1.5 metres is required to permit two people operating wheelchairs to pass one another. However, this path leads to a set of stairs for the ground-related units, so two people would be unable to operate wheelchairs simultaneously. We feel that the 915 mm is an appropriate width, whereas increasing this would lessen the amount of landscaping provided and increase the amount of hardscape.	
[All entrances should be shown on Site Plan.	Entrances are indicated on the Site Plan on drawing no. A0-800.	
	 Driveway access to parking garage must be 6.7m wide (6.3m shown), 6m aisle width in garage is permitted. Please include the required relief accordingly. 	Section 107(1)(a)(iii)(aa)(ii) indicates a maximum, not a minimum, driveway width of 6.7 metres for a mid-rise apartment building with 20 or more parking spaces. The proposed 6.3 metres is therefore compliant.	



	Comment	Response
		Structure has been adjusted to avoid interference with garbage removal. A clear path of 2 m has been provided for garbage removal - building structure has been adjusted accordingly.
	https://ottawa.ca/en/living-ottawa/laws-licences-and-permits/laws/laws-z/solid-waste-management-law-no-2012-370	
	B2. • Please confirm that a minimum of 50% of the bicycle parking	This has been adjusted on the plans - there is a small amount of interference on one corner. Please confirm this is acceptable. 50% of bicycle parking provided as horizontal spaces at floor level - confirmed We are showing a minimum width of 0.6m for stacked bicycle parking Outdoor bicycle parking will be well lit for security
		Acknowledged.
_	Please include height of the projections. Relief from Section 64 is required.	
	Urban Design We have reviewed the applicant's responses to the UDRP and have the following comment: • We have raised concern around the proximity of the overhanging balconies located at the south-west corner of the building regarding potential overlook towards the private rear yards of the low-rise residential block to the south. We recommend the design consider how to mitigate this condition (perhaps by changing their orientation) and that the balconies not be larger than the maximum typically allowed in the zoning.	
	Heritage	
	Background: The subject property (All Saints) is designated under Part IV of the Ontario Heritage Act. A heritage permit is required for the proposed new construction, to be approved by City Council after consultation with the Built Heritage Committee. The heritage permit application should be submitted prior to the Site Plan Control application.	Noted.
	Comments on the Proposal	
	The existing proposal would mean that only the first floor of the apse is visible, since the second floor would be within a unit and the gym. • Consider the relocation of the north stair to provide better visibility of the apse from Laurier, and to also minimize the visual impact of	Enclosed the apse entirely within the lobby - see above comments regarding the roof. One apartment unit has been removed to allow the apse to be visible completely from Laurier Ave. and from the lobby. North stair - see above comments See revised elevations regarding the addition of masonry Window treatment - to be determined Metal panels - agreed - we will aim to make the panelling darker.



No.	Comment	Response
12	Transition	Balconies have been reduced in scale and simplified on the South façade. The drive aisle supporting posts are
	• Look for ways to provide a better transition to the southern neighbour on Blackburn and open up the space more. One consideration	structurally required.
	would be to remove the drive aisle roof or supporting posts.	
13	Heritage Impact Assessment	
	 Please refer to the attached Heritage Impact Assessment for comments that need to be addressed in the next round. 	Ashley provided comments in a marked up PDF of the HIA.





315 + portion of 321 Chapel Street (Future 8 Blackburn Avenue) Responses ZBLA Pre-Consultation Phase 3 Comments February 7, 2024

No.	Comment	Consultant	Response
	Planning		
	Deficiencies:		
1		Linebox, Fotenn	Acknowledged and adjusted.
	should be still compliant with ZBL despite this change. Please submit the plan for review prior to formal application.		
	08°9 (
	Comments:		
3		Linebox	Acknowledged and adjusted.
	façade.		
	Urban Design		
	Comments:		
4			Acknowledged.
	recommendations that are being postponed until the Site Plan Application phase. We do not have any concerns about this, however, in		
	order to keep record, they will be brought forward at the initial stages of the SPA process. We have no additional urban design		
	comments at this time.		





315 + portion of 321 Chapel Street (Future 8 Blackburn Avenue) Responses to SPC Pre-Consultation Phase 1 Comments May 22, 2024

	Way 22, 2024		
No.	Comment	Consultant	Response
	Planning		
	Comments:		
5	A Maintenance and Liability Agreement for the proposed landscaping elements will be required as well.	Fotenn, Windmill	Noted.
9	Interaction with public realm along Laurier Avenue Minor Corridor Prominent entrance along Laurier is still not accommodated. Laurier is a minor corridor, please treat the frontage of the building accordingly. More prominent front entrance to the ground floor amenity is beneficial to shift the focus from emergency exit on the front façade. Additionally, the area allows to design an inviting outdoor amenity to be used by residents and their guests that will in turn contribute to animation of public realm along Laurier corridor. Please, consider only minor alterations to glazing and maintaining transparency and coloured glass element.	Linebox	Many revisions have been made to respond to city comments to make the entrance off of Laurier Ave. more prominent. These include: the removal of the 2nd floor dwelling unit and amenity space to fully expose the apse to the public, the centralization of the doorway on the facade and on the path to Laurier Ave, the incorporation of coloured glass to accentuate the entrance and make it more prominent, the removal of any articulation of the facade of the exit stair, and the creation of a welcoming landscaped area off of Laurier Ave. No other changes are proposed.
	Floor Plans		
10	There are inconsistencies between measurements for some parking spaces: Level 2 Basement Plan: Vestion Parking Parking	Linebox	A Standard parking space beside exit stairs provided with no measurement inconsistencies or interferences. B2 parking space in South East corner shows one compact parking spot impeded upon by one column by 50mm and against one wall. With the column impediment, the parking space is 2350mm x 5200. Please note if this is acceptable.



No. Comment	Consultant	Response
Level B1 Basement Plan: VESTIBULE STANDARD (2500-5200) (*/-28'-4") STANDA STANDA STANDA STANDA STANDA STANDA	Linebox	A Standard parking space beside exit stairs provided with no measurement inconsistencies or interferences.
Additionally, the drive aisle seems to be narrower than 6 metres here:	7.464 (1/24) 4 (1/24) 4 (1/24) 4 (1/24) 4	Acknowledged. Modifications to the plans will be made to maintain 6m aisle throughout.
1.525 % (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**) - 5 - 07) (**)	Please, ensure that aisles for accessing bicycle parking spaces are 1.5 metres in width as per requirements of the Zoning By-law (Section 111).	Acknowledged. Modifications to the plans will be made to maintain 1.5m aisle throughout.
Urban Design		
Submission Requirements: 14 An Urban Design Brief is required. Please see attached customized Terms of Reference to guide the preparation	n of the submission. Linebox	Acknowledged
14(a) The Urban Design Brief should be structured by generally following the headings highlighted under Section 3 – C Terms of Reference.	Contents of these Linebox	Acknowledged

No.	Comment	Consultant	Response
14(b)	Please note that the Urban Design Brief will also serve as the submission to the Urban Design Review Panel (see notes below) if required.	Linebox	Acknowledged
15	Additional drawings and studies are required as shown on the ASPIL. Please follow the terms of reference (Planning application submission information and materials City of Ottawa) to prepare these drawings and studies. These include (ie. The UDRP drawings).	Linebox	Acknowledged
	https://ottawa.ca/en/planning-development-and-construction/residential-property-regulations/development-application-review-process/development-application-submission/planning-application-submission-information-and-materials		
	Urban Design Review Panel Review and Report		
16	The site is located within a Design Priority Area and is subject to review by the Urban Design Review Panel. UDRP review occurs		We have confirmed with City Staff that a second trip to UDRP is not required.
	within the Preconsultation stage. To proceed with a UDRP review, please contact udrp@ottawa.ca.		
17	The submission of a UDRP report is a requirement for deeming an application complete. Please follow the instructions provided in the		We have confirmed with City Staff that a second trip to UDRP is not required.
	Terms of Reference available here: Urban Design Review Panel Report (ottawa.ca).		
18	This proposal has been to the panel recently (July 2023) during the re-zoning process and we believe that the design is generally in a		Full responses to all UDRP comments has been provided under a separate cover, titled 'UDRP Report.'
	good place. We would be willing to recommend an exemption to visiting the UDRP again during the Site Plan Application after the		
	UDRP recommendations are responded to in full. The initial response dated 2023-11-27 (attached) postponed many responses until		
	the SPA. A full response to the UDRP recommendations will now be required and submitted as part of the UDRP report (noted above)		
	to ensure a complete submission.		
	Comments:		
19	We would be happy to discuss these responses and any other design related questions as required.		Noted.







315 + 321 Chapel Street Responses to UDRP Comments May 2024

8.1 The Panel appreciates the overall massing of the project and the material selection. 8.2 The Panel appreciates the reuse of the stone and the decision to construct using mass timbre which can be exemplary for the Ottawa area going forward. 8.3 The Panel appreciates that the treatment around the apse of the church is trending in the right direction. 8.4 The Panel recommends giving greater consideration to making the area around the apse entirely public space. 8.5 The Panel recommends giving more thought to the exterior lighting in public spaces. 8.6 The Panel has concerns with the projected balconies, especial around the corners and as an overlook 8.7 The Panel appreciates the reuse of the stone and the decision to construct using mass timbre which can be extended. 8.6 Acknowledged. 8.7 Acknowledged. 8.8 Acknowledged. 8.8 The Panel recommends giving greater consideration to making the area around the apse entirely public functionality and security of the building. The apse remains visible to the exterior from Laurier Ave. and the Blackburn St entrance for the entire height of the apse until its soffit. The apse will be visible from both entrances through the large windows. 8.8 Exterior lighting has been considered by an electrical consultant and a lighting plan has been prepared, available under a separate cover. 8.6 The Panel has concerns with the projected balconies, especial around the corners and as an overlook 8.7 The balcony locations on the south façade have been carefully reviewed. The proposed	No.	Comment	Response
The Panel appreciates the overall massing of the project and the material selection. Acknowledged.	8		
he exemplary for the Ottawa area agring forward. 3.3 The Panel appreciates the reuse of the stone and the decision to construct using mass timbre which can be exemplarly for the Ottawa area agring forward. 3.4 The Panel appreciates that the treatment around the apse of the church is trending in the right direction. 3.5 The Panel recommends giving greater consideration to making the area around the apse entirely public spaces. 3.6 The Panel recommends giving more thought to the exterior lighting in public spaces. 3.7 The Panel recommends giving more thought to the exterior lighting in public spaces. 3.8 The Panel recommends giving more thought to the exterior lighting in public spaces. 3.8 The Panel as concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. 3.7 The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. 3.8 The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. 3.8 The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. 3.8 The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the buildings. 3.8 The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the buildings. 3.8 The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the buildings. 3.8 The Panel strongly recommends allowing parking garage ramp as proposed and integrating it into the buildings. 3.9 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 3.9 Ensure that materials are robust enough to provide longevity to the building. 3.1 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 3.1 The Panel has conc	8.1		Acknowledged.
1. The Panel appreciates that the treatment around the apse of the church is trending in the right direction. 1. The Panel recommends giving greater consideration to making the area around the apse entirely public space. 1. The Panel recommends giving more thought to the exterior lighting in public spaces. 1. The Panel recommends giving more thought to the exterior lighting in public spaces. 1. The Panel recommends giving more thought to the exterior lighting in public spaces. 1. The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. 1. The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. 1. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. 1. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. 1. The Panel has concerns with the metal paneling and the articulation of the building above the church. 1. The Panel has concerns with the metal paneling and the articulation of the building above the church. 1. Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 1. Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 2. Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 3. The Panel has concerns with the approach taken to the stainway on the exterior of the building. 3. The Panel has concerns with the approach taken to the stainway on the exterior of the building. 3. The Panel has concerns with the approach taken to the stainway on the exterior of the building. 3. The Panel has concerns with the approach taken to the stainway on the exterior of the building. 3. The Panel has concerns with the approach taken to th			
8.4 The Panel recommends giving greater consideration to making the area around the apse entirely public space. 8.5 The Panel recommends giving more thought to the exterior lighting in public spaces. 8.6 The Panel recommends giving more thought to the exterior lighting in public spaces. 8.7 The Panel recommends giving more thought to the exterior lighting in public spaces. 8.8 The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. 8.7 The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. 8.8 The Panel has concerns with the metal paneling and the articulation of the building above the church. 8.9 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 8.10 Ensure that malerials are robust enough to provide longevity to the building. 8.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.13 Stro pedigin & Public Receipt. 8.14 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.15 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.16 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the building. 8.17 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.18 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.19 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the building. 8.10 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the building. 8.11 The Panel has concerns with the approach taken to the stairway on the exterior of		be exemplary for the Ottawa area going forward.	
space. ### functionality and security of the building. The apse remains visible to the exterior from Laurier Ave. and the Blackburn St entrance for the entire height of the apse until its soffit. The Panel recommends giving more thought to the exterior lighting in public spaces. ### The Panel recommends giving more thought to the exterior lighting in public spaces. ### The Panel recommends giving more thought to the exterior lighting in public spaces. ### The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. ### The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. ### The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. ### The Panel has concerns with the metal paneling and the articulation of the building above the church. ### Deale has concerns with the metal paneling and the articulation of the building above the church. ### Deale has concerns with the metal paneling and that they are distinct from the colouration of the church as well as between certain windows. This provides texture, variation, and interest to the façade, similar to the detailed stonework of the church. ### Deale has concerns with the approach taken to the stairway on the exterior of the building. ### Explore different ways to address the stairway/vertical portion on Laurier Avenue. ### Explore different ways to address the stairway/vertical portion on Laurier Avenue. ### Explore different ways to address the stairway/vertical portion on Laurier Avenue. ### Explore different ways to address the stairway/vertical portion on Laurier Avenue. ### Explore different ways to address the stairway/vertical portion on Laurier Avenue. ### Explore different ways to address the stairway/vertical portion on Laurier Avenue. ### Explore different ways to address the stairway/vertical portion on Laurier Avenue. ### Explore differ	8.3	The Panel appreciates that the treatment around the apse of the church is trending in the right direction.	Acknowledged.
tunctionality and security of the building. The apse remains visible to the exterior from Laurier Ave and the Blackburn St entrance for the entire height of the apse until its soffit. The Panel recommends giving more thought to the exterior lighting in public spaces. Exterior lighting has been considered by an electrical consultant and a lighting plan has been prepared, available under a separate cover. The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating linto the building. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating linto the building. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the materials and that they are distinct from the colouration of the church. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairwa	8.4	The Panel recommends giving greater consideration to making the area around the apse entirely public	The building amenity space and lobby surrounds the apse and is necessary to the
Laurier Ave. and the Blackburn St entrance for the entire height of the apse until its soffit. The apse will be visible form both entrances through the large windows. 8.6 The Panel recommends giving more thought to the exterior lighting in public spaces. 8.6 The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. 8.7 The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. 8.8 The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. 8.9 The Panel has concerns with the metal paneling and the articulation of the building above the church. 8.9 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 8.10 Ensure that materials are robust enough to provide longevity to the building. 8.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.13 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.14 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.15 The Panel has concerns with the approach taken to the church building showed the church as well as between certain vindows. The provides of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½-storey residential. 8.16 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.17 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.18 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.19 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and			
The Panel recommends giving more thought to the exterior lighting in public spaces. The Panel recommends giving more thought to the exterior lighting in public spaces. The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has been paraliced by a the propriet of the church but in a champagne, metalic tone. We intend to select a colour/fone that is either lighter or darker than the stone of the church so that the church is not lost in the new background f			
been prepared, available under a separate cover. The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church so that the other is a variety of textures in the materials and that they are distinct from the colouration of the church so that the other is a variety of textures in the materials and that they are distinct from the colouration of the church so that the other is not be in the same colour family of the church but in a champagne, metalic tone. We lintend to select a colour/tone that is either lighter or darker than the stone of the church so that the other is not lost in the new background façade. Acknowledged. The Panel has concerns with the approach taken to the stainway on the exterior of the building. The Panel has concerns with the approach taken to the stainway on the exterior of the building. The Panel has concerns with the approach taken to the stainway on the exterior of the building. The Panel has concerns with the approach taken to the stainway on the exterior of the building. The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½- storey residential. The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive.			· ·
The Panel has concerns with the projected balconies, especial around the corners and as an overlook issue on the buildings to the south. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the metal paneling and the articulation of the building above the church. The Panel has concerns with the materials and that they are distinct from the colouration of the church. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the sta	8.5	The Panel recommends giving more thought to the exterior lighting in public spaces.	Exterior lighting has been considered by an electrical consultant and a lighting plan has
abalconies respect all zoning requirements and do not exceed the maximum allowable depth. Their shape, size, and concept has also been simplified, as per city comments. The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. Understood. The parking ramp has been partially covered by the building but cannot be completely covered. Details of setterior cladding will be deeply considered. The plan is to provide more "textured" or folded metal panels on the projection over the church as well as between certain windows. This provides texture, variation, and interest to the façade, similar to the detailed stonework of the church. Agreed - we aim to be in the same colour family of the church but in a champagne, metalic tone. We intend to select a colour/tone that is either lighter or darker than the stone of the church so that the church is not lost in the new background façade. Acknowledged. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the provided buffer to the south stair has been removed - see above response.			been prepared, available under a separate cover.
The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. 8.8 The Panel has concerns with the metal paneling and the articulation of the building above the church. 8.9 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 8.10 Ensure that materials are robust enough to provide longevity to the building. 8.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.13 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.14 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.15 The Panel recommends allowing for landscaped separation between parking entrance and the southern required with the provided between the neighbouring property. Allowing for some inner block vegetation would be positive. 8.16 The Panel has concerns with the surface parking next to the church is understood. The parking ramp has been parking ant phas been parking and hat they building above the church. 8.16 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 8.17 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 8.18 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 8.19 Ensure that materials are robust enough to provide longevity to the building. 8.10 Ensure that materials are robust enough to provide longevity to the suit in a champagne, metalic tone. We intend to select a colour/tone that is either lighter or darker than the stone of the church is not lost in the new background façade. 8.10 Ensure that materials are robust enou	8.6	The Panel has concerns with the projected balconies, especial around the corners and as an overlook	The balcony locations on the south façade have been carefully reviewed. The proposed
The Panel strongly recommends reconsidering the parking garage ramp as proposed and integrating it into the building. The Panel has concerns with the metal paneling and the articulation of the building above the church. Details of exterior cladding will be deeply considered. The plan is to provide more "textured" or folded metal panels on the projection over the church as well as between certain windows. This provides texture, variation, and interest to the façade, similar to the detailed stonework of the church. 8.9 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 8.10 Ensure that materials are robust enough to provide longevity to the building. 8.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 9.1 Site Design & Public Realm 9.2 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½-storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 9.3 The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street		issue on the buildings to the south.	balconies respect all zoning requirements and do not exceed the maximum allowable depth.
into the building. The Panel has concerns with the metal paneling and the articulation of the building above the church. Beautiful of the panel has concerns with the metal paneling and the articulation of the building above the church. Beautiful of the panel has concerns with the metal paneling and the articulation of the building above the church. Beautiful of the panel has concerns with the metal paneling and the articulation of the building above the church. Beautiful of the panel has concerns with the metal paneling and the articulation of the building above the church. Beautiful of the panel has concerns with the metal paneling and the articulation of the building above the church. Beautiful of the panel has concerns with the metal paneling and the articulation of the building above the church. Beautiful of the panel has concerns with the metal paneling and the articulation of the building above the church. Beautiful of the panel has concerns with the metal paneling and the articulation of the detailed stonework of the church. Beautiful of the panel has concerns with the materials and that they are distinct from the colouration of the stonework of the church. Beautiful of the panel has concerns with the approach taken to the stairway on the exterior of the building. Beautiful of the panel has concerns with the approach taken to the stairway on the exterior of the building. Beautiful of the stair has been modified so that the prominence of the exit stair has been removed. It has been blended into the overall north façade by setting back the roftop stair access from the façade has been modified so that the prominence of the stair has been been denoting any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. Beautiful of the stair has been removed - see above response. Beautiful of the stair has been removed - see above response. The Panel recommends allowing space for a landscape buffer to the south side of the pr			Their shape, size, and concept has also been simplified, as per city comments.
The Panel has concerns with the metal paneling and the articulation of the building above the church. Details of exterior cladding will be deeply considered. The plan is to provide more "textured" or folded metal panels on the projection over the church as well as between certain windows. This provides texture, variation, and interest to the façade, similar to the detailed stonework of the church. B.9 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. B.10 Ensure that materials are robust enough to provide longevity to the building. B.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. B.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. B.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. B.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. B.13 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½-storey residential. B.13 The Panel recommends allowing for some inner block vegetation would be positive. B.14 The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street	8.7		Understood. The parking ramp has been partially covered by the building but cannot be
or folded metal panels on the projection over the church as well as between certain windows. This provides texture, variation, and interest to the façade, similar to the detailed stonework of the church. 8.9 Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. 8.10 Ensure that materials are robust enough to provide longevity to the building. 8.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.13 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½-storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 8.3 The Panel has concerns with the surface parking next to the church and the easement required with the required with the residue stonework of the church. 8.4 Agreed - we aim to be in the same colour family of the church but in a champagne, metalic tone. We intend to select a colour/tone that is either lighter or darker than the stone of the church is other church is other than the solurour be in the parking to be in the church in the inchurch. 8.5 Ensure that materials are robust in the new background façade. 8.6 Adknowledged. 8.6 Acknowledged. 8.7 The façade has been modified so that the prominence of the exit stair has been removed. It has been blended into the overall north façade by setting back the rooftop stair access from the façade and removing any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. 8.11 The verticality of the stair has been removed - se		<u> </u>	
Sensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. Sensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. Sensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. Sensure that materials are robust enough to provide longevity to the building. Sensure that materials are robust enough to provide longevity to the building. Sensure that materials are robust enough to provide longevity to the building. Sensure that materials are robust enough to provide longevity to the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. Sensure that materials are robust enough to provide longevity to the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Facade has been modified so that the prominence of the exit stair has been removed. It has been blended into the overall north façade by setting back the rooftop stair access from the façade and removing any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. Site Design & Public Realm	8.8	The Panel has concerns with the metal paneling and the articulation of the building above the church.	
Stonework of the church. Stonework of the church. Agreed - we aim to be in the same colour family of the church but in a champagne, metalic tone. We intend to select a colour/tone that is either lighter or darker than the stone of the church so that the church is not lost in the new background façade. Acknowledged. Acknowledged. The Panel has concerns with the approach taken to the stairway on the exterior of the building. Acknowledged. The façade has been modified so that the prominence of the exit stair has been removed. It has been blended into the overall north façade by setting back the rooftop stair access from the façade and removing any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. The verticality of the stair has been removed - see above response. Site Design & Public Realm The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½-storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 9.3 The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street			· · · · ·
Ensure there is a variety of textures in the materials and that they are distinct from the colouration of the church. Ensure that materials are robust enough to provide longevity to the building. Ensure that materials are robust enough to provide longevity to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. Explore different ways to address the stairway/vertical portion on Laurier Avenue. Explore different ways to address the stairway/vertical portion on Laurier Avenue. Site Design & Public Realm The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½-storey residential. The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. Ensure that materials are robust enough to provide longevity to the building. Acknowledged. The façade has been modified so that the prominence of the exit stair has been removed. It has been blended into the overall north façade by setting back the rooftop stair access from the façade and removing any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. There will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp and will be provided between the neighbouring property to the south and the parking ramp path will be provided between the neighbouring property to the south and the parking ramp path will be provided between the neighbouring property to the south and the parking ramp path will be provided between the nei			
church. Ensure that materials are robust enough to provide longevity to the building. B.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. B.2 Explore different ways to address the stairway/vertical portion on Laurier Avenue. B.3 Explore different ways to address the stairway/vertical portion on Laurier Avenue. B.4 Explore different ways to address the stairway/vertical portion on Laurier Avenue. B.5 Site Design & Public Realm 9.1 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½-storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. tone. We intend to select a colour/tone that is either lighter or darker than the stone of the church is not lost in the new background façade. Acknowledged. Acknowledged. The façade has been modified so that the prominence of the exit stair has been removed. It has been blended into the overall north façade by setting back the rooftop stair access from the façade and removing any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. The verticality of the stair has been removed - see above response. The rewill be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp There will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp There will be provided between the neighbouring property to the south and the parking ramp The Panel has concerns with the surface parking occupying 321 Chapel Street			
Ensure that materials are robust enough to provide longevity to the building. 8.10 Ensure that materials are robust enough to provide longevity to the building. 8.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 9 Site Design & Public Realm 9.1 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½ -storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 9.3 The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street	8.9		
8.10 Ensure that materials are robust enough to provide longevity to the building. 8.11 The Panel has concerns with the approach taken to the stairway on the exterior of the building. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 9.1 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½ -storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 8.10 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 8.11 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½ -storey residential. 9.1 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 8.10 Explore that materials are robust the prominence of the exit stair has been removed. It has been modified so that the prominence of the exit stair has been removed. It has been modified so that the prominence of the exit stair has been removed. It has been modified so that the prominence of the exit stair has been removed. It has been modified so that the prominence of the exit stair has been removed - see above response. 8.12 Explore different ways to address the stairway/vertical portion to the stair. The exit doors at the base will be the same finish as the surrounding facade. 8.12 The Panel has concerns with the surface parking next to the church and the easement required with the provided between the neighbouring property to the south and the parking ramp path will be provided between th		church.	· · · · · · · · · · · · · · · · · · ·
The Panel has concerns with the approach taken to the stairway on the exterior of the building. The Panel has concerns with the approach taken to the stairway on the exterior of the building. The façade has been modified so that the prominence of the exit stair has been removed. It has been blended into the overall north façade by setting back the rooftop stair access from the façade and removing any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. There will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp arm will be landscaping planned for the Southwest corner of the site. A concrete paver path will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the neighbouring property to the south and the parking ramp arm will be provided between the ne	2.42		
has been blended into the overall north façade by setting back the rooftop stair access from the façade and removing any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 9 Site Design & Public Realm 9.1 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½ -storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 9.3 The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street			
the façade and removing any ornamentation that would draw attention to the stair. The exit doors at the base will be the same finish as the surrounding facade. 8.12 Explore different ways to address the stairway/vertical portion on Laurier Avenue. 9.1 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½ -storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 1. The Panel has concerns with the surface parking next to the church and the easement required with the surface parking lot is associated with the office building occupying 321 Chapel Street	8.11	The Panel has concerns with the approach taken to the stairway on the exterior of the building.	· · · · · · · · · · · · · · · · · · ·
doors at the base will be the same finish as the surrounding facade. Explore different ways to address the stairway/vertical portion on Laurier Avenue. The verticality of the stair has been removed - see above response. The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½ -storey residential. The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. The Panel has concerns with the surface parking next to the church and the easement required with the doors at the base will be the same finish as the surrounding facade. The verticality of the stair has been removed - see above response. There will be landscaping planned for the Southwest corner of the site. A concrete paver path will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp There will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp There will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp There will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp			
Explore different ways to address the stairway/vertical portion on Laurier Avenue. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response. The verticality of the stair has been removed - see above response.			
Site Design & Public Realm 9.1 The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½ -storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 9.3 The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street	0.40	Evalue different ways to address the stainway/vertical parties on Laurier Avenue	
The Panel recommends allowing space for a landscape buffer to the south side of the proposal along Blackburn Avenue which will help with the transition and relationship to the 2½ -storey residential. The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street	0.12		The verticality of the stall has been removed - see above response.
Blackburn Avenue which will help with the transition and relationship to the 2½-storey residential. 9.2 The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. 9.3 The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street	0 1		There will be landscaping planned for the Southwest corner of the site. A concrete power
The Panel recommends allowing for landscaped separation between parking entrance and the southern neighbouring property. Allowing for some inner block vegetation would be positive. The Panel recommends allowing for landscaped separation between parking entrance and the southern path will be landscaping planned for the Southwest corner of the site. A concrete paver path will be provided between the neighbouring property to the south and the parking ramp are parking lot is associated with the office building occupying 321 Chapel Street	9.1		, , ,
neighbouring property. Allowing for some inner block vegetation would be positive. path will be provided between the neighbouring property to the south and the parking ramp The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street	0.2	·	
9.3 The Panel has concerns with the surface parking next to the church and the easement required with the The surface parking lot is associated with the office building occupying 321 Chapel Street	9.2		. •.
		Ineignbouring property. Allowing for some infler block vegetation would be positive.	pair will be provided between the heighbouring property to the south and the parking ramp
	9.3	The Panel has concerns with the surface parking next to the church and the easement required with the	The surface parking lot is associated with the office building occupying 321 Chapel Street
		adjacent office building on Chapel Street.	



No.	Comment	Response
9.4	The Panel encourages pursuing a joint parking area with pervious paving and plantings.	part of the proposed redevelopment, but the development does include either the All Saints
9.5	The Panel recommends removing the angled parking nearest to church if possible and providing plantings.	Church or the office building at 321 Chapel Street.
9.6	The Panel recommends pursuing the opportunity for strong exterior lighting on the church to highlight its heritage aspect as well as lighting on the apse.	The lighting of the apse will take place on the interior of the new building and within the existing windows of the apse. The exterior of the church outside of the new building is not part of this project's scope.
9.7	Consider making it more installation-like.	Agreed - we intend to design the lighting and treating the apse windows with care
	The Panel strongly recommends enclosing the parking ramp under the building and within the building footprint to allow for it to be covered rather than wrapping the ramp around the exterior of the footprint as is proposed.	Understood. The parking ramp has been partially covered by the building but cannot be completely covered.
10.1	Sustainability The Denal appreciates the reuse of meterials	Asknowledged
	The Panel appreciates the reuse of materials. Consider applying more use of existing materials in the design.	Acknowledged. Acknowledged. During construction, the stone will be assessed to determine to what extent it can be re-used in the project.
		The stone will be re-used in the landscaping of the property and depending on its condition, opportunities to explore re-use in other ways will be explored.
10.3	The Panel appreciates the integration of green elements on the roof terrace.	Acknowledged.
10.4	Explore ways to push this further (e.g., biodiversity, water retention, heat island reduction, etc.).	Acknowledged. This has been considered in the landscaping of the site and the roof terrace.100% of the roof consists of high albedo elements (a combination of green roof, pavers with SRI values greater than 0.33 and a cool roof). 100% of the landscaped area will be irrigated using reused rain water, contributing further to water retention. All plantings will consist of native species and have been selected to increase the biodiversity. Plant species recommendations are proposed to emulate beneficial plantings rich with species.
		Wherever hardscaping is not being installed on the roof terrace, green roof and white roofing will be used to reduce heat island effect.
		Within the building, the structure is planned to be primarily composed of mass timber, a highly renewable and sustainable construction system.
11	Built Form & Architecture	
11.1	The Panel appreciates the sensitive integration with the heritage component and the connection with the history of the site.	Acknowledged.
11.2	The Panel appreciates the thoughtfulness and focus on the intersection between old and new.	Acknowledged.
11.3	The Panel appreciates the massing of the project overall and the elegance of the design.	Acknowledged.
11.4	The Panel supports the architectural palette and overall design of the brick volume.	Acknowledged.
11.5	The Panel appreciates the two-tone material approach and the bronze colouration.	Acknowledged.
	Ensure the materials are robust and durable enough to provide longevity and long-lasting elegance to the building.	Acknowledged.



No.	Comment	Response
11.7	The Panel has concerns with the metal paneling as a background to the heritage church because it	Agreed - we aim to be in the same colour family of the church but in a champagne, metalic
	matches too closely with the colour of the church stone and does not provide a contrast.	tone. We intend to select a colour/tone that is either lighter or darker than the stone of the
		church so that the church is not lost in the new background façade.
11.8	Ensure that there is a distinction between the church stone material and the backdrop material at its	Agreed - we aim to be in the same colour family of the church but in a champagne, metalic
	connection with the heritage building in order to highlight the heritage of the church.	tone. We intend to select a colour/tone that is either lighter or darker than the stone of the
		church so that the church is not lost in the new background façade.
11.9	The Panel has concerns with the amount of metal paneling on the upper volumes and its durability long-	Metal panels will be the direction we move forward with as there are weight constraints
	term.	associated with the CLT wall system we are using. The panels will nonetheless be robust
		and durable throughout the lifespan of the building
11.10	The Panel encourages the applicant to pursue more robust materials and design solutions for the upper	Metal panels will be the direction we move forward with as there are weight constraints
	volumes.	associated with the CLT wall system we are using. The panels will nonetheless be robust
		and durable throughout the lifespan of the building
11.11	The Panel appreciates how the vertically fluted panels add rigidity and texture to the façade.	Acknowledged.
-	Consider more texture and more verticality in the materiality of the upper volumes.	Agreed - we intend to increase the amount of textured panels in that region
11.13	The Panel strongly recommends extending the brick volume further west along Laurier Avenue to at	I believe more clarification would be required to understand this comment fully. If the intent is
	least 2/3 of the building façade rather than 1/3. The masonry provides a complementary contrast with	to extend the brick volume to the West, that will increase the building footprint. If that is the
	the stone church and an elegant design solution.	intent of the comment, we will definitely consider it. If the intent is to only extend the brick
		finish, we intended that section of the North facade, beside the church, to allow for more
		transparency to the apse (all the glazing).
11.14	The Panel has concerns with the design of the balconies distracting from the heritage building.	The balcony shape, size, and concept has been simplified, and do not distract from the
		heritage building.
11.15	The Panel is unsure whether the curvature and/or the amount of projection is necessary. Consider	The balconies have been reduced in size and depth throughout the project.
	exploring alternative ways of giving residents outdoor spaces.	
11.16	The Panel has concerns with the style and geometry of the balconies, particularly the large wrap-around	The balconies on the south façade were reviewed during the SPC process. Their shape,
	balconies on the south façade.	size, and concept has also been simplified, as per city comments. They respect all zoning
		requirements and do not exceed the maximum allowable depth.
11.17	The Panel encourages the applicant to explore alternatives to the wrap-around style of the corner	See above comment. Also note that the wraparound balcony is only proposed for the fourth
	balconies.	storey; all other balconies are proposed as standard projecting balconies on the south
		façade.
11.18	The Panel suggests there may be an opportunity to be more buttress-like with the balcony designs.	This item has been considered and we find it may conflict with the previous comments and
		requests to simplify the geometry of the balconies, which we've done.
11.19	The Panel has concerns with the central vertical volume projection on the north façade. It is reading too	If this is in reference to the exit stair, this has been resolved. The façade has been modified
	strongly for what it is.	so that the prominence of the exit stair has been removed. It has been blended into the
		overall north façade by setting back the rooftop stair access from the façade and removing
		any ornamentation that would draw attention to the stair. The exit doors at the base will be
		the same finish as the surrounding facade.
11.20	The Panel has concerns with the west façade behind the church.	As was recommended during the UDRP, we are considering adding more texture to the
		metal panelling in the projection over the church.
11.21	The Panel has concerns with the articulation on the west being very flat.	As was recommended during the UDRP, we are considering adding more texture to the
		metal panelling in the projection over the church.
11.22	The Panel recommends the applicant explore design solutions to break up the west façade and add	As was recommended during the UDRP, we are considering adding more texture to the
	more texture and depth to it.	metal panelling in the projection over the church.



No.	Comment	Response
11.23	The Panel recommends considering how to best articulate the west façade to create a quiet background	Agreed - we aim to be in the same colour family of the church but in a champagne, metalic
	for the church.	tone. We intend to select a colour/tone that is either lighter or darker than the stone of the
		church so that the church is not lost in the new background façade.
11.24	The Panel is unsure whether the extruded floating element above the church is successful.	This item was discussed at later meetings with the city. We noted the alterations and
		addition of detail elements (guard rails, texture façade) and there was agreement that it was
		much improved.
11.25	The Panel recommends relocating the mail room in the ground floor plan (perhaps behind elevators) to	The lobby has been greatly modified since UDRP. The entire volume of the apse has been
	allow for more public uses surrounding the church apse and allow for the apse to be viewed in the round	left exposed for two full storeys. All constructed program has been moved away from the
	completely.	heritage structure to leave it exposed.
11.26	The Panel appreciates the skillfully designed lobby space.	Acknowledged.
11.27	The Panel appreciates the windows with arched mullions, but integrating operable windows is	Acknowledged. The arched mullions have been removed from the design.
	necessary.	
11.28	Consider adding mullions to help with the proportions of this large piece of glass.	Acknowledged. Mullions and operability has been integrated into the design and elevations.







315 + portion of 321 Chapel Street (Future 8 Blackburn Avenue) Responses to Round 3 SPC Comments October 10, 2024

	October 10, 2024		
No.	Comment	Response	
	Next Steps		
2	As per the provincial Bill 185, Cutting Red Tape to Build More Homes Act, applicants are no longer required to partake in pre- consultation, but they may choose to participate. Should your team wish to continue with the pre-consultation process, pre- consultation fees still apply. Staff encourage further pre-consultation steps to take place as there are a number of deficiencies noted below. Alternatively, should your team wish to skip any further pre-consultation steps, and proceed directly to applying for the required applications, please be advised that upon application, the City will assess whether the submission is "complete" or "incomplete". Staff will review the submission to ensure all the material outlined on the Study Plan and Identification List (SPIL) is provided and that this material meets the City's Terms of Reference. Should it be deemed "incomplete" the submission will be put on hold.		
3	In your next pre-consultation submission or application submission, please ensure that all comments detailed herein are addressed. A detailed cover letter stating how each comment has been addressed must be included with the submission materials. Please coordinate the numbering of your responses within the cover letter with the comment number(s) herein.	Acknowledged, this table provides responses to comments received.	
	Planning		
	Deficiencies:		
1	Measurements for aisles to access bicycle parking spaces are missing on the ground floor plan so it's not possible to verify compliance with the Zoning By-law requirements.	The Ground Floor Plan has been updated to show dimensions of bicycle parking typologies and access aisles.	
2	Previous response: A Standard parking space beside exit stairs provided with no measurement inconsistencies or interferences. B2 parking space in South East corner shows one compact parking spot impeded upon by one column by 50mm and against one wall. With the column impediment, the parking space is 2350mm x 5200. Please note if this is acceptable. P COMPACT (2400 x 5200) Response: Unfortunately, while very minor, this would be a deficiency that requires resolution.	The parking garage layout has been revised to ensure that all parking spaces are zoning compliant with regard to length, width, and proximity to a wall or column in the case of compact parking spaces. Some parking spaces were not zoning compliant and they have been provided for compact cars, but they have not been counted toward the zoning compliant parking space total of 47 spaces. The resident and visitor rate below is derived from the zoning compliant 47 spaces only. All other spaces are provided in excess of the required minimums. Resident: 43 spaces provided, rate of 0.355 (required rate: 0.35) Visitor: 4 spaces provided, rate of 0.03 (required rate: 0.03) An additional 6 non-standard vehicle parking spaces are provided. Further detail is provided on the architectural set.	
	Comments		
4	Your response no. 28 to transportation comments states the following: "Acknowledged, the design for SPC Phase 3 submission shows a 1.5-metre sidewalk; however, this will be revised to show a 1.8-metre sidewalk for the final SPC submission. Unfortunately, the design was too far advanced to accommodate a 1.8-metre sidewalk for SPC Phase 3 submission. Civil, Landscape, and Architectural plans will be updated accordingly." Will this revision impact the soil volumes for trees? Please, elaborate.	The sidewalk has been widened per city request - it is a minimum of 1.8 m in width when adjacent to the paved bus pad, and increases to 2.3 m when proceeding east toward Blackburn Ave.	



Deficiencies: Submission Requirements Although a the components for a complete application have been provided, the terms of the Urban Design Brief REPORT (Anthough and the components for a complete application have been provided, the terms of the Urban Design Brief ResPORT (Anthough and the components for a complete application have been provided in the components for a complete application have been provided in the components for the Urban Design Brief Instead. Our components of the URBP report was submitted to Christopher Moise on August 2 at the following link: https://doi.org/10.10.10.10.10.10.10.10.10.10.10.10.10.1	No.	Comment	Response
Deficiencies:			
Submission Requirements Although although alth components for a complete application have been provided, the terms of the Urban Design Brief REPORT (see terms of reference link below) have NOT been followed. The current report reads as an Urban Design Brief instead. Please result intellowing the infections below. Although the current report reads as an Urban Design Brief instead. Please result intellowing the infections below. The current report reads as an Urban Design Brief instead. Please results intelligent to the submission of a UPP report to a requirement for deeming an application complete. Please follow the instructions (high the provided property of the provided provided and satisfies documents as a state of the provided provided and satisfies outstanding design commitments: Comments on Design We have no additional urban design comments. Engineering Plans: To grading Plan, Dwg GP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: *Alt be southwest cover of building shown on this plan, there is a roll an advanced provided to maintain all drainage on the property and direct it to Blandburn. Previous wall to keep all surface water on this property, unless draining to a public roadway, and not allowing to flow to the register of the property, unless draining to apublic roadway, and not allowing to flow to heighbouring strange. This location will need a strend from the instructions of the submission of the submission better. Although the control of the submission of the submission better. Although the control of the submission of the submission provided permission letter. dated and signed from this landowner for our files. *Constitution will require the control of the submission provided permission letter. dated and signed from this landowner for our files. *Previous plan and Servicing Plan to show emergency overflow. Although the provided permission letter. dated and signed from this landowner for our files. *Previous plan and Servicing Plan to show emergency overflow. Although t			
A hough all the components for a complete application have been provided, the terms of the Uthan Design Brief REPORT (see terms of reference link below) have NOT been followed. The current report reads as an Uthan Design Brief Instead. Please resubmit following the circulates below. Urban Design Review Panel Review and Report The submission of a UDRP report is a requirement for deerning an application complete. Please follow the instructions provided in the Terms of Reference available here than Design Review Panel Report Comments Comm			
The submission of a UDRP report is a requirement for deeming an application complete. Please follow the instructions provided in the Terms of Reference available here: Urban Design Review Panel Report (https://documents.ofswa.ca/sites/documents/files/udrp report tor, en.pdf) Comments on Design We have no additional urban design comments. Noted. **Continued to the plants of	4	Although all the components for a complete application have been provided, the terms of the Urban Design Brief REPORT (see terms of reference link below) have NOT been followed. The current report reads as an Urban Design Brief instead.	https://fotennottawa-my.sharepoint.com/:f:/g/personal/nahal_fotenn_com/EgRKu5ZflSVNjxj-
Comments on Design We have no additional uban design comments. Tognisering Plans: 1 Grading Plan, Dwg GP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: How does drainage work on North raised patio for entrances to units? Grades are 70.58 at building and at retaining walls. How will water escape and ensure it does not enter building at lowest opening? At the southwest corner of building shown on this plan, there is a soft landscaped area, which should have a barrier curb (or wall to see gal surface water on this property, unless draining to a public roadway, and not allowing for flow to neighbouring lands. Show all top and bottom elevations of this wall or curb, as required. There is no 19, 0.09 metres difference between CB on road and elevation shown for top of grade for entrance to US parking garage, This location will need a trench drain to ensure no excess water gets into parking garage during a major rain event. We recognize there is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard) is required. Construction within rear lot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission latter, dated and signed from this landowner for our files. Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: Please provide a lot state of the proposed grading is to route the water away from the building to route the water away from the building to route the water away from the building to route the water away from the publication and creating on the property and direct it to Blackburn. Previous wall to see the seap area per existing drainage on the property and direct it to Blackburn. Previous draining and the seap area per existing drainage on the property and direct it to Blackburn. Previous draining and the seap area per existing drainage on the property and direct it to Blackburn. Pr		The submission of a UDRP report is a requirement for deeming an application complete. Please follow the instructions provided in the Terms of Reference available here: Urban Design Review Panel Report (https://documents.ottawa.ca/sites/documents/files/udrp_report_tor_en.pdf)	Later that day, he confirmed that the UDRP Report is suitable and satisfies outstanding design comments.
Noted. State Servicing Plans Noted.		Comments:	
Plans: 1. Grading Plan, Dwg GP-1, prepared by Stantac Consulting Ltd., Rev. 1, dated May 19, 2024: 1. How does drainage work on North relased patio for entrances to units? Grades are 70.58 at building and at retaining walls. 1. How will water escape and ensure it does not enter building at lowest openings? 1. At the southwest corner of building shown on this plan, there is a soft landscaped area, which should have a barrier cut (or wall to toke pall surface water on this property, unless draining to a public roadway, and not allowing to flow to neighbouring lands. Show all top and bottom elevations of this wall or curb, as required. 1. There is only 0.09 metres difference between CB or not and and elevation shown for top of grade for entrance to UG parking garage. This location will need a trench drain to ensure no excess water gets into parking garage during a major rain event. We recognize there is no sag in roadway at this location, so no additional miligation measures (to achieve 350 mm freeboard) is required. 2. Construction within rear lot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission letter, dated and signed from this landowner for our files. 2. Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: 2. Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: 3. Please provide all details of cistem, including, but not limited to, lank interior floor, outlet pipe and emergency (with alarm) overflow elevation information. Nor rates and vessel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servicing Plan to show emergency overflow location. Please provide all details of cistem, including, but not limited to, lank interior floor, outlet pipe and emergency (with alarm) overflow elevation information. Nor rates and vessel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servic		Comments on Design	
Plans: Grading Plan, Dwg GP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: How does drainage work on North raised patio for entrances to units? Grades are 70.58 at building and at retaining walls. How will water escape and ensure it does not enter building at lowest openings? At the southwest corner for building shown on this plan, there is a soft indiscasped area, which should have a barrier curb (or variety of the property and precited to Blackburn. Previous wall) to keep all surface water on this property, unless draining to a public roadway, and not allowing to flow to neighbouring lands. Show all top and bottom elevations of this wall or curb, as required. There is only 0.98 metres difference between CB on road and elevation shown for top of grade for entrance to US parking grage during an irrie event. We recognize there is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard) is required. Construction within rear lot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission letter, dated and signed from this landowner for our files. Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: Proposed grading its to route the water away from the building so the provision on the proposed building. Trench drain agreement of private approach by the stilling surface drainage glading and surface agraement of provided with this submission pain execution (signature page) and a description of the landowner for the site from 321 Chapel to be included within this development that shows a general description noting a purchase and sale agreement. This document is being submission pain execution (signature page) and a description of the lands (schedules). This documentation as sufficient to assistly the intent of this review comment. This document is being submission pain execution (signature page) and a description of the lands (schedules). This security is	6	We have no additional urban design comments.	Noted.
From the Surface of Plan, Dwg GP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: - How does drainage work on North raised patio for entrances to units? Grades are 70,58 at building and at retaining walls. How will water escape and ensure it does not enter building at lowest openings? - At the southwest corner of building shown on this plan, there is a soft landscaped area, which should have a barrier curb (or wall) to keep all surface water on this property, unless draining to a public roadway, and not allowing to flow to neighbouring lands. Show all top and bottom elevations of this wall or curb, as required. - There is only 0.09 metres difference between CB on road and elevation shown for top of grade for entrance to UG parking garage. This location will need a trench drain to ensure no excess water gets into parking garage during a major rain event. We recognize there is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard) is required. - Construction within rear lot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission letter, dated and signed from this landowner for our files. - Please provide all details of cistern, including, but not limited to, tank interior floor, outled May 19, 2024: - Please provide all details of cistern, including, but not limited to, tank interior floor, outled May 19, 2024: - Please provide all details of cistern, including, but not put limited to, tank interior floor, outled with six submission pands and servicing plan and Servicing Plan to show emergency overflow location. Please label appropriately, Refer to DWG A0-800 within SS & SWMR peport. Above and below grade storage vessels will require use of 50% of peaking factor. - Please provide all legals of cistern, including but not plan the provided by Mechanical consultant for the building plumbing desi storage volumes and service location and sizes have been coordinated accordingly. - This will		Engineering	
How does drainage work on North raised patio for entrances to units? Grades are 70.58 at building and at retaining walls. How will water escape and ensure if does not enter building at lowest openings? At the southwest corner of building shown on this plan, there is a soft landscaped area, which should have a barrier curb (or wall) to keep all surface water on this property, unless draining to a public roadway, and not allowing to flow to neighbouring ands. Show all top and bottom elevations of this wall or curb, as required. Toe Wall will be provided to maintain all drainage on the property and direct it to Blackburn. Previous conteplated to maintain all drainage on the property and direct it to Blackburn. Previous conteplated to maintain all drainage on the property and direct it to Blackburn. Previous conteplated to maintain all drainage on the property and direct it to Blackburn. Previous conteplated to maintain all drainage on the property and direct it to Blackburn. Previous conteplated to maintain all drainage on the property and direct it to Blackburn. Previous conteplated to maintain the soft scape area per existing drainage conditions. In the soft of the existing drainage conditions. To Wall will be provided to maintain all drainage on the proposed previous conteplated to maintain all drainage on the proposed previous conteplated to maintain the soft scape area per existing drainage conditions. To Wall will be provided to maintain all drainage on the property and direct it to Blackburn. Previous conteplated to maintain the soft scape area per existing drainage conditions. To Wall will be provided grading meets the requirements of private approach bylaw. The existing surface drainage garage. The secondary among an existing drainage conditions. To wall will be provided grading meets the requirements of private approach bylaw. The existing surface drainage garage. The soft proposed grading meets the requirements of private approach bylaw. The existing and surface drainage garage. The soft propose		Plans:	
How does drainage work on North raised patio for entrances to units? Grades are 70.58 at building and at retaining walls. How will water escape and ensure it does not enter building at lowest openings? At the southwest corner of building shown on this plan, there is a soft landscaped area, which should have a barrier curb (or wall) to keep all surface water on this property, unless draining to a public roadway, and not allowing to flow to neighbouring and so. Show all top and bottom elevations of this wall or curb, as required. There is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard) is required. Construction within rear lot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission letter, dated and signed from this landowner for our files. Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vessel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servicing plan and Servicing plan to show emergency overflow location. Please label appropriately. Refer to DWG A0-800 within SS & SWM Report. Above and below grade storage vessels will require use of 50% of peaking factor. **Proposed grading is to route the water away from the building and the table in about the continue of building should to the content of the proposed to maintain all drainage on the proposed of the proposed did to Blackburn. Previous contenting and surface area per existing drainage conditions. In This will be provided grading meets the requirements of private approach bylaw. The existing surface drainage gliackburn is routed south away from the proposed building. Trench drain is proposed at the bottom of the con	1	Grading Plan, Dwg GP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:	
- At the southwest corner of building shown on this plan, there is a soft landscaped area, which should have a barrier curb (or wall) to keep all surface water on this property, unless draining to a public roadway, and not allowing to flow to neighbouring lands. Show all top and bottom elevations of this wall or curb, as required. 1 There is only 0.09 metres difference between CB on road and elevation shown for top of grade for entrance to UG parking garage. This location will need a trench drain to ensure no excess water gets into parking garage during a major rain event. We recognize there is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard) is required. 1 Construction within rear lot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission letter, dated and signed from this landowner for our files. 2 Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: 1 Please provide all details of cistem, including, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vessel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Sis Servicing Plan to show emergency overflow. 2 Site Servicing Plan and Servicing Plan to show emergency overflow location. Please label appropriately. Refer to DWG A0-800 within SS & SWM Report. Above and below grade storage vessels will require use of 50% of peaking factor. 2 Please provided to maintain all drainage on the provided to maintain the soft scape area per existing drainage conditions. 2 Proposed grading meets the requirements of private approach bykew in the existing surface drainage and selection of private approach bykew. The existing surface drainage allackburn is routed south away from the proprised existing from the provised building. Trench drain is proposed building. Trench drain is proposed at the obtom complex from th		How does drainage work on North raised patio for entrances to units? Grades are 70.58 at building and at retaining walls.	Proposed grading is to route the water away from the building towards the access ramp and out to the street
wall) to keep all surface water on this property, unless draining to a public roadway, and not allowing to flow to neighbouring lands. Show all top and bottom elevations of this wall or curb, as required. There is only 0.09 metres difference between CB on road and elevation shown for top of grade for entrance to UG parking garage. This location will need a trench drain to ensure no excess water gets into parking garage during a major rain event. We recognize there is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard) is required. **Construction within rear tot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission letter, dated and signed from this landowner for our files. **Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:** **Please provide all details of cistern, including, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vessed capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servicing Plan to show emergency overflow within SS & SWM Report. Above and below grade storage vessels will require use of 50% of peaking factor. **Please provide length of service on plans, for Water and Sewer.** All dimensions have been shown on the Site Servicing Plans **Storm Drainage Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:** **All dimensions have been shown on the Site Servicing Plans **All dimensions have been shown on the Site Servicing Plans **All dimensions have been shown on the Site Servicing Plans **All dimensions have been shown on the Site Servicing Plans			
Index. Show all top and bottom elevations of this wall or curb, as required. There is only 0.03 metres difference between CS on road and elevation shown for top of grade for entrance to US parking garage. This location will need a trench drain to ensure no excess water gets into parking garage during a major rain event. We recognize there is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard) is required. Construction within rear tot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission letter, dated and signed from this landowner for our files. Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: Please provide all details of cistern, including, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vessel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servicing Plan to show emergency overflow location. Please label appropriately. Refer to DWG A0-800 within SS & SWM Report. All dimensions have been shown on the Site Servicing Plans Storm Planspe Plans Day Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: All dimensions have been shown on the Site Servicing Plans Storm Planspe Pl			Toe Wall will be provided to maintain all drainage on the property and direct it to Blackburn. Previous proposal conteplated to maintain the soft scape area per existing drainage conditions.
* There is only 0.09 metres difference between CB on road and elevation shown for top of grade for entrance to UG parking garage. This location will need a trench drain to ensure no excess water gets into parking garage during a major rain event. We recognize there is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard is required. * Construction within rear lot access laneway requires coordination with neighbouring landowner, we understand. Please provide permission letter, dated and signed from this landowner for our files. * We (the applicant) have executed an agreement of purchase and sale with the landowner for the slive from 321 Chapel to be included within this development application. Provided with this submission pa an excerpt from the purchase and sale agreement. This documentation st sufficient to satisfy the intent of this review comment. This document is being submitted in confidence would ask that it not be made available to the public. 2 Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: * Please provide all details of cistern, including, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vassel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servicing Plan to show emergency overflow location. Please label appropriately. Refer to DWG A0-800 within SS & SWM Report. Above and below grade storage vessels will require use of 50% of peaking factor. * Please provide length of service on plans, for Water and Sewer. 3 Storm Parange Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:			
provide permission letter, dated and signed from this landowner for our files. from 321 Chapel to be included within this development application. Provided with this submission pa an excerpt from the purchase and sale agreement that shows a general description of the lands (schedules). This documentation at sufficient to satisfy the intent of this review comment. This document is being submitted in confidence would ask that it not be made available to the public. Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: Please provide all details of cistern, including, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vessel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servicing and SWM (SS & SWM) Report recommendations. Alarm to be on both pumped or gravity discharge situations with emergency overflow. Grading plan and Servicing Plan to show emergency overflow location. Please label appropriately. Refer to DWG A0-800 within SS & SWM Report. Please provide length of service on plans, for Water and Sewer. Please provide length of service on plans, for Water and Sewer. All dimensions have been shown on the Site Servicing Plans All dimensions have been shown on the Site Servicing Plans		• There is only 0.09 metres difference between CB on road and elevation shown for top of grade for entrance to UG parking garage. This location will need a trench drain to ensure no excess water gets into parking garage during a major rain event. We recognize there is no sag in roadway at this location, so no additional mitigation measures (to achieve 350 mm freeboard)	Proposed grading meets the requirements of private approach bylaw. The existing surface drainage on Blackburn is routed south away from the proposed building. Trench drain is proposed at the bottom of the ramp.
Site Servicing Plan, Dwg SSP-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024: Please provide all details of cistern, including, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vessel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servicing and SWM (SS & SWM) Report recommendations. Alarm to be on both pumped or gravity discharge situations with emergency overflow. Grading plan and Servicing Plan to show emergency overflow location. Please label appropriately. Refer to DWG A0-800 within SS & SWM Report. Above and below grade storage vessels will require use of 50% of peaking factor. Please provide length of service on plans, for Water and Sewer. All dimensions have been shown on the Site Servicing Plans Storm Drainage Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:		provide permission letter, dated and signed from this landowner for our files.	We (the applicant) have executed an agreement of purchase and sale with the landowner for the sliver of land from 321 Chapel to be included within this development application. Provided with this submission package is an excerpt from the purchase and sale agreement that shows a general description noting a purchase of the land, its execution (signature page) and a description of the lands (schedules). This documentation should be sufficient to satisfy the intent of this review comment. This document is being submitted in confidence and we would ask that it not be made available to the public.
Please provide all details of cistern, including, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vessel capacity. Ensure there is a secondary back up pump. This should be in conjunction with Site Servicing and SWM (SS & SWM) Report recommendations. Alarm to be on both pumped or gravity discharge situations with emergency overflow. Grading plan and Servicing Plan to show emergency overflow location. Please label appropriately. Refer to DWG A0-800 within SS & SWM Report. Above and below grade storage vessels will require use of 50% of peaking factor. Please provide length of service on plans, for Water and Sewer. All dimensions have been shown on the Site Servicing Plans Storm Drainage Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:	2		'
Grading plan and Servicing Plan to show emergency overflow location. Please label appropriately. Refer to DWG A0-800 within SS & SWM Report. Above and below grade storage vessels will require use of 50% of peaking factor. Please provide length of service on plans, for Water and Sewer. All dimensions have been shown on the Site Servicing Plans Storm Drainage Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:		• Please provide all details of cistern, including, but not limited to, tank interior floor, outlet pipe and emergency (with alarm) overflow elevation information, flow rates and vessel capacity. Ensure there is a secondary back up pump. This should be in	This will be provided by Mechanical consultant for the building as it constitutes building plumbing design. The storage volumes and service location and sizes have been coordinated accordingly.
within SS & SWM Report. Above and below grade storage vessels will require use of 50% of peaking factor. • Please provide length of service on plans, for Water and Sewer. 3 Storm Drainage Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:		Alarm to be on both pumped or gravity discharge situations with emergency overflow.	
• Please provide length of service on plans, for Water and Sewer. All dimensions have been shown on the Site Servicing Plans Storm Drainage Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:			
• Please provide length of service on plans, for Water and Sewer. 3 Storm Drainage Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:		Above and below grade storage vessels will require use of 50% of peaking factor.	
3 Storm Drainage Plan, Dwg SD-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:			All dimensions have been shown on the Site Servicing Plans
	3		p
In Diamage Man to show grainage within the suffounding area with existing public intrastructure, not just site. This pian is to live will review the SL) drawing and report and ensure the areas are consistent, however, typically, we	-	• Drainage Plan to show drainage within the surrounding area with existing public infrastructure, not just site. This plan is to	We wil review the SD drawing and report and ensure the areas are consistent, however, typicaly, we only
correspond with Site Servicing and SWM Report and it's recommendations.			



No.	Comment	Response
4	Sanitary Drainage Plan, Dwg SA-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:	
	• Drainage Plan to show drainage within the surrounding area with existing public infrastructure, not just site. This plan is to	Drainage areas applicable to the Sanitary sewer design have been properly identified.
	correspond with Site Servicing and SWM Report.	
5	Existing Conditions Plan, Dwg EX-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:	
	• Please show existing water services and label appropriately. Also note whether they are to be kept or abandoned & blanked	Will update drawings accordingly.
	at main.	
6	Notes and Legends Drawing, Dwg NL-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:	Table 1981 - 11 1
	• Please add note regarding adhering to City Sewer and Water Guidelines, By-laws, Standard Detail Drawings, Approved Products (all as amended) and MECP regulations and e-laws (as amended).	Note will be added.
	• Please add note regarding contractor requirement to regularly clean debris and keep dust down on all roadways affected by	Note will be added.
7	Erosion Control & Detail Sheet, Dwg ECDS-1, prepared by Stantec Consulting Ltd., Rev. 1, dated May 19, 2024:	
	• Please add note regarding contractor requirement to regularly clean debris and keep dust down on all roadways affected by	Note will be added
0		
8	Roof Plan is required, including ponding contours and table with roof drain numbers, corresponding flow rates and weir	We do not anticipate any ponding on the roof, all regualted design storm events are managed with internal
		cystern design by mechical engineer. So no ponding plan available.
9	Landscape Plans, Dwgs L100, L101, L200, L600-602, all prepared by Stantec Consulting Ltd., Rev. 5 and dated May 05	
		City Standear details will be used for the landscape elements planting, hardscape, curbs, etc.) where
		applicable,
	request for a change, this must go through the deviation process with the City of Ottawa.	
	• Please do not plant on top of water services with trees. Only shallow rooted plantings that will not interfere with services to	Tree planting will be review with siter servicing plan plan adjusted to avoid any conflicts.
	site. See Servicing Drawing.	
	Studies:	
1	Geotechnical Investigation Report, prepared by Paterson Group Inc., dated August 1, 2023:	
	Please speak to protection of any nearby buildings on site or those within neighbouring properties.	This comment has been acknowledged and the report has been revised accordingly to include a "Vibration Considerations" in Section 5.2 of the current Geotechnical Investigation Report. This section details precautionary measures regarding the reduction of vibration levels during construction operations considering the adjacent existing structure on the subject property and neighbouring the subject site.
		Additionally, Reference should be made to Section 6.3 of the current Geotechnical Investigation Report which proposes suitable excavation and temporary shoring measures to maintain adequate support of existing neighbouring structures and infrastructure.
2	Roadway Traffic Noise Assessment, dated August 9, 2023, and Addendum Eng. Letter, dated February 9, 2024, both p	
	• Stationary Noise Study will be required and conditioned as part of approval process, unless submitted and approved prior to	
	drafting DAR. Study should speak to mechanical units of this building and any mitigation required for occupants as well as neighbouring properties.	
3	Site Servicing and SWM Report, prepared by Stantec Consulting Ltd., dated May 21, 2024:	
<u> </u>	• See comments for Site Servicing Plan in regard to Cistern details, related to design and recommendations in SS & SWM	Refer to response Item 2 Engineering Plans
4		Incier to response item 2 Engineering Fians
4	Tree Conservation Report, prepared by IFS Associates Inc., dated February 9, 2024:	
		Noted.
5	Site Lighting Certificate, prepared by Smith + Anderson, dated April 24, 2024:	
	No comments	Noted, please note that an updated Site Lighting Certificate prepared by GWAL is included in this submission package.
6	Wind Study.	
	Due to height, a wind study is required. Please submit as soon as possible for our review.	Submission folder has been updated with the Wind Study and Addendum letter and sent to Shawn Wessel on July 23, 2024. Per correspondence, Shawn indicated that he has reviewed the Wind Studty and Addendum and stated he does not have any comments and "they are deemed acceptable for our purposes."
	Environmental Remediation Unit	
7	The ERU has reviewed the Phase One and Phase Two ESAs submitted with the application and has no comment.	Noted.
8	It is notes that a Record of Site Condition will need to be filed by the Ministry of Environment, Conservation & Parks in order	Noted.
	to develop the property for residential land use.	



No.	Comment	Response
	Transportation	
	- TIA Scoping Report – CGH, Dated February 04, 2024	
	- Signage Plan 001, Revision #2, Dated April 24, 2024	
	Deficiencies:	
	Transportation Engineering	
	Site and Floor Plans:	
9	A direct path (i.e., with stairs) to the amenity entrance from Laurier Avenue next to the accessible ramps is recommended.	Please refer to updated Landscape and Site Plan - an accessible path and direct staircase has been provided
	Trained pair (i.e., with stails) to the amenity entrance from Eaurer revenue flext to the accessible ramps is recommended.	from Laurier Avenue.
10	The site plan's "zoning matrix" states that the development proposes 85 bicycle parking spaces. TES counts 143 bicycle	Revised
' '	parking spaces including 58 stacked spaces (58 x 2 = 116), 13 vertical spaces, and 14 outdoor spaces. It appears that the 58	
	stacked spaces weren't counted twice when identifying the total as 85 (143-58 = 85). Recommend fixing the zoning matrix to	
	identify the correct number of bicycle parking spaces provided.	
11	The exterior bicycle parking located at the northwest corner of the proposed building is labeled as having five spots, when it	Revised
1	has four. Please revise.	
12	Note the following outstanding items:	Revised, sidewalks on both Laurier Avenue and Blackburn Avenue have been widened to 1.8 m.
-	• Laurier Avenue and Blackburn Avenue sidewalks must be widened to a minimum 1.8m in the next site plan submission, as	,
	committed to in comment/response 28.	
	Comments:	
	Transportation Engineering	
	Signage Plan:	
13	Dimension the length of the proposed loading zone, distance between the loading zone and Laurier Avenue / Blackburn	A revised dimensioned signage plan has been appended to this comment response to address this comment.
1.0	Avenue intersection and spacing between the existing and proposed one-hour parking restriction signs to better characterize	The short term parking area is proposed to permit three 6.7m on-street parallel parking spaces.
	the signage plan. At a minimum, scale the drawing so that dimensions can be measured.	The effect term parking area to proposed to permit times c.r.m. on except parking opasses.
	Site and Floor Plans:	
14	Note the following outstanding items:	Please see response to Planning comment #4, this has been revised as requested.
1	Bus stop modifications at Laurier Avenue will be discussed further in the future through site plan conditions, per	I read to respond to rearming comment in it, the read society of equations
	comment/response 29. A note on the site plan would be appreciated to document the intent to improve the bus stop	
	pad/platform.	
	Traffic Signal Design	
15	No comments for this current circulation. The Traffic Signal Design Unit reserves the right to make future comments based on	Noted.
	subsequent submissions.	
16	Should any lane arrangements be modified (example lane closure to facilitate shoring, deliveries, etc.) within 30m of a	Noted.
	signalized intersection or at a signalized intersection, the proponent will be required to provide Traffic Control Plans in	
	AutoCAD (.dwg) format to the City's Traffic Signal Design Unit to update signal legal drawings as well as assess any changes	
	to signal displays or operation. Required signal changes are at the sole discretion of the City Traffic Signal Design Unit and	
	costs associated with changes including legal drawing update with or without signal changes are the responsibility of the	
	Traffic Management	
	Comments:	
	We require the following information:	
17	Diagram:	Preliminary Construction Management Plan sent to Pagamo Amade (pagamo.amade@ottawa.ca)
	Labelled graphic showing proposed construction area within ROW	, January (Fraganisana (Fragani
1	Meant to be preliminary	
18	Checklist:	Construction traffic to enter and exit the site on Blackburn, No interruption to bus routes (on Laurier) is
	Will construction require the temporary detour of a bus route?	required.
	• Will this work block a bike lane?	No bike lane relocation is required as there is no bike lanes adjacent to the consatrution site.
	Will this work block a sidewalk?	• Sidewalks access on Blackburn and Laurier is to be maintained through all construction phases.
	Will this work require a lane of traffic to be closed?	• It is anticipated that all work is to occur within the construction area boundries and no traffic lane/road closure
	Will this work require road closure?	will be required. However,road cuts permits and closures will be reuqired for the incoming new services for
1		water, storm, and sanitary. Permit aplication is to be submitted.
		mater, eterrin, and carmary. I crimit approached to be obtained.



No.	Comment	Response
	General comments:	
19	The Project Manager is asked to contact the City of Ottawa Traffic Management Unit Pagamo Amade (pagamo.amade@ottawa.ca) to discuss the potential traffic impacts of the project.	The Preliminary Construction Management Plan was shared with Mr. Pagamo Amade on August 28, 2024. On August 29, 2024, Mr. Amade confirmed that he had no concerns with the Plan.
20	If the proposed work requires the closure of traffic lanes (at any time) the contractor must submit a Traffic Management Plan to the City of Ottawa Bylaws, Permits & Inspections Unit.	No traffic lanes closure is required, please refer to attached The Preliminary Construction Management Plan for more info and details.
21	If the proposed work will interfere with pedestrian access to/from a transit stop, the contractor must contact OC Transpo at least 10 working days prior to starting construction to arrange for the temporary relocation of the affected transit stop(s) as	Sidewalks to remain open during construction, based on the project needs, Local Authorities will be contacted. Please refer to attached The Preliminary Construction Management Plan for more info and details.
22	Coordinate the temporary removal of on-street parking, (if required) through the City Traffic Management Inspector.	No street parking removal required, please refer to attached The Preliminary Construction Management Plan for more info and details.
23	Maintain pedestrian access and provide pedestrian detours if necessary. If the closure of a sidewalk is required and pedestrians must be detoured, the contractor is required to provide ten (10) business days' notice to adjacent home/business owners and contact the local area Councillor's office. Additional details can be found at Ottawa.ca/roadactivity.	
24	Maintain local and emergency access at all times. Where access cannot be maintained the contractor must contact the City Traffic Management Inspector to discuss alternatives. Environment	Local and emergency access will be kept at all times. If needed, Traffic management inspector will be contacted. Please refer to attached The Preliminary Construction Management Plan for more info and details.
	Comments:	
25	Please, consult the previous comments. No new comments received.	
20	Forestry	
	Deficiencies:	
26		Noted
20	None – the Planning Forester has no objections to the approval of the zoning application.	Noted.
0.7	Comments:	NI-4-J
27	A tree permit is required prior to any tree removal. Tree permits can be released once the site plan control application has been approved.	Noted.
28	Compensation will be required for any city tree removed – compensation amounts will be calculated during the site planning stage.	Noted.
29	The TCR will need to be resubmitted with any future site plan application. Please note that if there are changes to the site plan, the TCR will need to be updated.	A revised TCR is included in this submission. The TCR includes the updated Site Plan.
		Please note that Tree #19, located on 14 Blackburn Avenue, is in poor health and is a hazard. Windmill has reached out to the neighbour to recommend that the tree be removed and replaced and the neighbour is aware it has been flagged as hazardous.
		The tree would not survive construction due to its proximity to the pathway and retaining walls and it is described in the TCR as being in "very poor" health.
30	Soil volumes for new trees meet City requirements.	Noted.
	Parkland	
	Comments:	
31	Parkland Dedication By-law No. 2022-280	
32	Thank you for providing the required information for Parkland Dedication calculation. Please, indicate any changes to this numbers during the application submission.	Project statistics for the parkland dedication calculation are as follows: • Lot area of the site to be re-developed, in square meters: 1,622.2 4m²
		Number of residential units proposed: 121 (increased from 117)
		• Total building Gross Floor Area (GFA): 8,400 (decreased from 8,423 m²)
		GFA of other uses within the building: No other uses proposed
	Heritage	
	Comments:	
33	Heritage staff are pleased to see the re-introduction of more stone on the podium level on Laurier Avenue.	Noted, thank you.




No.	Comment	Response
34	The design approved in the heritage permit included detailed brickwork around the windows within the brick-clad portions of the building. This detail seems to have been lost in this SPC submission. While subtle in nature, this detail elevated the design of the new construction to harmonize with that of the former All Saints Anglican Church. Please revisit this design detail.	Our project Heritage Consultants have provided responses below: Barry Padolsky: "I concur with the staff comment that brick surrounds framing the windows add interest and contribute to promoting a visual focus on the lower scale brick-clad podium portion of the overall massing. I also note that (in the rendering) a livelier overall brickwork pattern and colour is suggested. If the final brick selection contains a rich coursing pattern and lively colour range, this revision may achieve the same objective of elevating the visual design. I recommend that this alternative be explored." John Stewart: "In our analysis, features that were identified as defining heritage attributes include the dressed and rusticated limestone, along with the church's buttresses and gothic windows. It was also noted that the neighbouring residences with their elaborate brickwork, use of stone details and corbelling help define the neighborhood and maintain the distinction between institutional (limestone) and residential (Rideau redbrick). The use of the salvage masonry material used at the terraces provides texture and visual appeal. Similarly, the brick helps to place the podium in relation to neighbouring homes. Both Barry and I concur that the cladding should be real and that it needs to convey some of the playfulness and shadowing rather than just flat panel cladding."
35	The proposed metal cladding in the heritage permit was better suited to the project, as it helped to keep the upper storeys in the background, allowing the former church to remain the focal point. Please revert back to a flat metal panel.	We concur with the intent of the staff comment on the importance of keeping upper part of the building in the background. However, we believe that the changes to the metal cladding details are visually minor and will not significantly draw visual attention away from the focal point (All Saints Church). We believe that simplifying the form of the balconies on the upper part of the building helps maintain visual attention on the podium elements and the Church.
36	Please be reminded that the heritage permit contains the following condition:	It is recognized that a heritage protection plan identifying risks and mitigation strategies will be prepared by a
36(a)	The applicant providing a detailed protection plan for the former All Saints Anglican Church and financial securities related to the implementation of the protection plan as a condition of Site Plan approval, to be implemented prior to demolition and construction Please provide a detailed protection plan for the former All Saints Anglican Church with your formal Site Plan Control application. The report should include an evaluation of potential risks to the heritage building and a detailed plan for protection and mitigation of these risks including but not limited to:	qualified Constructor/ Contractor
	 Pre-construction building condition survey and documentation Vibration and crack monitoring Monitoring reports 	
	Implementation of physical protection for the former church	
	Conservation Authority	
27		
37	No comments. Waste Management Services	
	Deficiencies:	
38	This location would get city multi residential collection, but I need some info before accepting the site plan, is the 2.3m	As confirmed via email with André Laplante dated August 8, 2024, a 2-metre path is required, not 2.3 m. This
20	pathway leading to the street free of obstructions and is it a clear 2.3 m throughout the length of the pathway?	has been provided in the plans.
39	What is the sq f of the garbage room and the how wide is the opening of the garbage room door? Other	773.9sqft, and the opening is 2135x2135mm
40	Building Code Services No further comments	
40	No further comments	



No	Comment	Response
	Community Association Comments	
41	There is nothing I can see in the proposed redevelopment plan concerning the white pines to the east of All Saints Church. One of these trees appears to be 80 years old or more. Both appear healthy and in good condition. Please let me know what the plans are to save these trees.	Per the Tree Conservation Report, Tree #12 is a White Pine. This is proposed to be removed as it is located in the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building. If the approved building area for the new building.
42	High rise buildings are known to create microclimates. Two high rises on the north side of Laurier Av and another on the south side are known to create changes in the local air currents. For example, the gap between 373 Laurier and its neighbour to the west creates an air canyon on windy winter days and areas of turbulence around the south facing entries of the high rises on the north side. Adding a fourth high rise in the same area may increase these disturbances. Are there plans to address the possible effects of wind currents should a fourth high building be added to the existing three? Survey Plan	While windier conditions may occassionally occur in the area, the assessment of wind comfort conditions is based on winds that occur 80% of the time, per the City of Ottawa Terms of Reference. The pedestrian level wind study found conditions to be suitable for the intended pedestrian uses throughout the year, following the introduction of the proposed development.
43	Site Plan requires a note stating where property boundary & topographic information was derived from.	A note has been added to the Site Plan to indicate the survey source.
43	Joile Flair requires a note stating where property boundary & topographic information was derived from.	JA note has been added to the Site Plan to indicate the survey source.

SITE, CONTEXT, & ANALYSIS

- Perspective images to and / or from the site
- Built and natural heritage assets on site and adjacent area




X | SURROUNDING SITE.





















345 LAURIER AVE

373 LAURIER AVE

408 LAURIER AVE








X | BUILT & NATURAL HERITAGE ASSETS ON SITE & ADJACENT SITES.


All Saints Anglican Church is a designated heritage resource under Part IV of the Ontario Heritage Act. However, Bate Memorial Hall is not. The Statement of Significance references the grounds as an important component of the site's heritage. The majority of the subject site is located directly north of the Russell-Range Heritage Conservation District (HCD); the sliver of land proposed to be assembled from 321 Chapel Street is located within the Russell-Range HCD. Additionally, the Wilbrod-Laurier Heritage Conservation District is located across the street on the north side of Laurier Avenue East. The Russell-Range HCD was designated as part V of the Ontario Heritage Act in 2018 as part of the Sandy Hill Heritage Study Phase II.




X | CHURCH HERITAGE ARCHITECTURE.




















X | SURROUNDING HERITAGE ARCHITECTURE & CONTEXT.
















DESIGN RESEARCH

DESIGN EVOLUTION

Major changes:

- Simplification and reduction in size of balconies to simplify facade and remove competition with the heritage church building and surrounding community
- Removal of second floor condo unit on north facade adjacent to church apse to completely expose the apse to views to Laurier Ave.
- Laurier Ave. access centralized to improve visibility of apse and emphasize the entrance to the ground floor amenity space and exterior terrace
- De-emphasis of exit stair massing on North facade



AERIAL VIEWS - PRE APP CONSULTATION 23/04/03

AERIAL VIEWS - ZONING DESIGN BRIEF 24/01/24













STREET VIEWS - PRE APP CONSULTATION 23/04/03



STREET VIEWS - SPC 24/09/27









STREET VIEWS - SPC 24/09/27









STREET VIEWS - ZONING DESIGN BRIEF 24/01/24

APPENDIX

- SITE PLAN
- LANDSCAPE PLANS (GROUND AND ROOF)
- ELEVATIONS
- FLOOR PLANS

