GEMTEC
www.gemtec.ca

Phase One Environmental Site Assessment
1052, 1060, and 1064 St. Laurent Boulevard
Ottawa, Ontario

GEMTEC Project: 103499.002

GEMTEC
www.gemtec.ca

Submitted to:

Performance Mazda Ottawa
1469 Youville Drive
Orleans, Ontario
K1C 4R1

Phase One Environmental Site Assessment
1052, 1060, and 1064 St. Laurent Boulevard
Ottawa, Ontario

August 8, 2025
GEMTEC Project: 103499.002

experience • knowledge • integrity

GEMTEC Consulting Engineers and Scientists Limited
32 Steacie Drive
Ottawa, ON, Canada
K2K 2A9

August 8, 2025 File: 103499.002

Performance Mazda Ottawa
1469 Youville Drive
Orleans, Ontario
K1C 4R1

Attention: Mr. John McEwan

Re: Phase One Environmental Site Assessment
1052, 1060, and 1064 St. Laurent Boulevard (St. Laurent Properties)
Ottawa, Ontario

Enclosed is our Phase One Environmental Site Assessment (ESA) report for the above-noted property. The report presented herein is based on the scope of work summarized in the proposal dated May 28, 2025. This report was prepared by Mohit Bhargav, M.Sc.E., P.Eng., and reviewed by Daniel Elliot, B.Sc., P.Geo., QP_{ESA}.

Mohit Bhargav, M.Sc.E., P.Eng.
Environmental Engineer

Daniel Elliot, P.Geo., QP_{ESA}
Senior Environmental Geoscientist

MB/DE

N:\Projects\103400\103499.002\05_Technical Work\Phase One ESA Report\103499.002_RPT_PhaseOneESA_2025-8-8_Rev0.docx

1.0 EXECUTIVE SUMMARY

GEMTEC Consulting Engineers and Scientists Limited (GEMTEC) was retained by Performance Mazda Ottawa to carry out a Phase One Environmental Site Assessment (ESA) for the properties located at 1052, 1060, and 1064 St. Laurent Boulevard (collectively referred to as the Site) in Ottawa, Ontario. It is understood that the Phase One ESA is required to support a Record of Site Condition (RSC) for a proposed commercial/residential development at the Site.

The Site is developed with three structures, covers an approximate area of 0.88 acres and fronts along St. Laurent Boulevard. The preliminary proposed development for the Site involves the construction of a mixed-use building spanning across the three land parcels that make up the Site. The proposed structure is expected to be approximately 30 storeys in height, with the ground level designated for commercial use and the upper levels consisting of residential units. The development will also include a three-storey underground parking garage.

This Phase One ESA was carried out in accordance with Ontario Regulation (O. Reg.) 153/04, as amended. The Site is considered an enhanced investigation property as defined by O. Reg. 153/04 due to the presence of an automotive shop/garage ('Shore Automotive') located at 1064 St. Laurent Boulevard.

The primary objective of this Phase One ESA is to identify and document current and historical environmental conditions and operations or practices at and in the vicinity of the Site that have the potential to impact soil and/or groundwater quality at the Site, and to determine if such operations or practices result in any Areas of Potential Environmental Concern (APECs) in association with the Site. The general objectives were met though the evaluation of the information gathered from the review of records, interviews, and a Site reconnaissance.

Based on the Phase One ESA findings, Potentially Contaminating Activities (PCAs) were identified resulting in the following APECs:

- APEC 1 – Presence of a former aboveground storage tank (AST) located in the northwest corner of structure at 1052 St. Laurent Boulevard. Contaminants of Potential Concern (COPCs) include Petroleum Hydrocarbon F1-F4 (PHCs) and Benzene, Toluene, Ethylbenzene, and Xylene (BTEX) with potential for impacts in soil and groundwater;
- APEC 2 – Area of known soil contamination in southeast corner of 1060 St. Laurent Boulevard. COPCs include Metals (Lead), and PHCs in soil;
- APEC 3 – Automotive Shop with ASTs and Oil Water Separator at 1060 St. Laurent Boulevard. COPCs include PHCs, Volatile Organic Compounds (VOCs), Metals (including Hydride Forming Metals), Other Regulated Parameters (ORP), Polycyclic Aromatic Hydrocarbon (PAHs) in soil and groundwater;
- APEC 4 – Presence of former retail fuel outlets and garages (off-Site and upgradient) in the southern and the eastern portion of 1064 St. Laurent Boulevard. COPCs include

PHCs, VOCs, Metals (including Hydride Forming Metals), ORP, and PAHs in soil and groundwater;

- APEC 5 – Likely present of fill material related to structures at localized areas on 1052 St. Laurent Boulevard and 1064 St. Laurent Boulevard within the former building footprints. COPCs include PHCs, PAHs, BTEX, Metals (and Hydride Forming Metals), and ORP in soil;
- APEC 6 – Road salting activities during the winter months on-Site. COPCs include Electrical Conductivity (EC) and Sodium Adsorption Ratio (SAR) in soil; and,
- APEC 7 – Road salting activities during the winter months along St. Laurent Boulevard. COPCs include EC and SAR in soil.

Based on the findings of this report, a Phase Two ESA is recommended to confirm the presence of absence of COPCs within the APECs. A Phase Two ESA would be required to support an RSC filing.

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY III

2.0 INTRODUCTION 7

2.1 Site Information 8

3.0 SCOPE OF THE INVESTIGATION 8

3.1 General Objectives 8
3.2 Records Review 8
3.3 Interview 9
3.4 Site Reconnaissance 9

4.0 RECORDS REVIEW 10

4.1 General 10
4.1.1 Phase One Study Area Determination 10
4.1.2 First Developed Use Determination 10
4.1.3 Fire Insurance Plans 10
4.1.4 Chain of Title 12
4.1.5 Environmental Reports 14

4.2 Environmental Source Information 15
4.2.1 ERIS Database Report 15
4.2.2 City Directories 16
4.2.3 Technical Standards and Safety Authority (TSSAs) 17
4.2.4 Ontario Ministry of Environment, Conservation and Parks (MECP) 18
4.2.5 Historic Land Use Inventory (HLUI) 18

4.3 Physical Setting Sources 19
4.3.1 Aerial Photographs 19
4.3.2 Topography, Hydrology and Geology 21
4.3.3 Fill Materials 23
4.3.4 Water Bodies, Areas of Natural Significance and Groundwater Information 23
4.3.5 Well Records 24

4.4 Site Operating Records 24

5.0 INTERVIEWS 26

6.0 SITE RECONNAISSANCE 26

6.1 General Requirements 26
6.2 Specific Observation at Site 26
6.2.1 Enhanced Investigation Property 30
6.2.2 Surrounding Land Use 31

6.3 Written Description of Investigation 31

7.0 REVIEW AND EVALUATION OF INFORMATION 32

7.1 Current and Past Uses 32
7.2 Potentially Contaminating Activity 38
7.3 Areas of Potential Environmental Concern 46
7.4 Phase One Conceptual Site Model 49
7.4.1 Uncertainty and Absence of Information 51

8.0 CONCLUSIONS 51

8.1 Whether Phase Two ESA Required Before RSC Submitted 51
8.2 RSC Based on Phase One ESA Alone 52

9.0 REFERENCES 53

10.0 LIMITATIONS AND USE OF REPORT 55

11.0 SIGNATURES 56

LIST OF APPENDICES

APPENDIX A	Figures
APPENDIX B	Qualifications of Assessors
APPENDIX C	Fire Insurance Records
APPENDIX D	Chain of Title
APPENDIX E	ERIS Report
APPENDIX F	City Directory Records
APPENDIX G	TSSA Records
APPENDIX H	FOI Records
APPENDIX I	Historic Land Use Inventory
APPENDIX J	Aerial Photographs
APPENDIX K	Site Photographs

2.0 INTRODUCTION

GEMTEC Consulting Engineers and Scientists Limited (GEMTEC) was retained by Performance Mazda Ottawa to carry out a Phase One Environmental Site Assessment (ESA) for the properties located at 1052, 1060, and 1064 St. Laurent Boulevard (collectively referred to as the Site) in Ottawa, Ontario. It is understood that the Phase One ESA is required to support a Record of Site Condition (RSC) for a proposed commercial/residential development at the Site.

The preliminary proposed development for the Site involves the construction of a mixed-use building spanning across the three land parcels that make up the Site. The proposed structure is expected to be approximately 30 storeys in height, with the ground level designated for commercial use and the upper levels consisting of residential units. The development will also include a three-storey underground parking garage. The following is known about the individual land parcels.

- 1052 St. Laurent Boulevard – This parcel is currently occupied by a two-storey building with a basement. The first level and basement are used by a pawn shop, while the second level is occupied by a computer shop and community centre;
- 1060 St. Laurent Boulevard – This parcel contains a one-storey building with a basement, which is currently occupied by a restaurant; and,
- 1064 St. Laurent Boulevard – This parcel is occupied by a one-storey building housing an automotive shop/garage.

The Site is developed with three structures, covers an approximate area of 0.88 acres and fronts along St. Laurent Boulevard. The location of the Site is provided on Figure A.1 in Appendix A with Site features shown in Figure A.2 in Appendix A.

This Phase One ESA was carried out in accordance with Ontario Regulation (O. Reg.) 153/04, as amended. The Site is considered an enhanced investigation property as defined by O. Reg. 153/04 due to the presence of an automotive shop/garage (‘Shore Automotive’) located at 1064 St. Laurent Boulevard.

The primary objective of this Phase One ESA is to identify and document current and historical environmental conditions and operations or practices at and in the vicinity of the Site that have the potential to impact soil and/or groundwater quality at the Site, and to determine if such operations or practices result in any Areas of Potential Environmental Concern (APECs) in association with the Site. The general objectives were met through the evaluation of the information gathered from the review of records, interviews, and a Site reconnaissance.

The Phase One ESA was conducted by GEMTEC staff members whose qualifications are provided in Appendix B.

2.1 Site Information

GEMTEC was retained by Performance Mazda Ottawa to conduct a Phase One ESA at the Site:

Information	Description
Municipal Address	1052 St. Laurent Boulevard, 1060 St. Laurent Boulevard, and 1064 St. Laurent Boulevard
Property Identification Number	04253-0270 (LT), 04253-0271 (LT), and 04253-0272 (LT)
Legal Description	1052 St. Laurent Boulevard: Pt Lt 1, Pl 79, As in OT74832 Except OT78524; Ottawa//Gloucester 1060 St. Laurent Boulevard: Pt Lts 1 & 2, Pl 79, As on OT63102; Ottawa/Gloucester 1064 St. Laurent Boulevard: Pt Lts 2, 3 & 4, Pl 79, As in NS57788 Except Pt 1, 5R11050; Ottawa/Gloucester

The contact information for the Site is:

Owner/Client	Address	Contact Information
Owner: Stan Bernard Automotive Limited Site Owner contact: Andrew Bernard and John McEwan	1469 Youville Drive, Orleans, Ontario K1C 4R1	Email: JMcEwan@performancemazda.com; abernard@performancemazda.com Phone Number: (613) 913-7845

3.0 SCOPE OF THE INVESTIGATION

3.1 General Objectives

The Phase One ESA was carried out in accordance with O. Reg. 153/04, as amended. The primary objective of the Phase One ESA is to identify any former, or current, operations or practices that may represent APECs with respect to the Site.

The general objectives were met through the evaluation of the information gathered from the review of records and available documents, interviews with relevant persons, and a Site reconnaissance.

3.2 Records Review

A review of information was conducted to identify actual or potential sources of contamination within the Phase One Study Area from the following sources:

- Fire Insurance Maps and Reports – Verisk was contacted and requested to search for fire insurance records. Relevant records, where available, were obtained for the Site and Phase One Study Area;

- Title Abstract – A chain of title (back to crown) for the Site was requested through Environmental Risk Information Services (ERIS);
- City Directories – A City Directory Report was requested through ERIS for the Site and surrounding streets within the Phase One Study Area;
- ERIS Databases – The ERIS report searches 74 public and private information databases to identify potential environmental concerns. An ERIS report was obtained for the Site and Phase One Study Area;
- Ministry of Environment, Conservation and Parks (MECP) - A Freedom of Information (FOI) request was submitted to the MECP for environmental records relating to the Site;
- Technical Standards and Safety Authority (TSSA) - A records search request was submitted to the TSSA for information relating to fuel storage at the Site and/or surrounding properties, where applicable;
- Aerial Photographs - Aerial photographs for various years were obtained from ERIS and reviewed on-line, where available. Aerial photos were reviewed for the Site and Phase One Study Area to identify APECs resulting from historical land uses on the Site and surrounding areas;
- Historic Land Use Inventory (HLUI) – HLUI was received from the City of Ottawa and was reviewed for the City and the Phase One Study Area;
- Bedrock and Overburden Geology Maps – Overburden and bedrock geology maps provided by Natural Resources Canada were reviewed to identify the underlying soil deposits and bedrock types; and,
- Well Records – The MECP Well Records website was searched for the Site and the Phase One Study Area. Any records obtained were reviewed for depth to groundwater and soil stratigraphy.

3.3 Interview

Interviews were conducted with Mr. Andrew Barnard, the current Site owner, on July 15, 2025, and with Mr. John McEwan, the Site contact, and Mr. Denis Shank, the Property Manager for the Site, on June 19, 2025.

3.4 Site Reconnaissance

The Site was visually assessed to document current conditions and to evaluate the potential for environmental impacts to on-Site soil and groundwater. Adjacent and neighbouring properties within the Phase One Study Area were assessed from publicly accessible boundaries to evaluate the potential for environmental impacts to the Site.

4.0 RECORDS REVIEW

4.1 General

4.1.1 Phase One Study Area Determination

For the purpose of this Phase One ESA, the Phase One Study Area is the area within a 250 m radius of the boundary of the Site. Based on GEMTEC's review of the historical and current information compiled as part of this Phase One ESA for the area surrounding the Site and observations of neighbouring properties made during the Site reconnaissance, it was concluded that an assessment of information pertaining to properties within 250 m of the boundary of the Site was sufficient to achieve the objectives of the Phase One ESA.

The Site and limits of the Phase One Study Area are provided on Figure A.1 in Appendix A.

4.1.2 First Developed Use Determination

Based on the review of the historical records (aerial photographs) obtained as part of this assessment, the Site appears undeveloped and vacant until 1933. Based on the 1945 aerial photograph (photo resolution is poor), the Site appears to be a part of a larger land parcel with a structure to the south of the southern Site boundary with a driveway (on-Site) from St. Laurent Boulevard. Based on this, the first developed use of the Site is sometime between 1933 and 1945.

4.1.3 Fire Insurance Plans

Fire insurance plans (FIPs), insurance reports and/or inspection reports were requested from Verisk and EnviroScan (Opta Information Intelligence) for the Site and surrounding properties. GEMTEC relied upon available FIPs, insurance reports and/or inspection reports from previous investigations conducted at the Site. A copy of the available FIPs, insurance reports, inspection reports and/or Siteplan report is provided in Appendix C.

The findings from FIPs are discussed below:

- Two gasoline service stations (or retail fuel outlets) were located across St. Laurent Boulevard equipped with three Underground Storage Tanks (USTs) each. The distance of these retail fuel outlets was at least 40 to 50 m from the eastern Site boundary.
- An additional retail fuel outlet was located to the south of the intersection of St. Laurent Boulevard and Cyrville Road with 4 USTs. The distance of this gasoline service station is at least 130 m from the Site boundary.

The findings from Insurance Reports are discussed below:

- All Risk Report – 2004 Milaur Automotive Ltd. O/A Midas Muffler 1064 St. Laurent Blvd Ottawa ON K1K2B4.
    - The building was occupied by a muffler repair shop and listed for mechanical repairs and oil changes. The building was constructed in 1970s.

    - No tanks were listed for heating fuel tanks.
    - The Site was listed for special hazards such as flammable liquids, hot work, solvent recycling, undercoating, and arts washing.
    - Information about two tanks were available which were present at the Site.
        - 1 x 803 litres (L) steel Aboveground Storage Tank (AST), for storage of new oil, was located inside the building.
        - 1 x 900 L steel AST, for storage of used oil, was located within the building.
- Multirisk Report – 1999 Centre Daccess Pour Femmes Inc 1052 St. Laurent Blvd Ottawa, Ontario K1K3B4, Reference Number 10684699.
    - The building was heated using natural gas and electrical baseboards.
- Construction, Occupancy, Protection, Exposure (COPE) Report – 1999 Manuel Desousa 1052 St Laurent Bl Ottawa Ontario K1K 3B4, Reference Number 10684699.
    - The building was constructed in 1969 and heated using central heat warm air gas.
- COPE Report – 1997 1052 1056 St. Laurent Blvd Ottawa Ontario K1K 3B4, Reference Number 10684699.
    - The building was constructed in 1969 and heated using central heat warm air gas.
- COPE Report – 1989 1052 1056 St. Laurent Blvd Ottawa Ontario K1K3B4, Reference Number 068469.
    - The building was constructed in 1970 and heated using oil fired hot air.
    - A former heating oil tank was noted at the Site in 1989 as part of a property underwriter report. No information regarding if the heating oil was stored in an AST or UST was available in the report.
- Commercial Property Fire Inspection Survey Form Report – 1983 1064 St. Laurent Blvd Ottawa Ontario K1K3B4.
    - The Site was owned by Performance Motors and the structure was heated using a gas-fired forced air furnace.
- Commercial Property Fire Rating Form Report – 1983 Performance Motors 1064 St. Laurent Blvd Ottawa ON K1K 3B4.
    - The report indicates the Site was owned by Performance Motors and the structure was heated using a gas-fired forced air furnace.
- Fire Inspection and Rate Calculation Form Report – 1981 1064 St. Laurent Blvd Ottawa Ontario K1K3B4.
    - The approximate age of the building was 20 years. The building was heated using a gas-fired forced air furnace.

Based on the above, the following Potentially Contaminating Activities (PCAs) were identified:

- PCA #27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles; and,
- PCA #28. Gasoline and Associated Products Storage in Fixed Tanks.

4.1.4 Chain of Title

A chain of title search from crown to present-day was obtained from ERIS and is included in Appendix D. The following are of note based on a review of the title abstracts going back to the mid 1800s which includes the first developed use:

Owners Name – 1052 St. Laurent Boulevard	Dates of Ownership
Crown	Before June 26, 1846
John Sharpe	June 26, 1846 to October 7, 1875
Frederick Sparks, Charles Wolff	October 7, 1875 to April 12, 1877
Esther S. Wolff	April 12, 1877 to March 23, 1922
James C.S. Wolff	March 23, 1922 to March 23, 1922
Charles A. Seguin	March 23, 1922 to March 23, 1931
Julien Lanthier	March 23, 1931 to October 5, 1937
Leopold CYR	October 5, 1937 to June 25, 1945
Noel Brault	June 25, 1945 to September 12, 1945
Louis Barthelette	September 12, 1945 to June 27, 1947
James H. Carson	June 27, 1947 to September 30, 1964
Hain Holdings Limited	September 30, 1964 to April 15, 1967
Manuel De Sousa	April 15, 1967 to June 22, 1997
Manuel De Sousa, Beatriz De Sousa	June 22, 1997 to November 8, 1999
Federal Superannuates National Association	November 8, 1999 to May 12, 2016
National Association of Federal Retirees (Name Change from Federal Superannuates National Association)	May 12, 2016 to May 17, 2016
2505531 Ontario Limited	May 17, 2016 to May 31, 2021
Stan Barnard Automotive Limited	May 31, 2021 to present

Owners Name – 1060 St. Laurent Boulevard	Dates of Ownership
Crown	Before June 26, 1846
John Sharpe	June 26, 1846 to October 7, 1875
Frederick Sparks, Charles Wolff	October 7, 1875 to April 12, 1877
Esther S. Wolff	April 12, 1877 to March 23, 1922
James C.S. Wolff	March 23, 1922 to March 23, 1922

Owners Name – 1060 St. Laurent Boulevard	Dates of Ownership
Charles A. Seguin	March 23, 1922 to March 23, 1931
Julien Lanthier	March 23, 1931 to October 5, 1937
Leopold CYR	October 5, 1937 to June 25, 1945
Noel Brault	June 25, 1945 to September 12, 1945
Louis Barthelette Jr.	September 12, 1945 to April 9, 1946
Louis Barthelette Sr.	April 9, 1946 to August 27, 1947
Raoul Leroux, Aurora Leroux	August 27, 1947 to October 29, 1964
Donald Eng, Gam Eng, Gam Eng – Estate	October 29, 1964 to October 19, 2004
Donald Eng	October 19, 2004 to October 29, 2004
2053943 Ontario Inc.	October 29, 2004 to November 15, 2019
2644545 Ontario Inc.	November 15, 2019 to October 18, 2021
Stan Barnard Automotive Limited	October 18, 2021 to present

Owners Name – 1064 St. Laurent Boulevard	Dates of Ownership
Crown	Before June 26, 1846
John Sharpe	June 26, 1846 to October 7, 1875
Frederick Sparks, Charles Wolff	October 7, 1875 to April 12, 1877
Esther S. Wolff	April 12, 1877 to March 23, 1922
James C.S. Wolff	March 23, 1922 to March 23, 1922
Charles A. Seguin	March 23, 1922 to March 23, 1931
Julien Lanthier	March 23, 1931 to October 5, 1937
Leopold CYR	October 5, 1937 to June 25, 1945
Noel Brault	June 25, 1945 to September 12, 1945
Louis Barthelette Jr.	September 12, 1945 to April 9, 1946
Louis Barthelette Sr.	April 9, 1946 to November 7, 1946
Alfred Barthelette	November 7, 1946 to September 25, 1958
Georgette Salkaly	September 25, 1958 to September 14, 1964
Ronald Taylor, Doanld Maclaurin	September 14, 1964 to September 6, 1966
A&W Drive-in of Canada Ltd.	September 6, 1966 to June 29, 1979
Stan Barnard Automotive Limited	June 29, 1979 to present

4.1.5 Environmental Reports

Several environmental reports (for the Site) were available for GEMTEC to review during the preparation of this Phase One ESA report.

- Supplemental Phase II Environmental Site Assessment, 1060 St. Laurent Boulevard, Ottawa, Ontario. Prepared by GEMTEC dated October 2024.
    - This Supplemental Phase II ESA is completed in general accordance with Canadian Standards Association (CSA) Z769-00 (R2023). It was conducted for due diligence purposes to delineate the impacts that were identified as part of the Phase I and Phase II Environmental Site Assessments completed by LRL Associates Limited in September 2019. A total of three boreholes (BH/MW24-1, BH/MW24-2 and BH24-3) were advanced at the Site with BH/MW24-1 and BH/MW24-2 as groundwater monitoring wells. The reported concentrations of the soil and groundwater samples submitted for analysis of a combination of Petroleum Hydrocarbons (PHCs), Polycyclic Aromatic Hydrocarbons (PAHs), Benzene, Toluene, Ethylbenzene, and Xylene (BTEX) and/or metals satisfied MECP Table 3 Site Condition Standards (SCS). GEMTEC concluded that the impacted soil was isolated in the vicinity of BH19-4 and should be addressed at the time of redevelopment of the land parcel.
- Phase I Environmental Site Assessment, 1064 St. Laurent Boulevard, Ottawa, Ontario. Prepared by GEMTEC dated September 2024.
    - The Phase I ESA was completed in accordance with CSA Group Z768-01 (R2022). Site reconnaissance identified the presence of ASTs (including work bench automotive tanks) along with floor drains and an oil-water separator in the automotive shop/garage. A Phase II ESA was recommended for the land parcel.
- Phase I Environmental Site Assessment, 1052 St. Laurent Boulevard, Ottawa, Ontario. Prepared by GEMTEC dated August 2024.
    - The Phase I ESA was completed in accordance with CSA Group Z768-01 (R2022), and no environmental concerns were noted for the land parcel.
- Phase I Environmental Site Assessment, 1052 St. Laurent Boulevard, Ottawa, Ontario. Prepared by McIntosh Perry dated April 2021.
    - The Phase I ESA was completed in accordance with CSA Z768-01 (R2016), and no environmental concerns were identified for the Site. The report also discussed the two pipes in the basement which were likely to be former vent and fill pipes from an AST (Pinchin, November 2015). The report also discussed the exceedances for lead and PHC F4 at 1060 St. Laurent Boulevard but were not considered a concern because of the relatively low mobility of lead and PHC F4 in soil, and the lack of any PHC F4 exceedances in groundwater.
- Phase I and Phase II Environmental Site Assessment, 1060 St. Laurent Boulevard, Ottawa, Ontario. Prepared by LRL Associates Limited dated September 2019.

- LRL Associates Limited conducted a Phase I ESA followed by a Phase II ESA. Four boreholes (with three monitoring wells) were advanced at the Site at strategic locations based on identified areas of concern (as part of the Phase I ESA).
- The soil and groundwater samples were submitted for Volatile Organic Compounds (VOCs), PHCs, Metals, and Polychlorinated Biphenyls (PCBs).
- The results of the soil samples were below MECP Table 3 SCS with the exceptions of PHC F4 and lead at BH19-4 (1.2 to 1.4 m bgs), detected at concentrations of 5,410 µg/g and 223 µg/g, above the applicable SCS of 3,300 µg/g and 120 µg/g, respectively. The source of the exceedance was unknown.
    - *GEMTEC noted that the LRL Phase II ESA conclusion section specifies that the PHC F4 and lead exceedances were located at BH19-2. Based on the laboratory chain of custody and LRL analytical tables, it appears that the exceedances were located at BH19-4.*
- The results of the groundwater samples were below MECP Table 3 SCS and the groundwater flow direction was towards the north.

- Phase I Environmental Site Assessment, 1052 St. Laurent Boulevard, Ottawa, Ontario. Prepared by Pinchin dated November 2015.
    - The Phase I ESA was completed in accordance with CSA Z768-01 (R2012). No environmental concerns were identified at the land parcel. The report indicated that the building was heated by an oil-fired forced air furnace. Two pipes (likely former vent pipe and former fill pipe) were identified in the basement which were likely associated with an AST in the basement of the building.

Based on the above, the following PCAs were identified:

- PCA #27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles;
- PCA #28. Gasoline and Associated Products Storage in Fixed Tanks; and,
- OT1. Area of Known Soil Contamination.

4.2 Environmental Source Information

4.2.1 ERIS Database Report

GEMTEC contacted ERIS to conduct a search of 74 public and private information databases for the Site and the Phase One Study Area. The complete ERIS report, including a list of databases searched, is provided in Appendix E. The listings of note for the Site and adjacent properties are provided in the table below:

Address/ Location	Distance from the Site	Company/ Name	Description
1110 St. Laurent Boulevard	50 m south	Firestone, Willy's Roll Off, Tomlinson Environmental Services Ltd.	Listed for garage, UST and several spills (in 1991 and 2012).
1116 St. Laurent Boulevard (also listed as 1110 St. Laurent Boulevard)	50 m south	Conseil Des Ecoles Catholiques De Langue	Generator Number: ON1285763. Listed for PCBs in 1995 to 2001.
1007 St. Laurent Boulevard	120 m north	Sunoco, M Ellis, 6151892 Canada Inc., Suncor Energy Products Partnership	Listed as a retail fuel outlet (with several USTs) and a fuel spill of 1,500 L in 1991 with confirmation of soil contamination.
1018 Cyrville Road	130 m southeast	Petro Canada, E Anne Brundige/Cathys Corner, 6151892 Canada Inc.	Listed as a retail fuel outlet with several USTs.
1045 St. Laurent Boulevard (also listed as 1021 St. Laurent Boulevard)	140 m east	One Stop Laundromat	Generator Number: ON1297600. Listed as a waste generator for halogenated solvents between 1992 and 1998.

The unplottable report summary was reviewed to determine if any of the records were located on the Site or within the Phase One Study Area. The entries were only located geographically by concession, lot number, or company. Due to the uncertainty related to the location of the entries, which could not be confirmed as being present within the Phase One Study Area, these activities were not summarized in this report.

Based on the above, the following Potentially Contaminating Activities (PCAs) were identified:

- PCA #28. Gasoline and Associated Products Storage in Fixed Tanks;
- PCA #37. Operation of Dry Cleaning Equipment (where chemicals are used); and,
- OT2. Listed for PCB Storage.

4.2.2 City Directories

A review of the city directories from 1950 to 2021 was completed for the Site and the surrounding properties. A summary of relevant information based on a review of the city directory information is provided in the table below. A copy of the city directory records is provided in Appendix F.

Civic Address	City Directory Information
Site (1052 St. Laurent Boulevard)	2021 – Howard's Pawn Shop and Mr. Gold Cash; 2006 to 2012 – Federal Superannuates National; 2000 – Trademark Leather; and 1971 to 1994 – De Sousa Upholstering.
Site (1060 St. Laurent Boulevard)	1993 to 2021 – Brother Wu Restaurant; and 1966 to 1987 – Moon Palace Tavern Restaurant.
Site (1064 St. Laurent Boulevard) – Also listed as 1070 St. Laurent Boulevard in City Directories	2000 to 2017 – Midas Auto SVC Experts; 1982 to 1993 – Performance Mazda Ottawa Inc.; 1971 to 1976 – A&W Canada; and 1966 – D&R Drive In Take-out Food.
1091 St. Laurent Boulevard	1981 to 1994 – Midas Muffler & Brake Shop; 1971 – Scott Service Station; and 1966 – Rolly Service Station.
1007 St. Laurent Boulevard – Also listed as 1035 St. Laurent Boulevard	2021 – Petro Canada; 2000 to 2017 – St. Laurent Sunoco; and 1971 to 1994 – John's Sunoco Service Station.
1110 St. Laurent Boulevard	2012 to 2021 – Mercedes Benz Canada Inc.; 2000 to 2012 – Ogilive Motors Ltd.; 1987 to 1994 – St. Laurent Tire and Auto Service; and 1971 to 1982 – Firestone Tire and Rubber Company of Canada.
1045 St. Laurent Boulevard	1987 to 1994 – One Stop Laundromat and Dry Cleaners; 1981 to 1982 – Brown's Cleaners; and 1971 to 1976 – Cleanorama Dry Cleaners and Laundry.
1018 Cyrville Road	1987 to 2021 – Petro Canada; 1981 to 1982 – Gulf Self Serve Gas Station; and 1971 to 1976 – Esso Gas Bar.
1061 St. Laurent Boulevard – Also listed at the land parcel of 1021 St. Laurent Boulevard	1966 – Thompson's Al Fina Service Station; and 1961 – Lavigne Service Station.

Based on the above, the following PCAs were identified:

- PCA #27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles;
- PCA #28. Gasoline and Associated Products Storage in Fixed Tanks; and,
- PCA #37. Operation of Dry-Cleaning Equipment (where chemicals are used).

4.2.3 Technical Standards and Safety Authority (TSSAs)

The TSSA was contacted for available records for properties listed below. The response indicated that there were no records available.

- 1012 St. Laurent Boulevard;
- 1052 St. Laurent Boulevard;

- 1054 St. Laurent Boulevard;
- 1056 St. Laurent Boulevard;
- 1060 St. Laurent Boulevard;
- 1064 St. Laurent Boulevard;
- 1076 St. Laurent Boulevard;
- 1021 St. Laurent Boulevard;
- 1091 St. Laurent Boulevard;
- 1099 St. Laurent Boulevard;
- 693 Alesther Street; and,
- 1021 Cyrville Road.

The civic address of 1021 St. Laurent Boulevard and 1021 Cyrville Road were listed for propane as asset class/inventory context. A copy of the search requests and the response from the TSSA are provided in Appendix G.

Based on the TSSA response, no PCAs were identified.

4.2.4 Ontario Ministry of Environment, Conservation and Parks (MECP)

A Freedom of Information request was submitted to the MECP for a search of environmental records relating to the Site. The response dated June 12, 2025, from the MECP indicated that there were no records available for the Site. A copy of the response is provided in Appendix H.

Based on the MECP response, no PCAs were identified.

4.2.5 Historic Land Use Inventory (HLUI)

A Historic Land Use Inventory (HLUI) request was requested from the City of Ottawa for a search of environmental records relating to the Site. A copy of the response, dated June 23, 2025, is provided in Appendix I and indicated the following:

Civic Address	City Directory Information
1099 St. Laurent Boulevard	Presence of a retail fuel outlet with USTs (based on FIPs from 1956).
1107 St. Laurent Boulevard	Presence of a retail fuel outlet with USTs (based on FIPs from 1956).
46 Cyrville Road	Presence of a retail fuel outlet with USTs (based on FIPs from 1956).
1091 St. Laurent Boulevard	Presence of a retail fuel outlet with USTs (based on aerial imagery from 1958 and pump island was removed sometime between 1965 and 1991).
1018 Cyrville Road	Presence of a retail fuel outlet with USTs (based on aerial imagery from 1958).

Civic Address	City Directory Information
1007 St. Laurent Boulevard	Presence of a retail fuel outlet with USTs (based on aerial imagery from 1999 and 2002).
1021 St. Laurent Boulevard (corrected address from 1061 St. Laurent Boulevard)	Presence of tanks. The tanks are associated with Lavigne Service Station, Giguere Service Station, and Scott's Service Station
997 St. Laurent Boulevard	Presence of retail fuel outlet with USTs (based on aerial imagery 1965 and 1976).
1021 St. Laurent Boulevard	Clean-O-Rama Drycleaners and Laundries, Brown Cleaners, and One Stop Laundromat and Dry Cleaners listed as a drycleaner (between 1970s to 1980s).
1110 St. Laurent Boulevard	Firestone Tire and Rubber Company of Canada, St. Laurent Tire and Auto Service, and Ogilive Motors Limited listed as a Service Station (between 1970s and 2000s).
1012 St. Laurent Boulevard	Brown Cleaners listed for laundries and cleaners (in 2012).
1064 St. Laurent Boulevard	Performance Motos Ottawa, Midas Auto Service Experts, and Stan Bernard Automotive Limited listed as automotive.
1076 St. Laurent Boulevard	Performance Motos listed as motor vehicle repair shop in 1980s.
557 Queen Mary Street	Listed for a fuel oil UST in 1959.

Based on the review of the HLUI, following PCAs were identified.

- PCA #27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles;
- PCA #28. Gasoline and Associated Products Storage in Fixed Tanks; and,
- PCA #37. Operation of Dry-Cleaning Equipment (where chemicals are used).

4.3 Physical Setting Sources

4.3.1 Aerial Photographs

Aerial photographs were provided to GEMTEC by ERIS and were obtained from various sources including the National Air Photo Library (NAPL), and Google Earth®. Aerials were selected for review considering suitable scale for analysis and coverage area. The earliest photograph obtained was from 1933. Observations made with respect to the reviewed aerial photographs are summarized in the table below:

Date	Photograph Source	Observations (Site)	Observations (Surrounding Properties)
1933	NAPL through ERIS	The Site was undeveloped and appeared to be part of a larger land parcel. The photo resolution was poor.	The Phase One Study Area was primarily agricultural interspersed with community use roadways. A structure was present to the south of the Site. Cyrville Road and St. Laurent Boulevard were constructed sometime before 1933.
1945	NAPL through ERIS	The photo resolution remained poor. However, the Site appeared to be developed (with a driveway from St. Laurent Boulevard) as part of the land parcel to the south of the Site.	Several developments were visible to the south of the Site along St. Laurent Boulevard and Cyrville Road.
1958	GeoOttawa	Two structures were present in the northern portion of the Site (at the land parcels of 1052 and 1060 St. Laurent Boulevard). The structures appear to be residential dwelling. The southern portion of the Site appear to be used as an open area with structure located to the south of the southern boundary of the Site. The photo resolution remained poor.	Two retail fuel outlets were observed to the east of St. Laurent Boulevard. A garage was also observed at the land parcel of 1021 St. Laurent Boulevard. The north and the west of the Phase One Study Area were primarily residential. Commercial dwellings were primarily present along St. Laurent Boulevard. A school was constructed at 557 Queen Mary Street between 1945 and 1958.
1965	GeoOttawa	The photo resolution improved. The structure layout in the northern portion of the Site remained same (at the land parcel of 1052 and 1060 St. Laurent Boulevard). The southern portion of the Site was developed with a structure (centrally located at 1064 St. Laurent Boulevard) with some ground disturbance seen to the south of the new developed structure.	No significant changes were noted within the Phase One Study Area. The north and the west of the Phase One Study Area were developed with residential dwellings.
1976	GeoOttawa	The photo resolution deteriorated. The two structures located in the northern portion of the Site (at 1052 St. Laurent Boulevard and 1060 St. Laurent Boulevard) were replaced with buildings that match the current footprint of the existing structures (in 2025). An addition to the building at 1064 St. Laurent Boulevard is also visible. It is likely that the land parcels of 1064 St. Laurent Boulevard and 1076 St. Laurent Boulevard were severed sometime	Cyrville Road was realigned, and the layout of the Phase One Study Area matched its current configuration (2025)

Date	Photograph Source	Observations (Site)	Observations (Surrounding Properties)
		between 1965 and 1976 considering the layout of the land parcels.	
1983	GeoOttawa	The photo resolution remained poor. No significant changes were noted to the Site.	No significant changes were noted for the Phase One Study Area.
1991	GeoOttawa	The photo resolution improved, and no significant changes were noted in the northern portion of the Site (land parcels of 1052 St. Laurent Boulevard and 1060 St. Laurent Bouelovard). The structure located in the southern portion of the Site (at 1064 St. Laurent Boulevard) was replaced with building that match the current footprint of the existing structure (in 2025). Cars were parked in the parking area to the east and the south of this structure.	No significant changes were noted for the Phase One Study Area.
2002	GeoOttawa	No significant changes were noted for the Site.	No significant changes were noted for the Phase One Study Area.
2011	GeoOttawa	No significant changes were noted for the Site.	No significant changes were noted for the Phase One Study Area.
2022	GeoOttawa	No significant changes were noted for the Site.	No significant changes were noted for the Phase One Study Area.

Aerial photographs provided by ERIS are included in Appendix I. Based on the above-noted aerial photograph review, the following PCAs were identified:

- PCA #27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles;
- PCA #28. Gasoline and Associated Products Storage in Fixed Tanks; and,
- PCA #30. Importation of Fill Material of Unknown Quality.

4.3.2 Topography, Hydrology and Geology

Topic	Description	Comment / Source
Topography of Site and Surrounding Area	The Site is at an elevation of between approximately 70 m above sea level (asl) as per Toporama. Based on previous investigations completed at the Site, the Site is at an elevation ranging between 64 m asl and 74 m asl. Based on topographic mapping, the Site is	Toporama, GEMTEC (2024), McIntosh Perry (2021), LRL

Topic	Description	Comment / Source
	relatively flat and generally at grade with St. Laurent Boulevard.	Associates (2019), and Pinchin (2015).
Overburden Soils	Fine textured glaciomarine deposits of silt and clay, minor sand and gravel. As per previous intrusive investigations at the Site, the native overburden consists of silty sand/ silt and sand with gravel underlain by clayey sand/sandy clay over till.	Ontario Geologic Survey, GEMTEC (2024), LRL Associates (2019).
Type of Bedrock	Shale, limestone, dolostone, siltstone of Georgian Bay Formation, Blue Mountain Formation, Billings Formation of Collingwood Member and Eastview Member. No bedrock was identified as part of previous intrusive investigations at the Site.	Ontario Geologic Survey.
Depth to Bedrock	Approximately 6 metres below ground surface (m bgs) based on the ERIS Report. As per Ontario Geologic Survey, the depth to bedrock is expected to be 3 to 10 m bgs. As per intrusive investigations at the Site, no bedrock was encountered. However, BH19-4 had inferred bedrock refusal at 1.73 m bgs as per Phase I and Phase II Environmental Site Assessment (LRL Associates, 2019).	ERIS Report, Ontario Geologic Survey, LRL Associates (2019).
Inferred Near Surface Groundwater Flow	The inferred direction of both local and regional groundwater flow is expected to be west/northwest as the Rideau River is located approximately 2.2 kilometres (km) west of the Site. As per intrusive investigations at the Site, the groundwater flow direction was reported to the north as per Phase I and Phase II Environmental Site Assessment (LRL Associates, 2019).	Google Earth, GeoOttawa, LRL Associates (2019).
Site Grade Relative to the Adjoining Properties	Based on topographic mapping and Google Earth, the Site appears to follow the topography of the area and is at grade to properties located adjacent to the Site.	Toporama, Google Earth
Depth to Groundwater	The depth to groundwater is expected to be approximately 1.74 to 2.83 m bgs.	MECP Water Well Records, GEMTEC (2024), LRL Associates (2019).

4.3.3 Fill Materials

Topic	Description	Comment / Source
Fill Materials	Based on the review of available aerial photographs and in the absence of documentation regarding any backfilling activities that may have taken place following demolition of former structures at the Site, there is a possibility that fill material maybe present at the Site.	Aerial photographs

Based on the above-noted discussion about fill materials, the following PCA was identified.

- PCA #30. Importation of Fill Material of Unknown Quality.

4.3.4 Water Bodies, Areas of Natural Significance and Groundwater Information

Topic	Description	Comment / Source
Nearest Open Water Body	Rideau River is located approximately 2.2 km of the west of the Site.	Google Earth, GeoOttawa
Areas of Natural and Scientific Interest ("ANSIs")	None identified.	
Provincial Parks or Conservation Reserves	None identified.	
Provincially Significant Wetlands or Designated Wilderness Areas	None identified.	
Environmentally Significant Areas per Municipal Official Plan(s)	None identified.	
Areas Designated Under the Niagara Escarpment Plan or the Oak Ridges Moraine Conservation Plan	Not applicable.	

Topic	Description	Comment / Source
Threatened or Endangered Species Habitat	A natural heritage report was not available for review.	
Wellhead Protection Areas	The Phase One Study Area is not located within a wellhead protection area or other area identified by the City of Ottawa in its official plan for the protection of groundwater.	
Municipal Drinking Water Distribution Systems	Considering the urban nature of the Phase One Study Area, it is likely that the wells, as listed in the database, are no longer in use and reflect the water supply conditions prior to the extensive urbanization of the Phase One Study Area that has occurred since approximately the late 1980s. The Site and surrounding properties are likely serviced by a municipal drinking water system, as defined under the Safe Drinking Water Act, 2002.	

4.3.5 Well Records

Topic	Description	Comment / Source
Wells (location, stratigraphy of the overburden, from ground surface to bedrock, depth to bedrock, depth to water table)	Based on a review of the MECP Well Records, three wells were identified at the Site (1060 St. Laurent Boulevard). The general soil stratigraphy at these wells were asphalt underlain by sand with gravel at depths ranging between 0.2 m bgs and 0.3 m bgs followed by clay/sand. No information was available about the depth to bedrock. The water level was encountered between 1.74 and 2.83 m bgs. Majority of the wells were located to the east of St. Laurent Boulevard. Their locations are shown on Figure A.1 in Appendix A.	MECP Water Well Records, GEMTEC (2024), LRL Associates (2019).

4.4 Site Operating Records

At the time of the Site reconnaissance, the Site was used for commercial purposes (including an automotive shop/garage). Based on the information reviewed as part of this Phase One ESA, the Site is an enhanced investigation property (refer to Section 6.2.1). The following information was available:

Topic	Description of the Information or Document	Information Relevant to the Phase One ESA
Regulatory Permits and Records	Not available	None
Materials Safety Data Sheets (MSDS)	Not available	None
Underground utility drawings	Not available	None
Inventory of ASTs and USTs	One double walled AST for used oil was reportedly at the Site. Three work bench automotive tanks were also reportedly present at the Site for the storage of engine oils.	Yes
Environmental monitoring data, including data created in response to an order or request of the Ministry	Not available	None
Waste management records, including current and historical waste storage location and waste receiver information maintained by the Ministry	Not available	None
Process, production and maintenance documents related to APECs	Not available	None
Records of spills and records of discharges of contaminants, including records of spills and records of discharges of contaminants of which notice is required to be given to the Ministry under the Act and records of such spills and discharges required to be kept pursuant to O. Reg. 675/98	No reported spills.	None
Emergency response and contingency plans, including spill prevention and contingency plans prepared pursuant to section 91.1 of the Act, and O. Reg. 224/07	Spill kits were present at the Site.	None
Environmental audit reports	Not available	None
A Site plan of the facility	Not available	None

5.0 INTERVIEWS

Interviews were conducted with Mr. Andrew Barnard, the current Site owner, on July 15, 2025, and with Mr. John McEwan, the Site contact, and Mr. Denis Shank, the Property Manager for the Site, on June 19, 2025.

Mr. Andrew Bernard, the current Site owner (hereinafter referred to as the “Site Representative”), responded to a detailed environmental questionnaire on July 15, 2025. Additionally, Mr. John McEwan, the Site contact, and Mr. Denis Shank, the Property Manager for the Site, were also interviewed on June 19, 2025, at the time of Site reconnaissance. Pursuant to the requirements O. Reg. 153/04, the Site Representative was interviewed as the “current owner” with knowledge of current Site operations. Relevant information obtained during the interview and Site reconnaissance, including that relating to PCAs and APECs, is provided in Section 6.0.

6.0 SITE RECONNAISSANCE

6.1 General Requirements

The Site reconnaissance was completed by Mr. Mohit Bhargav, M.Sc.E., P.Eng. of GEMTEC on June 19, 2025, from approximately 10:00 AM to 11:30 AM. The weather at the time of the Site reconnaissance was sunny and approximately 20 degrees Celsius.

The Site reconnaissance was completed to identify any PCAs associated with the current activities on the Site and/or surrounding properties.

At the time of the Site reconnaissance, the Site was developed with the following:

- 1052 St. Laurent Boulevard – This parcel is currently occupied by a two-storey building with a basement. The first level and basement are used by a pawn shop, while the second level is occupied by a computer shop and community centre;
- 1060 St. Laurent Boulevard – This parcel contains a one-storey building with a basement, which is currently occupied by a restaurant; and,
- 1064 St. Laurent Boulevard – This parcel is occupied by a one-storey building housing an automotive shop/garage.

The exterior area is primarily asphalt graded driveway and parking area. Photographs of the Site were taken during the Site reconnaissance to document the general condition of the Site and any PCAs. The relevant photographs are presented in Appendix J.

6.2 Specific Observation at Site

The following observations were made during the Site reconnaissance:

Topic	Observations	Source
Number and Age of Buildings on the Site	1052 St. Laurent Boulevard: Two-storey building with a basement. This structure was constructed sometime in 1960s. 1060 St. Laurent Boulevard: One-storey building with a basement. This structure was constructed sometime in 1960s. 1064 St. Laurent Boulevard: One-storey building housing an automotive shop/garage. No basement and was constructed sometime in 1980s.	Site representative, Site observation
General Descriptions of Each Building (including improvements)	1052 St. Laurent Boulevard: Two-storey building with a basement. The first level and basement are used by a pawn shop, while the second level is occupied by a computer shop and community centre. Brick structure with metal roof and concrete floor in the basement. 1060 St. Laurent Boulevard: One-storey building with a basement which is currently occupied by a restaurant. Brick structure with metal roof and concrete floor in the basement. 1064 St. Laurent Boulevard: One-storey building housing an automotive shop/garage. Brick structure with metal rood and slab on grade concrete floor with no basement.	Site representative, Site observation
Approximate Building Areas	1052 St. Laurent Boulevard: Approximately 220 ft^2 per floor totaling to 660 ft^2. 1060 St. Laurent Boulevard: Approximately 60 ft^2 per floor totaling to 120 ft^2. 1064 St. Laurent Boulevard: Approximately 500 ft^2.	Site representative, Site observation
Number of Floors Above Ground	1052 St. Laurent Boulevard: Two floors. 1060 St. Laurent Boulevard: One floor. 1064 St. Laurent Boulevard: One floor.	Site representative, Site observation
Number, Age, and Depth of Levels Below Ground Level	1052 St. Laurent Boulevard: One basement level since 1960s. Approximately 8 feet in depth. 1060 St. Laurent Boulevard: One basement level since 1960s. Approximately 8 feet in depth. 1064 St. Laurent Boulevard: No basement level.	Site representative, Site observation
Number and Details of all Aboveground Storage Tanks (ASTs)	GEMTEC Site assessor, Site contact, and Property Manager were accompanied by an independent contractor (Modern Niagara) to help evaluate the potential presence of a former oil tank for heating purposes at the Site. 1052 St. Laurent Boulevard: No ASTs were identified. However, two pipes (likely vent and fill pipes) in the basement were identified which were likely associated with a former AST. Same finding was discussed by GEMTEC (2024), McIntosh Perry (2021), and Pinchin (2015). 1060 St. Laurent Boulevard: No evidence of a former AST was noted for 1060 St. Laurent Boulevard. 1064 St. Laurent Boulevard: A total of 5 tanks were identified. One double walled AST for used oil was reportedly at the Site. Three work bench automotive tanks were also reportedly present at the Site for the storage of engine oils. All tanks were present along the	Site representative, Site observation

Topic	Observations	Source
	northern and the western Site boundary. No former ASTs were identified at the Site.	
Number and Details of all Underground Storage Tanks (USTs)	No USTs were observed or reported on the Site.	Site representative, Site observation
Underground Utilities Potable and Non-Potable Water Sources	The Site was municipally serviced for water.	Site representative
Utility Lines Present (i.e., Electrical, Natural Gas, other)	No utility drawings are available for the Site. However, based on Site representative, the Site is municipally serviced for natural gas, hydro, water and sewer.	Site representative, Site observation
Sanitary/Process Wastewater Receptor	None identified or reported.	Site observations, Site representative
Sanitary Sewer Connection	The Site is connected to the municipal sewer system.	Site representative, Site observation
Septic Systems	None identified or reported.	Site observations, Site representative
Storm Water Flow	Overland flow.	Site observations, Site representative
Storm Sewer Connection	None identified or reported.	Site observations, Site representative
Interior of Structures Entry and Exit Points for Site Buildings	1052 St. Laurent Boulevard: Entry and exit point for this structure is through the east and the west. 1060 St. Laurent Boulevard: Entry and exit point for this structure is through the east and the west. 1064 St. Laurent Boulevard: Entry and exit point for this structure is through the east and the south.	Site observations, Site representative
Existing and Former Heating System(s) (include fuel type / source)	1052 St. Laurent Boulevard: Currently natural gas and former heating source was oil. 1060 St. Laurent Boulevard: Currently natural gas and no information is available for the former heating source (if any). 1064 St. Laurent Boulevard: Currently natural gas and no information is available for the former heating source (if any).	Site representative
Existing and Former Cooling System(s) (include fuel type / source)	1052 St. Laurent Boulevard: Air conditioning with refrigerant. 1060 St. Laurent Boulevard: Air conditioning with refrigerant. 1064 St. Laurent Boulevard: Air conditioning with refrigerant.	Site observations, Site representative

Topic	Observations	Source
Drains, Pits, and Sumps (include current use, if any, and former use)	1052 St. Laurent Boulevard: A pit was identified in the basement and no signs of contamination (odours, staining, and/or sheen) were identified. 1060 St. Laurent Boulevard: A pit was identified in the basement and no signs of contamination (odours, staining, and/or sheen) were identified. 1064 St. Laurent Boulevard: Floor drains were identified in the automotive garage discharging into an oil water separator. No signs of contamination (odours, staining, and/or sheen) were identified.	Site observations, Site representative
Unidentified Substances	None identified.	Site observations
Floor Stains or Corrosion Located near a Potential Discharge Location	None identified.	Site observations, Site representative
Miscellaneous Exterior Location of any Current and Former Wells	Intrusive investigations have been completed for the Site, however, GEMTEC could not locate the monitoring wells advanced as part of the Phase I and Phase II Environmental Site Assessment (LRL Associates, 2019).	Site observations, Site representative
Ground Cover (i.e., grass, gravel, soil, or pavement, etc.)	The exterior area was primarily asphalt graded driveway and parking lot. Vegetation (such as trees and bushes) were primarily present along the Site boundaries to the north, the west, and the south.	Site observations, Site representative
Current or Former Railway Lines or Spurs	None identified.	Site observations, Site representative
Presence of Stained Soil, Vegetation, or Pavement	None observed.	Site observations
Presence of Stressed Vegetation	None observed.	Site observations
Areas Where Fill and/or Debris Materials Appear to Have Been Placed	The Site representative confirmed that no fill material was brought on the Site since their ownership.	Site observations, Site representative
Potentially Contaminating Activity	At the time of the Site visit, the following PCAs (based on O. Reg. 153/04, Table 2 – Potentially Contaminating Activities) were observed and/or reported: • PCA #27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles. • PCA #28. Gasoline and Associated Products Storage in Fixed Tanks. • OT3. Salt application for de-icing activities relating to vehicular traffic and pedestrian safety on-Site.	Site observations, Site representative

6.2.1 Enhanced Investigation Property

Based on the information reviewed as part of this Phase One ESA, the Site is considered an enhanced investigation property as defined by O. Reg. 153/04 due to the presence of an automotive shop/garage ('Shore Automotive') located at 1064 St. Laurent Boulevard.

Topic	Observations	Source
Operations at the property, including processing or manufacturing	The land parcel of 1064 St. Laurent Boulevard was used as an automotive shop/garage. No processing or manufacturing is done at the Site.	Site observation, Site representative
Hazardous materials used or stored at the Site	Chemicals such as engine oils etc. are stored at the Site in work bench tanks and AST. No spray paint work is done at the Site.	Site observation, Site representative
Products manufactured at the Site	None observed or reported.	Site observation, Site representative
By-products and wastes at the Site	Waste oil is stored in one of the ASTs. The contents of this AST are disposed of on an as-needed basis.	Site observation, Site representative
Raw materials handling and storage locations at the Site	None observed or reported.	Site observation, Site representative
Location and contents of drums, totes and bins at the Site	All the AST and the work bench tanks are located along the northern building line and the western building line of the structure. A tote of shop cloth was identified.	Site observation, Site representative
The location, installation date, source of incoming liquid and effluent discharge location for all oil-water separators	An oil water separator is centrally located within the building footprint of 1064 St. Laurent Boulevard. Floor drains are located along the southern and the eastern portion of the structure which discharges into the oil water separator. The oi water separator was reportedly installed in 2000s.	Site observation, Site representative

Topic	Observations	Source
All vehicle and equipment maintenance areas, including the locations of maintenance, fluid storage, and waste storage areas	Vehicle maintenance area is located along the southern and the eastern portions of the structure with hydraulic lifts. The inventory of supplies (including engine oils etc.) are located in the northern portion of the Site. Waste storage area (such as totes) are located within the automotive shop/garage and dumpsters are stored outside along the western Site boundary.	Site observation, Site representative
Details of all spills including the dates, locations, materials involved, and volumes of material spilled	None observed or reported.	Site observation, Site representative, ERIS
Details of liquid discharge points such as water and French drains, including their locations	Two floor drains within the automotive shop/garage discharge into the oil water separator.	Site observations, Site representative
Details of all hydraulic lift equipment at the property, including elevators, in-ground hoists and loading docks	The hydraulic lifts are located along the eastern and the southern portion of the structure along the bay doors.	Site observations, Site representative

6.2.2 Surrounding Land Use

During the Site reconnaissance, a visual reconnaissance of the outdoor operations in the Phase One Study Area was carried out from the Site and publicly accessible areas. The surrounding properties include residential, and commercial land uses, as illustrated in Figure A.1, in Appendix A.

North (down-gradient): Residential and commercial (primarily along St. Laurent Boulevard) interspersed with community use roadways.

East (cross-gradient): Primarily commercial.

West (cross-gradient): Primarily residential followed by institutional (at 557 Queen Mary Street).

South (up-gradient): Residential and commercial (primarily along St. Laurent Boulevard) interspersed with community use roadways.

6.3 Written Description of Investigation

At the time of the Site reconnaissance, the Site was developed with three structures. The Site reconnaissance was conducted by a GEMTEC Site assessor, accompanied by the Site contact,

Property Manager, and an independent contractor (Modern Niagara). The purpose included evaluating potential evidence of former oil tanks for heating at the Site.

1052 St. Laurent Boulevard was developed with a two-storey building including a basement. The ground floor and basement were occupied by a pawn shop, while the second floor was occupied by a computer shop and community centre. The structure was constructed sometime in 1960s. During the inspection, two pipes (interpreted as likely vent and fill pipes) were observed in the basement, suggesting the historical presence of an AST (in the basement) used for heating purposes. Although the AST had since been removed, the exact date of removal was unknown. The structure was fully serviced by municipal water, sewer, hydro, and natural gas.

1060 St. Laurent Boulevard was developed with a one-storey building with a basement and currently operates as a restaurant. The structure was constructed sometime in 1960s and was fully serviced by municipal water, sewer, hydro, and natural gas. No evidence of current and/or former ASTs or USTs was observed during the Site reconnaissance.

1064 St. Laurent Boulevard was developed with a one-storey automotive shop/garage. This structure was built in 1980s. This structure had concrete slab on grade with no basement. The concrete slab had floor drains that discharged into an oil water separator. Several ASTs and workbench storage tanks for engine oil were present along the northern and the western building line of this structure. No evidence for a former AST or UST was observed for 1064 St. Laurent Boulevard.

The exterior area is primarily asphalt graded driveway and parking area. The surrounding properties within the Phase One Study Area included commercial along St. Laurent Boulevard and primarily residential to the west of the Site.

The findings from the Site reconnaissance indicated the presence of PCAs contributing to APECs, as summarized below.

- PCA #27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles;
- PCA #28. Gasoline and Associated Products Storage in Fixed Tanks; and,
- OT3. Salt application for de-icing activities relating to vehicular traffic and pedestrian safety on-Site.

7.0 REVIEW AND EVALUATION OF INFORMATION

7.1 Current and Past Uses

Current and past uses of the Site since the date of first developed use are summarized in the table below:

Year	Owner – 1052 St. Laurent Boulevard	Property Use	Description of Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
Before June 26, 1846	Crown	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
June 26, 1846 to October 7, 1875	John Sharpe	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
October 7, 1875 to April 12, 1877	Frederick Sparks, Charles Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
April 12, 1877 to March 23, 1922	Esther S. Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1922 to March 23, 1922	James C.S. Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1922 to March 23, 1931	Charles A. Seguin	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1931 to October 5, 1937	Julien Lanthier	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel was undeveloped and appeared to be part of a larger land parcel.
October 5, 1937 to June 25, 1945	Leopold CYR	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel remained undeveloped.
June 25, 1945 to September 12, 1945	Noel Brault	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel remained undeveloped.
September 12, 1945 to June 27, 1947	Louis Barthelette	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel remained undeveloped. No aerial photograph or other records available between 1946 and 1947.
June 27, 1947 to September 30, 1964	James H. Carson	Residential	Residential	A structure was constructed at this land parcel and appeared to be a residential dwelling based on aerial photograph from 1958.

Year	Owner – 1052 St. Laurent Boulevard	Property Use	Description of Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
September 30, 1964 to April 15, 1967	Hain Holdings Limited	Residential	Residential	No changes noted compared to the aerial photograph from 1965.
April 15, 1967 to June 22, 1997	Manuel De Sousa	Commercial	Commercial	The former structure was replaced with a structure that matched the current footprint of the existing structure (in 2025). Based on earliest available insurance report (1989), this land parcel was used for commercial purposes.
June 22, 1997 to November 8, 1999	Manuel De Sousa, Beatriz De Sousa	Commercial	Commercial	No significant changes were noted at this land parcel.
November 8, 1999 to May 12, 2016	Federal Superannuates National Association	Commercial	Commercial	No significant changes were noted at this land parcel.
May 12, 2016 to May 17, 2016	National Association of Federal Retirees (Name Change from Federal Superannuates National Association)	Commercial	Commercial	No significant changes were noted at this land parcel.
May 17, 2016 to May 31, 2021	2505531 Ontario Limited	Commercial	Commercial	No significant changes were noted at this land parcel.
May 31, 2021 to present	Stan Barnard Automotive Limited	Commercial	Commercial	No significant changes were noted at this land parcel.

Year	Owner – 1060 St. Laurent Boulevard	Property Use	Description of Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
Before June 26, 1846	Crown	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.

Year	Owner – 1060 St. Laurent Boulevard	Property Use	Description of Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
June 26, 1846 to October 7, 1875	John Sharpe	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
October 7, 1875 to April 12, 1877	Frederick Sparks, Charles Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
April 12, 1877 to March 23, 1922	Esther S. Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1922 to March 23, 1922	James C.S. Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1922 to March 23, 1931	Charles A. Seguin	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1931 to October 5, 1937	Julien Lanthier	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel was undeveloped and appeared to be part of a larger land parcel.
October 5, 1937 to June 25, 1945	Leopold CYR	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel remained undeveloped.
June 25, 1945 to September 12, 1945	Noel Brault	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel remained undeveloped.
September 12, 1945 to April 9, 1946	Louis Barthelette Jr.	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel remained undeveloped. No aerial photograph or other records available for 1946.
April 9, 1946 to August 27, 1947	Louis Barthelette Sr.	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photograph or other records available between 1946 and 1947.
August 27, 1947 to October 29, 1964	Raoul Leroux, Aurora Leroux	Residential	Residential	A structure was constructed at this land parcel and appeared to be a residential dwelling based on aerial photograph from 1958.

Year	Owner – 1060 St. Laurent Boulevard	Property Use	Description of Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
October 29, 1964 to October 19, 2004	Donald Eng, Gam Eng, Gam Eng – Estate	Commercial	Commercial	The former structure was replaced with a structure that matched the current footprint of the existing structure (in 2025). Based on earliest available records (City Directories), this land parcel was used as a Moon Palace Tavern Restaurant (1966 to 1987).
October 19, 2004 to October 29, 2004	Donald Eng	Commercial	Commercial	No significant changes were noted at this land parcel.
October 29, 2004 to November 15, 2019	2053943 Ontario Inc.	Commercial	Commercial	No significant changes were noted at this land parcel.
November 15, 2019 to October 18, 2021	2644545 Ontario Inc.	Commercial	Commercial	No significant changes were noted at this land parcel.
October 18, 2021 to present	Stan Barnard Automotive Limited	Commercial	Commercial	No significant changes were noted at this land parcel.

Year	Owner – 1064 St. Laurent Boulevard	Property Use	Description of Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
Before June 26, 1846	Crown	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
June 26, 1846 to October 7, 1875	John Sharpe	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
October 7, 1875 to April 12, 1877	Frederick Sparks, Charles Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.

Year	Owner – 1064 St. Laurent Boulevard	Property Use	Description of Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
April 12, 1877 to March 23, 1922	Esther S. Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1922 to March 23, 1922	James C.S. Wolff	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1922 to March 23, 1931	Charles A. Seguin	Agricultural or Other Uses	Assumed undeveloped / agricultural	No aerial photographs were available prior to 1933.
March 23, 1931 to October 5, 1937	Julien Lanthier	Agricultural or Other Uses	Undeveloped / agricultural	This land parcel was undeveloped and appeared to be part of a larger land parcel.
October 5, 1937 to June 25, 1945	Leopold CYR	Residential	Residential	This land parcel appeared to be developed (with a driveway from St. Laurent Boulevard) as part of the land parcel to the south of this land parcel.
June 25, 1945 to September 12, 1945	Noel Brault	Residential	Residential	The Site appeared to be developed (with a driveway from St. Laurent Boulevard) as part of the land parcel to the south of this land parcel.
September 12, 1945 to April 9, 1946	Louis Barthelette Jr.	Residential	Residential	No aerial photograph or other records available between 1945 and 1946.
April 9, 1946 to November 7, 1946	Louis Barthelette Sr.	Residential	Residential	No aerial photograph or other records available for 1946.
November 7, 1946 to September 25, 1958	Alfred Barthelette	Residential	Residential	This land parcel was an open area for the structure located to the south of the southern boundary of the Site.
September 25, 1958 to	Georgette Salkaly	Residential	Residential	This land parcel was an open area for the

Year	Owner – 1064 St. Laurent Boulevard	Property Use	Description of Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
September 14, 1964				structure located to the south of the southern boundary of the Site.
September 14, 1964 to September 6, 1966	Ronald Taylor, Doanld Maclaurin	Residential	Residential	This land parcel was developed with a structure (centrally located with some ground disturbance seen to the south of the structure.
September 6, 1966 to June 29, 1979	A&W Drive-in of Canada Ltd.	Commercial	Commercial	An addition to the structure was visible fronting along St. Laurent Boulevard. It is likely that the land parcels of 1064 St. Laurent Boulevard and 1076 St. Laurent Boulevard were severed sometime between 1965 and 1976 considering the layout of the land parcels.
June 29, 1979 to present	Stan Barnard Automotive Limited	Commercial	Commercial	The former structure was replaced with a structure that matched the current footprint of the existing structure (in 2025). Cars were parked in the parking area to the east and the south of this structure. No changes to this land parcel since 1979.

7.2 Potentially Contaminating Activity

As per O. Reg. 153/04, a PCA means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred on the Site or in the Phase One Study Area. As per the regulation, a PCA located on the Site or in the Phase One Study Area may require the identification of an APEC. As per the regulation, an APEC means the area on, in or under the Site where one or more contaminants are potentially present, as determined through the identification of past or present uses on, in or under the Site and the identification of a PCA.

A summary of the identified PCAs and the rationale for the identification of PCAs as an APEC are provided in the table below. PCA locations are shown on Figure A.3 in Appendix A.

PCA Reference # on Figure A.3	Address/ Location	PCA ID	Distance from Site	Description	APEC Rationale
27-1	1064 St. Laurent Boulevard	#27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	On-Site	Presence of an automotive shop/garage since at least 1980s.	Yes On-Site PCA creates an APEC as per O.Reg. 153/04.
28-1	1052 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	On-Site	During the Site reconnaissance, two pipes (interpreted as likely vent and fill pipes) were observed in the basement, suggesting the historical presence of an AST (in the basement) used for heating purposes. Same findings were reported by GEMTEC (2024), McIntosh Perry (2021), and Pinchin (2015).	Yes On-Site PCA creates an APEC as per O.Reg. 153/04.
28-2	1064 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	On-Site	AST and work bench storage tanks for engine oils were present along the northern and the western building line of the structure.	Yes On-Site PCA creates an APEC as per O.Reg. 153/04.
30-1	1052 St. Laurent Boulevard	#30. Importation of Fill Material of Unknown Quality	On-Site	In the absence of documentation regarding any backfilling activities that may have taken place following demolition of former structures at the Site, there is a possibility that fill material maybe present at the Site.	Yes On-Site PCA creates an APEC as per O.Reg. 153/04.
30-2	1064 St. Laurent Boulevard	#30. Importation of Fill Material of Unknown Quality	On-Site	In the absence of documentation regarding any backfilling activities that may have taken place following demolition of former structures at the Site, there is a possibility that fill material maybe present at the Site.	Yes On-Site PCA creates an APEC as per O.Reg. 153/04.

PCA Reference # on Figure A.3	Address/ Location	PCA ID	Distance from Site	Description	APEC Rationale
OT1-1	1060 St. Laurent Boulevard	OT1. Area of Known Soil Contamination	On-Site	LRL completed a Phase I ESA and Phase II ESA (2019) for 1060 St. Laurent Boulevard. Exceedances of lead and PHC F4 were identified compared to MECP Table 3 SCS. GEMTEC (2024) advanced three boreholes installed with two monitoring wells. No soil and groundwater exceedances were identified indicating that the contaminated soil was localized in a small area (fronting along St. Laurent Boulevard).	Yes On-Site PCA creates an APEC as per O.Reg. 153/04.
27-2	1076 St. Laurent Boulevard	#27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	South adjacent	Based on review of the HLUI, a garage was present at 1076 St. Laurent Boulevard and 1064 St. Laurent Boulevard.	Yes Based on the distance from the Site and the groundwater flow direction (LRL Associates, 2019).
28-3	Not available	#28. Gasoline and Associated Products Storage in Fixed Tanks	50 m east across St. Laurent Boulevard	One retail fuel outlet was located across St. Laurent Boulevard equipped with three USTs.	No Based on the previous environmental investigation completed at 1060 St. Laurent Boulevard by LRL Associates (2019).
27-3	1091 St. Laurent Boulevard	#27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	50 m southeast across St. Laurent Boulevard	As per City Directories and HLUI, a service station was identified at this land parcel.	Yes Based on the distance from the Site, local topography (cross gradient), and groundwater flow

PCA Reference # on Figure A.3	Address/ Location	PCA ID	Distance from Site	Description	APEC Rationale
					direction (LRL Associates, 2019).
28-4	1091 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	50 m southeast across St. Laurent Boulevard	One retail fuel outlet was located across St. Laurent Boulevard equipped with three USTs.	Yes Based on the distance from the Site, local topography (cross gradient), and groundwater flow direction (LRL Associates, 2019).
28-5	1099 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	80 m southeast across St. Laurent Boulevard	One retail fuel outlet was located across St. Laurent Boulevard equipped with USTs as per HLUI.	Yes Based on the distance from the Site, local topography (cross gradient), and groundwater flow direction (LRL Associates, 2019).
27-4	1116 St. Laurent Boulevard	#27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	60 m south	Listed for garage/service station, UST and several spills (in 1991 and 2012).	Yes Based on the distance from the Site, local topography (up gradient), and groundwater flow direction (LRL Associates, 2019).
28-6	1116 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	60 m south	Listed for garage/service station, UST and several spills (in 1991 and 2012).	Yes Based on the distance from the Site, local topography (up gradient), and groundwater flow

PCA Reference # on Figure A.3	Address/ Location	PCA ID	Distance from Site	Description	APEC Rationale
					direction (LRL Associates, 2019).
OT3-1	1052 St. Laurent Boulevard, 1060 St. Laurent Boulevard, and 1064 St. Laurent Boulevard	OT3. Salt application for de-icing activities relating to vehicular traffic and pedestrian safety on-Site.	On-Site	Road salting is carried out during the winter both on-site and along St. Laurent Boulevard to ensure the safety of vehicular traffic and pedestrians.	Yes On-Site PCA creates an APEC as per O.Reg. 153/04.
OT3-2	St. Laurent Boulevard	OT3. Salt application for de-icing activities relating to vehicular traffic and pedestrian safety on-Site.	Site adjacent along St. Laurent Boulevard	Road salting is carried out during the winter both on-site and along St. Laurent Boulevard to ensure the safety of vehicular traffic and pedestrians.	Yes Based on the distance from the Site.
OT2-1	1116 St. Laurent Boulevard	OT2. Listed for PCB Storage.	60 m south	Listed for PCB Storage.	No Based on the mobility of contaminants (PCBs) in soil.
28-7	1018 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	150 m southeast	Listed as a retail fuel outlet with several USTs.	No Based on the distance from the Site.
37-1	1021 St. Laurent Boulevard	#37. Operation of Dry Cleaning Equipment (where chemicals are used)	75 m north	Listed as a historical dry cleaner as per HLUI.	No Based on the distance from the Site, local topography (down gradient), and groundwater flow direction (LRL Associates, 2019).

PCA Reference # on Figure A.3	Address/ Location	PCA ID	Distance from Site	Description	APEC Rationale
27-5	1045 St. Laurent Boulevard	#27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	140 m east	Listed a historical service station with tanks as per HLUI.	No Based on the distance from the Site, local topography (down gradient), and groundwater flow direction (LRL Associates, 2019).
28-8	1045 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	140 m east	Listed a historical service station with tanks as per HLUI.	No Based on the distance from the Site, local topography (down gradient), and groundwater flow direction (LRL Associates, 2019).
37-2	1045 St. Laurent Boulevard (also listed as 1021 St. Laurent Boulevard)	#37. Operation of Dry Cleaning Equipment (where chemicals are used)	140 m east	Listed as a historical dry cleaner as per City Directories and HLUI.	No Based on the distance from the Site, local topography (down gradient), and groundwater flow direction (LRL Associates, 2019).
28-9	1007 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	130 m north	Listed as a retail fuel outlet as per ERIS, HLUI, and City Directories.	No Based on the distance from the Site, local topography (down gradient), and groundwater flow

PCA Reference # on Figure A.3	Address/ Location	PCA ID	Distance from Site	Description	APEC Rationale
					direction (LRL Associates, 2019).
28-10	997 St. Laurent Bouelvard	#28. Gasoline and Associated Products Storage in Fixed Tanks	130 m north	Listed as a retail fuel outlet as per ERIS, HLUI, and City Directories.	No Based on the distance from the Site, local topography (down gradient), and groundwater flow direction (LRL Associates, 2019).
28-11	557 Queen Mary Stret	#28. Gasoline and Associated Products Storage in Fixed Tanks	90 m west	Listed for fuel oil UST in 1959 as per HLUI.	No Based on the distance from the Site, local topography (down gradient), and groundwater flow direction (LRL Associates, 2019).

7.3 Areas of Potential Environmental Concern

A summary of the APECs identified at the Site is provided in the table below. The APEC locations are presented in Figure A.4 in Appendix A. Contaminants of Potential Concern (COPCs) are specified using the method groups as identified in the MECP document "*Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act and Excess Soil Quality",* dated February 19, 2021.

Area of Potential Environmental Concern	Location of Area of Potential Environmental Concern on Site	Potentially Contaminating Activity	Location of PCA (on-Site or off Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, Soil and/or Sediment)
APEC 1 – Presence of a former AST	Northwest corner of structure at 1052 St. Laurent Boulevard	#28. Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, BTEX	Soil and Groundwater
APEC 2 – Area of known soil contamination	Southeast corner of 1060 St. Laurent Boulevard	OT1. Area of Known Soil Contamination	On-Site	Metals (Lead), PHCs	Soil
APEC 3 – Automotive Shop with ASTs and Oil Water Separator	Land parcel of 1064 St. Laurent Boulevard	#27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	On-Site	PHCs, VOCs, Metals, ORP, PAHs	Soil and Groundwater
APEC 4 – Presence of former retail fuel outlets and garages (off-Site and upgradient)	Southern and eastern portion of 1064 St. Laurent Boulevard	#27. Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles #28. Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs, VOCs, Metals, ORP, PAHs	Soil and Groundwater
APEC 5 – Likely present of fill material related to structures	Localized areas on 1052 St. Laurent Boulevard and 1064 St. Laurent Boulevard within the former building footprints.	#30. Importation of Fill Material of Unknown Quality	On-Site	PHCs, PAHs, BTEX, Metals, ORP	Soil
APEC 6 – Road salting activities during the winter months on-Site	Exterior area of the Site. Includes asphalt graded parking lots.	OT3. Salt application for de-icing activities relating to vehicular traffic and pedestrian safety on-Site.	On-Site	EC, SAR	Soil

Area of Potential Environmental Concern	Location of Area of Potential Environmental Concern on Site	Potentially Contaminating Activity	Location of PCA (on-Site or off Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, Soil and/or Sediment)
APEC 7 – Road salting activities during the winter months along St. Laurent Boulevard	Along the eastern Site boundary	OT3. Salt application for de-icing activities relating to vehicular traffic and pedestrian safety on-Site.	Off-Site	EC, SAR	Soil

Notes:
Metals – Metals parameters as per O. Reg. 153/04 including hydride forming metals (Antimony, Arsenic, Selenium)
ORP - Other Regulated Parameters including Electrical Conductivity (EC), Sodium Adsorption Ratio (SAR), pH, Hot Water Soluble Boron (B-HWS), Cyanide (CN-), Hexavalent Chromium (CrVI) and Mercury (Hg)
PHCs – Petroleum Hydrocarbon F1-F4
BTEX - Benzene, Toluene, Ethylbenzene, and Xylenes
VOCs – Volatile Organic Compounds
PAHs – Polycyclic Aromatic Hydrocarbons
EC – Electrical Conductivity
SAR – Sodium Adsorption Ratio

7.4 Phase One Conceptual Site Model

The following key features (as required by O. Reg. 153/04) are presented in Figures A.1, A.2, A.3 and A.4 in Appendix A:

- Existing buildings and structures;
- Water bodies and ANSIs located in the Phase One Study Area;
- Drinking water wells on the Site;
- Roads (including names) within the Phase One Study Area;
- Uses of properties adjacent to the Site; and,
- Location of identified PCAs in the Phase One Study Area (including any storage tanks).

The following describes the Phase One ESA Conceptual Site Model (CSM) based on the information obtained and reviewed as part of this Phase One ESA:

- The Site is developed with three structures, covers an approximate area of 0.88 acres and fronts along St. Laurent Boulevard;
- The Site reconnaissance was conducted by a GEMTEC Site assessor, accompanied by the Site contact, Property Manager, and an independent contractor (Modern Niagara). The purpose included evaluating potential evidence of former oil tanks for heating at the Site.
    - 1052 St. Laurent Boulevard was developed with a two-storey building including a basement. The ground floor and basement were occupied by a pawn shop, while the second floor was occupied by a computer shop and community centre. The structure was constructed sometime in 1960s. During the inspection, two pipes (interpreted as likely vent and fill pipes) were observed in the basement, suggesting the historical presence of an AST (in the basement) used for heating purposes. Although the AST had since been removed, the exact date of removal was unknown. The structure was fully serviced by municipal water, sewer, hydro, and natural gas.
    - 1060 St. Laurent Boulevard was developed with a one-storey building with a basement and currently operates as a restaurant. The structure was constructed sometime in 1960s and was fully serviced by municipal water, sewer, hydro, and natural gas. No evidence of current and/or former ASTs or USTs was observed during the Site reconnaissance.
    - 1064 St. Laurent Boulevard was developed with a one-storey automotive shop/garage. This structure was built in 1980s. This structure had concrete slab on grade with no basement. The concrete slab had floor drains that discharged into an oil water separator. Several ASTs and workbench storage tanks for engine oil were present along the northern and the western building line of this structure. No evidence for a former AST or UST was observed for 1064 St. Laurent Boulevard.

- The exterior area is primarily asphalt graded driveway and parking area. The surrounding properties within the Phase One Study Area included commercial along St. Laurent Boulevard and primarily residential to the west of the Site.
- Historically, the Site was vacant and undeveloped until approximately 1933. Based on the 1945 aerial photograph, the Site appears to be a part of a larger land parcel with a structure to the south of the southern Site boundary with a driveway (on-Site) from St. Laurent Boulevard. The former structures at 1052, 1060, and 1064 St. Laurent Boulevard were replaced with structures (in 1960s, 1960s, and 1980s respectively) that matched the current footprint of the existing structure (in 2025);
- The Site was serviced with municipal water, natural gas, hydro and municipal sewer. Based on the MECP Water Well Records, four wells were identified at the land parcel of 1060 St. Laurent Boulevard and were associated with investigations completed by LRL Associates (2019);
- The Site is at an elevation of between approximately 70 m asl as per Toporama. Based on previous investigations completed at the Site, the Site is at an elevation ranging between 64 m asl and 74 m asl. The Site is relatively flat and generally at grade with St. Laurent Boulevard;
- Surficial soil conditions are primarily characterized by fine textured glaciomarine deposits of silt and clay, minor sand and gravel. As per previous intrusive investigations at the Site, the overburden consists of silty sand/silt and sand with gravel underlain by clayey sand/sandy clay over till;
- Bedrock geology consists of shale, limestone, dolostone, siltstone of Georgian Bay Formation, Blue Mountain Formation, Billings Formation of Collingwood Member and Eastview Member. Bedrock was not identified as part of previous intrusive investigations at the Site and is expected to be approximately 6 m bgs based on the ERIS Report. As per Ontario Geologic Survey, the depth to bedrock is expected to be 3 to 10 m bgs;
- The depth to groundwater is expected to be approximately 1.74 to 2.83 m bgs based on review of on-Site wells from MECP Water Well Records, GEMTEC (2024), and LRL Associates (2019).
- The inferred direction of both local and regional groundwater flow is expected to be west/northwest as the Rideau River is located approximately 2.2 km west of the Site. As per intrusive investigation at the Site, the groundwater flow direction was reported to the north as per Phase I and Phase II Environmental Site Assessment (LRL Associates, 2019);
- No ANSIs were identified on the Site or within the Phase One Study Area;
- The closest surface water body was the Rideau River located approximately 2.2 km west of the Site;
- Based on available information, buried services are likely associated with hydro, municipal water, municipal sewer, and natural gas. Given their location and likely depth, these buried

services are not anticipated to influence the distribution of contamination, if any, at the Site.

- Based on the Phase One ESA findings, PCAs were identified resulting in the following APECs:
    - APEC 1 – Presence of a former AST located in the northwest corner of structure at 1052 St. Laurent Boulevard. COPCs include PHCs and BTEX with potential for impacts in soil and groundwater;
    - APEC 2 – Area of known soil contamination in southeast corner of 1060 St. Laurent Boulevard. COPCs include Metals (Lead), and PHCs in soil;
    - APEC 3 – Automotive Shop with ASTs and Oil Water Separator at 1060 St. Laurent Boulevard. COPCs include PHCs, VOCs, Metals (and Hydride Forming Metals), ORP, PAHs in soil and groundwater;
    - APEC 4 – Presence of former retail fuel outlets and garages (off-Site and upgradient) in the southern and the eastern portion of 1064 St. Laurent Boulevard. COPCs include PHCs, VOCs, Metals (and Hydride Forming Metals), ORP, and PAHs in soil and groundwater;
    - APEC 5 – Likely present of fill material related to structures at localized areas on 1052 St. Laurent Boulevard and 1064 St. Laurent Boulevard within the former building footprints. COPCs include PHCs, PAHs, BTEX, Metals (and Hydride Forming Metals), and ORP in soil;
    - APEC 6 – Road salting activities during the winter months on-Site. COPCs include Electrical Conductivity (EC) and Sodium Adsorption Ratio (SAR) in soil; and,
    - APEC 7 – Road salting activities during the winter months along St. Laurent Boulevard. COPCs include EC and SAR in soil.

7.4.1 Uncertainty and Absence of Information

There are no material deviations to the Phase One ESA requirements set out in O. Reg. 153/04 that would cause uncertainty or absence of information that would affect the validity of the Phase One ESA CSM or the findings of this Phase One ESA.

8.0 CONCLUSIONS

8.1 Whether Phase Two ESA Required Before RSC Submitted

Based on the information obtained and reviewed as part of this Phase One ESA which is considered as fulfilling the specific objectives and requirements of Parts II through V of Schedule D to O. Reg. 15/304, five APECs were identified at the Site. Based on the findings of this report, a Phase Two ESA is recommended to confirm the presence of absence of COPCs within the APECs. A Phase Two ESA would be required to support an RSC filing.

8.2 RSC Based on Phase One ESA Alone

Given the identification of APECs associated with the Site, an RSC cannot be filed based on the Phase One ESA alone.

9.0 REFERENCES

Aerial Photographs for the years 1933, 1945, and 1983 – obtained by ERIS on May 17, 2024 and June 9, 2025.

City Directories, obtained by ERIS – June 14, 2024.

Chain of Titles – requested by ERIS – June 20, 2025.

ERIS Database Report, obtained by ERIS – May 30, 2025.

MECP FOI A-2025-03276 Record release letter – June 12, 2025.

Ministry of Natural Resources. 2014. Make a natural heritage area map. Accessed: July 2025.

Ontario Geological Survey 2010. Surficial geology of Southern Ontario; Ontario Geological Survey, Miscellaneous Release--Data 128-Revision 1.

Ontario Geological Survey 2011. 1:250,000 scale bedrock geology of Ontario; Ontario Geological Survey, Miscellaneous Release---Data 126-Revision 1.

Ontario Ministry of the Environment. Ontario Regulation 153/04, Made under the Environmental Protection Act, Part XV.1 – Records of Site Condition.

Opta Information Intelligence Enviroscan. Order No. 24053100242 – June 6, 2024.

Opta Information Intelligence Enviroscan. Order No. 21033100146 – April 7, 2021.

Phase I Environmental Site Assessment, 1064 St. Laurent Boulevard, Ottawa, Ontario. Prepared by GEMTEC dated September 2024.

Phase I Environmental Site Assessment, 1052 St. Laurent Boulevard, Ottawa, Ontario. Prepared by GEMTEC dated August 2024.

Phase I Environmental Site Assessment, 1052 St. Laurent Boulevard, Ottawa, Ontario. Prepared by McIntosh Perry dated April 2021.

Phase I and Phase II Environmental Site Assessment, 1060 St. Laurent Boulevard, Ottawa, Ontario. Prepared by LRL Associates Limited dated September 2019.

Phase I Environmental Site Assessment, 1052 St. Laurent Boulevard, Ottawa, Ontario. Prepared by Pinchin dated November 2015.

Supplemental Phase II Environmental Site Assessment, 1060 St. Laurent Boulevard, Ottawa, Ontario. Prepared by GEMTEC dated October 2024.

TSSA response on July 31, 2025 and June 25, 2024.

Toporama Atlas of Canada – Accessed July 2025.

Verisk Enviroscan Report, obtained by ERIS – June 12, 2025.

10.0 LIMITATIONS AND USE OF REPORT

This report was prepared for the exclusive use of Performance Mazda Ottawa and is based on data and information collected during the Phase One ESA of the Site conducted by GEMTEC. This report may not be relied upon by any other person or entity without the express written consent of GEMTEC and Performance Mazda Ottawa. In evaluating this Site, GEMTEC has relied in good faith on information provided by others. We accept no responsibility for any deficiencies or inaccuracies in this report as a result of omissions, misinterpretations, or fraudulent acts of others. GEMTEC disclaims any responsibility of consequential financial effects on transactions or property values, or requirements for follow-up actions and costs.

The scope and the period of GEMTEC's assessment are described in this Report, and are subject to restrictions, assumptions and limitations. Except as noted herein, the work was conducted in accordance with the scope of work and terms and conditions within GEMTEC's proposal. Distances noted in this report were determined using mapping data of variable accuracy and should therefore be considered approximate. GEMTEC did not perform a complete assessment of all possible conditions or circumstances that may exist at the Site referenced in the report. Conditions may therefore exist which were not detected given the limited nature of the assessment GEMTEC was retained to undertake with respect to the Site and additional environmental studies and actions may be required. In addition, it is recognized that the passage of time affects the information provided in the report. It is understood that the services provided for in the scope of work allowed GEMTEC to form no more than an opinion of the actual conditions at the Site at the time of the Site visit and cannot be used to assess the effect of any subsequent changes in any laws or regulations and the environmental quality of the Site or its surroundings. Asbestos and mould surveys were not performed. If a service is not expressly indicated, do not assume it has been provided. The conclusions provided herein represent the best judgment of GEMTEC based on current environmental standards. Due to the nature of the investigation and the limited data available, we cannot warrant against undiscovered environmental liabilities.

The scope of the Phase One ESA is sufficient to identify existing and/or potential environmental liabilities that are obvious from visual examination of surface features and from available sources of information. This level of work is a method of risk reduction, not risk elimination. No building materials, water, liquid, gas, products or chemical sampling and/or testing on or in the vicinity of the Site was carried out as part of this assessment. The Phase One ESA does not include a program of intrusive observation/testing. These activities would be carried out as part of a Phase Two ESA. This environmental assessment included only a cursory overview of the neighbouring land uses from public right of ways and from the Site and does not constitute a complete assessment of the adjacent sites.

11.0 SIGNATURES

The undersigned Qualified Person confirms that the Phase One ESA was conducted and/or supervised by the Qualified Person and that all findings and conclusions of the Phase One ESA are included in the report.

We trust this report provides sufficient information for your present purposes. If you have any questions concerning this report, please do not hesitate to contact our office.

Regards,

GEMTEC Consulting Engineers and Scientists Limited

Mohit Bhargav, M.Sc.E., P.Eng.
Environmental Engineer

Daniel Elliot, P.Geo., QP_{ESA}
Senior Environmental Geoscientist

January 7, 2026

APPENDIX A

Figures

DONALD STREET
ST LAURENT BOULEVARD
WOLFFDALE CRESCENT
ALESTHER STREET
QUEEN MARY STREET
PRINCE ALBERT STREET
COVENTRY ROAD
CYRVILLE ROAD
INNES ROAD
COMMERCIAL
RESIDENTIAL
INSTITUTIONAL
70

KEY PLAN
1 : 25,000



LEGEND

- MECP PUBLIC WELL RECORD
- PHASE ONE PROPERTY BOUNDARY
- PHASE ONE STUDY AREA (250 m RADIUS AROUND PHASE ONE PROPERTY BOUNDARY)
- GROUND SURFACE CONTOUR
- WATERCOURSE

DATA SOURCES AND REFERENCES

1. Coordinate system: CSRS.UTM-18N
2. Distances, elevations, and coordinates are shown in metres unless denoted otherwise
3. This drawing is a schematic representation and should not be taken as a substitute for a legal survey.
4. Image @2025 Google Maps, CNES / Airbus, First Base Solutions, Maxar Technologies
5. Contains information licensed under the Open Government Licence – Ontario
6. Geographic dataset source: Ontario GeoHub

SCALE
1:2,500
0 50 100 150m

DRAWING
SITE AND
PHASE ONE STUDY AREA

CLIENT
PERFORMANCE MAZDA OTTAWA

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
1052, 1060, AND 1064 ST. LAURENT BOULEVARD
OTTAWA, ONTARIO

DRAWN BY	CHECKED BY
SL / MY	MB / DE
PROJECT NO. 103499.002	REVISION NO. 0
DATE AUGUST 2025	FIGURE NO. **FIGURE A.1**

GEMTEC
CONSULTING ENGINEERS AND SCIENTISTS
32 Steacie Drive
Ottawa, ON, K2K 2A9
Tel: (613) 836-1422
www.gemtec.ca
ottawa@gemtec.ca

N:\PROJECTS\103400\103499.002\06_CIVIL DRAFTING\ESA ONE R0\103499.002_ESA_ONE_R0_2025_08.DWG

LEGEND

- PHASE ONE PROPERTY BOUNDARY
- FORMER BUILDING STRUCTURE (1965)
- FORMER BUILDING STRUCTURE (1976)
- BOREHOLE LOCATION (Previous Investigation by GEMTEC, 2024)
- BOREHOLE LOCATION (Previous Investigation by LRL Associates, 2019)
- BOREHOLE LOCATION (Previous Investigation by LRL Associates, 2019)

DATA SOURCES AND REFERENCES

1. Coordinate system: CSRS.UTM-18N
2. Distances, elevations, and coordinates are shown in metres unless denoted otherwise
3. This drawing is a schematic representation and should not be taken as a substitute for a legal survey.
4. Image @2025 Google Maps, CNES / Airbus, First Base Solutions, Maxar Technologies
5. Contains information licensed under the Open Government Licence – Ontario
6. Geographic dataset source: Ontario GeoHub

SCALE 1:2,500

0 50 100 150m

DRAWING
SITE FEATURES

CLIENT
PERFORMANCE MAZDA OTTAWA

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
1052, 1060, AND 1064 ST. LAURENT BOULEVARD
OTTAWA, ONTARIO

DRAWN BY	CHECKED BY
SL / MY	MB / DE
PROJECT NO. 103499.002	REVISION NO. 0
DATE AUGUST 2025	FIGURE NO. **FIGURE A.2**

GEMTEC
Consulting Engineers and Scientists
32 Steacie Drive
Ottawa, ON, K2K 2A9
Tel: (613) 836-1422
www.gemtec.ca
ottawa@gemtec.ca

N:\PROJECTS\103400\103499.002\06_CIVIL DRAFTING\ESA ONE R0\103499.002_ESA_ONE_R0_2025_08.DWG

LEGEND

- PCA# — PCA CONTRIBUTING TO AN APEC
- PCA# — PCA NOT CONTRIBUTING TO AN APEC
- PHASE ONE PROPERTY BOUNDARY
- PHASE ONE STUDY AREA (250 m RADIUS AROUND PHASE ONE PROPERTY BOUNDARY)

PCA ID	Description
PCA # 27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles
PCA # 28	Gasoline and Associated Products Storage in Fixed Tanks
PCA # 30	Importation of Fill Material of Unknown Quality
PCA # 37	Operation of Dry Cleaning Equipment (where chemicals are used)
OT1	Area of known soil contamination
OT2	Listed for PCB Storage
OT3	Road salting activities during winter months

DATA SOURCES AND REFERENCES

1. Coordinate system: CSRS.UTM-18N
2. Distances, elevations, and coordinates are shown in metres unless denoted otherwise
3. This drawing is a schematic representation and should not be taken as a substitute for a legal survey.
4. Image @2025 Google Maps, CNES / Airbus, First Base Solutions, Maxar Technologies
5. Contains information licensed under the Open Government Licence – Ontario
6. Geographic dataset source: Ontario GeoHub

SCALE 1:2,500

0 50 100 150m

DRAWING
POTENTIALLY CONTAMINATING ACTIVITIES

CLIENT
PERFORMANCE MAZDA OTTAWA

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
1052, 1060, AND 1064 ST. LAURENT BOULEVARD
OTTAWA, ONTARIO

DRAWN BY	CHECKED BY
SL / MY	MB / DE
PROJECT NO. 103499.002	REVISION NO. 0
DATE AUGUST 2025	FIGURE NO. **FIGURE A.3**

GEMTEC
Consulting Engineers and Scientists
32 Steacie Drive
Ottawa, ON, K2K 2A9
Tel: (613) 836-1422
www.gemtec.ca
ottawa@gemtec.ca

N:\PROJECTS\103400\103499.002\06_CIVIL DRAFTING\ESA ONE R0\103499.002_ESA_ONE_R0_2025_08.DWG

LEGEND

PHASE ONE PROPERTY BOUNDARY

APEC #1	AREAS OF POTENTIAL ENVIRONMENTAL CONCERN
APEC 1	Presence of a former AST
APEC 2	Area of known soil contamination
APEC 3	Automotive Shop with ASTs and Oil Water Separator
APEC 4	Presence of former retail fuel outlets and garages (off-site and upgradient)
APEC 5	Likely presence of fill material related to former structures.
APEC 6	Road salting activities during the winter months on-Site.
APEC 7	Road salting activities during the winter months along St. Laurent Boulevard.

DATA SOURCES AND REFERENCES

1. Coordinate system: CSRS.UTM-18N
2. Distances, elevations, and coordinates are shown in metres unless denoted otherwise
3. This drawing is a schematic representation and should not be taken as a substitute for a legal survey.
4. Image @2025 Google Maps, CNES / Airbus, First Base Solutions, Maxar Technologies
5. Contains information licensed under the Open Government Licence – Ontario
6. Geographic dataset source: Ontario GeoHub

SCALE 1:2,500

0 50 100 150m

DRAWING
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

CLIENT
PERFORMANCE MAZDA OTTAWA

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
1052, 1060, AND 1064 ST. LAURENT BOULEVARD
OTTAWA, ONTARIO

DRAWN BY	CHECKED BY
SL / MY	MB / DE
PROJECT NO. 103499.002	REVISION NO. 0
DATE AUGUST 2025	FIGURE NO. **FIGURE A.4**

GEMTEC
Consulting Engineers and Scientists
32 Steacie Drive
Ottawa, ON, K2K 2A9
Tel: (613) 836-1422
www.gemtec.ca
ottawa@gemtec.ca

N:\PROJECTS\103400\103499.002\06_CIVIL DRAFTING\ESA ONE R0\103499.002_ESA_ONE_R0_2025_08.DWG

APPENDIX B

Qualifications of Assessors

GEMTEC Consulting Engineers and Scientists Limited
32 Steacie Drive
Ottawa, ON, Canada
K2K 2A9
613.836.1422
ottawa@gemtec.ca
www.gemtec.ca

QUALIFICATION OF ASSESSORS

Mohit Bhargav, M.Sc.E., P.Eng. – Environmental Engineer

The primary assessor for this Phase One Environmental Site Assessment (ESA) was Mr. Mohit Bhargav, Environmental Scientist with GEMTEC. Mohit has Master of Science Civil Engineering with a specialization in water/wastewater treatment. Mr. Bhargav's formal education and work experience in environmental consulting with GEMTEC has provided him with the knowledge and expertise to identify sources of environmental concern and evaluate their potential to cause adverse environmental impacts.

Daniel Elliot, B.Sc., P.Geo., QP_{ESA} – Senior Environmental Geoscientist

The Phase One ESA was carried out under the oversight of Mr. Daniel Elliot. Daniel has 14 years of experience in the environmental sector in jurisdictions across Canada and the Unites States. His early career with the Morwick G360 Groundwater Research Institute saw him carrying out research projects developing and using cutting edge techniques and technology. Since moving into consulting, he has gained extensive experience providing various environmental services including Phase One and Two Environmental Site Assessments, contaminant and hydrogeological site characterization, remedial planning, and implementation; risk assessment; filing of Records of Site Conditions; compliance and contract support; and waste and excess soil characterization/management. Daniel is a practicing member of the Association of Professional Geoscientists of Ontario and is a "qualified person" under Ontario Regulation 153/04 and Ontario Regulation 406/19.

APPENDIX C

Fire Insurance Records

opta
INFORMATION INTELLIGENCE

enviroscan

An SCM Company

175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

T: 905-882-6300
W: www.optaintel.ca

Report Completed By:

Stephanie

Site Address:

1052 St. Laurent Boulevard Ottawa ON

Project No:

21033100146

Opta Order ID:

88367

Requested by:

Eleanor Goolab
Ecolog Eris

Date Completed:

4/7/2021 1:36:37 PM

Project Name: Phase I ESA
1052 St. Laurent Blvd

Project #: 21033100146

ENVIROSCAN Report

Search Area: 1052 St. Laurent Boulevard Ottawa ON

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

enviroscan
OPTA INFORMATION INTELLIGENCE



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Opta Historical Environmental Services Enviroscan™ Terms and Conditions

Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Opta's records relating to the described property (hereinafter referred to as the "Property"). Opta makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Opta's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Opta does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

Disclaimer

Opta disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Opta Reports or from any tortious acts or omissions of Opta's agents, employees or representatives.

Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.

Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

ENVIROSCAN Report

Report Index

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

enviroscan
OPTA INFORMATION INTELLIGENCE

Page **Report Title**

6 (1958) Volume: Ottawa Volume 2 Firemap: 255
8 (1958) Volume: Ottawa Volume 2 Firemap: 256
9 (1999) COPE Report - 1999 MANUEL DESOUSA 1052 ST LAURENT BL OTTAWA ON K1K 3B4 Reference No: 10684699 (distance = 19 metres*)
12 (1997) Cope Report - 1997 1052 1056 St. Laurent Blvd Ottawa ON K1K3B4 (distance = 0 metres*)
19 (1989) Cope Report - 1989 1052 1056 St. Laurent Blvd Ottawa ON K1K3B4 (distance = 0 metres*)
25 (1999) Multirisk Report - 1999 CENTRE DACCESS POUR FEMMES INC 1052 St. Laurent Blvd Ottawa ON K1K3B4 (distance = 0 metres*)

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

Project Name: Phase I ESA
1052 St. Laurent Blvd

Project #: 21033100146

ENVIROSCAN Report

1958 Volume: Ottawa 2 Firemap: 255
Ottawa Volume 2 Plan: 1448 (1956)
Sheet: 255 (1958)

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map

The detailed FIP is on the following page



ENVIROSCAN Report

1958 Volume: Ottawa 2 Firemap: 255
Ottawa Volume 2 Plan: 1448 (1956)
Sheet: 255 (1958)

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

OPTA INFORMATION INTELLIGENCE



Project Name: Phase I ESA
1052 St. Laurent Blvd

Project #: 21033100146

ENVIROSCAN Report

1958 Volume: Ottawa 2 Firemap: 256
Ottawa Volume 2 Plan: 1448 (1956)
Sheet: 256 (1958)

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map

The detailed FIP is on the following page



ENVIROSCAN Report

1958 Volume: Ottawa 2 Firemap: 256
Ottawa Volume 2 Plan: 1448 (1956)
Sheet: 256 (1958)

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

OPTA INFORMATION INTELLIGENCE



This plan is the property of the UNDERWRITERS' SURVEY BUREAU, LIMITED, (unauthorized reproduction prohibited) and is issued on the following conditions: that the plan is to be kept in good order, that it is to be used only in connection with business of Companies, Members of the Canadian Underwriters' Association and is to be returned on request to the UNDERWRITERS' SURVEY BUREAU, LIMITED, Toronto and Montreal.

COPYRIGHT REGISTERED AT OTTAWA
BY THE
UNDERWRITERS' SURVEY BUREAU, LIMITED
TORONTO AND MONTREAL

ENVIROSCAN Report

COPE Report - 1999 MANUEL DESOUSA 1052 ST LAURENT BL OTTAWA ON K1K 3B4 Reference No: 10684699

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10684699

1999

INSURERS' ADVISORY ORGANIZATION 2008-Nov-17
CONFIDENTIAL - FOR USE OF MEMBERS ONLY 13:07 [Mon]
NOT FOR GENERAL DISTRIBUTION

COPE (Construction, Occupancy, Protection, Exposure) REPORT

Risk: MANUEL DESOUSA
1052 (1052 ST. LAURENT BL
OTTAWA ON
K1K 3B4

Reference No. 10684699 / Building No. 01 ENTIRE BUILDING

(Surveyed By BRIAN YOUNG on 99.03.25)

Please note that the information contained in this report was gathered during a physical inspection of the risk by an IAO Loss Control Representative.

If you wish to obtain building or contents rates for this risk, please refer to the Rate Card in the list of products available for this risk. Please call the IAO Help Desk or your local IAO Representative for help in obtaining a rate for this risk, or do it yourself by going to www.iao.ca and using the New X-rate to generate a new rate yourself.

IAO reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from an inspection of the premises and/or from data supplied by or on behalf of the Purchaser. IAO does not purport to list all hazards. While changes and modifications referred to in the reports are designed to upgrade protection and loss prevention of the premises, IAO assumes no responsibility for management and control of these activities. IAO will not be responsible to the Purchaser for any loss or damages, whether consequential or other, however caused, incurred or suffered, as a result of the service being provided.

------ CODING ------

Industry Code:	249 - Woodmakers excl. Sawmills - Wood Products Mfg., Wo
Construction Code:	2 - Non-Combustible / Masonry Walls
Risk Classification:	NS - Non-Sprinklered
Protection Code:	2 - Non-Sprinklered, Fully Protected, Gr 3
Combustibility	M4

------ BRIEF DESCRIPTION ------

THIS IS A 2 STY WITH BST BLDG WITH C.B.B.F.
& C.B. WALLS, CONC FLOORS, & STEEL DECK
CLASS II ROOF. THE PREMISES ARE OCCUPIED BY
VARIOUS TENANTS. EXPOSURES: MODERATE. MUN
PROT STND
FOR FUS CLASS 3. PRIV PROT IS NON STND.
HSKPING IS GOOD. CIRCUIT BREAKERS ARE USED.

------ COMMENTS ------

THIS RISK IS GOOD IN CLASS.
DESIRABLE IMPROVEMENTS:
1. PROVIDE EACH TENANT WITH A "2A; 10B,C"
RATED EXTINGUISHER.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

COPE Report - 1999 MANUEL DESOUSA 1052 ST LAURENT BL OTTAWA ON K1K 3B4 Reference No: 10684699

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

enviroscan
OPTA INFORMATION INTELLIGENCE

AIS Ref No.: 10684699

1999

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

2. EXTINGUISHERS NEED SERVICING IN HOBBY WOODWORKING SHOP.

------ CONSTRUCTION ------

WALLS - MASONRY:
70% Concrete Block 200mm Thick C-2 Type: W-1
30% (CBBF) Concrete Block Br 303mm Thick C-2 Type: W-1

PANEL in MASONRY or FIRE RESISTIVE WALLS:
15% Glass C-1

MASONRY and FIRE RESISTIVE FLOOR and ROOFS:
66% Reinforced Concrete - Fl Hours: 3.00 Listed? N Type: D-1

NON-COMBUSTIBLE FLOORS and ROOFS:
33% Class II Steel Deck - Ro C-6

------ SECONDARY CONSTRUCTION ------

HEIGHT:
Number of Storeys: 02
Basements: 1

Combustible Storeys Without Grade Access: 0

VERTICAL OPENINGS:
Stairs BST - 1ST Comb.: 02 Const.: 4
Type: Open (V-4) 0 Hrs-Walls/ 0 Hrs-Doors
Stairs 1ST - 2ND Comb.: 02 Const.: 4
Type: Open (V-4) 0 Hrs-Walls/ 0 Hrs-Doors

AREA:

Grade: 227 m2 Total: 682 m2 Effective: 682 m2

L1, L2 Area 73%

ROOF SURFACE:
100 % Approved

BUILDING CONDITION:
Type C-0

Year Built: 1969 Air Conditioning: Window-Type (100%)

Basement: 100% of grnd fl, 100% Finished

COMMON HAZARDS: 7211A2 - Central Heat Warm Air Gas

------ PROTECTION ------

MUNICIPAL PROTECTION:
Distance from Hydrants: Standard Congested Area: No
Distance to Fire Hall: < 2.5 km Accessibility: Good
FUS Protection Class: 03
Revised Class: 03
IAO Protection Class: 03

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

COPE Report - 1999 MANUEL DESOUSA 1052 ST LAURENT BL OTTAWA ON K1K 3B4 Reference No: 10684699

Requested by:
Eleanor Goolab
Date Completed: 04/07/2021 13:36:37

enviroscan
OPTA INFORMATION INTELLIGENCE

AIS Ref No.: 10684699

1999

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

INTERNAL PROTECTION:
MANUAL FIRE FIGHTING EQUIPMENT: Non-Standard Port. extinguishers
None Standpipe & hose

------ EXPOSURE ------

NONE NOTED:

------ OCCUPANCY - MANUEL DESOUSA ------

Industry Code: 2490 - Woodmakers excl. Sawmills - Wood Products Mfg

Occupancy: 6122M - HOBBY WOODWORKING SHOP

Location: BASEM Area: 93 m2 13.6% of Total

Combustibility Code: 04 - Free Burning
Susceptibility Code: 04 - Heavy Damage

------ OCCUPANCY - CENTRE EMERSION ------

Industry Code: 8323 - Schools, Other (N.O.C.)

Occupancy: 5266A - CONPUTER TRAINING SCHOOL

Location: 1ST & Area: 270 m2 39.5% of Total

Combustibility Code: 02 - Limited Combustibility
Susceptibility Code: 01 - Minimal Damage

------ OCCUPANCY - CONCEPT PRESTIGE ------

Industry Code: 6610 - Office Tenants (N.O.C.)

Occupancy: 5382 - OFFICE, NO ACCESS

Location: 2ND Area: 227 m2 33.2% of Total

Combustibility Code: 02 - Limited Combustibility
Susceptibility Code: 04 - Heavy Damage

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Cope Report - 1997 1052 1056 St. Laurent Blvd Ottawa ON K1K3B4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

Insurers' Advisory Organization
Confidential
For Use of Subscribers Only
Not For General Distribution
Fire Rate Calculation Detail

Reference No. : 10684699 (File No.:)
Fire Division: 1 Description: ENTIRE BLDG

Name of Insured: MANUEL DESOUSA
Address : 1052 1056 ST LAURENT BL

City, Prov : OTTAWA, ON
Postal Code : K1K 3B4

IAO Representative: HERB NELSON
Date Surveyed : 1997.02.19

---------- Coding ----------

Industry= 2490 Territory= 63 Construction= 2
Protection= 2 Combustibility= 4

---------- Description ----------

THIS IS A 2 STOREY CBBF & CB BLDG. WITH CONCRETE FLOORS AND A STEEL DECK ROOF OCC AS A HOBBY SHOP IN THE BSMT AND VACANT 1ST & 2ND FLOORS. EXPOSURES ARE MODERATE. MUN PROT IS STD FOR FUS CLASS 3. PRIV PROT IS STD. HOUSEKEEPING IS GOOD. CIRC BREAKERS ARE USED.

---------- Remarks ----------

THIS RISK IS AVERAGE IN CLASS.
DESIRABLE IMPROVEMENTS: NONE

---------- Basic Construction ----------

Item 211	Masonry Walls:				
	(CBBF) Concrete Block Brick Faced			C-2	
	Type W-1 Thickness	300mm	30% of	0 pts	0
	Concrete Block			C-2	
	Type W-1 Thickness	200mm	70% of	0 pts	0
Item 221	Masonry and Fire Resistive Floors:				
	Reinforced Concrete			D-1	
	Fire Rating 2hrs	Listed? Yes	33.33% of	0 pts	0
	Reinforced Concrete on Prot. Steel			D-1	
	Fire Rating 2hrs	Listed? Yes	33.33% of	0 pts	0
Item 222	Non-Combustible Roof:				
	Class II Steel Deck			C-6	
			33.33% of	250 pts	83.33

Total Basic Construction Charges	83.333
Schedule Base	150
Building Base	233.33

Item 230	Combustibility Modifier:	
	Building Base x .001 x Modifier 1.1	
	Basic Building Rate	0.257

---------- Secondary Constructions ----------

Item 300 Building Height:
Number of Storeys 2
Combustible Storeys Without Grade Access 0 0%
Number of Basements 1

Item 310 Vertical Openings:
Type: Stairs 100% of 20% 20%
Location: BSMT-1ST
Prot: V-4 , Open, 0.00 hrs/Walls, 0.00 hrs/Doors
Type: Stairs 50% of 20% 10%
Location: 1ST-2ND
Prot: V-4 , Open, 0.00 hrs/Walls, 0.00 hrs/Doors

Item 320 Area:
Grade 227.6 sq.m. Total 682.8 sq.m. Effect 682.8 sq.m. 0%

Item 330 Roof Surface:
Approved 100% 0%

Built in 1970
Air Conditioning: 50% Window-Type

Basement:
100% of Ground Floor
100% Finished
0% Unfinished
Elevator:

Total Secondary Construction Charges 30%

---------- Occupancy ----------

Item 417 Occupancy Charge:
Major Charge 188% + 20% of 0% 188%

Item 721 Common Hazard:
Item: 7211A2 CENTL HEAT WARM AIR-GAS 3%
Net Occupancy Charge 191%

Item 418 Occupancy Modification:
L1, L2 Area 86% Factor 0.7

Total Occupancy Charge 133.7%

---------- Exposure ----------

Item 830 Exposure Charges:

Total Exposure Charges	0%
Unprotected Bldg Rate	0.678

---------- Municipal Protection ----------

Item 920 Municipal Protection:

Hydrants Distance Standard
Accessibility Good
Firehall Distance < 2.5 km
Congested Area No
FUS Prot Class 3 Revised Class 3 Factor 0.44

Protected Building Rate	0.298

---------- Building Adjustment Factor ----------

Item 1000 Building Adjustment Factor:

Eff FUS Prot Class 3 Factor 0.49

Gross Building Rate	0.146

---------- Internal Protection ----------

Item 1111 Manual Fire Fighting Equipment:
Fire Extinguishers: Standard — Credit 3%

Item 1113 Automatic Fire Detection Systems:
Local - Partial Protection — Credit 0%

EC Charge	
Final Building Rate	0.142

---------- Occupancy And Contents ----------

Major Occupant: MANUAL DESOUSA
Occupancy Charge:
6122M1 WOODWORKING HOBBY SHOP 188%
Special Hazard:
Location: BSMT Area: 93 sq.m.
13.62% of Total
Occ'y= 188% Hazard= 0% Separated= 1 Net Occ'y= 188%

Comb.Cl:	4	Susc.Cl:	4	Ind.Code:	2490
Susc.:	0.6	Hazard :	1	Content Adj.:	0.16
Gross Bldg:	0.146	Gross Cont.:	0.242	Int.Prot:	0.95

Occupancy Specific Protection 1
Automatic Sprinkler 1
Automatic Alarms 1

EC Charge
Contents Rate 0.23

Minor Occupant: MANUAL DESOUSA
Occupancy Charge:
5551 BST - VACANT OFFICES 0%
Special Hazard:
Location: BSMT Area: 135 sq.m.
19.77% of Total
Occ'y= 0% Hazard= 0% Separated= 1 Net Occ'y= 0%

Minor Occupant: MANUAL DESOUSA
Occupancy Charge:
5551 1ST- VACANT OFFICES 0%
Special Hazard:
Location: 1052 Area: 227 sq.m.
33.24% of Total
Occ'y= 0% Hazard= 0% Separated= 1 Net Occ'y= 0%

Minor Occupant: MANUAL DESOUSA
Occupancy Charge:
5551 2ND - VACANT OFFICES 0%
Special Hazard:
Location: 1056 Area: 227 sq.m.
33.24% of Total
Occ'y= 0% Hazard= 0% Separated= 1 Net Occ'y= 0%

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

1997



INSURED: MANUEL DESOUSA

LOCATION: 1052-1056 ST LAURENT BLVD. OTTAWA, ONT

SCALE: 1" = 30' FILE NO.

Insurers' Advisory Organization (1989) Inc.

REPRESENTATIVE: HERB NELSON

DATE: FEB. 19, 1997

LCED.301.0291

Cope Report - 1989 1052 1056 St. Laurent Blvd Ottawa ON K1K3B4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.



INSURERS' ADVISORY ORGANIZATION

CONFIDENTIAL
FOR USE OF MEMBERS ONLY
NOT FOR GENERAL DISTRIBUTION
FIRE RATE CALCULATION DETAIL

REFERENCE NUMBER: 068469
BUILDING NUMBER: 1

NAME OF RISK: MANUEL DESOUSA
STREET: 1052-1056 ST LAURENT BLVD
CITY, PROVINCE: OTTAWA, ONTARIO
POSTAL CODE:

SURVEYED BY: C LAFLEUR DATE: 02-MAR-89
RATED BY: C LAFLEUR DATE: 21-MAR-89

- - - - - - CODING - - - - - -

INDUSTRY 651 TERRITORY 63 CONSTRUCTION 2
PROTECTION 2 COMBUSTIBILITY H5

- - - - - - BRIEF DESCRIPTION - - - - - -

THIS IS A 2 STOREY & BST B/CB,CB BLDG WITH
CONC FLRS & A STEEL DECK ROOF. OCCUPIED AS
AN UPHOLSTERING SHOP AND INSURANCE OFFICE.
SURVEY BASED ON AN EXISTING FILE. EXPOSURES:
MODERATE. MUNICIPAL PROTECTION STD FOR FUS
CLASS 3. PRIVATE PROTECTION NOT KNOWN.
HOUSEKEEPING IS AVERAGE. CIRCUIT BREAKERS
ARE USED.

- - - - - - COMMENTS - - - - - -

THIS RISK IS AVERAGE IN CLASS.
DESIRABLE IMPROVEMENTS: NONE AT THIS TIME.

- - - - - - BASIC CONSTRUCTION - - - - - -

ITEM 211 MASONRY WALLS:

B/CB WALLS	C-2			
TYPE W-1 THICKNESS	300MM	30% OF	Ø PTS	Ø
C.B. WALLS	C-2			
TYPE W-1 THICKNESS	200MM	70% OF	Ø PTS	Ø

ITEM 221 MASONRY & FIRE RESISTIVE FLOORS & ROOF:

GRADE FLOOR CONCRETE				
TYPE D-1 HOURS 2.00 LISTED? U		33% OF	Ø PTS	Ø

ITEM 222 NON-COMBUSTIBLE FLOORS & ROOF:

CONC/METAL PAN 2ND FLR	C-3	33% OF	140 PTS	46
CL 1 STEEL DECK ROOF	C-5	33% OF	200 PTS	66

TOTAL BASIC CONSTRUCTION CHARGES	112
SCHEDULE BASE	150
BUILDING BASE	262

ITEM 230 COMBUSTIBILITY MODIFIER:
BUILDING BASE X .001 X MODIFIER 1.2
BASIC BUILDING RATE .314

- - - - - SECONDARY CONSTRUCTION - - - - -

ITEM 300 HEIGHT:
NUMBER OF STOREYS: 2 AND BASEMENTS: YES
COMBUSTIBLE STOREYS WITHOUT GRADE ACCESS: Ø Ø%

ITEM 310 VERTICAL OPENINGS:
BST-2ND OPEN
TYPE V-4 HOURS .ØØ COMB CL H5 CONS CL 2 30%

ITEM 320 AREA:
BLDG DIMENSIONS (M):
X X X
AREA (SQ M): GRADE 228 TOTAL 684
EFFECTIVE 684 Ø%

ITEM 330 ROOF SURFACE:
APPROVED 100% OF Ø% Ø%

ITEM 380 BUILDING CONDITION:
GOOD C-. Ø%
BUILT IN: 1970
AIR CONDITIONING: NIL
BASEMENT: FINISHED
ELEVATORS: NIL
TOTAL SECONDARY CONSTRUCTION CHARGES 30%

- - - - - - OCCUPANCY - - - - - -

ITEM 417 OCCUPANCY CHARGE:
MAJOR CHARGE 350% PLUS 20% OF 0% 350%

ITEM 721 COMMON HAZARDS:
ITEM 721-1A3 OIL FIRED HOT AIR 6%
NET OCCUPANCY CHARGE 356%

ITEM 418 OCC'Y MODIFICATION:
L1, L2 AREA 67% FACTOR .9
TOTAL OCCUPANCY CHARGE 320%

- - - - - - EXPOSURE - - - - - -

TOTAL EXPOSURE CHARGES 0%
UNPROTECTED BUILDING RATE 1.413

- - - - - - MUNICIPAL PROTECTION - - - - - -

ITEM 920 MUNICIPAL PROTECTION:
DISTANCE OF HYDRANTS: STANDARD
ACCESSIBILITY: GOOD
DISTANCE TO FIREHALL: STANDARD
CONGESTED AREA: NO
F.U.S. PROT CLASS 03 REVISED CLASS 03 FACTOR .44
PROTECTED BUILDING RATE .622

- - - - - - BUILDING ADJUSTMENT FACTOR - - - - - -

ITEM 1000 BUILDING ADJUSTMENT FACTOR:
PROTECTION CLASS 03 FACTOR .87
GROSS BUILDING RATE .541

- - - - - - INTERNAL PROTECTION - - - - - -

FINAL BUILDING RATE .541

- - - - OCCUPANCY AND CONTENTS - - - -

PIGION-ROY INSURANCE
ITEM 538-1 1NSURANCE OFFICE 0%
LOCATION: 52-54 AREA: 456(SQ M) 67.0% OF TOTAL
OCC'Y 0% HAZARDS 0% SEP'T .00 NET 0%

COMB CL L2 SUSC CL S2 IND CODE 64
SUSC .200 HAZARD 1.00 CONTENTS ADJ .42
GROSS BLDG .541 GROSS CONT .625 INT PROT .00
CONTENTS RATE .625

- -

DESOUSA UPHOLSTERING-LOCKED
ITEM 554-1 UPHOLSTERING SHOP 350%
LOCATION: BST AREA: 228(SQ M) 33.0% OF TOTAL
MAJOR OCC'Y 350% HAZARDS 0% SEP'T .00 NET 350%

COMB CL H5 SUSC CL S4 IND CODE 259
SUSC .600 HAZARD 1.00 CONTENTS ADJ .59
GROSS BLDG .541 GROSS CONT .895 INT PROT .00
CONTENTS RATE .895

- -

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

1989



Multirisk Report - 1999 CENTRE DACCESS POUR FEMMES INC 1052 St. Laurent Blvd Ottawa ON K1K3B4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

Ontario Branch
Confidential Report

MULTIRISK SURVEY

Insured:	CENTRE D'ACCESS POUR FEMMES INC.
Location Surveyed:	1052 ST-LAURENT S BL OTTAWA H P A, ONTARIO K1K 3B4
Person Contacted:	Monique Deray
Telephone Number:	(613) 747-2800
Policy Number:	82028288
AIS Reference:	10684699
Surveyed by:	Luc McCann
Date of Survey:	1999.06.15

Committed to Service Excellence

NOTE: The sole purpose of this report is to provide insurance pricing and underwriting information about the particular insured and location named. Only the person requesting this survey will receive a copy of the report, and IAO asks that it be kept strictly confidential. This report does not guarantee compliance with any standards or with any federal, provincial or municipal codes, ordinances or regulations. Tests of fire and other protection equipment have not been conducted or witnessed during this survey.

IAO reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from a survey of the premises and/or from data supplied by or on behalf of the Purchaser. IAO does not purport to list all hazards. While changes and modifications, referred to in the reports are designed to upgrade protection and loss prevention of the premises, IAO assumes no responsibility for management and control of these activities. IAO will not be responsible to the Purchaser for any loss or damages, whether consequential or other, however caused, incurred or suffered, as a result of the services being provided.

CENTRE D'ACCESS POUR FEMMES INC.
1052 BL ST-LAURENT S; OTTAWA H P A, ONTARIO

M U L T I R I S K - F I R E, L I A B I L I T Y A N D B A S I C C R I M E

OCCUPANCY:

The insured is a tenant at this location. They have been in operation since 1986 and at this location for 3 year(s). They occupy 308 sq. m and are the major occupant, having 4 employees. The premises are in good condition. The insured is interested in loss prevention, however there have not been any losses during the last 3 years.

* Occupancy Description (Insured / major tenant if insured is non-occupant)

  This is a non profit organization specializing in helping women find a place in today's job market. No courses are given and the computers are used mainly for job hunting as well as helping the candidate to produce an adequate Resume.

  The insured made it clear that this not a school but a motivation and help center. Groups usually average ten persons at a time.

* Other Classes of Occupants

  The landlord is retired and occupies a small portion of the basement as an upholstering shop. The stock is quite limited and the landlord is quoting as saying that this is a hobby and that the work performed is for friends and acquaintances.

  The second floor is presently vacant but will, soon, be occupied by a leather goods retail store.

* Undersirable Features

  No portable fire extinguishers.
  The space under the staircase leading to the basemnt is used for storage.

It is recommended that this location be resurveyed in 1 year(s).

BUILDING:

* Built - 1969 (est.) Height: Storey(s) (excluding basement) - 2
* There are no additions.
* Renovation(s) - 1999
* Building condition - Good

* Area: Ground Floor - 194 sq. m Total (including basement) - 582 sq. m

---

BASIC CONSTRUCTION:

* Walls - 50% Masonry - Concrete blocks, brick faced
  50% Masonry - Concrete block with aluminum clad

* Floors - (excluding basement) 100% Concrete

* Roof - 100% - Steel Deck Class II
  - Surface material(s) - Tar and gravel
  - Original roof.

INTERIOR FINISH:

* Walls - 100% non-combustible

* Ceilings - 100% non-combustible

BASEMENTS:

* Number of basements - 1
* Total Area - 194 sq. m
* Finished - 59% Unfinished - 41%

VERTICAL OPENINGS:

* Stairs - Protection open

MEZZANINE: None

OUTBUILDINGS: None

HEATING:

* Forced Warm Air - 99% - Natural gas
  - Original installation.
  - Installation appears safe

* Electric Baseboard Units - 1% - Electric
  - Original installation.
  - Installation appears safe

* Heating appliances - All enclosed in a separate room
* Combustible materials - Not stored in this room at time of survey

* Fuel Tanks/Supply:
  - Supply - UG Natural Gas Connection

* Chimneys:
  - Masonry - Standard

ELECTRICAL:

* Condition - Good and appeared safe at the time of the survey.
* Wiring - Conduit, BX, Non-Metallic
* Overcurrent protection - Circuit Breakers.
* Electrical system - Original installation.

PLUMBING:

* Condition - Good at the time of the survey.
* Piping is Copper
* Plumbing - Original installation.

EXPOSURES: (within 15m of the risk):

* FRONT: OPEN

* REAR: OPEN

* RIGHT: OPEN

* LEFT: TO BUILDING
  Construction - Masonry / Non-combustible.
  Occupancy - Restaurant(s).
  Distance - 8 m Height - 1 storeys
  Protection - Non-Sprinklered Grading - Moderate

MUNICIPAL PROTECTION:

* The FUS Public Fire Protection Classification is 3
* Responding (career) fire department Ottawa
* Distance from risk Less than 2.5 km
* Access via Paved roads. Year-round.

* The building itself is easily accesible to the fire department.
* Two hydrants within 155m (standard)

PRIVATE PROTECTION at this location includes the following:

* Non-standard extinguishers

* An automatic sprinkler system is not present.

M U L T I R I S K - L I A B I L I T Y

OCCUPANCY - GENERAL INFORMATION

* Neighbourhood is predominantly commercial
* Insured - tenant Area occupied - 308 sq. m
* 90% accessible to public. Public access is considered light
* Gross revenue - could not be determined at the time of the survey

---

PREMISES information at the time of this survey

* The following appeared to be SATISFACTORY:

  Stairs, ramps, handrails; Floor surfaces & coverings; Wall & ceilings; Inerior Lighting; Exterior Lighting; Emergency Lighting; Interior Housekeeping; Exterior Housekeeping; Washrooms; Sidewalks, Yards & Parking Lots; Snow & ice removal; Signs & Awnings; Roof attachments; Fire exits

* Elevating devices in operation - none

M U L T I R I S K - B A S I C C R I M E

NEIGHBOURHOOD:

* Predominantly commercial
* Stable
* Best described as having a moderate crime rate

BUSINESS:

* Description - Job reinsertion center for Women
* Hours of Operation - 8:00 a.m. to 16:00 p.m. Mon to Thurs. and 8:00 a.m. to 12:00p.m. Fridays
* Typical Stock - Computer PC's and office equipment.
* Target Stock Details - Computer PC's and office equipment.
* Smash and Grab exposure is low
* There is no safe on the premises

GENERAL PROTECTION at the time of this survey:

* The following appeared to be SATISFACTORY:

  Exterior Lighting, Interior Lighting, Roof Accessability, Police Patrols

* The following were found to be UNSATISFACTORY, (refre to the Remarks and Recommendations for further details):

  Target stock protection

* Security Alarm System - Yes

SECURITY SYSTEM (TENANT or OWNER/OCCUPANT):

* A premises alarm system is in place
* The extent of protection by this system is perimeter, space/area
* The alarm is Local alarm
* Line security is not provided
* The type of line security is Digital Dialer

PHYSICAL PROTECTION (TENANT or OWNER/OCCUPANT):

* The exterior locks at this location are deadbolt
* The windows are barred

This report section is designed to provide basic crime information only. More detailed crime information can be obtained by ordering an Expanded Crime Supplement.

M U L T I R I S K
R E M A R K S / R E C O M M E N D A T I O N S

REMARKS:

* Fire, Liability & Basic Crime - This is a reinsertion center for Women looking for a job. There are no courses given on the premises and the computers, all Pentium, are used to hunt for jobs as well as prepare adequate resumes. There are approximately twenty six individual PC's on the premises at this time.

The space under the staircase leading to the basement is used for storage and could hinder egress (Recommendation made).

There are no portable fire extinguishers on the premises (Recommendation made).

The alarm system is local only and, due to the nature of the target equipment, the protection is not adequate (Recommendation made).

RECOMMENDATIONS:

* 99-1 Fire, Liability & Basic Crime - Provide 4 (2 per floor) ULC or equivalent labelled portable extinguishers designed expressly for electronic equipment. They should be placed in readily accessible and visible locations.

* 99-2 Fire, Liability & Basic Crime - Fire exit ways should not be impeded. The storage area under the basement to ground staircase should be cleaned and kept clean.

* 99-2 Fire, Liability & Basic Crime - A full alarm system for the occupancy should be connected with a ULC listed monitoring station and consideration should be given to providing a dedicated line for the system.



opta
INFORMATION INTELLIGENCE

enviroscan

175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

T: 1 877 244 9437
W: optaintel.ca

Nate

Site Address:
1064 St. Laurent Blvd, Ottawa, ON

Project No:
24053100242

Opta Order ID:
145089

Requested by:
Eleanor Goolab
ERIS

Date Completed:
6/6/2024 1:59:18 PM

Project Name: Phase I Environmental Site Assessment
1064 St. Laurent Ottawa Ontario
Project #: 24053100242
P.O. #: 103499.001

ENVIROSCAN Report

Search Area: 1064 St. Laurent Blvd, Ottawa, ON

Requested by:
Eleanor Goolab
Date Completed: 06/06/2024 13:59:18

enviroscan
OPTA INFORMATION INTELLIGENCE



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Opta Historical Environmental Services Enviroscan™ Terms and Conditions

Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Opta's records relating to the described property (hereinafter referred to as the "Property"). Opta makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Opta's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Opta does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

Disclaimer

Opta disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Opta Reports or from any tortious acts or omissions of Opta's agents, employees or representatives.

Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.

Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

175 Commerce Valley Drive W
Markham, Ontario
L3T 7Z3

T: 877.244.9437
Toll Free: 877.244.9437
F: 877.244.9437

www.optaintel.ca

ENVIROSCAN Report

Report Index

Page **Report Title**

5 (1983) Commercial Property Fire Rating Form Report - 1983 PERFORMANCE MOTORS 1064 St. Laurent Blvd Ottawa ON K1K3B4 (distance = 0 metres*)

8 (1983) Commercial Property Fire Inspection Survey Form Report - 1983 1064 St. Laurent Blvd Ottawa ON K1K3B4 (distance = 0 metres*)

12 (1981) Fire Inspection and Rate Calculation Form Report - 1981 1064 St. Laurent Blvd Ottawa ON K1K3B4 (distance = 0 metres*)

16 (2004) All Risk Report - 2004 MILAUR AUTOMOTIVE LTD. O/A MIDAS MUFFLER 1064 St. Laurent Blvd Ottawa ON K1K3B4 (distance = 0 metres*)

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Commercial Property Fire Rating Form Report - 1983 PERFORMANCE MOTORS 1064 St. Laurent Blvd Ottawa ON K1K3B4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

COMMERCIAL PROPERTY FIRE RATING FORM

CODING			
IND.	TERR.	CONS.	PROT.
551	63	4	2

LOCATION Ottawa NAME Performance Motors FILE NO.

ADDRESS 1064 St. Laurent Blvd. Insp'd. by C.F.L. Date April 26/83

Rated by C.F.L. Date May 2/83

BASIC CONSTRUCTION: (SECTION II)

Construction Class 4 Bldg. Comb. Class L2

WALLS (ITEMS 210-215)

WALL AREA	MASONRY Wall Type	MASONRY Wall Thick.	FIRE RES. Dam. Type	FIRE RES. Fire Res.	NON COMB	COMB	DETAIL OF WALL CONSTRUCTION	% OF WALL PERIM	POINTS	CHARGES
	W-1	20.3	D-1	2HR			Concrete Blocks	100% x	—	—
	W-		D-	HR				% x		
	W-		D-	HR				% x		
	W-		D-	HR				% x		
	W-		D-	HR				% x		
								% x		—
								30 % x	20	6
								% x		—

Columns in (or adjacent to) non-bearing masonry walls: Unprot. metal ☐ Comb. ☐

Panels in masonry or fire resistive walls: Comb. ☐ Non-comb. ☐ Glass ☑ Slow burning ☐

Special Conditions (Describe).....

FLOOR(S) AND ROOF (ITEMS 220-223)

LEVEL	DIMENSIONS	MAS. or F.R. Dam. Type	MAS. or F.R. Fire Res.	NON COMB	COMB	DETAILS OF FLOOR/ROOF MATERIALS	% of Total Floor/Roof Area	POINTS	CHARGES
Grade	74.4	D-1	2 HR			Concrete on earth	20 % x	—	—
Roof	111.0	D-	-1 HR	✓		Class II Steel Deck	30 % x	250	75
		D-	HR				% x		
Grade	111.0	D-	HR		✓	3 ord. wood joist	30 % x	300	150
Roof	74.4	D-	HR		✓		20 % x		
	370.8								

Total Basic Construction Charges. 231

Schedule Base ..... + 150

Building Base ..... = 381

Building Base x .9 Comb. Modifier (ITEM 230) x .001 = **BASIC BUILDING RATE:** .343

(carried fwd. overleaf) *

SECONDARY CONSTRUCTION: (SECTION III)

	% CHARGE
Height: (ITEM 300) Nbr. Storeys 1 Bast. YES Comb. Stories (Without ground level access) L2	—
Vertical Openings: (ITEM 310) Type V4, Fm. BT, To 1ST, Enclosure —, Doors —, 1st. % Chge. 10	10
Area: (ITEM 320) Grade Floor Area 185.4 Total Area 296.4 Effective Area 296.4	—
Roof Surface: (ITEM 330) Approved ☑ Other (Described)	—
Combustible Concealed Spaces: (ITEM 340) Roof Space; Percentage of total roof area — %	—
Ceiling Space; Percentage of total floor area — %	—
Combustible Interior Construction: (ITEM 350) Floor Surfacing; Percentage of total floor area — %	
Interior Walls or Partitions; Percentage of total exterior wall area — %	—
Mezzanines or Decks; Percentage of total floor/roof area — %	—
Combustible Interior Finish or Insulation: (ITEM 360) Walls: Percentage of total area of exterior walls; Ord. Dam. 38x30 % Spec. Dam. — %	11
Roof & Floor(s): Percentage of total area of ceilings; Ord. Dam. — % Spec. Dam. — %	
Combustible Exterior Finish or Attachments: (ITEM 370) False Mansard 55% x 30 x .5	8
Building Condition: (ITEM 380) Good ☐; Average ☑; Poor ☐;	—
Total Secondary Construction Charges:	29

(carried fwd. overleaf) **

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

OCCUPANCY (SECTION II)

St. No. Floor	Floor Area	% of Total Area	Occ'y Item No.	Name and Description of Occupancy and Hazards	Basic Occ'y Charge	Haz. Charges	Sep'd. Occ'y Factor	Total Occ'y Charge	Comb. Cl.	Susc. Cl.	Ind. Code
Common Hazards Applicable to Building				H.A. gas central furnace		5					
1064	296.4	100%	508 3-A	Auto - showroom sales offices	50	—	—	50	L2	S2	551

TOTAL 296.4 — Building IND. CODE 551

Major Occupancy Charge ..... 50 %
20% of _____ (next 10 highest additional Total Occupancy Charges) ..... — %
Common Hazards applicable to the Building ..... 5 %
Net Occupancy Charge ..... 55 %
L1, L2 Area _____ %
Net Occupancy Charge x _____ Occ'y Mod. Factor (ITEM 418) ..... = — %
**Total Secondary Construction Charge (brought forward from overleaf) ..... + 29 %

*E.C. EXTRA		
IND. CODE	PERIL	ADD'L RATE

EXPOSURE: (SECTION VIII) Non Chargeable ☑

Facing Wall of Exposure						Facing Wall of Risk			
Mas. Semi-Prot.	Mas. Unprot.	Non Comb.	Comb.	Comb. Class	Lt/Wt.	Comb. & Non Comb.	Masonry Unprot.	Masonry Semi-Prot.	Exposure Distance
									—
									—

Exposure Charge ..... + — %
Party Wall Charge (ITEM 831) ..... + — %
Communication Charge (ITEM 832) ..... + — %
+ 100 %

• (brought forward from overleaf) BASIC BUILDING RATE .343 x 184 % = UNPROTECTED BLDG. RATE .631

MUNICIPAL PROTECTION: (SECTION IX)
F.U.S. Prot. Class 3 Revised Prot. Class ____
Dist. to Hydrants: Stdr. ☑ Non Stdr. ☐ .....m Accessibility: Good ☑ Poor ☐
Dist. to Fire Hall: Stdr. ☑ Non Stdr. ☐ .....km. Congested Area: Yes ☐ No ☑
Unprotected Bldg. Rate x .44 Protection Class Factor ..... = PROTECTED BLDG. RATE .278

BUILDING ADJUSTMENT FACTOR: (SECTION X)
Protected Bldg. Rate x 1.06 Building Adjustment Factor ..... = GROSS BLDG. RATE .295

INTERNAL PROTECTION: (SECTION XI)
Extinguishers Stdr. ☐ ____% Credit W. & C. Stdr. ☐ ____% Credit
S.P. & H. Stdr. ☐ ____% Credit Automatic Fire Detection System Stdr. ☐ ____% Credit
Automatic Sprinklers ☐ (Describe) ..... ____% Credit
Other Auto. Protection ☐ (Describe) ..... ____% Credit
GROSS BLDG. RATE ____ Less ____ % = ____ Less ____ % = ____ Less ____ % = FINAL BLDG. RATE .295

CONTENTS RATES (SECTION XII) GW 11/5/83

ITEM →	1200	1210	1220

Ind. Code	Susc. Class	OCCUPANCY	Susc. Charge		Hazards Adj.		Conts. Adj. Factor		Adj. Conts. Charge		Gross Bldg. Rate		Gross Conts. Rate		Int. Prot. Factor		FINAL CONTS. RATE
551	S2	Auto showroom sales office	.200	x	—	x	.80	=	.160	+	.295	=	.455	.	—	=	.455
				x		x		=		+		=		x		=	
				x		x		=		+		=		x		=	
				x		x		=		+		=		x		=	
				x		x		=		+		=		x		=	
				x		x		=		+		=		x		=	

Indicate with * any rate subject to E. C. Extra

Commercial Property Fire Inspection Survey Form Report - 1983 1064 St. Laurent Blvd Ottawa ON K1K3B4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

1983

INSURERS' ADVISORY ORGANIZATION OF CANADA

ONTARIO REGION

☐ Mercantile Risk
☐ Miscellaneous Risk

COMMERCIAL PROPERTY FIRE INSPECTION SURVEY FORM

(Use this form for all Non-Manufacturing risks, and some Manufacturing risks with five hands or less, of all construction, but excluding Sprinklered properties)

Address : No. 1064 Street/Road Etc., St Laurent Blvd.
Municipality Ottawa (Formerly) _____
Owned by: Performance Motors Occupied by: same
Age of building (Built in) ____ : ____ : ____. Additions (Built in) ____ : ____ : ____ : ____ : ____.
Is building completely finished & out of workmens hands? Yes ☑; No ☐ IBC Code: Terr: 63 Ind: 551 Cons: 4 Prot: 2

BASIC CONSTRUCTION - (SECTION II)

- EXTERIOR WALLS:

N S E W (Refers to compass point direction of wall, i.e. North, South, East or West)

☐ INDEPENDENT ☑ BEARING ☐ NON-BEARING ☐ PARTY ☐ PARAPET

(Describe material & thickness of all walls including make-up of combustible walls & any fire retardant impregnation. Also, check off appropriate wall supports below:)

Concrete Blocks

COLUMNS OF WOOD ☐; HEAVY WOOD (min. 150mm x 300mm) ☐; UNPROTECTED STEEL ☐; PROTECTED STEEL ☐, protected by _____ having a fire-resistance rating of _____ hrs.
PANELS of Non-Combustible material or GLASS ☐; COMBUSTIBLE ☐ (describe) _____
Wall: N. 2 % S. 50 % E. 50 % W. 3 %

- FLOORS & ROOF: (Describe Floor & Roof Materials Including Thickness & Nature Of Supports)

Floor Level	% Aut. Spk. Sec	Fire Resistive & Masonry	Fire Res. in Hrs.	Non-Combustible	Combustible
Grade	0%	Concrete on earth	2	185.4	
Roof	0%	Bar Joist Steel Deck	-1	185.4	
SPACE	0%	111.0			Wood joist.
Roof	0%	111.0			

COMBUSTIBLE FLR. on Lowest BASEMENT Level: Yes ☐; No ☑. If Yes, Describe & Give Percentage - _____

SECONDARY CONSTRUCTION - (SECTION III)

- HEIGHT: (Nbr.) 1 Storeys High; Basement: Yes ☑; No ☐. (Nbr.) 1 Combustible Storeys Without Ground Level Access.
- VERTICAL OPENINGS: Elevators ☐; Stairs ☑; Other ☐ (describe) _____

(Describe Construction & Type of Enclosure (s) & Door (s) Fully)

Elv., Stway or Other	Nbr.	From:	To:	ENCLOSURE(S)	DOOR(S)
Stair	1	1st	B1	-	-

- AREA: Basement : 12.2 x 9.1 : ____ x ____ : ____ x ____ = 111.0 m²
1st. Floor : 15.2 x 12.2 : ____ x ____ : ____ x ____ = 185.4 m²
2nd Floor : ____ x ____ : ____ x ____ : ____ x ____ = ____ m²
3rd(& Other): ____ x ____ : ____ x ____ : ____ x ____ = ____ m²
EFFECTIVE AREA: 296.4 m²
Separation Walls ☐ (describe) _____. Total Area 296.4 m²

- ROOF SURFACE: Non-Combustible ☐ (describe) _____. Combustible ☐ (describe) _____.
Patent (✓). FALSE ROOF over Masonry or Fire Resistive Roof ( ) (describe) _____.

- COMBUSTIBLE CONCEALED SPACES: Combustible Space In Roof ☐, &/or Ceiling ☐. If In Roof, Is This An Attic ☐, Cut Off ☐, Shut Off ☐, With Access Limited By Trap(s)/Hatchway(s) ☐. In Proportion To Total Roof/Ceiling Area COMBUSTIBLE CONCEALED SPACE Comprises ____% In ROOF &/or ____% In CEILING. Describe _____.

- continued -

- COMBUSTIBLE INTERIOR CONSTRUCTION: Floor Surfacing ☐ (describe & give % of total floor area affected) —; Partitions/Walls ☐ (describe & give % of total interior wall area) —; Mezzanines/Decks ☐ (describe & give % of total area of floors & r) —.

- INTERIOR FINISH or INSULATION: (Specify Where SPECIAL DAMAGE Materials Are Used)

Specify FLOOR	BT S/S	1ST			And comb. finish on Masonry walls = 38%	
Walls:	CB.	MS, GYP				
Ceiling:	GYP.	GYP, AMT.				
Interior Partitions	—	GYP				
Smoke Developed	—	-425				
Flame Spread	—	-200				

Ordinary Damage Material Attached To Fire Resistive or Non-Combustible Walls ☑ and/or Ceiling ☐

- COMB. EXTERIOR ATTACHMENTS OR FINISH: Attachments ☑ Comprise Of (describe & give chargeable %) Canopy = 172.6M² COMB.; Finish (☑ Comprises Of (describe & give chargeable %) Fabric Marquee = 55%; Smoke Developed - 200 or Less ☐; Over 200 ☑; Flame Spread Rating 425. None Of The Above ☐. Are Attachments/Finish Attached/Applied To Fire Resistive or Non-Comb., Walls or Roof? Yes ☐; No ☐.

- BUILDING CONDITION: Moderate ☑, Major ☐, Extreme Deficiencies ☐. Describe Sub-Standard Structural Conditions —.

COMMON HAZARDS - (SECTION VII, Items 720-724)

- HEATING: Building Heated? Yes ☑; No ☐. Borrowed Heat ☐. Describe Heating System Including Controls & Fuel Used: D.F.W.A gas furnace - Central.
Describe Chimney(s) & Deficiencies If Any: —

- ELECTRICAL: FUSES: Type "S" ☐; Type "C" & Rejector System ☐; Circuit Breakers ☑; ORDINARY ☐; Used Exclusively ☐. Aluminum Wiring ☐; Rigid Conduit ☐; Other ☑ (describe) Open ☐.
Electrical Equipment Defects: None ☑; Minor ☐; Moderate ☐; Major ☐; Serious ☐. Describe Condition: —

- HOUSEKEEPING: See General Underwriting Comments Section (Page 3) OK.

MUNICIPAL PROTECTION - (SECTION IX)

- FIRE DEPARTMENT: Risk Within 2.5 km Of Nearest Fire Hall? Yes ☑; No ☐. If No - State Distance To Fire Hall: ____km.

- HYDRANTS: Two Hydrants Within 155m of Risk? Yes ☑; No ☐. And All Parts Of Building Within 155m Of At Least One Hydrant? Yes ☑; No ☐. MAINS - 150mm ☐; 200mm ☐; 300mm ☑. Other (describe) —
Circulating ☐; and/or Dead End ☐ Mains. Describe Deficiency (if any): —

- ACCESSIBILITY: Risk Accessible At Least On One Side By Street 15m In Width? Yes ☑; No ☐. If No - Describe —

- CONGESTED AREA: Congested/Conflagration Hazard Prevails? Yes ☐; No ☑. If Yes, Describe Under General Underwriting Comments.

- PRIVATE PROTECTION: Is There Exclusive Private Protection ☐. Or Supplement To Municipal Protection ( ). Describe —

INTERNAL PROTECTION - (SECTION XI)

- MANUAL FIRE FIGHTING EQUIPMENT: Standard ☑; Non-Standard ☐. (See Occupancy Section, page 3).

- WATCHMAN SERVICE: Standard ☐, Including Proprietary Supervision ☐, Including Central Station Supervisory Ser. ☐. Describe: —

- AUTOMATIC FIRE DETECTION SYSTEM: Full Protection ☐; Partial Protection (i.e. Minimum Requirements) ☐; Describe (& Attach Form No. 2184-6/80, for Automatic Fire Alarm Detection Systems, After Completion) —

- PARTIAL AUTOMATIC SPRINKLER SYSTEMS: Acceptable Waterflow Alarm To Approved CENTRAL STATION ☐. No Such Alarm ☐. Total area Protected by Automatic Sprinklers Comprises — M².

- OTHER LIMITED AUTOMATIC FIRE PROTECTION SYSTEMS: (Other Than A.S.) Area Protected by: HALON ☐; CO_2 ☐; HIGH EXPENSION FOAM ☐; Other (describe) —, Comprises — m².

- continued -

- continued

COMMERCIAL PROPERTY FIRE INSPECTION SURVEY FORM
OCCUPANCY & SPECIAL HAZARDS - (SECTIONS IV, V, VI & VII)

- SEPARATED OCCUPANCY: Is There Any Occupant(s) Cut-Off VERTICALLY ☐ /HORIZONTALLY ☐? Yes ☐; No ☑.
If Yes - Such Occupant Occupies _____ m^2, Comprising _____ % Of The Total Floor Area;
Describe: _____.

OCCUPANCY DETAILS: Indicate: 1) Business Name Of Each Tenant, 2) Special Hazards Including Process Operation(s) And Faults Of Management, 3) Number, Type and Location Of Manual Fire Fighting Equipment, 4) Any Other Exceptional Features Of The Risk Not Discussed Elsewhere, and 5) Any Vacant Section(s).

CIVIC NO.	FLOOR LEVEL	AREA (m^2)	IBC IND. CODE	
1644	BTS	276.4	551	Performance Motors: retail new cars-auto showroom, offices
	1ST			
				BT ⓪63c 1ST ⓪2A.
Total Floor Area		276.4	551	← (Building Owner's Interest) - Continued on attached sheet ☐ -

GENERAL UNDERWRITING COMMENTS

- HOUSEKEEPING & MAINTENANCE: Excellent ☐; Good ☐; Average ☑; Poor ☐ (describe) _____

- NEIGHBOURHOOD: Isolated ☐; Residential ☐; Commercial ☑; Industrial ☐; Congested/Conflagration Hazard ☐ (describe) _____

- OPINION OF RISK: Excellent ☐; Good ☐; Average ☑; Poor ☐ (describe) _____

- continued -

Fire Inspection and Rate Calculation Form Report - 1981 1064 St. Laurent Blvd Ottawa ON K1K3B4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

INSURERS' ADVISORY ORGANIZATION OF CANADA

ONTARIO REGION
MISCELLANEOUS CLASS RISKS

FIRE INSPECTION AND RATE CALCULATION FORM

1. (Use this form for risks of all construction (excluding fire resistive) rated from the MISCELLANEOUS CLASS SCHEDULE.)

LOCATION: OTTAWA
ADDRESS: 1064 ST LAURENT BD.
(Formerly)
IAO PLAN – Sheet No.: 256 ; Block No.: 2022 ; Plan No.: ; NOP ☐ ; See Attached Diagram ☑

		Charges	Ded.
1-RISK MAGNITUDE:	Wall material classification: Indicate if exterior walls are: Part Glass Walls 30x50%		
	(a) Masonry – Solid Brick, Stone, Solid Concrete, Hollow Concrete Block, Tile or Gypsum Block 100 %	20	
	(b) Veneered – Frame Veneered with Brick, Perma Stone or Tile. %		
	(c) Frame – Including Frame covered with Roughcast, Metal, Rigid Asbestos, Patent Siding or Steel on Steel buildings with combustible contents		
	NOTE: If Mixed Construction, show % of each type of construction including attachments:		
	(d) Area of Grade floor – 2000 sq.ft.		
	(e) Height – 1 Storey(s); Basement – Yes ☑ No ☐ Basement Charge		
2-ROOF:	(a) Is covering Wood Shingles ☐; Tar Paper ☐; or Mansard type roof? ☑	10	
	(b) Is roof 2" or better Tongue and Grooved or Splined plank supported on steel joists, Heavy wood or Laminated beams (No wood joists) and all floors equivalent or better? Yes ☐ No ☑		
	(c) Is roof space (mean height over 3 feet) designed for occupancy or used for storage? Yes ☐ No ☑		
	Used for ventilating fan? Yes ☐ No ☑		
	Insulated with combustible insulation? (loose or in batts) Yes ☐ No ☑		
3-FLOORS:	Grade – Concrete Yes ☐ No ☑		
	Steel Supports Yes ☐ No ☐; Protected Yes ☐ No ☐		
	Other Construction		
	Other Floors wood floor	—	—
4-FLOOR OPENINGS:	(Masonry Buildings only) All stairways and elevator shafts masonry enclosed with metal covered doors, automatic or self-closing at each floor level (including basement) Yes ☐ No ☑ If No, describe open stairs 1st to 2nd.	10	
5-METAL SUPPORTS:	(Masonry or B. V. Buildings only) Are steel columns, beams or trusses (if any) protected in standard manner? Yes ☐ No ☑	5	
6-INTERIOR FINISH:	(a) Masonry or B. V. Buildings – Does combustible finish exceed 10% of interior finish? Yes ☑ No ☐	15	
	(b) Other than Masonry or B. V. Buildings – Are interior walls, ceilings and partitions THROUGHOUT, finished with non-combustible material? Yes ☐ No ☐		
7-HEATING:	(a) Stoves or Space Heaters – (Coal or Oil fuel): Yes ☐ No ☐		
	(b) Hot air furnaces (Coal or Oil fuel) Convection type? Yes ☐ No ☐; Forced warm air? Yes ☑ No ☐	5	
	NOTE: If wood used for fuel, double charges under (a) or (b).		
	(c) Gas fired furnaces, Space or unit heaters: (Natural or L.P.) Approved? Yes ☐ No ☐		
	(d) Electric Heating: Portable, safely arranged? Yes ☐ No ☐; Permanently installed? Yes ☐ No ☐; Approved: Yes ☐ No ☐		
	(e) Hot Water or Steam: Yes ☐ No ☐; Standard fire-resistive room: Yes ☐ No ☐		
	(f) Borrowed Heat: Yes ☐ No ☐; Any heating devices in building?: Yes ☐ No ☐		
8-CHIMNEYS AND VENTS:	(a) Masonry, Solid Brick from ground: Yes ☐ No ☐; Bracket: Yes ☐ No ☐		
	(b) Metal Prefabricated Listed Factory Built: Yes ☐ No ☐; Listed Type "B" vents: Yes ☑ No ☐	—	—
	(c) Metal Stacks: Yes ☐ No ☐; Gauge of Steel inches. Foundation		
	Stove Pipe Chimney: Yes ☐ No ☐; Clay, Cement or Asbestos pipe: Yes ☐ No ☐		
	(d) Fuel: Oil ☐ Gas ☑ Coal ☐; Wood ☐		
	SUB-TOTAL (Carried forward)	65	—

		Charges	Ded.
	(Total brought fwd.)	65	—
9-ELECTRIC WIRING:	Exclusively Type "S" fuses or Type "C" fuses and rejector system or circuit breakers ☒ Yes ☐ No	—	
10-INSIDE FIRE PROTECTION:	(a) Portable Fire Extinguishers (to NFPA Standard No. 10): (For details see page 3 – "Occupancy By Floor".) ☒ Yes ☐ No	5	5
	(b) Standpipe and Hose System (to NFPA Standard No. 14): ☐ Yes ☐ No		
	(c) Watchman and Approved Clock (Standard): ☐ Yes ☐ No		
	(d) Partial Automatic Sprinkler System: ☐ Yes ☐ No		
	(e) Private Automatic Fire Alarm Detection System: (Have Survey form completed) ☐ Yes ☐ No		
11-MUNICIPAL PROTECTION:	Grading Class No. 3 is building within 500' of two hydrants on 6" or larger circulating mains: 2 (500') ☒ Yes ☐ No	18	
	If not, give details	—	
12-OCCUPANCY:	Occupancy Item No. 37 Describe Auto Sales office	—	
	Additional Occupancy Charges:		
	(a) Are incense braziers used? ☐ Yes ☐ No		
	(b) Are incense braziers kept in metal or metal lined cabinets used for these only? ☐ Yes ☐ No		
	(c) Are Altar or Votive candles used? ☐ Yes ☐ No		
	Alight during services only? ☐ Yes ☐ No		
	(d) Is there a tower or steeple over 10' in height above peak, of other than Masonry Construction? ☐ Yes ☐ No		
	(e) Are mops, polishes, and cleaning materials kept in metal or metal lined lockers? ☐ Yes ☐ No		
	(f) Is Parish Hall used for regular social functions? – (i.e. Weekly or Monthly) ☐ Yes ☐ No		
	(g) Are cooking facilities used daily? ☐ Yes ☐ No		
	(h) Is there Manual Training: Using power? ☐ Yes ☐ No		
	(i) Is there a pipe organ in building? ☐ Yes ☐ No		
13-EXPOSURES:	Describe detached +40'	—	
	NOTE: A diagram must be attached to this form – Diagram to show: Construction of walls (exterior, interior, division and curtain), Height(s), Outline of building(s) within 40 ft. of risk, fences, natural obstacles, hydrants. Scale 50 ft. = 1 inch or 100 ft. = 1 inch.		
	Communicating Structures – Does building communicate with another structure by:		
	(a) Standard Class "A" fire doors in masonry walls ☐ Yes ☐ No		
	(b) One storey and/or basement passageway without fire door cut off ☐ Yes ☐ No		
	(c) Unprotected doorway openings in masonry wall (Code 054 only – Schools) ☐ Yes ☐ No		
	NOTE: In each of (a), (b), (c) above, separate surveys are required on each section.		
14-FAULTS OF MANAGEMENT OR POOR MAINTENANCE – (Other than charged under Occupancy)	Describe: none of note	—	
	TOTALS	83	.05
	Less Deductions	-05	
	80% Gross Bldg. Rate	78	
	No Co. Gross Bldg. Rate	104	

IBC Ind. Code(s)	IAO Rate Code(s) Occ'y	C/P 2	IBC Codes: Terr 6 3 · Ind 6 6 1 · Cons 4 · Prot 2	Contents Factor	No Co.	80% Co.	N.T. Rates	80% Co.
661	075		Building (1-CB-0) (1960's)	–	104	78	x .54	.421
				%				
				%				
–			Technical (School) Equipment	%				
–			Computer Contents	%				
661	085		Office Contents	%				
			Pipe Organ Contents	110%	115	86	x .50	.430
–			Dwelling Contents	%				
				%				

Requested by: Royal Ins. Report No.
Date: Nov. 1981

Initial: C.R.
Date: Nov. 25/81

DEC 2 1981

2.

OCCUPANCY (& PROCESS IF ANY)

NAME OF RISK: (Name of building and/or (Owner)) Stan Berna Ltd

LOCATION: (i.e. Municipal address) No. 1064 St Laurent Blvd. Ottawa

Sheet No. 256
Block No. 2022
Plan No.
NOP ☑ See Diagram ☐

OCCUPANCY BY FLOOR: Report briefly on:
(indicate any vacant section(s))
(i) Heating and location; (ii) Special hazards and processes if any; (iii) Location, number and type of extinguishers;
(iv) Any other exceptional feature of the risk, including heavy exposures; (v) Automatic Fire Alarm Detection System(s) and have Survey (form) completed.

Basement: not in use, O F.W.A gas furnace
O68C

1st. Floor: Performance Motors - Fiat, Mazda, Suzuki auto dealer sales offices.
O 2A
no repair shop.

2nd. Floor: —

3rd. Floor: —

Other Floors: —

3.

GENERAL UNDERWRITING COMMENTS

(a) **HOUSEKEEPING & MAINTENANCE:** Excellent ☐; Good ☑; Average ☐; Poor ☐, (If so, describe): (see charges under Faults of Management ☐);

(b) **NEIGHBOURHOOD:** Residential ☐; Commercial ☑; Industrial ☐; Congested Area ☐, (If so, describe):

(c) **OPINION OF RISK:** Excellent ☐; Good ☑; Average ☐; Poor ☐, (If so, describe): Number of Fire Divisions 1; (show on Plan and indicate openings)

(d) **APPROXIMATE AGE OF BUILDING:** 20 years. Additions: —

All Risk Report - 2004 MILAUR AUTOMOTIVE LTD. O/A MIDAS MUFFLER 1064 St. Laurent Blvd Ottawa ON K1K3B4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

CGI All Risk
INSPECTION REPORT

Supplement/s attached: ☒ Yes # of : ☐ No

1.0 BASIC INFORMATION

Insured:	Milaur Automotive Ltd. o/a Midas Muffler	**Policy Number**	
Date of survey (YYYY/MM/DD):	2004/11/18	**CGI Loss Control Specialist:**	Barry Cross
Person Contacted: Position	Greg Recoskie/Jean Guy	**Telephone No.**	(613) 829-7980
Mailing Address if Different for risk:	(unit # street # & name)	(City, Town, Village)	**CGI AIS No.: 11135706 Tracking No.: 5598812**
Location Surveyed:	1064 St Laurent Boulevard (unit # street # & name)	Ottawa (City, Town, Village)	Ontario (Province) K1K 3B4 (postal code)
Secondary address (If any)	(unit # street # & name)	(City, Town, Village)	(Province) (postal code)
IBC Territory Code	63	**IBC Building Ind. Code: 5523**	**SR/MA File No.**
Underwriter:		**Broker:**	

The ***CGI Risk•Score*** and comments contained in this report are based on conditions and practices observed during our survey and other pertinent data supplied by management personnel at the risk.

Recommendations in this report are made to point out those areas where remedial action could have the beneficial effect of making the above premises safer and thus more desirable from an underwriting standpoint.

Thank you for choosing CGI to perform this inspection. Please do not hesitate to contact us if we can be of any further assistance.

2.0 CGI Risk•Score

	1	2	3	4	5	6	7	8	9	Comments
Property				X						*Recommendations apply.*
Liability		X								*No unusual liability hazards noted.*
Crime		X								*No unusual crime hazards noted.*

(1=Excellent & 9=Poor)

Committed to Service Excellence

CGI reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from an inspection of the premises and/or from data supplied by or on behalf of the Purchaser. CGI does not purport to list all hazards. While changes and modifications referred to in the reports are designed to upgrade protection and loss prevention of the premises, CGI assumes no responsibility for management and control of these activities. CGI will not be responsible to the Purchaser for any losses or damages, whether consequential or other, however caused, incurred of suffered, as a result of the services being provided.

RISK ALERT ISSUED: ☐ **Yes** ☒ **No** **IF YES, DESCRIBE** (*A risk alert is a telephone notification to the Inspection requestor, of a situation which could imminently cause a serious loss. A Critical Recommendation will be issued to address the situation.)*

Meaning of the **CGI Risk•Score:** The CGI Score is a grading of the risk inspected versus other risks in this class. Similar to the "Commercial" Fire Protection Grading system in design, there is range of 9 categories, with a grading or "score" of 1 being the most desirable. The CGI Score is based on a number of objective criteria pertaining to the risk at the time of our survey, tempered with the experienced judgement of our Loss Control Specialist. As a general guideline, the scores mean the following criteria:

1-3	Risks in this range are well maintained, with no apparent moral hazards or management problems. Undesirable features are non-existent and recommendations, if any, are desirable. Risks in this category are excellent (no deficiencies) to better than average for their class.
4-6	The maintenance of Risks in this range is considered average. Moral hazards are not apparent, but there may be possible management problems (e.g. poor housekeeping). Undesirable features noted are correctable, and recommendations will vary from desirable to important. Risks in this category are considered average for their class.
7-9	Risks in this range tend to be poorly maintained. Moral hazards and management problems (e.g. poor housekeeping and maintenance, poor attitude) are evident. Significant undesirable conditions are present and cannot or will not be corrected. Critical Recommendations may be present. Risks in this category are significantly below average for their class with little or no indication for improvement.

3.0 REMARKS

This building appears to be well maintained and is situated in a busy commercial sector of the city. The extinguishers have not been serviced and are not properly distributed (Rec. made).
No special liability hazards were noted at the time of this survey.
No special crime hazards were noted at the time of this survey.

4.0 RECOMMENDATIONS

Please note that these recommendations are classified as either ☐ **Critical,** ☒ **Important, or** ☐ **Desirable Improvement**. **"Critical"** recommendations are those aimed at correcting undesirable feature/s which, if left unattended, could cause a serious loss and should be rectified immediately. This class of recommendation is only used in extreme situations. **"Important"** recommendations are intended to highlight undesirable feature/s which if left unattended, could cause a serious loss and should be rectified as soon as possible. **"Desirable Improvement"** recommendations are those aimed at correcting an undesirable feature which can be improved when feasible, to help reduce the risk of a loss.

☒ Listed below	or	☐ None

04-1	☐ Critical ☒ Important ☐ Desirable Improvement
	All portable fire extinguishers in your premises should be serviced and tagged by an authorized service contractor annually to ensure good working order in compliance with NFPA #10 Code standard requirements.

04-2	☐ Critical ☒ Important ☐ Desirable Improvement
	Portable fire extinguishers should be strategically installed in designated areas where they will be readily accessible and immediate1y available in the event of a fire in accordance with NFPA Standard No. 10, "Portable Fire Extinguishers".

04-3	☐ Critical ☒ Important ☐ Desirable Improvement
	Smoking in the building should be discouraged in accordance with the city by-law.

	☐ Critical ☐ Important ☐ Desirable Improvement

	☐ Critical ☐ Important ☐ Desirable Improvement

5.0 OCCUPANCY INFORMATION

The Insured is:	☐ Owner Occupant	☐ Non-occupant building owner	☒ Tenant
Insured's Occupancy Description: The entire building is occupied as a muffler repair shop with some mechanical repairs and oil changes.			
IBC Code: 5523	IBC Subcode: 00	Premises Intrusion Alarm: Acceptable	
Special Hazard Code(s):		Description:	
Name of building owner(if not Insured):	Unknown to employee.	Number of years bldg. Owned:	
Number of years at this location: 7	Area occupied (sq. m): 391	Business hours: 7:30am-6pm Mon.-Fri.; 8am-4pm Sat.	
Days per week: 6 days	Annual Revenue (optional):	Payroll (optional):	
Previous loss history past 3 years ☐ Yes ☐ No ☒ Undetermined		Previous loss history past 6 years ☐ Yes ☐ No ☒ Undetermined	
Explain loss history:			
Insured Values: Property: $		Contents: $255,000	
Combustibility of Occupancy: M3		Susceptibility of Occupancy: S3-Moderate Damage	

Occupancy: **Major Tenant is:** ☒ Insured or ☐ See Major Tenant Below		☒ refer to Occupancy Specific Supplement
Major Tenant in Building	Combustibility Code: --	Susceptibility Code: --
Name:	Area occupied (sq.m):	IBC Code:
Occupancy Description:		IBC Sub Code:
Special Hazard Code(s):	Description:	
Special Hazard Code(s):	Description:	
Previous loss history past 3 years ☐ Yes ☐ No ☐ Undetermined	Previous loss history past 6 years ☐ Yes ☐ No ☐ Undetermined	
Number of years at this location:	Premises Intrusion Alarm: --	
Other Classes of Occupants		
DESCRIBE PARTITION WALLS BETWEEN TENANTS:		
Name:	Area occupied (sq.m):	IBC Code:
Occupancy Description:		IBC Sub Code:
Special Hazard Code(s):	Description:	
Special Hazard Code(s):	Description:	
Previous loss history past 3 years ☐ Yes ☐ No ☐ Undetermined	Previous loss history past 6 years ☐ Yes ☐ No ☐ Undetermined	
Number of years at this location:	Premises Intrusion Alarm: --	
Name:	Area occupied (sq.m):	IBC Code:

Occupancy Description:	IBC Sub Code:
Special Hazard Code(s):	Description:
Special Hazard Code(s):	Description:
Previous loss history past 3 years ☐ Yes ☐ No ☐ Undetermined	Previous loss history past 6 years ☐ Yes ☐ No ☐ Undetermined
Number of years at this location:	Premises Intrusion Alarm: --
Areas not surveyed:	☐ For additional tenants see attached list
Comments:	

6.0 BUILDING CONSTRUCTION (IBC Major Construction Class 2)

Building condition:	☐ Above Average	☒ Average	☐ Moderate deficiencies	☐ Major deficiencies

Year built: (yyyy)	1970's	Area occupied by insured (sq. m): 391	Combustibility of Building M3
Ground floor area (sq. m):	391 sq. m	Total floor area (excl. bsmt.)	391 sq. m
Height (excluding basement):	6 m	Number of Stories: 5 (above grade)	
Basement: ☐ Yes ☒ No		Area of basement: - (sq. m)	Total area: 391 sq. m
Additions (year & brief description):	none		
Renovations (year & brief description):	none		

Wall construction:	Reinforced Concrete % ( )	Masonry: %: ( )	Non Combustible: 27%: (Metal/Steel Frame)	Brick/stone veneer: 73%: (BV/Steel Frame)	Wood frame: %: ( )
	Other: %, Describe:				
	Insulation:				
	Panels in Walls:	Glass: %	Combustible: %	Non Combustible: %	
Floor Construction:	Concrete: 100%	Concrete on metal pan: %	Wood joist: %		
	Other: %, Describe:				
Roof Type:	☒ Flat	☐ Quonset	☐ Peaked	☐ Other:	
Roof Construction:	☐ Concrete: %	☐ Steel deck: %	☐ Wood joist: %	☒ Steel/Steel: 100%	
	☐ Other Combustible: %		☐ Other Non Combustible: %		
Roof Surface:	☒ Tar & Gravel: %	☐ Metal: %	☐ Asphalt Shingles: %	☐ Wood Shakes: %	
	☐ Rubber membrane: %	☐ Other Combustible: %	☐ Other Non Combustible: %		
Resurfaced:	☒ No	☐ Yes	Date:		
Interior Finish Walls:	Combustible:	Ordinary Damage Material: %	Special Damage Material: %		
	Non Combustible: 100%		Open: %		
Interior Finish Ceilings:	Combustible:	Ordinary Damage Material: %	Special Damage Material: %		
	Non Combustible: 100%		Open: %		
Vertical Openings:	☒ None	☐ Stairs:	Protection Type: -- hrly. rate	☐ Elevator:	Protected: ☐ Yes ☐ No
	☐ Escalator: ☐ Open ☐ Enclosed	☐ Atrium: % of Grade Floor	# of Floors:		
	☐ Other:				
Horizontal Separation:	Major Partition Construction:	☒ Not Applicable	☐ Frame	☐ Drywall on Studs	
		☐ Concrete Block		☐ Other:	

	Proper Opening Protection:	☐ Yes	☐ No	☒ Not Applicable
Mezzanines: ☒ No ☐ Yes	Combustible: %	Non Combustible: %		
	Mezzanines Percentage of Floor below: % (if over 25% treated as an additional floor)			
Combustible Concealed Spaces:	☒ No	☐ Yes	If yes, %, and describe:	
Concealed space properly protected:	☐ No	☐ Yes	☒ Not applicable	Comment:
Building Description:	Shopping Mall: ☐ Yes ☒ No	Industrial Mall: ☐ Yes ☒ No	Strip Mall: ☐ Yes ☒ No	
	Stand Alone: ☒ Yes ☐ No	Other, Describe:		
Building Construction Comments:				

7.0 FIRE EXPOSURES (Within 50m of risk) ☐ None

Exposing Structures Within 50m:

	Distance	Height	Construction of Exposure Facing Wall	Exposure Occupancy Hazard	Exposure Hazard Description	Exposure Comb. Code	Opening in Facing Wall of Risk Yes	No
Front	_____ m	_____ sto.	--	--		--	☐	☐
Rear	*13* m	*2* sto.	Combustible	Light (L1,L2)	Dwelling	L2	☒	☐
Left	*18* m	*1* sto.	Combustible	Medium (M3,M4)	Convenience store.	M3	☒	☐
Right	*3* m	*1* sto.	Masonry	Medium (M3,M4)	Restaurant	M3	☐	☒

Exposing Structure Addresses:

Front:		Left:	
Rear:		Right:	
Comments: _____			

8.0 COMMON HAZARDS (Heating, electrical, plumbing)

HEATING:

Forced warm air:	☐ Electric	%	☐ Gas	%	☐ Oil	%	Solid Fuel	%	Other: _____	
Suspended unit heaters:	☐ Electric	%	☐ Gas	%	☐ Oil	%			Other: _____	
Portable heaters:	☐ Electric	%	☐ Gas	%	☐ Oil	%	Solid Fuel	%	Other: _____	
Hot water/steam	☐ Electric	%	☐ Gas	%	☐ Oil	%	Solid Fuel	%	Other: _____	
Solid Fuel Burning:	Non-Hazardous:	%, Describe _____			Hazardous:	%, Describe _____				
Other Hazardous:	%	Describe _____								
Other Non-Hazardous:	100%	Describe *Radiant*								
Electric baseboard units:	☐ %									
Installation Appears Safe:	☒ Yes	☐ No	Describe: _____							
Unheated	☐ %	Borrowed Heat: ☐ %								
Boiler:	☐ Yes	☒ No	Age: _____ and Make: _____		Date of last Boiler Inspection: (yyyy/mm/dd) _____					
Appliances enclosed in a non-combustible room:	☐ Yes	☒ No	☐ Not required							
Combustible materials stored in the room:	☐ Yes	☐ No	☒ Not applicable							
Heating Fuel Tanks:	☒ None	☐ Inside	☐ Outside	☐ Above ground	☐ Below ground	Age (yyyy) _____ Capacity (L) _____				
Fill and vent piping: Inside	☒ N/A	☐ No	☐ Yes, _____							
Chimneys:	☐ Masonry	☒ ULC Factory built	☐ Unlabelled pre-fab	☐ Other: _____						
	☒ Standard	☐ Non-standard _____								
Installation defects:	☒ None	☐ Moderate	☐ Major, _____							
Installation replaced:	☒ No	☐ Yes	(yyyy) _____ and _____%							

_____% Air Conditioned	Type:	☐ Roof-Top	☐ Central	☐ Other: _____
Comments: _____				

ELECTRICAL:

Type:	☒ Conduit	☒ BX	☐ Non-metallic	☐ Knob & Tube _____	☐ Other: _____
Temporary wiring or extension cords:	☒ No	☐ Yes _____			
Overcurrent protection:	☒ Circuit Breakers	Fuses:	☐ Ordinary	☐ Type P	☐ Type D ☐ Other: _____
Installation defects:	☒ None	☐ Moderate	☐ Major		
Installation (wiring) replaced:	☒ No	☐ Yes	(yyyy)_____ and _____%		
Installation Appears Safe:	☒ Yes	☐ No	Describe: _____		
Partial changes/extensions:	☒ No	☐ Yes Describe: _____			
Comments: _____					

PLUMBING:

Type:	☒ Copper	☐ Galvanized	☐ Plastic	☐ Other: _____
Installation Replaced:	☒ No	☐ Yes	(yyyy) _____ and _____%	
Condition:	☒ Good	☐ Fair	☐ Poor _____	
Installation appears safe:	☒ Yes	☐ No: _____		
Comments: _____				

SMOKING:

Smoking Restricted:	☐ Yes	☒ No			
"No Smoking" Signs posted:	☐ Yes	☒ No	Enforced:	☐ Yes	☒ No
Comments: *Rec. made.*					

HOUSEKEEPING:

☐ Good	☒ Average	☐ Poor	☐ Unacceptable
Comments: _____			

9.0 FIRE PROTECTION

PUBLIC:

F.U.S. Protection Class: *03*	Primary Responding Fire Department: *Ottawa H.P.A.*		Bldg. Prot. Code (NS or AS): *2*	
☒ Full time	☐ Part Time/Volunteer		☐ Composite	
Distance to Fire Department:	*≤2* km			
Roads: ☒ Paved ☐ Unpaved	Accessible Year-round: ☒ Yes ☐ No		Congested/Inaccessible: ☐ Yes ☒ No	
Water Supply:	☒ Public	☐ Private		
Number of Hydrants:	*2* within 155 m,	_____ within 156 - 305 m,	_____ Over 305 m,	☐ None

PRIVATE:

The following appeared to be satisfactory:

	Yes	No		Date Last Serviced	Comments
Portable Extinguishers	☐	☒		*Jan./2002*	*Rec. made.*
Standpipe/Inside Hoses	☐	☐	N/A ☒	_____	_____
Watchman Service	☐	☐	N/A ☒	_____	_____
Fire Detection System:	☒ None	☐ Full	☐ Partial, Describe:	_____	
i) Type of Detectors:	_____				
ii) Detector location:	Describe: _____				

iii) Maintenance contract:	Yes ☐	No ☐	Company: _____	Telephone #: _____
iv) Connected to:	☐ ULC Listed Station	☐ Unlisted Service	☐ Fire/Police Department	☐ Local only
	☐ Other: _____			
Name of Company:	_____			
Automatic Sprinkler Protection:	☒ None	☐ Full Premises	☐ Partial (describe): _____	
	Sprinkler Supplement Attached	☐ Yes	☐ No (Sprinkler System Not Tested or Evaluated)	
Fire Protection Comments: _____				

10.0 ALL RISK:

Information Confirmed by: ☒ Person Contacted or: Jean Guy (Manager)

EARTHQUAKE

What is the earthquake zone:	2		
Is there any earthquake history in the area:	☐ No	☒ Yes	☐ Undetermined
If **Yes**, describe history Light tremors.			
Significant exterior wall or foundation cracks noted?	☒ No	☐ Yes	Describe: _____
Sagging?	☒ No	☐ Yes	Describe: _____
Comments: _____			

FLOOD

Is this establishment located on a flood plain:	☒ No	☐ Yes	
Is it located near a body of water:	☒ No	☐ Yes	Describe: _____
Distance to nearest body of water:	_____	☒ None determined	
Is there a history of flooding:	☒ No	☐ Yes	If **yes**, give history: _____
Evidence of water damage:	☒ No	☐ Yes	Describe: _____
Years knowledge of risk: 2			
Comments: _____			

WATER DAMAGE

Plumbing is:	☒ Copper	☐ Galvanized	☐ Plastic	☐ Other	Describe: _____
Is there evidence of corrosion:			☒ No	☐ Yes	Describe: _____
Is the building sprinklered:			☒ No	☐ Yes	Comment: _____
Is stock susceptible to water damage:			☒ No	☐ Yes	Describe: _____
Are all window/skylight openings adequately sealed:			☒ Yes	☐ No	Describe: _____
Does water main pass under building:			☒ No	☐ Yes	Describe: _____
Is the roof covering adequate:			☒ Yes	☐ No	Most recent roof repair date: _____
Inside and/or roof storage tanks/process equipment:			☒ No	☐ Yes	Describe: _____

Tanks/equipment satisfactorily controlled:	☐ No	☐ Yes	If Either Describe: _____
Is there use of: ☐ Skids ☒ Shelving	☐ Floor Drains		☐ Covers over stock/equipment
Sewer Backup claim in the last three years:	☒ No	☐ Yes	☐ Describe: _____
Comments: _____			

COLLAPSE AND/OR SEWER BACKUP

Is there any history of collapse:	☒ No	☐ Yes	Describe: _____
Is there any history of sewer back-up:	☒ No	☐ Yes	Describe: _____
Are sewer back-up protection devices in place:	☒ No	☐ Yes	Describe: _____
Comments: _____			

ADDITIONAL PERILS

If Yes, Describe:

Is lightning protection in place:		☒ No	☐ Yes	Describe: _____		
Is risk located within 5 km of airport:		☒ No	☐ Yes	Beneath a flight path:	☐ Yes	☐ No
Is the yard fenced: ☒ No		☐ Yes	Are gates locked when the premises are closed:		☐ Yes	☐ No
Is the yard and the exterior of the building lit:		☐ No	☒ Yes	Describe: _____		
Is the risk located in a high wind/hail area:		☒ No	☐ Yes	Describe: _____		
Are there visible signs of vandalism at the risk:		☒ No	☐ Yes	Describe: _____		
In the area:		☒ No	☐ Yes	Describe: _____		
Is the risk protected from Impact exposure:	Automobile	☐ No	☒ Yes	Describe: _____		
	Aircraft	☒ No	☐ Yes	Describe: _____		
	Train	☐ No	☐ Yes	Describe: n/a		
	Boat	☐ No	☐ Yes	Describe: n/a		
Comments: _____						

11.0 BASIC PREMISES LIABILITY

The following appeared to be satisfactory: If No Describe				
Stairs, Ramps & Handrails:	Yes ☒	No ☐	N/A ☐	Comments: _____
Floor Surfaces & Coverings:	Yes ☒	No ☐	N/A ☐	Comments: _____
Walls & Ceilings:	Yes ☒	No ☐	N/A ☐	Comments: _____
Interior & Exterior Lighting:	Yes ☒	No ☐	N/A ☐	Comments: _____
Emergency Lighting:	Yes ☒	No ☐	N/A ☐	Comments: _____
Interior & Exterior Housekeeping:	Yes ☒	No ☐	N/A ☐	Comments: _____
Washrooms:	Yes ☐	No ☐	N/A ☒	Comments: _____
Sidewalks, Yards & Parking Lots:	Yes ☒	No ☐	N/A ☐	Comments: _____
Fire Exits:	Yes ☒	No ☐	N/A ☐	Comments: _____
Fire Alarm System (s):	Yes ☐	No ☐	N/A ☒	Comments: _____
Snow & Ice Removal:	Yes ☒	No ☐	N/A ☐	Comments: _____
Elevating devices:	Yes ☐	No ☐	N/A ☒	Comments: _____
Satellite Dishes:	Yes ☐	No ☐	N/A ☒	Comments: _____

Exterior Signs:	Yes ☒	No ☐	N/A ☐	Comments: _____	
CO detectors where required:	Yes ☐	No ☐	N/A ☒	Comments: _____	
Swimming Pool:	Yes ☐	No ☐	N/A ☒	Comments: _____	
Other:	Yes ☐	No ☐	N/A ☒	Comments: _____	
Comments: _____					

12.0 BASIC CRIME

☐ Refer to Expanded Crime Supplement

Crime Experience	☐ Low	☒ Moderate	☐ High		
Type of Neighbourhood:	☒ Commercial	☐ Industrial	☐ Rural	☐ Residential	☐ Isolated
Neighbourhood appears to be:	☒ Stable	Changing via:	☐ Expansion/growth	☐ Renovation	☐ Deterioration
Comments: _____					

BUSINESS

Automatic Teller Machine:	☒ No	☐ Yes		
Safe on Premises:	☒ No	☐ Yes	☐ Unable to Determine	
Guard Service:	☒ No	☐ Yes	☐ Unable to Determine	Describe: _____
Typical Stock:	_____			
Smash & Grab exposure:	☒ No	☐ Yes	☐ Unable to Determine	
Comments: _____				

GENERAL PROTECTION

The following appeared to be satisfactory: If No Describe

Exterior Lighting:	☒ Yes	☐ No	☐ N/A	Comments: _____
Interior Lighting:	☒ Yes	☐ No	☐ N/A	Comments: _____
Roof Accessibility:	☒ Yes	☐ No	☐ N/A	Comments: _____
Police Patrols:	☒ Yes	☐ No	☐ N/A	Comments: _____
Yard Fenced:	☐ Yes	☐ No	☒ N/A	Describe: _____
Comments: _____				

SECURITY ALARM SYSTEM

Premises alarm system in use:	☐ N/A	☒ Yes	☐ No	☐ Disconnected	Date Installed: (yyyy)Unknown
Applies to:	☒ Building	☐ Insured Tenant	☐ Other, Describe: _____		
Alarm System is:	☒ Acceptable	☐ Unacceptable (see rec.)			
Monitored by:	☐ ULC Listed Station	☒ Unlisted Station	☐ Local Alarm	☐ Unknown	☐ Unable to Determine
Comments: _____					

PHYSICAL PROTECTION

Door locks:	☒ Deadbolt	☐ Spring	☐ Panic	☐ Other: _____	
Windows Protected:	☒ No	☐ Yes	☐ N/A	If **yes**, describe _____	
Other Openings:	☒ No	☐ Yes	Protected:	☐ No	☐ Yes
Comments: _____					

OTHER COMMENTS:

_____

CGI Information Systems and Management Consultants Inc.

GARAGE/AUTO BODY SHOP
INSPECTION REPORT SUPPLEMENT
CONFIDENTIAL

Location Surveyed: 1064 St. Laurent Boulevard Ottawa, Ontario	**CGI AIS No.: 11135706**
Date of survey (YYYY/MM/DD): 2004/11/18	**CGI Loss Control Specialist:** Barry Cross

1.0 PRINCIPAL OCCUPANCY

☐ Auto Dealer	☒ Auto Repair Shop	☐ Body Shop or Paint Shop	☐ Small Engine repair
☐ Metalworker	☐ Fiberglass Worker	☐ Other _____	
Spray Painting Supplement Attached:	☐ Yes	☒ No	

AUTO REPAIR, SERVICING OR REFINISHING:

Type of Vehicles Serviced: Cars and light trucks.				
Number of Service Bays: 7				
Number of Staff: 5	Licensed: 4	Unlicensed: _____	Apprentices: _____	
Number of Supervisors /Management per Shift:	_____	Licensed Also:	☐ Yes	☒ No
Are checklists followed on all work performed:	☒ Yes	☐ No		
Is all completed work checked prior to vehicle release:	☒ Yes	☐ No		
Average number of customer vehicles on lot:	Daytime: 6	Night Time: 0		
Vehicle sales:	☐ Yes	☒ No	How many: _____	
Towing Service	☐ Yes	☒ No	Number of Tow trucks : _____	
Propane/Natural Gas conversion performed:	☒ No	☐ Yes	Describe: _____	
Courtesy / Rental Vehicles offered	☒ No	☐ Yes	Describe: _____	
Gas Tank Repairs	☐ No	☒ Yes	Describe: _____	
If Yes, gas retrieval system used?	☐ No	☒ Yes	Describe: Gas caddy.	
Comments: _____				

2.0 RECORD KEEPING

Orderly Records Maintained:	☒ Yes	☐ No	
Types:	☐ Complaints	☒ Customer Files	
	☐ Work Performed	☒ Job Specifications	
	☐ Testing Done	☐ Other _____	
Records Reviewed / Audited:	☒ Yes	☐ No	Frequency: At random.

Committed to Service Excellence

CGI reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from an inspection of the premises and/or from data supplied by or on behalf of the Purchaser. CGI does not purport to list all hazards. While changes and modifications referred to in the reports are designed to upgrade protection and loss prevention of the premises, CGI assumes no responsibility for management and control of these activities. CGI will not be responsible to the Purchaser for any losses or damages, whether consequential or other, however caused, incurred of suffered, as a result of the services being provided.

	Done By: Midas
Type of Subcontracted Work:	_____
Comments: _____	

3.0 SPECIAL HAZARDS

The following appeared to be satisfactory: If "No" describe:

	Yes	No	N/A	Comments
Flammable Liquids	☒	☐	☐	_____
Hot Work	☒	☐	☐	_____
Solvent Recycling	☒	☐	☐	_____
Undercoating	☒	☐	☐	_____
Parts Washing	☒	☐	☐	_____
Fiber-glassing	☐	☐	☒	_____
Other: _____	☐	☐	☐	_____
Comments: _____				

4.0 STORAGE TANKS ☐ None

Operated by:	☐ Insured	☐ Corporation	☐ Other	Hours of Operation: _____
Number of Pumps:	Gas _____	Full Service _____	Self-Serve _____	
	Diesel _____	Full Service _____	Self-Serve _____	
	Propane _____	Full Service _____	Self-Serve _____	

Propane Dispensers Licensed:	☐ Yes	☐ No	
All pumps/tanks protected by crash guards:	☐ Yes	☐ No	Remarks: _____
Are level measurements taken:	☐ Yes	☐ No	
Frequency:	☐ Daily	☐ Other: _____	Record kept: ☐ No ☐ Yes
Is Insured aware of who to contact in the event of a spill or emergency:	☐ Yes	☐ No	
Emergency telephone numbers posted:	☐ Yes	☐ No	
Is a non-combustible absorbent material available:	☐ No	☐ Yes	If Yes, what: _____
Fire Extinguisher located on or near pump island:	☐ Yes	☐ No	

Above Ground	Under Ground	Age	Capacity (litres)	Contents	Inside	Outside	Construction
☒	☐	*6*	*803*	*new oil*	☒	☐	*steel*
☒	☐	*10*	*900*	*used oil*	☒	☐	*steel*
☐	☐	_____	_____	_____	☐	☐	_____
☐	☐	_____	_____	_____	☐	☐	_____
Comments: _____							

5.0 TIRE STORAGE

	New	Used	Number of Tires (average)	Dollar Value
Tires stored inside	50	_____	60	*$8000*
Tires Stored outside	_____	_____	_____	$ _____
Stored in trailer outside	_____	_____	_____	$ _____
Stored in outbuilding	_____	_____	_____	$ _____
Comments: _____				

6.0 ELECTRONIC EQUIPMENT

Specialized Diagnostic Equipment:		☒ Yes	☐ No			
Source:		☒ Local	☐ United States	☐ Foreign		
Approximate Value:		$_____	☒ Undetermined			
Availability of Replacement:		☒ Yes	☐ No			
Reciprocal Agreement for Temporary Use:		☐ Yes	☒ No			
Electronic Data Processing:	☐ Main Frame	☐ Mini System	☒ PC Stand Alone	Age: Unknown	Approx. Value: $Unknown	
Is equipment:	☒ Owned	☐ Leased				
Is all equipment in one room	☒ Yes	☐ No	where Office section.	Connected to central location:	☐ Yes	☒ No
Surge Protection:	☒ Yes	☐ No	Adequate:	☒ Yes	☐ No	
Data properly backed-up and stored:	☒ Yes	☐ No	Frequency: _____			
Data Storage/back-up copy taken off premises:	☒ Yes	☐ No				
Describe other systems & users:	_____					
Comments: _____						

7.0 SIGNS

Exterior Signs						
Construction:	☐ Wood	☒ Metal	☐ Glass	☒ Plastic	☐ Other _____	☐ Not Applicable
Location	☒ Mounted on wall		☐ Mounted on roof		☒ Self-supported	☐ Other _____
Properly Secured:	☒ Yes		☐ No _____			
Overall Condition:	*Good*					
Comments: _____						

8.0 ADDITIONAL COMMENTS: (if required)

_____

Enviroscan Report

Site address:	1052, 1060 & 1064 St. Laurent Boulevard, Ottawa, ON
Project #:	24102901203
P.O. #:	160674
Requested by:	Eleanor Goolab
Date Completed:	6/12/2025 5:37:17 PM

CONFIDENTIAL

Project #: 24102901203 | P.O. #: 103499.002
Requested by: Eleanor Goolab | Date Completed: 06/12/2025 17:37:17

Search Area: 1052, 1060 & 1064 St. Laurent Boulevard, Ottawa, ON



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Project #: 24102901203 | P.O. #: 103499.002
Requested by: Eleanor Goolab | Date Completed: 06/12/2025 17:37:17

Historical Environmental Services Enviroscan Terms and Conditions

Terms and Conditions

Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Verisk's records relating to the described property (hereinafter referred to as the "Property"). Verisk makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Verisk's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Verisk does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

Disclaimer

Verisk disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Verisk Reports or from any tortious acts or omissions of Verisk's agents, employees or representatives.

Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.

Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

Project #: 24102901203 | P.O. #: 103499.002
Requested by: Eleanor Goolab | Date Completed: 06/12/2025 17:37:17

Report Index

Page **Report Title**

5 (1970) Siteplan Report - 1970 MR. E. DE SOUSA 1052-1056 St. Laurent Boulevard Ottawa ON K1K3B4 (distance = 0 metres*)

7 (1996) Siteplan Report - 1996 STAN BERNARD AUTOMOBILE LTD 1064 St. Laurent Boulevard Ottawa ON K1K3B4 (distance = 0 metres*)

9 (1983) Siteplan Report - 1983 PERFORMANCE MOTORS 1064 St. Laurent Boulevard Ottawa ON K1K3B4 (distance = 0 metres*)

Project #: 24102901203 | P.O. #: 103499.002
Requested by: Eleanor Goolab | Date Completed: 06/12/2025 17:37:17

Siteplan Report - 1970 MR. E. DE SOUSA 1052-1056 St. Laurent Boulevard Ottawa ON K1K3B4

DIAGRAM

(Note: — A Diagram is not required if the Risk and all property within 100 feet is exactly as shown on the insurance plan.)

Show all Buildings within 50 feet of the Risk and describe their occupancy, show also any openings between adjoining Buildings and all exposed Windows.

Show location of Hydrants

Show Frame Buildings with BLACK, Brick Building with RED, Stone or Concrete Buildings with BLUE and Brick Veneered, Brick Nogged or Metal Clad Buildings with DOTTED RED lines for which purpose a red pencil can be used. Be sure to state exact distance between buildings shown.

Please Draw Diagram at a scale of 50 feet = 1 inch (same as the Insurance Plans).

NORTH



WEST **EAST**

SOUTH

EXPOSURE: Note — These questions must be answered fully.

North 40 ft. to building built of DWG. stories high, occupied as .....

South 25' " " MASONRY 1 " " RESTAURANT

East ST. " " — " " —

West OPEN " " — " " —

I hereby state that the above questions are fully and correctly answered, and agree that they shall form the basis of rating to be given by the C.U.A.

DATE Dec. 8 , 19 70 SIGNATURE H. Lefort.
(State whether Owner, Occupant or Architect)

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

Project #: 24102901203 | P.O. #: 103499.002
Requested by: Eleanor Goolab | Date Completed: 06/12/2025 17:37:17

Siteplan Report - 1996 STAN BERNARD AUTOMOBILE LTD 1064 St. Laurent Boulevard Ottawa ON K1K3B4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.



INSURED: STAN BERNARD AUTOMOBILE LTD
LOCATION: 1064 ST LAURENT BLVD
OTTAWA, ONT
SCALE: 1" = 50'
FILE NO. 90 CM025199Z

Insurers' Advisory Organization (1989) Inc.
REPRESENTATIVE: DONNA JOHNSON
DATE: Oct 8/96

LCED.301.0291

Project #: 24102901203 | P.O. #: 103499.002
Requested by: Eleanor Goolab | Date Completed: 06/12/2025 17:37:17

Siteplan Report - 1983 PERFORMANCE MOTORS 1064 St. Laurent Boulevard Ottawa ON K1K3B4

DIAGRAM IAO PLAN: Sheet No. 56; Block No. 2022; Plan No. _____ OP ☑; Scale: 1cm = 6m ☑ 1cm = 12m ☐

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.



EXPOSURE - (SECTION VIII)

WALL OF BUILDING BEING RATED					BETWEEN BLDGS.		FACING WALL OF EXPOSURE						
Direction	Blnk.	Comb. & Non-Comb	Msnry. Up	Msnry. Sp	Distance	Party Wall	Blnk.	Msnry. Sp	Msnry. Up	Non-Comb.	Comb.	Occ'y Haz.	Length / Height
NORTH			✓		50'				✓			M3	60'
SOUTH			✓		60'				✓			M3	90'
EAST			✓		200'				✓			M3	
WEST			✓		65'						✓	L2	UNS. 100'

Requested by: General Accident.

Sig. Of Insp. C. Laflin

Dt. April 26/83 (Inspected) / May 2/83 (Written Up)

Report Date: April 15/83 (Dt. Request Recd. In IAO Service Office)

Revised By: _____

Dt. _____ / _____

ONT. 2000c - 9/81

Office

175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

1.877.244.9437

optaintel.ca

Verisk.com

©Verisk Analytics Inc. All rights reserved.

CONFIDENTIAL

APPENDIX D

Chain of Title

CHAIN OF TITLE REPORT

Project #: 24102901203
Address: 1052 St. Laurent Blvd., Ottawa
Legal Description: Part Lot 1 Plan 79 as in OT74832 Ex OT78524

PIN #: 04253-0270 (LT)

Searched at: Ottawa
LRO #: 4

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent (100 Acres)	26 06 1846	Crown	**John SHARPE**
2661	Deed	07 10 1875	John Sharpe	Frederick SPARKS Charles WOLFF
79	Plan	12 04 1877	Federick Sparks Charles Wolff	Esther S. WOLFF
31502	Deed	23 03 1922	Esther S. Wolff	James C. S. WOLFF
31503	Deed	23 03 1922	James C. S. Wolff	Charles A. SEGUIN
35616	Deed	23 03 1931	Charles A. Seguin	Julien LANTHIER
37667	Deed	05 10 1937	Julien Lanthier	Leopold CYR
41268	Deed	25 06 1945	Leopold Cyr	Noel BRAULT
GL41461	Deed	12 09 1945	Noel Brault	Louis BARTHELETTE

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #: 24102901203
Address: 1052 St. Laurent Blvd., Ottawa
Legal Description: Part Lot 1 Plan 79 as in OT74832 Ex OT78524

Searched at: Ottawa
LRO #: 4

PIN #: 04253-0270 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
GL43555	Deed	27 06 1947	Louis Barthelette	James H. CARSON
OT62690	Deed	30 09 1964	James H. Carson	Hain Holdings Limited
OT74832	Deed	15 04 1967	Hain Holdings Limited	Manuel DE SOUSA
N696466	Deed	22 06 1994	Manuel De Sousa	Manuel DE SOUSA Beatriz DE SOUSA
AT1242927	Deed	08 11 1999	Manuel De Sousa Beatriz De Sousa	Federal Superannuates National Association
OC1786365	Name Change	12 05 2016	Federal Superannuates National Association	National Association of Federal Retirees
OC1787760	Deed	17 05 2016	National Association of Federal Retirees	2505531 Ontario Ltd.
OC2353537	Deed **(Present Owner)**	31 05 2021	2505531 Ontario Ltd.	**Stan Bernard Automotive Limited**

PROPERTY DESCRIPTION: PT LT 1, PL 79 , AS IN OT74832 EXCEPT OT78524; OTTAWA/GLOUCESTER

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
FIRST CONVERSION FROM BOOK 95

PIN CREATION DATE:
1997/01/27

OWNERS' NAMES
STAN BERNARD AUTOMOTIVE LIMITED

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1997/01/27 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1997/01/27						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1997/01/25 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1997/01/27 ***						
N696466	1994/06/22	TRANSFER		*** COMPLETELY DELETED ***	DE SOUSA, MANUEL DE SOUSA, BEATRIZ	
LT1242927	1999/11/08	TRANSFER		*** COMPLETELY DELETED *** DE SOUSA, MANUEL DE SOUSA, BEATRIZ	FEDERAL SUPERANNUATES NATIONAL ASSOCIATION	
	REMARKS: PLANNING ACT STATEMENTS					
OC1754859	2016/01/08	APL DEL EXECUTION		*** COMPLETELY DELETED *** FEDERAL SUPERANNUATES NATIONAL ASSOCIATION		
	REMARKS: DELETE S/T EXECUTION NO. 95-005405					
OC1784043	2016/05/03	LR'S ORDER		LAND REGISTRAR, OTTAWA-CARLETON LAND REGISTRY OFFICE		C
	REMARKS: AMENDING THE DESCRIPTIONS OF 04265-0031 AND 04253-0270 AND INSTRUMENT LIST OF 04265-0031					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
OC1786365	2016/05/12	APL CH NAME OWNER		*** COMPLETELY DELETED *** FEDERAL SUPERANNUATES NATIONAL ASSOCIATION	NATIONAL ASSOCIATION OF FEDERAL RETIREES	
OC1787760	2016/05/17	TRANSFER		*** COMPLETELY DELETED *** NATIONAL ASSOCIATION OF FEDERAL RETIREES	2505531 ONTARIO LTD.	
	REMARKS: PLANNING ACT STATEMENTS.					
OC1787761	2016/05/17	CHARGE		*** COMPLETELY DELETED *** 2505531 ONTARIO LTD.	BANK OF MONTREAL	
OC1787762	2016/05/17	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** 2505531 ONTARIO LTD.	BANK OF MONTREAL	
	REMARKS: OC1787761					
OC2353537	2021/05/31	TRANSFER	$2,750,000	2505531 ONTARIO LTD.	STAN BERNARD AUTOMOTIVE LIMITED	C
	REMARKS: PLANNING ACT STATEMENTS.					
OC2353538	2021/05/31	CHARGE		*** COMPLETELY DELETED *** STAN BERNARD AUTOMOTIVE LIMITED	THE BANK OF NOVA SCOTIA	
OC2353539	2021/05/31	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** STAN BERNARD AUTOMOTIVE LIMITED	THE BANK OF NOVA SCOTIA	
	REMARKS: OC2353538					
OC2404629	2021/09/27	DISCH OF CHARGE		*** COMPLETELY DELETED *** BANK OF MONTREAL		
	REMARKS: OC1787761.					
OC2421401	2021/11/09	CHARGE	$25,000,000	STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C
OC2421412	2021/11/09	NO ASSGN RENT GEN		STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C
	REMARKS: OC2421401. OC2421401					
OC2421647	2021/11/10	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE BANK OF NOVA SCOTIA		
	REMARKS: OC2353538.					



ServiceOntario

PRINTED ON 20 JUN, 2025 AT 16:05:55
FOR BERTUCCI

SCALE

0 20 40 60 80 meters

PROPERTY INDEX MAP

OTTAWA-CARLETON(No. 04)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© King's Printer for Ontario, 2025

CHAIN OF TITLE REPORT

Project #: 24102901203
Address: 1060 St. Laurent Blvd., Ottawa
Legal Description: Part Lots 1 & 2 Plan 79 as in OT63102

Searched at: Ottawa
LRO #: 4

PIN #: 04253-0271 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent **(100 Acres)**	26 06 1846	Crown	**John SHARPE**
2661	Deed	07 10 1875	John Sharpe	Frederick SPARKS Charles WOLFF
79	Plan	12 04 1877	Federick Sparks Charles Wolff	Esther S. WOLFF
31502	Deed	23 03 1922	Esther S. Wolff	James C. S. WOLFF
31503	Deed	23 03 1922	James C. S. Wolff	Charles A. SEGUIN
35616	Deed	23 03 1931	Charles A. Seguin	Julien LANTHIER
37667	Deed	05 10 1937	Julien Lanthier	Leopold CYR
41268	Deed	25 06 1945	Leopold Cyr	Noel BRAULT
GL41461	Deed	12 09 1945	Noel Brault	Louis BARTHELETTE

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #: 24102901203 **Searched at:** Ottawa
Address: 1060 St. Laurent Blvd., Ottawa **LRO #:** 4
Legal Description: Part Lots 1 & 2 Plan 79 as in OT63102

PIN #: 04253-0271 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
GL41990	Deed	09 04 1946	Louis Barthelette Jr.	Louis BARTHELETTE, Sr.
GL45800	Deed	27 08 1947	Louis Barthelette Sr.	Raoul LEROUX Aurora LEROUX
OT63102	Deed	29 10 1964	Raoul Leroux Aurora Leroux	Donald ENG Gam ENG
OC394202	Deed	19 10 2004	Gam Eng - Estate	Donald ENG
OC399137	Deed	29 10 2004	Donald Eng	2053943 Ontario Inc.
OC2166130	Deed	15 11 2019	2053943 Ontario Inc.	2644545 Ontario Inc.
OC2412538	Name Change **(Present Owner)**	18 10 2021	2644545 Ontario Inc.	**Stan Bernard Automotive Limited**

* CERTIFIED IN ACCORDANCE WITH THE LAND TITLES ACT * SUBJECT TO RESERVATIONS IN CROWN GRANT *

PROPERTY DESCRIPTION: PT LTS 1 & 2, PL 79 , AS IN OT63102 ; OTTAWA/GLOUCESTER

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
FIRST CONVERSION FROM BOOK 95

PIN CREATION DATE:
1997/01/27

OWNERS' NAMES
STAN BERNARD AUTOMOTIVE LIMITED

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1997/01/27 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1997/01/27						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1997/01/25 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1997/01/27 ***						
OT63102	1964/10/29	TRANSFER		*** COMPLETELY DELETED ***	ENG, DONALD ENG, GAM	
OC394202	2004/10/19	APL OF SURV-LAND		*** COMPLETELY DELETED *** ENG, GAM	ENG, DONALD	
OC399137	2004/10/29	TRANSFER		*** COMPLETELY DELETED *** ENG, DONALD	2053943 ONTARIO INC.	
REMARKS: PLANNING ACT STATEMENTS						
OC399138	2004/10/29	CHARGE		*** COMPLETELY DELETED *** 2053943 ONTARIO INC.	THE CANADA TRUST COMPANY	
OC540096	2005/11/30	CHARGE		*** COMPLETELY DELETED *** 2053943 ONTARIO INC.	THE TORONTO-DOMINION BANK	

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
OC589778	2006/05/08	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE CANADA TRUST COMPANY		
	REMARKS: RE: OC399138					
OC2166130	2019/11/15	TRANSFER	$950,000	2053943 ONTARIO INC.	2644545 ONTARIO INC.	C
OC2166131	2019/11/15	CHARGE		*** COMPLETELY DELETED *** 2644545 ONTARIO INC.	THE BANK OF NOVA SCOTIA	
OC2168193	2019/11/22	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE TORONTO-DOMINION BANK		
	REMARKS: OC540096.					
OC2412538	2021/10/18	APL CH NAME OWNER		2644545 ONTARIO INC.	STAN BERNARD AUTOMOTIVE LIMITED	C
OC2421401	2021/11/09	CHARGE	$25,000,000	STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C
OC2421412	2021/11/09	NO ASSGN RENT GEN		STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C
	REMARKS: OC2421401. OC2421401					
OC2421648	2021/11/10	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE BANK OF NOVA SCOTIA		
	REMARKS: OC2166131.					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.



ServiceOntario

PRINTED ON 20 JUN, 2025 AT 16:03:00
FOR BERTUCCI

SCALE

0 20 40 60 80 meters

PROPERTY INDEX MAP

OTTAWA-CARLETON(No. 04)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© King's Printer for Ontario, 2025

CHAIN OF TITLE REPORT

Project #: 24102901203
Address: 1064 St. Laurent Blvd., Ottawa
Legal Description: Part Lots 2-4 Plan 79 NS 57788 Ex Part 1, 5R11050

Searched at: Ottawa
LRO #: 4

PIN #: 04253-0272 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent (100 Acres)	26 06 1846	Crown	**John SHARPE**
2661	Deed	07 10 1875	John Sharpe	Frederick SPARKS Charles WOLFF
79	Plan	12 04 1877	Federick Sparks Charles Wolff	Esther S. WOLFF
31502	Deed	23 03 1922	Esther S. Wolff	James C. S. WOLFF
31503	Deed	23 03 1922	James C. S. Wolff	Charles A. SEGUIN
35616	Deed	23 03 1931	Charles A. Seguin	Julien LANTHIER
37667	Deed	05 10 1937	Julien Lanthier	Leopold CYR
41268	Deed	25 06 1945	Leopold Cyr	Noel BRAULT
GL41461	Deed	12 09 1945	Noel Brault	Louis BARTHELETTE

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #:	24102901203	**Searched at:**	Ottawa
Address:	1064 St. Laurent Blvd., Ottawa	**LRO #:**	4
Legal Description:	Part Lots 2-4 Plan 79 NS 57788 Ex Part1, 5R11050		
PIN #:	04253-0272 (LT)		

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
GL41990	Deed	09 04 1946	Louis Barthelette, Jr.	Louis BARTHELETTE, Sr.
42863	Deed	07 11 1946	Louis Barthelette, Sr.	The Director, The Veterans' Land Act
1070	Deed	18 04 1950	Louis Barthelette	Alfred BARTHELETTE
OT5927	Deed	25 09 1958	Alfred Barthelette	Georgette SAIKALY
OT53422	Deed	01 11 1962	The Director, The Veterans' Land Act	Charles BRAZEAU
OT63155	Deed (Lt 4)	02 03 1964	Charles Brazeau	Ronald TAYLOR Donald MACLAURIN
OT62495	Deed (Lts 2 & 3)	14 09 1964	Georgette Saikaly	Ronald TAYLOR Donald MACLAURIN
OT72595	Deed	06 09 1966	Ronald Taylor Donald MacLaurin	A & W Drive-In of Canada Ltd.
NS57788	Deed **(Present Owner)**	29 06 1979	A & W Food Services of Canada Ltd.	**Stan Bernard Automotive Limited**

PROPERTY DESCRIPTION: PT LTS 2, 3 & 4, PL 79 , AS IN NS57788 EXCEPT PT 1, 5R11050 ; OTTAWA/GLOUCESTER

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
FIRST CONVERSION FROM BOOK 95

PIN CREATION DATE:
1997/01/27

OWNERS' NAMES
STAN BERNARD AUTOMOTIVE LIMITED

CAPACITY SHARE
BENO

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1997/01/27 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1997/01/27						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1997/01/25 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1997/01/27 ***						
NS57788	1979/06/29	TRANSFER	$225,000		STAN BERNARD AUTOMOTIVE LIMITED	C
N401025	1987/07/31	AGREEMENT			THE CORPORATION OF THE CITY OF OTTAWA	C
	REMARKS: SITE PLAN CONTROL					
N524295	1990/02/21	CHARGE		**** COMPLETELY DELETED ****	ROYNAT INC.	
LT1111049	1998/03/20	NOTICE OF LEASE		**** COMPLETELY DELETED **** STAN BERNARD AUTOMOTIVE LIMITED.	MIDAS REALTY CORPORATION OF CANADA INC.	
LT1135890	1998/07/21	NOTICE		STAN BERNARD AUTOMOTIVE LIMITED	THE CORPORATION OF THE CITY OF OTTAWA	C
	REMARKS: N401025					
OC168885	2003/02/12	DISCH OF CHARGE		**** COMPLETELY DELETED **** ROYNAT INC.		

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
	REMARKS: RE: N524295					
OC2421268	2021/11/09	APL (GENERAL)		*** COMPLETELY DELETED *** STAN BERNARD AUTOMOTIVE LIMITED		
	REMARKS: DELETE LT1111049					
OC2421413	2021/11/09	NO ASSGN RENT GEN		STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C



ServiceOntario

PRINTED ON 20 JUN, 2025 AT 16:04:53
FOR BERTUCCI

SCALE

0 20 40 60 80 meters

PROPERTY INDEX MAP

OTTAWA-CARLETON(No. 04)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© King's Printer for Ontario, 2025



ServiceOntario

PRINTED ON 20 JUN, 2025 AT 16:03:00
FOR BERTUCCI

SCALE

0 20 40 60 80 meters

PROPERTY INDEX MAP

OTTAWA-CARLETON(No. 04)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© King's Printer for Ontario, 2025



ServiceOntario

PRINTED ON 20 JUN, 2025 AT 16:05:55
FOR BERTUCCI

SCALE

0 20 40 60 80 meters

PROPERTY INDEX MAP

OTTAWA-CARLETON(No. 04)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© King's Printer for Ontario, 2025

* CERTIFIED IN ACCORDANCE WITH THE LAND TITLES ACT * SUBJECT TO RESERVATIONS IN CROWN GRANT *

PROPERTY DESCRIPTION: PT LTS 1 & 2, PL 79 , AS IN OT63102 ; OTTAWA/GLOUCESTER

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
FIRST CONVERSION FROM BOOK 95

PIN CREATION DATE:
1997/01/27

OWNERS' NAMES
STAN BERNARD AUTOMOTIVE LIMITED

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1997/01/27 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1997/01/27						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1997/01/25 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1997/01/27 ***						
OT63102	1964/10/29	TRANSFER		*** COMPLETELY DELETED ***	ENG, DONALD ENG, GAM	
OC394202	2004/10/19	APL OF SURV-LAND		*** COMPLETELY DELETED *** ENG, GAM	ENG, DONALD	
OC399137	2004/10/29	TRANSFER		*** COMPLETELY DELETED *** ENG, DONALD	2053943 ONTARIO INC.	
REMARKS: PLANNING ACT STATEMENTS						
OC399138	2004/10/29	CHARGE		*** COMPLETELY DELETED *** 2053943 ONTARIO INC.	THE CANADA TRUST COMPANY	
OC540096	2005/11/30	CHARGE		*** COMPLETELY DELETED *** 2053943 ONTARIO INC.	THE TORONTO-DOMINION BANK	

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
OC589778	2006/05/08	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE CANADA TRUST COMPANY		
	REMARKS: RE: OC399138					
OC2166130	2019/11/15	TRANSFER	$950,000	2053943 ONTARIO INC.	2644545 ONTARIO INC.	C
OC2166131	2019/11/15	CHARGE		*** COMPLETELY DELETED *** 2644545 ONTARIO INC.	THE BANK OF NOVA SCOTIA	
OC2168193	2019/11/22	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE TORONTO-DOMINION BANK		
	REMARKS: OC540096.					
OC2412538	2021/10/18	APL CH NAME OWNER		2644545 ONTARIO INC.	STAN BERNARD AUTOMOTIVE LIMITED	C
OC2421401	2021/11/09	CHARGE	$25,000,000	STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C
OC2421412	2021/11/09	NO ASSGN RENT GEN		STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C
	REMARKS: OC2421401. OC2421401					
OC2421648	2021/11/10	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE BANK OF NOVA SCOTIA		
	REMARKS: OC2166131.					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

PROPERTY DESCRIPTION: PT LT 1, PL 79 , AS IN OT74832 EXCEPT OT78524; OTTAWA/GLOUCESTER

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
FIRST CONVERSION FROM BOOK 95

PIN CREATION DATE:
1997/01/27

OWNERS' NAMES
STAN BERNARD AUTOMOTIVE LIMITED

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1997/01/27 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1997/01/27						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1997/01/25 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1997/01/27 ***						
N696466	1994/06/22	TRANSFER		*** COMPLETELY DELETED ***	DE SOUSA, MANUEL DE SOUSA, BEATRIZ	
LT1242927	1999/11/08	TRANSFER		*** COMPLETELY DELETED *** DE SOUSA, MANUEL DE SOUSA, BEATRIZ	FEDERAL SUPERANNUATES NATIONAL ASSOCIATION	
	REMARKS: PLANNING ACT STATEMENTS					
OC1754859	2016/01/08	APL DEL EXECUTION		*** COMPLETELY DELETED *** FEDERAL SUPERANNUATES NATIONAL ASSOCIATION		
	REMARKS: DELETE S/T EXECUTION NO. 95-005405					
OC1784043	2016/05/03	LR'S ORDER		LAND REGISTRAR, OTTAWA-CARLETON LAND REGISTRY OFFICE		C
	REMARKS: AMENDING THE DESCRIPTIONS OF 04265-0031 AND 04253-0270 AND INSTRUMENT LIST OF 04265-0031					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
OC1786365	2016/05/12	APL CH NAME OWNER		*** COMPLETELY DELETED *** FEDERAL SUPERANNUATES NATIONAL ASSOCIATION	NATIONAL ASSOCIATION OF FEDERAL RETIREES	
OC1787760	2016/05/17	TRANSFER		*** COMPLETELY DELETED *** NATIONAL ASSOCIATION OF FEDERAL RETIREES	2505531 ONTARIO LTD.	
	REMARKS: PLANNING ACT STATEMENTS.					
OC1787761	2016/05/17	CHARGE		*** COMPLETELY DELETED *** 2505531 ONTARIO LTD.	BANK OF MONTREAL	
OC1787762	2016/05/17	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** 2505531 ONTARIO LTD.	BANK OF MONTREAL	
	REMARKS: OC1787761					
OC2353537	2021/05/31	TRANSFER	$2,750,000	2505531 ONTARIO LTD.	STAN BERNARD AUTOMOTIVE LIMITED	C
	REMARKS: PLANNING ACT STATEMENTS.					
OC2353538	2021/05/31	CHARGE		*** COMPLETELY DELETED *** STAN BERNARD AUTOMOTIVE LIMITED	THE BANK OF NOVA SCOTIA	
OC2353539	2021/05/31	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** STAN BERNARD AUTOMOTIVE LIMITED	THE BANK OF NOVA SCOTIA	
	REMARKS: OC2353538					
OC2404629	2021/09/27	DISCH OF CHARGE		*** COMPLETELY DELETED *** BANK OF MONTREAL		
	REMARKS: OC1787761.					
OC2421401	2021/11/09	CHARGE	$25,000,000	STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C
OC2421412	2021/11/09	NO ASSGN RENT GEN		STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C
	REMARKS: OC2421401. OC2421401					
OC2421647	2021/11/10	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE BANK OF NOVA SCOTIA		
	REMARKS: OC2353538.					



ServiceOntario

PRINTED ON 20 JUN, 2025 AT 16:04:53
FOR BERTUCCI

SCALE

0 20 40 60 80 meters

PROPERTY INDEX MAP

OTTAWA-CARLETON(No. 04)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© King's Printer for Ontario, 2025

PROPERTY DESCRIPTION: PT LTS 2, 3 & 4, PL 79 , AS IN NS57788 EXCEPT PT 1, 5R11050 ; OTTAWA/GLOUCESTER

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
FIRST CONVERSION FROM BOOK 95

PIN CREATION DATE:
1997/01/27

OWNERS' NAMES
STAN BERNARD AUTOMOTIVE LIMITED

CAPACITY SHARE
BENO

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1997/01/27 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1997/01/27						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1997/01/25 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1997/01/27 ***						
NS57788	1979/06/29	TRANSFER	$225,000		STAN BERNARD AUTOMOTIVE LIMITED	C
N401025	1987/07/31	AGREEMENT			THE CORPORATION OF THE CITY OF OTTAWA	C
	REMARKS: SITE PLAN CONTROL					
N524295	1990/02/21	CHARGE		**** COMPLETELY DELETED ****	ROYNAT INC.	
LT1111049	1998/03/20	NOTICE OF LEASE		**** COMPLETELY DELETED **** STAN BERNARD AUTOMOTIVE LIMITED.	MIDAS REALTY CORPORATION OF CANADA INC.	
LT1135890	1998/07/21	NOTICE		STAN BERNARD AUTOMOTIVE LIMITED	THE CORPORATION OF THE CITY OF OTTAWA	C
	REMARKS: N401025					
OC168885	2003/02/12	DISCH OF CHARGE		**** COMPLETELY DELETED **** ROYNAT INC.		

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
	REMARKS: RE: N524295					
OC2421268	2021/11/09	APL (GENERAL)		*** COMPLETELY DELETED *** STAN BERNARD AUTOMOTIVE LIMITED		
	REMARKS: DELETE LT1111049					
OC2421413	2021/11/09	NO ASSGN RENT GEN		STAN BERNARD AUTOMOTIVE LIMITED	BANK OF MONTREAL	C

APPENDIX E

ERIS Report

ERIS

DATABASE REPORT

Project Property:	*Phase One Environmental Site Assessment - St. Laurent Boulevard Properties* *1052, 1060 and 1064 St. Laurent Boulevard* *Ottawa ON K1K 3B4*
Project No:	*103499.002*
Report Type:	*RSC Report (Urban)*
Order No:	*24102901203*
Requested by:	*GEMTEC Consulting Engineers and Scientists Limited (Ontario)*
Date Completed:	*May 30, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....33
Map.....64
Aerial.....65
Topographic Map.....66
Detail Report.....67
Unplottable Summary.....303
Unplottable Report.....308
Appendix: Database Descriptions.....392
Definitions.....402

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*Phase One Environmental Site Assessment - St. Laurent Boulevard Properties 1052, 1060 and 1064 St. Laurent Boulevard Ottawa ON K1K 3B4*
Project No:	*103499.002*

Order Information:

Order No:	*24102901203*
Date Requested:	*October 29, 2024*
Requested by:	*GEMTEC Consulting Engineers and Scientists Limited (Ontario)*
Report Type:	*RSC Report (Urban)*

Historical/Products:

Aerial Photographs	*Aerials - National Collection*
ERIS Xplorer	*ERIS Xplorer*
Insurance Products	*Fire Insurance Maps/Inspection Reports/Site Plans*
Land Title Search	*Historical Land Title Search*
Topographic Map	*RSC Maps*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	8	8
CA	Certificates of Approval	Y	0	7	7
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	3	3
EASR	Environmental Activity and Sector Registry	Y	0	4	4
EBR	Environmental Registry	Y	0	1	1
ECA	Environmental Compliance Approval	Y	0	11	11
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	5	15	20
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	4	4
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	10	10
FSTH	Fuel Storage Tank - Historic	Y	0	5	5
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	131	131
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	1	1

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	2	2
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	1	1
NPR2	National Pollutant Release Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory - Historic	Y	0	1	1
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	2	2
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	29	29
PFAS	Ontario PFAS Spills	Y	0	0	0
PFCH	NPRI Reporters - PFAS Substances	Y	0	0	0
PFHA	Potential PFAS Handlers from NPRI	Y	0	0	0
PINC	Pipeline Incidents	Y	0	0	0
PPHA	Potential PFAS Handlers from EASR	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	0	5	5
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	0	0
RST	Retail Fuel Storage Tanks	Y	0	9	9
SCT	Scott's Manufacturing Directory	Y	0	0	0
SPL	Ontario Spills	Y	0	32	32
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
WDSH	***Waste Disposal Sites - MOE 1991 Historical Approval Inventory***	*Y*	*0*	*0*	*0*
WWIS	***Water Well Information System***	*Y*	*2*	*26*	*28*
		Total:	*7*	*307*	*314*

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	EHS		1064 St. Laurent Blvd Ottawa ON K1K 3B4	WSW/0.0	0.00	67
2	WWIS		ON **Well ID:** 7347865	NW/0.0	0.00	67
3	EHS		1060 St Laurent Blvd Ottawa ON K1K 3B4	NW/0.0	0.00	68
4	WWIS		ON **Well ID:** 7347868	NNE/0.0	1.00	68
5	EHS		1052 St. Laurent Blvd Ottawa ON K1K 3B4	N/0.0	0.14	69
6	EHS		1052 St. Laurent Blvd Ottawa ON K1K 3B4	NNW/0.0	0.14	69
7	EHS		1052 St Laurent Blvd Ottawa ON K1K3B4	NNW/0.0	0.14	69

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
8	SPL	MAC'S	MAC'S MILK 1076 ST. LAURENT BLVD. CONVENIENCE STORE/GAS BAR OTTAWA CITY ON K1K 3B4	SSE/7.2	0.00	69
9	SPL	OTTAWA	707 Alesther St OTTAWA ON	WSW/21.5	0.00	70
10	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7191558	E/43.9	1.00	71
11	PES	K MART STORES STORE #5420	1055 ST LAURENT BLVD OTTAWA ON K1K 3B1	ENE/50.6	1.00	74
11	SPL	PRIVATE OWNER	1055 ST. LAURENT BLVD NEAR K-MART STORE MOTOR VEHICLE (OPERATING FLUID) GLOUCESTER CITY ON K1K 3B1	ENE/50.6	1.00	75
11	GEN	ZELLERS PHARMACY	1055 ST. LAURENT BLVD. OTTAWA ON K1K 3B1	ENE/50.6	1.00	76
11	PES	ZELLERS STORE #313 - ZELLERS PLAZA	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	ENE/50.6	1.00	76
11	GEN	Riocan Property	1055 St. Laurent Blvd. Ottawa ON K1K 3B1	ENE/50.6	1.00	76
11	PES	ZELLERS STORE #313 - ZELLERS PLAZA	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	ENE/50.6	1.00	77
11	SPL		1055 St.Laurent Blvd. Ottawa ON K1K 3B1	ENE/50.6	1.00	77
11	GEN	Zellers # 313	1055 St. Laurent Blvd Ottawa ON K1K 3B1	ENE/50.6	1.00	78

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	EHS		1055 St Laurent Blvd Ottawa ON K1K 3B1	ENE/50.6	1.00	78
11	PES	ZELLERS STORE #313 - ZELLERS PLAZA	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	ENE/50.6	1.00	78
11	EASR	TARGET CANADA CO.	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	ENE/50.6	1.00	79
11	EASR	TARGET CANADA CO.	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	ENE/50.6	1.00	79
11	NPRI	ZELLERS	105 105-1055 ST LAURENT Boulevard OTTAWA ON K1K3B1	ENE/50.6	1.00	79
11	GEN	Target Canada Co.	1055 St. Laurent Blvd. Ottawa ON K1K 3B1	ENE/50.6	1.00	82
11	GEN	Target Canada Co.	1055 St. Laurent Blvd. Ottawa ON K1K 3B1	ENE/50.6	1.00	83
11	PES	TARGET CANADA CO. O/A TARGET STORE T3658	1055 ST.LAURENT BLVD OTTAWA ON K1K3B1	ENE/50.6	1.00	85
11	PES	K MART STORES STORE #5420	1055 ST LAURENT BLVD OTTAWA ON K1K3B1	ENE/50.6	1.00	85
11	PES	ZELLERS STORE #313 - ZELLERS PLAZA	1055 ST. LAURENT BLVD OTTAWA ON K1K3B1	ENE/50.6	1.00	86
12	GEN	RioCan Management Inc.	1091 St-Laurent Blvd. Ottawa ON	E/55.7	1.00	86
13	WWIS		1055 ST. LAWRENT BLVD Ottawa ON ***Well ID:*** 7191555	NNE/58.0	1.00	87
14	SPL		694 Alesther Dr, Ottawa ON	W/58.0	0.00	89

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
15	WWIS		1110 ST. LAURENT BLVD. Ottawa ON ***Well ID:*** 7174555	SSE/64.1	0.00	90
16	WWIS		lot 9 ON ***Well ID:*** 1500404	SSE/64.2	0.00	93
17	WWIS		ON ***Well ID:*** 1508882	SSE/71.0	0.00	96
18	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7191559	NNE/76.1	1.00	99
19	SPL	Waste Services (CA) Inc.; Waste Services (CA) Inc.	1020 St. Laurant St. Ottawa ON	NNW/83.7	0.00	102
19	SPL	Waste Services (CA) Inc.	1020 St. Laurent St, Ottawa Ottawa ON	NNW/83.7	0.00	103
19	EHS		1020 St Laurent Blvd Ottawa ON K1K 4S2	NNW/83.7	0.00	104
20	SPL	O.C. TRANSPO	CORNER ST. LAURENT & CYRVILLE ROAD MOTOR VEHICLE (OPERATING FLUID) OTTAWA CITY ON	SE/91.6	0.00	104
21	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205218	N/93.1	1.00	105
22	WWIS		ON ***Well ID:*** 7306228	SSE/94.3	0.00	108
23	GEN	CONSEIL DES ECOLES CATHOLIQUES DE LANGUE	EDUCATION SANS FRONTIERE 1116 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B6	SSE/100.9	0.00	109
23	GEN	CONSEIL DES ECOLES CATHOLIQUES DE LANGUE	EDUCATION SANS FRONTIERE 1116 BOUL. ST-LAURENT OTTAWA ON K1K 3B6	SSE/100.9	0.00	109
23	EASR	MIERINS DEALERSHIP HOLDINGS INC.	1116 St. Laurent Boulevard Ottawa ON K1K 3B6	SSE/100.9	0.00	109

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
24	WWIS		1076 ST. LAURENT BLVD OTTAWA ON ***Well ID:*** 1535863	SE/106.5	0.00	110
25	WWIS		1055 ST LAURENT BLVD Ottawa ON ***Well ID:*** 7191556	N/107.3	1.00	113
26	WWIS		lot 8 ON ***Well ID:*** 1500398	WSW/107.5	0.00	116
27	SPL	OC Transpo<UNOFFICIAL>	St Laurent Blvd northbound 100 m south of Donald St Ottawa ON	N/108.4	1.00	119
28	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205219	NNE/112.5	1.00	120
29	BORE		ON	S/113.8	0.00	123
30	EHS		1055 & 1091 St.Laurent Boulevard and 1235 and 1236 Donald Street Ottawa ON	ENE/115.8	1.00	124
31	SPL	FIRESTONE	FIRESTONE 1110 ST. LAURENT BLVD. VEHICLE SERVICE STATION OTTAWA CITY ON K1K 3B6	SSE/119.3	0.00	124
31	CA		1110 St. Laurent Boulevard Ottawa ON K1K 3B6	SSE/119.3	0.00	125
31	CA	Ogilvie Realty Ltd.	1110 St. Laurent Boulevard Ottawa ON K1K 3B6	SSE/119.3	0.00	126
31	EHS		1110 Ste Laurent Blvd Ottawa ON	SSE/119.3	0.00	126
31	ECA	Ogilvie Realty Ltd.	1110 St. Laurent Blvd Ottawa ON K1Z 7L9	SSE/119.3	0.00	126

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
31	ECA	Ogilvie Realty Ltd.	1110 St. Laurent Blvd Ottawa ON K1Z 7L9	SSE/119.3	0.00	126
31	SPL	Willy's Roll-off<UNOFFICIAL>	1110 St-Laurent Blvd Ottawa ON K1K 3B6	SSE/119.3	0.00	127
31	ECA	Ogilvie Realty Ltd.	1110 St. Laurent Boulevard Ottawa ON K1Z 7L9	SSE/119.3	0.00	128
31	ECA	Ogilvie Realty Ltd.	1110 St. Laurent Boulevard Ottawa ON K1Z 7L9	SSE/119.3	0.00	128
31	EHS		1110 St Laurent Blvd Ottawa ON K1K3B6	SSE/119.3	0.00	128
31	ECA	Ogilvie Realty Limited	1110 St. Laurent Blvd Ottawa ON K1K 3B6	SSE/119.3	0.00	128
31	SPL	Tomlinson Environmental Services Ltd	1110 Saint Laurent Boulevard Ottawa ON	SSE/119.3	0.00	129
32	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205220	NNE/122.6	1.00	129
33	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205223	E/123.5	1.00	132
34	EHS		1091 St. Laurent Blvd Ottawa ON K1K 3B1	ENE/126.1	1.00	136
35	EHS		St Laurent Enbridge Ottawa ON	WNW/127.1	0.00	136
36	EHS		n/a Ottawa ON	NNW/139.0	1.00	136
37	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7191560	NNE/139.2	1.00	136

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
38	SPL	SUNOCO	1007 ST. LAURENT STREET SERVICE STATION OTTAWA CITY ON K1K 3B1	N/139.6	1.00	139
38	PRT	M ELLIS	1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	N/139.6	1.00	140
38	CA	MCDONALD'S REST. OF CANADA LTD.	1007 ST. LAURENT BOULEVARD OTTAWA CITY ON K1K 3B1	N/139.6	1.00	140
38	RST	ST LAURENT FUN FOOD SUNOCO	1007 ST LAURENT BLVD OTTAWA ON K1K3B1	N/139.6	1.00	141
38	RST	ST LAURENT SUNOCO	1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	N/139.6	1.00	141
38	FSTH	6151892 CANADA INC	1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	N/139.6	1.00	141
38	FSTH	6434118 CANADA INC O/A SUNOCO	1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	N/139.6	1.00	142
38	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1007 ST. LAURENT BLVD OTTAWA ON	N/139.6	1.00	142
38	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1007 ST. LAURENT BLVD OTTAWA ON	N/139.6	1.00	142
38	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1007 ST. LAURENT BLVD OTTAWA ON	N/139.6	1.00	143
38	RST	ST LAURENT SUNOCO	1007 ST LAURENT BLVD OTTAWA ON K1K3B1	N/139.6	1.00	143
38	RST	PETRO CANADA	1007 ST LAURENT BLVD OTTAWA ON K1K3B1	N/139.6	1.00	143
38	EXP	6205429 CANADA INC	1007 ST. LAURENT BLVD OTTAWA ON	N/139.6	1.00	143

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
38	EXP	6205429 CANADA INC	1007 ST. LAURENT BLVD OTTAWA ON	N/139.6	1.00	143
38	EXP	6205429 CANADA INC	1007 ST. LAURENT BLVD OTTAWA ON	N/139.6	1.00	144
38	EXP	6205429 CANADA INC	1007 ST. LAURENT BLVD OTTAWA ON	N/139.6	1.00	144
38	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1007 ST. LAURENT BLVD OTTAWA ON	N/139.6	1.00	144
39	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7191557	NNE/145.4	1.00	144
40	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205221	NNE/146.5	1.00	147
41	BORE		ON	WSW/147.7	-1.00	150
42	WWIS		lot 8 ON ***Well ID:*** 1500399	WSW/147.7	-1.00	152
43	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205222	NNE/152.1	1.00	155
44	GEN	ONE STOP LAUNDROMAT(OUT OF BUSINESS)-589	914115 ONT. INC. 1045 ST. LAURENT BLVD. OTTTAWA ON K1K 3B1	ENE/160.8	1.00	158
44	GEN	ONE STOP LAUNDROMAT 29-589	914115 ONT. INC. 1045 ST. LAURENT BLVD. OTTTAWA ON K1K 3B1	ENE/160.8	1.00	159
45	SPL	PETRO-CANADA	1018 SYRVILLE RD TANK TRUCK (CARGO) GLOUCESTER CITY ON K1J 7S4	SE/161.2	0.00	159
45	PRT	E ANNE BRUNDIGE	1018 CYRVILLE RD GLOUCESTER ON K1J 7S4	SE/161.2	0.00	160

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
45	PRT	CATHYS CORNER	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	160
45	FSTH	1343615 ONTARIO INC O/A PETRO CANADA	1018 CYRVILLE RD GLOUCESTER ON K1J 7S4	SE/161.2	0.00	160
45	DTNK	ERIC ROY	1018 CYRVILLE RD GLOUCESTER ON K1J 7S4	SE/161.2	0.00	161
45	DTNK	6205429 CANADA INC O/A GAS STN	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	161
45	DTNK	6205429 CANADA INC O/A GAS STN	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	162
45	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	163
45	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	163
45	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	163
45	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	163
45	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	164
45	SPL		1018 Cyrville Rd Ottawa ON	SE/161.2	0.00	164
45	INC	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	165
45	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	SE/161.2	0.00	166

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
46	BORE		ON	W/164.8	-1.00	166
47	SPL		1021 St. Laurent Blve Ottawa ON	NE/193.4	1.00	167
47	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 262	1021 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B1	NE/193.4	1.00	168
47	EHS		1021 St Laurent Blvd Ottawa ON K1K 3B1	NE/193.4	1.00	168
47	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 262	1021 St. Laurent Boulevard Ottawa ON K1K 3B1	NE/193.4	1.00	169
47	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 262	1021 ST. LAURENT BOULEVARD OTTAWA ON K1K3B1	NE/193.4	1.00	169
48	BORE		ON	ESE/194.3	1.08	169
49	WWIS		lot 26 con 1 ON ***Well ID:*** 1501137	ESE/194.4	1.08	171
49	WWIS		lot 25 con 2 ON ***Well ID:*** 1501337	ESE/194.4	1.08	174
50	SPL	Rio Can Properties<UNOFFICIAL>	1021 Cyrville Rd. Ottawa ON	ESE/195.0	1.00	176
50	CA	RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	ESE/195.0	1.00	177
50	CA	RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	ESE/195.0	1.00	177
50	SPL	Metro Ontario Incorporated	1021 Cyrville Road Ottawa ON K1J 7S3	ESE/195.0	1.00	178

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
50	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 896	1021 CYRVILLE ROAD, UNIT 1 OTTAWA ON K1J7S3	ESE/195.0	1.00	178
50	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 896	1021 Cyrville Road, Unit 1 Ottawa ON K1J 7S3	ESE/195.0	1.00	179
50	SPL	Metro Ontario Incorporated	1021 Cyrville Road Ottawa ON K1J 7S3	ESE/195.0	1.00	179
50	ECA	RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	ESE/195.0	1.00	180
50	ECA	RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	ESE/195.0	1.00	180
50	ECA	RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	ESE/195.0	1.00	181
50	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 896	1021 CYRVILLE ROAD, UNIT 1 OTTAWA ON K1J7S3	ESE/195.0	1.00	181
51	SPL	SHELL CANADA PRODUCTS LTD.	AT THE QUEEN MARY PUBLIC SCHOOL AT 557 QUEEN MARY ROAD TANK TRUCK (CARGO) OTTAWA CITY ON K1K 1V9	W/195.3	-1.00	181
51	GEN	Ottawa-Carleton District School Board	Queen Mary Street Public School 557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	182
51	GEN	Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	183
51	GEN	Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	183
51	GEN	Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	183

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
51	GEN	Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	184
51	GEN	Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON	W/195.3	-1.00	184
51	GEN	Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	185
51	GEN	Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	185
51	GEN	Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	186
51	GEN	Ottawa-Carleton District School Board Health & Safety	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	187
51	GEN	Ottawa-Carleton District School Board Health & Safety	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	188
51	GEN	Ottawa-Carleton District School Board Health & Safety	557 Queen Mary Street Ottawa ON K1K 1V9	W/195.3	-1.00	189
51	GEN	Ottawa-Carleton District School Board	Queen Mary Public School, 557 Queen Mary Street Ottawa ON	W/195.3	-1.00	189
52	WWIS		lot 26 con 1 ON ***Well ID:*** 7411205	SE/209.6	0.00	193
53	WWIS		1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205224	E/209.7	2.00	194
54	CA	TAGR MANAGEMENT LIMITED	1130 ST. LAURENT BOULEVARD OTTAWA CITY ON K1K 3B6	S/212.7	-1.00	197
55	SPL	BFI Canada<UNOFFICIAL>	Corner of Donald Street and St. Laurent Ottawa ON	NNW/219.0	1.00	197

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
55	SPL	Storm sewer<UNOFFICIAL>	Intersection of Donald and St. Laurent Blvd. Ottawa ON	NNW/219.0	1.00	198
55	SPL	City of Ottawa	St Laurent and Donald Ottawa ON	NNW/219.0	1.00	199
56	CA	OTTAWA CITY	DONALD ST/ST.LAURENT BLVD. OTTAWA CITY ON	NNW/219.0	1.00	200
57	BORE		ON	N/231.2	1.00	200
58	WWIS		lot 26 con 1 ON ***Well ID:*** 1501135	ESE/232.2	1.00	202
59	HINC		1240 DONALD STREET OTTAWA ON	ENE/232.8	2.00	205
59	GEN	KONE INC	1240-1244 DONALD ST OTTAWA ON	ENE/232.8	2.00	205
59	GEN	GREENWIN PROPERTY MANAGEMENT INC	1240-1244 DONALD STREET OTTAWA ON K1J 8V6	ENE/232.8	2.00	205
59	EHS		1240 and 1244 Donald St Ottawa ON K1J8R7	ENE/232.8	2.00	206
59	EHS		1240 & 1244 Donald St Ottawa ON	ENE/232.8	2.00	206
60	BORE		ON	N/237.7	1.00	206
61	ECA	Richcraft Construction (1984) Ltd.	741 Bernard St Ottawa ON K1G 4K1	SW/251.0	-1.00	208
62	EASR	RICHCRAFT HOMES LTD/MAISONS RICHCRAFT LTEE	ON	WSW/253.2	-1.00	208

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
63	EHS		1089 Ogilvie Road and 1137 Cyrville Rd Ottawa ON	SE/256.5	0.00	208
64	BORE		ON	WSW/260.0	-1.00	208
65	BORE		ON	N/260.8	1.00	209
66	GEN	BELL CANADA	490 COVENTRY ROAD OTTAWA ON K1K 2C4	SSW/263.3	-1.00	211
67	INC		Coventry Road at St Laurent Boulevard, Ottawa ON	SE/265.3	0.00	212
68	SPL	TEXACO	TEXACO SERVICE STATION AT CORNER OF ST. LAURENT BLVD., OGILVY RD SERVICE STATION OTTAWA CITY ON	SE/266.8	0.00	213
69	GEN	KONICA ONE HOUR PHOTO	1239 DONALD ST. OTTAWA ON K1J 8W3	NNW/270.1	1.00	213
69	GEN	KONICA ONE HOUR PHOTO 23-368	1239 DONALD ST. OTTAWA ON K1J 8W3	NNW/270.1	1.00	214
69	GEN	FUJI IMAGE (OUT OF BUSINESS)Y LTD.15-593	1239 DONALD STREET GLOUCESTER ON K1J 8W3	NNW/270.1	1.00	214
69	GEN	Rio Can Property Services	1239 Donald Street Ottawa ON K1J 8W3	NNW/270.1	1.00	215
70	WWIS		lot 26 con 1 ON ***Well ID:*** 1501132	ESE/270.3	1.00	215
71	EHS		1059 Ogilvie Road Gloucester ON K1J 7S6	E/272.2	0.97	217
72	EHS		1240 Donald St Gloucester ON K1J 8R7	ENE/284.1	2.00	218

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	NPCB	CADILLAC FAIRVIEW CORPORATION LIMITED	1200 ST. LAURENT BOULVARD; ST. LAURENT SHOPPING CE OTTAWA ON K1K 3B8	S/291.1	-1.00	218
73	OPCB	CADILLAC FAIRVIEW CORPORATION LIMITED	1200 ST. LAURENT BOULVARD ST. LAURENT SHOPPING CENTRE OTTAWA ON K1K 3B8	S/291.1	-1.00	218
73	OPCB	CADILLAC FAIRVIEW CORPORATION LIMITED	1200 ST. LAURENT BOULVARD ST. LAURENT SHOPPING CENTRE OTTAWA ON K1K 3B8	S/291.1	-1.00	219
73	GEN	BLACK PHOTO CORPORATION	1200 ST. LAURENT BOULEVARD, OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	S/291.1	-1.00	219
73	GEN	BLACK PHOTO CORPORATION	1200 ST. LAURENT BOULEVARD ST. LAURENT SHOPPING CENTRE OTTAWA ON K1K 3B8	S/291.1	-1.00	219
73	GEN	BLACK PHOTO CORPORATION 05-410	1200 ST. LAURENT BOULEVARD - OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	S/291.1	-1.00	220
73	GEN	BLACK PHOTO CORPORATION	ST. LAURENT SHOPPING CENTRE 1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	S/291.1	-1.00	220
73	GEN	CADILLAC FAIRVIEW CORPORATION LTD.08-539	1200 ST. LAURENT BLVD. OTTAWA ON K1K 3B8	S/291.1	-1.00	221
73	GEN	CADILLAC FAIRVIEW CORPORATION LTD.08-539	1200 ST. LAURENT BLVD. PO BOX 199 OTTAWA ON K1K 3B8	S/291.1	-1.00	221
73	GEN	CADILLAC FAIRVIEW CORPORATION LIMITED	1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	S/291.1	-1.00	222
73	GEN	CADILLAC FAIRVIEW CORP. LTD.	N. MALL AREA-ENT. BANK & SHOP. DRUG M. C/O 1200 ST.-LAURENT BLVD. OTTAWA ON K1K 3B8	S/291.1	-1.00	223
73	GEN	CADILLAC (SEE & USE ON0733507) 08-539	N. MALL AREA-ENT. BANK & SHOP. DRUG M. C/O 1200 ST.-LAURENT BLVD. OTTAWA ON K1K 3B8	S/291.1	-1.00	223

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	JAPAN CAMERA CENTRE	PHOTO MINUTES ONTARIO INC. 1200 ST.LAURENT OTTAWA ON K9K 3B8	S/291.1	-1.00	223
73	GEN	JAPAN CAMERA CENTRE 31-345	PHOTO MINUTES ONTARIO INC. 1200 ST.LAURENT OTTAWA ON K9K 3B8	S/291.1	-1.00	224
73	GEN	BLACK (OUT OF BUS) 05-661	ST.LAURENT11-1200ST.LAURENT BLVD-OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	S/291.1	-1.00	224
73	GEN	BLACK PHOTO CORPORATION 05-661	ST.LAURENT11-1200ST.LAURENT BLVD-OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	S/291.1	-1.00	224
73	GEN	CAREER CANADA COLLEGE	1200 ST. LAURENT BOULEVARD SUITE 261 OTTAWA ON	S/291.1	-1.00	225
73	GEN	FORZANI GROUP LTD., THE	SPORT CHEK, ST. LAURENT MALL 1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	S/291.1	-1.00	225
73	GEN	DEVAN PROPERTIES LTD.	1200 ST-LAURENT BOULEVARD OTTAWA ON K1K 3B8	S/291.1	-1.00	225
73	GEN	CAREER CANADA COLLEGE	1200 ST. LAURENT BOULEVARD, SUITE 261 OTTAWA ON	S/291.1	-1.00	226
73	GEN	SPORT CHEK	ST. LAURENT MALL 1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	S/291.1	-1.00	227
73	GEN	SHOPPERS DRUG MART	1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	S/291.1	-1.00	227
73	GEN	CAREER CANADA COLLEGE	1200 ST. LAURENT BOULEVARD, SUITE 261 Unit 261 OTTAWA ON K1K 3B8	S/291.1	-1.00	228
73	GEN	7139490 ONTARIO LIMITED	1200 LAURENT BLVD. OTTAWA ON K1K 3B8	S/291.1	-1.00	228

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	CDI COLLEGE	1200 ST. LAURENT BOULEVARD, SUITE 261 OTTAWA ON	S/291.1	-1.00	228
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	229
73	PES	IAN MCNEIL PHARMACIES INC	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	230
73	PES	SHOPPERS DRUG MART#0621 (ST. LAURENT SHOPPING CENTRE)	1200 ST. LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	230
73	SPL	Canadian Waste Management<UNOFFICIAL>	1200 St. Laurent St. Ottawa ON	S/291.1	-1.00	231
73	GEN	CDI COLLEGE	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	S/291.1	-1.00	231
73	GEN	Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	S/291.1	-1.00	232
73	GEN	Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	S/291.1	-1.00	232
73	PES	IAN MCNEIL PHARMACIES INC	1200 ST LAURENT BLVD OTTAWA ON K1K3B8	S/291.1	-1.00	233
73	PES	TLM PHARMACIES INC.	1200 ST. LAURENT BLVD OTTAWA ON K1K3B3	S/291.1	-1.00	233
73	EBR	713949 Ontario Limited	1200 St. Laurent Boulevard Ottawa K1K 3B8 CITY OF OTTAWA ON	S/291.1	-1.00	233
73	GEN	Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	S/291.1	-1.00	234

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON	S/291.1	-1.00	234
73	GEN	Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON	S/291.1	-1.00	235
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON	S/291.1	-1.00	235
73	PES	CINDY CHANGOOR PHARMACY LTD	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	236
73	ECA	713949 Ontario Limited	1200 St. Laurent Blvd Ottawa ON	S/291.1	-1.00	236
73	GEN	The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON	S/291.1	-1.00	237
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON	S/291.1	-1.00	237
73	GEN	Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON	S/291.1	-1.00	238
73	GEN	Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	S/291.1	-1.00	238
73	GEN	CINDY CHANGOOR PHARMACY LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	239
73	GEN	The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON	S/291.1	-1.00	239
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON	S/291.1	-1.00	239
73	GEN	Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON	S/291.1	-1.00	240

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	S/291.1	-1.00	241
73	PES	TLM PHARMACIES INC.	1200 ST. LAURENT BLVD OTTAWA ON K1K 3B3	S/291.1	-1.00	241
73	PES	CINDY CHANGOOR PHARMACY LTD	1200 ST LAURENT BLVD OTTAWA ON K1K3B8	S/291.1	-1.00	242
73	GEN	Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON	S/291.1	-1.00	242
73	SPL	City of Ottawa	1200 Saint Laurent Boulevard Ottawa ON	S/291.1	-1.00	242
73	GEN	CINDY CHANGOOR PHARMACY LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	243
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	244
73	GEN	Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON	S/291.1	-1.00	245
73	GEN	Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	S/291.1	-1.00	245
73	GEN	CINDY CHANGOOR PHARMACY LIMITED	1200 ST LAURENT BLVD OTTAWA ON	S/291.1	-1.00	245
73	GEN	The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON	S/291.1	-1.00	246
73	GEN	Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON	S/291.1	-1.00	246
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON	S/291.1	-1.00	246

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	S/291.1	-1.00	247
73	SPL		1200 St. Laurent Boulevard Ottawa ON	S/291.1	-1.00	248
73	SPL		1200 St. Laurent Blvd. Ottawa ON	S/291.1	-1.00	249
73	SPL		1200 St Laurent Ave Ottawa ON	S/291.1	-1.00	250
73	ECA	713949 Ontario Limited	1200 St. Laurent Blvd Ottawa ON K1K 3B8	S/291.1	-1.00	250
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	251
73	GEN	St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	S/291.1	-1.00	252
73	GEN	FGL SPORTS LIMITED	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	S/291.1	-1.00	252
73	GEN	Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	S/291.1	-1.00	252
73	GEN	Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	S/291.1	-1.00	253
73	GEN	The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	S/291.1	-1.00	253
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	254
73	GEN	Cindy Changoor Pharmacy Limited (641)	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	S/291.1	-1.00	255

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	Cindy Changoor Pharmacy Limited (621)	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	S/291.1	-1.00	255
73	GEN	Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	S/291.1	-1.00	256
73	GEN	Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	S/291.1	-1.00	256
73	GEN	Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	S/291.1	-1.00	257
73	GEN	St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	S/291.1	-1.00	257
73	GEN	Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	S/291.1	-1.00	257
73	GEN	Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	S/291.1	-1.00	258
73	GEN	St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	S/291.1	-1.00	258
73	GEN	Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	S/291.1	-1.00	259
73	GEN	CINDY CHANGOOR PHARMACY LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	259
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	260
73	GEN	The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	S/291.1	-1.00	261
73	GEN	FGL SPORTS LIMITED	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	S/291.1	-1.00	261

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	S/291.1	-1.00	261
73	GEN	Herzing College St. Laurent Blvd Ottawa	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	S/291.1	-1.00	262
73	GEN	Cindy Changoor Pharmacy Limited (621)	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	S/291.1	-1.00	262
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	263
73	EHS		1200 St Laurent Blvd Ottawa ON K1K 4H4	S/291.1	-1.00	264
73	PES	IAN MCNEIL PHARMACIES INC	1200 ST LAURENT BLVD OTTAWA ON K1K3B8	S/291.1	-1.00	264
73	PES	TLM PHARMACIES INC.	1200 ST. LAURENT BLVD OTTAWA ON K1K3B3	S/291.1	-1.00	264
73	PES	SHOPPERS DRUG MART#0621 (ST. LAURENT SHOPPING CENTRE)	1200 ST. LAURENT BLVD OTTAWA ON K1K3B8	S/291.1	-1.00	265
73	GEN	St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	S/291.1	-1.00	265
73	GEN	FGL SPORTS LIMITED	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	S/291.1	-1.00	265
73	GEN	Cindy Changoor Pharmacy Limited (621)	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	S/291.1	-1.00	266
73	GEN	713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	S/291.1	-1.00	266
73	GEN	Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	S/291.1	-1.00	269

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	FGL SPORTS LIMITED	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	S/291.1	-1.00	271
73	GEN	LensCrafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	S/291.1	-1.00	271
73	GEN	St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	S/291.1	-1.00	272
73	GEN	Ben Gunter Pharmacy Inc	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	S/291.1	-1.00	272
73	GEN	Morguard Real Estate Investment Trust	1200 St. Laurent Blvd. Ottawa ON	S/291.1	-1.00	273
73	GEN	Shoppers Drug Mart	1200 ST. LAURENT BLVD Ottawa ON	S/291.1	-1.00	274
73	GEN	LCBO	540-1200 ST. LAURENT BLVD Ottawa ON K1K3B8	S/291.1	-1.00	277
73	GEN	EssilorLuxottica of Canada	1200 St. Laurent Blvd Ottawa ON	S/291.1	-1.00	278
73	GEN	St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	S/291.1	-1.00	280
73	GEN	Sport Chek	1200 St. Laurent Blvd. Ottawa ON	S/291.1	-1.00	283
73	GEN	LCBO	1200 Saint Laurent Boulevard Ottawa ON	S/291.1	-1.00	286
73	GEN	EssilorLuxottica of Canada	1200 Saint Laurent Boulevard Ottawa ON	S/291.1	-1.00	287
73	GEN	St Laurent Dental Centre	1200 Saint Laurent Boulevard Ottawa ON	S/291.1	-1.00	287

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	RTM	1200 Saint Laurent Boulevard Ottawa ON	S/291.1	-1.00	288
73	GEN	American Eagle Outfitters Canada Corporation	1200 Saint Laurent Boulevard Ottawa ON	S/291.1	-1.00	288
74	SPL		OTTAWA ON	ESE/291.4	1.00	289
75	PRT	JOSEPH T SAAB	1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	ESE/295.8	1.00	290
75	PRT	JOE T SAAB 135247 CANADA INC	1057 CYRVILLE RD GLOUCESTER ON	ESE/295.8	1.00	290
75	RST	SAAB GAS CENTRE	1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	ESE/295.8	1.00	290
75	RST	SAAB GAS CENTRE	1057 CYRVILLE RD OTTAWA ON K1J 7S3	ESE/295.8	1.00	290
75	FSTH	1427229 ONTARIO INC ATTN JOSEPH T SAAB	1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	ESE/295.8	1.00	290
75	FSTH	1427229 ONTARIO INC ATTN JOSEPH T SAAB	1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	ESE/295.8	1.00	291
75	RST	SAAB GAS CENTRE	1057 CYRVILLE RD GLOUCESTER ON K1J7S3	ESE/295.8	1.00	291
75	RST	SAAB GAS CENTRE	1057 CYRVILLE RD GLOUCESTER ON K1J7S3	ESE/295.8	1.00	291
75	RST	SAAB GAS CENTRE	1057 CYRVILLE RD GLOUCESTER ON K1J7S3	ESE/295.8	1.00	292
75	SPL	Carlsbad Auto 1057 Cyrville Road	1057 Cyrville Road, Ottawa OTTAWA ON	ESE/295.8	1.00	292

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
75	GEN	Norris Construction Management Inc.	1057 Cyrville Road Ottawa ON	ESE/295.8	1.00	293
75	GEN	SAAB Gas Center	1057 Cyrville Road Ottawa ON	ESE/295.8	1.00	293
75	GEN	SAAB Gas Centre	1057 Cyrville Road Ottawa ON	ESE/295.8	1.00	294
75	GEN	BELL CANADA	1057 Cyrville Road Ottawa ON	ESE/295.8	1.00	295
76	SPL		1233 Donald St. Ottawa ON	N/297.0	1.00	295
77	WWIS		lot 26 con 2 ON ***Well ID:*** 1501342	SE/298.0	0.00	296
78	GEN	Elite Environmental Group Inc	1105 Hardy Ave Ottawa ON K1K3H8	WSW/298.4	-1.69	299
79	PES	LOBLAW SUPERMARKETS LTD. STORE NO. 180-2	1235 DONALD STREET GLOUCESTER ON K1J 8W3	N/298.6	1.00	299
79	PES	LOBLAWS #180	1235 DONALD STREET GLOUCESTER ON K1J 8W3	N/298.6	1.00	299
79	PES	LOBLAWS SUPERMARKETS LIMITED	1235 DONALD STREET OTTAWA ON K1J 8W3	N/298.6	1.00	300
79	GEN	Rio-Can Property Services	1235 Donald Street Ottawa ON K1J 8W3	N/298.6	1.00	300
79	PES	LOBLAW SUPERMARKETS LTD. STORE NO. 180-2	1235 DONALD STREET GLOUCESTER ON K1J8W3	N/298.6	1.00	301
79	PES	LOBLAWS SUPERMARKETS LIMITED	1235 DONALD STREET OTTAWA ON K1J8W3	N/298.6	1.00	301

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
79	PES	LOBLAWS #180	1235 DONALD STREET GLOUCESTER ON K1G1W3	N/298.6	1.00	301
79	GEN	TJX Canada	1235 Donald Street Ottawa ON	N/298.6	1.00	302

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 8 BORE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	113.8	29
	ON	147.7	41
	ON	164.8	46
	ON	194.3	48
	ON	231.2	57
	ON	237.7	60
	ON	260.0	64
	ON	260.8	65

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 7 CA site(s) within approximately 0.30 kilometers of

the project property.

Site	Address	Distance (m)	Map Key
	1110 St. Laurent Boulevard Ottawa ON K1K 3B6	119.3	31
Ogilvie Realty Ltd.	1110 St. Laurent Boulevard Ottawa ON K1K 3B6	119.3	31
MCDONALD'S REST. OF CANADA LTD.	1007 ST. LAURENT BOULEVARD OTTAWA CITY ON K1K 3B1	139.6	38
RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	195.0	50
RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	195.0	50
TAGR MANAGEMENT LIMITED	1130 ST. LAURENT BOULEVARD OTTAWA CITY ON K1K 3B6	212.7	54
OTTAWA CITY	DONALD ST/ST.LAURENT BLVD. OTTAWA CITY ON	219.0	56

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 3 DTNK site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ERIC ROY	1018 CYRVILLE RD GLOUCESTER ON K1J 7S4	161.2	45
6205429 CANADA INC O/A GAS STN	1018 CYRVILLE RD GLOUCESTER ON	161.2	45
6205429 CANADA INC O/A GAS STN	1018 CYRVILLE RD GLOUCESTER ON	161.2	45

Site	Address	Distance (m)	Map Key

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011 - Apr 30, 2025 has found that there are 4 EASR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
TARGET CANADA CO.	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	50.6	11
TARGET CANADA CO.	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	50.6	11
MIERINS DEALERSHIP HOLDINGS INC.	1116 St. Laurent Boulevard Ottawa ON K1K 3B6	100.9	23
RICHCRAFT HOMES LTD/MAISONS RICHCRAFT LTEE	ON	253.2	62

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Apr 30, 2025 has found that there are 1 EBR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
713949 Ontario Limited	1200 St. Laurent Boulevard Ottawa K1K 3B8 CITY OF OTTAWA ON	291.1	73

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011 - Apr 30, 2025 has found that there are 11 ECA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Ogilvie Realty Ltd.	1110 St. Laurent Boulevard Ottawa ON K1Z 7L9	119.3	31

Site	Address	Distance (m)	Map Key
Ogilvie Realty Ltd.	1110 St. Laurent Blvd Ottawa ON K1Z 7L9	119.3	31
Ogilvie Realty Ltd.	1110 St. Laurent Blvd Ottawa ON K1Z 7L9	119.3	31
Ogilvie Realty Ltd.	1110 St. Laurent Boulevard Ottawa ON K1Z 7L9	119.3	31
Ogilvie Realty Limited	1110 St. Laurent Blvd Ottawa ON K1K 3B6	119.3	31
RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	195.0	50
RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	195.0	50
RioKim Holdings (Ontario) Inc.	1021 Cyrville Road Ottawa ON	195.0	50
Richcraft Construction (1984) Ltd.	741 Bernard St Ottawa ON K1G 4K1	251.0	61
713949 Ontario Limited	1200 St. Laurent Blvd Ottawa ON K1K 3B8	291.1	73
713949 Ontario Limited	1200 St. Laurent Blvd Ottawa ON	291.1	73

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Aug 31, 2024 has found that there are 20 EHS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1064 St. Laurent Blvd Ottawa ON K1K 3B4	0.0	1
	1060 St Laurent Blvd Ottawa ON K1K 3B4	0.0	3
	1052 St. Laurent Blvd Ottawa ON K1K 3B4	0.0	5
	1052 St. Laurent Blvd Ottawa ON K1K 3B4	0.0	6
	1052 St Laurent Blvd Ottawa ON K1K3B4	0.0	7
	1055 St Laurent Blvd Ottawa ON K1K 3B1	50.6	11
	1020 St Laurent Blvd Ottawa ON K1K 4S2	83.7	19
	1055 & 1091 St.Laurent Boulevard and 1235 and 1236 Donald Street Ottawa ON	115.8	30
	1110 St Laurent Blvd Ottawa ON K1K3B6	119.3	31
	1110 Ste Laurent Blvd Ottawa ON	119.3	31
	1091 St. Laurent Blvd Ottawa ON K1K 3B1	126.1	34

Site	Address	Distance (m)	Map Key
	St Laurent Enbridge Ottawa ON	127.1	35
	n/a Ottawa ON	139.0	36
	1021 St Laurent Blvd Ottawa ON K1K 3B1	193.4	47
	1240 & 1244 Donald St Ottawa ON	232.8	59
	1240 and 1244 Donald St Ottawa ON K1J8R7	232.8	59
	1089 Ogilvie Road and 1137 Cyrville Rd Ottawa ON	256.5	63
	1059 Ogilvie Road Gloucester ON K1J 7S6	272.2	71
	1240 Donald St Gloucester ON K1J 8R7	284.1	72
	1200 St Laurent Blvd Ottawa ON K1K 4H4	291.1	73

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Oct 2023 has found that there are 4 EXP site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
6205429 CANADA INC	1007 ST. LAURENT BLVD OTTAWA ON	139.6	38

Site	Address	Distance (m)	Map Key
6205429 CANADA INC	1007 ST. LAURENT BLVD OTTAWA ON	139.6	38
6205429 CANADA INC	1007 ST. LAURENT BLVD OTTAWA ON	139.6	38
6205429 CANADA INC	1007 ST. LAURENT BLVD OTTAWA ON	139.6	38

FST - Fuel Storage Tank

A search of the FST database, dated Oct 2023 has found that there are 10 FST site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1007 ST. LAURENT BLVD OTTAWA ON	139.6	38
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1007 ST. LAURENT BLVD OTTAWA ON	139.6	38
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1007 ST. LAURENT BLVD OTTAWA ON	139.6	38
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1007 ST. LAURENT BLVD OTTAWA ON	139.6	38
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	161.2	45
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	161.2	45

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	161.2	45
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	161.2	45
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	161.2	45
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	161.2	45

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 5 FSTH site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
6434118 CANADA INC O/A SUNOCO	1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	139.6	38
6151892 CANADA INC	1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	139.6	38
1343615 ONTARIO INC O/A PETRO CANADA	1018 CYRVILLE RD GLOUCESTER ON K1J 7S4	161.2	45
1427229 ONTARIO INC ATTN JOSEPH T SAAB	1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	295.8	75
1427229 ONTARIO INC ATTN JOSEPH T SAAB	1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	295.8	75

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Dec 31, 2024 has found that there are 131 GEN site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ZELLERS PHARMACY	1055 ST. LAURENT BLVD. OTTAWA ON K1K 3B1	50.6	11
Riocan Property	1055 St. Laurent Blvd. Ottawa ON K1K 3B1	50.6	11
Zellers # 313	1055 St. Laurent Blvd Ottawa ON K1K 3B1	50.6	11
Target Canada Co.	1055 St. Laurent Blvd. Ottawa ON K1K 3B1	50.6	11
Target Canada Co.	1055 St. Laurent Blvd. Ottawa ON K1K 3B1	50.6	11
RioCan Management Inc.	1091 St-Laurent Blvd. Ottawa ON	55.7	12
CONSEIL DES ECOLES CATHOLIQUES DE LANGUE	EDUCATION SANS FRONTIERE 1116 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B6	100.9	23
CONSEIL DES ECOLES CATHOLIQUES DE LANGUE	EDUCATION SANS FRONTIERE 1116 BOUL. ST-LAURENT OTTAWA ON K1K 3B6	100.9	23
ONE STOP LAUNDROMAT(OUT OF BUSINESS)-589	914115 ONT. INC. 1045 ST. LAURENT BLVD. OTTTAWA ON K1K 3B1	160.8	44
ONE STOP LAUNDROMAT 29-589	914115 ONT. INC. 1045 ST. LAURENT BLVD. OTTTAWA ON K1K 3B1	160.8	44
Ottawa-Carleton District School Board	Queen Mary Street Public School 557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51

Site	Address	Distance (m)	Map Key
Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON	195.3	51
Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board Health & Safety	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board Health & Safety	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board Health & Safety	557 Queen Mary Street Ottawa ON K1K 1V9	195.3	51
Ottawa-Carleton District School Board	Queen Mary Public School, 557 Queen Mary Street Ottawa ON	195.3	51

Site	Address	Distance (m)	Map Key
KONE INC	1240-1244 DONALD ST OTTAWA ON	232.8	59
GREENWIN PROPERTY MANAGEMENT INC	1240-1244 DONALD STREET OTTAWA ON K1J 8V6	232.8	59
BELL CANADA	490 COVENTRY ROAD OTTAWA ON K1K 2C4	263.3	66
KONICA ONE HOUR PHOTO	1239 DONALD ST. OTTAWA ON K1J 8W3	270.1	69
KONICA ONE HOUR PHOTO 23-368	1239 DONALD ST. OTTAWA ON K1J 8W3	270.1	69
FUJI IMAGE (OUT OF BUSINESS)Y LTD.15-593	1239 DONALD STREET GLOUCESTER ON K1J 8W3	270.1	69
Rio Can Property Services	1239 Donald Street Ottawa ON K1J 8W3	270.1	69
BLACK PHOTO CORPORATION	1200 ST. LAURENT BOULEVARD, OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	291.1	73
BLACK PHOTO CORPORATION	1200 ST. LAURENT BOULEVARD ST. LAURENT SHOPPING CENTRE OTTAWA ON K1K 3B8	291.1	73
BLACK PHOTO CORPORATION 05-410	1200 ST. LAURENT BOULEVARD - OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	291.1	73
BLACK PHOTO CORPORATION	ST. LAURENT SHOPPING CENTRE 1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	291.1	73

Site	Address	Distance (m)	Map Key
CADILLAC FAIRVIEW CORPORATION LTD.08-539	1200 ST. LAURENT BLVD. OTTAWA ON K1K 3B8	291.1	73
CADILLAC FAIRVIEW CORPORATION LTD.08-539	1200 ST. LAURENT BLVD. PO BOX 199 OTTAWA ON K1K 3B8	291.1	73
CADILLAC FAIRVIEW CORPORATION LIMITED	1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	291.1	73
CADILLAC FAIRVIEW CORP. LTD.	N. MALL AREA-ENT. BANK & SHOP. DRUG M. C/O 1200 ST.-LAURENT BLVD. OTTAWA ON K1K 3B8	291.1	73
CADILLAC (SEE & USE ON0733507) 08-539	N. MALL AREA-ENT. BANK & SHOP. DRUG M. C/O 1200 ST.-LAURENT BLVD. OTTAWA ON K1K 3B8	291.1	73
JAPAN CAMERA CENTRE	PHOTO MINUTES ONTARIO INC. 1200 ST. LAURENT OTTAWA ON K9K 3B8	291.1	73
JAPAN CAMERA CENTRE 31-345	PHOTO MINUTES ONTARIO INC. 1200 ST. LAURENT OTTAWA ON K9K 3B8	291.1	73
BLACK (OUT OF BUS) 05-661	ST.LAURENT11-1200ST.LAURENT BLVD-OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	291.1	73
BLACK PHOTO CORPORATION 05-661	ST.LAURENT11-1200ST.LAURENT BLVD-OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	291.1	73
CAREER CANADA COLLEGE	1200 ST. LAURENT BOULEVARD SUITE 261 OTTAWA ON	291.1	73
FORZANI GROUP LTD., THE	SPORT CHEK, ST. LAURENT MALL 1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	291.1	73
DEVAN PROPERTIES LTD.	1200 ST-LAURENT BOULEVARD OTTAWA ON K1K 3B8	291.1	73

Site	Address	Distance (m)	Map Key
CAREER CANADA COLLEGE	1200 ST. LAURENT BOULEVARD, SUITE 261 OTTAWA ON	291.1	73
SPORT CHEK	ST. LAURENT MALL 1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	291.1	73
SHOPPERS DRUG MART	1200 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B8	291.1	73
CAREER CANADA COLLEGE	1200 ST. LAURENT BOULEVARD, SUITE 261 Unit 261 OTTAWA ON K1K 3B8	291.1	73
7139490 ONTARIO LIMITED	1200 LAURENT BLVD. OTTAWA ON K1K 3B8	291.1	73
CDI COLLEGE	1200 ST. LAURENT BOULEVARD, SUITE 261 OTTAWA ON	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
CDI COLLEGE	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	291.1	73
Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	291.1	73
Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	291.1	73
Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	291.1	73

Site	Address	Distance (m)	Map Key
The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON	291.1	73
Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON	291.1	73
The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON	291.1	73
Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON	291.1	73
Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	291.1	73
CINDY CHANGOOR PHARMACY LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON	291.1	73
Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON	291.1	73
Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	291.1	73

Site	Address	Distance (m)	Map Key
Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON	291.1	73
CINDY CHANGOOR PHARMACY LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON	291.1	73
Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	291.1	73
CINDY CHANGOOR PHARMACY LIMITED	1200 ST LAURENT BLVD OTTAWA ON	291.1	73
The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON	291.1	73
Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON	291.1	73
Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73

Site	Address	Distance (m)	Map Key
St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	291.1	73
FGL SPORTS LIMITED	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	291.1	73
Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	291.1	73
Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	291.1	73
The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
Cindy Changoor Pharmacy Limited (641)	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	291.1	73
Cindy Changoor Pharmacy Limited (621)	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	291.1	73
Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	291.1	73
Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	291.1	73
St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	291.1	73
Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	291.1	73

Site	Address	Distance (m)	Map Key
Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	291.1	73
St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	291.1	73
Everest College of Business	1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON K1K 3B8	291.1	73
CINDY CHANGOOR PHARMACY LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
The Forzani Group	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	291.1	73
FGL SPORTS LIMITED	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	291.1	73
St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	291.1	73
Herzing College St. Laurent Blvd Ottawa	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	291.1	73
Cindy Changoor Pharmacy Limited (621)	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73

Site	Address	Distance (m)	Map Key
St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	291.1	73
FGL SPORTS LIMITED	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	291.1	73
Cindy Changoor Pharmacy Limited (621)	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	291.1	73
713949 ONTARIO LIMITED	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
Herzing College	1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	291.1	73
FGL SPORTS LIMITED	1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	291.1	73
LensCrafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	291.1	73
St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	291.1	73
Ben Gunter Pharmacy Inc	1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	291.1	73
Lens Crafters #939	1200 St. Laurent Blvd Ottawa ON K1K3B8	291.1	73
Morguard Real Estate Investment Trust	1200 St. Laurent Blvd. Ottawa ON	291.1	73
Shoppers Drug Mart	1200 ST. LAURENT BLVD Ottawa ON	291.1	73

Site	Address	Distance (m)	Map Key
LCBO	540-1200 ST. LAURENT BLVD Ottawa ON K1K3B8	291.1	73
EssilorLuxottica of Canada	1200 St. Laurent Blvd Ottawa ON	291.1	73
St. Laurent Dental Center	1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	291.1	73
Sport Chek	1200 St. Laurent Blvd. Ottawa ON	291.1	73
LCBO	1200 Saint Laurent Boulevard Ottawa ON	291.1	73
EssilorLuxottica of Canada	1200 Saint Laurent Boulevard Ottawa ON	291.1	73
St Laurent Dental Centre	1200 Saint Laurent Boulevard Ottawa ON	291.1	73
RTM	1200 Saint Laurent Boulevard Ottawa ON	291.1	73
American Eagle Outfitters Canada Corporation	1200 Saint Laurent Boulevard Ottawa ON	291.1	73
Norris Construction Management Inc.	1057 Cyrville Road Ottawa ON	295.8	75
SAAB Gas Center	1057 Cyrville Road Ottawa ON	295.8	75

Site	Address	Distance (m)	Map Key
SAAB Gas Centre	1057 Cyrville Road Ottawa ON	295.8	75
BELL CANADA	1057 Cyrville Road Ottawa ON	295.8	75
Elite Environmental Group Inc	1105 Hardy Ave Ottawa ON K1K3H8	298.4	78
Rio-Can Property Services	1235 Donald Street Ottawa ON K1J 8W3	298.6	79
TJX Canada	1235 Donald Street Ottawa ON	298.6	79

HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 1 HINC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1240 DONALD STREET OTTAWA ON	232.8	59

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated 31 Oct, 2023 has found that there are 2 INC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1018 CYRVILLE RD GLOUCESTER ON	161.2	45
	Coventry Road at St Laurent Boulevard, Ottawa ON	265.3	67

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 1 NPCB site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CADILLAC FAIRVIEW CORPORATION LIMITED	1200 ST. LAURENT BOULVARD; ST. LAURENT SHOPPING CE OTTAWA ON K1K 3B8	291.1	73

NPRI - National Pollutant Release Inventory - Historic

A search of the NPRI database, dated 1993-May 2017 has found that there are 1 NPRI site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ZELLERS	105 105-1055 ST LAURENT Boulevard OTTAWA ON K1K3B1	50.6	11

OPCB - Inventory of PCB Storage Sites

A search of the OPCB database, dated 1987-Oct 2004; 2012-Dec 2013 has found that there are 2 OPCB site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CADILLAC FAIRVIEW CORPORATION LIMITED	1200 ST. LAURENT BOULVARD ST. LAURENT SHOPPING CENTRE OTTAWA ON K1K 3B8	291.1	73
CADILLAC FAIRVIEW CORPORATION LIMITED	1200 ST. LAURENT BOULVARD ST. LAURENT SHOPPING CENTRE OTTAWA ON K1K 3B8	291.1	73

PES - Pesticide Register

A search of the PES database, dated Oct 2011 - Apr 30, 2025 has found that there are 29 PES site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ZELLERS STORE #313 - ZELLERS PLAZA	1055 ST. LAURENT BLVD OTTAWA ON K1K3B1	50.6	11

Site	Address	Distance (m)	Map Key
K MART STORES STORE #5420	1055 ST LAURENT BLVD OTTAWA ON K1K3B1	50.6	11
K MART STORES STORE #5420	1055 ST LAURENT BLVD OTTAWA ON K1K 3B1	50.6	11
ZELLERS STORE #313 - ZELLERS PLAZA	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	50.6	11
ZELLERS STORE #313 - ZELLERS PLAZA	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	50.6	11
ZELLERS STORE #313 - ZELLERS PLAZA	1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	50.6	11
TARGET CANADA CO. O/A TARGET STORE T3658	1055 ST.LAURENT BLVD OTTAWA ON K1K3B1	50.6	11
METRO ONTARIO INC O/A METRO/FOOD BASICS # 262	1021 ST. LAURENT BOULEVARD OTTAWA ON K1K3B1	193.4	47
METRO ONTARIO INC O/A METRO/FOOD BASICS # 262	1021 St. Laurent Boulevard Ottawa ON K1K 3B1	193.4	47
METRO ONTARIO INC O/A METRO/FOOD BASICS # 262	1021 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B1	193.4	47
METRO ONTARIO INC O/A METRO/FOOD BASICS # 896	1021 CYRVILLE ROAD, UNIT 1 OTTAWA ON K1J7S3	195.0	50
METRO ONTARIO INC O/A METRO/FOOD BASICS # 896	1021 CYRVILLE ROAD, UNIT 1 OTTAWA ON K1J7S3	195.0	50
METRO ONTARIO INC O/A METRO/FOOD BASICS # 896	1021 Cyrville Road, Unit 1 Ottawa ON K1J 7S3	195.0	50

Site	Address	Distance (m)	Map Key
IAN MCNEIL PHARMACIES INC	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
SHOPPERS DRUG MART#0621(ST. LAURENT SHOPPING CENTRE)	1200 ST. LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
IAN MCNEIL PHARMACIES INC	1200 ST LAURENT BLVD OTTAWA ON K1K3B8	291.1	73
TLM PHARMACIES INC.	1200 ST. LAURENT BLVD OTTAWA ON K1K3B3	291.1	73
CINDY CHANGOOR PHARMACY LTD	1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	291.1	73
TLM PHARMACIES INC.	1200 ST. LAURENT BLVD OTTAWA ON K1K 3B3	291.1	73
CINDY CHANGOOR PHARMACY LTD	1200 ST LAURENT BLVD OTTAWA ON K1K3B8	291.1	73
IAN MCNEIL PHARMACIES INC	1200 ST LAURENT BLVD OTTAWA ON K1K3B8	291.1	73
TLM PHARMACIES INC.	1200 ST. LAURENT BLVD OTTAWA ON K1K3B3	291.1	73
SHOPPERS DRUG MART#0621(ST. LAURENT SHOPPING CENTRE)	1200 ST. LAURENT BLVD OTTAWA ON K1K3B8	291.1	73
LOBLAW SUPERMARKETS LTD. STORE NO. 180-2	1235 DONALD STREET GLOUCESTER ON K1J 8W3	298.6	79

Site	Address	Distance (m)	Map Key
LOBLAWS #180	1235 DONALD STREET GLOUCESTER ON K1J 8W3	298.6	79
LOBLAWS SUPERMARKETS LIMITED	1235 DONALD STREET OTTAWA ON K1J 8W3	298.6	79
LOBLAW SUPERMARKETS LTD. STORE NO. 180-2	1235 DONALD STREET GLOUCESTER ON K1J8W3	298.6	79
LOBLAWS SUPERMARKETS LIMITED	1235 DONALD STREET OTTAWA ON K1J8W3	298.6	79
LOBLAWS #180	1235 DONALD STREET GLOUCESTER ON K1G1W3	298.6	79

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 5 PRT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
M ELLIS	1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	139.6	38
E ANNE BRUNDIGE	1018 CYRVILLE RD GLOUCESTER ON K1J 7S4	161.2	45
CATHYS CORNER	1018 CYRVILLE RD GLOUCESTER ON	161.2	45
JOE T SAAB 135247 CANADA INC	1057 CYRVILLE RD GLOUCESTER ON	295.8	75
JOSEPH T SAAB	1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	295.8	75

Site	Address	Distance (m)	Map Key

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Apr 30, 2024 has found that there are 9 RST site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PETRO CANADA	1007 ST LAURENT BLVD OTTAWA ON K1K3B1	139.6	38
ST LAURENT FUN FOOD SUNOCO	1007 ST LAURENT BLVD OTTAWA ON K1K3B1	139.6	38
ST LAURENT SUNOCO	1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	139.6	38
ST LAURENT SUNOCO	1007 ST LAURENT BLVD OTTAWA ON K1K3B1	139.6	38
SAAB GAS CENTRE	1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	295.8	75
SAAB GAS CENTRE	1057 CYRVILLE RD OTTAWA ON K1J 7S3	295.8	75
SAAB GAS CENTRE	1057 CYRVILLE RD GLOUCESTER ON K1J7S3	295.8	75
SAAB GAS CENTRE	1057 CYRVILLE RD GLOUCESTER ON K1J7S3	295.8	75
SAAB GAS CENTRE	1057 CYRVILLE RD GLOUCESTER ON K1J7S3	295.8	75

SPL - Ontario Spills

A search of the SPL database, dated 1988-Jun 2024; Aug-Feb 2025 has found that there are 32 SPL site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
MAC'S	MAC'S MILK 1076 ST. LAURENT BLVD. CONVENIENCE STORE/GAS BAR OTTAWA CITY ON K1K 3B4	7.2	8
OTTAWA	707 Alesther St OTTAWA ON	21.5	9
PRIVATE OWNER	1055 ST. LAURENT BLVD NEAR K-MART STORE MOTOR VEHICLE (OPERATING FLUID) GLOUCESTER CITY ON K1K 3B1	50.6	11
	1055 St.Laurent Blvd. Ottawa ON K1K 3B1	50.6	11
	694 Alesther Dr, Ottawa ON	58.0	14
Waste Services (CA) Inc.; Waste Services (CA) Inc.	1020 St. Laurant St. Ottawa ON	83.7	19
Waste Services (CA) Inc.	1020 St. Laurent St, Ottawa Ottawa ON	83.7	19
O.C. TRANSPO	CORNER ST. LAURENT & CYRVILLE ROAD MOTOR VEHICLE (OPERATING FLUID) OTTAWA CITY ON	91.6	20
OC Transpo<UNOFFICIAL>	St Laurent Blvd northbound 100 m south of Donald St Ottawa ON	108.4	27
FIRESTONE	FIRESTONE 1110 ST. LAURENT BLVD. VEHICLE SERVICE STATION OTTAWA CITY ON K1K 3B6	119.3	31

Site	Address	Distance (m)	Map Key
Willy's Roll-off<UNOFFICIAL>	1110 St-Laurent Blvd Ottawa ON K1K 3B6	119.3	31
Tomlinson Environmental Services Ltd	1110 Saint Laurent Boulevard Ottawa ON	119.3	31
SUNOCO	1007 ST. LAURENT STREET SERVICE STATION OTTAWA CITY ON K1K 3B1	139.6	38
PETRO-CANADA	1018 SYRVILLE RD TANK TRUCK (CARGO) GLOUCESTER CITY ON K1J 7S4	161.2	45
	1018 Cyrville Rd Ottawa ON	161.2	45
	1021 St. Laurent Blve Ottawa ON	193.4	47
Metro Ontario Incorporated	1021 Cyrville Road Ottawa ON K1J 7S3	195.0	50
Rio Can Properties<UNOFFICIAL>	1021 Cyrville Rd. Ottawa ON	195.0	50
Metro Ontario Incorporated	1021 Cyrville Road Ottawa ON K1J 7S3	195.0	50
SHELL CANADA PRODUCTS LTD.	AT THE QUEEN MARY PUBLIC SCHOOL AT 557 QUEEN MARY ROAD TANK TRUCK (CARGO) OTTAWA CITY ON K1K 1V9	195.3	51
BFI Canada<UNOFFICIAL>	Corner of Donald Street and St. Laurent Ottawa ON	219.0	55
Storm sewer<UNOFFICIAL>	Intersection of Donald and St. Laurent Blvd. Ottawa ON	219.0	55

Site	Address	Distance (m)	Map Key
City of Ottawa	St Laurent and Donald Ottawa ON	219.0	55
TEXACO	TEXACO SERVICE STATION AT CORNER OF ST. LAURENT BLVD., OGILVY RD SERVICE STATION OTTAWA CITY ON	266.8	68
Canadian Waste Management<UNOFFICIAL>	1200 St. Laurent St. Ottawa ON	291.1	73
City of Ottawa	1200 Saint Laurent Boulevard Ottawa ON	291.1	73
	1200 St. Laurent Boulevard Ottawa ON	291.1	73
	1200 St. Laurent Blvd. Ottawa ON	291.1	73
	1200 St Laurent Ave Ottawa ON	291.1	73
	OTTAWA ON	291.4	74
Carlsbad Auto 1057 Cyrville Road	1057 Cyrville Road, Ottawa OTTAWA ON	295.8	75
	1233 Donald St. Ottawa ON	297.0	76

WWIS - Water Well Information System

A search of the WWIS database, dated Dec 31 2023 has found that there are 28 WWIS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON ***Well ID:*** 7347865	0.0	2
	ON ***Well ID:*** 7347868	0.0	4
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7191558	43.9	10
	1055 ST. LAWRENT BLVD Ottawa ON ***Well ID:*** 7191555	58.0	13
	1110 ST. LAURENT BLVD. Ottawa ON ***Well ID:*** 7174555	64.1	15
	lot 9 ON ***Well ID:*** 1500404	64.2	16
	ON ***Well ID:*** 1508882	71.0	17
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7191559	76.1	18
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205218	93.1	21
	ON ***Well ID:*** 7306228	94.3	22
	1076 ST. LAURENT BLVD OTTAWA ON ***Well ID:*** 1535863	106.5	24

Site	Address	Distance (m)	Map Key
	1055 ST LAURENT BLVD Ottawa ON ***Well ID:*** 7191556	107.3	25
	lot 8 ON ***Well ID:*** 1500398	107.5	26
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205219	112.5	28
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205220	122.6	32
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205223	123.5	33
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7191560	139.2	37
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7191557	145.4	39
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205221	146.5	40
	lot 8 ON ***Well ID:*** 1500399	147.7	42
	1055 ST. LAURENT BLVD Ottawa ON ***Well ID:*** 7205222	152.1	43
	lot 25 con 2 ON ***Well ID:*** 1501337	194.4	49
	lot 26 con 1 ON	194.4	49

Site	Address	Distance (m)	Map Key
	Well ID: 1501137		
	lot 26 con 1 ON	209.6	52
	Well ID: 7411205		
	1055 ST. LAURENT BLVD Ottawa ON	209.7	53
	Well ID: 7205224		
	lot 26 con 1 ON	232.2	58
	Well ID: 1501135		
	lot 26 con 1 ON	270.3	70
	Well ID: 1501132		
	lot 26 con 2 ON	298.0	77
	Well ID: 1501342		



Map: 0.3 Kilometer Radius

Order Number: 24102901203

Address: 1052, 1060 and 1064 St. Laurent Boulevard, Ottawa, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Aerial

Year: 2023

Order Number: 24102901203

Address: 1052, 1060 and 1064 St. Laurent Boulevard, Ottawa, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Address: 1052, 1060 and 1064 St. Laurent Boulevard, ON

Source: ESRI World Topographic Map

Order Number: 24102901203

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	WSW/0.0	70.9 / 0.00	1064 St. Laurent Blvd Ottawa ON K1K 3B4	EHS

Order No:	24053100242	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	05-JUN-24	**Search Radius (km):**	.25
Date Received:	31-MAY-24	**X:**	-75.6393562
Previous Site Name:		**Y:**	45.4266386
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 1	NW/0.0	70.9 / 0.00	ON	WWIS

Well ID:	7347865	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	11/25/2019
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C40419	**Contractor:**	1844
Tag:	A251159	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1007722508	**Tag No:**	A251159
Depth M:		**Contractor:**	1844
Year Completed:	2019	**Latitude:**	45.4268177306223
Well Completed Dt:	10/02/2019	**Longitude:**	-75.6393369055781
Audit No:	C40419	**Y:**	45.42681772391938
Path:		**X:**	-75.63933674423058

Bore Hole Information

Bore Hole ID:	1007722508	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	449986.00
Code OB Desc:		**North83:**	5030565.00

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/02/2019	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

3 | ***1 of 1*** | ***NW/0.0*** | ***70.9 / 0.00*** | ***1060 St Laurent Blvd Ottawa ON K1K 3B4*** | ***EHS***

Order No:	20190819197	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Select Report	**Client Prov/State:**	ON
Report Date:	26-AUG-19	**Search Radius (km):**	.25
Date Received:	19-AUG-19	**X:**	-75.639384
Previous Site Name:		**Y:**	45.426853
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Title Searches; Topographic Maps; City Directory; Aerial Photos		

---

4 | ***1 of 1*** | ***NNE/0.0*** | ***71.9 / 1.00*** | ***ON*** | ***WWIS***

Well ID:	7347868	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	11/25/2019
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C47013	**Contractor:**	1844
Tag:	A251159	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1007723408	**Tag No:**	A251159
Depth M:		**Contractor:**	1844
Year Completed:	2019	**Latitude:**	45.4269180258499
Well Completed Dt:	09/03/2019	**Longitude:**	-75.6391079404237
Audit No:	C47013	**Y:**	45.42691801914941
Path:		**X:**	-75.63910777810517

Bore Hole Information

Bore Hole ID:	1007723408	**Elevation:**	
DP2BR:		**Elevrc:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450004.00
Code OB Desc:		**North83:**	5030576.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/03/2019	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

5 | ***1 of 1*** | ***N/0.0*** | ***71.0 / 0.14*** | ***1052 St. Laurent Blvd Ottawa ON K1K 3B4*** | ***EHS***

Order No:	24051600078	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Select Report	**Client Prov/State:**	ON
Report Date:	22-MAY-24	**Search Radius (km):**	.25
Date Received:	16-MAY-24	**X:**	-75.6392004
Previous Site Name:		**Y:**	45.4269691
Lot/Building Size:			
Additional Info Ordered:	Aerial Photos		

---

6 | ***1 of 1*** | ***NNW/0.0*** | ***71.0 / 0.14*** | ***1052 St. Laurent Blvd Ottawa ON K1K 3B4*** | ***EHS***

Order No:	21033100146	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	06-APR-21	**Search Radius (km):**	.25
Date Received:	31-MAR-21	**X:**	-75.6393116
Previous Site Name:		**Y:**	45.4269933
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

---

7 | ***1 of 1*** | ***NNW/0.0*** | ***71.0 / 0.14*** | ***1052 St Laurent Blvd Ottawa ON K1K3B4*** | ***EHS***

Order No:	20151105011	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	10-NOV-15	**Search Radius (km):**	.25
Date Received:	05-NOV-15	**X:**	-75.639395
Previous Site Name:		**Y:**	45.426978
Lot/Building Size:			
Additional Info Ordered:			

---

8 | ***1 of 1*** | ***SSE/7.2*** | ***70.9 / 0.00*** | ***MAC'S MAC'S MILK 1076 ST. LAURENT BLVD. CONVENIENCE STORE/GAS BAR OTTAWA CITY ON K1K 3B4*** | ***SPL***

Ref No:	77536	**Municipality No:**	20101
Year:		**Nature of Damage:**	
Incident Dt:	10/14/1992	**Discharger Report:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/14/1992	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	DRAIN-ALL
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	OTTAWA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER TRANSPORTATION ACCIDENT		
Incident Preceding Spill:			
Incident Reason:	ERROR		
Incident Summary:	MAC'S MILK-UNKN. QTY. FURNACE OIL TO GRD WHEN CAR DROVE IN TO TANK.		
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	1 of 1	WSW/21.5	70.9 / 0.00	OTTAWA 707 Alesther St OTTAWA ON	SPL

Ref No:	1-C3D7H	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	4/6/2021 12:30:00 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/6/2021 12:54:20 PM	**Impact to Health:**	0 No Impact
Dt Document Closed:	4/29/2021 3:14:55 PM	**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa District Office		
Nearest Watercourse:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Name:	
Site Address:	707 Alesther St
Site Region:	
Site Municipality:	OTTAWA
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	OTTAWA
Client Type:	Government, Municipal
Source Type:	
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	
Incident Summary:	City of Ottawa: Hyd Oil Spill to Asphalt
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	70 litre (L)
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	HYDRAULIC OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	Lower Ottawa
Property Tertiary Watershed:	02LA-Rideau
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00003920520"],"wkts":["POINT (-75.6395528000 45.4264241000)"],"creation_date":"2021-04-06"}
Time Reported:	
System Facility Address:	

10	1 of 1	E/43.9	71.9 / 1.00	1055 ST. LAURENT BLVD Ottawa ON	WWIS

Well ID:	7191558	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/14/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z156894	**Contractor:**	7241
Tag:	A113448	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191558.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/24/2012
Year Completed: 2012
Depth (m): 5.79
Latitude: 45.426724370836
Longitude: -75.6383259832005
X: -75.63832582097727
Y: 45.42672436410812
Path: 719\7191558.pdf

Bore Hole Information

Bore Hole ID: 1004204431
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/24/2012
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 450065.00
North83: 5030554.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004526930
Layer: 3
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 85
Material 2 Desc: SOFT
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 3.0999999046325684
Formation End Depth: 5.789999961853027
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004526929
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 85
Material 2 Desc: SOFT
Material 3:
Material 3 Desc:

Formation Top Depth: 0.3100000023841858
Formation End Depth: 3.0999999046325684
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004526928
Layer: 1
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 68
Material 2 Desc: DRY
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526939
Layer: 2
Plug From: 0.3100000023841858
Plug To: 2.440000057220459
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526940
Layer: 3
Plug From: 2.440000057220459
Plug To: 5.789999961853027
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526938
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004526937
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004526927
Casing No: 0
Comment:

Alt Name:

Construction Record - Casing

Casing ID:	1004526933
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	2.740000009536743
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004526934
Layer:	1
Slot:	10
Screen Top Depth:	2.740000009536743
Screen End Depth:	5.789999961853027
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004526932
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004526931
Diameter:	8.25
Depth From:	0.0
Depth To:	5.789999961853027
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	1 of 18	ENE/50.6	71.9 / 1.00	K MART STORES STORE #5420 1055 ST LAURENT BLVD OTTAWA ON K1K 3B1	PES

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

District: ***MOE District:***
County: ***SWP Area Name:***
Trade Name:
PDF URL:

---

11 ***2 of 18*** ***ENE/50.6*** ***71.9 / 1.00*** ***PRIVATE OWNER*** ***SPL***
1055 ST. LAURENT BLVD NEAR K-MART STORE
MOTOR VEHICLE (OPERATING FLUID)
GLOUCESTER CITY ON K1K 3B1

Ref No:	154350	***Municipality No:***	20105
Year:		***Nature of Damage:***	
Incident Dt:	4/7/1998	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	4/8/1998	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	OTTAWA-CARLETON R.M.
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	GLOUCESTER CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER CAUSE (N.O.S.)		
Incident Preceding Spill:			
Incident Reason:	INTENTIONAL/PLANNED		
Incident Summary:	PRIVATE OWNER-4 L WASTE MOTOR OIL DUMPED ONTO SNOW AT PLAZA,CLEANING UP		
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	3 of 18	ENE/50.6	71.9 / 1.00	ZELLERS PHARMACY 1055 ST. LAURENT BLVD. OTTAWA ON K1K 3B1	GEN

Generator Info

Generator No:	ON1514511	**Choice of Contact:**	
Approval Years:	00,01	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6031
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHARMACIES		

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	4 of 18	ENE/50.6	71.9 / 1.00	ZELLERS STORE #313 - ZELLERS PLAZA 1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	PES

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	5 of 18	ENE/50.6	71.9 / 1.00	Riocan Property 1055 St. Laurent Blvd. Ottawa ON K1K 3B1	GEN

Generator Info

Generator No:	ON3699865	**Choice of Contact:**	
Approval Years:	05	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	452110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Co Admin:
Phone No Admin:
SIC Description: Department Stores

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

11 | ***6 of 18*** | ***ENE/50.6*** | ***71.9 / 1.00*** | ***ZELLERS STORE #313 - ZELLERS PLAZA***
1055 ST. LAURENT BLVD
OTTAWA ON K1K 3B1 | ***PES***

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

11 | ***7 of 18*** | ***ENE/50.6*** | ***71.9 / 1.00*** | ***1055 St.Laurent Blvd.***
Ottawa ON K1K 3B1 | ***SPL***

Ref No: 4838-7U4RQ7
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/19/2009
Dt Document Closed:
Site No:
MOE Response: Priority Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Zellers Store Parking Lot.<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Incident Cause:	Unknown
Incident Preceding Spill:	
Incident Reason:	Spill
Incident Summary:	Zellers: Leaking diesel from saddle tank of parked TT.
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Other Impact(s)
Contaminant Qty:	5 L
Contaminant Qty 1:	5
Contaminant Unit:	L
Contaminant Code:	
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Transport Truck
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

11 | ***8 of 18*** | ***ENE/50.6*** | ***71.9 / 1.00*** | ***Zellers # 313***
1055 St. Laurent Blvd
Ottawa ON K1K 3B1 | ***GEN***

Generator Info

Generator No:	ON3688802	***Choice of Contact:***	
Approval Years:	2009	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	452110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Department Stores		

Waste Detail(s)

Waste Class:	243
Waste Class Name:	PCBS

---

11 | ***9 of 18*** | ***ENE/50.6*** | ***71.9 / 1.00*** | ***1055 St Laurent Blvd***
Ottawa ON K1K 3B1 | ***EHS***

Order No:	20121019031	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	30-OCT-12	***Search Radius (km):***	.25
Date Received:	19-OCT-12	***X:***	-75.637133
Previous Site Name:		***Y:***	45.427607
Lot/Building Size:			
Additional Info Ordered:			

---

11 | ***10 of 18*** | ***ENE/50.6*** | ***71.9 / 1.00*** | ***ZELLERS STORE #313 - ZELLERS PLAZA***
1055 ST. LAURENT BLVD | ***PES***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				OTTAWA ON K1K 3B1	

Detail Licence No: 23-01-12909-0
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: LIMITED
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

11	11 of 18	ENE/50.6	71.9 / 1.00	TARGET CANADA CO. 1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	EASR

Approval No: R-002-9399386639
Status: REGISTERED
Date: 2014-02-15
Record Type: EASR
Link Source: MOFA
Project Type: Standby Power System
Full Address:
Approval Type: EASR-Standby Power System
SWP Area Name: Rideau Valley
PDF NAICS Code:
PDF URL:
PDF Site Location:

MOE District: Ottawa
Municipality: OTTAWA
Latitude: 45.42722222
Longitude: -75.63833333
Geometry X:
Geometry Y:

11	12 of 18	ENE/50.6	71.9 / 1.00	TARGET CANADA CO. 1055 ST. LAURENT BLVD OTTAWA ON K1K 3B1	EASR

Approval No: R-003-3399410951
Status: REGISTERED
Date: 2014-02-15
Record Type: EASR
Link Source: MOFA
Project Type: Heating System
Full Address:
Approval Type: EASR-Heating System
SWP Area Name: Rideau Valley
PDF NAICS Code:
PDF URL:
PDF Site Location:

MOE District: Ottawa
Municipality: OTTAWA
Latitude: 45.42722222
Longitude: -75.63833333
Geometry X:
Geometry Y:

11	13 of 18	ENE/50.6	71.9 / 1.00	ZELLERS 105 105-1055 ST LAURENT Boulevard OTTAWA ON K1K3B1	NPRI

NPRI ID: 8800000461
Org ID:

Other ID:		***Submit Date:***	
No Other ID:		***Last Modified:***	
Track ID:		***Contact ID:***	
Report ID:		***Cont Type:***	MED
Report Type:		***Contact Title:***	Mr.
Rpt Type ID:		***Cont First Name:***	FRED
Report Year:	2004	***Cont Last Name:***	WARE
Not-Current Rpt?:		***Contact Position:***	SENIOR MANGER ENERGY ENVIRONMENT SOURCING INITIATIVES
Yr of Last Filed Rpt:		***Contact Fax:***	
Fac ID:		***Contact Ph.:***	
Fac Name:	ZELLERS STORE, #313 ZELLERS PLAZA	***Cont Area Code:***	416
Fac Address1:		***Contact Tel.:***	8614938
Fac Address2:		***Contact Ext.:***	
Fac Postal Zip:		***Cont Fax Area Cde:***	416
Facility Lat:		***Contact Fax:***	8616619
Facility Long:		***Contact Email:***	fred.ware@hbc.com
DLS (Last Filed Rpt):		***Latitude:***	
Facility DLS:		***Longitude:***	
Datum:		***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	20	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	53		
NAICS 2 Description:	Real Estate and Rental and Leasing		
NAICS Code (4 digit):	5311		
NAICS 4 Description:	Lessors of Real Estate		
NAICS Code (6 digit):	531120		
NAICS 6 Description:	Lessors of Non-Residential Buildings (except Mini-Warehouses)		

Substance Release Report

CAS No:	11104-93-1
Report ID:	
Rpt Period:	2004
Subst Released:	Nitrogen oxides (expressed as NO2)
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	630-08-0
Report ID:	
Rpt Period:	2004
Subst Released:	Carbon monoxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	74-82-8
Report ID:	
Rpt Period:	2004
Subst Released:	Methane

Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M08
Report ID:
Rpt Period: 2004
Subst Released: PM - Total Particulate Matter
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 10024-97-2
Report ID:
Rpt Period: 2004
Subst Released: Nitrous oxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 7446-09-5
Report ID:
Rpt Period: 2004
Subst Released: Sulphur dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 124-38-9
Report ID:
Rpt Period: 2004
Subst Released: Carbon dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004
Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No:	NA - M09
Report ID:	
Rpt Period:	2004
Subst Released:	PM10 - Particulate Matter <= 10 Microns
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes

CAS No:	NA - M10
Report ID:	
Rpt Period:	2004
Subst Released:	PM2.5 - Particulate Matter <= 2.5 Microns
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	14 of 18	ENE/50.6	71.9 / 1.00	Target Canada Co. 1055 St. Laurent Blvd. Ottawa ON K1K 3B1	GEN

Generator Info

Generator No:	ON4832079	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	452110
Country:	Canada		
Co Admin:	Carolyn Bue		
Phone No Admin:	800-587-2228 Ext.		
SIC Description:	DEPARTMENT STORES		

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

11	*15 of 18*	*ENE/50.6*	*71.9 / 1.00*	***Target Canada Co.*** ***1055 St. Laurent Blvd.*** ***Ottawa ON K1K 3B1***	***GEN***

Generator Info

Generator No:	ON4832079	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	452110
Country:	Canada		
Co Admin:	Carolyn Bue		
Phone No Admin:	800-587-2228 Ext.		
SIC Description:	DEPARTMENT STORES		

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

11 | ***16 of 18*** | ***ENE/50.6*** | ***71.9 / 1.00*** | ***TARGET CANADA CO. O/A TARGET STORE T3658***
1055 ST.LAURENT BLVD
OTTAWA ON K1K3B1 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	17011	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	7472600
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

11 | ***17 of 18*** | ***ENE/50.6*** | ***71.9 / 1.00*** | ***K MART STORES STORE #5420***
1055 ST LAURENT BLVD
OTTAWA ON K1K3B1 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	07015	**Operator Class:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	
Licence Type:	Retail Vendor Class 03	**Oper Phone No:**	
Licence Type Code:	21	**Operator Ext:**	
Licence Class:	03	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

11 | ***18 of 18*** | ***ENE/50.6*** | ***71.9 / 1.00*** | ***ZELLERS STORE #313 - ZELLERS PLAZA***
1055 ST. LAURENT BLVD
OTTAWA ON K1K3B1 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	12909	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	7464675
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

12 | ***1 of 1*** | ***E/55.7*** | ***71.9 / 1.00*** | ***RioCan Management Inc.***
1091 St-Laurent Blvd.
Ottawa ON | ***GEN***

Generator Info

Generator No:	ON8515215	**Choice of Contact:**	
Approval Years:	2013	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	531310
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	REAL ESTATE PROPERTY MANAGERS		

Waste Detail(s)

Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	1 of 1	NNE/58.0	71.9 / 1.00	1055 ST. LAWRENT BLVD Ottawa ON	WWIS

Well ID: 7191555
Construction Date:
Use 1st: Monitoring
Use 2nd: Municipal
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z156895
Tag: A086697
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/14/2012
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191555.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/24/2012
Year Completed: 2012
Depth (m): 3.96
Latitude: 45.4275587195109
Longitude: -75.638821154129
X: -75.63882099188983
Y: 45.42755871315902
Path: 719\7191555.pdf

Bore Hole Information

Bore Hole ID: 1004204422
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/24/2012
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 450027.00
North83: 5030647.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004526664
Layer: 2
Color: 2

General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 85
Material 2 Desc: SOFT
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 2.440000057220459
Formation End Depth: 3.9600000381469727
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004526663
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 85
Material 2 Desc: SOFT
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 0.0
Formation End Depth: 2.440000057220459
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526674
Layer: 3
Plug From: 0.9100000262260437
Plug To: 3.9600000381469727
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526673
Layer: 2
Plug From: 0.3100000023841858
Plug To: 0.9100000262260437
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526672
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004526671
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID:	1004526662
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004526667
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004526668
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004526666
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004526665
Diameter:	8.25
Depth From:	0.0
Depth To:	3.9600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	1 of 1	W/58.0	70.9 / 0.00	694 Alesther Dr, Ottawa ON	SPL

Ref No:	1-1TQH3K	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	5/30/2022 12:00:00 PM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	5/30/2022 5:15:22 PM	***Impact to Health:***	0 No Impact
Dt Document Closed:	5/31/2022 8:48:36 AM	***Agency Involved:***	
Site No:			
MOE Response:	Desktop Response		

Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Ottawa District Office
Nearest Watercourse:	
Site Name:	
Site Address:	694 Alesther Dr, Ottawa
Site Region:	
Site Municipality:	
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	
Incident Summary:	Ottawa - 300L hydraulic oil to road, cleaned.
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	300 litre (L)
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	HYDRAULIC OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	Lower Ottawa
Property Tertiary Watershed:	
Sector Type:	GENERAL FREIGHT TRUCKING, LOCAL
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00003923569"],"wkts":["POINT (-75.6403152000 45.4267399000)"],"creation_date":"2022-05-30"}
Time Reported:	
System Facility Address:	

15 | ***1 of 1*** | ***SSE/64.1*** | ***70.9 / 0.00*** | ***1110 ST. LAURENT BLVD. Ottawa ON*** | ***WWIS***

Well ID:	7174555	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	01/06/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z134644	**Contractor:**	6964
Tag:	A108229	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	

Clear/Cloudy: ***UTM Reliability:***
Municipality: OTTAWA CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7174555.pdf

Additional Detail(s) (Map)

Well Completed Date: 04/04/2011
Year Completed: 2011
Depth (m): 5.6
Latitude: 45.4258219434993
Longitude: -75.6387376491109
X: -75.63873748737092
Y: 45.42582193640318
Path: 717\7174555.pdf

Bore Hole Information

Bore Hole ID: 1003629422 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 18
Code OB: ***East83:*** 450032.00
Code OB Desc: ***North83:*** 5030454.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 04/04/2011 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004043124
Layer: 4
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 28
Material 2 Desc: SAND
Material 3: 72
Material 3 Desc: GRAVELLY
Formation Top Depth: 2.450000047683716
Formation End Depth: 5.599999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004043123
Layer: 3
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT

Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 81
Material 3 Desc: SANDY
Formation Top Depth: 0.800000011920929
Formation End Depth: 2.450000047683716
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004043122
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 01
Material 3 Desc: FILL
Formation Top Depth: 0.15000000596046448
Formation End Depth: 0.800000011920929
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004043121
Layer: 1
Color:
General Color:
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.15000000596046448
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004043132
Layer: 2
Plug From: 2.5899999141693115
Plug To: 4.570000171661377
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004043131
Layer: 1
Plug From: 0.0
Plug To: 2.5899999141693115
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004043130
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: HS AUGER

Pipe Information

Pipe ID: 1004043120
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004043127
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.9000000953674316
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004043128
Layer: 1
Slot: 10
Screen Top Depth: 2.9000000953674316
Screen End Depth: 4.570000171661377
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.0

Water Details

Water ID: 1004043126
Layer: 1
Kind Code:
Kind:
Water Found Depth: 1.5499999523162842
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004043125
Diameter: 22.0
Depth From: 0.0
Depth To: 5.599999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

16	1 of 1	SSE/64.2	70.9 / 0.00	lot 9 ON	WWIS

Well ID: 1500404
Construction Date:
Use 1st: Not Used
Flowing (Y/N):
Flow Rate:
Data Entry Status:

Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	03/14/1949
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	2311
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	009
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	JG
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY (GLOUCESTER)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1500404.pdf

Additional Detail(s) (Map)

Well Completed Date:	03/05/1949
Year Completed:	1949
Depth (m):	18.288
Latitude:	45.4258024192725
Longitude:	-75.639009705467
X:	-75.63900954296444
Y:	45.42580241213142
Path:	150\1500404.pdf

Bore Hole Information

Bore Hole ID:	10022449	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450010.70
Code OB Desc:		**North83:**	5030452.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	9
Date Completed:	03/05/1949	**UTMRC Desc:**	unknown UTM
Remarks:		**Location Method:**	p9
Location Method Desc:	Original Pre1985 UTM Rel Code 9: unknown UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930989182
Layer:	2
Color:	
General Color:	
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	

Formation Top Depth:	20.0
Formation End Depth:	60.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930989181
Layer:	1
Color:	
General Color:	
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	09
Material 2 Desc:	MEDIUM SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961500404
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10571019
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930037832
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	60.0
Casing Diameter:	4.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930037831
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	23.0
Casing Diameter:	4.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991500404
Pump Set At:	
Static Level:	46.0
Final Level After Pumping:	86.0
Recommended Pump Depth:	
Pumping Rate:	0.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933452921
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	56.0
Water Found Depth UOM:	ft

---

17 ***1 of 1*** ***SSE/71.0*** ***70.9 / 0.00*** ***ON*** ***WWIS***

Well ID:	1508882	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	11/28/1952
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	1107
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1508882.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/05/1952
Year Completed:	1952
Depth (m):	45.4152
Latitude:	45.4257588457244
Longitude:	-75.6387535552967
X:	-75.6387533929414
Y:	45.42575883930307

Path: 150\1508882.pdf

Bore Hole Information

Bore Hole ID:	10030916	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450030.70
Code OB Desc:		**North83:**	5030447.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	11/05/1952	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931010857
Layer: 1
Color:
General Color:
Material 1: 23
Material 1 Desc: PREVIOUSLY DUG
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 21.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931010858
Layer: 2
Color: 2
General Color: GREY
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 21.0
Formation End Depth: 149.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961508882
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10579486
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930054462
Layer: 1
Material:
Open Hole or Material:
Depth From:
Depth To: 14.0
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930054464
Layer: 3
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 149.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930054463
Layer: 2
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 21.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991508882
Pump Set At:
Static Level: 11.0
Final Level After Pumping: 18.0
Recommended Pump Depth:
Pumping Rate: 8.0
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0

Flowing: No

Water Details

Water ID: 933463580
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 149.0
Water Found Depth UOM: ft

---

18 ***1 of 1*** ***NNE/76.1*** ***71.9 / 1.00*** ***1055 ST. LAURENT BLVD Ottawa ON*** ***WWIS***

Well ID: 7191559
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z156893
Tag: A112765
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/14/2012
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191559.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/25/2012
Year Completed: 2012
Depth (m): 4.88
Latitude: 45.4277647343522
Longitude: -75.6390024453486
X: -75.63900228261635
Y: 45.42776472707144
Path: 719\7191559.pdf

Bore Hole Information

Bore Hole ID: 1004204434
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/25/2012
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:

Elevation:
Elevrc:
Zone: 18
East83: 450013.00
North83: 5030670.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1004526984
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.0
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004526985
Layer:	2
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	2.440000057220459
Formation End Depth:	3.6600000858306885
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004526986
Layer:	3
Color:	8
General Color:	BLACK
Material 1:	06
Material 1 Desc:	SILT
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	3.6600000858306885
Formation End Depth:	4.880000114440918
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004526994
Layer:	1
Plug From:	0.0

Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526995
Layer: 2
Plug From: 0.3100000023841858
Plug To: 1.5
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526996
Layer: 3
Plug From: 1.5
Plug To: 4.880000114440918
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004526993
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004526983
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004526989
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.8300000429153442
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004526990
Layer: 1
Slot: 10
Screen Top Depth: 1.8300000429153442
Screen End Depth: 4.880000114440918
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water Details

Water ID: 1004526988
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004526987
Diameter: 8.25
Depth From: 0.0
Depth To: 4.880000114440918
Hole Depth UOM: m
Hole Diameter UOM: cm

19	*1 of 3*	*NNW/83.7*	*70.9 / 0.00*	***Waste Services (CA) Inc.; Waste Services (CA) Inc.*** ***1020 St. Laurant St.*** ***Ottawa ON***	*SPL*

Ref No: 2433-824HX7
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/27/2010
Dt Document Closed: 2/1/2010
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 1020 St. Laurant St.<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Waste Services (CA) Inc.; Waste Services (CA) Inc.
Client Type:
Source Type:
Incident Cause: Other Discharges
Incident Preceding Spill:
Incident Reason: Fire/Explosion - Resulting from fires/explosions (Not occurrences which cause a fire or explosion)
Incident Summary: WSI: Garbage Truck Fire, Fire water to CB
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 L
Contaminant Qty 1: 0
Contaminant Unit: L
Contaminant Code: 46
Contaminant Name: FIRE WATER (PARTICULATE CONTAMINANT)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Motor Vehicle
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

19 | ***2 of 3*** | ***NNW/83.7*** | ***70.9 / 0.00*** | ***Waste Services (CA) Inc.***
1020 St. Laurent St, Ottawa
Ottawa ON | ***SPL***

Ref No: 0122-824LEY
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/27/2010
Dt Document Closed: 2/1/2010
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Waste Services vehicle fire<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Waste Services (CA) Inc.
Client Type:
Source Type:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Incident Reason: Spill
Incident Summary: Duplicate report...See master 2433-824HX7
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 46
Contaminant Name: FIRE WATER (PARTICULATE CONTAMINANT)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Waste Disposal Site
SAC Action Class: Highway Spills (usually highway accidents)
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	3 of 3	NNW/83.7	70.9 / 0.00	1020 St Laurent Blvd Ottawa ON K1K 4S2	EHS

Order No:	20180622039	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	28-JUN-18	**Search Radius (km):**	.25
Date Received:	22-JUN-18	**X:**	-75.639825
Previous Site Name:		**Y:**	45.427692
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	1 of 1	SE/91.6	70.9 / 0.00	O.C. TRANSPO CORNER ST. LAURENT & CYRVILLE ROAD MOTOR VEHICLE (OPERATING FLUID) OTTAWA CITY ON	SPL

Ref No:	117690	**Municipality No:**	20101
Year:		**Nature of Damage:**	
Incident Dt:	8/25/1995	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/25/1995	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	WORKS
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	OTTAWA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	O.C. TRANSPO - 10 L ENGINE ANTIFREEZE TO C/B.		
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			

Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

21 | **1 of 1** | **N/93.1** | **71.9 / 1.00** | **1055 ST. LAURENT BLVD**
Ottawa ON | **WWIS**

Well ID:	7205218	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	07/23/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z168882	**Contractor:**	7241
Tag:	A149970	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7205218.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/04/2013
Year Completed:	2013
Depth (m):	3.96
Latitude:	45.4279178175796
Longitude:	-75.6389913892558
X:	-75.63899122704085
Y:	45.42791781141721
Path:	720\7205218.pdf

Bore Hole Information

Bore Hole ID:	1004448552	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450014.00
Code OB Desc:		**North83:**	5030687.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/04/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004875885
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004875884
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004875886
Layer:	3
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	1.5
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004875895
Layer:	2
Plug From:	0.3100000023841858
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Annular Space/Abandonment

Sealing Record

Plug ID:	1004875894
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004875896
Layer:	3
Plug From:	0.9100000262260437
Plug To:	3.9600000381469727
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004875893
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	D.P

Pipe Information

Pipe ID:	1004875883
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004875889
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004875890
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004875888
Layer:	
Kind Code:	

Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004875887
Diameter: 8.25
Depth From: 0.0
Depth To: 3.9600000381469727
Hole Depth UOM: m
Hole Diameter UOM: cm

---

22 **1 of 1** **SSE/94.3** **70.9 / 0.00** **ON** **WWIS**

Well ID: 7306228
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C34332
Tag: A132292
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: OTTAWA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 02/15/2018
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6964
Form Version: 8
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1006990219
Depth M:
Year Completed: 2017
Well Completed Dt: 12/10/2017
Audit No: C34332
Path:

Tag No: A132292
Contractor: 6964
Latitude: 45.4255424216262
Longitude: -75.6388239768168
Y: 45.42554241533624
X: -75.63882381456645

Bore Hole Information

Bore Hole ID: 1006990219
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/10/2017
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:

Elevation:
Elevrc:
Zone: 18
East83: 450025.00
North83: 5030423.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Source Revision Comment:					
Supplier Comment:					
23	1 of 3	SSE/100.9	70.9 / 0.00	CONSEIL DES ECOLES CATHOLIQUES DE LANGUE EDUCATION SANS FRONTIERE 1116 ST. LAURENT BOULEVARD OTTAWA ON K1K 3B6	GEN

Generator Info

Generator No:	ON1285763	**Choice of Contact:**	
Approval Years:	95,96,97,98	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	8511
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELEMT./SECON. EDUC.		

Waste Detail(s)

Waste Class:	243
Waste Class Name:	PCB'S

23	2 of 3	SSE/100.9	70.9 / 0.00	CONSEIL DES ECOLES CATHOLIQUES DE LANGUE EDUCATION SANS FRONTIERE 1116 BOUL. ST-LAURENT OTTAWA ON K1K 3B6	GEN

Generator Info

Generator No:	ON1285763	**Choice of Contact:**	
Approval Years:	99,00,01	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	8511
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELEMT./SECON. EDUC.		

Waste Detail(s)

Waste Class:	243
Waste Class Name:	PCB'S

23	3 of 3	SSE/100.9	70.9 / 0.00	MIERINS DEALERSHIP HOLDINGS INC. 1116 St. Laurent Boulevard Ottawa ON K1K 3B6	EASR

Approval No:	R-009-3111707108	**MOE District:**	Ottawa
Status:	REGISTERED	**Municipality:**	Ottawa
Date:	2019-11-07	**Latitude:**	45.425
Record Type:	EASR	**Longitude:**	-75.63777778
Link Source:	MOFA	**Geometry X:**	
Project Type:	Water Taking - Construction Dewatering	**Geometry Y:**	
Full Address:			

Approval Type: EASR-Water Taking - Construction Dewatering
SWP Area Name: Rideau Valley
PDF NAICS Code:
PDF URL:
PDF Site Location:

---

24 | **1 of 1** | **SE/106.5** | **70.9 / 0.00** | **1076 ST. LAURENT BLVD OTTAWA ON** | **WWIS**

Well ID: 1535863
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z19254
Tag: A008880
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: OTTAWA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 10/17/2005
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1844
Form Version: 3
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/153\1535863.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/12/2005
Year Completed: 2005
Depth (m): 4.88
Latitude: 45.4255279929008
Longitude: -75.6381846703322
X: -75.63818450804655
Y: 45.42552798638476
Path: 153\1535863.pdf

Bore Hole Information

Bore Hole ID: 11316402
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/12/2005
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 450075.00
North83: 5030421.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID:	932997356
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.05000000074505806
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932997359
Layer:	4
Color:	4
General Color:	GREEN
Material 1:	
Material 1 Desc:	
Material 2:	84
Material 2 Desc:	SILTY
Material 3:	05
Material 3 Desc:	CLAY
Formation Top Depth:	2.2100000381469727
Formation End Depth:	4.880000114440918
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932997357
Layer:	2
Color:	2
General Color:	GREY
Material 1:	01
Material 1 Desc:	FILL
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	28
Material 3 Desc:	SAND
Formation Top Depth:	0.05000000074505806
Formation End Depth:	0.6600000262260437
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932997358
Layer:	3
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	84
Material 2 Desc:	SILTY

Material 3: 29
Material 3 Desc: FINE GRAVEL
Formation Top Depth: 0.6600000262260437
Formation End Depth: 2.2100000381469727
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933278681
Layer: 1
Plug From: 0.0
Plug To: 1.2100000381469727
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 961535863
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11331257
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930855846
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 4.5
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933414976
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 4.880000114440918
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.5

Water Details

Water ID: 934065952
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 3.0

Water Found Depth UOM: m

Hole Diameter

Hole ID: 11533982
Diameter: 10.0
Depth From: 0.0
Depth To: 4.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

25 | **1 of 1** | **N/107.3** | **71.9 / 1.00** | **1055 ST LAURENT BLVD Ottawa ON** | **WWIS**

Well ID: 7191556
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z156891
Tag: A112761
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/14/2012
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191556.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/24/2012
Year Completed: 2012
Depth (m): 7.62
Latitude: 45.4280521127329
Longitude: -75.6391207390076
X: -75.63912057720094
Y: 45.42805210631258
Path: 719\7191556.pdf

Bore Hole Information

Bore Hole ID: 1004204425
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/24/2012
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:

Elevation:
Elevrc:
Zone: 18
East83: 450004.00
North83: 5030702.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004526824
Layer: 2
Color: 8
General Color: BLACK
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.6100000143051147
Formation End Depth: 3.9600000381469727
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004526825
Layer: 3
Color: 2
General Color: GREY
Material 1: 17
Material 1 Desc: SHALE
Material 2: 71
Material 2 Desc: FRACTURED
Material 3:
Material 3 Desc:
Formation Top Depth: 3.9600000381469727
Formation End Depth: 7.619999885559082
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004526823
Layer: 1
Color: 6
General Color: BROWN
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 28
Material 2 Desc: SAND
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526836
Layer: 3
Plug From: 4.269999980926514

Plug To:	7.619999885559082
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004526835
Layer:	2
Plug From:	0.3100000023841858
Plug To:	4.269999980926514
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004526834
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004526833
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1004526822
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004526829
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	4.570000171661377
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004526830
Layer:	1
Slot:	10
Screen Top Depth:	4.570000171661377
Screen End Depth:	7.619999885559082
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004526828
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004526827
Diameter:	8.0
Depth From:	4.269999980926514
Depth To:	7.619999885559082
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1004526826
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	4.269999980926514
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

26 ***1 of 1*** ***WSW/107.5*** ***70.9 / 0.00*** ***lot 8 ON*** ***WWIS***

Well ID:	1500398	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	02/25/1949
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	1107
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	008
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	JG
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY (GLOUCESTER)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1500398.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/30/1948
Year Completed:	1948
Depth (m):	53.0352
Latitude:	45.4258838346567
Longitude:	-75.6405445786775
X:	-75.64054441651925
Y:	45.42588382805919

Path: 150\1500398.pdf

Bore Hole Information

Bore Hole ID:	10022443	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	449890.70
Code OB Desc:		***North83:***	5030462.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	07/30/1948	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	p9

Location Method Desc: Original Pre1985 UTM Rel Code 9: unknown UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 930989166
Layer: 2
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 3.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930989165
Layer: 1
Color:
General Color:
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 3.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930989167
Layer: 3
Color: 8
General Color: BLACK

Material 1:	08
Material 1 Desc:	FINE SAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	18.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930989168
Layer:	4
Color:	2
General Color:	GREY
Material 1:	26
Material 1 Desc:	ROCK
Material 2:	19
Material 2 Desc:	SLATE
Material 3:	
Material 3 Desc:	
Formation Top Depth:	25.0
Formation End Depth:	174.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961500398
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10571013
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930037819
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	25.0
Casing Diameter:	4.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930037820
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	174.0

Casing Diameter:	4.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	BAILER
Pump Test ID:	991500398
Pump Set At:	
Static Level:	15.0
Final Level After Pumping:	174.0
Recommended Pump Depth:	
Pumping Rate:	5.0
Flowing Rate:	
Recommended Pump Rate:	0.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	2
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933452915
Layer:	1
Kind Code:	3
Kind:	SULPHUR
Water Found Depth:	174.0
Water Found Depth UOM:	ft

---

27 | **1 of 1** | **N/108.4** | **71.9 / 1.00** | **OC Transpo<UNOFFICIAL>**
St Laurent Blvd northbound 100 m south of Donald St
Ottawa ON | **SPL**

Ref No:	5744-7X5TWB	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/24/2009	**Impact to Health:**	
Dt Document Closed:	11/10/2009	**Agency Involved:**	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Roadway and CB<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:			
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	OC Transpo<UNOFFICIAL>		
Client Type:			

Source Type:	
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	
Incident Summary:	OC Transpo: leak of coolant to CB
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Surface Water Pollution
Contaminant Qty:	40 L
Contaminant Qty 1:	40
Contaminant Unit:	L
Contaminant Code:	27
Contaminant Name:	COOLANT N.O.S.
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Motor Vehicle
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

28 **1 of 1** **NNE/112.5** **71.9 / 1.00** **1055 ST. LAURENT BLVD**
Ottawa ON **WWIS**

Well ID:	7205219	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	07/23/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z168881	**Contractor:**	7241
Tag:	A149969	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7205219.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/02/2013
Year Completed:	2013
Depth (m):	4.27
Latitude:	45.4280014687029
Longitude:	-75.6385193460999
X:	-75.63851918406812
Y:	45.428001462278544
Path:	720\7205219.pdf

Bore Hole Information

Bore Hole ID:	1004448555	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	450051.00
Code OB Desc:		***North83:***	5030696.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	07/02/2013	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004875900
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	34
Material 1 Desc:	TILL
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	3.0999999046325684
Formation End Depth:	4.269999980926514
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004875898
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	0.0
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004875899
Layer:	2
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY

Material 2: 06
Material 2 Desc: SILT
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 1.2200000286102295
Formation End Depth: 3.0999999046325684
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004875908
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004875910
Layer: 3
Plug From: 0.9100000262260437
Plug To: 4.269999980926514
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004875909
Layer: 2
Plug From: 0.3100000023841858
Plug To: 0.9100000262260437
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004875907
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: D.P

Pipe Information

Pipe ID: 1004875897
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004875903
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.2200000286102295
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1004875904
Layer:	1
Slot:	10
Screen Top Depth:	1.2200000286102295
Screen End Depth:	4.269999980926514
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004875902
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004875901
Diameter:	8.25
Depth From:	0.0
Depth To:	4.269999980926514
Hole Depth UOM:	m
Hole Diameter UOM:	cm

29 ***1 of 1*** ***S/113.8*** ***70.9 / 0.00*** ***ON*** ***BORE***

Borehole ID:	613480	***Inclin FLG:***	No
OGF ID:	215514762	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:		***Primary Name:***	
Completion Date:		***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:		***Township:***	
Sec. Water Use:		***Latitude DD:***	45.425354
Total Depth m:	-999	***Longitude DD:***	-75.639005
Depth Ref:	Ground Surface	***UTM Zone:***	18
Depth Elev:		***Easting:***	450011
Drill Method:		***Northing:***	5030402
Orig Ground Elev m:	70.4	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	71.1		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218395320	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	5.5	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	

Material 2: ***Geologic Group:***
Material 3: ***Geologic Period:***
Material 4: ***Depositional Gen:***
Gsc Material Description:
Stratum Description: SAND.

Geology Stratum ID: 218395321 ***Mat Consistency:*** Compact
Top Depth: 5.5 ***Material Moisture:***
Bottom Depth: ***Material Texture:***
Material Color: Grey ***Non Geo Mat Type:***
Material 1: Bedrock ***Geologic Formation:***
Material 2: Shale ***Geologic Group:***
Material 3: ***Geologic Period:***
Material 4: ***Depositional Gen:***
Gsc Material Description:
Stratum Description: BEDROCK. COMPACT. BEDROCK. GREY,STIFF. BEDROCK. GREY,FOSSILIFEROUS. GREY,SOFT. SI **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type: Data Survey ***Source Appl:*** Spatial/Tabular
Source Orig: Geological Survey of Canada ***Source Iden:*** 1
Source Date: 1956-1972 ***Scale or Res:*** Varies
Confidence: H ***Horizontal:*** NAD27
Observatio: ***Verticalda:*** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 059880 NTS_Sheet: 31G05G
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier: 1 ***Horizontal Datum:*** NAD27
Source Type: Data Survey ***Vertical Datum:*** Mean Average Sea Level
Source Date: 1956-1972 ***Projection Name:*** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

30	*1 of 1*	*ENE/115.8*	*71.9 / 1.00*	***1055 & 1091 St.Laurent Boulevard and 1235 and 1236 Donald Street Ottawa ON***	*EHS*

Order No: 20080129001 ***Nearest Intersection:***
Status: C ***Municipality:***
Report Type: Custom Report ***Client Prov/State:*** ON
Report Date: 2/6/2008 ***Search Radius (km):*** 0.25
Date Received: 1/29/2008 ***X:*** -75.637784
Previous Site Name: ***Y:*** 45.427511
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps And /or Site Plans

31	*1 of 12*	*SSE/119.3*	*70.9 / 0.00*	***FIRESTONE FIRESTONE 1110 ST. LAURENT BLVD. VEHICLE SERVICE STATION OTTAWA CITY ON K1K 3B6***	*SPL*

Ref No: 59460 ***Municipality No:*** 20101
Year: ***Nature of Damage:***
Incident Dt: 11/5/1991 ***Discharger Report:***
Dt MOE Arvl on Scn: ***Material Group:***
MOE Reported Dt: 11/5/1991 ***Impact to Health:***
Dt Document Closed: ***Agency Involved:*** MOE, MCCR.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: UNDERGROUND TANK LEAK
Incident Preceding Spill:
Incident Reason: UNKNOWN
Incident Summary: FIRESTONE - WASTE OIL INTO SOIL FROM LEAKING UNDERGROUND STORAGE TANK.
Environment Impact: CONFIRMED
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	2 of 12	SSE/119.3	70.9 / 0.00	1110 St. Laurent Boulevard Ottawa ON K1K 3B6	CA

Certificate #: 6557-4SUR6N
Application Year: 01
Issue Date: 2/5/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Ogilvie Realty Ltd.
Client Address: 1475 Carling Avenue
Client City: Ottawa
Client Postal Code: K1Z 7L9
Project Description: This is an application for Municipal and Private Sewage Works Certificate of Approval to install new flow control roof drains on an addition to an existing garage.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	3 of 12	SSE/119.3	70.9 / 0.00	Ogilvie Realty Ltd. 1110 St. Laurent Boulevard Ottawa ON K1K 3B6	CA

Certificate #: 0991-6RMGRA
Application Year: 2006
Issue Date: 8/9/2006
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	4 of 12	SSE/119.3	70.9 / 0.00	1110 Ste Laurent Blvd Ottawa ON	EHS

Order No: 20101214018
Status: C
Report Type: Standard Report
Report Date: 12/17/2010
Date Received: 12/14/2010 11:13:21 AM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: ; City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.638495
Y: 45.425401

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	5 of 12	SSE/119.3	70.9 / 0.00	Ogilvie Realty Ltd. 1110 St. Laurent Blvd Ottawa ON K1Z 7L9	ECA

Approval No: 1990-8PHQGU
Approval Date: 2011-12-19
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Ogilvie Realty Ltd.
Address: 1110 St. Laurent Blvd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6810-8KMJHU-14.pdf
PDF Site Location:

MOE District: Ottawa
City:
Longitude: -75.64338
Latitude: 45.424328
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	6 of 12	SSE/119.3	70.9 / 0.00	Ogilvie Realty Ltd. 1110 St. Laurent Blvd Ottawa ON K1Z 7L9	ECA

Approval No: 2128-8RHRNJ
Approval Date: 2012-04-17
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS

MOE District: Ottawa
City:
Longitude: -75.64338
Latitude: 45.424328
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Business Name: Ogilvie Realty Ltd.
Address: 1110 St. Laurent Blvd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0239-8QLJUR-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	7 of 12	SSE/119.3	70.9 / 0.00	Willy's Roll-off<UNOFFICIAL> 1110 St-Laurent Blvd Ottawa ON K1K 3B6	SPL

Ref No: 6033-8V2MUX
Year:
Incident Dt: 07-JUN-12
Dt MOE Arvl on Scn:
MOE Reported Dt: 07-JUN-12
Dt Document Closed:
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 1110 Saint-Laurent Blvd.<UNOFFICIAL>
Site Address: 1110 St-Laurent Blvd
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Willy's Roll-off<UNOFFICIAL>
Client Type:
Source Type:
Incident Cause: Valve / Fitting Leak Or Failure
Incident Preceding Spill:
Incident Reason:
Incident Summary: Willy's Roll-Offs: <100L of Hydraulic Oil to ground
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code: 15
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Motor Vehicle
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	8 of 12	SSE/119.3	70.9 / 0.00	Ogilvie Realty Ltd. 1110 St. Laurent Boulevard Ottawa ON K1Z 7L9	ECA

Approval No:	0991-6RMGRA	**MOE District:**	Ottawa
Approval Date:	2006-08-09	**City:**	
Status:	Approved	**Longitude:**	-75.64338
Record Type:	ECA	**Latitude:**	45.424328
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Ogilvie Realty Ltd.		
Address:	1110 St. Laurent Boulevard		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/9623-6PLSE7-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	9 of 12	SSE/119.3	70.9 / 0.00	Ogilvie Realty Ltd. 1110 St. Laurent Boulevard Ottawa ON K1Z 7L9	ECA

Approval No:	6557-4SUR6N	**MOE District:**	Ottawa
Approval Date:	2001-02-05	**City:**	
Status:	Approved	**Longitude:**	-75.64338
Record Type:	ECA	**Latitude:**	45.424328
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Ogilvie Realty Ltd.		
Address:	1110 St. Laurent Boulevard		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7143-4QWRQW-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	10 of 12	SSE/119.3	70.9 / 0.00	1110 St Laurent Blvd Ottawa ON K1K3B6	EHS

Order No:	20170908030	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	14-SEP-17	**Search Radius (km):**	.25
Date Received:	08-SEP-17	**X:**	-75.638589
Previous Site Name:		**Y:**	45.425481
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	11 of 12	SSE/119.3	70.9 / 0.00	Ogilvie Realty Limited 1110 St. Laurent Blvd Ottawa ON K1K 3B6	ECA

Approval No:	2990-BWCKZ9	**MOE District:**	Ottawa
Approval Date:	2021-01-19	**City:**	
Status:	Approved	**Longitude:**	-75.64338
Record Type:	ECA	**Latitude:**	45.424328
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Ogilvie Realty Limited		

Address: 1110 St. Laurent Blvd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7213-BJZJZM-14.pdf
PDF Site Location:

---

31 | **12 of 12** | **SSE/119.3** | **70.9 / 0.00** | **Tomlinson Environmental Services Ltd**
1110 Saint Laurent Boulevard
Ottawa ON | **SPL**

Ref No: 4208-BPAS22
Year:
Incident Dt: 2020/05/04
Dt MOE Arvl on Scn:
MOE Reported Dt: 2020/05/04
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office: Ottawa
Nearest Watercourse:
Site Name: Spill Site<UNOFFICIAL>
Site Address: 1110 Saint Laurent Boulevard
Site Region: Eastern
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 5030403.73
Easting: 450078.64
Entity Operating Name:
Client Name: Tomlinson Environmental Services Ltd
Client Type: Corporation
Source Type: Truck - Only Saddle Tanks
Incident Cause:
Incident Preceding Spill: Collision/Accident
Incident Reason: Operator/Human Error
Incident Summary: Tomlinson Environmental: 50 L diesel to asphalt, cntd.
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 50 L
Contaminant Qty 1: 50
Contaminant Unit: L
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1202
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

---

32 | **1 of 1** | **NNE/122.6** | **71.9 / 1.00** | **1055 ST. LAURENT BLVD**
Ottawa ON | **WWIS**

Well ID:	7205220	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	07/23/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z168880	**Contractor:**	7241
Tag:	A149968	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7205220.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/04/2013
Year Completed:	2013
Depth (m):	3.06
Latitude:	45.428047329545
Longitude:	-75.6383664618631
X:	-75.63836629983673
Y:	45.42804732312199
Path:	720\7205220.pdf

Bore Hole Information

Bore Hole ID:	1004448558	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450063.00
Code OB Desc:		**North83:**	5030701.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/04/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004875956
Layer:	3
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY

Material 2: 06
Material 2 Desc: SILT
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 1.5
Formation End Depth: 3.059999942779541
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004875954
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004875955
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 0.3100000023841858
Formation End Depth: 1.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004875964
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004875963
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: D.P

Pipe Information

Pipe ID: 1004875953

Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004875959
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004875960
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.059999942779541
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004875958
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004875957
Diameter:	8.25
Depth From:	0.0
Depth To:	3.059999942779541
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

33 | ***1 of 1*** | ***E/123.5*** | ***71.9 / 1.00*** | ***1055 ST. LAURENT BLVD Ottawa ON*** | ***WWIS***

Well ID:	7205223	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	07/23/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z168877	**Contractor:**	7241
Tag:	A150122	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	

Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7205223.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/02/2013
Year Completed:	2013
Depth (m):	4.57
Latitude:	45.4269009515748
Longitude:	-75.6373308850761
X:	-75.63733072331618
Y:	45.42690094511582
Path:	720\7205223.pdf

Bore Hole Information

Bore Hole ID:	1004448567	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450143.00
Code OB Desc:		**North83:**	5030573.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/02/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004876081
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876083
Layer:	4

Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	2.440000057220459
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876080
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876082
Layer:	3
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	1.2200000286102295
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876092
Layer:	2
Plug From:	0.3100000023841858
Plug To:	1.2200000286102295
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876093
Layer:	3
Plug From:	1.2200000286102295
Plug To:	4.570000171661377

Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004876091
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004876090
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: D.P

Pipe Information

Pipe ID: 1004876079
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004876086
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004876087
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 4.570000171661377
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004876085
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004876084
Diameter: 8.25
Depth From: 0.0
Depth To: 4.570000171661377
Hole Depth UOM: m
Hole Diameter UOM: cm

---

34 | **1 of 1** | **ENE/126.1** | **71.9 / 1.00** | **1091 St. Laurent Blvd**
Ottawa ON K1K 3B1 | **EHS**

Order No: 22091900088
Status: C
Report Type: Custom Report
Report Date: 28-SEP-22
Date Received: 19-SEP-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.63740607
Y: 45.42709599

---

35 | **1 of 1** | **WNW/127.1** | **70.9 / 0.00** | **St Laurent Enbridge**
Ottawa ON | **EHS**

Order No: 21111000142
Status: C
Report Type: Custom Report
Report Date: 15-NOV-21
Date Received: 10-NOV-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .1
X: -75.64126019
Y: 45.42730237

---

36 | **1 of 1** | **NNW/139.0** | **71.9 / 1.00** | **n/a**
Ottawa ON | **EHS**

Order No: 21121500314
Status: C
Report Type: Custom Report
Report Date: 06-MAY-22
Date Received: 15-DEC-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.63962759
Y: 45.42829613

---

37 | **1 of 1** | **NNE/139.2** | **71.9 / 1.00** | **1055 ST. LAURENT BLVD**
Ottawa ON | **WWIS**

Well ID: 7191560
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z157210
Tag: A112763
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/14/2012
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:

Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191560.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/25/2012
Year Completed:	2012
Depth (m):	3.96
Latitude:	45.4282624887002
Longitude:	-75.6385222891366
X:	-75.63852212692586
Y:	45.42826248229056
Path:	719\7191560.pdf

Bore Hole Information

Bore Hole ID:	1004204437	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	450051.00
Code OB Desc:		***North83:***	5030725.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/25/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004527040
Layer:	3
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	2.440000057220459
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004527038
Layer:	1

Color:	6
General Color:	BROWN
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004527039
Layer:	2
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	1.2200000286102295
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004527050
Layer:	3
Plug From:	0.9100000262260437
Plug To:	3.9600000381469727
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004527049
Layer:	2
Plug From:	0.3100000023841858
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004527048
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004527047
Method Construction Code:	D
Method Construction:	Direct Push

Other Method Construction:

Pipe Information

Pipe ID:	1004527037
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004527043
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004527044
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004527042
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004527041
Diameter:	8.25
Depth From:	0.0
Depth To:	3.9600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	1 of 17	N/139.6	71.9 / 1.00	***SUNOCO*** ***1007 ST. LAURENT STREET SERVICE STATION*** ***OTTAWA CITY ON K1K 3B1***	SPL

Ref No:	49890	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	4/30/1991	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	4/30/1991	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	MCCR

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site No:	
MOE Response:	
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	OTTAWA CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	UNDERGROUND TANK LEAK
Incident Preceding Spill:	
Incident Reason:	CORROSION
Incident Summary:	SUNOCO: 1 500 L FUEL TO GROUND FROM LEAKING TANK
Environment Impact:	CONFIRMED
Health Env Consequence:	
Nature of Impact:	Soil contamination
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	2 of 17	N/139.6	71.9 / 1.00	M ELLIS 1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	PRT

Location ID:	11110
Type:	retail
Expiry Date:	1994-11-30
Capacity (L):	26400
Licence #:	0055598001

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	3 of 17	N/139.6	71.9 / 1.00	MCDONALD'S REST. OF CANADA LTD. 1007 ST. LAURENT BOULEVARD OTTAWA CITY ON K1K 3B1	CA

Certificate #:	8-4205-96-
Application Year:	96
Issue Date:	10/24/1996

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: COMMERCIAL KITCHEN EXHAUST HOOD
Contaminants:
Emission Control:

38	4 of 17	N/139.6	71.9 / 1.00	ST LAURENT FUN FOOD SUNOCO 1007 ST LAURENT BLVD OTTAWA ON K1K3B1	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 6137413539
List Name:
Description:

38	5 of 17	N/139.6	71.9 / 1.00	ST LAURENT SUNOCO 1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

38	6 of 17	N/139.6	71.9 / 1.00	6151892 CANADA INC 1007 ST LAURENT BLVD OTTAWA ON K1K 3B1	FSTH

License Issue Date: 9/11/2006
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Not-Active
Year of Installation: 1980
Corrosion Protection:
Capacity: 36000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Not-Active
Year of Installation: 1980
Corrosion Protection:
Capacity: 24000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Not-Active
Year of Installation: 1980
Corrosion Protection:
Capacity: 36000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Not-Active
Year of Installation: 1980
Corrosion Protection:
Capacity: 24000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

---

38 | **7 of 17** | **N/139.6** | **71.9 / 1.00** | **6434118 CANADA INC O/A SUNOCO**
1007 ST LAURENT BLVD
OTTAWA ON K1K 3B1 | **FSTH**

License Issue Date: 11/5/2007 3:23:00 PM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

---

38 | **8 of 17** | **N/139.6** | **71.9 / 1.00** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
1007 ST. LAURENT BLVD
OTTAWA ON | **FST**

Inventory No: 11498165
Inventory Status: active
Installation Year: 1997
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description:
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

38 | **9 of 17** | **N/139.6** | **71.9 / 1.00** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
1007 ST. LAURENT BLVD
OTTAWA ON | **FST**

Inventory No: 11498171
Inventory Status: active
Installation Year: 1997
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Model:					
Description:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	10 of 17	N/139.6	71.9 / 1.00	SUNCOR ENERGY PRODUCTS PARTNERSHIP 1007 ST. LAURENT BLVD OTTAWA ON	FST

Inventory No: 11498184
Inventory Status: active
Installation Year: 1997
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description:
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	11 of 17	N/139.6	71.9 / 1.00	ST LAURENT SUNOCO 1007 ST LAURENT BLVD OTTAWA ON K1K3B1	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 6137413539
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	12 of 17	N/139.6	71.9 / 1.00	PETRO CANADA 1007 ST LAURENT BLVD OTTAWA ON K1K3B1	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 6137413539
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	13 of 17	N/139.6	71.9 / 1.00	6205429 CANADA INC 1007 ST. LAURENT BLVD OTTAWA ON	EXP

Inventory No: 11335800
Inventory Status: EXPIRED
Installation Year: 1980
Capacity: 24000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Diesel
Tank Material: Fiberglass (FRP)
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	14 of 17	N/139.6	71.9 / 1.00	6205429 CANADA INC 1007 ST. LAURENT BLVD OTTAWA ON	EXP

Inventory No: 11335778
Tank Material: Fiberglass (FRP)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory Status:	EXPIRED	**Corrosion Protect:**	Coating
Installation Year:	1980	**Overfill Protection:**	
Capacity:	36000	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:			
Previous Fuel Type:	Gasoline		

---

38 | ***15 of 17*** | ***N/139.6*** | ***71.9 / 1.00*** | ***6205429 CANADA INC*** ***1007 ST. LAURENT BLVD*** ***OTTAWA ON*** | ***EXP***

Inventory No:	11335735	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Coating
Installation Year:	1980	**Overfill Protection:**	
Capacity:	36000	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:			
Previous Fuel Type:	Gasoline		

---

38 | ***16 of 17*** | ***N/139.6*** | ***71.9 / 1.00*** | ***6205429 CANADA INC*** ***1007 ST. LAURENT BLVD*** ***OTTAWA ON*** | ***EXP***

Inventory No:	11335758	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Coating
Installation Year:	1980	**Overfill Protection:**	
Capacity:	24000	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:			
Previous Fuel Type:	Gasoline		

---

38 | ***17 of 17*** | ***N/139.6*** | ***71.9 / 1.00*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** ***1007 ST. LAURENT BLVD*** ***OTTAWA ON*** | ***FST***

Inventory No:	9816494	**Tank Material:**	
Inventory Status:	Active	**Corrosion Protect:**	
Installation Year:		**Overfill Protection:**	
Capacity:	150000	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			
Description:			

---

39 | ***1 of 1*** | ***NNE/145.4*** | ***71.9 / 1.00*** | ***1055 ST. LAURENT BLVD*** ***Ottawa ON*** | ***WWIS***

Well ID:	7191557	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	

Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/14/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z156892	**Contractor:**	7241
Tag:	A112762	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: GLOUCESTER TOWNSHIP
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191557.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/24/2012
Year Completed:	2012
Depth (m):	3.96
Latitude:	45.4283517094598
Longitude:	-75.6386639137559
X:	-75.63866375166575
Y:	45.428351701956736
Path:	719\7191557.pdf

Bore Hole Information

Bore Hole ID:	1004204428	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450040.00
Code OB Desc:		**North83:**	5030735.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/24/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1004526862
Layer:	2
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	91

Material 3 Desc: WATER-BEARING
Formation Top Depth: 2.440000057220459
Formation End Depth: 3.9600000381469727
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004526861
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 68
Material 2 Desc: DRY
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 2.440000057220459
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526872
Layer: 3
Plug From: 0.9100000262260437
Plug To: 3.9600000381469727
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526871
Layer: 2
Plug From: 0.3100000023841858
Plug To: 0.9100000262260437
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004526870
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004526869
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004526860
Casing No: 0

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1004526865
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004526866
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004526864
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004526863
Diameter:	8.25
Depth From:	0.0
Depth To:	3.9600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

40 | **1 of 1** | **NNE/146.5** | **71.9 / 1.00** | **1055 ST. LAURENT BLVD**
Ottawa ON | **WWIS**

Well ID:	7205221	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	07/23/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z168879	**Contractor:**	7241
Tag:	A149967	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	

Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7205221.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/04/2013
Year Completed:	2013
Depth (m):	3.66
Latitude:	45.42832563644
Longitude:	-75.6384974341297
X:	-75.63849727234148
Y:	45.42832562891819
Path:	720\7205221.pdf

Bore Hole Information

Bore Hole ID:	1004448561	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	450053.00
Code OB Desc:		***North83:***	5030732.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	07/04/2013	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004876009
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876010
Layer:	3
Color:	2

General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	1.5
Formation End Depth:	3.6600000858306885
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876008
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876020
Layer:	3
Plug From:	0.9100000262260437
Plug To:	3.6600000858306885
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876019
Layer:	2
Plug From:	0.3100000023841858
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876018
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004876017
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	D.P

Pipe Information

Pipe ID:	1004876007
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004876013
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004876014
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.5999999046325684
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004876012
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004876011
Diameter:	8.25
Depth From:	0.0
Depth To:	3.6600000858306885
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

41 ***1 of 1*** ***WSW/147.7*** ***69.9 / -1.00*** ***ON*** ***BORE***

Borehole ID:	613487	***Inclin FLG:***	No
OGF ID:	215514766	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:		***Primary Name:***	
Completion Date:	AUG-1948	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:		***Township:***	

Sec. Water Use:		***Latitude DD:***	45.425793
Total Depth m:	22.9	***Longitude DD:***	-75.641055
Depth Ref:	Ground Surface	***UTM Zone:***	18
Depth Elev:		***Easting:***	449851
Drill Method:		***Northing:***	5030452
Orig Ground Elev m:	61	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	71.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218395343	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.2	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Soil	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SOIL.		

Geology Stratum ID:	218395344	***Mat Consistency:***	
Top Depth:	1.2	***Material Moisture:***	
Bottom Depth:	5.5	***Material Texture:***	
Material Color:	Blue	***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	CLAY. BLUE.		

Geology Stratum ID:	218395346	***Mat Consistency:***	
Top Depth:	6.1	***Material Moisture:***	
Bottom Depth:	22.9	***Material Texture:***	
Material Color:	Blue	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Slate	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	BEDROCK. BLUE. 00075 VELOCITY = 5130. BEDROCK. SEISMIC VELOCITY = 11800. UNSPECIFIED. D **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218395345	***Mat Consistency:***	
Top Depth:	5.5	***Material Moisture:***	
Bottom Depth:	6.1	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SAND. GREY.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:		**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 05995 NTS_Sheet:		
Confiden 1:			

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

42	1 of 1	WSW/147.7	69.9 / -1.00	lot 8 ON	WWIS

Well ID:	1500399	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	02/25/1949
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1107
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	008
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	JG
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY (GLOUCESTER)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1500399.pdf

Additional Detail(s) (Map)

Well Completed Date:	08/11/1948
Year Completed:	1948
Depth (m):	22.86
Latitude:	45.4257909593461
Longitude:	-75.6410548456279
X:	-75.64105468369377
Y:	45.42579095222667
Path:	150\1500399.pdf

Bore Hole Information

Bore Hole ID:	10022444	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	449850.70
Code OB Desc:		**North83:**	5030452.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	9

Date Completed: 08/11/1948 ***UTMRC Desc:*** unknown UTM
Remarks: ***Location Method:*** p9
Location Method Desc: Original Pre1985 UTM Rel Code 9: unknown UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 930989169
Layer: 1
Color:
General Color:
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930989171
Layer: 3
Color: 2
General Color: GREY
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 18.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930989172
Layer: 4
Color: 3
General Color: BLUE
Material 1: 26
Material 1 Desc: ROCK
Material 2: 19
Material 2 Desc: SLATE
Material 3:
Material 3 Desc:
Formation Top Depth: 20.0
Formation End Depth: 75.0
Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID:	930989170
Layer:	2
Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	4.0
Formation End Depth:	18.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961500399
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10571014
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930037821
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	20.0
Casing Diameter:	4.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930037822
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	75.0
Casing Diameter:	4.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	BAILER
Pump Test ID:	991500399
Pump Set At:	
Static Level:	15.0
Final Level After Pumping:	17.0

Recommended Pump Depth:	
Pumping Rate:	8.0
Flowing Rate:	
Recommended Pump Rate:	8.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	2
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933452916
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	75.0
Water Found Depth UOM:	ft

---

43 ***1 of 1*** ***NNE/152.1*** ***71.9 / 1.00*** ***1055 ST. LAURENT BLVD Ottawa ON*** ***WWIS***

Well ID:	7205222	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Test Hole	***Date Received:***	07/23/2013
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z168878	***Contractor:***	7241
Tag:	A149966	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7205222.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/04/2013
Year Completed:	2013
Depth (m):	3.96
Latitude:	45.4283972131919
Longitude:	-75.6385749422794
X:	-75.63857477985073
Y:	45.428397206321094
Path:	720\7205222.pdf

Bore Hole Information

Bore Hole ID:	1004448564	***Elevation:***	

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450047.00
Code OB Desc:		**North83:**	5030740.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/04/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004876022
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876023
Layer:	2
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876024
Layer:	3
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	77
Material 3 Desc:	LOOSE

Formation Top Depth:	1.5
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876025
Layer:	4
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	2.440000057220459
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876034
Layer:	2
Plug From:	0.3100000023841858
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876035
Layer:	3
Plug From:	0.9100000262260437
Plug To:	3.9600000381469727
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876033
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004876032
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	D.P

Pipe Information

Pipe ID:	1004876021
Casing No:	0
Comment:	

Alt Name:

Construction Record - Casing

Casing ID:	1004876028
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004876029
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004876027
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004876026
Diameter:	8.25
Depth From:	0.0
Depth To:	3.9600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	1 of 2	ENE/160.8	71.9 / 1.00	ONE STOP LAUNDROMAT(OUT OF BUSINESS) -589 914115 ONT. INC. 1045 ST. LAURENT BLVD. OTTTAWA ON K1K 3B1	GEN

Generator Info

Generator No:	ON1297600	**Choice of Contact:**	
Approval Years:	92,93,95,96,97,98	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	9729
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	OTHER LAUND. SERV.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	2 of 2	ENE/160.8	71.9 / 1.00	ONE STOP LAUNDROMAT 29-589 914115 ONT. INC. 1045 ST. LAURENT BLVD. OTTTAWA ON K1K 3B1	GEN

Generator Info

Generator No: ON1297600
Approval Years: 94
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: OTHER LAUND. SERV.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 9729

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	1 of 15	SE/161.2	70.9 / 0.00	PETRO-CANADA 1018 SYRVILLE RD TANK TRUCK (CARGO) GLOUCESTER CITY ON K1J 7S4	SPL

Ref No: 46426
Year:
Incident Dt: 2/7/1991
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/7/1991
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: GLOUCESTER CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: PETRO CANADA-3 LITRES OF GASOLINE FROM TRUCKS HOSE 2 LITRES CLEANED-UP
Environment Impact: POSSIBLE
Health Env Consequence:

Municipality No: 20105
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

45	2 of 15	SE/161.2	70.9 / 0.00	E ANNE BRUNDIGE 1018 CYRVILLE RD GLOUCESTER ON K1J 7S4	PRT

Location ID: 5279
Type: retail
Expiry Date: 1994-12-31
Capacity (L): 0
Licence #: 0018847001

45	3 of 15	SE/161.2	70.9 / 0.00	CATHYS CORNER 1018 CYRVILLE RD GLOUCESTER ON	PRT

Location ID: 5279
Type: retail
Expiry Date: 1996-03-31
Capacity (L): 145000
Licence #: 0076440239

45	4 of 15	SE/161.2	70.9 / 0.00	1343615 ONTARIO INC O/A PETRO CANADA 1018 CYRVILLE RD GLOUCESTER ON K1J 7S4	FSTH

License Issue Date: 9/1/2005
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation:
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation:
Corrosion Protection:
Capacity: 25000

Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	
Corrosion Protection:	
Capacity:	35000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	
Corrosion Protection:	
Capacity:	35000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	
Corrosion Protection:	
Capacity:	25000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

---

45 **5 of 15** **SE/161.2** **70.9 / 0.00** **ERIC ROY**
1018 CYRVILLE RD
GLOUCESTER ON K1J 7S4 **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No:	9519735	**Expired Date:**	5/20/2009
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

---

45 **6 of 15** **SE/161.2** **70.9 / 0.00** **6205429 CANADA INC O/A GAS STN**
1018 CYRVILLE RD
GLOUCESTER ON **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No:	11318343	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	77358	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

45	***7 of 15***	***SE/161.2***	***70.9 / 0.00***	***6205429 CANADA INC O/A GAS STN 1018 CYRVILLE RD GLOUCESTER ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	11318362	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	78457	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

45 | **8 of 15** | **SE/161.2** | **70.9 / 0.00** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
1018 CYRVILLE RD
GLOUCESTER ON | **FST**

Inventory No: 11318286
Inventory Status: active
Installation Year: 1991
Capacity: 25000
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBSSuper gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

45 | **9 of 15** | **SE/161.2** | **70.9 / 0.00** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
1018 CYRVILLE RD
GLOUCESTER ON | **FST**

Inventory No: 11318324
Inventory Status: active
Installation Year: 1991
Capacity: 25000
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

45 | **10 of 15** | **SE/161.2** | **70.9 / 0.00** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
1018 CYRVILLE RD
GLOUCESTER ON | **FST**

Inventory No: 11318266
Inventory Status: active
Installation Year: 1991
Capacity: 35000
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBSRegular gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

45 | **11 of 15** | **SE/161.2** | **70.9 / 0.00** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
1018 CYRVILLE RD
GLOUCESTER ON | **FST**

Inventory No: 11318305
Inventory Status: active
Installation Year: 1991
Capacity: 25000
Capacity Unit: L

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBSRegular gasoline

---

45 | **12 of 15** | **SE/161.2** | **70.9 / 0.00** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
1018 CYRVILLE RD
GLOUCESTER ON | **FST**

Inventory No: 10762215
Inventory Status: active
Installation Year: 1991
Capacity: 35000
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBSRegular gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

45 | **13 of 15** | **SE/161.2** | **70.9 / 0.00** | **1018 Cyrville Rd**
Ottawa ON | **SPL**

Ref No: 1155-9C6K9V
Year:
Incident Dt: 2013/10/04
Dt MOE Arvl on Scn:
MOE Reported Dt: 2013/10/04
Dt Document Closed:
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Petro Canada Store #14177<UNOFFICIAL>
Site Address: 1018 Cyrville Rd
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: Operator/Human error
Incident Preceding Spill:
Incident Reason: Operator/Human Error
Incident Summary: Petro Canada, 20L Gas to grnd, Pump Hit
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty: 20 L
Contaminant Qty 1: 20
Contaminant Unit: L
Contaminant Code: 12
Contaminant Name: GASOLINE
Contaminant Limit 1:
Contam Limit Freq 1:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Unknown / N/A
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

45 | ***14 of 15*** | ***SE/161.2*** | ***70.9 / 0.00*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP***
1018 CYRVILLE RD
GLOUCESTER ON | ***INC***

Incident No: 1258132
Incident ID:
Instance No: 30179806
Status Code:
Incident Status: Non Mandated
Incident Severity:
Task No:
Attribute Category: FS-Incident
Context:
Date of Occurrence: 10/4/2013
Time of Occurrence:
Occr Insp Start Dt:
Incident Creat On: 10/4/2013
Instance Creat Dt:
Instance Install Dt:
Approx Quant Rel:
Tank Capacity:
Fuels Occur Type: Liquid Petroleum Spill
Occur Type Rpt: Liquid Petroleum Spill
Occur Category:
Fuel Type Involved: Gasoline
Fuel Type Reported: Transportation Fuel
Enforcement Policy:
Prc Escalation Req:
Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 1018 CYRVILLE RD
Invent Postal Code: K1J 7S4
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: CAR HIT DISPENSER
Operation Type Involved: Retail Fuel Station (FS, SS, Multifunctional)

Any Health Impact:
Any Enviro Impact:
Service Intrp:
Was Prop Damaged:
Reside App. Type:
Commer App. Type:
Indus App. Type:
Institut App. Type:
Depth Ground Cover:
Operation Pressure:
Equipment Type:
Equipment Model:
Serial No:
Cylinder Capacity:
Cylinder Cap Units:
Cylinder Mat Type:
Pump Flow Rate Cap:
Contam. Migrated:
Near Body of Water:
Drainage System:
Sub Surface Contam:
Tank Material Type:
Tank Storage Type:
Tank Location Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	15 of 15	SE/161.2	70.9 / 0.00	SUNCOR ENERGY PRODUCTS PARTNERSHIP 1018 CYRVILLE RD GLOUCESTER ON	FST

Inventory No: 30179806
Inventory Status: Active
Installation Year:
Capacity: 145000
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
46	1 of 1	W/164.8	69.9 / -1.00	ON	BORE

Borehole ID: 613498
OGF ID: 215514774
Status:
Type: Borehole
Use:
Completion Date: DEC-1958
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 4.3
Depth Ref: Ground Surface
Depth Elev:
Drill Method:
Orig Ground Elev m: 70.3
Elev Reliabil Note:
DEM Ground Elev m: 70.6
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 45.42633
Longitude DD: -75.641572
UTM Zone: 18
Easting: 449811
Northing: 5030512
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218395374
Top Depth: 0
Bottom Depth: .3
Material Color:
Material 1: Unknown
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: UNSPECIFIED.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395375
Top Depth: .3
Bottom Depth: .9
Material Color:
Material 1: Silt
Material 2: Sand
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SILT.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395377
Mat Consistency: Dense

Top Depth:	1.8	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	CLAY. . BEDROCK. BEDROCK. BEDROCK. . SAND. BROWN,GREY, DENSE TO VERY DENSE. BEDR **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218395376	**Mat Consistency:**	
Top Depth:	.9	**Material Moisture:**	
Bottom Depth:	1.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 060060 NTS_Sheet: 31G05G		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

47 | **1 of 5** | **NE/193.4** | **71.9 / 1.00** | **1021 St. Laurent Blve Ottawa ON** | **SPL**

Ref No:	5027-6FUNX4	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/2/2005	**Discharger Report:**	0
Dt MOE Arvl on Scn:		**Material Group:**	Gases/Particulate
MOE Reported Dt:	9/2/2005	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	Loeb Grocery Store<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			

Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	Pipe Or Hose Leak
Incident Preceding Spill:	
Incident Reason:	
Incident Summary:	Loeb Grocery: Freon HP 80 to atm
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	223.6 Kg
Contaminant Qty 1:	223.6
Contaminant Unit:	Kg
Contaminant Code:	
Contaminant Name:	FREON HP-80 (CFC)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	Spills to Air - gases and vapours
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

47 | ***2 of 5*** | ***NE/193.4*** | ***71.9 / 1.00*** | ***METRO ONTARIO INC O/A METRO/FOOD BASICS # 262
1021 ST. LAURENT BOULEVARD
OTTAWA ON K1K 3B1*** | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

47 | ***3 of 5*** | ***NE/193.4*** | ***71.9 / 1.00*** | ***1021 St Laurent Blvd
Ottawa ON K1K 3B1*** | ***EHS***

Order No:	20121018009	**Nearest Intersection:**	
Status:	C	**Municipality:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	24-OCT-12	**Search Radius (km):**	.25
Date Received:	18-OCT-12	**X:**	-75.638523
Previous Site Name:		**Y:**	45.428307
Lot/Building Size:			
Additional Info Ordered:			

---

47 | ***4 of 5*** | ***NE/193.4*** | ***71.9 / 1.00*** | ***PES***

METRO ONTARIO INC O/A METRO/FOOD BASICS # 262
1021 St. Laurent Boulevard
Ottawa ON K1K 3B1

Detail Licence No:	23-01-15326-0	**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	LIMITED	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

47 | ***5 of 5*** | ***NE/193.4*** | ***71.9 / 1.00*** | ***PES***

METRO ONTARIO INC O/A METRO/FOOD BASICS # 262
1021 ST. LAURENT BOULEVARD
OTTAWA ON K1K3B1

Detail Licence No:		**Operator Box:**	
Licence No:	15326	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

48 | ***1 of 1*** | ***ESE/194.3*** | ***72.0 / 1.08*** | ***ON*** | ***BORE***

Borehole ID:	615072	**Inclin FLG:**	No
OGF ID:	215516014	**SP Status:**	Initial Entry

Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:	DEC-1958	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.425548
Total Depth m:	29.6	**Longitude DD:**	-75.636578
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	450201
Drill Method:		**Northing:**	5030422
Orig Ground Elev m:	70.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	69.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218400332	**Mat Consistency:**	Compact
Top Depth:	7.6	**Material Moisture:**	
Bottom Depth:	29.6	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SHALE. 00093GREY,COMPACT. BEDROCK. BLACK,WEATHERED. 000100140008910030RED. 0000500400 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218400330	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	6.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	CLAY.		

Geology Stratum ID:	218400331	**Mat Consistency:**	
Top Depth:	6.1	**Material Moisture:**	
Bottom Depth:	7.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Boulders	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:		**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 07580 NTS_Sheet:		

Confiden 1:

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

49 ***1 of 2*** ***ESE/194.4*** ***72.0 / 1.08*** ***lot 26 con 1 ON*** ***WWIS***

Well ID:	1501137	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Public	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	12/19/1958
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	1802
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	026
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1501137.pdf

Additional Detail(s) (Map)

Well Completed Date:	12/04/1958
Year Completed:	1958
Depth (m):	29.5656
Latitude:	45.4255459594733
Longitude:	-75.6365780649246
X:	-75.63657790313333
Y:	45.42554595217514
Path:	150\1501137.pdf

Bore Hole Information

Bore Hole ID:	10023180	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	450200.70
Code OB Desc:		***North83:***	5030422.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	12/04/1958	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5
Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m		
Elevrc Desc:			
Location Source Date:			

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 930991070
Layer: 3
Color:
General Color:
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 25.0
Formation End Depth: 97.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930991068
Layer: 1
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930991069
Layer: 2
Color:
General Color:
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2: 13
Material 2 Desc: BOULDERS
Material 3:
Material 3 Desc:
Formation Top Depth: 20.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961501137
Method Construction Code: 1
Method Construction: Cable Tool

Other Method Construction:

Pipe Information

Pipe ID:	10571750
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930039266
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	27.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930039267
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	97.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991501137
Pump Set At:	
Static Level:	12.0
Final Level After Pumping:	80.0
Recommended Pump Depth:	
Pumping Rate:	33.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	2
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933453825
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	93.0
Water Found Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	2 of 2	ESE/194.4	72.0 / 1.08	lot 25 con 2 ON	WWIS

Well ID:	1501337	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	12/06/1960
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1802
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	025
Depth to Bedrock:		**Concession:**	02
Well Depth:		**Concession Name:**	OF
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1501337.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/26/1960
Year Completed:	1960
Depth (m):	12.192
Latitude:	45.4255459594733
Longitude:	-75.6365780649246
X:	-75.63657790313333
Y:	45.42554595217514
Path:	150\1501337.pdf

Bore Hole Information

Bore Hole ID:	10023380	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	450200.70
Code OB Desc:		**North83:**	5030422.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	09/26/1960	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930991578
Layer:	1
Color:	3

General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930991579
Layer: 2
Color: 8
General Color: BLACK
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 18.0
Formation End Depth: 40.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961501337
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 10571950
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930039643
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930039644
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:

Depth To:	40.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991501337
Pump Set At:	
Static Level:	15.0
Final Level After Pumping:	40.0
Recommended Pump Depth:	30.0
Pumping Rate:	17.0
Flowing Rate:	
Recommended Pump Rate:	17.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933454035
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	38.0
Water Found Depth UOM:	ft

---

50 | ***1 of 11*** | ***ESE/195.0*** | ***71.9 / 1.00*** | ***Rio Can Properties<UNOFFICIAL>*** ***1021 Cyrville Rd.*** ***Ottawa ON*** | ***SPL***

Ref No:	2370-6QLTPG	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	6/9/2006	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	6/9/2006	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	Rio Can Properties<UNOFFICIAL>		
Site Address:	1021 Cyrville Rd.		
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Waste Care Services<UNOFFICIAL>		
Client Type:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Type:	Other Motor Vehicle
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	Other - Reason not otherwise defined
Incident Summary:	Oil spill on gnd: 1021 Cyrville Rd, Ottawa
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	754 L
Contaminant Qty 1:	754
Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	OIL (PETROLEUM BASED, NOT SPECIFIED)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	2 of 11	ESE/195.0	71.9 / 1.00	RioKim Holdings (Ontario) Inc. 1021 Cyrville Road Ottawa ON	CA

Certificate #:	0488-6C5MLJ
Application Year:	2005
Issue Date:	5/10/2005
Approval Type:	Municipal and Private Sewage Works
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	3 of 11	ESE/195.0	71.9 / 1.00	RioKim Holdings (Ontario) Inc. 1021 Cyrville Road Ottawa ON	CA

Certificate #:	7080-6DTNEZ
Application Year:	2005
Issue Date:	6/29/2005
Approval Type:	Municipal and Private Sewage Works
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	4 of 11	ESE/195.0	71.9 / 1.00	Metro Ontario Incorporated 1021 Cyrville Road Ottawa ON K1J 7S3	SPL

Ref No:	1354-8B2RX7	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/9/2010	**Impact to Health:**	
Dt Document Closed:	11/12/2010	**Agency Involved:**	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Food Basics 1021 Cyrville Road<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:			
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	Unknown		
Incident Preceding Spill:			
Incident Reason:	Other - Reason not otherwise defined		
Incident Summary:	Food basics, truck spilled diesel		
Environment Impact:	Not Anticipated		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	9 L		
Contaminant Qty 1:	9		
Contaminant Unit:	L		
Contaminant Code:	13		
Contaminant Name:	DIESEL FUEL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:	Land Spills		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	5 of 11	ESE/195.0	71.9 / 1.00	METRO ONTARIO INC O/A METRO/FOOD BASICS # 896 1021 CYRVILLE ROAD, UNIT 1 OTTAWA ON K1J7S3	PES

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:				**Operator No:**	
Approval Date:				**Operator Type:**	
Report Source:				**Oper Area Code:**	
Licence Type:	Vendor			**Oper Phone No:**	
Licence Type Code:				**Operator Ext:**	
Licence Class:				**Operator Lot:**	
Licence Control:				**Oper Concession:**	
Latitude:				**Operator Region:**	
Longitude:				**Operator District:**	
Lot:				**Operator County:**	
Concession:				**Op Municipality:**	
Region:				**Post Office Box:**	
District:				**MOE District:**	
County:				**SWP Area Name:**	
Trade Name:					
PDF URL:					

50	6 of 11	ESE/195.0	71.9 / 1.00	**METRO ONTARIO INC O/A METRO/FOOD BASICS # 896** **1021 Cyrville Road, Unit 1** **Ottawa ON K1J 7S3**	PES

Detail Licence No:	23-01-15177-0	**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	LIMITED	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

50	7 of 11	ESE/195.0	71.9 / 1.00	**Metro Ontario Incorporated** **1021 Cyrville Road** **Ottawa ON K1J 7S3**	SPL

Ref No:	6215-9ZP53K	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	8/23/2015	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/23/2015	**Impact to Health:**	
Dt Document Closed:	11/24/2015	**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Food Basics<UNOFFICIAL>		
Site Address:	1021 Cyrville Road		
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			

Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	Metro Ontario Incorporated
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	Equipment Failure
Incident Summary:	Food Basics 250 pounds of R404A to atm
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	250 lb
Contaminant Qty 1:	250
Contaminant Unit:	lb
Contaminant Code:	38
Contaminant Name:	REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Air Spills - Gases and Vapours
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

50 | ***8 of 11*** | ***ESE/195.0*** | ***71.9 / 1.00*** | ***RioKim Holdings (Ontario) Inc.*** ***1021 Cyrville Road*** ***Ottawa ON*** | ***ECA***

Approval No:	6180-6C5MSY	**MOE District:**	Ottawa
Approval Date:	2005-05-10	**City:**	
Status:	Approved	**Longitude:**	-75.63683999999999
Record Type:	ECA	**Latitude:**	45.426204999999996
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Business Name:	RioKim Holdings (Ontario) Inc.		
Address:	1021 Cyrville Road		
Full Address:			
Full PDF Link:			
PDF Site Location:			

---

50 | ***9 of 11*** | ***ESE/195.0*** | ***71.9 / 1.00*** | ***RioKim Holdings (Ontario) Inc.*** ***1021 Cyrville Road*** ***Ottawa ON*** | ***ECA***

Approval No:	0488-6C5MLJ	**MOE District:**	Ottawa
Approval Date:	2005-05-10	**City:**	
Status:	Approved	**Longitude:**	-75.63684
Record Type:	ECA	**Latitude:**	45.426205
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: RioKim Holdings (Ontario) Inc.
Address: 1021 Cyrville Road
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3434-6C3QRA-14.pdf
PDF Site Location:

---

50 | **10 of 11** | **ESE/195.0** | **71.9 / 1.00** | **RioKim Holdings (Ontario) Inc.**
1021 Cyrville Road
Ottawa ON | **ECA**

Approval No: 7080-6DTNEZ
Approval Date: 2005-06-29
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
MOE District: Ottawa
City:
Longitude: -75.63684
Latitude: 45.426205
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: RioKim Holdings (Ontario) Inc.
Address: 1021 Cyrville Road
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9368-6B8LUL-14.pdf
PDF Site Location:

---

50 | **11 of 11** | **ESE/195.0** | **71.9 / 1.00** | **METRO ONTARIO INC O/A METRO/FOOD BASICS # 896**
1021 CYRVILLE ROAD, UNIT 1
OTTAWA ON K1J7S3 | **PES**

Detail Licence No:
Licence No: 15177
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

51 | **1 of 14** | **W/195.3** | **69.9 / -1.00** | **SHELL CANADA PRODUCTS LTD.**
AT THE QUEEN MARY PUBLIC SCHOOL AT 557 QUEEN MARY ROAD TANK TRUCK (CARGO)
OTTAWA CITY ON K1K 1V9 | **SPL**

Ref No: 80371
Year:
Incident Dt: 12/29/1992
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/30/1992
Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt Document Closed:		**Agency Involved:**	REPORT FAXED TO MCCR
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	OTTAWA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	CONTAINER OVERFLOW		
Incident Preceding Spill:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	SHELL HOME HEATING - 2 L OF FURNACE OIL TO CEMENT WHILE MAKING DELIVERY.		
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:	Other		
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

51	2 of 14	W/195.3	69.9 / -1.00	**Ottawa-Carleton District School Board** **Queen Mary Street Public School 557 Queen Mary Street** **Ottawa ON K1K 1V9**	GEN

Generator Info

Generator No:	ON7493298	**Choice of Contact:**	
Approval Years:	02,03,04	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

---

51 | ***3 of 14*** | ***W/195.3*** | ***69.9 / -1.00*** | ***Ottawa-Carleton District School Board*** ***557 Queen Mary Street*** ***Ottawa ON K1K 1V9*** | ***GEN***

Generator Info

Generator No: ON4309427
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Elementary and Secondary Schools

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611110

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

51 | ***4 of 14*** | ***W/195.3*** | ***69.9 / -1.00*** | ***Ottawa-Carleton District School Board*** ***557 Queen Mary Street*** ***Ottawa ON K1K 1V9*** | ***GEN***

Generator Info

Generator No: ON4309427
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Elementary and Secondary Schools

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611110

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

51 | ***5 of 14*** | ***W/195.3*** | ***69.9 / -1.00*** | ***Ottawa-Carleton District School Board*** ***557 Queen Mary Street*** ***Ottawa ON K1K 1V9*** | ***GEN***

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON4309427
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Elementary and Secondary Schools

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611110

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	6 of 14	W/195.3	69.9 / -1.00	Ottawa-Carleton District School Board 557 Queen Mary Street Ottawa ON K1K 1V9	GEN

Generator Info

Generator No: ON4309427
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Elementary and Secondary Schools

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611110

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	7 of 14	W/195.3	69.9 / -1.00	Ottawa-Carleton District School Board 557 Queen Mary Street Ottawa ON	GEN

Generator Info

Generator No: ON4309427
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611110

Phone No Admin:
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

51 | ***8 of 14*** | ***W/195.3*** | ***69.9 / -1.00*** | ***Ottawa-Carleton District School Board***
557 Queen Mary Street
Ottawa ON K1K 1V9 | ***GEN***

Generator Info

Generator No: ON4309427
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Greg Benson
Phone No Admin: 613-596-8211 Ext.8549
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 611110

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

51 | ***9 of 14*** | ***W/195.3*** | ***69.9 / -1.00*** | ***Ottawa-Carleton District School Board***
557 Queen Mary Street
Ottawa ON K1K 1V9 | ***GEN***

Generator Info

Generator No:	ON4309427	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	611110
Country:	Canada		
Co Admin:	Greg Benson		
Phone No Admin:	613-596-8211 Ext.8549		
SIC Description:	ELEMENTARY AND SECONDARY SCHOOLS		

Waste Detail(s)

Waste Class:	121
Waste Class Name:	ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS

51	***10 of 14***	***W/195.3***	***69.9 / -1.00***	***Ottawa-Carleton District School Board*** ***557 Queen Mary Street*** ***Ottawa ON K1K 1V9***	***GEN***

Generator Info

Generator No:	ON4309427	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	611110
Country:	Canada		
Co Admin:	Greg Benson		
Phone No Admin:	613-596-8211 Ext.8549		
SIC Description:	ELEMENTARY AND SECONDARY SCHOOLS		

Waste Detail(s)

Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

51 | ***11 of 14*** | ***W/195.3*** | ***69.9 / -1.00*** | ***Ottawa-Carleton District School Board Health & Safety***
557 Queen Mary Street
Ottawa ON K1K 1V9 | ***GEN***

Generator Info

Generator No: ON4309427
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 146 R
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

---

51 | ***12 of 14*** | ***W/195.3*** | ***69.9 / -1.00*** | ***Ottawa-Carleton District School Board Health & Safety***
557 Queen Mary Street
Ottawa ON K1K 1V9 | ***GEN***

Generator Info

Generator No: ON4309427
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 146 R
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	13 of 14	W/195.3	69.9 / -1.00	Ottawa-Carleton District School Board Health & Safety 557 Queen Mary Street Ottawa ON K1K 1V9	GEN

Generator Info

Generator No:	ON4309427	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class:	121 C
Waste Class Name:	Alkaline slutions - containing heavy metals

Waste Detail(s)

Waste Class:	213 I
Waste Class Name:	Petroleum distillates

Waste Detail(s)

Waste Class:	146 R
Waste Class Name:	Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class:	146 T
Waste Class Name:	Other specified inorganic sludges, slurries or solids

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	14 of 14	W/195.3	69.9 / -1.00	Ottawa-Carleton District School Board Queen Mary Public School, 557 Queen Mary Street Ottawa ON	GEN

Generator Info

Generator No:	ON4309427	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	

Status: Registered
MHSW Facility:
PO Box No:
SIC Code:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 146 R
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 121 C
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Generator Info as of Dec 2024

Generator No: ON4309427
Generator Company Name: Ottawa-Carleton District School Board
Street: Queen Mary Public School, 557 Queen Mary Street
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K1V9
Waste Class: 146 T, 146 R, 121 C, 122 C, 213 I, 112 C

Waste Class Decoded:

146 - OTHER SPECIFIED INORGANICS; 146 - OTHER SPECIFIED INORGANICS; 121 - ALKALINE WASTES - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 213 - PETROLEUM DISTILLATES; 112 - ACID WASTE - HEAVY METALS

Generator Info as of Dec 2024

Generator No: ON4309427
Generator Company Name: Ottawa-Carleton District School Board
Street: Queen Mary Public School, 557 Queen Mary Street

City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1K1V9
Waste Class:	145 L,145 I,146 T,146 R,121 C,122 C,213 I,112 C

Waste Class Decoded:

145 - PAINT/PIGMENT/COATING RESIDUES; 145 - PAINT/PIGMENT/COATING RESIDUES; 146 - OTHER SPECIFIED INORGANICS; 146 - OTHER SPECIFIED INORGANICS; 121 - ALKALINE WASTES - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 213 - PETROLEUM DISTILLATES; 112 - ACID WASTE - HEAVY METALS

2017 Generator Info

Gen No:	ON4309427	***Choice of Contact:***	CO_OFFICIAL
ID:	17172	***Phone No Official:***	613-596-8211 Ext.8495
Contaminated Fac:	N	***Phone No Admin:***	613-596-8211 Ext.8549
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	611110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	Ottawa-Carleton District School Board
Gen Div:	Health & Safety
Gen Op Name:	Ottawa-Carleton District School Board
Gen Op Div:	Health & Safety
Site Adrs1:	557 Queen Mary Street
Site Bldg:	Queen Mary Public School
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 1V9
Site Country:	Canada
Co Official:	Clint Vester
Co Admin:	Greg Benson

2018 Generator Info

Gen No:	ON4309427	***Choice of Contact:***	CO_OFFICIAL
ID:	17174	***Phone No Official:***	613-596-8211 Ext.8495
Contaminated Fac:	N	***Phone No Admin:***	613-596-8211 Ext.8549
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	611110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	Ottawa-Carleton District School Board
Gen Div:	Health & Safety
Gen Op Name:	Ottawa-Carleton District School Board
Gen Op Div:	Health & Safety
Site Adrs1:	557 Queen Mary Street
Site Bldg:	Queen Mary Public School
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 1V9
Site Country:	Canada
Co Official:	Clint Vester
Co Admin:	Greg Benson

2019 Generator Info

Gen No:	ON4309427	***Choice of Contact:***	CO_OFFICIAL
ID:	17064	***Phone No Official:***	613-596-8211 Ext.8495
Contaminated Fac:	N	***Phone No Admin:***	613-596-8211 Ext.8549
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	611110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Ottawa-Carleton District School Board		
Gen Div:	Health & Safety		
Gen Op Name:	Ottawa-Carleton District School Board		
Gen Op Div:	Health & Safety		
Site Adrs1:	557 Queen Mary Street		
Site Bldg:	Queen Mary Public School		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K1K 1V9		
Site Country:	Canada		
Co Official:	Clint Vester		
Co Admin:	Greg Benson		

2020 Generator Info

Gen No:	ON4309427	***Choice of Contact:***	CO_OFFICIAL
ID:	16776	***Phone No Official:***	613-596-8211 Ext.8495
Contaminated Fac:	N	***Phone No Admin:***	613-596-8211 Ext.8549
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	611110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Ottawa-Carleton District School Board		
Gen Div:	Health & Safety		
Gen Op Name:	Ottawa-Carleton District School Board		
Gen Op Div:	Health & Safety		
Site Adrs1:	557 Queen Mary Street		
Site Bldg:	Queen Mary Public School		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K1K 1V9		
Site Country:	Canada		
Co Official:	Clint Vester		
Co Admin:	Greg Benson		

2021 Generator Info

Gen No:	ON4309427	***Choice of Contact:***	CO_OFFICIAL
ID:	16824	***Phone No Official:***	613-596-8211 Ext.8495
Contaminated Fac:	N	***Phone No Admin:***	613-596-8211 Ext.8549
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	611110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Ottawa-Carleton District School Board		
Gen Div:	Health & Safety		
Gen Op Name:	Ottawa-Carleton District School Board		
Gen Op Div:	Health & Safety		
Site Adrs1:	557 Queen Mary Street		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Bldg: Queen Mary Public School
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 1V9
Site Country: Canada
Co Official: Clint Vester
Co Admin: Greg Benson

---

52 | **1 of 1** | **SE/209.6** | **70.9 / 0.00** | **lot 26 con 1 ON** | **WWIS**

Well ID: 7411205
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C54300
Tag: A328048
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 02/17/2022
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7328
Form Version: 8
Owner:
County: OTTAWA-CARLETON
Lot: 026
Concession: 01
Concession Name: OF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1008965447
Depth M:
Year Completed: 2022
Well Completed Dt: 01/31/2022
Audit No: C54300
Path:

Tag No: A328048
Contractor: 7328
Latitude: 45.424803718256
Longitude: -75.6373200675828
Y: 45.42480371087518
X: -75.63731990598491

Bore Hole Information

Bore Hole ID: 1008965447
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/31/2022
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 450142.00
North83: 5030340.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
53	1 of 1	E/209.7	72.9 / 2.00	1055 ST. LAURENT BLVD Ottawa ON	WWIS

Well ID: 7205224
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z168876
Tag: A149951
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 07/23/2013
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7205224.pdf

Additional Detail(s) (Map)

Well Completed Date: 07/02/2012
Year Completed: 2012
Depth (m): 4.57
Latitude: 45.4270062301624
Longitude: -75.6362071475118
X: -75.63620698605682
Y: 45.42700622326154
Path: 720\7205224.pdf

Bore Hole Information

Bore Hole ID: 1004448570
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 07/02/2012
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 450231.00
North83: 5030584.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004876139
Layer: 2
Color: 6

General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876140
Layer:	3
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	1.2200000286102295
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876141
Layer:	4
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	2.440000057220459
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004876138
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	73
Material 2 Desc:	HARD
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876149
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876150
Layer:	2
Plug From:	0.3100000023841858
Plug To:	1.2200000286102295
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004876151
Layer:	3
Plug From:	1.2200000286102295
Plug To:	4.570000171661377
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004876148
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	D.P

Pipe Information

Pipe ID:	1004876137
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004876144
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004876145
Layer:	1
Slot:	10
Screen Top Depth:	1.5
Screen End Depth:	4.570000171661377

Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004876143
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004876142
Diameter:	8.25
Depth From:	0.0
Depth To:	4.570000171661377
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

54 | ***1 of 1*** | ***S/212.7*** | ***69.9 / -1.00*** | ***TAGR MANAGEMENT LIMITED***
1130 ST. LAURENT BOULEVARD
OTTAWA CITY ON K1K 3B6 | ***CA***

Certificate #:	8-4152-95-
Application Year:	95
Issue Date:	9/20/1995
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	EXHAUST FOR PERKINS FAMILY RESTAURANT
Contaminants:	Odour/Fumes
Emission Control:	No Controls

---

55 | ***1 of 3*** | ***NNW/219.0*** | ***71.9 / 1.00*** | ***BFI Canada<UNOFFICIAL>***
Corner of Donald Street and St. Laurent
Ottawa ON | ***SPL***

Ref No:	1522-6JKRAV	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11/28/2005	**Discharger Report:**	0
Dt MOE Arvl on Scn:		**Material Group:**	Oil
MOE Reported Dt:	11/28/2005	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	BFI Canada<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			

Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: BFI Canada<UNOFFICIAL>
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill:
Incident Reason:
Incident Summary: 200L hydraulic oil, BFI Canada, Ottawa
Environment Impact: Possible
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit: L
Contaminant Code:
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other Motor Vehicle
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

55 | ***2 of 3*** | ***NNW/219.0*** | ***71.9 / 1.00*** | ***Storm sewer<UNOFFICIAL>*** ***Intersection of Donald and St. Laurent Blvd.*** ***Ottawa ON*** | ***SPL***

Ref No: 5510-6N4TRJ
Year:
Incident Dt: 3/21/2006
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/21/2006
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Ottawa
Nearest Watercourse:
Site Name: Storm sewer<UNOFFICIAL>
Site Address: Intersection of Donald and St. Laurent Blvd.
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: City of Ottawa
Client Type:
Source Type: Sewer
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	Equipment Failure
Incident Summary:	Ottawa: 20 L antifreeze to S/S from leaky bus
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	20 L
Contaminant Qty 1:	20
Contaminant Unit:	L
Contaminant Code:	24
Contaminant Name:	ETHYLENE GLYCOL (ANTIFREEZE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

55 | ***3 of 3*** | ***NNW/219.0*** | ***71.9 / 1.00*** | ***City of Ottawa***
St Laurent and Donald
Ottawa ON | ***SPL***

Ref No:	2722-882MQC	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/5/2010	**Impact to Health:**	
Dt Document Closed:	9/14/2010	**Agency Involved:**	
Site No:			

MOE Response:	No Field Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	MVA<UNOFFICIAL>
Site Address:	
Site Region:	
Site Municipality:	
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	Other Transport Accident
Incident Preceding Spill:	
Incident Reason:	Other - Reason not otherwise defined
Incident Summary:	OC Transpo 10-15gal (45.5-68.2L) transmission oil, cntnd
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Other Impact(s)
Contaminant Qty:	68.2 L
Contaminant Qty 1:	68.2

Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	TRANSMISSION OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Motor Vehicle
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

56 | ***1 of 1*** | ***NNW/219.0*** | ***71.9 / 1.00*** | ***OTTAWA CITY***
DONALD ST/ST.LAURENT BLVD.
OTTAWA CITY ON | ***CA***

Certificate #:	3-0790-99-
Application Year:	99
Issue Date:	7/14/1999
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

---

57 | ***1 of 1*** | ***N/231.2*** | ***71.9 / 1.00*** | ***ON*** | ***BORE***

Borehole ID:	613562	**Inclin FLG:**	No
OGF ID:	215514814	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:	NOV-1972	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.429131
Total Depth m:	5	**Longitude DD:**	-75.639686
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	449961
Drill Method:		**Northing:**	5030822
Orig Ground Elev m:	69.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	70		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218395622	**Mat Consistency:**	

Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:		**Geologic Formation:**	
Material 2:	Till	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Bedrock	**Depositional Gen:**	

Gsc Material Description:
Stratum Description: ARTIFICIAL.

Geology Stratum ID:	218395623	**Mat Consistency:**	Dense
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Unknown	**Geologic Formation:**	
Material 2:	Till	**Geologic Group:**	
Material 3:	Shale	**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: UNSPECIFIED. DENSE.

Geology Stratum ID:	218395625	**Mat Consistency:**	Dense
Top Depth:	2.7	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Unknown	**Geologic Formation:**	
Material 2:	Till	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: UNSPECIFIED. DENSE.

Geology Stratum ID:	218395624	**Mat Consistency:**	Dense
Top Depth:	2	**Material Moisture:**	
Bottom Depth:	2.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Unknown	**Geologic Formation:**	
Material 2:	Till	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: UNSPECIFIED. DENSE TO VERY DENSE.

Geology Stratum ID:	218395626	**Mat Consistency:**	Dense
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Till	**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: SAND. VERY DENSE. 00000 010 00050 014 00065 012 00090 011 00140 010 000000160 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 060700 NTS_Sheet: 31G05G
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

58 ***1 of 1*** ***ESE/232.2*** ***71.9 / 1.00*** ***lot 26 con 1 ON*** ***WWIS***

Well ID:	1501135	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	07/07/1955
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	3113
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	026
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1501135.pdf

Additional Detail(s) (Map)

Well Completed Date:	03/26/1955
Year Completed:	1955
Depth (m):	44.8056
Latitude:	45.4255038043471
Longitude:	-75.6360662763416
X:	-75.63606611422468
Y:	45.42550379706475
Path:	150\1501135.pdf

Bore Hole Information

Bore Hole ID:	10023178	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	450240.70
Code OB Desc:		***North83:***	5030417.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	03/26/1955	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	p9
Location Method Desc:	Original Pre1985 UTM Rel Code 9: unknown UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	930991063
Layer:	3
Color:	2
General Color:	GREY
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	11.0
Formation End Depth:	147.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930991062
Layer:	2
Color:	
General Color:	
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	09
Material 2 Desc:	MEDIUM SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	5.0
Formation End Depth:	11.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930991061
Layer:	1
Color:	
General Color:	
Material 1:	03
Material 1 Desc:	MUCK
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961501135
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10571748
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930039262
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	16.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930039263
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	147.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991501135
Pump Set At:	
Static Level:	4.0
Final Level After Pumping:	147.0
Recommended Pump Depth:	
Pumping Rate:	2.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

Water Details

Water ID:	933453822
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	143.0
Water Found Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	1 of 5	ENE/232.8	72.9 / 2.00	1240 DONALD STREET OTTAWA ON	HINC

External File Num: FS INC 0703-01004
Fuel Occurrence Type: CO Release
Date of Occurrence: 3/2/2007
Fuel Type Involved: Natural Gas
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Multi-unit Residential
Service Interruptions: No
Property Damage: No
Fuel Life Cycle Stage: Utilization
Root Cause: Root Cause: Equipment/Material/Component:No Procedures:No Maintenance:Yes Design:No Training: Yes Management:Yes Human Factors:Yes
Reported Details:
Fuel Category: Gaseous Fuel
Occurrence Type: Incident
Affiliation: Emergency Services (Fire, Police,etc)
County Name: Ottawa
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	2 of 5	ENE/232.8	72.9 / 2.00	KONE INC 1240-1244 DONALD ST OTTAWA ON	GEN

Generator Info

Generator No: ON2960863
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Elevator and Escalator Installation Contractors

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 238291

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	3 of 5	ENE/232.8	72.9 / 2.00	GREENWIN PROPERTY MANAGEMENT INC 1240-1244 DONALD STREET OTTAWA ON K1J 8V6	GEN

Generator Info

Generator No: ON6430229
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years:	2011	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	531310
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

---

59 | **4 of 5** | **ENE/232.8** | **72.9 / 2.00** | **1240 and 1244 Donald St Ottawa ON K1J8R7** | **EHS**

Order No:	20141111023	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	17-NOV-14	**Search Radius (km):**	.25
Date Received:	11-NOV-14	**X:**	-75.635794
Previous Site Name:		**Y:**	45.427757
Lot/Building Size:			
Additional Info Ordered:			

---

59 | **5 of 5** | **ENE/232.8** | **72.9 / 2.00** | **1240 & 1244 Donald St Ottawa ON** | **EHS**

Order No:	20180115086	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	22-JAN-18	**Search Radius (km):**	.25
Date Received:	15-JAN-18	**X:**	-75.635633
Previous Site Name:		**Y:**	45.427734
Lot/Building Size:			
Additional Info Ordered:			

---

60 | **1 of 1** | **N/237.7** | **71.9 / 1.00** | **ON** | **BORE**

Borehole ID:	613565	**Inclin FLG:**	No
OGF ID:	215514815	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:	NOV-1972	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.429223
Total Depth m:	4.3	**Longitude DD:**	-75.639304
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	449991
Drill Method:		**Northing:**	5030832
Orig Ground Elev m:	69.6	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	69.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218395634	**Mat Consistency:**	Dense
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	2	**Material Texture:**	

Material Color: | ***Non Geo Mat Type:***
Material 1: Unknown | ***Geologic Formation:***
Material 2: Till | ***Geologic Group:***
Material 3: Shale | ***Geologic Period:***
Material 4: | ***Depositional Gen:***
Gsc Material Description:
Stratum Description: UNSPECIFIED. DENSE.

Geology Stratum ID: 218395635 | ***Mat Consistency:*** Compact
Top Depth: 2 | ***Material Moisture:***
Bottom Depth: 3.5 | ***Material Texture:***
Material Color: | ***Non Geo Mat Type:***
Material 1: Unknown | ***Geologic Formation:***
Material 2: Till | ***Geologic Group:***
Material 3: | ***Geologic Period:***
Material 4: | ***Depositional Gen:***
Gsc Material Description:
Stratum Description: UNSPECIFIED. LOOSE TO COMPACT.

Geology Stratum ID: 218395636 | ***Mat Consistency:*** Dense
Top Depth: 3.5 | ***Material Moisture:***
Bottom Depth: 4.3 | ***Material Texture:***
Material Color: | ***Non Geo Mat Type:***
Material 1: Unknown | ***Geologic Formation:***
Material 2: Till | ***Geologic Group:***
Material 3: | ***Geologic Period:***
Material 4: | ***Depositional Gen:***
Gsc Material Description:
Stratum Description: UNSPECIFIED. DENSE. 00000 023 00050 015 00065 012 00115 012 0000002200050023000 65 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218395633 | ***Mat Consistency:***
Top Depth: 0 | ***Material Moisture:***
Bottom Depth: 1.5 | ***Material Texture:***
Material Color: | ***Non Geo Mat Type:***
Material 1: | ***Geologic Formation:***
Material 2: Clay | ***Geologic Group:***
Material 3: Sand | ***Geologic Period:***
Material 4: Boulders | ***Depositional Gen:***
Gsc Material Description:
Stratum Description: ARTIFICIAL.

Source

Source Type: Data Survey | ***Source Appl:*** Spatial/Tabular
Source Orig: Geological Survey of Canada | ***Source Iden:*** 1
Source Date: 1956-1972 | ***Scale or Res:*** Varies
Confidence: H | ***Horizontal:*** NAD27
Observatio: | ***Verticalda:*** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 060730 NTS_Sheet: 31G05G
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier: 1 | ***Horizontal Datum:*** NAD27
Source Type: Data Survey | ***Vertical Datum:*** Mean Average Sea Level
Source Date: 1956-1972 | ***Projection Name:*** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	1 of 1	SW/251.0	69.9 / -1.00	Richcraft Construction (1984) Ltd. 741 Bernard St Ottawa ON K1G 4K1	ECA

Approval No: 4016-8XDQCU
Approval Date: 2012-08-27
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Richcraft Construction (1984) Ltd.
Address: 741 Bernard St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6546-8XCQJP-14.pdf
PDF Site Location:
MOE District: Ottawa
City:
Longitude: -75.64118
Latitude: 45.424744
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
62	1 of 1	WSW/253.2	69.9 / -1.00	RICHCRAFT HOMES LTD/MAISONS RICHCRAFT LTEE ON	EASR

Approval No: R-009-3110585386
Status: REGISTERED
Date: 2018-09-17
Record Type: EASR
Link Source: MOFA
Project Type: Water Taking - Construction Dewatering
Full Address:
Approval Type: EASR-Water Taking - Construction Dewatering
SWP Area Name: Rideau Valley
PDF NAICS Code:
PDF URL:
PDF Site Location:
MOE District: Ottawa
Municipality:
Latitude: 45.425
Longitude: -75.64194444
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
63	1 of 1	SE/256.5	70.9 / 0.00	1089 Ogilvie Road and 1137 Cyrville Rd Ottawa ON	EHS

Order No: 20020327007
Status: C
Report Type: Complete Report
Report Date: 4/8/02
Date Received: 3/27/02
Previous Site Name:
Lot/Building Size: 82,115 square feet & 113,500 square feet
Additional Info Ordered:
Nearest Intersection: Located on the southwest corner of Oglivie Road and Cummings Ave.
Municipality:
Client Prov/State: QC
Search Radius (km): 0.40
X: -75.632011
Y: 45.424995

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	1 of 1	WSW/260.0	69.9 / -1.00	ON	BORE

Borehole ID: 613479
OGF ID: 215514761
Status:
Type: Borehole
Use:
Completion Date:
Static Water Level:
Primary Water Use:
Sec. Water Use:
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 45.425156

Total Depth m:	-999	**Longitude DD:**	-75.642198
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	449761
Drill Method:		**Northing:**	5030382
Orig Ground Elev m:	69.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	69.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218395318	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND.		

Geology Stratum ID:	218395319	**Mat Consistency:**	Compact
Top Depth:	2.1	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK. COMPACT. BEDROCK. GREY,STIFF. BEDROCK. GREY,FOSSILIFEROUS. GREY,SOFT. SI **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 059870 NTS_Sheet: 31G05G		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
65	1 of 1	N/260.8	71.9 / 1.00	ON	BORE

Borehole ID:	613566	**Inclin FLG:**	No
OGF ID:	215514816	**SP Status:**	Initial Entry

Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:		***Primary Name:***	
Completion Date:	NOV-1972	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:		***Township:***	
Sec. Water Use:		***Latitude DD:***	45.429401
Total Depth m:	4.3	***Longitude DD:***	-75.639689
Depth Ref:	Ground Surface	***UTM Zone:***	18
Depth Elev:		***Easting:***	449961
Drill Method:		***Northing:***	5030852
Orig Ground Elev m:	69.6	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	69.8		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218395641	***Mat Consistency:***	Dense
Top Depth:	3.5	***Material Moisture:***	
Bottom Depth:	4.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	TILL. DENSE TO VERY DENSE. 00025 018 00040 012 00090 010 00115 009 00025008000400 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218395638	***Mat Consistency:***	Compact
Top Depth:	.8	***Material Moisture:***	
Bottom Depth:	1.2	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Unknown	***Geologic Formation:***	
Material 2:	Till	***Geologic Group:***	
Material 3:	Shale	***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	UNSPECIFIED. LOOSE TO COMPACT.		

Geology Stratum ID:	218395640	***Mat Consistency:***	Dense
Top Depth:	2.7	***Material Moisture:***	
Bottom Depth:	3.5	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Unknown	***Geologic Formation:***	
Material 2:	Till	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	UNSPECIFIED. DENSE.		

Geology Stratum ID:	218395637	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.8	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:		***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:	Soil	***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	ARTIFICIAL.		

Geology Stratum ID:	218395639	**Mat Consistency:**	Dense
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	2.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Unknown	**Geologic Formation:**	
Material 2:	Till	**Geologic Group:**	
Material 3:	Shale	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	UNSPECIFIED. DENSE TO VERY DENSE.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 060740 NTS_Sheet: 31G05G		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	1 of 1	SSW/263.3	69.9 / -1.00	**BELL CANADA** **490 COVENTRY ROAD** **OTTAWA ON K1K 2C4**	GEN

Generator Info

Generator No:	ON0473807	**Choice of Contact:**	
Approval Years:	88	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6351
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	GARAGES(GEN. REPAIR)		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

---

67 | **1 of 1** | **SE/265.3** | **70.9 / 0.00** | **Coventry Road at St Laurent Boulevard, Ottawa ON** | **INC**

Incident No:	931800	**Any Health Impact:**	No
Incident ID:	3089930	**Any Enviro Impact:**	No
Instance No:		**Service Intrp:**	No
Status Code:	Causal Analysis Complete	**Was Prop Damaged:**	No
Incident Status:		**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:	4157601	**Indus App. Type:**	
Attribute Category:	FS-Perform L1 Near Miss Insp	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	36
Date of Occurrence:	2012/05/29 00:00:00	**Operation Pressure:**	45
Time of Occurrence:	12:44:00	**Equipment Type:**	
Occr Insp Start Dt:	2012/06/06 00:00:00	**Equipment Model:**	
Incident Creat On:		**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	N/A	**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	N/A	**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:	NULL	**Tank Storage Type:**	
Prc Escalation Req:	NULL	**Tank Location Type:**	

Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type: Main Distribution Pipeline
Pipeline Involved: Transmission pipeline
Pipe Material: Plastic
Regulator Location: Outside
Regulator Type: Service Regulator (up to 60 psi intake)
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: Coventry Road at St Laurent Boulevard, Ottawa - Near Miss
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: near miss
Operation Type Involved: N/A

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	1 of 1	SE/266.8	70.9 / 0.00	TEXACO TEXACO SERVICE STATION AT CORNER OF ST. LAURENT BLVD., OGILVY RD SERVICE STATION OTTAWA CITY ON	SPL

Ref No:	27561	Municipality No:	20101
Year:		Nature of Damage:	
Incident Dt:	11/8/1989	Discharger Report:	
Dt MOE Arvl on Scn:		Material Group:	
MOE Reported Dt:	11/8/1989	Impact to Health:	
Dt Document Closed:		Agency Involved:	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	OTTAWA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	UNDERGROUND TANK LEAK		
Incident Preceding Spill:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	TEXACO SERVICE CENTRE - UNKNOWN AMOUNT OF DIESEL & GASOLINE TO LAND		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
69	1 of 4	NNW/270.1	71.9 / 1.00	KONICA ONE HOUR PHOTO 1239 DONALD ST. OTTAWA ON K1J 8W3	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON1138100	***Choice of Contact:***	
Approval Years:	89	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	9931
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHOTOGRAPHERS		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

69	*2 of 4*	*NNW/270.1*	*71.9 / 1.00*	***KONICA ONE HOUR PHOTO 23-368*** ***1239 DONALD ST.*** ***OTTAWA ON K1J 8W3***	***GEN***

Generator Info

Generator No:	ON1138100	***Choice of Contact:***	
Approval Years:	92,93,94,95,96,97,98	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	9931
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHOTOGRAPHERS		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

69	*3 of 4*	*NNW/270.1*	*71.9 / 1.00*	***FUJI IMAGE (OUT OF BUSINESS)Y LTD.15-593*** ***1239 DONALD STREET*** ***GLOUCESTER ON K1J 8W3***	***GEN***

Generator Info

Generator No:	ON1144401	***Choice of Contact:***	
Approval Years:	92,93,94,95,96,97,98	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	9931
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHOTOGRAPHERS		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
69	4 of 4	NNW/270.1	71.9 / 1.00	Rio Can Property Services 1239 Donald Street Ottawa ON K1J 8W3	GEN

Generator Info

Generator No:	ON9270336	***Choice of Contact:***	
Approval Years:	05	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	531310
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Real Estate Property Managers		

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	1 of 1	ESE/270.3	71.9 / 1.00	lot 26 con 1 ON	WWIS

Well ID:	1501132	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	11/16/1948
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	2311
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	026
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1501132.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/08/1948
Year Completed:	1948
Depth (m):	19.812
Latitude:	45.4252809216432
Longitude:	-75.6356802886483
X:	-75.63568012715864
Y:	45.425280914803764
Path:	150\1501132.pdf

Bore Hole Information

Bore Hole ID:	10023175	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	450270.70
Code OB Desc:		***North83:***	5030392.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	10/08/1948	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	p9

Location Method Desc: Original Pre1985 UTM Rel Code 9: unknown UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 930991055
Layer: 1
Color:
General Color:
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2: 09
Material 2 Desc: MEDIUM SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930991056
Layer: 2
Color:
General Color:
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 10.0
Formation End Depth: 65.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961501132
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10571745
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930039256
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 12.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930039257
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 65.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991501132
Pump Set At:
Static Level: 8.0
Final Level After Pumping: 28.0
Recommended Pump Depth:
Pumping Rate: 5.0
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933453819
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 58.0
Water Found Depth UOM: ft

71	1 of 1	E/272.2	71.8 / 0.97	1059 Ogilvie Road	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Gloucester ON K1J 7S6	

Order No: 21062900038
Status: C
Report Type: RSC Report (Urban)
Report Date: 05-JUL-21
Date Received: 29-JUN-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -75.63529262
Y: 45.42610701

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
72	1 of 1	ENE/284.1	72.9 / 2.00	1240 Donald St Gloucester ON K1J 8R7	EHS

Order No: 22052400036
Status: C
Report Type: Standard Report
Report Date: 27-MAY-22
Date Received: 24-MAY-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.6357701
Y: 45.4280464

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	1 of 116	S/291.1	69.9 / -1.00	CADILLAC FAIRVIEW CORPORATION LIMITED 1200 ST. LAURENT BOULVARD; ST. LAURENT SHOPPING CE OTTAWA ON K1K 3B8	NPCB

Company Code: F1506
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 10.00 KG

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 400.00 KG

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	2 of 116	S/291.1	69.9 / -1.00	CADILLAC FAIRVIEW CORPORATION LIMITED 1200 ST. LAURENT BOULVARD ST. LAURENT SHOPPING CENTRE OTTAWA ON K1K 3B8	OPCB

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Year: 1998
Site Number: 40291A007
Name Owner:
Additional Site Information:

--Details--
Quantity: 4.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 800.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Ballasts with High Level PCBs (>1000 ppm)

73	3 of 116	S/291.1	69.9 / -1.00	CADILLAC FAIRVIEW CORPORATION LIMITED 1200 ST. LAURENT BOULVARD ST. LAURENT SHOPPING CENTRE OTTAWA ON K1K 3B8	OPCB

Year: 1995
Site Number: 40291A007
Name Owner:
Additional Site Information:

--Details--
Quantity: 4.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 800.00
Address Site:
Description: Weight of Drums of Ballasts with High Level PCBs (>1000 ppm) kg

---

73	4 of 116	S/291.1	69.9 / -1.00	BLACK PHOTO CORPORATION 1200 ST. LAURENT BOULEVARD, OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	GEN

Generator Info

Generator No: ON0074368
Approval Years: 90
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: CAMERA/PHOTO. SUPPLY

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6571

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

73	5 of 116	S/291.1	69.9 / -1.00	BLACK PHOTO CORPORATION 1200 ST. LAURENT BOULEVARD ST. LAURENT	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				SHOPPING CENTRE OTTAWA ON K1K 3B8	

Generator Info

Generator No:	ON0074368	***Choice of Contact:***	
Approval Years:	92,93,97	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6571
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	CAMERA/PHOTO. SUPPLY		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

73	***6 of 116***	***S/291.1***	***69.9 / -1.00***	***BLACK PHOTO CORPORATION 05-410*** ***1200 ST. LAURENT BOULEVARD - OTTAWA C/O*** ***371 GOUGH ROAD*** ***MARKHAM ON L3R 4B6***	***GEN***

Generator Info

Generator No:	ON0074368	***Choice of Contact:***	
Approval Years:	94,95,96	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6571
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	CAMERA/PHOTO. SUPPLY		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

73	***7 of 116***	***S/291.1***	***69.9 / -1.00***	***BLACK PHOTO CORPORATION*** ***ST. LAURENT SHOPPING CENTRE 1200 ST. LAURENT BOULEVARD*** ***OTTAWA ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON0074368	***Choice of Contact:***	
Approval Years:	98,99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6571
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	CAMERA/PHOTO. SUPPLY		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	8 of 116	S/291.1	69.9 / -1.00	CADILLAC FAIRVIEW CORPORATION LTD.08-539 1200 ST. LAURENT BLVD. OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No: ON0733507
Approval Years: 92,93,96,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: DEPARTMENT STORES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6411

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	9 of 116	S/291.1	69.9 / -1.00	CADILLAC FAIRVIEW CORPORATION LTD.08-539 1200 ST. LAURENT BLVD. PO BOX 199 OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No: ON0733507
Approval Years: 94,95
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: DEPARTMENT STORES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6411

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

73 | ***10 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***CADILLAC FAIRVIEW CORPORATION LIMITED***
1200 ST. LAURENT BOULEVARD
OTTAWA ON K1K 3B8 | ***GEN***

Generator Info

Generator No: ON0733507
Approval Years: 99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: DEPARTMENT STORES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6411

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	11 of 116	S/291.1	69.9 / -1.00	CADILLAC FAIRVIEW CORP. LTD. N. MALL AREA-ENT. BANK & SHOP. DRUG M. C/O 1200 ST.-LAURENT BLVD. OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No:	ON0733604	**Choice of Contact:**	
Approval Years:	89,90	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6411
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	DEPARTMENT STORES		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	12 of 116	S/291.1	69.9 / -1.00	CADILLAC (SEE & USE ON0733507) 08-539 N. MALL AREA-ENT. BANK & SHOP. DRUG M. C/O 1200 ST.-LAURENT BLVD. OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No:	ON0733604	**Choice of Contact:**	
Approval Years:	92,93,94,95,96,97,98	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6411
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	DEPARTMENT STORES		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	13 of 116	S/291.1	69.9 / -1.00	JAPAN CAMERA CENTRE PHOTO MINUTES ONTARIO INC. 1200 ST. LAURENT OTTAWA ON K9K 3B8	GEN

Generator Info

Generator No:	ON0772000	**Choice of Contact:**	
Approval Years:	86,87,88,89,90	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6571
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	CAMERA/PHOTO. SUPPLY		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

73	14 of 116	S/291.1	69.9 / -1.00	JAPAN CAMERA CENTRE 31-345 PHOTO MINUTES ONTARIO INC. 1200 ST. LAURENT OTTAWA ON K9K 3B8	GEN

Generator Info

Generator No: ON0772000
Approval Years: 92,93,94,95,96,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: CAMERA/PHOTO. SUPPLY

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6571

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

73	15 of 116	S/291.1	69.9 / -1.00	BLACK (OUT OF BUS) 05-661 ST.LAURENT11-1200ST.LAURENT BLVD-OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	GEN

Generator Info

Generator No: ON1338120
Approval Years: 92,93,96,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: CAMERA/PHOTO. SUPPLY

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6571

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

73	16 of 116	S/291.1	69.9 / -1.00	BLACK PHOTO CORPORATION 05-661 ST.LAURENT11-1200ST.LAURENT BLVD-OTTAWA C/O 371 GOUGH ROAD MARKHAM ON L3R 4B6	GEN

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No:	ON1338120	**Choice of Contact:**	
Approval Years:	94,95	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6571
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	CAMERA/PHOTO. SUPPLY		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

73	**17 of 116**	**S/291.1**	**69.9 / -1.00**	**CAREER CANADA COLLEGE** **1200 ST. LAURENT BOULEVARD SUITE 261** **OTTAWA ON**	**GEN**

Generator Info

Generator No:	ON1776701	**Choice of Contact:**	
Approval Years:	94,95,96,97,98	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	8599
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	OTHER EDUC. SERV.		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

73	**18 of 116**	**S/291.1**	**69.9 / -1.00**	**FORZANI GROUP LTD., THE** **SPORT CHEK, ST. LAURENT MALL 1200 ST. LAURENT BOULEVARD** **OTTAWA ON K1K 3B8**	**GEN**

Generator Info

Generator No:	ON2010401	**Choice of Contact:**	
Approval Years:	95,96,97,98	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6541
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	SPORTING GOODS STORE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

73	**19 of 116**	**S/291.1**	**69.9 / -1.00**	**DEVAN PROPERTIES LTD.** **1200 ST-LAURENT BOULEVARD**	**GEN**

OTTAWA ON K1K 3B8

Generator Info

Generator No:	ON2259500	***Choice of Contact:***	
Approval Years:	97,98,99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	7512
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	NON-RES. BLDG. OPER.		

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

73	***20 of 116***	***S/291.1***	***69.9 / -1.00***	***CAREER CANADA COLLEGE*** ***1200 ST. LAURENT BOULEVARD, SUITE 261*** ***OTTAWA ON***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON1776701	***Choice of Contact:***	
Approval Years:	99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	8599
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	OTHER EDUC. SERV.		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

73	***21 of 116***	***S/291.1***	***69.9 / -1.00***	***SPORT CHEK*** ***ST. LAURENT MALL 1200 ST. LAURENT BOULEVARD*** ***OTTAWA ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON2010401	***Choice of Contact:***	
Approval Years:	99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6541
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	SPORTING GOODS STORE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

73	***22 of 116***	***S/291.1***	***69.9 / -1.00***	***SHOPPERS DRUG MART*** ***1200 ST. LAURENT BOULEVARD*** ***OTTAWA ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON2530720	***Choice of Contact:***	
Approval Years:	99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6031
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHARMACIES		

Waste Detail(s)

Waste Class:	261

Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

73	*23 of 116*	*S/291.1*	*69.9 / -1.00*	***CAREER CANADA COLLEGE*** ***1200 ST. LAURENT BOULEVARD, SUITE 261*** ***Unit 261*** ***OTTAWA ON K1K 3B8***	*GEN*

Generator Info

Generator No: ON1776701
Approval Years: 02
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

73	*24 of 116*	*S/291.1*	*69.9 / -1.00*	***7139490 ONTARIO LIMITED*** ***1200 LAURENT BLVD.*** ***OTTAWA ON K1K 3B8***	*GEN*

Generator Info

Generator No: ON2259500
Approval Years: 02,03,04
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

73	*25 of 116*	*S/291.1*	*69.9 / -1.00*	***CDI COLLEGE*** ***1200 ST. LAURENT BOULEVARD, SUITE 261*** ***OTTAWA ON***	*GEN*

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON1776701	***Choice of Contact:***	
Approval Years:	03,04,05	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	611710
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Educational Support Services		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

73	***26 of 116***	***S/291.1***	***69.9 / -1.00***	***713949 ONTARIO LIMITED 1200 ST LAURENT BLVD OTTAWA ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON9634909	***Choice of Contact:***	
Approval Years:	04,05,06,07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	121
Waste Class Name:	ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

73 | ***27 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***IAN MCNEIL PHARMACIES INC***
1200 ST LAURENT BLVD
OTTAWA ON K1K 3B8 | ***PES***

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

73 | ***28 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***SHOPPERS DRUG MART#0621(ST. LAURENT SHOPPING CENTRE)***
1200 ST. LAURENT BLVD
OTTAWA ON K1K 3B8 | ***PES***

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PDF URL:

---

73 | **29 of 116** | **S/291.1** | **69.9 / -1.00** | **Canadian Waste Management<UNOFFICIAL>** | **SPL**
1200 St. Laurent St.
Ottawa ON

Ref No: 8753-658LKK
Year:
Incident Dt: 9/27/2004
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/27/2004
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Ottawa
Nearest Watercourse:
Site Name: ST. LAURENT SHOPPING CENTRE COMPACTOR<UNOFFICIAL>
Site Address:
Site Region: Eastern
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Canadian Waste Management<UNOFFICIAL>
Client Type:
Source Type:
Incident Cause: Pipe Or Hose Leak
Incident Preceding Spill:
Incident Reason: Unknown - Reason not determined
Incident Summary: Canadian Waste: Compactor H oil leak to CB
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Other Impact(s); Surface Water Pollution
Contaminant Qty: 4.5 L
Contaminant Qty 1:
Contaminant Unit: L
Contaminant Code: 15
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Water
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Oil
Impact to Health:
Agency Involved:

---

73 | **30 of 116** | **S/291.1** | **69.9 / -1.00** | **CDI COLLEGE** | **GEN**
1200 ST. LAURENT BLVD. Unit 19
OTTAWA ON K1K 3B8

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON1776701	***Choice of Contact:***	
Approval Years:	06	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	611690
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Schools and Instruction		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

73	***31 of 116***	***S/291.1***	***69.9 / -1.00***	***Everest College of Business*** ***1200 ST. LAURENT BLVD. Unit 19*** ***OTTAWA ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON1776701	***Choice of Contact:***	
Approval Years:	07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	611690
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Schools and Instruction		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

73	***32 of 116***	***S/291.1***	***69.9 / -1.00***	***Lens Crafters #939*** ***1200 St. Laurent Blvd*** ***Ottawa ON K1K3B8***	***GEN***

Generator Info

Generator No:	ON8845420	***Choice of Contact:***	
Approval Years:	07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	446130
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Optical Goods Stores		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

73 | ***33 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***IAN MCNEIL PHARMACIES INC***
1200 ST LAURENT BLVD
OTTAWA ON K1K3B8 | ***PES***

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

73 | ***34 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***TLM PHARMACIES INC.***
1200 ST. LAURENT BLVD
OTTAWA ON K1K3B3 | ***PES***

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

73 | ***35 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***713949 Ontario Limited***
1200 St. Laurent Boulevard Ottawa K1K 3B8
CITY OF OTTAWA
ON | ***EBR***

EBR Registry No: 011-4959
Ministry Ref No: 4424-8MQJ5G
Notice Type: Instrument Decision
Notice Stage:
Notice Date: May 01, 2013

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:

Proposal Date: November 07, 2011 ***Site Location Map:***
Year: 2011
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: 713949 Ontario Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 55 City Center Drive , 1000, Mississauga Ontario, Canada L5B 1M3
Comment Period:
URL:
Summary:

Site Location Details:

1200 St. Laurent Boulevard Ottawa K1K 3B8 CITY OF OTTAWA

73	***36 of 116***	***S/291.1***	***69.9 / -1.00***	***Everest College of Business*** ***1200 ST. LAURENT BLVD. Unit 19*** ***OTTAWA ON***	***GEN***

Generator Info

Generator No: ON1776701 ***Choice of Contact:***
Approval Years: 2009 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 611690
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Schools and Instruction

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

73	***37 of 116***	***S/291.1***	***69.9 / -1.00***	***The Forzani Group*** ***1200 St. Laurent Blvd. Unit# Y005*** ***Ottawa ON***	***GEN***

Generator Info

Generator No: ON6481594 ***Choice of Contact:***
Approval Years: 2009 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 451110
Country:
Co Admin:
Phone No Admin:
SIC Description: Sporting Goods Stores

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	38 of 116	S/291.1	69.9 / -1.00	Lens Crafters #939 1200 St. Laurent Blvd Ottawa ON	GEN

Generator Info

Generator No:	ON8845420	**Choice of Contact:**	
Approval Years:	2009	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	446130
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Optical Goods Stores		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	39 of 116	S/291.1	69.9 / -1.00	713949 ONTARIO LIMITED 1200 ST LAURENT BLVD OTTAWA ON	GEN

Generator Info

Generator No:	ON9634909	**Choice of Contact:**	
Approval Years:	2009	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	531100
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	121
Waste Class Name:	ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

73 ***40 of 116*** ***S/291.1*** ***69.9 / -1.00*** ***CINDY CHANGOOR PHARMACY LTD***
1200 ST LAURENT BLVD
OTTAWA ON K1K 3B8 ***PES***

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

73 ***41 of 116*** ***S/291.1*** ***69.9 / -1.00*** ***713949 Ontario Limited***
1200 St. Laurent Blvd
Ottawa ON ***ECA***

Approval No: 2562-96MNV7
Approval Date: 23-APR-13
Status: Approved
Record Type:
Link Source:
SWP Area Name:
Approval Type:

MOE District:
City: Ottawa
Longitude:
Latitude:
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Project Type: Air/Noise
Business Name:
Address:
Full Address:
Full PDF Link:
PDF Site Location:

---

73 | **42 of 116** | **S/291.1** | **69.9 / -1.00**

The Forzani Group
1200 St. Laurent Blvd. Unit# Y005
Ottawa ON

GEN

Generator Info

Generator No: ON6481594
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Sporting Goods Stores

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 451110

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

73 | **43 of 116** | **S/291.1** | **69.9 / -1.00**

713949 ONTARIO LIMITED
1200 ST LAURENT BLVD
OTTAWA ON

GEN

Generator Info

Generator No: ON9634909
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 531100

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

73 | ***44 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***Lens Crafters #939***
1200 St. Laurent Blvd
Ottawa ON | ***GEN***

Generator Info

Generator No: ON8845420
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Optical Goods Stores

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 446130

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

73 | ***45 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***Everest College of Business***
1200 ST. LAURENT BLVD. Unit 19
OTTAWA ON | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON1776701	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	611690
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Schools and Instruction		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

73	***46 of 116***	***S/291.1***	***69.9 / -1.00***	***CINDY CHANGOOR PHARMACY LIMITED*** ***1200 ST LAURENT BLVD*** ***OTTAWA ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON6759537	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	414510
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

73	***47 of 116***	***S/291.1***	***69.9 / -1.00***	***The Forzani Group*** ***1200 St. Laurent Blvd. Unit# Y005*** ***Ottawa ON***	***GEN***

Generator Info

Generator No:	ON6481594	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	451110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Sporting Goods Stores		

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

73	***48 of 116***	***S/291.1***	***69.9 / -1.00***	***713949 ONTARIO LIMITED*** ***1200 ST LAURENT BLVD*** ***OTTAWA ON***	***GEN***

Generator Info

Generator No: ON9634909
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 531100

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

73	**49 of 116**	**S/291.1**	**69.9 / -1.00**	**Lens Crafters #939** **1200 St. Laurent Blvd** **Ottawa ON**	**GEN**

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON8845420
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Optical Goods Stores

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 446130

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

73	50 of 116	S/291.1	69.9 / -1.00	Everest College of Business 1200 ST. LAURENT BLVD. Unit 19 OTTAWA ON	GEN

Generator Info

Generator No: ON1776701
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Schools and Instruction

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611690

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

73	51 of 116	S/291.1	69.9 / -1.00	TLM PHARMACIES INC. 1200 ST. LAURENT BLVD OTTAWA ON K1K 3B3	PES

Detail Licence No: 23-01-14744-0
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: LIMITED
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PDF URL:

---

73 | **52 of 116** | **S/291.1** | **69.9 / -1.00** | **CINDY CHANGOOR PHARMACY LTD**
1200 ST LAURENT BLVD
OTTAWA ON K1K3B8 | **PES**

Detail Licence No:		**Operator Box:**	
Licence No:	16026	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	7457015
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

73 | **53 of 116** | **S/291.1** | **69.9 / -1.00** | **Lens Crafters #939**
1200 St. Laurent Blvd
Ottawa ON | **GEN**

Generator Info

Generator No:	ON8845420	**Choice of Contact:**	
Approval Years:	2013	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	446130
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	OPTICAL GOODS STORES		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

---

73 | **54 of 116** | **S/291.1** | **69.9 / -1.00** | **City of Ottawa**
1200 Saint Laurent Boulevard | **SPL**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Ottawa ON	

Ref No:	6110-8YGVW8	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	25-SEP-12	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	25-SEP-12	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Bus Route<UNOFFICIAL>		
Site Address:	1200 Saint Laurent Boulevard		
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	City of Ottawa		
Client Type:			
Source Type:			
Incident Cause:	Other		
Incident Preceding Spill:			
Incident Reason:	Other		
Incident Summary:	City of Ottawa: Glycol from bus to road, clnd		
Environment Impact:	Not Anticipated		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	100 L		
Contaminant Qty 1:	100		
Contaminant Unit:	L		
Contaminant Code:	24		
Contaminant Name:	GLYCOL/WATER SOLUTION		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Unknown		
SAC Action Class:	Land Spills		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

73	55 of 116	S/291.1	69.9 / -1.00	CINDY CHANGOOR PHARMACY LIMITED 1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No:	ON6759537	**Choice of Contact:**	
Approval Years:	2012	**Contaminated Fac:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors

MHSW Facility:
SIC Code: 414510

---

73 | ***56 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***713949 ONTARIO LIMITED***
1200 ST LAURENT BLVD
OTTAWA ON K1K 3B8 | ***GEN***

Generator Info

Generator No: ON9634909
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 531100

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

73 | ***57 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***Herzing College***
1200 St. Laurent Blvd. Suite 408
Ottawa ON | ***GEN***

Generator Info

Generator No: ON5006290
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Community Colleges and C.E.G.E.P.s

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611210

---

73 | ***58 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***Everest College of Business***
1200 ST. LAURENT BLVD. Unit 19
OTTAWA ON K1K 3B8 | ***GEN***

Generator Info

Generator No: ON1776701
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Schools and Instruction

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611690

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

73 | ***59 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***CINDY CHANGOOR PHARMACY LIMITED***
1200 ST LAURENT BLVD
OTTAWA ON | ***GEN***

Generator Info

Generator No: ON6759537
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PHARMACEUTICALS AND PHARMACY SUPPLIES WHOLESALER-DISTRIBUTORS

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 414510

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

---

73 | ***60 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***The Forzani Group*** ***1200 St. Laurent Blvd. Unit# Y005*** ***Ottawa ON*** | ***GEN***

Generator Info

Generator No: ON6481594
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: SPORTING GOODS STORES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 451110

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

73 | ***61 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***Herzing College*** ***1200 St. Laurent Blvd. Suite 408*** ***Ottawa ON*** | ***GEN***

Generator Info

Generator No: ON5006290
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611210

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

73 | ***62 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***713949 ONTARIO LIMITED*** ***1200 ST LAURENT BLVD*** ***OTTAWA ON*** | ***GEN***

Generator Info

Generator No: ON9634909
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 531100

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

73	63 of 116	S/291.1	69.9 / -1.00	**Everest College of Business** **1200 ST. LAURENT BLVD. Unit 19** **OTTAWA ON**	GEN

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON1776701
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ALL OTHER SCHOOLS AND INSTRUCTION

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611690

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

73 | **64 of 116** | **S/291.1** | **69.9 / -1.00** | **1200 St. Laurent Boulevard Ottawa ON** | **SPL**

Ref No: 8105-ADMP4S
Year:
Incident Dt: 9/8/2016
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/9/2016
Dt Document Closed:
Site No: NA
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: St. Laurent Station<UNOFFICIAL>
Site Address: 1200 St. Laurent Boulevard
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 5030031
Easting: 450000
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill: Unknown / N/A
Incident Reason: Unknown / N/A
Incident Summary: OLRT: 2 L of oil to railroad track ballast rock
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 2 L
Contaminant Qty 1: 2
Contaminant Unit: L
Contaminant Code: 15
Contaminant Name: OIL (PETROLEUM BASED, NOT SPECIFIED)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	65 of 116	S/291.1	69.9 / -1.00	1200 St. Laurent Blvd. Ottawa ON	SPL

Ref No:	4856-ADLNYN	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/7/2016	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/8/2016	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	

Site No:	NA
MOE Response:	
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	St. Laurent Stn. west end<UNOFFICIAL>
Site Address:	1200 St. Laurent Blvd.
Site Region:	
Site Municipality:	Ottawa
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Unknown / N/A
Incident Summary:	OLRT:1/2 L diesel fuel to ballast rock; clnd
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0.5 L
Contaminant Qty 1:	0.5
Contaminant Unit:	L
Contaminant Code:	13
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	66 of 116	S/291.1	69.9 / -1.00	1200 St Laurent Ave Ottawa ON	SPL

Ref No:	2348-A9KSEQ	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2016/05/02	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2016/05/02	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:	Unknown Name		
Site Name:	Catch Basin<UNOFFICIAL>		
Site Address:	1200 St Laurent Ave		
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	5030031		
Easting:	450000		
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Incident Reason:	Equipment Failure		
Incident Summary:	Leak 1 L hydraulic fluid to CB, cleaning		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	1 L		
Contaminant Qty 1:	1		
Contaminant Unit:	L		
Contaminant Code:	15		
Contaminant Name:	HYDRAULIC OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Surface Water		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Unknown / N/A		
SAC Action Class:	Watercourse Spills		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	67 of 116	S/291.1	69.9 / -1.00	713949 Ontario Limited 1200 St. Laurent Blvd Ottawa ON K1K 3B8	ECA

Approval No:	2562-96MNV7	**MOE District:**	Ottawa
Approval Date:	2013-04-23	**City:**	
Status:	Approved	**Longitude:**	-75.636734
Record Type:	ECA	**Latitude:**	45.42296

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	713949 Ontario Limited		
Address:	1200 St. Laurent Blvd		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4424-8MQJ5G-14.pdf		
PDF Site Location:			

73	68 of 116	S/291.1	69.9 / -1.00	713949 ONTARIO LIMITED 1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No:	ON9634909	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	531100
Country:	Canada		
Co Admin:	Krista Stemmler		
Phone No Admin:	613-739-1070 Ext.220		
SIC Description:	531100		

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

73	69 of 116	S/291.1	69.9 / -1.00	**St. Laurent Dental Center** **1200 St. Laurent Blvd. box 203** **Ottawa ON K1K 3B8**	GEN

Generator Info

Generator No: ON5012892
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Kristine Preston
Phone No Admin: 613 744 6611 Ext.204
SIC Description: OFFICES OF DENTISTS
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621210

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

73	70 of 116	S/291.1	69.9 / -1.00	**FGL SPORTS LIMITED** **1200 St. Laurent Blvd. Unit# Y005** **Ottawa ON K1K 3B8**	GEN

Generator Info

Generator No: ON6481594
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: SPORTING GOODS STORES
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 451110

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

73	71 of 116	S/291.1	69.9 / -1.00	**Everest College of Business** **1200 ST. LAURENT BLVD. Unit 19** **OTTAWA ON K1K 3B8**	GEN

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No:	ON1776701	**Choice of Contact:**	CO_ADMIN
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	611690
Country:	Canada		
Co Admin:	Cindy Moreau		
Phone No Admin:	613-236-8282 Ext.		
SIC Description:	ALL OTHER SCHOOLS AND INSTRUCTION		

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

73 | ***72 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***Herzing College***
1200 St. Laurent Blvd. Suite 408
Ottawa ON K1K 3B8 | ***GEN***

Generator Info

Generator No:	ON5006290	**Choice of Contact:**	CO_ADMIN
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	611210
Country:	Canada		
Co Admin:	Leroux Stephanie		
Phone No Admin:	613-742-8099 Ext.11231		
SIC Description:	611210		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

---

73 | ***73 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***The Forzani Group***
1200 St. Laurent Blvd. Unit# Y005
Ottawa ON K1K 3B8 | ***GEN***

Generator Info

Generator No:	ON6481594	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	451110
Country:	Canada		
Co Admin:			
Phone No Admin:			

SIC Description: SPORTING GOODS STORES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	74 of 116	S/291.1	69.9 / -1.00	713949 ONTARIO LIMITED 1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No: ON9634909
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Krista Stemmler
Phone No Admin: 613-739-1070 Ext.220
SIC Description: 531100

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 531100

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	75 of 116	S/291.1	69.9 / -1.00	Cindy Changoor Pharmacy Limited (641) 1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	GEN

Generator Info

Generator No: ON2971904
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Nastran Najafi-Fard
Phone No Admin: 416-493-1220 Ext.3218
SIC Description: 446110

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 446110

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	76 of 116	S/291.1	69.9 / -1.00	Cindy Changoor Pharmacy Limited (621) 1200 ST. LAURENT BLVD Ottawa ON K1K 3B8	GEN

Generator Info

Generator No: ON2971904
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Nastran Najafi-Fard
Phone No Admin: 416-493-1220 Ext.3218
SIC Description: 446110

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 446110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	77 of 116	S/291.1	69.9 / -1.00	Herzing College 1200 St. Laurent Blvd. Suite 408 Ottawa ON K1K 3B8	GEN

Generator Info

Generator No:	ON5006290	**Choice of Contact:**	CO_ADMIN
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	611210
Country:	Canada		
Co Admin:	Sherri Calvin		
Phone No Admin:	613-742-8099 Ext.		
SIC Description:	611210		

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	78 of 116	S/291.1	69.9 / -1.00	Lens Crafters #939 1200 St. Laurent Blvd Ottawa ON K1K3B8	GEN

Generator Info

Generator No:	ON8845420	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	446130
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	OPTICAL GOODS STORES		

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	79 of 116	S/291.1	69.9 / -1.00	Lens Crafters #939 1200 St. Laurent Blvd Ottawa ON K1K3B8	GEN

Generator Info

Generator No:	ON8845420	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	446130
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	OPTICAL GOODS STORES		

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	80 of 116	S/291.1	69.9 / -1.00	St. Laurent Dental Center 1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	GEN

Generator Info

Generator No:	ON5012892	***Choice of Contact:***	CO_ADMIN
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621210
Country:	Canada		
Co Admin:	Kristine Preston		
Phone No Admin:	613 744 6611 Ext.204		
SIC Description:	OFFICES OF DENTISTS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	81 of 116	S/291.1	69.9 / -1.00	Lens Crafters #939 1200 St. Laurent Blvd Ottawa ON K1K3B8	GEN

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON8845420
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: OPTICAL GOODS STORES
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 446130

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

73	82 of 116	S/291.1	69.9 / -1.00	**Herzing College** **1200 St. Laurent Blvd. Suite 408** **Ottawa ON K1K 3B8**	GEN

Generator Info

Generator No: ON5006290
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Leroux Stephanie
Phone No Admin: 613-742-8099 Ext.11231
SIC Description: 611210
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 611210

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

73	83 of 116	S/291.1	69.9 / -1.00	**St. Laurent Dental Center** **1200 St. Laurent Blvd. box 203** **Ottawa ON K1K 3B8**	GEN

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON5012892
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Kristine Preston
Phone No Admin: 613 744 6611 Ext.204
SIC Description: OFFICES OF DENTISTS
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621210

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

73	84 of 116	S/291.1	69.9 / -1.00	**Everest College of Business** **1200 ST. LAURENT BLVD. Unit 19** **OTTAWA ON K1K 3B8**	GEN

Generator Info

Generator No: ON1776701
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Cindy Moreau
Phone No Admin: 613-236-8282 Ext.
SIC Description: ALL OTHER SCHOOLS AND INSTRUCTION
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 611690

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

73	85 of 116	S/291.1	69.9 / -1.00	**CINDY CHANGOOR PHARMACY LIMITED** **1200 ST LAURENT BLVD** **OTTAWA ON K1K 3B8**	GEN

Generator Info

Generator No: ON6759537
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: PHARMACEUTICALS AND PHARMACY SUPPLIES WHOLESALER-DISTRIBUTORS
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 414510

Waste Detail(s)

Waste Class: 242

Waste Class Name: HALOGENATED PESTICIDES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	86 of 116	S/291.1	69.9 / -1.00	713949 ONTARIO LIMITED 1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No:	ON9634909	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2014	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	531100
Country:	Canada		
Co Admin:	Krista Stemmler		
Phone No Admin:	613-739-1070 Ext.220		
SIC Description:	531100		

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	87 of 116	S/291.1	69.9 / -1.00	The Forzani Group 1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	GEN

Generator Info

Generator No:	ON6481594	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2014	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	451110
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	SPORTING GOODS STORES		

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	88 of 116	S/291.1	69.9 / -1.00	FGL SPORTS LIMITED 1200 St. Laurent Blvd. Unit# Y005 Ottawa ON K1K 3B8	GEN

Generator Info

Generator No:	ON6481594	**Choice of Contact:**	
Approval Years:	As of Dec 2018	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	89 of 116	S/291.1	69.9 / -1.00	St. Laurent Dental Center 1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8	GEN

Generator Info

Generator No:	ON5012892	**Choice of Contact:**	
Approval Years:	As of Dec 2018	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	90 of 116	S/291.1	69.9 / -1.00	**Herzing College St. Laurent Blvd Ottawa** **1200 St. Laurent Blvd. Suite 408** **Ottawa ON K1K 3B8**	GEN

Generator Info

Generator No:	ON5006290	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:	255	***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	91 of 116	S/291.1	69.9 / -1.00	**Cindy Changoor Pharmacy Limited (621)** **1200 ST. LAURENT BLVD** **Ottawa ON K1K 3B8**	GEN

Generator Info

Generator No:	ON2971904	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	92 of 116	S/291.1	69.9 / -1.00	713949 ONTARIO LIMITED 1200 ST LAURENT BLVD OTTAWA ON K1K 3B8	GEN

Generator Info

Generator No:	ON9634909	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	121 C
Waste Class Name:	Alkaline slutions - containing heavy metals

Waste Detail(s)

Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	146 T
Waste Class Name:	Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class:	212 I
Waste Class Name:	Aliphatic solvents and residues

Waste Detail(s)

Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues

Waste Detail(s)

Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

73 | **93 of 116** | **S/291.1** | **69.9 / -1.00** | **1200 St Laurent Blvd Ottawa ON K1K 4H4** | **EHS**

Order No: 20181001022
Status: C
Report Type: Custom Report
Report Date: 16-OCT-18
Date Received: 01-OCT-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .1
X: -75.640113
Y: 45.422088

---

73 | **94 of 116** | **S/291.1** | **69.9 / -1.00** | **IAN MCNEIL PHARMACIES INC 1200 ST LAURENT BLVD OTTAWA ON K1K3B8** | **PES**

Detail Licence No:
Licence No: 13683
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 7957015
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

73 | **95 of 116** | **S/291.1** | **69.9 / -1.00** | **TLM PHARMACIES INC. 1200 ST. LAURENT BLVD OTTAWA ON K1K3B3** | **PES**

Detail Licence No:
Licence No: 14744
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 7457015
Operator Ext:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

73 | **96 of 116** | **S/291.1** | **69.9 / -1.00** | **SHOPPERS DRUG MART#0621(ST. LAURENT SHOPPING CENTRE)**
1200 ST. LAURENT BLVD
OTTAWA ON K1K3B8 | **PES**

Detail Licence No:		**Operator Box:**	
Licence No:	13238	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	7457015
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

73 | **97 of 116** | **S/291.1** | **69.9 / -1.00** | **St. Laurent Dental Center**
1200 St. Laurent Blvd. box 203
Ottawa ON K1K 3B8 | **GEN**

Generator Info

Generator No:	ON5012892	**Choice of Contact:**	
Approval Years:	As of Jul 2020	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

---

73 | **98 of 116** | **S/291.1** | **69.9 / -1.00** | **FGL SPORTS LIMITED**
1200 St. Laurent Blvd. Unit# Y005
Ottawa ON K1K 3B8 | **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON6481594	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues

73	***99 of 116***	***S/291.1***	***69.9 / -1.00***	***Cindy Changoor Pharmacy Limited (621)*** ***1200 ST. LAURENT BLVD*** ***Ottawa ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON2971904	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	Pharmaceuticals

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

73	***100 of 116***	***S/291.1***	***69.9 / -1.00***	***713949 ONTARIO LIMITED*** ***1200 ST LAURENT BLVD*** ***OTTAWA ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON9634909	***Choice of Contact:***	
Approval Years:	As of Oct 2019	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

2017 Generator Info

Gen No: ON9634909
ID: 37645
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 531100
NAICS Code2:
NAICS Code3:
Gen Name: 713949 ONTARIO LIMITED
Gen Div:
Gen Op Name: 713949 ONTARIO LIMITED
Gen Op Div:
Site Adrs1: 1200 ST LAURENT BLVD
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: OTTAWA
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: Benoit Gauthier
Co Admin: Krista Stemmler
Choice of Contact: CO_OFFICIAL
Phone No Official: (613) 745-6850 Ext.
Phone No Admin: 613-739-1070 Ext.220
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2017 Generator Manifest

ID: 66455
Generator No: ON9634909
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 750.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 2
District: 402

2018 Generator Info

Gen No: ON9634909
ID: 38384
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 531100
NAICS Code2:
NAICS Code3:
Gen Name: 713949 ONTARIO LIMITED
Gen Div:
Gen Op Name: 713949 ONTARIO LIMITED
Gen Op Div:
Site Adrs1: 1200 ST LAURENT BLVD
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: OTTAWA
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: Benoit Gauthier
Co Admin: Krista Stemmler
Choice of Contact: CO_OFFICIAL
Phone No Official: (613) 745-6850 Ext.
Phone No Admin: 613-739-1070 Ext.220
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2018 Generator Manifest

ID:	67017	***Sum Received Qty:***	20.0
Generator No:	ON9634909	***Waste Class Name:***	ALIPHATIC SOLVENTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	I	***District:***	402
Waste Code:	212		

2018 Generator Manifest

ID:	67016	***Sum Received Qty:***	100.0
Generator No:	ON9634909	***Waste Class Name:***	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	C	***District:***	402
Waste Code:	122		

2019 Generator Info

Gen No:	ON9634909	***Choice of Contact:***	CO_OFFICIAL
ID:	38956	***Phone No Official:***	(613) 745-6850 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613-739-1070 Ext.220
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	531100	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	713949 ONTARIO LIMITED		
Gen Div:			
Gen Op Name:	713949 ONTARIO LIMITED		
Gen Op Div:			
Site Adrs1:	1200 ST LAURENT BLVD		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	OTTAWA		
Province Out:			
Site Postal Code:	K1K 3B8		
Site Country:	Canada		
Co Official:	Benoit Gauthier		
Co Admin:	Krista Stemmler		

2019 Generator Manifest

ID:	67058	***Sum Received Qty:***	376.0
Generator No:	ON9634909	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	I	***District:***	402
Waste Code:	145		

2019 Generator Manifest

ID:	67059	***Sum Received Qty:***	17780.0
Generator No:	ON9634909	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	3
Waste Char:	L	***District:***	402
Waste Code:	251		

73	***101 of 116***	***S/291.1***	***69.9 / -1.00***	***Herzing College*** ***1200 St. Laurent Blvd. Suite 408*** ***Ottawa ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON5006290	***Choice of Contact:***	
Approval Years:	As of Oct 2019	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:	255	***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	Pharmaceuticals

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

2017 Generator Info

Gen No:	ON5006290	***Choice of Contact:***	CO_ADMIN
ID:	19862	***Phone No Official:***	613-742-8099 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613-742-8099 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	611210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Herzing College		
Gen Div:	St. Laurent Blvd Ottawa		
Gen Op Name:	Herzing College		
Gen Op Div:	St. Laurent Blvd Ottawa		
Site Adrs1:	1200 St. Laurent Blvd.		
Site Bldg:			
Site Pobox:	255		
Province In:	ONTARIO		
Site Adrs2:	Suite 408		
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K1K 3B8		
Site Country:	Canada		
Co Official:	Sherri Calvin		
Co Admin:	Sherri Calvin		

2018 Generator Info

Gen No:	ON5006290	***Choice of Contact:***	CO_ADMIN
ID:	19966	***Phone No Official:***	613-742-8099 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613-742-8099 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	611210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Herzing College		
Gen Div:	St. Laurent Blvd Ottawa		
Gen Op Name:	Herzing College		
Gen Op Div:	St. Laurent Blvd Ottawa		
Site Adrs1:	1200 St. Laurent Blvd.		
Site Bldg:			

Site Pobox:	255
Province In:	ONTARIO
Site Adrs2:	Suite 408
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 3B8
Site Country:	Canada
Co Official:	Sherri Calvin
Co Admin:	Sherri Calvin

2019 Generator Info

Gen No:	ON5006290	**Choice of Contact:**	CO_ADMIN
ID:	19990	**Phone No Official:**	613-742-8099 Ext.
Contaminated Fac:	N	**Phone No Admin:**	613-742-8099 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	611210	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			

Gen Name:	Herzing College
Gen Div:	St. Laurent Blvd Ottawa
Gen Op Name:	Herzing College
Gen Op Div:	St. Laurent Blvd Ottawa
Site Adrs1:	1200 St. Laurent Blvd.
Site Bldg:	
Site Pobox:	255
Province In:	ONTARIO
Site Adrs2:	Suite 408
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 3B8
Site Country:	Canada
Co Official:	Sherri Calvin
Co Admin:	Sherri Calvin

---

73 | ***102 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***FGL SPORTS LIMITED***
1200 St. Laurent Blvd. Unit# Y005
Ottawa ON K1K 3B8 | ***GEN***

Generator Info

Generator No:	ON6481594	**Choice of Contact:**	
Approval Years:	As of Nov 2021	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues

---

73 | ***103 of 116*** | ***S/291.1*** | ***69.9 / -1.00*** | ***LensCrafters #939***
1200 St. Laurent Blvd
Ottawa ON K1K3B8 | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON8845420	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues

73	***104 of 116***	***S/291.1***	***69.9 / -1.00***	***St. Laurent Dental Center*** ***1200 St. Laurent Blvd. box 203*** ***Ottawa ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON5012892	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

73	***105 of 116***	***S/291.1***	***69.9 / -1.00***	***Ben Gunter Pharmacy Inc*** ***1200 ST. LAURENT BLVD*** ***Ottawa ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON2971904	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		

Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	106 of 116	S/291.1	69.9 / -1.00	Morguard Real Estate Investment Trust 1200 St. Laurent Blvd. Ottawa ON	GEN

Generator Info

Generator No: ON7569372
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Generator Info as of Dec 2024

Generator No: ON7569372
Generator Company Name: Morguard Real Estate Investment Trust
Street: 1200 St. Laurent Blvd.
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K3B8
Waste Class: 212 L, 331 I, 122 I, 263 I, 212 I, 145 I, 122 C, 252 L, 212 L, 251 L

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 331 - WASTE COMPRESSED GASES; 122 - ALKALINE WASTES - OTHER METALS; 263 - ORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 122 - ALKALINE WASTES - OTHER METALS; 252 - WASTE OILS & LUBRICANTS; 212 - ALIPHATIC SOLVENTS; 251 - OIL SKIMMINGS & SLUDGES

Generator Info as of Dec 2024

Generator No: ON7569372
Generator Company Name: Morguard Real Estate Investment Trust
Street: 1200 St. Laurent Blvd.
City: Ottawa
Province State: Ontario

Country: Canada
Postal Code: K1K3B8
Waste Class: 331 I,122 I,263 I,212 I,145 I,122 C,252 L,212 L,251 L

Waste Class Decoded:

331 - WASTE COMPRESSED GASES; 122 - ALKALINE WASTES - OTHER METALS; 263 - ORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 122 - ALKALINE WASTES - OTHER METALS; 252 - WASTE OILS & LUBRICANTS; 212 - ALIPHATIC SOLVENTS; 251 - OIL SKIMMINGS & SLUDGES

2021 Generator Info

Gen No:	ON7569372	**Choice of Contact:**	CO_OFFICIAL
ID:	30824	**Phone No Official:**	613-745-2383 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	452999	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			

Gen Name: Morguard Real Estate Investment Trust
Gen Div:
Gen Op Name: Morguard Real Estate Investment Trust
Gen Op Div:
Site Adrs1: 1200 St. Laurent Blvd.
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: Patric Provencher
Co Admin:

2021 Generator Manifest

ID:	55223	**Sum Received Qty:**	4750.0
Generator No:	ON7569372	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	402
Waste Code:	251		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	107 of 116	S/291.1	69.9 / -1.00	**Shoppers Drug Mart** **1200 ST. LAURENT BLVD** **Ottawa ON**	GEN

Generator Info

Generator No:	ON2971904	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Generator Info as of Dec 2024

Generator No: ON2971904
Generator Company Name: Shoppers Drug Mart
Street: 1200 ST. LAURENT BLVD
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K3B8
Waste Class: 312 P, 261 A, 252 L, 145 L, 212 L

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS; 252 - WASTE OILS & LUBRICANTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 212 - ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No: ON2971904
Generator Company Name: Shoppers Drug Mart
Street: 1200 ST. LAURENT BLVD
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K3B8
Waste Class: 312 P,261 A

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

2017 Generator Info

Gen No: ON2971904
ID: 12063
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 446110
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_ADMIN
Phone No Official: 613-745-7015 Ext.
Phone No Admin: 416-493-1220 Ext.3218
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Gen Name: Cindy Changoor Pharmacy Limited (621)
Gen Div:
Gen Op Name: Shoppers Drug Mart 621
Gen Op Div:
Site Adrs1: 1200 ST. LAURENT BLVD
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8

Site Country: Canada
Co Official: Cindy Nicole Giby
Co Admin: Nastran Najafi-Fard

2018 Generator Info

Gen No:	ON2971904	***Choice of Contact:***	CO_ADMIN
ID:	11860	***Phone No Official:***	613-745-7015 Ext.
Contaminated Fac:	N	***Phone No Admin:***	416-493-1220 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	446110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name: Cindy Changoor Pharmacy Limited (621)
Gen Div:
Gen Op Name: Shoppers Drug Mart 621
Gen Op Div:
Site Adrs1: 1200 ST. LAURENT BLVD
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: Cindy Nicole Giby
Co Admin: Pharmacy Operations Development

2019 Generator Info

Gen No:	ON2971904	***Choice of Contact:***	CO_ADMIN
ID:	11577	***Phone No Official:***	613-745-7015 Ext.
Contaminated Fac:	N	***Phone No Admin:***	416-493-1220 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	446110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name: Cindy Changoor Pharmacy Limited (621)
Gen Div:
Gen Op Name: Shoppers Drug Mart 621
Gen Op Div:
Site Adrs1: 1200 ST. LAURENT BLVD
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: Cindy Nicole Giby
Co Admin: Pharmacy Operations Development

2020 Generator Info

Gen No:	ON2971904	***Choice of Contact:***	CO_ADMIN
ID:	11220	***Phone No Official:***	613-745-7015 Ext.
Contaminated Fac:	N	***Phone No Admin:***	416-493-1220 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	446110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	Ben Gunter Pharmacy Inc
Gen Div:	
Gen Op Name:	Shoppers Drug Mart 621
Gen Op Div:	
Site Adrs1:	1200 ST. LAURENT BLVD
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 3B8
Site Country:	Canada
Co Official:	Ben Gunter
Co Admin:	Pharmacy Operations Development

2020 Generator Manifest

ID:	30254	**Sum Received Qty:**	21.2
Generator No:	ON2971904	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	P	**District:**	402
Waste Code:	312		

2021 Generator Info

Gen No:	ON2971904	**Choice of Contact:**	CO_ADMIN
ID:	11047	**Phone No Official:**	613-745-7015 Ext.
Contaminated Fac:	N	**Phone No Admin:**	416-493-1220 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	446110	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			

Gen Name:	Ben Gunter Pharmacy Inc
Gen Div:	
Gen Op Name:	Shoppers Drug Mart 621
Gen Op Div:	
Site Adrs1:	1200 ST. LAURENT BLVD
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 3B8
Site Country:	Canada
Co Official:	Ben Gunter
Co Admin:	Pharmacy Operations Development

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	***108 of 116***	***S/291.1***	***69.9 / -1.00***	***LCBO*** ***540-1200 ST. LAURENT BLVD*** ***Ottawa ON K1K3B8***	***GEN***

Generator Info

Generator No:	ON6013736	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	109 of 116	S/291.1	69.9 / -1.00	EssilorLuxottica of Canada 1200 St. Laurent Blvd Ottawa ON	GEN

Generator Info

Generator No: ON8845420
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No: ON8845420
Generator Company Name: EssilorLuxottica of Canada
Street: 1200 St. Laurent Blvd
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K 3B8
Waste Class: 312 P, 261 A, 252 L, 145 L, 212 L

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS; 252 - WASTE OILS & LUBRICANTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 212 - ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No: ON8845420

Generator Company Name:	EssilorLuxottica of Canada
Street:	1200 St. Laurent Blvd
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1K 3B8
Waste Class:	252 L,145 L,212 L

Waste Class Decoded:

252 - WASTE OILS & LUBRICANTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 212 - ALIPHATIC SOLVENTS

2017 Generator Info

Gen No:	ON8845420	***Choice of Contact:***	CO_OFFICIAL
ID:	34576	***Phone No Official:***	734-521-8119 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	446130	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	Lens Crafters #939
Gen Div:	
Gen Op Name:	Lens Crafters #939
Gen Op Div:	
Site Adrs1:	1200 St. Laurent Blvd
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K3B8
Site Country:	Canada
Co Official:	Carly Doulos
Co Admin:	

2018 Generator Info

Gen No:	ON8845420	***Choice of Contact:***	CO_OFFICIAL
ID:	35234	***Phone No Official:***	734-521-8119 Ext.
Contaminated Fac:	N	***Phone No Admin:***	513-765-6239 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	446130	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	LensCrafters #939
Gen Div:	
Gen Op Name:	LensCrafters #939
Gen Op Div:	
Site Adrs1:	1200 St. Laurent Blvd
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K3B8
Site Country:	Canada
Co Official:	Rachael Griffin
Co Admin:	Jay McDonald

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2021 Generator Info

Gen No:	ON8845420	***Choice of Contact:***	CO_OFFICIAL
ID:	36316	***Phone No Official:***	513-765-4311 Ext.
Contaminated Fac:	N	***Phone No Admin:***	513-765-6239 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	446130	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	LensCrafters #939		
Gen Div:			
Gen Op Name:	LensCrafters #939		
Gen Op Div:			
Site Adrs1:	1200 St. Laurent Blvd		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K1K3B8		
Site Country:	Canada		
Co Official:	Melissa Olberding		
Co Admin:	Jay McDonald		

73	***110 of 116***	***S/291.1***	***69.9 / -1.00***	***St. Laurent Dental Center 1200 St. Laurent Blvd. box 203 Ottawa ON K1K 3B8***	***GEN***

Generator Info

Generator No:	ON5012892	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

2017 Generator Info

Gen No:	ON5012892	***Choice of Contact:***	CO_ADMIN
ID:	19884	***Phone No Official:***	6137446611 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613 744 6611 Ext.204
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	St. Laurent Dental Center		
Gen Div:			
Gen Op Name:	St. Laurent Dental Center		
Gen Op Div:			
Site Adrs1:	1200 St. Laurent Blvd. box 203		
Site Bldg:			
Site Pobox:			

Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 3B8
Site Country:	Canada
Co Official:	David G Campbell
Co Admin:	Kristine Preston

2017 Generator Manifest

ID:	43889	***Sum Received Qty:***	67.0
Generator No:	ON5012892	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	3
Waste Char:	P	***District:***	305
Waste Code:	312		

2018 Generator Info

Gen No:	ON5012892	***Choice of Contact:***	CO_ADMIN
ID:	19991	***Phone No Official:***	6137446611 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613 744 6611 Ext.204
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	St. Laurent Dental Center
Gen Div:	
Gen Op Name:	St. Laurent Dental Center
Gen Op Div:	
Site Adrs1:	1200 St. Laurent Blvd. box 203
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 3B8
Site Country:	Canada
Co Official:	David G Campbell
Co Admin:	Kristine Preston

2018 Generator Manifest

ID:	43823	***Sum Received Qty:***	25.5
Generator No:	ON5012892	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	P	***District:***	305
Waste Code:	312		

2019 Generator Info

Gen No:	ON5012892	***Choice of Contact:***	CO_ADMIN
ID:	20014	***Phone No Official:***	6137446611 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613 744 6611 Ext.204
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	St. Laurent Dental Center
Gen Div:	
Gen Op Name:	St. Laurent Dental Center

Gen Op Div:
Site Adrs1: 1200 St. Laurent Blvd. box 203
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: David G Campbell
Co Admin: Kristine Preston

2019 Generator Manifest

ID: 43362
Generator No: ON5012892
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 41.0
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 2
District: 305

2020 Generator Info

Gen No: ON5012892
ID: 19742
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621210
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_ADMIN
Phone No Official: 6137446611 Ext.
Phone No Admin: 613 744 6611 Ext.204
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402
Gen Name: St. Laurent Dental Center
Gen Div:
Gen Op Name: St. Laurent Dental Center
Gen Op Div:
Site Adrs1: 1200 St. Laurent Blvd. box 203
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: David G Campbell
Co Admin: Kristine Preston

2020 Generator Manifest

ID: 40090
Generator No: ON5012892
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 19.0
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 1
District: 305

2021 Generator Info

Gen No: ON5012892
ID: 19892
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621210
NAICS Code2:
Choice of Contact: CO_ADMIN
Phone No Official: 6137446611 Ext.
Phone No Admin: 613 744 6611 Ext.204
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

NAICS Code3:
Gen Name: St. Laurent Dental Center
Gen Div:
Gen Op Name: St. Laurent Dental Center
Gen Op Div:
Site Adrs1: 1200 St. Laurent Blvd. box 203
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: David G Campbell
Co Admin: Kristine Preston

2021 Generator Manifest

ID:	41433	***Sum Received Qty:***	43.0
Generator No:	ON5012892	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	***111 of 116***	***S/291.1***	***69.9 / -1.00***	***Sport Chek*** ***1200 St. Laurent Blvd.*** ***Ottawa ON***	***GEN***

Generator Info

Generator No:	ON6481594	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No: ON6481594
Generator Company Name: Sport Chek
Street: 1200 St. Laurent Blvd.
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K3B8
Waste Class: 212 L, 331 I, 122 I, 263 I, 212 I, 145 I, 122 C, 252 L, 212 L, 251 L

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 331 - WASTE COMPRESSED GASES; 122 - ALKALINE WASTES - OTHER METALS; 263 - ORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 122 - ALKALINE WASTES - OTHER METALS; 252 - WASTE OILS & LUBRICANTS; 212 - ALIPHATIC SOLVENTS; 251 - OIL SKIMMINGS & SLUDGES

Generator Info as of Dec 2024

Generator No:	ON6481594
Generator Company Name:	Sport Chek
Street:	1200 St. Laurent Blvd.
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1K3B8
Waste Class:	212 L

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS

2017 Generator Info

Gen No:	ON6481594	***Choice of Contact:***	CO_ADMIN
ID:	25509	***Phone No Official:***	403 717 1327 Ext.
Contaminated Fac:	N	***Phone No Admin:***	416 544 7634 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	451110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	FGL SPORTS LIMITED
Gen Div:	
Gen Op Name:	FGL SPORTS LIMITED
Gen Op Div:	
Site Adrs1:	1200 St. Laurent Blvd. Unit# Y005
Site Bldg:	SPORT CHEK ST. LAURENT
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K1K 3B8
Site Country:	Canada
Co Official:	Scott Suvanto
Co Admin:	Liza Sagherian

2018 Generator Info

Gen No:	ON6481594	***Choice of Contact:***	CO_ADMIN
ID:	25824	***Phone No Official:***	403 717 1327 Ext.
Contaminated Fac:	N	***Phone No Admin:***	416 544 7634 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	451110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	FGL SPORTS LIMITED
Gen Div:	
Gen Op Name:	FGL SPORTS LIMITED
Gen Op Div:	
Site Adrs1:	1200 St. Laurent Blvd. Unit# Y005
Site Bldg:	SPORT CHEK ST. LAURENT
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	

Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: Scott Suvanto
Co Admin: Liza Sagherian

2019 Generator Info

Gen No: ON6481594
ID: 26033
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 451110
NAICS Code2:
NAICS Code3:
Gen Name: FGL SPORTS LIMITED
Gen Div:
Gen Op Name: Sport Chek# 330
Gen Op Div:
Site Adrs1: 1200 St. Laurent Blvd. Unit# Y005
Site Bldg: SPORT CHEK # 330
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: Scott Suvanto
Co Admin: Liza Sagherian
Choice of Contact: CO_ADMIN
Phone No Official: 403-592-8290 Ext.80095
Phone No Admin: 416-480-9780 Ext.27634
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2019 Generator Manifest

ID: 50973
Generator No: ON6481594
Receiver Type: 030
Waste Char: L
Waste Code: 212
Sum Received Qty: 96.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 402

2020 Generator Info

Gen No: ON6481594
ID: 25758
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 451110
NAICS Code2:
NAICS Code3:
Gen Name: FGL SPORTS LIMITED
Gen Div:
Gen Op Name: Sport Chek# 330
Gen Op Div:
Site Adrs1: 1200 St. Laurent Blvd. Unit# Y005
Site Bldg: SPORT CHEK # 330
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1K 3B8
Site Country: Canada
Co Official: Scott Suvanto
Co Admin: Liza Sagherian
Choice of Contact: CO_ADMIN
Phone No Official: 403-592-8290 Ext.80095
Phone No Admin: 416-480-9780 Ext.27634
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2020 Generator Manifest

ID:	47472	***Sum Received Qty:***	95.0
Generator No:	ON6481594	***Waste Class Name:***	ALIPHATIC SOLVENTS
Receiver Type:	030	***Count Manifests:***	1
Waste Char:	L	***District:***	402
Waste Code:	212		

2021 Generator Info

Gen No:	ON6481594	***Choice of Contact:***	CO_ADMIN
ID:	26203	***Phone No Official:***	403-592-8290 Ext.80095
Contaminated Fac:	N	***Phone No Admin:***	416-480-9780 Ext.27634
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	451110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	FGL SPORTS LIMITED		
Gen Div:			
Gen Op Name:	Sport Chek# 330		
Gen Op Div:			
Site Adrs1:	1200 St. Laurent Blvd. Unit# Y005		
Site Bldg:	SPORT CHEK # 330		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K1K 3B8		
Site Country:	Canada		
Co Official:	Scott Suvanto		
Co Admin:	Liza Sagherian		

2021 Generator Manifest

ID:	49328	***Sum Received Qty:***	95.0
Generator No:	ON6481594	***Waste Class Name:***	ALIPHATIC SOLVENTS
Receiver Type:	030	***Count Manifests:***	1
Waste Char:	L	***District:***	402
Waste Code:	212		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	***112 of 116***	***S/291.1***	***69.9 / -1.00***	***LCBO*** ***1200 Saint Laurent Boulevard*** ***Ottawa ON***	***GEN***

Generator Info as of Dec 2024

Generator No:	ON001066350
Generator Company Name:	LCBO
Street:	1200 Saint Laurent Boulevard
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1K 3B8
Waste Class:	312 P, 263 I, 263 L, 212 I

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info as of Dec 2024

Generator No:	ON001066350
Generator Company Name:	LCBO
Street:	1200 Saint Laurent Boulevard
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1K 3B8
Waste Class:	212 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS

73	***113 of 116***	***S/291.1***	***69.9 / -1.00***	***EssilorLuxottica of Canada*** ***1200 Saint Laurent Boulevard*** ***Ottawa ON***	***GEN***

Generator Info as of Dec 2024

Generator No:	ON001053259
Generator Company Name:	EssilorLuxottica of Canada
Street:	1200 Saint Laurent Boulevard
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1K 3B8
Waste Class:	312 P, 263 I, 263 L, 212 I

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No:	ON001053259
Generator Company Name:	EssilorLuxottica of Canada
Street:	1200 Saint Laurent Boulevard
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1K 3B8
Waste Class:	263 I,263 L

Waste Class Decoded:

263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS

73	***114 of 116***	***S/291.1***	***69.9 / -1.00***	***St Laurent Dental Centre*** ***1200 Saint Laurent Boulevard*** ***Ottawa ON***	***GEN***

Generator Info as of Dec 2024

Generator No: ON001053220
Generator Company Name: St Laurent Dental Centre
Street: 1200 Saint Laurent Boulevard
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K 3B8
Waste Class: 312 P, 263 I, 263 L, 212 I

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No: ON001053220
Generator Company Name: St Laurent Dental Centre
Street: 1200 Saint Laurent Boulevard
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K 3B8
Waste Class: 312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

73	*115 of 116*	*S/291.1*	*69.9 / -1.00*	***RTM*** ***1200 Saint Laurent Boulevard*** ***Ottawa ON***	***GEN***

Generator Info as of Dec 2024

Generator No: ON001069863
Generator Company Name: RTM
Street: 1200 Saint Laurent Boulevard
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1K 3B8
Waste Class: 251 L

Waste Class Decoded:

251 - OIL SKIMMINGS & SLUDGES

73	*116 of 116*	*S/291.1*	*69.9 / -1.00*	***American Eagle Outfitters Canada Corporation*** ***1200 Saint Laurent Boulevard*** ***Ottawa ON***	***GEN***

Generator Info as of Dec 2024

Generator No: ON001070761
Generator Company Name: American Eagle Outfitters Canada Corporation

Street:	1200 Saint Laurent Boulevard
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1K 3B8
Waste Class:	261 L,331 I,212 I

Waste Class Decoded:

261 - PHARMACEUTICALS; 331 - WASTE COMPRESSED GASES; 212 - ALIPHATIC SOLVENTS

---

74 | **1 of 1** | **ESE/291.4** | **71.9 / 1.00** | **OTTAWA ON** | **SPL**

Ref No:	1-3GMT4U	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	5/15/2023 12:44:06 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	5/15/2023 12:44:06 PM	**Impact to Health:**	
Dt Document Closed:	5/15/2023 1:16:27 PM	**Agency Involved:**	

Site No:	
MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Ottawa District Office
Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	OTTAWA
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	Fire
Incident Reason:	
Incident Summary:	Saab Gas Centre: fire in garage; oil & water mixture to parking lot; cntd, clng
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	2000 litre (L)
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	OILY WATER
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	Lower Ottawa
Property Tertiary Watershed:	02KF - Central Ottawa - Mississippi
Sector Type:	GASOLINE STATIONS WITH CONVENIENCE STORES
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00004012328"],"wkts":["POINT (-75.6354989000 45.4251175000)"],"creation_date":"2023-05-15"}
Time Reported:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
System Facility Address:					
75	1 of 14	ESE/295.8	71.9 / 1.00	JOSEPH T SAAB 1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	PRT
Location ID:	5280				
Type:	retail				
Expiry Date:	1995-04-30				
Capacity (L):	0				
Licence #:	0051652001				
75	2 of 14	ESE/295.8	71.9 / 1.00	JOE T SAAB 135247 CANADA INC 1057 CYRVILLE RD GLOUCESTER ON	PRT
Location ID:	5280				
Type:	retail				
Expiry Date:	1995-03-31				
Capacity (L):	5000				
Licence #:	0034419001				
75	3 of 14	ESE/295.8	71.9 / 1.00	SAAB GAS CENTRE 1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	RST
Headcode:	00426100				
Headcode Desc:	DIESEL FUEL				
Phone:					
List Name:					
Description:					
75	4 of 14	ESE/295.8	71.9 / 1.00	SAAB GAS CENTRE 1057 CYRVILLE RD OTTAWA ON K1J 7S3	RST
Headcode:	1186800				
Headcode Desc:	Service Stations-Gasoline, Oil & Natural Gas				
Phone:	6137451886				
List Name:					
Description:					
75	5 of 14	ESE/295.8	71.9 / 1.00	1427229 ONTARIO INC ATTN JOSEPH T SAAB 1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	FSTH
License Issue Date:	3/22/2002				
Tank Status:	Licensed				
Tank Status As Of:	August 2007				
Operation Type:	Retail Fuel Outlet				
Facility Type:	Gasoline Station - Full Serve				
--Details--					
Status:	Active				
Year of Installation:	1984				
Corrosion Protection:					

Capacity: 22600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 22600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 22600
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	6 of 14	ESE/295.8	71.9 / 1.00	1427229 ONTARIO INC ATTN JOSEPH T SAAB 1057 CYRVILLE RD GLOUCESTER ON K1J 7S3	FSTH

License Issue Date: 3/22/2002
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Full Serve

--Details--
Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 22600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 22600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 22600
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	7 of 14	ESE/295.8	71.9 / 1.00	SAAB GAS CENTRE 1057 CYRVILLE RD GLOUCESTER ON K1J7S3	RST

Headcode: 00426100
Headcode Desc: DIESEL FUEL
Phone: 6137451886
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	8 of 14	ESE/295.8	71.9 / 1.00	SAAB GAS CENTRE 1057 CYRVILLE RD GLOUCESTER ON K1J7S3	RST

Headcode: 01070540
Headcode Desc: PROPANE GAS TANKS & REFILLING

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone: 6137451886
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

75 | **9 of 14** | **ESE/295.8** | **71.9 / 1.00** | **SAAB GAS CENTRE**
1057 CYRVILLE RD
GLOUCESTER ON K1J7S3 | **RST**

Headcode: 00426100
Headcode Desc: DIESEL FUEL
Phone: 6137451886
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

75 | **10 of 14** | **ESE/295.8** | **71.9 / 1.00** | **Carlsbad Auto 1057 Cyrville Road**
1057 Cyrville Road, Ottawa
OTTAWA ON | **SPL**

Ref No: 1-3GMEPS
Year:
Incident Dt: 5/15/2023 9:10:35 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/15/2023 9:28:35 AM
Dt Document Closed: 7/13/2023 8:05:31 AM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Ottawa District Office
Nearest Watercourse:
Site Name: Carlsbad Auto 1057 Cyrville Road
Site Address: 1057 Cyrville Road, Ottawa
Site Region:
Site Municipality: OTTAWA
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: ALAN SAM KYOZ
Client Type: Private Business
Source Type: Container/Drum/Tote
Incident Cause:
Incident Preceding Spill: Other (specify)
Incident Reason: Fire
Incident Summary: Fire Saab Station /Carlsbad Auto Service -1057 Cyrville Rd
Environment Impact: 2 Minor Impact &/or Mortality
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 1 litre (L)
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: ENGINE OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air; Land
Activity Preceding Spill: Other (specify)
Property 2nd Watershed: Lower Ottawa
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Property Tertiary Watershed:	02KF - Central Ottawa - Mississippi
Sector Type:	GENERAL AUTOMOTIVE REPAIR
SAC Action Class:	Municipal Stormwater
Call Report Locatn Geodata:	{"integration_ids":["PR00004012328"],"wkts":["POINT (-75.6354989000 45.4251175000)"],"creation_date":"2023-05-15"}
Time Reported:	
System Facility Address:	1057 CYRVILLE RD, OTTAWA, ON K1J 7S3

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	11 of 14	ESE/295.8	71.9 / 1.00	**Norris Construction Management Inc.** **1057 Cyrville Road** **Ottawa ON**	GEN

Generator Info as of Dec 2024

Generator No:	ONS0402-1-3GMEPS-1
Generator Company Name:	Norris Construction Management Inc.
Street:	1057 Cyrville Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J 7S3
Waste Class:	212 L, 252 L, 221 I, 221 L, 146 L

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 252 - WASTE OILS & LUBRICANTS; 221 - LIGHT FUELS; 221 - LIGHT FUELS; 146 - OTHER SPECIFIED INORGANICS

Generator Info as of Dec 2024

Generator No:	ONS0402-1-3GMEPS-1
Generator Company Name:	Norris Construction Management Inc.
Street:	1057 Cyrville Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J 7S3
Waste Class:	221 L

Waste Class Decoded:

221 - LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	12 of 14	ESE/295.8	71.9 / 1.00	**SAAB Gas Center** **1057 Cyrville Road** **Ottawa ON**	GEN

Generator Info as of Dec 2024

Generator No:	ON001061659
Generator Company Name:	SAAB Gas Center
Street:	1057 Cyrville Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J 7S3
Waste Class:	212 L, 252 L, 221 I, 221 L, 146 L

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 252 - WASTE OILS & LUBRICANTS; 221 - LIGHT FUELS; 221 - LIGHT FUELS; 146 - OTHER SPECIFIED INORGANICS

Generator Info as of Dec 2024

Generator No:	ON001061659
Generator Company Name:	SAAB Gas Center
Street:	1057 Cyrville Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J 7S3
Waste Class:	212 L,252 L,221 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 252 - WASTE OILS & LUBRICANTS; 221 - LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	13 of 14	ESE/295.8	71.9 / 1.00	SAAB Gas Centre 1057 Cyrville Road Ottawa ON	GEN

Generator Info as of Dec 2024

Generator No:	ONS0402-1-3GMEPS-2
Generator Company Name:	SAAB Gas Centre
Street:	1057 Cyrville Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J 7S3
Waste Class:	212 L, 252 L, 221 I, 221 L, 146 L

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 252 - WASTE OILS & LUBRICANTS; 221 - LIGHT FUELS; 221 - LIGHT FUELS; 146 - OTHER SPECIFIED INORGANICS

Generator Info as of Dec 2024

Generator No:	ONS0402-1-3GMEPS-2
Generator Company Name:	SAAB Gas Centre
Street:	1057 Cyrville Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J 7S3
Waste Class:	146 L

Waste Class Decoded:

146 - OTHER SPECIFIED INORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	14 of 14	ESE/295.8	71.9 / 1.00	BELL CANADA 1057 Cyrville Road Ottawa ON	GEN

Generator Info as of Dec 2024

Generator No:	ON001068459
Generator Company Name:	BELL CANADA
Street:	1057 Cyrville Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J 7S3
Waste Class:	251 L

Waste Class Decoded:

251 - OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	1 of 1	N/297.0	71.9 / 1.00	1233 Donald St. Ottawa ON	SPL

Ref No:	2610-7H2H8J	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:		***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	7/30/2008	***Impact to Health:***	
Dt Document Closed:	9/22/2008	***Agency Involved:***	
Site No:			
MOE Response:	No Further Response (PR-PIR Table A)		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	Spill Site<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	Other Discharges		
Incident Preceding Spill:			
Incident Reason:	Negligence (Apparent) - Caused by lack of diligence		
Incident Summary:	Ottawa: 20 L spill of cooking oil to the pavement, cleaned		
Environment Impact:	Not Anticipated		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	20 L		
Contaminant Qty 1:	20		
Contaminant Unit:	L		
Contaminant Code:	16		
Contaminant Name:	COOKING OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			

Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

77 | **1 of 1** | **SE/298.0** | **70.9 / 0.00** | **lot 26 con 2 ON** | **WWIS**

Well ID: 1501342
Construction Date:
Use 1st: Domestic
Use 2nd: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 02/25/1949
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1107
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 026
Concession: 02
Concession Name: OF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1501342.pdf

Additional Detail(s) (Map)

Well Completed Date: 05/28/1948
Year Completed: 1948
Depth (m): 21.336
Latitude: 45.4243776491571
Longitude: -75.6362453683648
X: -75.63624520598901
Y: 45.42437764188065
Path: 150\1501342.pdf

Bore Hole Information

Bore Hole ID: 10023385
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 05/28/1948
Remarks:
Location Method Desc: Original Pre1985 UTM Rel Code 9: unknown UTM
Elevrc Desc:
Location Source Date:

Elevation:
Elevrc:
Zone: 18
East83: 450225.70
North83: 5030292.00
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 930991588
Layer: 1
Color:
General Color:
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930991589
Layer: 2
Color: 2
General Color: GREY
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 2.0
Formation End Depth: 16.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930991590
Layer: 3
Color:
General Color:
Material 1: 19
Material 1 Desc: SLATE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 16.0
Formation End Depth: 70.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961501342
Method Construction Code: 1
Method Construction: Cable Tool

Other Method Construction:

Pipe Information

Pipe ID: 10571955
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930039653
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 16.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930039654
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 70.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991501342
Pump Set At:
Static Level: 10.0
Final Level After Pumping: 70.0
Recommended Pump Depth:
Pumping Rate: 5.0
Flowing Rate:
Recommended Pump Rate: 2.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933454041
Layer: 1
Kind Code: 3
Kind: SULPHUR
Water Found Depth: 70.0
Water Found Depth UOM: ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	1 of 1	WSW/298.4	69.2 / -1.69	Elite Environmental Group Inc 1105 Hardy Ave Ottawa ON K1K3H8	GEN

Generator Info

Generator No:	ON6301372	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	146 T
Waste Class Name:	OTHER SPECIFIED INORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	1 of 8	N/298.6	71.9 / 1.00	LOBLAW SUPERMARKETS LTD. STORE NO. 180-2 1235 DONALD STREET GLOUCESTER ON K1J 8W3	PES

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	2 of 8	N/298.6	71.9 / 1.00	LOBLAWS #180 1235 DONALD STREET GLOUCESTER ON K1J 8W3	PES

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Concession: ***Op Municipality:***
Region: ***Post Office Box:***
District: ***MOE District:***
County: ***SWP Area Name:***
Trade Name:
PDF URL:

---

79 | ***3 of 8*** | ***N/298.6*** | ***71.9 / 1.00*** | ***LOBLAWS SUPERMARKETS LIMITED*** ***1235 DONALD STREET*** ***OTTAWA ON K1J 8W3*** | ***PES***

Detail Licence No: ***Operator Box:***
Licence No: ***Operator Class:***
Status: ***Operator No:***
Approval Date: ***Operator Type:***
Report Source: ***Oper Area Code:***
Licence Type: Vendor ***Oper Phone No:***
Licence Type Code: ***Operator Ext:***
Licence Class: ***Operator Lot:***
Licence Control: ***Oper Concession:***
Latitude: ***Operator Region:***
Longitude: ***Operator District:***
Lot: ***Operator County:***
Concession: ***Op Municipality:***
Region: ***Post Office Box:***
District: ***MOE District:***
County: ***SWP Area Name:***
Trade Name:
PDF URL:

---

79 | ***4 of 8*** | ***N/298.6*** | ***71.9 / 1.00*** | ***Rio-Can Property Services*** ***1235 Donald Street*** ***Ottawa ON K1J 8W3*** | ***GEN***

Generator Info

Generator No: ON8432453 ***Choice of Contact:***
Approval Years: 02,03,04 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:***
Country:
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: WASTE OILS & LUBRICANTS

---

79 **5 of 8** **N/298.6** **71.9 / 1.00** **LOBLAW SUPERMARKETS LTD. STORE NO. 180-2**
1235 DONALD STREET
GLOUCESTER ON K1J8W3 **PES**

Detail Licence No:
Licence No: 10155
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 7311575
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

79 **6 of 8** **N/298.6** **71.9 / 1.00** **LOBLAWS SUPERMARKETS LIMITED**
1235 DONALD STREET
OTTAWA ON K1J8W3 **PES**

Detail Licence No:
Licence No: 10199
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 7446635
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

79 **7 of 8** **N/298.6** **71.9 / 1.00** **LOBLAWS #180**
1235 DONALD STREET
GLOUCESTER ON K1G1W3 **PES**

Detail Licence No:
Licence No: 10132
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 7487141
Operator Ext:
Operator Lot:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

79	8 of 8	N/298.6	71.9 / 1.00	***TJX Canada*** ***1235 Donald Street*** ***Ottawa ON***	***GEN***

Generator Info as of Dec 2024

Generator No:	ON001062084
Generator Company Name:	TJX Canada
Street:	1235 Donald Street
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J 8W3
Waste Class:	212 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS

Unplottable Summary

Total: 95 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA		St. Laurent Boulevard	Ottawa ON	
CA		Lot 25 & 26, Concession 1	Ottawa ON	
CA		Lot 25 & 26, Concession 1	Ottawa ON	
CA	City of Ottawa	Cyrville Road	Ottawa ON	
CA	Donald Street to Easement	St. Laurent Boulevard	Ottawa ON	
CA		Ogilvie Rd., Part of Rd. Allowance	Gloucester ON	
CA	CITY	ST. LAURENT BLVD. EXT.	OTTAWA ON	
CA	CITY	ST. LAURENT BLVD. EXT.	OTTAWA ON	
CA	RICHCRAFT HOMES OTTAWA BUSINESS PARK	ST. LAURENT BLVD.	OTTAWA CITY ON	
CA	OTTAWA-CARLETON REGIONAL TRANSIT COMM.	ST. LAURENT BLVD.	OTTAWA CITY ON	
CA	GIL BERN CHARLES CORPORATION LIMITED	ST. LAURENT BLVD.	OTTAWA CITY ON	
CA	EASTERN ONTARIO LAND TRUST INC.	OGILVIE RD.	GLOUCESTER CITY ON	
CA	COLONNADE DEVELOPMENT INC.	ST. LAURENT BLVD. OTTAWA BUS.	OTTAWA CITY ON	
CA	OTTAWA-CARLETON REG. HOUSING AUTHORITY	ST. LAURENT BOULEVARD	OTTAWA CITY ON	
CA	CADILLAC FAIRVIEW CORP. BAY STORE	ST. LAURENT SHOPPING CENTRE	OTTAWA CITY ON	
CA	OTTAWA CITY OTTAWA BUS. PK PH. IV	ST. LAURENT BLVD.	OTTAWA CITY ON	
CA	R.M. OF OTTAWA-CARLETON, CONROY ROAD	ST. LAURENT BLVD.	OTTAWA CITY ON	

CA	OTTAWA CITY - VANIER PKWY. REC. COMPLEX	COVENTRY RD./STM-WATER MGT.	OTTAWA CITY ON
CA	BEAUREGARD PRINTERS LIMITED-PT.BLK. 'B'	COVENTRY ROAD	OTTAWA CITY ON
CA	LOWE-MARTIN LTD.	COVENTRY ROAD	OTTAWA CITY ON
CA	CADILLAC FAIRVIEW CORP. BAY STORE	ST. LAURENT SHOPPING CENTRE	OTTAWA CITY ON
CA	MINISTRY OF GOVERNMENT SERVICES	ST. LAURENT BLVD.OTTAWA BUS.PK	OTTAWA CITY ON
CA	COLONNADE DEVELOPMENT INC.	ST. LAURENT BLVD. OTTAWA BUS.	OTTAWA CITY ON
CA	OTTAWA-CARLETON REGIONAL TRANSIT COMM.	ST. LAURENT BLVD.	OTTAWA CITY ON
CA	RICHCRAFT HOMES OTTAWA BUSINESS PARK	ST. LAURENT BLVD.	OTTAWA CITY ON
CA	OTTAWA CITY A.J. ROBINSON & ASSOC. INC.	QUEEN MARY ST.	OTTAWA CITY ON
CA	EASTERN ONTARIO LAND TRUST INC.	OGILVIE RD.	GLOUCESTER CITY ON
CA	OTTAWA CITY ST. LAURENT BLVD.	ST. LAURENT BLVD. BUS.PK PH.IV	OTTAWA CITY ON
CA	GIL BERN CHARLES CORPORATION LIMITED	ST. LAURENT BLVD.	OTTAWA CITY ON
CA	Richcraft Homes Ltd.		Ottawa ON
CA	Richcraft Homes Ltd.		Ottawa ON
CA	Richcraft Homes Ltd.		Ottawa ON
CA	Petro-Canada		Ottawa ON
CA	Richcraft Homes Ltd.		Ottawa ON
CA	Richcraft Homes Ltd.		Ottawa ON
CONV	Willy's Roll-Off LTD.		Ottawa ON
CONV	Waste Services (CA) Inc		Ottawa ON
CONV	SHELL CANADA PRODUCTS LIMITED		DON MILLS ON
CONV	WILLY'S ROLL-OFFS LTD.		ON

EBR	Tomlinson Environmental Services Ltd.	Mobile Facility Ottawa CITY OF OTTAWA	ON	
EBR	Richcraft Homes Ltd.	Ottawa, ON Canada	ON	
ECA	Tomlinson Environmental Services Ltd.	Mobile Facility	Ottawa ON	K2R 6K7
ECA	Richcraft Construction (1984) Ltd.		Ottawa ON	K1G 4K1
ECA	The Bell Telephone Company of Canada or Bell Canada	Multiple Sites Across Ontario	Ottawa ON	H3B 2M8
ECA	Tomlinson Environmental Services Ltd.	Mobile Facility	Ottawa ON	K1G 3N4
ECA	The Bell Telephone Company of Canada or Bell Canada	Multiple Sites Across Ontario	Ottawa ON	H3B 2M8
ECA	Richcraft Homes Ltd.		Ottawa ON	K1G 4K1
ECA	Richcraft Homes Ltd.		Ottawa ON	K1G 4K1
ECA	Richcraft Homes Ltd.		Ottawa ON	K1G 4K1
ECA	Richcraft Homes Ltd.		Ottawa ON	K1G 4K1
ECA	Petro-Canada Inc.		Ottawa ON	L6L 6N5
GEN	RW Tomlinson	St. Laurent Blvd Guideway	Ottawa ON	K1G 3N4
GEN	Tomlinson Environmental Services	All Catch Basins in the City of Ottawa Serviced by TES-Industrial Waste Division	Ottawa ON	K1N 1J1
GEN	City of Ottawa	Ogilvie Road just south of Montreal Road	Ottawa ON	K2G 7E6
GEN	RW Tomlinson	St. Laurent Blvd Guideway	Ottawa ON	K1G 3N4
GEN	RW Tomlinson	St. Laurent Blvd Guideway	Ottawa ON	K1G 3N4
GEN	Imperial Oil	Ogilvie Road	Ottawa ON	
GEN	CITY OF OTTAWA	COVENTRY ROAD @ HARDY AVE	OTTAWA ON	
GEN	Bell Canada	VARIOUS BELL CANADA MANHOLES AND ACCESS CHAMBERS WITHIN THE MOE EASTERN REG.	(SEE SCHEDULE "B") ON	
SPL	OC TRANSPO	MOTOR VEHICLE (OPERATING FLUID)	OTTAWA CITY ON	
SPL	ONTARIO HYDRO	ST. LAURENT SHOPPING CENTRE, ST. LAURENTBLVD. TRANSFORMER	OTTAWA CITY ON	

SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	Shell Canada Products Limited	Shell Canada	Ottawa ON
SPL	UNKNOWN	CYRVILLE DRAIN ON ST. LAURENT BLVD.	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	SERVICE STATION	OTTAWA CITY ON
SPL	City of Ottawa	Ogilvie Road (south of montreal rd)	Ottawa ON
SPL	PETRO-CANADA	SERVICE STATION	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	INTERLING FREIGHT LINES	ST. LAURENT SHOPPING CENTRE. TRANSPORT TRUCK (CARGO)	OTTAWA CITY ON
SPL	Tomlinson Environmental Services Ltd.		Ottawa ON
SPL	Bell Canada		Ottawa ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
WWIS		lot 9	ON
WWIS		con 1	ON
WWIS		lot 7	ON
WWIS		lot 7	ON
WWIS		con 1	ON

WWIS	lot 26	ON
WWIS	lot 26	ON
WWIS	lot 26	ON
WWIS	lot 9	ON
WWIS	lot 8	ON
WWIS	con 1	ON
WWIS	lot 26	ON
WWIS	con 1	ON
WWIS	lot 9	ON
WWIS	lot 7	ON
WWIS	lot 8	ON
WWIS	lot 8	ON

Unplottable Report

Site:
St. Laurent Boulevard Ottawa ON

Database: ***CA***

Certificate #:	7347-5DELJN
Application Year:	02
Issue Date:	8/28/02
Approval Type:	Municipal & Private water
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	City of Ottawa
Client Address:	1495 Heron Road
Client City:	Ottawa
Client Postal Code:	K1V 6A6
Project Description:	Approval is sought for the construction of watermains on St. Laurent Boulevard, and Sandridge Road.
Contaminants:	
Emission Control:	

Site:
Lot 25 & 26, Concession 1 Ottawa ON

Database: ***CA***

Certificate #:	3510-4QHTRG
Application Year:	00
Issue Date:	10/30/00
Approval Type:	Municipal & Private water
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	1270449 Ontario Inc.
Client Address:	1187 Bank Street
Client City:	Ottawa
Client Postal Code:	K1S 3X7
Project Description:	watermain construction on pooler ave, orvigale road, porter st.
Contaminants:	
Emission Control:	

Site:
Lot 25 & 26, Concession 1 Ottawa ON

Database: ***CA***

Certificate #:	6524-4QHTM6
Application Year:	00
Issue Date:	10/30/00
Approval Type:	Municipal & Private sewage
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	1270449 Ontario Inc.
Client Address:	1187 Bank Street
Client City:	Ottawa
Client Postal Code:	K1S 3X7
Project Description:	storm sewers construction on Saundres Ave; sanitary sewers construction on Pooler Ave, Orvigale Road, Porter St.
Contaminants:	
Emission Control:	

Site: ***City of Ottawa***
Cyrville Road Ottawa ON

Database: ***CA***

Certificate #: 4022-52WSQY
Application Year: 01
Issue Date: 9/27/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: The Corporation of the City of Ottawa
Client Address: 110 Laurier Avenue West
Client City: Ottawa
Client Postal Code: K1P 1J1
Project Description: storm sewer to be constructed on Cyrville Road.
Contaminants:
Emission Control:

Site: ***Donald Street to Easement***
St. Laurent Boulevard Ottawa ON

Database: ***CA***

Certificate #: 2225-4KFR7G
Application Year: 00
Issue Date: 5/23/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the City of Ottawa
Client Address: 111 Sussex Drive, 7th Floor
Client City: Ottawa
Client Postal Code: K1N 5A1
Project Description: Construction of a Sanitary Sewer in St. Laurent Blvd. from Donald Street to Easement
Contaminants:
Emission Control:

Site:
Ogilvie Rd., Part of Rd. Allowance Gloucester ON

Database: ***CA***

Certificate #: 7032-4H8TJA
Application Year: 00
Issue Date: 3/11/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Anglican Church Of The Epiphany
Client Address: 24 Steel St.
Client City: Gloucester
Client Postal Code:
Project Description: Construction of sanitary sewers along Ogilvie Rd..
Contaminants:
Emission Control:

Site: ***CITY***
ST. LAURENT BLVD. EXT. OTTAWA ON

Database: ***CA***

Certificate #: 3-0206-85-006
Application Year: 85
Issue Date: 3/21/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CITY***
ST. LAURENT BLVD. EXT. OTTAWA ON

Database: ***CA***

Certificate #: 7-0164-85-006
Application Year: 85
Issue Date: 3/29/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***RICHCRAFT HOMES OTTAWA BUSINESS PARK***
ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-1739-88-
Application Year: 88
Issue Date: 10/28/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OTTAWA-CARLETON REGIONAL TRANSIT COMM.***
ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-0207-89-
Application Year: 89
Issue Date: 3/7/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***GIL BERN CHARLES CORPORATION LIMITED***
ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-0436-87-
Application Year: 87
Issue Date: 5/14/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:

Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***EASTERN ONTARIO LAND TRUST INC.***
OGILVIE RD. GLOUCESTER CITY ON

Database: ***CA***

Certificate #: 7-1485-88-
Application Year: 88
Issue Date: 9/13/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***COLONNADE DEVELOPMENT INC.***
ST. LAURENT BLVD. OTTAWA BUS. OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-0783-89-
Application Year: 89
Issue Date: 5/26/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OTTAWA-CARLETON REG. HOUSING AUTHORITY***
ST. LAURENT BOULEVARD OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-1421-91-
Application Year: 91
Issue Date: 11/14/1991
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CADILLAC FAIRVIEW CORP. BAY STORE***
ST. LAURENT SHOPPING CENTRE OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-1653-89-

Application Year: 89
Issue Date: 10/10/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OTTAWA CITY OTTAWA BUS. PK PH. IV***
ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-0744-88-
Application Year: 88
Issue Date: 6/30/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF OTTAWA-CARLETON, CONROY ROAD***
ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-0635-88-
Application Year: 88
Issue Date: 5/13/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OTTAWA CITY - VANIER PKWY. REC. COMPLEX***
COVENTRY RD./STM-WATER MGT. OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-0590-92-
Application Year: 92
Issue Date: 9/18/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BEAUREGARD PRINTERS LIMITED-PT.BLK. 'B'***
COVENTRY ROAD OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-1368-91-
Application Year: 91
Issue Date: 9/9/1991
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***LOWE-MARTIN LTD.***
COVENTRY ROAD OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-0082-91-
Application Year: 91
Issue Date: 2/7/1991
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CADILLAC FAIRVIEW CORP. BAY STORE***
ST. LAURENT SHOPPING CENTRE OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-1989-89-
Application Year: 89
Issue Date: 10/10/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MINISTRY OF GOVERNMENT SERVICES***
ST. LAURENT BLVD.OTTAWA BUS.PK OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-1598-89-
Application Year: 89
Issue Date: 8/10/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***COLONNADE DEVELOPMENT INC.***
ST. LAURENT BLVD. OTTAWA BUS. OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-0911-89-
Application Year: 89
Issue Date: 5/26/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OTTAWA-CARLETON REGIONAL TRANSIT COMM.***
ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-0233-89-
Application Year: 89
Issue Date: 3/7/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***RICHCRAFT HOMES OTTAWA BUSINESS PARK***
ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-2055-88-
Application Year: 88
Issue Date: 10/28/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OTTAWA CITY A.J. ROBINSON & ASSOC. INC.***
QUEEN MARY ST. OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-2059-88-
Application Year: 88

Issue Date: 10/26/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***EASTERN ONTARIO LAND TRUST INC.***
OGILVIE RD. GLOUCESTER CITY ON

Database: ***CA***

Certificate #: 3-1727-88-
Application Year: 88
Issue Date: 9/13/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OTTAWA CITY ST. LAURENT BLVD.***
ST. LAURENT BLVD. BUS.PK PH.IV OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-0861-88-
Application Year: 88
Issue Date: 6/30/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***GIL BERN CHARLES CORPORATION LIMITED***
ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-0530-87-
Application Year: 87
Issue Date: 5/14/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Richcraft Homes Ltd.***
Ottawa ON

Database: ***CA***

Certificate #: 9817-7WNR3C
Application Year: 2009
Issue Date: 10/15/2009
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Richcraft Homes Ltd.***
Ottawa ON

Database: ***CA***

Certificate #: 9080-5UYQRL
Application Year: 2004
Issue Date: 1/8/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Richcraft Homes Ltd.***
Ottawa ON

Database: ***CA***

Certificate #: 7432-7UVKBU
Application Year: 2009
Issue Date: 8/13/2009
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Petro-Canada***
Ottawa ON

Database: ***CA***

Certificate #: 5607-79YMZ8
Application Year: 2008
Issue Date: 2/12/2008
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:

Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Richcraft Homes Ltd.***
Ottawa ON

Database: ***CA***

Certificate #: 3841-632P4R
Application Year: 2004
Issue Date: 7/20/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Richcraft Homes Ltd.***
Ottawa ON

Database: ***CA***

Certificate #: 1207-5YPRH9
Application Year: 2004
Issue Date: 5/6/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Willy's Roll-Off LTD.***
Ottawa ON

Database: ***CONV***

File No: 082170
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Location:
Region:
Ministry District:

Description: Willy's Roll-Off Ltd., 1092066 Ontario Inc., Willis and Susan McKeown and Percy Pyper Ltd. Pled guilty to impairing water quality, establishing a waste disposal site without approval, and failing to transport waste only to an approved site. They were fined a total of $150,000 plus victim fine surcharges. Numerous inspections conducted by the ministry in 2006 revealed quantities of construction and demolition waste deposited in a former aggregate pit site in Ottawa. The companies did not have approval to store waste at the site and only had ministry approval to transport waste to an approved site. Inspectors also discovered a pond that was almost completely covered in waste. Water samples revealed that water quality may have been impaired. The companies were charged following an investigation by the ministry's Investigations and Enforcement Branch. Four of the defendants pled guilty to depositing, causing or permitting waste to be deposited at a property that resulted in leachate being discharged into water that may have impaired the quality of water. The four defendants also pled guilty to permitting the delivery of

waste to the pit without approval. As well, three of the defendants pled guilty to failing to ensure that adequate steps were taken to comply with ministry approval requirements. The defendants were fined a total of $150,000 plus victim fine surcharges.

Background:
URL:

Additional Details

Publication Date:
Count:
Act:
Regulation:
Section:
Act/Regulation/Section:
Date of Offence:
Date of Conviction:
Date Charged: February 14, 2011
Charge Disposition: fine, victim fine surcharge
Fine: $150,000 (Total for 4 companies)
Synopsis:

Site: ***Waste Services (CA) Inc***
Ottawa ON

Database: ***CONV***

File No: 112803
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Location:
Region:
Ministry District:
Description: Santaro Development LLC has been fined $10,000 plus a victim fine surcharge, and Waste Services (CA) Inc. has been fined $7,500 plus a victim fine surcharge, after pleading guilty on November 13, 2008 to violations under the Environmental Protection Act. Santaro Development LLC pleaded guilty to operating a Waste Management System without a Certificate of Approval, and Waste Services (CA) Inc. pleaded guilty to arranging for the use of equipment, namely transport trucks, for the handling and transportation of waste that was not part of a Waste Management System for which a Certificate of Approval had been issued. The companies were given 60 days to pay. The Court heard that Santaro Development LLC is a New York Based trucking company. Waste Services (CA) Inc. is an Ontario company that operates waste disposal sites, transfer facilities and waste management systems, including a facility in Ottawa. During a ministry surveillance program, Santaro trucks were observed crossing the border into Canada, picking up waste at the Waste Services facility in Ottawa, and crossing back into the United States to dispose of the waste. At the time, Santaro did not have an approval from the ministry for a Waste Management System, and Waste Services did not ensure that Santaro had the necessary approval prior to arranging for it to transport waste from its facility. Santaro Development LLC and Waste Services (CA) Inc. were charged following an investigation by the Ministry of the Environment's Investigations and Enforcement Branch

Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section:
Act/Regulation/Section: EPA
Date of Offence:
Date of Conviction:
Date Charged: November 13, 2008
Charge Disposition: FINED, plus a victim fine surcharge
Fine: $7,500
Synopsis:

Site: ***SHELL CANADA PRODUCTS LIMITED***
DON MILLS ON

Database: ***CONV***

File No:
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: DISCHARGING A CONTAMINANT - ADVERSE EFFECT
Background:
URL:

Location:
Region: SOUTH EAST REGION
Ministry District:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 13(1)
Act/Regulation/Section: EPA- -13(1)
Date of Offence:
Date of Conviction:
Date Charged: 92/05/12
Charge Disposition:
Fine: 90000
Synopsis:

Site: ***WILLY'S ROLL-OFFS LTD.***
ON

Database: ***CONV***

File No:
Crown Brief No: 97-0152-0029
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: TRANSPORTING MUNICIPAL WASTE WITHOUT HAVING THE VEHICLE CLEARLY MARKED AND DELIVERING WASTE TO A FACILITY CONTRARY TO THE APPROVAL.
Background:
URL:

Location:
Region: EASTERN REGION
Ministry District: OTTAWA

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 186(3)
Act/Regulation/Section: EPA- -186(3)
Date of Offence:
Date of Conviction:
Date Charged: 2/10/99

Charge Disposition: SUSPENDED SENTENCE
Fine: $1,500.00
Synopsis:

Site: ***Tomlinson Environmental Services Ltd.***
Mobile Facility Ottawa CITY OF OTTAWA ON

Database: ***EBR***

EBR Registry No: 011-5279
Ministry Ref No: 7519-8P2K34
Notice Type: Instrument Decision
Notice Stage:
Notice Date: February 11, 2016
Proposal Date: December 05, 2011
Year: 2011
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Tomlinson Environmental Services Ltd.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 5597 Power Road, Ottawa Ontario, Canada K1G 3N4
Comment Period:
URL:
Summary:

Site Location Details:

Mobile Facility Ottawa CITY OF OTTAWA

Site: ***Richcraft Homes Ltd.***
Ottawa, ON Canada ON

Database: ***EBR***

EBR Registry No: 019-1273
Ministry Ref No: KV-C-001-18
Notice Type: Instrument
Notice Stage: Decision
Notice Date:
Proposal Date: February 27, 2020
Year: 2020
Decision Posted: May 10, 2021
Exception Posted:
Section: Section 17 (2) (c)
Act 1: Endangered Species Act , R.S.O. 2007
Act 2: Endangered Species Act, 2007
Site Location Map:
Instrument Type: Permit for activities to achieve an overall benefit to a species
Off Instrument Name: Permit for activities with conditions to achieve overall benefit to the species (ESA s.17(2) (c))
Posted By: Ministry of the Environment, Conservation and Parks
Company Name:
Site Address: Ottawa, ON Canada
Location Other:
Proponent Name: Richcraft Homes Ltd.
Proponent Address: Richcraft Homes Ltd. 2280 St. Laurent Boulevard Unit 201 Ottawa, ON K1G4K1 Canada
Comment Period: February 27, 2020 - March 28, 2020 (30 days) Closed
URL: https://ero.ontario.ca/notice/019-1273
Summary:

Site Location Details:

Part of Lot 8, Concession 1 in the Geographic Township of March, Ottawa.

Site: ***Tomlinson Environmental Services Ltd.***
Mobile Facility Ottawa ON K2R 6K7

Database: ***ECA***

Approval No: 7083-BXLJKZ
Approval Date: 2021-03-15
Status: Approved
Record Type: ECA
MOE District:
City:
Longitude:
Latitude:

Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Tomlinson Environmental Services Ltd.		
Address:	Mobile Facility		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/5994-BVEHYM-14.pdf		
PDF Site Location:			

Site: ***Richcraft Construction (1984) Ltd.***
Ottawa ON K1G 4K1

Database: ***ECA***

Approval No:	8872-97AJKR	***MOE District:***	
Approval Date:	2013-05-02	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Richcraft Construction (1984) Ltd.		
Address:			
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/1656-95PNJK-14.pdf		
PDF Site Location:			

Site: ***The Bell Telephone Company of Canada or Bell Canada***
Multiple Sites Across Ontario Ottawa ON H3B 2M8

Database: ***ECA***

Approval No:	6207-CZZPLF	***MOE District:***	North Bay
Approval Date:	July 31, 2024	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	-9016878.7543000001
SWP Area Name:		***Geometry Y:***	5700582.7322999965
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	The Bell Telephone Company of Canada or Bell Canada		
Address:	Multiple Sites Across Ontario		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4515-CV9N3P-14.pdf		
PDF Site Location:	Multiple Sites Across Ontario		

Site: ***Tomlinson Environmental Services Ltd.***
Mobile Facility Ottawa ON K1G 3N4

Database: ***ECA***

Approval No:	1685-A6EJ97	***MOE District:***	
Approval Date:	2016-02-03	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Tomlinson Environmental Services Ltd.		
Address:	Mobile Facility		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7519-8P2K34-14.pdf		
PDF Site Location:			

Site: ***The Bell Telephone Company of Canada or Bell Canada***

Database: ***ECA***

Multiple Sites Across Ontario Ottawa ON H3B 2M8

Approval No:	1529-B8QPS5	***MOE District:***	
Approval Date:	2019-12-11	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: The Bell Telephone Company of Canada or Bell Canada
Address: Multiple Sites Across Ontario
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9060-AW6T5N-14.pdf
PDF Site Location:

Site: ***Richcraft Homes Ltd.***
Ottawa ON K1G 4K1

Database: ***ECA***

Approval No:	5204-4RGRNN	***MOE District:***	
Approval Date:	2000-12-01	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Business Name: Richcraft Homes Ltd.
Address:
Full Address:
Full PDF Link:
PDF Site Location:

Site: ***Richcraft Homes Ltd.***
Ottawa ON K1G 4K1

Database: ***ECA***

Approval No:	5800-5UYNQD	***MOE District:***	
Approval Date:	2004-01-08	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: Richcraft Homes Ltd.
Address:
Full Address:
Full PDF Link:
PDF Site Location:

Site: ***Richcraft Homes Ltd.***
Ottawa ON K1G 4K1

Database: ***ECA***

Approval No:	6566-A7AMSG	***MOE District:***	
Approval Date:	2016-02-23	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Richcraft Homes Ltd.
Address:
Full Address:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1204-A4KTW4-14.pdf
PDF Site Location:

Site: ***Richcraft Homes Ltd.***
Ottawa ON K1G 4K1

Database: ***ECA***

Approval No: 9080-5UYQRL
Approval Date: 2004-01-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Richcraft Homes Ltd.
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5802-5UQM74-14.pdf
PDF Site Location:

Site: ***Petro-Canada Inc.***
Ottawa ON L6L 6N5

Database: ***ECA***

Approval No: 4810-4UMJP8
Approval Date: 2001-03-12
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Petro-Canada Inc.
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7825-4UCP9D-14.pdf
PDF Site Location:

Site: ***RW Tomlinson***
St. Laurent Blvd Guideway Ottawa ON K1G 3N4

Database: ***GEN***

Generator Info

Generator No: ON6732602
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: HIGHWAY, STREET AND BRIDGE CONSTRUCTION, OTHER HEAVY AND CIVIL ENGINEERING CONSTRUCTION
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 237310, 237990

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Site: ***Tomlinson Environmental Services***
All Catch Basins in the City of Ottawa Serviced by TES-Industrial Waste Division Ottawa ON K1N 1J1

Database: ***GEN***

Generator Info

Generator No:	ON6691940	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	562110, 562990
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	WASTE COLLECTION, ALL OTHER WASTE MANAGEMENT SERVICES		

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Site: ***City of Ottawa***
Ogilvie Road just south of Montreal Road Ottawa ON K2G 7E6

Database: ***GEN***

Generator Info

Generator No:	ON9284631	***Choice of Contact:***	CO_ADMIN
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	237110
Country:	Canada		
Co Admin:	jim r smith		
Phone No Admin:	613 745 2444 Ext.241		
SIC Description:	WATER AND SEWER LINE AND RELATED STRUCTURES CONSTRUCTION		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Site: ***RW Tomlinson***
St. Laurent Blvd Guideway Ottawa ON K1G 3N4

Database: ***GEN***

Generator Info

Generator No:	ON6732602	***Choice of Contact:***	
Approval Years:	As of Dec 2017	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Site: ***RW Tomlinson***
St. Laurent Blvd Guideway Ottawa ON K1G 3N4

Database: ***GEN***

Generator Info

Generator No: ON6732602
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

2017 Generator Info

Gen No: ON6732602
ID: 26481
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 237310
NAICS Code2: 237990
NAICS Code3:
Gen Name: RW Tomlinson
Gen Div:
Gen Op Name: RW Tomlinson
Gen Op Div:
Site Adrs1: St. Laurent Blvd Guideway
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1G 3N4
Site Country: Canada
Co Official: Matt Wiens
Co Admin:

Choice of Contact: CO_OFFICIAL
Phone No Official: 613-880-6590 Ext.
Phone No Admin:
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2018 Generator Info

Gen No: ON6732602
ID: 26847
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 237310
NAICS Code2: 237990
NAICS Code3:
Gen Name: RW Tomlinson
Gen Div:
Gen Op Name: RW Tomlinson
Gen Op Div:
Site Adrs1: St. Laurent Blvd Guideway
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K1G 3N4
Site Country: Canada
Co Official: Matt Wiens
Co Admin:

Choice of Contact: CO_OFFICIAL
Phone No Official: 613-880-6590 Ext.
Phone No Admin:
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Site: ***Imperial Oil***
Ogilvie Road Ottawa ON

Database: ***GEN***

Generator Info as of Dec 2024

Generator No:	ON001069798
Generator Company Name:	Imperial Oil
Street:	Ogilvie Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K1J8N4
Waste Class:	251 L

Waste Class Decoded:

251 - OIL SKIMMINGS & SLUDGES

Site: ***CITY OF OTTAWA***
COVENTRY ROAD @ HARDY AVE OTTAWA ON

Database: ***GEN***

Generator Info

Generator No:	ON6667785	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	541620
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Environmental Consulting Services		

Site: ***Bell Canada***
VARIOUS BELL CANADA MANHOLES AND ACCESS CHAMBERS WITHIN THE MOE EASTERN REG. (SEE SCHEDULE "B") ON

Database: ***GEN***

Generator Info

Generator No:	ONR000304	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	517110, 517210, 517510
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	WIRED TELECOMMUNICATIONS CARRIERS, WIRELESS TELECOMMUNICATIONS CARRIERS (EXCEPT SATELLITE)		

Waste Detail(s)

Waste Class:	150
Waste Class Name:	INERT INORGANIC WASTES

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Site: ***OC TRANSPO***
MOTOR VEHICLE (OPERATING FLUID) OTTAWA CITY ON

Database: ***SPL***

Ref No: 241575
Year:
Incident Dt: 10/6/2002
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/6/2002
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Preceding Spill:
Incident Reason: UNKNOWN
Incident Summary: OC TRANSPO: 10L ANTIFREEZE TO STORMS, ROAD. SEWERMATIC RESPONDING.
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Water course or lake
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: WATER, LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:

Municipality No: 20107
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

System Facility Address:

Site: ***ONTARIO HYDRO***
ST. LAURENT SHOPPING CENTRE, ST. LAURENTBLVD. TRANSFORMER OTTAWA CITY ON

Database: ***SPL***

Ref No:	4477	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	5/30/1988	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	5/30/1988	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	OTTAWA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER CONTAINER LEAK		
Incident Preceding Spill:			
Incident Reason:	UNKNOWN		
Incident Summary:	ONTARIO HYDRO-4.8 L 65% PCB OIL TO PAVEMENT		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	8471	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	8/22/1988	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	8/22/1988	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			

MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: ABOVE-GROUND TANK LEAK
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: UPLANDS AIRPORT - 50 L OF JET FUEL TO PAVEMENT FROM TANK TRUCK.
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No: 16382
Year:
Incident Dt: 3/27/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/27/1989
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:

Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: UPLANDS AIRPORT - 20 L OF JET FUEL TO GROUND.
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No: 21872
Year:
Incident Dt: 7/11/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/11/1989
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: SHELL REFUELING VEHICLE- 70 L AVIATION FUEL TO GROUND.
Environment Impact:
Health Env Consequence:
Nature of Impact:

Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No: 23253
Year:
Incident Dt: //
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/7/1989
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: SHELL- 4.5 LTR SPILL OF JET FUEL AT UPLANDS AIRPORT
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:

Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	26231	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	10/5/1989	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	10/5/1989	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	DEPT OF TRANSPORT

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: SHELL CANADA - 120L JET FUEL TO TERMINAL RAMP
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	81843	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	2/14/1993	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	

MOE Reported Dt:	2/14/1993	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	OTTAWA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	VALVE/FITTING LEAK OR FAILURE		
Incident Preceding Spill:			
Incident Reason:	UNKNOWN		
Incident Summary:	SHELL CANADA - 20 L OF AVIATION FUEL TO RAMP DUE TO TRUCK LEAK		
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Site: ***Shell Canada Products Limited***
Shell Canada Ottawa ON

Database: ***SPL***

Ref No:	6267-5M2K7H	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	4/28/2003	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	Oil
MOE Reported Dt:	4/28/2003	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	LOADING RACK 1<UNOFFICIAL>		
Site Address:			
Site Region:	Eastern		
Site Municipality:	Ottawa		
Site Lot:			

Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Shell Canada Products Limited
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill:
Incident Reason:
Incident Summary: Shell - 1L gasoline
Environment Impact: Possible
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 1 L
Contaminant Qty 1:
Contaminant Unit: L
Contaminant Code: 12
Contaminant Name: GASOLINE
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class: Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***UNKNOWN***
CYRVILLE DRAIN ON ST. LAURENT BLVD. OTTAWA CITY ON

Database: ***SPL***

Ref No: 99788
Year:
Incident Dt: //
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/12/1994
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: UNKNOWN
Incident Preceding Spill:
Incident Reason: UNKNOWN
Incident Summary: FAIR AMOUNT OF FUEL OIL INTO DRAIN,SOURCE UNKNOWNMOEE WILL NOTIFY WORKS

Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Water course or lake
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No: 81836
Year:
Incident Dt: 2/14/1993
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/14/1993
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: SHELL-25L OF JET A-1 FUELTO GROUND DURING FUELLINGCONTAINED, CLEANED UP.
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:

Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***SHELL CANADA PRODUCTS LTD.***
SERVICE STATION OTTAWA CITY ON

Database: ***SPL***

Ref No:	60160	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	11/24/1991	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	11/25/1991	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	SHELL, FIRE DEPT. TRIANGLE PUMP

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: OTHER CONTAINER LEAK
Incident Preceding Spill:
Incident Reason: CORROSION
Incident Summary: SHELL SERVICE STATION - 25 L. OF GASOLINE TO GROUND FROM LEAKY CAR
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***City of Ottawa***
Ogilvie Road (south of montreal rd) Ottawa ON

Database: ***SPL***

Ref No:	0248-BSEEXA	***Municipality No:***	

Year:		***Nature of Damage:***	
Incident Dt:	2020/08/12	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2020/08/12	***Impact to Health:***	2 - Minor Environment
Dt Document Closed:	2020/09/30	***Agency Involved:***	
Site No:	NA		
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	spill<UNOFFICIAL>		
Site Address:	Ogilvie Road (south of montreal rd)		
Site Region:	Eastern		
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	City of Ottawa		
Client Type:	Municipal Government		
Source Type:	Motor Vehicle		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Incident Reason:	Equipment Failure		
Incident Summary:	DUPLICATE OF 1085-BSEENY		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	25 L		
Contaminant Qty 1:	25		
Contaminant Unit:	L		
Contaminant Code:	27		
Contaminant Name:	COOLANT N.O.S.		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	n/a		
Receiving Medium:	Land		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Miscellaneous Communal		
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Site: ***PETRO-CANADA***
SERVICE STATION OTTAWA CITY ON

Database: ***SPL***

Ref No:	30833	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	2/12/1990	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2/12/1990	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			

Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: OTHER CONTAINER LEAK
Incident Preceding Spill:
Incident Reason: CORROSION
Incident Summary: PETRO CANADA SERVICE STN.FURANCE OIL LEAK.
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No: 30521
Year:
Incident Dt: 2/2/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/2/1990
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: VALVE/FITTING LEAK OR FAILURE

Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: SHELL TANK TRUCK-50 L AVIATION FUEL TO ASPHALT
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND / AIR
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***INTERLING FREIGHT LINES***
ST. LAURENT SHOPPING CENTRE. TRANSPORT TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No: 112925
Year:
Incident Dt: 5/9/1995
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/9/1995
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: UNKNOWN
Incident Summary: INTERLINK FREIGHT: 5 L DIESEL FUEL TO PAVED LOT,CONTAINED & CLEANED UP.
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Water course or lake
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:

Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***Tomlinson Environmental Services Ltd.***
Ottawa ON

Database: ***SPL***

Ref No: 0701-9KKJ43
Year:
Incident Dt: 2014/05/29
Dt MOE Arvl on Scn:
MOE Reported Dt: 2014/05/29
Dt Document Closed: 2014/11/07
Site No: NA
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 5555 power Road<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Tomlinson Environmental Services Ltd.
Client Type:
Source Type:
Incident Cause: Unknown / N/A
Incident Preceding Spill:
Incident Reason: Unknown / N/A
Incident Summary: Tomlinson Env: 100L oily water to lot, clnd
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s); Soil Contamination
Contaminant Qty: 100 L
Contaminant Qty 1: 100
Contaminant Unit: L
Contaminant Code: 15
Contaminant Name: OIL (PETROLEUM BASED, NOT SPECIFIED)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Unknown / N/A
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site: ***Bell Canada***
Ottawa ON

Database: ***SPL***

Ref No:	8881-9J2J33	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2014/04/10	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2014/04/10	***Impact to Health:***	
Dt Document Closed:	2014/11/04	***Agency Involved:***	
Site No:	NA		
MOE Response:	Referral to others		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	3212 Richmond Rd<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Bell Canada		
Client Type:			
Source Type:			
Incident Cause:	Leak/Break		
Incident Preceding Spill:			
Incident Reason:	Equipment Failure		
Incident Summary:	Bell Canada: possible >100 kg freon to atm.		
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:	0 other - see incident description		
Contaminant Qty 1:	0		
Contaminant Unit:	other - see incident description		
Contaminant Code:	38		
Contaminant Name:	FREON R-22 (CFC)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Pipeline/Components		
SAC Action Class:	Air Spills - Gases and Vapours		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	84404	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	4/21/1993	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	4/22/1993	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			

Site District Office:	
Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	OTTAWA CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE
Incident Preceding Spill:	
Incident Reason:	ERROR
Incident Summary:	SHELL CANADA - 40 L OF AVIATION FUEL AT GATE A DUE TO TRUCK LEAK
Environment Impact:	NOT ANTICIPATED
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Site:
lot 9 ON

Database:
WWIS

Well ID:	1528160	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	09/06/1994
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	137485	***Contractor:***	3644
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	009
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID: 10049699
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 08/23/1994
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931068782
Layer: 1
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 9.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931068783
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 12
Material 2 Desc: STONES
Material 3: 11
Material 3 Desc: GRAVEL
Formation Top Depth: 9.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931068784
Layer: 3
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 30.0

Formation End Depth: 63.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961528160
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10598269
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930086865
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 34.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930086866
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 63.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991528160
Pump Set At:
Static Level: 14.0
Final Level After Pumping: 50.0
Recommended Pump Depth: 50.0
Pumping Rate: 18.0
Flowing Rate:
Recommended Pump Rate: 15.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934387225
Test Type: Recovery
Test Duration: 30
Test Level: 14.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934905345
Test Type: Recovery
Test Duration: 60
Test Level: 14.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934112416
Test Type: Recovery
Test Duration: 15
Test Level: 15.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934656553
Test Type: Recovery
Test Duration: 45
Test Level: 14.0
Test Level UOM: ft

Water Details

Water ID: 933487754
Layer: 2
Kind Code: 5
Kind: Not stated
Water Found Depth: 56.0
Water Found Depth UOM: ft

Water Details

Water ID: 933487753
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 40.0
Water Found Depth UOM: ft

Site:
con 1 ON

Database: ***WWIS***

Well ID: 1525673
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No: 68558
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 10/21/1991
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3644
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 01

Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10047408
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/27/1991
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931061984
Layer: 1
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 32.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931061986
Layer: 3
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 45.0
Formation End Depth: 103.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931061985

Layer: 2
Color: 2
General Color: GREY
Material 1: 14
Material 1 Desc: HARDPAN
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 32.0
Formation End Depth: 45.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961525673
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10595978
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930082983
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 49.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930082984
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 103.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991525673
Pump Set At:
Static Level: 35.0
Final Level After Pumping: 55.0
Recommended Pump Depth: 55.0
Pumping Rate: 10.0
Flowing Rate:
Recommended Pump Rate: 8.0
Levels UOM: ft
Rate UOM: GPM

Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934105048
Test Type:
Test Duration: 15
Test Level: 55.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934388707
Test Type:
Test Duration: 30
Test Level: 55.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934906425
Test Type:
Test Duration: 60
Test Level: 55.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934649245
Test Type:
Test Duration: 45
Test Level: 55.0
Test Level UOM: ft

Water Details

Water ID: 933484724
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 70.0
Water Found Depth UOM: ft

Water Details

Water ID: 933484725
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 98.0
Water Found Depth UOM: ft

Site:
lot 7 ON

Database: ***WWIS***

Well ID: 1524618
Construction Date:
Use 1st: Cooling And A/C
Flowing (Y/N):
Flow Rate:
Data Entry Status:

Use 2nd:		***Data Src:***	1
Final Well Status:	Test Hole	***Date Received:***	06/21/1990
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	84331	***Contractor:***	5222
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	007
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	10046366	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	06/13/1990	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931058525
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	77
Material 2 Desc:	LOOSE
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	6.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931058526
Layer:	2
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	08
Material 2 Desc:	FINE SAND
Material 3:	

Material 3 Desc:
Formation Top Depth: 6.0
Formation End Depth: 12.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931058527
Layer: 3
Color: 8
General Color: BLACK
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3:
Material 3 Desc:
Formation Top Depth: 12.0
Formation End Depth: 21.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961524618
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10594936
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930081182
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 10.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Site:
lot 7 ON

Database: ***WWIS***

Well ID: 1528661
Construction Date:
Use 1st: Municipal
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: 147555
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 08/03/1995
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4006
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 007
Concession:

Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Concession Name: LI
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10050197
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/23/1995
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931070399
Layer: 3
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 31.0
Formation End Depth: 110.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931070400
Layer: 4
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2: 12
Material 2 Desc: STONES
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 110.0
Formation End Depth: 130.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931070397

Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931070398
Layer: 2
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2: 17
Material 2 Desc: SHALE
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 20.0
Formation End Depth: 31.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933113583
Layer: 2
Plug From: 15.0
Plug To: 115.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933113582
Layer: 1
Plug From: 0.0
Plug To: 15.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933113584
Layer: 3
Plug From: 115.0
Plug To: 130.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961528661
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID:	10598767
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930087739
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	130.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Water Details

Water ID:	933488460
Layer:	1
Kind Code:	5
Kind:	Not stated
Water Found Depth:	123.0
Water Found Depth UOM:	ft

Site: ***Database:*** ***WWIS***

con 1 ON

Well ID:	1529330	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Commerical	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Abandoned-Other	***Date Received:***	02/14/1997
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	169507	***Contractor:***	6844
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	10050866	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	12/06/1996	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931072413
Layer: 1
Color:
General Color:
Material 1: 23
Material 1 Desc: PREVIOUSLY DUG
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 17.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114302
Layer: 1
Plug From: 0.0
Plug To: 2.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114303
Layer: 2
Plug From: 2.0
Plug To: 17.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961529330
Method Construction Code: A
Method Construction: Digging
Other Method Construction:

Pipe Information

Pipe ID: 10599436
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930088795
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 17.0

Casing Diameter: 36.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933326678
Layer: 1
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 36.0

Water Details

Water ID: 933489269
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 6.0
Water Found Depth UOM: ft

Site:
lot 26 ON

Database:
WWIS

Well ID: 1529709
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No: 182706
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 12/22/1997
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1558
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 026
Concession:
Concession Name: LI
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10051244
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/11/1997
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931073578
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 79
Material 2 Desc: PACKED
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931073582
Layer: 5
Color: 1
General Color: WHITE
Material 1: 18
Material 1 Desc: SANDSTONE
Material 2: 73
Material 2 Desc: HARD
Material 3:
Material 3 Desc:
Formation Top Depth: 35.0
Formation End Depth: 75.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931073580
Layer: 3
Color: 2
General Color: GREY
Material 1: 14
Material 1 Desc: HARDPAN
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 13.0
Formation End Depth: 16.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931073581
Layer: 4
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2: 73
Material 2 Desc: HARD
Material 3:

Material 3 Desc:
Formation Top Depth: 16.0
Formation End Depth: 35.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931073579
Layer: 2
Color: 6
General Color: BROWN
Material 1: 14
Material 1 Desc: HARDPAN
Material 2: 13
Material 2 Desc: BOULDERS
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 4.0
Formation End Depth: 13.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114772
Layer: 1
Plug From: 22.0
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961529709
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10599814
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930089440
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 27.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930089441
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE

Depth From:
Depth To: 75.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991529709
Pump Set At:
Static Level: 12.0
Final Level After Pumping: 35.0
Recommended Pump Depth: 35.0
Pumping Rate: 30.0
Flowing Rate:
Recommended Pump Rate: 5.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934116660
Test Type:
Test Duration: 15
Test Level: 12.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934391634
Test Type:
Test Duration: 30
Test Level: 12.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934660796
Test Type:
Test Duration: 45
Test Level: 12.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934909333
Test Type:
Test Duration: 60
Test Level: 12.0
Test Level UOM: ft

Water Details

Water ID: 933489740
Layer: 1
Kind Code: 5
Kind: Not stated

Water Found Depth:
Water Found Depth UOM: ft

Site:
lot 26 ON

Database:
WWIS

Well ID:	1530327	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	12/08/1998
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	194764	***Contractor:***	1558
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	026
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	BF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	10051862	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	10/16/1998	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931075165
Layer:	2
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	86
Material 2 Desc:	STICKY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	11.0
Formation End Depth:	32.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID: 931075168
Layer: 5
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2: 73
Material 2 Desc: HARD
Material 3:
Material 3 Desc:
Formation Top Depth: 57.0
Formation End Depth: 71.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931075166
Layer: 3
Color: 2
General Color: GREY
Material 1: 14
Material 1 Desc: HARDPAN
Material 2: 13
Material 2 Desc: BOULDERS
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 32.0
Formation End Depth: 53.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931075167
Layer: 4
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 53.0
Formation End Depth: 57.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931075164
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 79
Material 2 Desc: PACKED
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 11.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	931075169
Layer:	6
Color:	2
General Color:	GREY
Material 1:	18
Material 1 Desc:	SANDSTONE
Material 2:	73
Material 2 Desc:	HARD
Material 3:	
Material 3 Desc:	
Formation Top Depth:	71.0
Formation End Depth:	223.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933115461
Layer:	1
Plug From:	53.0
Plug To:	45.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961530327
Method Construction Code:	5
Method Construction:	Air Percussion
Other Method Construction:	

Pipe Information

Pipe ID:	10600432
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930090406
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	59.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930090408
Layer:	3
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	175.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930090407
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	125.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991530327
Pump Set At:	
Static Level:	21.0
Final Level After Pumping:	55.0
Recommended Pump Depth:	90.0
Pumping Rate:	6.0
Flowing Rate:	
Recommended Pump Rate:	5.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Draw Down & Recovery

Pump Test Detail ID:	934662465
Test Type:	Recovery
Test Duration:	45
Test Level:	22.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934911009
Test Type:	Recovery
Test Duration:	60
Test Level:	21.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934393315
Test Type:	Recovery
Test Duration:	30
Test Level:	24.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934118327
Test Type:	Recovery
Test Duration:	15
Test Level:	26.0
Test Level UOM:	ft

Water Details

Water ID:	933490419
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	115.0
Water Found Depth UOM:	ft

Water Details

Water ID:	933490421
Layer:	3
Kind Code:	1
Kind:	FRESH
Water Found Depth:	211.0
Water Found Depth UOM:	ft

Water Details

Water ID:	933490420
Layer:	2
Kind Code:	1
Kind:	FRESH
Water Found Depth:	148.0
Water Found Depth UOM:	ft

Site:
lot 26 ON

Database:
WWIS

Well ID:	1530328	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Livestock	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Abandoned-Quality	***Date Received:***	12/08/1998
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	194762	***Contractor:***	1558
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	026
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	BF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	10051863	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	10/19/1998	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 933115462
Layer: 1
Plug From: 36.0
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961530328
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 10600433
Casing No: 1
Comment:
Alt Name:

Site:
lot 9 ON

Database: ***WWIS***

Well ID: 1534130
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No: 265562
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 10/23/2003
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1119
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 009
Concession:
Concession Name: BF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10543245
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/10/2003
Remarks:
Location Method Desc: Not Applicable i.e. no UTM

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932925089
Layer: 3
Color: 2
General Color: GREY
Material 1: 18
Material 1 Desc: SANDSTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 106.0
Formation End Depth: 220.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932925087
Layer: 1
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 59.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932925088
Layer: 2
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 59.0
Formation End Depth: 106.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933240997
Layer: 1
Plug From: 0.0
Plug To: 64.0

Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961534130
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 11091815
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930098283
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To:
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930098284
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To:
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991534130
Pump Set At:
Static Level: 12.0
Final Level After Pumping: 200.0
Recommended Pump Depth: 200.0
Pumping Rate: 3.0
Flowing Rate:
Recommended Pump Rate: 3.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934657211

Test Type: Recovery
Test Duration: 45
Test Level: 92.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934914658
Test Type: Recovery
Test Duration: 60
Test Level: 56.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934113637
Test Type: Recovery
Test Duration: 15
Test Level: 164.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934397251
Test Type: Recovery
Test Duration: 30
Test Level: 128.0
Test Level UOM: ft

Water Details

Water ID: 934037038
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 185.0
Water Found Depth UOM: ft

Water Details

Water ID: 934037039
Layer: 2
Kind Code: 5
Kind: Not stated
Water Found Depth: 203.0
Water Found Depth UOM: ft

Site:
lot 8 ON

Database: ***WWIS***

Well ID: 1500396
Construction Date:
Use 1st: Domestic
Use 2nd: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 02/26/1948
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1107
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 008
Concession:
Concession Name: JG

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: OTTAWA CITY (GLOUCESTER)
Site Info:

Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10022441
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/29/1947
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 930989161
Layer: 1
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 28.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930989162
Layer: 2
Color:
General Color:
Material 1: 26
Material 1 Desc: ROCK
Material 2: 19
Material 2 Desc: SLATE
Material 3:
Material 3 Desc:
Formation Top Depth: 28.0
Formation End Depth: 51.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961500396
Method Construction Code: 1

Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10571011
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930037815
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 28.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930037816
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 51.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: BAILER
Pump Test ID: 991500396
Pump Set At:
Static Level: 6.0
Final Level After Pumping: 6.0
Recommended Pump Depth:
Pumping Rate: 8.0
Flowing Rate:
Recommended Pump Rate: 8.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 2
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933452913
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 51.0
Water Found Depth UOM: ft

Site: ***Database:***

Well ID:	1501587	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	01/06/1947
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	3566
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	10023630	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	11/15/1946	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930992252
Layer:	2
Color:	
General Color:	
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	90.0
Formation End Depth:	167.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930992251
Layer:	1
Color:	2
General Color:	GREY

Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 90.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961501587
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572200
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930040106
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 92.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930040107
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 167.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991501587
Pump Set At:
Static Level: 10.0
Final Level After Pumping: 30.0
Recommended Pump Depth:
Pumping Rate: 30.0
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1

Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933454305
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth:
Water Found Depth UOM: ft

Site:
lot 26 ON

Database:
WWIS

Well ID: 1519599
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 05/28/1985
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1558
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 026
Concession:
Concession Name: BF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10041469
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 05/14/1985
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931042175
Layer: 4
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:

Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 49.0
Formation End Depth: 65.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931042172
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 17.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931042173
Layer: 2
Color: 2
General Color: GREY
Material 1: 14
Material 1 Desc: HARDPAN
Material 2: 13
Material 2 Desc: BOULDERS
Material 3:
Material 3 Desc:
Formation Top Depth: 17.0
Formation End Depth: 40.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931042174
Layer: 3
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 13
Material 3 Desc: BOULDERS
Formation Top Depth: 40.0
Formation End Depth: 49.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961519599
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10590039
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930072411
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 51.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930072412
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 65.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991519599
Pump Set At:
Static Level: 14.0
Final Level After Pumping: 20.0
Recommended Pump Depth: 30.0
Pumping Rate: 20.0
Flowing Rate:
Recommended Pump Rate: 5.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934383821
Test Type: Draw Down
Test Duration: 30
Test Level: 20.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934108530
Test Type: Draw Down

Test Duration: 15
Test Level: 20.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934653801
Test Type: Draw Down
Test Duration: 45
Test Level: 20.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934894144
Test Type: Draw Down
Test Duration: 60
Test Level: 20.0
Test Level UOM: ft

Water Details

Water ID: 933476639
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 55.0
Water Found Depth UOM: ft

Site:
con 1 ON

Database: ***WWIS***

Well ID: 1519865
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 09/16/1985
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1558
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 01
Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10041718
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 08/01/1985
Remarks:
Location Method Desc: Not Applicable i.e. no UTM

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931042997
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 81
Material 2 Desc: SANDY
Material 3: 11
Material 3 Desc: GRAVEL
Formation Top Depth: 5.0
Formation End Depth: 60.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931042996
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931042998
Layer: 3
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 60.0
Formation End Depth: 75.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961519865
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10590288
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930072830
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 62.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930072831
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 75.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991519865
Pump Set At:
Static Level: 25.0
Final Level After Pumping: 30.0
Recommended Pump Depth: 50.0
Pumping Rate: 10.0
Flowing Rate:
Recommended Pump Rate: 5.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934384474
Test Type: Draw Down
Test Duration: 30
Test Level: 30.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934109742
Test Type: Draw Down

Test Duration: 15
Test Level: 30.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934655014
Test Type: Draw Down
Test Duration: 45
Test Level: 30.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934895214
Test Type: Draw Down
Test Duration: 60
Test Level: 30.0
Test Level UOM: ft

Water Details

Water ID: 933476954
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 70.0
Water Found Depth UOM: ft

Site:
lot 9 ON

Database: ***WWIS***

Well ID: 1520604
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No: NA
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 08/12/1986
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3644
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 009
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10042446
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/05/1986
Remarks:
Location Method Desc: Not Applicable i.e. no UTM

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931045287
Layer: 2
Color: 2
General Color: GREY
Material 1: 14
Material 1 Desc: HARDPAN
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 13.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931045289
Layer: 4
Color: 1
General Color: WHITE
Material 1: 18
Material 1 Desc: SANDSTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 95.0
Formation End Depth: 105.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931045288
Layer: 3
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 25.0
Formation End Depth: 95.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931045286
Layer: 1
Color: 2
General Color: GREY

Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 13.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961520604
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10591016
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930074086
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 105.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930074085
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 27.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991520604
Pump Set At:
Static Level: 15.0
Final Level After Pumping: 60.0
Recommended Pump Depth: 60.0
Pumping Rate: 50.0
Flowing Rate:
Recommended Pump Rate: 15.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1

Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934387353
Test Type:
Test Duration: 30
Test Level: 60.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934906158
Test Type:
Test Duration: 60
Test Level: 60.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934648376
Test Type:
Test Duration: 45
Test Level: 60.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934112490
Test Type:
Test Duration: 15
Test Level: 60.0
Test Level UOM: ft

Water Details

Water ID: 933477896
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 100.0
Water Found Depth UOM: ft

Water Details

Water ID: 933477895
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 55.0
Water Found Depth UOM: ft

Site:
lot 7 ON

Database:
WWIS

Well ID: 1522583
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 09/27/1988
Selected Flag: TRUE

Casing Material:
Audit No: 38250
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Abandonment Rec:
Contractor: 1558
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 007
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10044395
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 08/13/1988
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931051957
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 79
Material 2 Desc: PACKED
Material 3:
Material 3 Desc:
Formation Top Depth: 4.0
Formation End Depth: 13.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931051958
Layer: 3
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 13.0
Formation End Depth: 55.0

Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931051960
Layer: 5
Color: 2
General Color: GREY
Material 1: 18
Material 1 Desc: SANDSTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 69.0
Formation End Depth: 100.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931051959
Layer: 4
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 55.0
Formation End Depth: 69.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931051956
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 79
Material 2 Desc: PACKED
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961522583
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10592965
Casing No: 1

Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930077635
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 74.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930077636
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 100.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991522583
Pump Set At:
Static Level: 20.0
Final Level After Pumping: 50.0
Recommended Pump Depth: 60.0
Pumping Rate: 20.0
Flowing Rate:
Recommended Pump Rate: 5.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934110919
Test Type: Draw Down
Test Duration: 15
Test Level: 50.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934904535
Test Type: Draw Down
Test Duration: 60
Test Level: 50.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934386344
Test Type: Draw Down
Test Duration: 30
Test Level: 50.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934656138
Test Type: Draw Down
Test Duration: 45
Test Level: 50.0
Test Level UOM: ft

Water Details

Water ID: 933480533
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 70.0
Water Found Depth UOM: ft

Water Details

Water ID: 933480534
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 93.0
Water Found Depth UOM: ft

Site:
lot 8 ON

Database: ***WWIS***

Well ID: 1522708
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No: 27005
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 10/26/1988
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3644
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 008
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10044518
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:

Cluster Kind:
Date Completed: 06/27/1988
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931052354
Layer: 1
Color: 2
General Color: GREY
Material 1: 14
Material 1 Desc: HARDPAN
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 35.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931052355
Layer: 2
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 35.0
Formation End Depth: 64.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961522708
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10593088
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930077851
Layer: 1
Material: 1

Open Hole or Material: STEEL
Depth From:
Depth To: 38.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930077852
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 64.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991522708
Pump Set At:
Static Level: 15.0
Final Level After Pumping: 50.0
Recommended Pump Depth: 50.0
Pumping Rate: 20.0
Flowing Rate:
Recommended Pump Rate: 10.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934905074
Test Type:
Test Duration: 60
Test Level: 50.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934386881
Test Type:
Test Duration: 30
Test Level: 50.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934656257
Test Type:
Test Duration: 45
Test Level: 50.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934111037
Test Type:
Test Duration: 15
Test Level: 50.0
Test Level UOM: ft

Water Details

Water ID: 933480702
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 56.0
Water Found Depth UOM: ft

Site:
lot 8 ON

Database: ***WWIS***

Well ID: 1523343
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No: 39079
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 04/04/1989
Selected Flag: TRUE
Abandonment Rec:
Contractor: 5222
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot: 008
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10045118
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/05/1988
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931054290
Layer: 2
Color: 6
General Color: BROWN

Material 1: 05
Material 1 Desc: CLAY
Material 2: 12
Material 2 Desc: STONES
Material 3: 13
Material 3 Desc: BOULDERS
Formation Top Depth: 6.0
Formation End Depth: 35.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931054291
Layer: 3
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 12
Material 2 Desc: STONES
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 35.0
Formation End Depth: 40.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931054289
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 77
Material 2 Desc: LOOSE
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 6.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931054292
Layer: 4
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 28
Material 2 Desc: SAND
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 40.0
Formation End Depth: 45.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933110253

Layer: 1
Plug From: 0.0
Plug To: 35.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961523343
Method Construction Code: 4
Method Construction: Rotary (Air)
Other Method Construction:

Pipe Information

Pipe ID: 10593688
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930078929
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 45.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991523343
Pump Set At:
Static Level: 10.0
Final Level After Pumping: 25.0
Recommended Pump Depth: 25.0
Pumping Rate: 20.0
Flowing Rate:
Recommended Pump Rate: 10.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934104458
Test Type: Draw Down
Test Duration: 15
Test Level: 25.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934649669
Test Type: Draw Down

Test Duration: 45
Test Level: 25.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934907292
Test Type: Draw Down
Test Duration: 60
Test Level: 25.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934389106
Test Type: Draw Down
Test Duration: 30
Test Level: 25.0
Test Level UOM: ft

Water Details

Water ID: 933481564
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 45.0
Water Found Depth UOM: ft

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Nov 2024

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Apr 2024

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Apr 30, 2024

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2022

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Apr 30, 2024

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Feb 2025

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Apr 2025

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Apr 30, 2025

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database (ODHD) is offered by the Province of Ontario's Ministry of Mines. The dataset contains information for over 164,000 percussion, overburden, sonic and diamond-drill holes. The presence of assay results with cutoff values for gold, silver, copper, zinc, lead, nickel and platinum group elements is noted. Drill hole data are compiled from assessment files that have been submitted to the ministry in accordance with the Ontario Mining Act (OMA). Source assessment file numbers are captured for cross reference with the Ontario Assessment File Database (OAFD). Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Aug 2024

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011 - Apr 30, 2025

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Apr 30, 2025

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011 - Apr 30, 2025

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Aug 31, 2024

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment, Conservation and Parks (MECP). These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2024

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Jan 2025

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: Oct 31, 2021

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. As of January 1, 2023, businesses and institutions subject to the amended Reg. 347: General – Waste Management are required to report their activities and pay fees through Resource Productivity & Recovery Authority (RPRA) online Hazardous Waste Program Registry (HWPR) rather than the Hazardous Waste Information Network (HWIN) system previously operated by the Ministry of the Environment, Conservation and Parks (MECP). Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Dec 31, 2024

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Apr 2024

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: 31 Oct, 2023

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2025

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment Conservation and Parks (MECP) provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act. MECP publicly releases the Environmental Compliance Report (ECR) on the Ontario Data Catalogue. In Ontario, all facilities with regulated wastewater discharges or air emissions under the Ontario Water Resources Act and the Environmental Protection Act must monitor and report any cases where approved operating limits have been exceeded.

Government Publication Date: Dec 31, 2023

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Feb 28, 2025

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Feb 2024

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Feb 28, 2025

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the Ministry of Natural Resources (MNR) handed over to the Ontario Oil, Gas and Salt Resources (OGSR) Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database includes well owner/operator, location, permit issue date, and well cap date, license number, status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provided for each well record.

Government Publication Date: 1800-Aug 2024

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Apr 30, 2025

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011 - Apr 30, 2025

Ontario PFAS Spills: Provincial PFAS

This specific list of spills includes those incidents where one or more of the listed contaminants are identified in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA), is originally sourced from the Ministry of the Environment, Conservation and Parks spills related data. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Jun 2024; Aug 2024; Oct-Nov 2024

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Feb 2024

Potential PFAS Handlers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Feb 2024

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Potential PFAS Handlers from EASR: Provincial PPHA

The Ontario Environmental Activity and Sector Registry (EASR), described in Ontario Regulation 245/11, allows businesses with less complex operations - and hence not requiring an Environmental Compliance Approval - to register their activities with the Ontario Ministry of the Environment, Conservation and Parks (MECP). This list of potential PFAS handlers includes those EASR facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used.

Government Publication Date: Jun 30, 2024

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Apr 30, 2025

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004-Apr 2025

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Apr 30, 2024

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Jun 2024; Aug-Feb 2025

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2021

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2024

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011 - Apr 30, 2025

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Dec 31 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX F

City Directory Records

CITY DIRECTORY

Project Property:	*Phase I Environmental Site Assessment - 1052 St. Laurent, Ottawa, Ontario* *1052 St. Laurent Blvd* *Ottawa,ON K1K 3B4*
Project No:	*103499.001*
Requested By:	*GEMTEC Consulting Engineers and Scientists Limited (Ontario)*
Order No:	*24053100257*
Date Completed:	*June 14, 2024*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

June 14, 2024
RE: CITY DIRECTORY RESEARCH
1052 St. Laurent Blvd
Ottawa,ON K1K 3B4

Thank you for contacting ERIS regarding our City Directory Search services. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. When searching a range of addresses, all civic addresses within that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on highly developed areas, while newly developed areas may be covered in the more recent years, older directories tend to cover only "central" parts of the city. To complete the search, we have either utilized the Toronto Reference Library, Library & Archives Canada and multiple digitized directories. While these do not claim to be a complete collection of all reverse listing city directories produced, ERIS has made every effort to provide accurate and complete information. ERIS shall not be held liable for missing, incomplete, or inaccurate information. If you believe there are additional addresses or streets that require searching, please contact us.

Search Criteria:

640-745 of Alesther Street

725 of Bernard Street

1015-1050 of Cyrville Road

580-1240 Even of Donald Street

550-600 of Prince Albert Street

555-600 of Queen Mary Street

995-1110 of Saint Laurent Boulevard

40-60 of Stately Private

445-605 of Wolffdale Crescent

Search Notes:

Wolffdale Crescent is also known as 445-605 Wolffdale Avenue in Ottawa. Bernard Street is also known as 725 Hardy Avenue in Ottawa.

Search Results Summary

Data from 2012 to 2021 does not include residential information

Date	Source	Comment
2021	DIGITAL BUSINESS DIRECTORY	
2017	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2006-07	VERNONS	
2000	POLKS	
1993-94	POLKS	
1987	MIGHTS	
1981-82	MIGHTS	
1976	MIGHTS	
1971	MIGHTS	
1966	MIGHTS	
1960	MIGHTS	
1955	MIGHTS	
1950	MIGHTS	

2021 ALESTHER STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2021 BERNARD STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

725 **OPTIONS BYTOWN NON PROFIT HSNG...** *SOCIAL SERVICE & WELFARE ORGANIZATIONS*

2021 CYRVILLE ROAD

SOURCE: DIGITAL BUSINESS DIRECTORY

1018 **PETRO-CANADA**...*ALTERNATIVE FUELS*
1021 **DOLLAR TREE**...*VARIETY STORES*
1021 **FOOD BASICS**...*GROCERS-RETAIL*
1021 **GLOBAL PET FOODS**...*FEDERAL GOVERNMENT CONTRACTORS*
1021 **HARMONY DENTISTRY**...*DENTISTS*
1021 **LA WEIGHT LOSS**...*WEIGHT CONTROL SERVICES*
1021 **PARTY CITY**...*DECORATION SUPPLIES-MANUFACTURERS*
1021 **POPEYE'S SUPPLEMENTS**...*VITAMIN & FOOD SUPPLEMENTS*
1021 **WESTERN UNION AGENT LOCATION**...*BILL PAYING SERVICE*
1050 **MATTRESS OUTLET**...*FURNITURE-DEALERS-RETAIL*

2021 DONALD STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

610 **INTERCONTINENTAL MUSIC LTD**...*MUSICAL INSTRUMENTS-DEALERS*

2021 PRINCE ALBERT STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2021 QUEEN MARY STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

557	**ANDREW FLECK CHILD CARE SVC**	*CHILD CARE SERVICE*
557	**OVERBROOK DAY CARE KNDRGRTN**	*CHILD CARE SERVICE*
557	**QUEEN MARY STREET PUBLIC SCH**	*SCHOOLS*
592	**CAPITAL CITY PLUMBING DRAIN**	*HEATING CONTRACTORS*

2021 SAINT LAURENT BOULEVARD

SOURCE: DIGITAL BUSINESS DIRECTORY

997 **CASH MONEY**...*CHECK CASHING SERVICE*
997 **CLORE BEAUTY SUPPLIES**...*BEAUTY SALONS*
997 **WESTERN UNION AGENT LOCATION**...*MONEY ORDER SERVICE*
1007 **MC DONALD'S**...*FOODS-CARRY OUT*
1007 **PETRO-CANADA**...*ALTERNATIVE FUELS*
1020 **ACACCIA FINE PASTRY DESSERT**...*BAKERS-RETAIL*
1020 **ALADDIN BAKERY**...*BAKERS-RETAIL*
1020 **AROMA SALT THRPY BEAUTY SPA**...*EXERCISE & PHYSICAL FITNESS PROGRAMS*
1020 **FUSION BOUTIQUE**...*CLOTHING-RETAIL*
1020 **GEELAND**...*GROCERS-RETAIL*
1020 **GIROUX RENE MEN'S WEAR LTD**...*CLOTHING-MANUFACTURERS*
1020 **MAMA CEE BEAUTY SALON**...*BARBERS*
1020 **MAMA CEE BEAUTY SALON SUPLS**...*LINGERIE*
1020 **MANGO CAFE**...*FOODS-CARRY OUT*
1020 **PHARMASAVE**...*PHARMACIES*
1021 **GIANT TIGER**...*SOCIAL SERVICE & WELFARE ORGANIZATIONS*
1021 **METRO**...*GROCERS-RETAIL*
1052 **HOWARD'S PAWN SHOP**...*JEWELERS-RETAIL*
1052 **MR GOLD CASH**...*JEWELERS-RETAIL*
1055 **BOSTON PIZZA**...*FOODS-CARRY OUT*
1055 **DECATHLON**...*SPORTING GOODS-RETAIL*
1060 **BROTHER WU RESTAURANT**...*FOODS-CARRY OUT*
1076 **JOES SMOKESHOP GROCERY**...*GROCERS-RETAIL*
1091 **BURRITO GRINGO**...*FOODS-CARRY OUT*
1091 **FIRST CHOICE HAIRCUTTERS**...*HAIR GOODS & SUPPLIES-RETAIL*
1091 **MASTERMIND TOYS**...*TOYS-RETAIL*
1091 **MONEY MART**...*CHECK CASHING SERVICE*
1091 **SALLY BEAUTY**...*BARBERS EQUIPMENT & SUPPLIES-MFRS*
1099 **BIGG'S DELI BAR**...*FOODS-CARRY OUT*
1110 **MERCEDES-BENZ CANADA INC**...*AUTOMOBILE REPAIRING & SERVICE*

2021 STATELY PRIVATE

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2021 WOLFFDALE CRESCENT

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2017 ALESTHER STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2017 BERNARD STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

725 **OPTIONS BYTOWN NON PROFIT HSNG**...*OTHER INDIVIDUAL & FAMILY SVCS*

2017 CYRVILLE ROAD

SOURCE: DIGITAL BUSINESS DIRECTORY

1018 **PETRO-CANADA**...*OTHER GASOLINE STATIONS*
1021 **1770765 ONTARIO INC**...*FULLSERVICE RESTAURANTS*
1021 **BANQUE LAURENTIENNE DU CANADA**...*COMMERCIAL BANKING*
1021 **DOLLAR TREE**...*ALL OTHER GENERAL MERCHANDISE STORES*
1021 **FOOD BASICS**...*SUPERMARKETS & OTHER GROCERY STORES*
1021 **L A WEIGHT LOSS**...*DIET & WEIGHT REDUCING CENTERS*
1021 **LAURIER OPTICAL**...*OFFICES OF OPTOMETRISTS*
1021 **MAGICUTS**...*BEAUTY SALONS*
1021 **MARK'S WORK WEARHOUSE**...*MEN'S CLOTHING STORES*
1021 **PARTY CITY**...*PARTY SUPPLIES*
1021 **POPEYE'S SUPPLEMENTS OTTAWA**...*FOOD, HEALTH, SUPPLEMENT STORES*
1021 **R E HEIN CONSTRUCTION**...*NEW SINGLEFAMILY GENERAL CONTRS*
1050 **BEDZZZ**...*FURNITURE STORES*
1050 **MOBILE PRESSURE CLEANING**...*COMPUTER & OFFICE MACHINE REPAIR*

2017 DONALD STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

610 **INTERCONTINENTAL MUSIC LTD**...*MUSICAL INSTRUMENT & SUPPLIES STORES*
610 **INTEX DISTRIBUTEUR D'INSTRS**...*MUSICAL INSTRUMENT & SUPPLIES STORES*
610 **INTEX MUSICAL INSTRUMENT DISTR**...*MUSICAL INSTRUMENT & SUPPLIES STORES*
1240 **BOGEL CONSTRUCTION**...*NEW SINGLEFAMILY GENERAL CONTRS*
1240 **GREENWIN INC**...*OFFICES OF REAL ESTATE AGENTS & BROKERS*
1240 **MASJID-DARIL-SALAM**...*RELIGIOUS ORGANIZATION*

2017 PRINCE ALBERT STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2017 QUEEN MARY STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

557 **OVERBROOK DAY CARE KNDRGRTN**...*CHILD DAY CARE SVCS*
557 **QUEEN MARY STREET SCHOOL**...*ELEMENTARY & SECONDARY SCHOOLS*

2017 SAINT LAURENT BOULEVARD

SOURCE: DIGITAL BUSINESS DIRECTORY

997 **BLEEKER STEREO TV LTD**...*HOUSEHOLD APPLIANCE STORES*
997 **CASH MONEY**...*PAYDAY LOANS*
997 **CLORE BEAUTY SUPPLIES**...*BEAUTY SALONS-EQUIPMENT & SUPLS (WHLS)*
997 **CODY PARTY CTR**...*GIFT, NOVELTY, & SOUVENIR STORES*
997 **WESTERN UNION**...*FINANCIAL TRANSACTION PROCESSING & CLEARING*
1000 **DANIER LEATHER**...*LUGGAGE & LEATHER GOODS STORES*
1007 **MC DONALD'S**...*LIMITEDSERVICE RESTAURANTS*
1007 **ST LAURENT SUNOCO**...*OTHER GASOLINE STATIONS*
1020 **1 FOR 1 PIZZA**...*FULL-SERVICE RESTAURANTS*
1020 **ALADDIN BAKERY**...*RETAIL BAKERIES*
1020 **CASH CONVERTERS**...*USED MERCHANDISE STORES*
1020 **CHATEAU FINE PASTRY**...*RETAIL BAKERIES*
1020 **DOUBLE DOUBLE PIZZA CHICKEN**...*LIMITEDSERVICE RESTAURANTS*
1020 **FINANCIERE WELLS FARGO**...*REAL ESTATE CREDIT*
1020 **FUSION BOUTIQUE**...*WOMEN'S CLOTHING STORES*
1020 **GEELAND**...*SUPERMARKETS & OTHER GROCERY STORES*
1020 **MAMA CEE BEAUTY SALON**...*BEAUTY SALONS*
1020 **MAMA CEE BEAUTY SALON SUPLS**...*BEAUTY SALONS*
1020 **MANGO CAFE**...*FULLSERVICE RESTAURANTS*
1020 **MERCERIE RENE GIROUX**...*MEN'S CLOTHING STORES*
1020 **RENE GIROUX MEN'S WEAR HATS**...*MEN'S CLOTHING STORES*
1020 **TONI'S FASHION**...*WOMEN'S CLOTHING STORES*
1021 **METRO**...*SUPERMARKETS & OTHER GROCERY STORES*
1033 **CLUB PARADISE TANNING STUDIO**...*OTHER PERSONAL CARE SVCS*
1037 **FIRST CHOICE HAIRCUTTERS**...*BEAUTY SALONS*
1037 **HYDRAGREEN**...*UNCLASSIFIED*
1045 **SOURCE**...*RADIO, TV & OTHER ELECTRONICS STORES*
1051 **FEDERAL SUPERANNUATES NATIONAL ASSOCIATION**...*DENTAL*
1055 **BLUE ORCHARD TECHNOLOGIES**...*FARMS*
1055 **BOSTON PIZZA**...*FULL-SERVICE RESTAURANTS*
1055 **CNIB CORNER STORE**...*OTHER GAMBLING INDUSTRIES*
1055 **TARGET**...*CHILDREN'S & INFANTS' CLOTHING STORES*
1055 **ZELLERS INC**...*DEPARTMENT STORES, EXCEPT DISCOUNT*
1060 **BROTHER WU RESTAURANT**...*FULL-SERVICE RESTAURANTS*
1064 **MIDAS AUTO SVC EXPERTS**...*GENERAL AUTOMOTIVE REPAIR*
1064 **MIDAS L'EXPERT ENTRETIEN**...*GENERAL AUTOMOTIVE REPAIR*
1076 **SAMMY'S CORNER CONFECTIONERY**...*CONVENIENCE STORES*
1076 **SAMMYS CONVENIENCE**...*CONVENIENCE STORES*
1091 **MONEY MART**...*FINANCIAL TRANSACTION PROCESSING & CLEARING*
1091 **PARTSOURCE**...*AUTOMOTIVE PARTS & ACCESSORIES STORES*
1091 **QUIZNOS**...*LIMITEDSERVICE RESTAURANTS*
1091 **RANDSTAD INTERIM INC**...*EMPLOYMENT PLACEMENT AGENCIES*
1091 **RIO CAN REIT**...*UNCLASSIFIED*
1091 **SALLY BEAUTY SUPPLY**...*COSMETIC & BEAUTY SUPPLY STORES*
1099 **BIGG'S DELI & BAR**...*FULL-SERVICE RESTAURANTS*
1110 **MERCEDES-BENZ SALES SVC**...*USED CAR DEALERS*
1110 **OGILVIE MERCEDES-BENZ**...*NEW CAR DEALERS*
1110 **OGILVIE REALTY LTD**...*OFFICES OF REAL ESTATE AGENTS & BROKERS*

2017 STATELY PRIVATE

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2017 WOLFFDALE CRESCENT

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2012 ALESTHER STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

733 **ST PREUX HERRIOT JEAN-BAPTISTE**...*UNCLASSIFIED*

2012 BERNARD STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

725 **OPTIONS BYTOWN NON PROFIT HSNG**...*OTHER INDIVIDUAL & FAMILY SVCS*

2012 CYRVILLE ROAD

SOURCE: DIGITAL BUSINESS DIRECTORY

1018 **PETRO-CANADA**...*OTHER GASOLINE STATIONS*
1021 **BANQUE LAURENTIENNE DU CANADA**...*COMMERCIAL BANKING*
1021 **DOLLAR BLITZ REALTY LTD**...*OFFICES OF REAL ESTATE AGENTS & BROKERS*
1021 **FOOD BASICS**...*SUPERMARKETS & OTHER GROCERY STORES*
1021 **MARK'S WORK WEARHOUSE**...*OTHER CLOTHING STORES*
1021 **PETCETERA**...*PET SERVICES*
1021 **POPEYE'S SUPPLEMENTS OTTAWA**...*FOOD, HEALTH, SUPPLEMENT STORES*
1021 **R E HEIN CONSTRUCTION**...*NEW SINGLE-FAMILY GENERAL CONTRS*
1050 **BEDZZZ**...*FURNITURE STORES*

2012 DONALD STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

610 **INTERCONTINENTAL MUSIC**...*MUSICAL INSTRUMENT & SUPPLIES STORES*
610 **INTEX DISTRIBUTEUR**...*MUSICAL INSTRUMENT & SUPPLIES STORES*
1240 **BOGEL CONSTRUCTION**...*NEW SINGLE-FAMILY GENERAL CONTRS*
1240 **DENTEK COMPUTER**...*COMPUTER & OFFICE MACHINE REPAIR*
1240 **EASTERN OTTAWA RESOURCE CTR**...*OTHER INDIVIDUAL & FAMILY SVCS*
1240 **MASJID-DARIL-SALAM**...*RELIGIOUS ORGANIZATION*

2012 PRINCE ALBERT STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2012 QUEEN MARY STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

557 **OVERBROOK DAY CARE KNDRGRTN**...*CHILD DAY CARE SVCS*

557 **QUEEN MARY STREET SCHOOL**...*ELEMENTARY & SECONDARY SCHOOLS*

579 **OSTCO CARPET IMPROVEMENTS INC**...*CARPET & UPHOLSTERY CLEANING SVCS*

2012 SAINT LAURENT BOULEVARD

SOURCE: DIGITAL BUSINESS DIRECTORY

997 **BLEEKER STEREO & TV LTD**...*HOUSEHOLD APPLIANCE STORES*
1007 **ST LAURENT SUNOCO**...*OTHER GASOLINE STATIONS*
1008 **GUY COURCHAINE RADIO & TV RPR**...*RADIO, TV & OTHER ELECTRONICS STORES*
1020 **1 FOR 1 PIZZA**...*LIMITED-SERVICE RESTAURANTS*
1020 **ALADDIN BAKERY**...*RETAIL BAKERIES*
1020 **CASH CONVERTERS**...*USED MERCHANDISE STORES*
1020 **CHATEAU FINE PASTRY**...*RETAIL BAKERIES*
1020 **DOUBLE DOUBLE PIZZA & CHICKEN**...*FULL-SERVICE RESTAURANTS*
1020 **DOUBLE PIZZA**...*FULL-SERVICE RESTAURANTS*
1020 **EURO CLASSIC FLORIST**...*FLORISTS*
1020 **FINANCIERE WELLS FARGO**...*REAL ESTATE CREDIT*
1020 **FUSION BOUTIQUE**...*WOMEN'S CLOTHING STORES*
1020 **GEELAND**...*SUPERMARKETS & OTHER GROCERY STORES*
1020 **LAYALINA**...*FULL-SERVICE RESTAURANTS*
1020 **MAMA CEE 2**...*WHOLESALE TRADE AGENTS & BROKERS*
1020 **MAMA CEE BEAUTY SALON & SUPPLY**...*BEAUTY SALONS*
1020 **MANGO'S**...*FULL-SERVICE RESTAURANTS*
1020 **R C REETTES FOODS**...*SUPERMARKETS & OTHER GROCERY STORES*
1020 **RENE GIROUX MEN'S WEAR**...*MEN'S CLOTHING STORES*
1020 **SATTRONICS**...*WIRED TELECOMMUNICATIONS CARRIERS*
1020 **STAR PLAY**...*RADIO, TV & OTHER ELECTRONICS STORES*
1021 **LOEB CANADA INC**...*SUPERMARKETS & OTHER GROCERY STORES*
1025 **SCOTIABANK**...*COMMERCIAL BANKING*
1033 **SPA CLUB ST LAURENT**...*FITNESS & RECREATIONAL SPORTS CENTERS*
1037 **FIRST CHOICE HAIRCUTTERS**...*BEAUTY SALONS*
1037 **HYDRAGREEN**...*UNCLASSIFIED*
1045 **RADIO SHACK**...*RADIO, TV & OTHER ELECTRONICS STORES*
1052 **FEDERAL SUPERNNAUATES NATIONAL**...*BUSINESS ASSOCIATIONS*
1055 **BLUE ORCHARD TECHNOLOGIES**...*FARMS*
1055 **BOSTON PIZZA**...*FULL-SERVICE RESTAURANTS*
1055 **CLUB PARADISE TANNING STUDIO**...*OTHER PERSONAL CARE SVCS*
1055 **CNIB CORNER STORE**...*OTHER GAMBLING INDUSTRIES*
1055 **DAHN YOGA**...*MISC SCHOOLS & INSTRUCTION*
1055 **ONLY DEALS DOLLAR STORE**...*OTHER GAMBLING INDUSTRIES*
1055 **ZELLERS INC**...*DEPARTMENT STORES, EXCEPT DISCOUNT*
1060 **BROTHER WU RESTAURANT**...*FULL-SERVICE RESTAURANTS*
1064 **MIDAS AUTO SVC EXPERTS**...*GENERAL AUTOMOTIVE REPAIR*
1076 **SAMMY'S CORNER CONFECTIONERY**...*CONVENIENCE STORES*
1076 **SAMMYS CONVENIENCE**...*SUPERMARKETS & OTHER GROCERY STORES*
1091 **MONEY MART NO 43**...*FINANCIAL TRANSACTION PROCESSING & CLEARING*
1091 **PARTS SOURCE**...*AUTOMOTIVE PARTS & ACCESSORIES STORES*
1091 **QUIZNOS SUBS**...*LIMITED-SERVICE RESTAURANTS*
1091 **RANDSTAD INTERIM INC**...*EMPLOYMENT PLACEMENT AGENCIES*
1091 **RIOCAN HOLDINGS INC**...*UNCLASSIFIED*
1099 **BIGG'S DELI & BAR**...*FULL-SERVICE RESTAURANTS*
1110 **OGILVIE MOTORS LTD**...*NEW CAR DEALERS*

2012 STATELY PRIVATE

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2012 WOLFFDALE CRESCENT

SOURCE: DIGITAL BUSINESS DIRECTORY

508 **MIRAKO INTERACTIVE INC**...*COMPUTER SYSTEMS DESIGN SVCS*
575 **PERFECT COMBUSTION**...*PLUMBING & HVAC CONTRS*

2006-07 ALESTHER STREET

SOURCE: VERNONS

David&Donald

■615 Haddad C 842-0775
X619 Crabtree Tom 744-0366
3)647 Dalpé M F A 745-9982
X647 Carisse André 746-3680
X651 Gaudreault Léopold 745-7786
1)655 Morse P&M 745-8203
■667 Charron L&F 746-3214
X671 Boyer David 744-2121
1)675 Giroux B 746-2088
7)679 Preston Gerald W 744-5361
X683 Berube A 749-3333
X687 Pomerleau Regent 746-7549
X687 Pomerleau Regent 749-0339
2)690 Ali H 746-6657
6)693 Farhat Mohamad 746-2753
■694 Quinn C 744-2731
2)696 Youssouf Abdi 842-8322
Hassan
■697 Noor L 842-4103
1)699 Mohamoud F 747-8989
2)709 Abdulrahman Jabir 741-7974
■715 Massie T 744-4983
7)720 O'Connell R E C 747-0672
■725 Thibert S 741-0398
3)725 Lessard L 745-9050
X727 Ahmed M 744-7047
X729 Navarrete Hector 741-2873
1)733 St Preux H 746-2982
8)735 Ricard Lisa 741-7650
8)745 Farhat A 742-5633

ALEUTIAN RD (NEPEAN)

X86 Dillabough Douglas J 684-8893

BERNARD ST

725 Apartments

4) -- Walfa Abdul 741-0164
■ -- Wastell John 741-0642
1) -- Mundela M A 741-1353
6) -- Sultan Youssef M 741-1629
1) -- Valiquette T 741-2904
X -- Baroud Adel 741-5319
■ -- Rashid Fawsia 741-5538
6) -- Boamah G B 741-7113
X -- Dilabio D 741-7230
X -- Elis Abdel 741-8785
X -- Mac Farlane Ian 742-0565
■ -- Yaraskavitch J 744-1408
■ -- Pleasant K 744-1515
X -- Sunstrum M 744-1969
■ -- Cope N 744-2471
■ -- Inabeza I 744-3165
2) -- Laframboise A 744-5930

1) -- Gaal E 744-8077
3) -- Brady R 744-8625
■ -- Monce F 746-1211
■ -- Appiah M 746-2624
■ -- Mehu G 746-3044
■ -- Elyas Djima 746-4371
2) -- Malek K 746-5745
1) -- Stone M 746-6348
4) -- Stanberry Eric 746-7184
5) -- Tancredi T 746-7199
X -- Perry R 746-8386
4) -- Lebrun G 746-9993
■ -- Marseille Bertrand Debora 747-0937
4) -- Feletele Maurice 749-3288
7) -- Ryan J 749-3664
■ -- Chavez R 842-0949
7) -- Wehbe A J 842-4261
■ -- Delyzer J 842-4819
3) -- Sokulski Christopher 842-7408
3) -- Bovaird J 842-9187
2) -- Option Bytown Non Profit Housing Corp ▲842-9582
X 22 Jennings J 744-0433
X 26 Addison M 744-3614
1) 43 Nsolo I 798-2954
X 46 Pichard Louis 741-2785
1) 74 Valeuer Nixon 744-0318
■ 84 Charles Allain 321-0538
X 86 Sinnott Norman 746-6467
1) 737 Thibeault L 744-1845
7) 727 Villeneuve R 744-7442

www.ersinfo.com

2006-07 CYRVILLE ROAD

SOURCE: VERNONS

CYRILLE RD (GLOUCESTER)

■1021 Banque Laurentienne Du Canada ▲744-3485

■1021 Laurentian Bank Of Canada ▲744-3485

CYRUS CRT (NEPEAN)

2006-07 DONALD STREET-A

SOURCE: VERNONS

■559 Bigras Jacques 749-8316
■576 Watters K 746-7030
1235 Units
■ — Dollarama ▲842-0712
■ — Advantage Foreign Exchange Inc ▲842-5176
(2) 8 Enterprise Location D'autos ▲742-6433
(2) 8 Enterprise Rent-A-Car ▲742-6433
1239 Units
(4) — Riocan Property Services ▲688-4100
(7) — Winners Apparel Ltd ▲746-0727
■ — Goodwill ▲842-3553
(4) — Riocan Properties ▲842-4794
1240 Apartments
■ — Dore V 521-2340
■ — Islam A 740-0679
■ — Adan-Adawi Maryan 740-1281
■ — Leung K 740-1293
■ — Kupi J 740-9903
■ — Thompson K 740-9946
■ — Ali A 741-0129
(1) — Tiker Hayati 741-1132
■ — Hebert R 741-1486
■ — Loumrhari A 741-1650
■ — Thomas Swapna 741-1817
■ — Auguste M-E 741-2434
■ — Woolard L 741-2908
■ — Eastern Ottawa Resource Centre ▲741-3843
■ — Chugunov A 741-4064
— — Mathias Ernest 741-4830
(3) — Kamal N 741-5376
(1) — Bowers J 741-5776
■ — De Guzman A 741-5935
■ — Recoskie Jn 741-6126
(3) — Kamal Naveed 741-6314
(3) — Neville S 741-8077
■ — Mcleod T 741-8359
■ — Deias Hassan 741-9041
■ — Mohamed F 741-9376
X — Cholay Annie 742-0582
— — Bernis D 742-0996
— — Boyce E 742-1230
■ — Clark Jamie 742-1331
(5) — Sattar K 742-3487
■ — Mercier Christine 742-4449
— — Provost R 742-5194
(3) — Le Q P 742-6468
— — Ten Brinke Kylie 742-6555
(8) — Hassan Fadumo 742-7194
(2) — Wadud A A 742-7578
■ — Peck A 742-8029
(1) — Sheikh R 742-8731
(8) — Hussein H 744-0130
(2) — Hoang Chau 744-0298
■ — Mcgregory D 744-0599
■ — Hong Siu 744-1585
■ — Quan S 744-2503
(5) — Cleroux Jean-Yves 744-2768
■ — Klepikova O 744-2795
(1) — Mangal A 744-3452
(3) — Jaraar Fahima 744-3839
■ — Cherian Pierre 744-3872
(1) — Beaudoin K 744-3960
■ — Scott Richard W 744-4449
■ — Charbonneau J 744-4462
■ — Aredo Y 744-4938
■ — Peacock P 744-5168
(1) — Aitouhmidou F 744-5883
■ — Labbe M 744-6564
X — Hamidi Mohammad 744-6940
(1) — Ntakarutimana J B 744-7113
■ — Ahmed A 744-7523
(1) — Elashhab S 744-7975
(3) — Al-Biladi S 744-8682
■ — Fyfe K 745-0832
(1) — Akter S 745-3104
(1) — Hasan S 745-4787
(2) — Wehaye A 745-6003
(2) — Dilara A 745-8382
■ — Hudson-Dupuis E 746-0130
— — Jean W 746-0475
■ — Gao W 746-0582
— — Clairoux C 746-0830
— — Yin E 746-1090
(1) — Deiorme A 746-2062
— — Djama A 746-2249
(1) — Lanthier Denis&Tracy 746-2825
■ — Chowdhury Z 746-3120
(8) — Pavkovic M 746-3863
(1) — Hassan A 746-4648
— — Dimitrova B 746-4844
(X) — Fraser F R 746-4957
(6) — Aheen Nabi 746-5285
— — Lachaine M 746-5932
■ — Hassan A 746-6222
— — Tuyizere C 746-7055
— — Thibeault P 746-7134
(2) — Faruk Omar 746-7205
■ — Coie J 746-7784
(5) — Ibrahim Hassen K 746-8113
(3) — Bastien A 746-9753
■ — Manahy S 746-9795
■ — Kabeya Yav 747-2814
(4) — Mendivelso Juan 747-2875
(1) — Matadamas M 747-2971

2006-07 DONALD STREET-B

SOURCE: VERNONS

2H) 337

■ – Yin S 747-7955
■ – Ayotte C 747-8332
– Elvert Varda 747-9180
6) – Hadi Abdul 747-9761
6) – Abdirahman A 748-0603
7) – Blais N 748-1603
■ – Wilick Shawn 748-1841
■ – Duquette E 748-5431
■ – Shirin Sultana 748-5585
■ – Robinson M 748-5145
X – Filipov Ilia 748-6363
■ – Alajam M 749-1816
■ – Louiseize Paul 749-4480
1) – Almoussawi B 842-0446
■ – Tanzima Syeda 842-0619
1) – Corrigan R 842-0925
2) – Sakha S 842-4315
■ – MacNeil B 842-4564
■ – Mahamoud A 1 842-4670
■ – Azimi D 842-4859
■ – Hani N 842-5059
■ – El-tannir K 842-5105
■ – Auclair Eric 842-5276
■ – Peck C 842-7425
3) – Waberi Mohamoud 842-7536
1) – Hassan A 842-8159
■ – Baillargeon S 842-8765
■ – Lu David 842-8889
■ – Krishn B 842-9554
4) – Shamiar Syed 842-9593
■ – Khan S 842-9902
■ 103 Awadh Jamal 744-0268
X 204 Ranville Adnen 741-9564
■ 301 Sani P 321-6954
X 701 Ozbay N 742-4478
■ 808 Akhand Mohammed 842-4439
■ 810 Bano Bibi 749-9413
■ 910 Youssouf Rahma 741-5377
■ 911 Massia R 747-7135
■ 1116 Bigras Jack 749-2959
1) 1201 Charette Michel 741-0067
1409 Yusuf Khadra 747-7013
■ 1505 Udemezue Pius 321-7107
1512 Gulam R 741-8136
■ 1809 Riaz Ammar 321-4643
7) 1243 Capital Nails ▲746-7878
1244 Apartments

2006-07 PRINCE ALBERT STREET

SOURCE: VERNONS

■ 527 Lauzon K 744-6559
540 Apartments
X – Beaudoin Hubert 741-9743
7) – Chretien Y Mrs 746-5113
■ – Brown E 747-9412
X 2 Lavigne S 745-7288
2) 548 Strange M B D 741-3810
X 548 Gervais J 745-2993
6) 548 McCrae Diane 747-7429
2) 553 Zvniga Herman A 742-9321
4) 554 Savoy Donald 748-5451
554 Apartments
X 1 Turcotte Euclide 741-0916
X 555 Bastien P J 746-9205
X 559 Ahmad Ahmad 746-5057
561 Apartments
■ Otta Al-hajjar Ahmad 745-8487
562 Apartments
X – Vezina Gerard 741-0332
X – Baker D 744-1661
4) – Pitts A 748-0307
X 3 Beaudry Carmen Mrs 749-5108
567 Apartments
1) Mnfl Kalf Amal 742-8399
568 Apartments
5) – Stamper John A 741-6787
X – Needham J 745-2487
1) – Fourtado L 746-1272
4) – Meloche M 842-5294
2) 3 Degady A 842-8323
5) 569 Aden Guedi I 742-0735
1) 573 Hersi Mahamoud 741-7925
574 Apartments
1) – Lalleur G 741-2745
■ – Abou Serhal J 749-0564
■ 3 Lacombe A N 321-9176
X Apt Verner A 748-6641
2) 579 Yusuf F M 746-1534
1) 579 Hirsi Sahra 746-2846
6) 580 Frizell J 746-2577
8) 580 Asselin M P 747-2953
580 Apartments
X 3 Smith Paul L 744-5835
3) 581 Bélanger D 741-4458
6) 586 Hoare L 748-6057
X 587 Paul D 745-7997
■ 589 Mohamud Marian 747-8565
5) 592 Cardinal Pierre 744-2104
■ 592 Jennings F 746-5315
592 Apartments
3) 4 Lévesque Camille 745-1582
X 597 Castilloux Philibert 745-1968
X 598 Lacroix T 746-0121
3) 598 Khalil Siham 748-0192
PRINCE CHARLES RD

2006-07 QUEEN MARY STREET

SOURCE: VERNONS

■	528	Laflame Christian	746-6926
■	528	Mclean E	842-4883
■	556	Al-Hajjar Mohamad	742-7944
3)	557	Overbrook Day Care Kindergarten & School Age Program	▲746-7762
5)	557	Ottawa-Carleton District School Board	▲749-1692
1)	568	Faye F	741-7729
1)	570	Bedard D	321-0709
2)	576	Chekhezzein Ezzeddine	748-1499
X	578	Bahnam Albert	741-8692
7)	579	Ostashek John	745-5043
X	579	Ostco Carpet Improvements Inc	▲745-5043
	580	Apartments	
■	--	MacQueen A	741-7508
2)	--	Fordjour A	744-5266
X	--	Martin Howard	744-8754
2)	--	Neville M	745-5751
2)	--	Pagliaro M	745-6598
3)	--	Cali M S	746-4649
■	--	Boutin M	746-5961
1)	--	Gleason Tl	747-9653
3)	--	Anderson M	749-4816
■	--	Levy Jasmine	842-4925
2)	203	Ruhana J	747-4432
1)	Apt	Robinson L	746-3523
X	591	Azzi Marwan	746-7338
■	596	A Hennessey E P	741-7583

QUEEN ST

2006-07 SAINT LAURENT BOULEVARD-A

SOURCE: VERNONS

2)	980	Bell C	748-3331
1)	980	Warwick D	842-0162
5)	997	Bleeker Stereo & TV Ltd	▲741-7934
5)	997	Bleeker Stereo & TV Ltd	▲741-7948
X	1006	Paquette Gaston	744-7394
X	1006	Paquette Berthe	749-3732
X	1007	St Laurent Sunoco	▲741-3539
5)	1007	Sunoco Inc	▲741-3539
1)	1008	Bachenskie C	742-8473
	1020	Units	
■	--	Financiere Wells Fargo	▲741-1090
■	--	Wells Fargo Financial	▲741-1090
4)	--	Mama Cee Beauty Salon & Supplies	▲741-5952
■	--	Geeland	▲742-4282
5)	--	Chateau Fine Pastry	▲744-1221
1)	--	Gabbi's Linen	▲745-4561
1)	--	K K Carribean & Asian Cusine	▲748-5550
3)	--	Mama Cee 2	▲748-9727

2006-07 SAINT LAURENT BOULEVARD-B

SOURCE: VERNONS

767

■	–	Mango's	▲749-6900
■	–	Euro Flowers Ottawa	▲842-5159
3)	–	Giroux Rene Men's Wear	▲842-9874
3)	–	Mercerie Giroux René	▲842-9874
4)	2	Al-Ba Toul Inc	▲748-1323
5)	1021	Loeb Canada Inc	▲745-9865
4)	1033	Club Paradise Tanning Studio	▲741-1064
■	1037	Hydragreen	▲745-8099
5)	1052	Federal Superannuates National Association	▲745-2559
1)	1055	C NIB Corner Store	▲744-8223
5)	1055	Zellers Inc	▲746-4575
4)	1055	Only Deals Dollar Store	▲842-0284
X	1060	Brother WU Restaurant	▲745-1791
5)	1064	Midas Auto Service Experts	▲744-1900
5)	1064	Midas L'Expert Entretien	▲744-1900
■	1076	Sammys Convenience	▲321-1727
1)	1076	Sammy's Corner Confectionary	▲745-6365
	1091	Units	
1)	–	Money Mart	▲741-2947
1)	–	Randstad Interim Inc	▲741-3533
1)	–	Money Mart No 43	▲741-9830
1)	–	Quiznos St Laurent	▲745-9696
1)	–	Riocan Holdings Inc	▲746-4911
1)	–	Auto Partsource	▲749-2227
8)	1099	Bigg's Deli & Bar	▲746-5040
3)	1110	Ogilvie Realty Ltd	▲288-9000
3)	1110	Mercedes-Benz Sales & Service	▲745-9000
2)	1110	Ogilvie Motors Ltd	▲745-9000
8)	1125	Bikes To Go	▲741-8646
3)	1130	Perkins Family Restaurant	▲747-9190
6)	1163	Pier 1 Imports	▲749-0407
X	1171	Canc Motors	▲741-6676

2006-07 STATELY PRIVATE

SOURCE: VERNONS

STREET NOT LISTED

2006-07 WOLFFDALE CRESCENT

SOURCE: VERNONS

3) 42 Bradford J R 747-2789
WOLFFDALE CRES
X447 Muldoon Michael J 745-5910
X450 Labreche Michel 749-3390
X451 Magalhaes Jose 745-0125
Louis
6) 455 Magalhaes Julio 842-3955
X458 Courville Serge 749-5103
X459 Pigeon P 742-1329
4) 462 Scheer I 747-0876
X463 Pigeon C 745-8287
1) 466 Clark S 747-3854
1) 467 Jarawan G 842-3485
3) 470 Lafleur Andre 741-2424
5) 471 Atallah 745-9792
Helene&Elias
X475 La Prade D J 745-2281
3) 478 Jean Gerard 744-3163
3) 479 Pare E 749-2122
X482 Labossiere Richard 745-2305
J
X483 Lamarande Robert 749-9068
1) 486 Bourguignon M&I 744-5575
1) 487 Allard D 746-9890
X490 Brunet Yves 746-5363
1) 491 Anderson S 741-6366
X494 Scott F H 745-1678
3) 495 Maxwell Jacques 748-0767
X502 Choquette R B 741-4356
3) 503 Girard N 746-8808
3) 503 McBride I 746-8808
X506 Mahoney K L 746-1839
5) 508 AbouZeid A 748-1431
X510 Bourgeois Ronal 745-5878
3) 511 Deschênes Jacques 744-3388
X512 McEwen R 749-4765
X516 Garrow W E 746-4525
6) 520 Cray H M 745-7222
6) 520 Cray J 842-8682
6) 524 Terrence B&M 742-1286
535 Richard Andre 741-4566
X535 Thenen N 746-1787
X535 Thenen Marcel 749-0371
X538 Seguin Yvan 749-2739
X539 Gauthier François 746-6687
X542 Day M 745-1287
7) 543 Roy M 842-4412
X546 Nguyen Van Loi 746-0201
547 Bumberca Una 744-2478
X550 Sigouin Douglas 746-1204
X551 Hunter Robert 746-0781
8) 555 Charron Jean-Paul 749-9237
5) 556 Saunol Jack 748-5262
X559 Hotte J Aurele 749-6314
1) 560 Laflamme P C 744-1143
X563 Lavigne Armand 745-8545
X566 Mayer Richard 745-1713
X567 Carisse G P 745-7437
X570 Riegie Jim 741-3899
3) 571 Lau C&R Parent 741-0695
3) 571 Parent R&C Lau 741-0695
X578 Wiebe A 741-9502
1) 579 Purvis Clayton 842-8380
X582 Hurd James 741-0813
X582 Hurd J Robert 842-7427
1) 583 Lebrun G&Ca 746-1309
X586 Goulet S 745-1484
X587 Armstrong Bernard 745-4643
X590 Reid T R C 741-5615
X591 McConnell L 746-0276
X596 Cuddener P 744-8278
X596 Spencer C 744-8278
X597 Stevenson B 744-7014
4) 602 Launn Robert 842-4657
WOLFGANG DR (NEPEAN)

2000 ALESTHER STREET

SOURCE: POLKS

611 Spearman Gerald E K1K 1J1 746-1882
615 Ewanovich W D K1K 1J1 746-9635
619 Crabtree Tom K1K 1J1 744-0366
647 Carisse Andre K1K 1H8 746-3680
Dalpe M F A K1K 1H8 745-9982
651 Gaudreault Leopold K1K 1H8 745-7786
663 Boyer Guy K1K 1H8 745-7933
667 Lethbridge R T K1K 1H8 747-9098
671 Boyer David K1K 1H8 744-2121
675 Alarie R K1K 1H8 746-2088
679 Preston Gerald W. K1K 1H8 744-5361
683 Berube A K1K 1H8 749-3333
687 POMERLEAU
REGENT K1K 1H8 746-7549
690 Chaar Janil K1K 1H9 741-6736
693(N) Farhat Mohamad K1K 1H8 746-2753
694 Fritz M & L K1K 1H9 748-9715
697 Leblond Gilles K1K 1H8 744-4934
698 Ahmad Yehia K1K 1H9 749-7360
699 Ajar Abdul K1K 1H8 744-3167
700 Smith-Doiron Paul J K1K 1H9 742-8675
703 Elhoss Salim K1K 1H8 747-0143
713 Karkache Nicolas K1K 1H8 744-4470
715(N) Massie Tommy R K1K 1H8 749-4858
720 O'Connell R E C K1K 4H3 747-0672
725 Lessard L K1K 1H7 745-9050
727 Ahmed M K1K 1H7 744-7047
729 Navarrete Hector K1K 1H7 741-2873
733 Elzein A K1K 1H7 744-0579
735 Ricard Lisa K1K 1H7 741-7650
737 Stevenson R A K1K 1H7 749-1942
739 Sarkis Richard K1K 1H7 745-6894
(N) Ssarkis M K1K 1H7 842-5118
743 Osman Ruqiyo K1K 1H7 748-7437
745 Farhat A K1K 1H7 742-5633

BUSINESSES 1 HOUSEHOLDS 74

ALEUTIAN DR (4)

2000 BERNARD STREET

SOURCE: POLKS

725	Abdi M	K1K 3H7 744-4666
	#26 Addison M	K1K 3H7 744-3614
	Aghazadeh M	K1K 3H7 744-0990
	(N)Anthony I	K1K 3H7 746-9125
	(N)Antoine D	K1K 3H7 741-9572
	(N)Appiah Malic	K1K 3H7 842-4680
	Baroud Adel	K1K 3H7 741-5319
	Bien-Aime P	K1K 3H7 744-7350
	Bissonnette D M	K1K 3H7 741-2921
	(N)Boamah G B	K1K 3H7 741-7113
	#71 Boudreau G	K1K 3H7 742-8962
	Coulombe H C	K1K 3H7 745-9665
	Dilabio D	K1K 3H7 741-7230
	Dooley Terrance	K1K 3H7 742-8605
	Drouillard J	K1K 3H7 748-8286
	#59 Elis Abdel	K1K 3H7 741-8785
	(N)Elkadri Noureddine.	K1K 3H7 842-4576
	#68 Felefele Maurice.	K1K 3H7 749-3288
	(N)Fernandes Veronica	K1K 3H7 749-8171
	Gooden N	K1K 3H7 748-7446
	Gravel J	K1K 3H7 745-5271
	(N)Hamidou Issa H	K1K 3H7 744-5670
	(N)Hassan A	K1K 3H7 748-6086
	(N)Hirpo Yenenesh	K1K 3H7 747-8678
	Idris A	K1K 3H7 745-6449
	#22 Jennings J	K1K 3H7 744-0433
	(N)Joseph J	K1K 3H7 741-3695
	Kamariza F	K1K 3H7 745-5369
	#81 Kennedy K	K1K 3H7 744-2092
	(N)Lachapelle Ron P	K1K 3H7 747-4866
	Lafleur Gerald	K1K 3H7 747-7596
	#57 Lavigne Rick	K1K 3H7 742-6699
	Lebrun Georges	K1K 3H7 745-4096
	(N)Leduc N	K1K 3H7 749-6391
	#78 Leger F	K1K 3H7 746-7555
	Lowe W	K1K 3H7 748-8238
	Lowe Wayne H	K1K 3H7 747-7830
	Mac Farlane Ian.	K1K 3H7 742-0565
	Mehari T	K1K 3H7 741-4928
	(N)Michael M	K1K 3H7 745-8385
	Miron Frank	K1K 3H7 749-7502
	Moore G C	K1K 3H7 749-3973
	(N)Mpolitolu N	K1K 3H7 746-5109
	(N)Nazar Mansor B	K1K 3H7 741-2397
	(N)O'Drane Michael	K1K 3H7 746-9827
	Perry R	K1K 3H7 746-8386
	#46 Pichard Louis	K1K 3H7 741-2785
	#75 Pitts A	K1K 3H7 748-0307
	Power John J	K1K 3H7 742-5144
	Roy Lynott	K1K 3H7 744-6322
	Ryan J	K1K 3H7 749-3664
	(N)Salame H & C	K1K 3H7 742-7487
	(N)Santo J	K1K 3H7 746-7551
	(N)Sauve L	K1K 3H7 745-7411
	#86 Sinnott Norman	K1K 3H7 746-6467
	(N)Sultan Youssef M	K1K 3H7 741-1629
	(N)Sunstrum M	K1K 3H7 744-1969
	#35 Toth Janos	K1K 3H7 747-7840
	Uluso Omar	K1K 3H7 747-6008
	Wehbe A J	K1K 3H7 842-4261
	Wood H	K1K 3H7 744-0807
737	#4 Le Blanc George	K1K 3H8 749-0149

2000 CYRVILLE ROAD

SOURCE: POLKS

RANGE NOT LISTED

2000 DONALD STREET

SOURCE: POLKS

571	Walsh Ivan	K1K 1L6 746-6717
572	Dube G	K1K 1L5 746-2664
575	Kiebbe Alex	K1K 1L5 746-6386
	Kiebbe B	K1K 1L5 746-5290
579	Mendes Manuel M	K1K 1L6 748-0933
580	(N) Nguyen Khanh	K1K 1L5 749-1855
583	(N) Tran H	K1K 1L6 741-3514
584	Buhain D P	K1K 1L6 744-7444
588	Abdel-Sayed Fred	K1K 1L4 746-6054
598	Burton E A	K1K 1L3 745-1712
599	Charron Edgar G	K1K 1L3 741-8155
603	Quintal Rita	K1K 1L3 749-2703
605	Delima J	K1K 1L3 746 5101
	(N) Lahoud Elias	K1K 1L3 741-4396
	Zurwerra P	K1K 1L3 749-4362
609	Amyanah R	
	(N) Collins Pierre & Guylaine	K1K 1L3 742-8971
	John A	K1K 1L3 742-5018
611	INTERCONTINENTAL MUSIC	K1K 1L4 748-9891
707	(N) #1244 Thompson Murray	741-6675
2112	(N) Bastien Denis	744-5718

BUSINESSES 51 HOUSEHOLDS 591

2000 PRINCE ALBERT STREET-A

SOURCE: POLKS

	#3 Leroux L	K1K 1Y6 744-4736
519	Lafreniere A	K1K 1Y7 741-1316
523	JOLY RAY & SONS PAINTERS INC	K1K 1Y7 741-0019
527	Kager A	K1K 1Y7 747-2594
540	Beaudoin Hubert	K1K 1Y6 741-9743
	Chretien Y	K1K 1Y6 746-5113
	#2 Lavigne S	K1K 1Y6 745-7288
	Moreau P	K1K 1Y6 746-9007
548	Gervais J	K1K 1Y6 745-2993
	(N) #2 Lamoureux Gerry	K1K 1Y6 744-0913
	(N) Mc Crae Diane	K1K 1Y6 747-7429
	Poulliotte A	K1K 1Y6 747-1515
553	Dasilva S	K1K 1Y5 749-1897
554	(N) #4 Gregoire G	K1K 1Y6 741-8450
	#2 Norton C I	K1K 1Y6 744-3829
	Pelletier T J	K1K 1Y6 745-0437
	(N) #1 Turcotte Euclide	K1K 1Y6 741-0916
555	Bastien P J	K1K 1Y5 746-9205
559	Ahmad Ahmad	K1K 1Y5 746-5057
561	Feghali Khalil	K1K 1Y5 749-1507
562	Baker D	K1K 1Y6 744-1661
	#3 Beaudry Carmen	K1K 1Y6 749-5108
	#4 Tessier Conrad	K1K 1Y6 749-3239
	Vezina Gerard	K1K 1Y6 741-0332
567	Abdi Nimo Hassan	K1K 1Y5 744-1815
568	#2 Beaudin M	K1K 1Y6 746-9921

PRINCE ALBERT ST cont'd

Address	Phone
#1 Lecuyer Gorden	K1K 1Y6 749-2050
#4 Levis Paul	K1K 1Y6 741-4833
Needham J	K1K 1Y6 745-2487
Romain R	K1K 1Y6 749-1404
573 Haye M	K1K 1Y5 749-9895
574 (N) Fontaine G	K1K 1Y6 746-5201
#3 Mc Mahon J F	K1K 1Y6 747-2748
Verner A	K1K 1Y6 748-6641
575 Belanger A L	K1K 1Y5 749-5906
579 Hirsi S	K1K 1Y5 746-2846
580 Asselin M P	K1K 1Y6 747-2953
(N) Frizell J	K1K 1Y6 746-2577
#1 Saunders D H	K1K 1Y6 749-1649
581 Belanger D	K1K 1Y5 741-4458
586 Dubreuil Victor	K1K 1Y6 749-2080
(N) Hoare L	K1K 1Y6 748-6057
#3 Lapointe J	K1K 1Y6 746-0470
587 Paul D	K1K 1Y5 745-7997
589 (N) Sambou Y	K1K 1Y5 749-2994
592 #2 Hancock M Y	K1K 1Y6 745-4026
#4 Levesque Camille	K1K 1Y6 745-1582
(N) Savage D	K1K 1Y6 749-5166
597 Castilloux Phillibert	K1K 1Y5 745-1968
598 #3 Canadien F L	K1K 1Y6 749-8762
#2 Franche Marcel	K1K 1Y6 748-7303
Lacroix T	K1K 1Y6 746-0121

BUSINESSES 3 HOUSEHOLDS 334

(N) Ouellette C	K1K 1W2 749-1546
528 Mirauta M	K1K 1W2 749-3054
556 Guardado Miguel	K1K 1W1 748-6234
557 OTTAWA-CARLETON DISTRICT SCHOOL BOARD	K1K 1V9 749-1692
OVERBROOK DAY CARE KINDERGARTEN & SCHOOL AGE PRGRM	K1K 1V9 746-7762
560 (N) Bleoo Lorraine & Stephane ♠	K1K 1W1 745-2828
568 Mathurin Joan	K1K 1W1 744-0070
576 Szola A	K1K 1W1 749-0152
578 Bahnam Albert ♠	K1K 1W1 741-8692
579 OSTCO CARPET IMPROVEMENTS INC	K1K 1V9 745-5043
Ostashek John	K1K 1V9 745-5043
580 (N) Ali Mohamed S	K1K 1W1 744-3641
(N) Allen P	K1K 1W1 744-7583
Beaudoin C	K1K 1W1 742-1863
(N) Berkeley Risha	K1K 1W1 747-9069
(N) Gleason T L	K1K 1W1 747-9653
(N) Haji-Mohamed Hubi Said	K1K 1W1 749-3734
Martin Howard	K1K 1W1 744-8754
Morel M	K1K 1W1 745-8748
Msamba L	K1K 1W1 747-1390
Murphy K	K1K 1W1 744-2829
Roussakis Z	K1K 1W1 744-0908
(N) Taylor T	K1K 1W1 742-5027
Trottier M	K1K 1W1 741-8734
(N) Ungama Patrick	K1K 1W1 746-7243
#306 Meloche Julie	K1K 1W1 745-0491
#405 Dobbie J A	K1K 1W1 749-2082
591 Azzi Marwan	K1K 1V9 746-7338
592 Moore T ♠	K1K 1W1 741-7458
596 Laurin C	K1K 4R5 741-1222
(N) #A Younessi B	K1K 4R5 746-4299

BUSINESSES 19 HOUSEHOLDS 370

www.erisinfo.com

		K1K 3B3 749-9805
975 (N)	Rahmaniam-Wardak B	K1K 3B1 739-0418
976 (N)	Morris Chris M	K1K 3B3 745-3717
(N)	#3 Murphy Lisa	K1K 3B3 749-7113
(N)	St-Denis Y M	K1K 3B3 741-0544
980	Geekie C	K1K 3B3 741-9637
	Patrice P & Ftk M	K1K 3B3 742-6615
	Roy Frances	K1K 3B3 741-6683
997	BLEEKER STEREO & TV LTD	K1K 3B1 741-7934

	Address	Phone
1006	Paquette Berthe	K1K 3B4 749-3732
	Paquette Gaston	K1K 3B4 744-7394
1007	ST LAURENT FUN FOOD SUNOCO	K1K 3B1 741-3539
	SUNOCO INC	K1K 3B1 741-3539
1008	COURCHAINE GUY RADIO & T V REPAIR	K1K 3B4 749-5330
1010 (N)	#800 Perreault A C	K1K 3B4 744-1539
1020	EURO FLORAL DESIGNS	K1K 3B4 842-5159
	KAMLO CONSTRUCTIONS SITE	K1K 3B4 742-7287
1021	LOEB CANADA INC	K1K 3B1 745-9865
	LOEB ST LAURENT	K1K 3B1 745-9865
1025	BANK OF NOVA SCOTIA	K1K 3B1 745-0091
	BANQUE SCOTIA	K1K 3B1 745-0091
1033	ULTRALUX	K1K 3B1 741-7112
1045	RADIOSHACK	K1K 3B1 746-5029
1052	Florent Pigeon	K1K 3B4 746-4383
1055	CNIB CORNER STORE	K1K 3B1 744-8223
	DOLLAR STORE PLUS THE	K1K 3B1 744-2265
	MAGICUTS	K1K 3B1 749-6856
	ZELLERS INC	K1K 3B1 746-4675
1056	TRADEMARK LEATHER	K1K 3B4 748-7762
1060	BROTHER WU RESTAURANT	K1K 3B4 745-1791
1064	MIDAS AUTO SERVICE EXPERTS	K1K 3B4 744-1900
	MIDAS L'EXPERT ENTRETIEN	K1K 3B4 744-1900
1076	SAMMY'S CORNER CONFECTIONERY	K1K 3B4 745-6365
1099	Bigg's Deli & Bar	K1K 3B1 746-5040
1110	MERCEDES BENZ SALES & SERVICE	K1K 3B6 745-9000
	OGILVIE MOTORS LTD	K1K 3B6 745-9000
	OGILVIE MOTORS MERCEDES BENZ	K1K 3B6 745-9000
1116	MAGIE DES LETTRES (LA)	K1K 3B6 748-3879
1125	BLINDS TO GO	K1K 3B5 741-8646
1130	PERKINS FAMILY RESTAURANT	K1K 3B6 747-9190
1133	ROCKIN JOHNNY'S DINER	K1K 3B5 744-3139
1163	PIER 1 IMPORTS	K1K 3B7 749-0407
	RON KELL'S TEXACO SERV STN	K1K 3B7 745-3941

STREET NOT LISTED

WOLFFDALE CRES (O)

446	Douville M	K1K 1N4	746-0119
447	Muldoon Michael J	K1K 1N6	745-5910
	Van Zandvoort Henri.	K1K 1N6	749-8898
450	Labreche Michel	K1K 1N4	749-3390
451	Magalhaes Jose Louis .	K1K 1N6	745-0126
454	Barry Kenneth	K1K 1N4	746-4823
455	(N) Cote T	K1K 1N6	747-8854
	(N) Magalhaes Julio	K1K 1N6	842-3955
458	Courville Serge	K1K 1N4	749-6103
459	Pigeon P	K1K 1N6	742-1329
463	Julien Dany & Nathalie	K1K 1N6	745-8317
	Pigeon C	K1K 1N6	745-8287
466	Smith R J	K1K 1N4	749-4555
467	Leblanc J R	K1K 1N6	745-2639
470	Lafleur Andre	K1K 1N4	741-2424
	Martell Mike	K1K 1N4	741-2424
	Peloquin Jean	K1K 1N4	741-2424
471	Lecavalier G	K1K 1N6	747-1746
475	La Prade D J	K1K 1N6	745-2281
478	(N) Reeve Derrick D	K1K 1N5	749-6792
	Reeve T	K1K 1N5	749-5699
479	(N) Pare M	K1K 1N6	749-2122
482	Labossiere R J	K1K 1N5	745-2305
483	Lamirande Robert	K1K 1N6	749-9098
486	Perras Rejean	K1K 1N5	748-3346
487	Bolger C M	K1K 1N6	745-3145
490	Brunet Yves	K1K 1N5	746-5363
491	Valiquet S	K1K 1N6	749-2597
494	Scott F H	K1K 1N5	745-1678
495	Maxwell Jacques	K1K 1N6	748-0767
498	Levesque Ernest	K1K 1N5	749-2674
502	Choquette R B	K1K 1N5	741-4356
503	Girard N	K1K 1N6	746-8808
	Mc Bride I	K1K 1N6	746-8808
506	Mahoney K L	K1K 1N5	746-1839
510	Bourgeois Ronal	K1K 1N5	745-5878
511	Deschenes Jacques	K1K 1N6	744-3388
512	Mc Ewen Melville	K1K 1N5	749-4765
516	Garrow W E	K1K 1N5	746-4525
520	(N) Cray H M	K1K 1N5	745-7222
524	(N) Lalonde Gaetan	K1K 1N5	744-1841
	(N) Terrence B & M	K1K 1N5	742-1286
535	Richard Andre	K1K 1N6	741-4566
	Therien Marcel	K1K 1N6	749-0371
	Therien N	K1K 1N6	746-1787
538	Seguin Yvan	K1K 1N5	749-2739
539	Gauthier Francois	K1K 1N6	746-6687
542	Day M	K1K 1N5	745-1287
543	Roy M	K1K 1N6	842-4412
546	(N) Nguyen L	K1K 1N5	842-4549
	Nguyen Van Loi	K1K 1N5	746-0201
547	(N) Casavant Marc-Andre	K1K 1N6	745-3663
	Casavant Paul	K1K 1N6	741-2809
550	Sigouin Douglas	K1K 1N5	746-1204
551	Hunter Robert	K1K 1N6	746-0781
555	Charron Jean-Paul	K1K 1N6	749-9237
559	Hotte J Aurele	K1K 1N6	749-6314
560	Latreille A G	K1K 1N5	744-1143
563	Lavigne Armand	K1K 1N6	745-8545
566	Mayer Richard	K1K 1N7	745-1713
567	Carisse G P	K1K 1N6	745-7437
570	Riegle Jim	K1K 1N7	741-3899
571	Kerwin Thomas	K1K 1N6	745-2728
	Shnay D	K1K 1N6	745-8226
574	Larocque F L	K1K 1N7	749-1206
575	PERFECT COMBUSTION	K1K 1N6	745-7826
	Moncion H	K1K 1N6	746-4996
578	Wehbe A	K1K 1N7	741-9502
	Wehbe L	K1K 1N7	744-6123
579	(N) Cray R	K1K 1N6	749-9693
582	Hurd James	K1K 1N7	741-0813
586	Goulet S	K1K 1N7	745-1484
587	Armstrong Bernard	K1K 1N6	745-4643
590	Reid T R C	K1K 1N7	741-5615
591	Mc Connell L	K1K 1N6	746-0276
596	Cuillerier P	K1K 1N7	744-8278
	Spencer C	K1K 1N7	744-8278
597	Stevenson B	K1K 1N6	744-7014

BUSINESSES 1 HOUSEHOLDS 77

Ewanovich Kim 746-9635
619 Crabtree Tom & Jeannie [5] ◎ 744-0366
• DONALD ST INTERSECTS
647 Carisse Yvonne M [9]+ ◎ 746-3680
Dalpe Alice F [9]+ 745-9982
651 Gaudreault Leopold & Georgette [8] ◎ 745-7786
655 Not Verified
• WOLFDALE CRES INTERSECTS
659 Paskevicius Albinas & Ale [9]+ ◎ 745-8910

663 Boyer Guy G & Cecile L [9]+ ◎ 745-7933
Boyer David 745-7933
667 Not Verified
671 Marquis Estelle [9]+ ◎ 749-1275
Viau Carole 749-1275
• WOLFDALE CRES INTERSECTS
675 Alarie Rodolph E [9]+ ◎ 746-2088
Giroux Bernadette 746-2088
Grimard Rene 746-2088
679 Not Verified
683 Berube Andre [9]+ ◎ 749-3333
687 Pomerleau Regent & Therese [9]+ ◎ 749-0339
Pomerleau Gilles 749-0339
Pomerleau Chantal H 749-0339
690 Chaar Jamil G C & Laila [4] 741-6736
692 Richer Danielle J [2] 749-3294
693 Gordon Michl J & Marlyn [8] 746-7923
694 Not Verified
696★Gagnon Louise M
697 Le Blond Gilles Y & Constance J [2] 744-4934
698 Gigoux Jean & Colette [9]+ 745-2340
Gigoux Marie J 745-2340
Gigoux Dominic 745-2340
699★Ajur Abdulaziz & Rabia 744-3167
700 Not Verified
702 Lyons Crystal [7] 741-5894
703 Maharry Mike & Zelda [8]
Watson Larry Ann
705 Sauve Raymond G & Jacqueline [9]+ ◎ 746-4983
707-713 Not Verified (3 Hses)
715 Smith-Doiron Lorraine B [4] 745-6304
Smith-Doiron Paul J 745-6304
Smith-Doiron Brenda 745-6304

55

• QUEEN MARY ST INTERSECTS
720 Potvin Carmelle A [2] ◎ 747-0737
722 Provencher Martin [2] 741-3815
727★Mc Edwards Anne D 741-5512
Sterling David 741-5512
729 Navarrete Hector & Mercedes [2] 741-2873
733 El-Zein Ibrahim & Salma S [8] 744-0579
735 Graham Wendy [2] 748-5916
Blam David 748-5916
737 Stevenson Robt A & Joyce M [9]+ 749-1942
Stevenson Sean B 749-1942
739 Rose Denis & Louise L [2] 745-4482
743 Not Verified
745 Ladouceur Sheila K [9]+ 748-7596
Simard Jamie 748-7596
79 HOUSEHOLDS

203

1993-94 BERNARD STREET

SOURCE: POLKS

• PRINCE ALBERT INTERSECTS
725 QUEEN MARY COURT
APARTMENTS senior citizen
1-3 Not Verified (2 Apts)
4 Cartier Noel [5] 741-8413
5★Berkeley E M
6 Not Verified
7 Not Verified
8★Desbiens L
9 Hughes [2]
11 Stuart Harold & Cecilia [8] 746-8717
12★Romain Robert A 749-1404
14 Lafleur G [2] 747-7596
15-16 Not Verified (2 Apts)
17★Fernandes V 745-3342
18 Not Verified
20 Binette Aine & Verna [4] 749-7165
22 Jennings Merving & Jennie [7] 744-6800
24 King Roger [2] 744-4509
24 Fortin Jenine 744-4509
26 Addison George & Marguarita [9]+ 744-3614
28 Not Verified
30 Pilon Bernard & Laura [7] 744-0559
32 Sunstrum M [9]+ 744-1969
33 Not Verified
34★Mann L B
35 Totch John [2] 747-0893
36★Louiseize Jean-Charles 744-2946
37 Not Verified
38★Mason W
39 Gauthier Lucienne [4] 746-0471
40★Gareau Denis
41 Abbott Bernard J [9]+ 741-7163
42 Groulx Claudette [2] 741-0769
43 Kladanac Joseph [2] 744-8196
44★Longpre M 748-0137
45 Pelletier Terry J [7] 745-0437
46 Feiffer Michael R [2] 747-4451
47 Bajorek Mike [2] 749-2597
48 Not Verified
49 Charlebois Guy [2] 749-7122
50 Not Verified
51 Lalonde Omer [4] 748-9858
52-53 Not Verified (2 Apts)
54 Kelford Jules L [2] 746-1303
55 Not Verified
56 Hoare [2] 748-6057
57 Agarwal Carmen [4] 746-9871
58 Bader Heinz K [2] 747-8561
59 Not Verified
60★Wetheritt D M 749-6453
61-65 Not Verified (5 Apts)
66 Lortie G [9]+ 746-8915
67★Bahey Muriel 749-4185
68 Not Verified
69 Turpin W P [2] 741-1743

1993-94 CYRVILLE ROAD

SOURCE: POLKS

STREET NOT LISTED

746-6717
575★Thomas Jeannine
576 Watters Keith J & Rita M [9]+ ◎
579 Mendes Manuel & Maria [2]
748-5290
580 Chenier Maurice & Therese L [8]
◎ 749-7910
583★Emond Laurent 746-7520
584 Lavoie Gaston J & Aida [5] ◎
741-3514
588 Abdel-Sayed Fred I [2] 744-7444
Bsmt Mc Laren L [2] 744-6678
• ALESTHER INTERSECTS
598 Burton Allen E & Reina M [9]+
◎ 746-6054
Burton Peter J 746-6054
599 Charron Emilienne [9]+ ◎ 745-1712
602★Roy Jacques 745-5178
603 Not Verified
605 Apartments
1 Not Verified
2 Lavergne Laurent [5] 746-6995
3-3 Not Verified (3 Apts)
609-2 Amyanah Rita A [9]+ 749-4362
Brassaid Cameron L
749-4362
Pepic Dorothy L 749-4362
609-3 Not Verified
610 Ayotte Weldon & Dorothy P [5] ◎
744-4567
Ayotte Kelly A 744-4567
652 HOUSEHOLDS
25 BUSINESSES

5 Not Verified
4 Kelly John & Janine [2] 741-0138
519★Dadust Jean-Marie ◎ 741-2428
523 Joly Raymond H [5] 745-8108
Joly Victor 745-8108
527 Lamoureux Lynn [2] 744-5378
• BERNARD INTERSECTS
540 Apartments
1 Lachapelle Eugene &
Constance [9]+ 749-1274
2 Lavigne Arth & Simone [9]+
745-7288
3 Beaudoin Hubert & Alice [8]
741-9743
4 Turpin Annie [8] 745-8468
548 Apartments
1★Nichol B 745-1982
2 Lamoureux Gerald & Anne-
Rose [2] 744-0813
3 Avon Florence A [2] 747-1515
4 Wilson Mary [2] 747-9475

553 Not Verified
554 Apartments
1 Not Verified
2 Norton Charles & Yvette [9]+ 744-3829
3 Potterton Patricia [4] 746-3892
4★Gregoire G 741-8450
555 Not Verified
559 Ahmad Ahamed & Maha [2] 746-5057
561 Feghali Khalil & Nazera [9]+ 749-1507
Feghali Joumana 749-1507
Joumana Jihad 749-1507
Feglali Wissa M 749-1507
Feglali Josette 749-1507
562 Apartments
1★Baker Dorthy
2★Fairbairn D A 741-7837
3 Beaudry Carmen C [9]+ 749-5108
4 Tessier Conrad & Georgette [9]+ 749-3239
567 Fish Dora [9]+ 746-1663
Fish Joanne C 746-1663
Fish Gayle E 746-1663
568 Apartments
1 Lecuyer Gertrude M [9]+ 749-2060
2 Beaudin Yvonne [9]+ 746-9921
3 Beaulieu Adelard & Irene [9]+ 745-2762
4 Levis Paul H & Marie [9]+ 741-4833
569 Villeneuve Donald & Annette [9]+ 745-5382
Villeneuve Julie 745-5382
Villeneuve Christine 745-5382
573★Guibord L 746-0567
574 Apartments
1 Henry Ernest L & Lucille [9]+ 749-4043
2 Not Verified
8308 3 Butler Leonard & Yvonne [2] 745-4165
4 Chretien Leon & Therese M [5] 741-0369
575 Belanger Guy & Anita L [5] 749-5906
579 Not Verified
580 Apartments
1 Boyer Roger [2] 745-2128
2★Dempsey M E 746-9922
3 Smith Paul L [4] 744-5835
4 Goyette Dorothy [8] 741-9694
581 Belanger Dolores [9]+ 741-4458
Belanger Mario R 741-4458
Belanger Luc 741-4458
Belanger Nathalie 741-4458
586 Apartments
1 Robertson Ernest [9]+ 749-9434
2 Asselin Alfred & Leurette [9]+ 745-6519
3 Lapointe Jacqueline [9]+ 746-0470
4 Dubreuil Victor E & Henrietta M [5] 749-2080
587 Paul Daniel & Louise [2] 745-7997
Paul Patrick 745-7997
589 Belisle Robert & Madelaine J [2] 741-9638
Belisle Stephen W 741-9638
Belisle Chris J 741-9638
592 Apartments
1 Richer Albert [9]+ 744-7182
2 Hancock Horace & Marie Y [9]+ 745-4026
3 Potvin Cecile L [9]+ 749-2555
4 Roberts Cliff & Aline [4] 744-5145
597 Castilloux Philbert G & Fleurette M [9]+ 745-1968
Castilloux Lina 745-1968
598 Apartments
1 Lacroix Therese [2] 746-0121
2 Franche Marcel A & Annette [7] 748-7303
3 Canadien J F & Jeanne [8] 749-8762
4 Patacairie Arthur J [8] 744-5623
599 Not Verified
360 HOUSEHOLDS
1 BUSINESS

M [2] 741-5734
528★Bujor Radu 749-3054
Mihaela Miraula 749-3054
• BERNARD INTERSECTS
556 Guardado Miguel & Martha [5] 748-6234
Guardado Miguel Jr 748-6234
Guardado Roberto 748-6234
557 QUEEN MARY SCHOOL 744-7374
OVERBROOK DAYCARE & SCHOOL AGE PROGRAM 746-7762
560 Charbonneau Gerard & Veronica [9]+ ◎ 746-1394
568 Charette Arth R [9]+ 746-3028
Polak Mitzi A 746-3028
570 Patafie Anthony J [9]+ 749-3433
578 Not Verified
579 Slade Edwin S & Kay [2] ◎ 744-6149
Slade Shane E 744-6149
579a Ostashek John [2] ◎ 746-5786
OSTCO CARPET IMPROVEMENTS 745-5043
579b-580 Not Verified (2 Hses)
581 Spagnoli Lelio & Liliana [9]+ ◎ 746-1144
Spagnoli Franca 745-1144
582 Not Verified
591 Jeanvenne Michel P & Julie L [5] 741-9787
Joseph Crystal Y 741-9787
592★Moore R 745-8558
• ALESTHER INTERSECTS
273 HOUSEHOLDS
15 BUSINESSES

741-6185
3 Sauve Suzanne [9]+ 749-7840
980 Apartments
1 Louis Joanne [7] 741-6238
1 Lauzon Louis A 741-6238
2★Martel Helene 741-8195
3★Lavine Francine 745-0860
997 BLEEKER STEREO & TV LTD tv & radio sales 741-7934
• DONALD ST ENDS
1006 Courchaine Aline [9]+ ◎ 749-8580
Rear Not Verified
1007 JOHN'S SUNOCO SERVICE STATION LTD 745-9668
ST LAURENT SELF SERVICE GAS BAR 744-1324
1008 COURCHAINE GUY T V tv & radio sls & repr 749-5330
Courchaine Guy A & Berthe [9]+ ◎ 741-6865
1012★Campbell Richd
1014 Driver Ross & Denise [2] 747-7947
1018 Taylor Ralph A & Mary R [7] 741-7054
Hutchinson Christopher L 741-7054
Taylor Jayson C 741-7054
1020 Beeler Arnold & Winnie [9]+ 741-1047
Beeler Leslie 741-1047
1021 ST LAURENT I G A FOODLINER 745-9865
1024 Zaroski Ann [9]+ 749-1283
Zaroski Earl M 749-1283
Zaroski Richd 749-1283
1025 BANK OF NOVA SCOTIA 745-0091
1028 Dore Leo Albert & Pauline [4] 745-4288
1029 RADIO SHACK electronics 746-5093
1030 Leblond Paul E & Lucille R [8] 748-1290
Leblond Gerald J 748-1290
1032 Simper Ian & Judy [9]+ 749-2102
1033 PEINTURES ULTRALUX 741-7112
1034 Reay John & Louise [4] 741-3713

ST LAURENT BLVD—Contd
1036 Mann Robt J & Joan M [5] 746-2005
1037 BANK OF NOVA SCOTIA loan dept 748-1772
1040 Perreault Jean Guy & Lise [2] 746-2976
Perreault Andre 746-2976
1042 Not Verified
1045 ONE STOP LAUNDROMAT AND DRY CLEANERS 741-2631
1046-1048 Not Verified (2 Hses)
1052 PIGEON-ROY INSURANCE BROKERS LTD 746-4383
1054 DE SOUSA B UPHOLSTERING 741-4277
PIGEON ROY APPRAISAL LTD 744-7670
1055 K-MART CANADA LTD department stores 746-4675
1060 BROTHER WU RESTAURANT 745-1791
1064 PERFORMANCE MAZDA OTTAWA INC auto dlrs 741-0123
1076 MAC'S CONVENIENCE STORE groceteria 745-6365
1091 MIDAS MUFFLER & BRAKE SHOP 744-1900

55

• QUEEN MARY INTERSECTS
1099 CASTELLO DELL. PASTA 744-7488
PRESTIGE DISTRIBUTION ALIMENTAIRE 744-6464
• CYRRILLE RD INTERSECTS
1105 Not Verified
1110 ST-LAURENT TIRE & SERVICE 745-7147
1116 CONSEIL SCOLIAIRE EDUC COOPERATIVE 747-2888
CONSEIL SCOLAIRE EDUC CO-OPERATIVE 747-1254
• COVENTRY RD INTERSECTS
1125 PUBLIC OPTICAL optical 745-4000
1129 CO-OPERATORS THE 745-0111
• OGILVIE RD INTERSECTS
1163 Not Verified
1171 CIVIC MOTORS LTD new cars 741-6676
1177 WATERBED GALLERY 742-1929

1993-94 STATELY PRIVATE

SOURCE: POLKS

STREET NOT LISTED

1993-94 WOLFFDALE CRESCENT-A

SOURCE: POLKS

WOLFFDALE CRES –WEST FROM ALESTHER FIRST SOUTH OF DONALD

446 Douville Paul E & Marcelle [9]-+ ◎ 746-0119
447 Muldoon Michl J & Doris S [9]-+ ◎ 745 5910
450 Labreche Michel R & Carole R ◎ 749-3390
451 Magalhaes Jose L & Candida [9]-+ ◎ 745-0126
Magalhaes George 745-0126
Magalhaes Julio M 745-0126
454 Barry Kenneth J & Annie M [9]-+ ◎ 746-4823
455 Not Verified
458 Courville Serge J & Huguette M [9]-+ ◎ 749-6103
Courville Anne M 749 6103
Courville Gilles 749-6103
459 Dumont Theophile [9]-+ ◎ 746-1189
462 Saikaley Naim [2] ◎ 748-3002
463 Pigeon Claude & Lorica [9]-+ ◎ 745-8287
Pigeon Pierre 745-8287
Pigeon Nathalie 745-8287
466 Smith [2]
467 Leblanc J Ronald & Jacqueline M [9]-+ ◎ 745-2639
470 Farat Jos & Amelia [5] ◎ 749-4194
Farat Caroline 749 4194
471 Lecavalier Gerry J & Danielle [7] ◎ 747-1746
475 Laprade Don J & Faye L [9]-+ ◎ 745-2281
Laprade Donald B 745-2281
Laprade Jas E 745-2281
• OKEE ST INTERSECTS
478 Lacelle Yvette [8] ◎ 741 9890
479 Pare Marielle [9]-+ ◎ 749-2122
Pare Eric 749-2122
482 Labossiere Richd J & Eva E [9]-+ ◎ 745-2305
483 Lamirande Robt A & Betty A [9]-+ ◎ 749-9098
Lamirande Kenneth J 749-9098
486 Allan Robt M [9]-+ ◎ 749-1419
487 Bolger Clarence & June [9]-+ ◎ 745-3145
Bolger David 745-3145
490 Escala Kent S & Micheline G [8] ◎ 746-7758
Escala Micheline G 746-7758
491 Paquette Carmen M [9]-+ ◎ 749-0346
494 Scott Omer & Frances [9]-+ ◎ 745-1678
Scott Donald L 745-1678
Scott Bernard R 745-1678
495 Not Verified
498 Levesque Ernest J & Frances M [9]-+ ◎ 749-2874
502 Kaluski Eva [9]-+ 746-1353
503 Duggan Frank J & Barbara [2] ◎ 741-5283
506 Mahoney Wm L & Kath L [9]-+ ◎ 746-1839
Mahoney Maureen 746-1839
08 Rybeck [2] 749-1358
510 Bookgeois Ronal & Lise [2] ◎ 745-5878
511 Deschenes Jacques & Lucie [2] ◎ 744-3388
512 Mc Ewen Melville W & Rena B [9]-+ ◎ 749-4765
Mc Ewen Dawnellen 749-4765
Mc Ewen Rena 749-4765
516 Garrow Viola M [9]-+ ◎ 746-4525
520 Kuffner Joan F [9]-+ ◎ 749-8839

1993-94 WOLFFDALE CRESCENT-B

SOURCE: POLKS

Baillon Monica M 749-8839
524 Leduc Lucien L & Margt [9]+ ◎ 749-2036
534-535 Not Verified (2 Hses)
538 Seguin Yvan & Germaine [9]+ ◎ 749-2739
539 Gauthier Francois H & Ruth A [9]+ ◎ 746-6687
542 Day Bernard L & Pearl [9]+ ◎ 749-4265
543 Tierney Ivan M & Annette A [9]+ ◎ 746-0455
546 Nguyen Van Loi & Nhan [4] ◎ 746-0201
547 Casavant Paul & Denise [9]+ ◎ 741-2809
550★Sigouin Douglas P & Theresa G ◎ 746-1204
Sigouin Theresa G 746-1204
551 Hunter Robt [9]+ ◎ 746-0781
555 Charron Jean-Paul & Patricia E [5] ◎
Charron Patricia E
Carmanico Shirley A
556★Leclerc Christine ◎
559 Hotte J Aurele & Rita [9]+ ◎ 749-6314
560 Latreille Andre G & Pauline C [9]+ ◎ 744-1143
563 Lavigne Armand J & Jeannette [9]+ ◎ 745-8545
566 Not Verified
567★Carisse Guy & Marie ◎ 745-7437
Okeefe Eliz E 745-7437
Carisse Alex 745-7437
570 Riegle Jim [8] ◎ 741-3899
Mooney Gordon 741-3899
571 Wojciechowski Teresa [4] ◎ 744-6079
574★Larocque Frances L ◎ 749-1206
575 Moncion Henri & Jeannine [9]+ ◎ 746-4996
578 Wehbe Abdel R & Khougia [2] ◎ 741-9502
579 Sullivan John R & Doris L [2] 749-3878
582 Hurd James E & Carolyn R [9]+ ◎ 741-0813
Hurd Carolyn R 741-0813
Hurd Robert 741-0813
583 Nass Leona [9]+ ◎ 746-8013
Harris Jim & Ann L 746-8013
Harris Ann L 746-8013
586 Goulet Michel & Suzanne [2] ◎ 745-1484
587 Armstrong Bernard P & Lucille [9]+ ◎ 745-4643
Ewing Wm E 745-4643
590 Reid Todd R & Ivy M [9]+ ◎ 741-5615
591 Mc Connell Keith & Lucille [9]+ ◎ 746-0276
596 Montgomery Philip D & Agnes J [9]+ ◎ 744-6622
597 Stevenson Bonnie J [8] ◎ 744-7014
Helpin Neil J 744-7014
602 Bertrand J Geo S & Emma M [9]+ ◎

67 HOUSEHOLDS

1987 ALESTHER STREET

SOURCE: MIGHTS

615 Turpin E 749-4825
619 Gauthier Gilles 741-5671

DONALD ST INTERSECTS

647 Carisse Yvonne M Mrs ◎ 746-3680
Dalpe Alice F 745-9982
651 Gaudreault Leopold ◎ 745-7786
655 Horne Robt J ◎ 749-2527
659 Paskevicius Albinas ◎ 745-8910
663 Boyer Guy G ◎ 745-7933
667 Dube Roger ◎ 745-4714
671 Marquis David ◎ 749-1275
675 Alarie Rodolph E ◎ 746-2088
679 Williams R J 749-3047
683 Berube Andre ◎ 749-3333
687 Pomerleau Regent ◎ 749-0339
690 Wehbe Abdel 741-9502
692 Legault Claire 741-9234
693 Gordon Michl 746-7923
694★Wyman Wm 746-2126
696★Bedard Richard 746-0549
697★Arraj Rafic 749-6959
698 Gigoux Jean 745-2340
699★Moran Fay 746-9618
700 Walsh Lorraine 745-8487
702★Lyons Hugh 741-5894
703 Maharry Mike 745-4774
705 Sauve Raymond 746-4983
707★Ostashek John
709 Lalonde Louise R
713 Vien Alexandre
715 No Return

55

QUEEN MARY ST INTERSECTS

720 Buxton L 745-4861
722★Karayanis J 749-4718
727 Sterling James A 741-4478
729 Livingston Alfred 745-0182
733 El-Zein Ibraham 744-6579
735 Brunet Jean-Guy 745-1069
737 Stevenson Robt 749-1942
739 Roy R M 749-9877
743 Joseph Cyril
745 Ladouceur S 748-7844

48

PRINCE ALBERT INTERSECTS

725 Queen Mary Court Apartments senior citizen
1 Glocking Diane J
3 Randal G
4 Vacant
5★Guigue J
6 Workshop
7 Lalonde O 748-9858
8 Mc Grath Anne 746-3693
11 Stuart H C 746-8717
12 Boyer L 744-0894
14 Vacant
15★Bissonette M
16 Dooley June 746-7078
17 Williams E 745-3535
18 Mark A 746-3369
20 Legault Aime 746-9529
22★Jennings Monique 744-6800
24 Vacant
26 Addisson G 744-3614
28★Munroe David 748-6339
30★Pilon B
32 Sunstrum W 744-1969
33 Beckton H
34 Young Ralph
35 Daley Leonard 741-7127
36 Brady R
37 Grandbois Alf 748-6567
38 Foubert G 745-8103
39 Renaud R
40 Cook P 745-2066
41 Abbott Bernard 741-7163
42 Kibbee G 749-3401
43 Kerr H

1018 Petro Canada Serv Station gas sta 741-9797
1021 Bytown Lumber Co Ltd bldg materials 745-6825
1050 Lepage & Robillard Ltd furn 745-1559
1067 Sunoco 745-1886

OGILVIE RD INTERSECTS

1066 Caisse Populaire Cyrville Rockland Inc credit union 745-2123

572 Dube Leo J ● 746-6717
575 Proulx Roland A ● 741-7490
576 Watters Keith J ● 746-7470
579 Nang Tom 745-7077
580 O C T L Carpets Ltd
Chenier Maurice ● 749-7918
583 Emond Laurent ●
584 Buhain D ● 741-3514
588 Brule Pierre ● 746-3411
ALESTHER INTERSECTS
598 Burton Allen E ● 746-6054
599 Charron Edgar G ● 745-1712
602 Barbeau Paul 748-9729
603 Chirita Stan ● 744-6621
605 Apartments
1 Power S 746-2834
2 Vacant
3 Piette Roland 741-9105
606 No Return
609 Amyanah R 749-4362
610 Serrurier Lise

204

1235 Steinberg Inc adm ofc 745-6172
1237 City & District Savings Bank
744-3484
1240 St Laurent Towers Apartments
741-1705
101 Doucette James 746-1413
102★Lalande C 723-8665
103★Cram Arthur 744-6348
104★Hunter Ross 748-7658
105 Davies Catrin 749-4005
106 Vacant
107 Leclerc Y
108 Schiedel
110 Nguyen Tien 745-8385
110★Nguyen Thoi
111★Benware Stephen
114★Kroon S 744-1587
201 No Return
202★Chenier Robert J 748-3314
203 Siroix Aurel 746-6198
204 Rainville Adrien 741-9564
205 Mac Gougan Peter D 745-3477
206★Dimech C J 745-3087
Vacant
208★Albert F P 749-9065
209 Nelligan Raymond 749-4594
210 Tierney Eileen 749-1185
211 Pilon Francois
212 Guay J P 749-3106
213★Lambert Jeff 745-2864
214 Rankin David
215 Gardner A 745-3298
216 Watford J
301 Belanger M 741-5585
302 Maitland A
303 Richardson D
304 Perrault Jules L 744-1655
305 Tessier J 746-7278
306 Mc Lean Keith 746-7866
307 Hachem Hachem
308 Tierney Jack 745-5936
309 Wong Man-Fai
310★Lacroix C
311★Chretien Camille 745-7983
312 Vanasse Carmel
313 Beauvais P 741-9862
314 Blais H 744-2394
315 Saadalla Melek 746-4090
316 Wistaff Susan 746-5117
401 Tawia Helga 749-8224
402 No Return
403 Oberndorfing Gerhart

4★Daly Dorothy
519 Vacant
523 Vacant
527 Dicaire Vienne ● 746-9618
BERNARD INTERSECTS
540 Apartments
1 Lachapelle Eugene 749-1274
2 Lavigne Arth 745-7288
3 Beaudoin H 741-9743
4 Turpin Gilbert H 745-8468
548 Apartments
1 Nichol Beulah Mrs 749-7045
2 Facette Armand G 741-7000
3 Proulx Lionel 749-9849
4 Seward Carmel M 741-7151
553 Hutchingame Maynard 749-5114
554 Apartments
1 Crossier Samuel E 745-9536
2 Norton Charles 744-3829
3 Vacant
4 Bourdau Ernest D 745-0684
555★Labelle Carole 745-6593
559 Bernique Leo 749-9369
561 Feghali Khali 749-1507
562 Apartments
1★Lochyer Arthur 745-2452
2 Marchand H 741-5078
3 Beaudry Carmen Mrs 749-5108
4 Tessier Conrad 749-3239
567 Fish Dora 746-1663
568 Apartments
1 Lecuyer Gordon 749-2050
2 Beaudin Maurice 746-9921
3 Beaulieu Adelard 745-2762
4 Levis Paul H 741-4833
569 Villeneuve Donald 745-5382
573 Julien Lionel C
574 Apartments
1 Henry Ernest L 749-4043
2 Wallingford Robt 746-0212
3 Mombourquette Paul 741-6844
4 Brunet Emile
575 Villeneuve Gerard 745-4990
579 Brazeau Raymond
580 Apartments
1 Russenstrom Arnold 745-8665
2 Mann Raymond
3 Mallette Leo P 741-3798
4 Goyette Dorothy 741-9694
581 Belanger Jean Claude 741-4458
586 Apartments
1 Robertson Ernest 749-9434
2 Asselin Alford 745-6519
3 Lapointe Jacqueline Mrs 746-0470
4 Nefedow Paul 749-5832
587 Paul Danl T 744-2192
589 Rodier Dorothy 746-5444
592 Apartments
1 Richer Albert 746-3598
2 Hancock Horace 745-4026
3 Potvin Cecile 749-2555
4 Lacelle Aurele 746-2723
597 Castilloux Philbert 745-1968
598 Apartments
1 Clayton Edw 749-7484
★Franche Marcel A
3 Canadien J F 749-8762
4 Patachirk Arthur J 744-5623
599 Moyneur Edw 744-1224

516 Vacant
520 Vacant
524 Vacant
528★Essiambre Mike R 749-8743
BERNARD BEGINS
556 Jean Baptiste Marthe 746-7134
557 Queen Mary Street School 749-1692
Overbrook Daycare & School Age
Program 746-7762

QUEEN MARY-Contd
560 Charbonneau Gerard E ® 746-1394
568 Charette Arth 746-3028
570 Patafie Anthony 749-3433
578 Paquette Noel ® 749-4161
579 Gauvin Paul E ® 746-0495
580 Levesque Leon ®
581 Spagnoli Lello ® 745-1144
582★Lopes Lois ® 746-2845
581★Drouin Jacques 744-3266
591★Brazeau Jacques 746-5143
592 Parsons Geo G ® 745-6140
Parsons James 745-6140
ALESTHER INTERSECTS

977★Constantineau Roger A 741-6601
980 Apartments
1★Louis Joanne 741-6238
2★Guenter Don
3★Bernique Don 744-6271
997 Bleeker Stereo & TV Ltd 741-7934
DONALD ST ENDS
1006 Courchaine Jean T V 749-5330
Courchaine Aline ® 746-5902
1007 John's Sunoco Service Station Ltd 745-9668
St Laurent Self Service Gas Station 744-1324
1008 Courchaine Guy A ® 741-6865
1012 Ottway K 746-0356
1014 Graham Douglas 746-9409
1018★Taylor Ralph A 741-7054
1020 Beeler Arnold 741-1047
1021 St Laurent I G A Foodliner 745-9865
1024 Zaroski Michl 749-1283
1025 Bank Of Nova Scotia 745-0091
1026 Bisson Denis
1029 Radio Shack 746-5029
1030 Leblond Paul E 748-1290
1032 Simper Ian 749-2102
1033 Peintures Ultralux 741-7112
1034 No Return
1036 Vacant
1037 Bank Of Nova Scotia loan dept
1040 Jamieson H
1042 Hough Garry A 745-0574
1045 One Stop Laundromat And Dry Cleaners 741-2631
1046★Antle V L
1048 Lalonde I 745-6152
1052 Pigeon-Roy Insurance Brokers Ltd 746-4383
1054 De Sousa B Upholstering 741-4277
5 Pigeon-Roy Real Estate Appraisal Ltd 744-7670
1055 K-Mart Department Stores 746-4675
1060 Moon Palace Tavern Restaurant 745-1791
1070 Performance Motors Ottawa 741-0123
1076 Mac's Convenience Store groceteria 745-6365
1091 Midas Muffler & Brake Shop 744-1900

55

QUEEN MARY ENDS
1099 Castello Della Pasta 744-7488
CYRVILLE RD BEGINS
1110 St-Laurent Tire And Auto Service 745-7147
1116 Vacant
COVENTRY RD ENDS

1125 Public Optical 745-4000
1129 Co Operator The 745-0111
OGILVIE RD BEGINS
1163 Texaco Service Station serv sta 741-1818
1171 Civic Motors Ltd new cars 741-6676
1177 Waterbed Warehouse 749-0816
1181 Charlie Chan take out & restr 745-9178

STREET NOT LISTED

WOLFFDALE CRES -WEST FROM ALESTHER FIRST SOUTH OF DONALD

446 Douville Paul ◎ 746-0119
447 Muldoon Michl J ◎ 745-5910
450★Belanger Guy C 745-4809
451 Magalhaes Jose L 745-0126
454 Barry Kenneth J ◎ 746-4823
455 Vincent Jean Serge ◎ 745-7322
458 Courville Serge ◎
459 Dumont Theophile ◎ 746-1189
462 Irani Halim ◎ 741-2581
463 Pigeon Claude ◎ 745-8287
466 Lane M ◎ 745-3316
467 Leblanc J Ronald ◎
470 Lafleur
471★Lecavalien Gerry J ◎ 746-5254
475 Laprade Don 745-2281
478 Lacelle J Louis ◎ 741-9890
479 Pare Marielle ◎ 749-2122
OKEE ST INTERSECTS

1987 WOLFFDALE CRESCENT-B

SOURCE: MIGHTS

482 Labossiere Richd ® 745-2305
483 Lamirande Robt A ® 749-9098
486 Allan Robt M ® 749-1419
487 Bolger Clarence ® 745-3145
490 Escala Kent ® 746-7758
491 Paquette Fernand ® 749-0346
494 Scott Omer ® 745-1678
495 Kelly Georges ® 746-7155
498 Levesque Ernest J ® 749-2674
502 Kaluski Peter ® 746-1353
503 Archambault Marcel ® 746-8371
506 Mahoney Wm L ® 746-1839
508 Ryback John G ® 749-1358
510 Bourgeois Ronald ® 744-2188
511★Fairfield Claude 749-6900
512 Mc Ewen Melville W ® 749-4765
516 Garrow Viola M ® 746-4525
520 Kuffner D ® 749-8839
524 Leduc Lucien L ® 749-2036
534 No Return
535 Therien Marcel 749-9087
538 Seguin Yvan ® 749-2739
539 Gauthier Francois H ® 746-6687
542 Day Bernard L ® 749-4265
543 Tierney Ivan M ® 746-0455
546 Tomczyk Patricia ® 749-6642
547 Casavant Paul ® 741-2809
550★Siquin Douglas ®
551 Hunter Robt ® 746-0781
555 Vacant
556 Hartnett Michl ® 745-8544
559 Hotte J Aurele ® 749-6314
560 Latreille Andre G ® 744-1143
563 Lavigne Armand J ® 745-8545
566 Mayer Richard ® 745-1713
567 Carisse Guy ® 745-7437
570 Riegle Jim ® 741-3899
571 Proulx Bernadette ® 746-1484
574 Larocque Frances Mrs ® 749-1206
575 Moncion Henri ® 746-4996
578 De Sousa Louis ®
579 Shaw M ® 749-8916
582 Hurd James E ® 741-0813
583 Nass Wm L ® 746-8013
586 Serrurier Emile ®
587 Armstrong Bernard ® 745-4643
590 Reid Todd R 741-5615
591 Mc Connell Keith ® 746-0276
596 Montgomery Philip D 744-6622
597 Stevenson B ® 744-7014
602 Bertrand Geo ®

1981-82 ALESTHER STREET-A

SOURCE: MIGHTS

618 Turpin Euclide ® 749-4825
619 Gauthier Rheal 741-5657
DONALD ST INTERSECTS
647 Carisse Andre ® 746-3680
Dalpe Alice 745-9982
651 Pilon Rheal J ® 749-3517
655 Horne Robt J ® 749-2527
659 Paskevicius Albinas ® 745-8910
663 Boyer Guy G ® 745-7933
667 Dube Roger ® 745-1714
671 Marquis David ® 749-1275
675 Alaric Rodolph E ® 746-2088
679★Williams R J 749-3047
683 Beaulieu Luce ® 741-3153
687 Pomerleau Regent ® 749-0339
690 Olive Wm 745-8193
692 Legault Claire 741-0194
693 Bailey Lucille
694 Leger Guy 748-2126
696 Craig James C 746-6149
697 Leclair Bernard
698★Gigoux Jean 745-2340
699★Khodeir Gilberte 741-2553
700 Walsh Gerry W 744-1564
702★Danis D A 746-8200
703 Faulkner Roy 749-8278
705 Sauve Raymond 475-4983

707★Campbell Glen 741-8708
709★Lalonde Louise R 741-3502
713 Vien Alexandre
715 Smith-Doiron Marcel 745-8986

QUEEN MARY ST INTERSECTS
727 Campbell Kenneth 746-5635
729 Mombourquette Paul 746-9848
733 Anderson Carol 746-5980
735 Brunet Jean-Guy 745-1069
737 Stevenson Robt 749-1942
739 Mullins Geo
743 Ouellette Rita 749-4640
745★Benson N 746-5822

PRINCE ALBERT INTERSECTS
725 Queen Mary Court Apartments
1 Workshop
2 Vacant
3★Brunet E
4 Berthelot Violet 749-4167
5★Froment A
6 Sarazin Agnes 741-3213
7★Siuyer Lloyd
8 Mc Grath Anne 746-3693
9★Goulet M I 746-7440
10 Vacant
11 Vacant
12★Osborne A 745-4322
13 Vacant
14 Vacant
15 Vacant
16 Guigue Rose
17★Williams E
18 Taylor Kate G 745-4651

Report ID: 24053100257 - 06/14/2024
www.erisinfo.com

1018 Gulf Self Serve gas sta 741-9797
1021 Bytown Lumber Co Ltd bldg materials 745-6825
1060 Lepage & Robillard furn 745-1559
OGILVIE RD INTERSECTS
1066 Caisse Populaire De Cyrville Ltee credit union 745-2123
1070 Pro Pool Table Sls & Service 741-6728

568 Bourguignon Guy 746-0462
571 Walsh Ivan V @ 749-9775
572 Dube Leo J @ 746-6717
575 Proulx Roland A @ 741-7490
576 Watters Keith J @ 746-7470
579 Villeneuve Aurele @ 746-8990
580 Neville Rufus V @ 749-8590
583 Emond Laurent
584★Lavoie Gaston @ 741-3514
588★Lafleche Albert J @ 746-5417
ALESTHER INTERSECTS
598 Burton Allen E @ 746-6054
599★Fournelle Ivan Y @ 741-9940
602 Roy Melvin
603 Shaw Myrtle 749-5416
605★Wint Keith 741-3239
Lavergne Laurent 746-6998
Dionne Denise 744-2257
606★Carey Robt 749-8054
★Beaulieu Alain 745-1688
609★Amyanah R 749-4362
Russell Kenneth 745-8719

Report ID: 24053100257 - 06/14/2024
www.erisinfo.com

DONALD—Contd
610 Gibson Coleen 741-6007

1239 Direct Film 745-5012
1240 St Laurent Towers Apartments 741-1705
101 Groulx M 744-1435
102★Villeneuve Regean 741-7799
103★Stang L 746-8156
104★Poirier Nicole
105 Brazeau M 746-0558
106 St Aubin B
107 Bowmen I 749-7904
108★Rombough Richd L
110 Vaillancourt J B 741-2432
111 Ayotte J M
114 Parent Francois 746-8643
201 Perron G 746-2916
202★Hotte L 741-1524
203 Proulx Michel
204★Rainville Adrien 741-9564
205★Lemieux Paul E
206 Mainville J M 741-5121
207 No Return
208 Schecter Syd
209 Nelligan Raymond 749-4594
210 Tierney Eileen 749-1185
211 Pilon Francois
212 Guay J P 749-3710
213★Comtois Richd 745-8734
214 Lacombe L
215 Mongeau Marguerite 749-5139
216★Simard Osias
301 Tetreault Louise 746-8413
302★Gordon S J 745-0147
303 Philippon Yolande 741-0692
304 Perrault Jules 744-1655
305★Hylton M 741-4449
306★Fortier R 744-2613
307★Dupuis F
308★Kamen Joseph
309★Fung V
310 Tessier Dan 741-8814
311★Leduc S D 741-5203
312★Blaschuk J
313★Mc Donald C 749-8407
314★Mc Curoy E 741-1172
315★Saadalla Melek Mrs 746-4090
316★Bahadur B 744-3622
401 Tawin Helga 749-8224
402 George Rita 741-5965
403 Nasrallah David 741-6598
404★Miller K 745-8491
405 Poulin Gerald 749-3447
406 Prest Rene 745-5459
407★Patry Claude 746-9643
408★Sinnathamby Sidney 749-7779
409★Coates R
410★Lavergne Danny 746-6869

3 Bellefeuille Ernest 745-2310
4 James Thos A 745-4976
519 Bouvier Andre
523 Jolicoeur Raymond 746-6046
527★Charbonneau Robt J 741-9389
BERNARD INTERSECTS
540 Apartments
1 Lachapelle Eugene 749-1274
2 Lavigne Arth 745-7288
3★Ballard R 746-6335
4 Constantineau Origene 741-7157
548 Apartments
1 Nichol Arth 749-7045
2 Facette Armand 741-7000
3 Proulx Lionel 749-9849
4 Seward Carmeli 741-7151
553 Hutchingame Maynard 749-5114
554 Apartments
1★Crossier Edw 745-9536
2 Cameron Pearl 741-1304
3★Mallette John 745-1863
4 Facette Lucien 745-0817
555 Wilkinson Lorne J 749-3840
559 Bernique Leo 749-9369
561 Laird Edw 745-8872
562 Apartments
1 Lockyer Arth 745-2452
2 Ryan Ida 745-6388
3 Beaudry Geo 749-5108
4 Tessier Conrad
567 Fish Dora 746-1663
568 Apartments
1★Lecuyer Gorden 749-2050
2 Beaudin Maurice 746-9921
3 Beaulieu Adelard 745-2762
4★Alleert Romeo 746-9351
569 Villeneuve Donald 741-5157
573 Julien Lionel C
574 Apartments
1 Olson Victor 749-0396
2 Saumier Rene
3 Barnade Alice 749-7615
4 Thompson Barbara
575 Villeneuve Gerard 745-4990
579 Labelle Raymond D
580 Apartments
1 Russenstrom Arnold 745-6685
2 Demers Georgette 741-9817
3★Mallette Leo P 741-3798
4 Mills David 746-7535
581 Belanger Jean Claude 741-4458
586 Apartments
1 Robertson Ernest 749-9434
2★Asselin Alford 745-6519
3★Faureau Lucien 746-1422
4 Nefedow Paul 749-5832
587★Paul Danl T 744-2192
589 Rodier Dorothy 746-1584
592 Apartments
1★Richer Albert 746-3598
2★Oblais Hamel 741-4359
3★Lefebvre Germaine A 749-4915
4 Vacant
597 Castilloux Philbert 745-1968
598 Apartments
1 Clayton Edw 749-7484
2 Desloges Raoul 745-4029
3★Descoeurs Gustave 745-3235

1981-82 PRINCE ALBERT STREET-B

SOURCE: MIGHTS

1 Randall Geo
599 Moyneur Edw

1981-82 QUEEN MARY STREET

SOURCE: MIGHTS

528 Gravel Jean Pierre 746-0746
BERNARD BEGINS
556★Goyette Albert 746-2553
557 Queen Mary Street School 749-1692
Overbrook Daycare & School Age Program 757-778
560 Vacant
568 Charette Arth 746-3028
570 Patafie Anthony 749-3433
578 Paquette Noel @ 749-4161
579 Gauvin Paul E @ 746-0495
580 Levesque Leon @ 745-4566
581 Spagnoli Lelio @ 745-1144
582 Lefebvre Napoleon @ 745-0189
591 Brazeau Jacques
592★Parsons Geo G @ 745-6140
★Parsons James
ALESTHER INTERSECTS

980★Walker D 745-3287
★Gaffin John J 745-6468
★Lauzon G 746-7309
DONALD ST ENDS
1006 Courchaine Jean Radio & TV Repairs 749-5330
Courchaine Jean © 746-5902
1007 John's Sunoco Service Station 745-9668
St Laurent Self Service Gas Station 744-1324
1008 Courchaine Guy A ©
1012 Butler James 749-4846
1014 Graham Douglas 746-9409
1018 Mc Govern Leo 741-5070
1020 Beeler Arnold 741-1047
1021 Joanisse I G A 745-9865
1024 Zaroski Michl 749-1283
1025 Bank Of Nova Scotia 745-0091
1026 Bisson Denis
1029 Radio Shack 746-5029
1030★Gauthier F 745-2916
1032 Simper Ian 749-2102
1033 International Paints 741-7112
1034 Hillier Gregory J 749-8990
1036 Mann Robt
1037 Vacant
1040 No Return
1042 Hough Gary 746-0016
1045 Brown's Cleaners coin dry cln & wash 741-2631
1046 Ethier Pierre 746-4285
1048★Baltussen Henry 745-6152
1052 Pigeon-Roy Limited insurance & real estate 746-4383
1054 De Sousa Manuel Upholstering uphol 746-6934
1055 K-Mart Department Stores 746-4675
1060 Moon Palace Tavern Restaurant 745-1791
1070 Performance Motors 741-0123
1076 Mac's Milk Ltd groceteria 745-6365
1091 Midas Muffler Shop 744-1900

QUEEN MARY ENDS
1099 Chantal's Dining Lounge restr 744-3365
CYRVILLE RD BEGINS
1110 Firestone Tire & Rubber Co Of Canada 745-7147
1116 Saint Laurent Separate School 745-0366
COVENTRY RD ENDS
1125 Carnatan Carpet Co Ltd 744-3636
1129 Bleeker Stereo & T V Ltd 741-7934
1133 No Return
OGILVIE RD BEGINS
1163 Texaco Serv Station serv sta 741-1818
Tilden-Rent-A-Car 745-0408
Ottawa Valley Auto Service 741-5360
1171 Civic Motors Ltd new cars 741-6676

STREET NOT LISTED

WOLFFDALE CRES —WEST FROM ALESTHER
FIRST SOUTH OF DONALD

446 Douville Paul © 746-0119
447 Muldoon Michl J © 745-5910
450★Moore Richd 745-0577
451★Magalhaes Jose L 745-0126
454 Barry Kenneth J © 746-4823
455 Vincent Jean Serge © 745-7322
458 Courville Serge ©
459 Dumont Theophile © 746-1189
462 Kassim Kalim © 745-5394
463 Pigeon Claude © 745-8287
466 Lane Martin © 745-3316
467 Leblanc J Ronald © 745-1611
470 Lafleur Geo E © 749-0258
471 Delorme Wilfrid © 746-0764
475 Laprade Don 745-2281
478 Raposo Pokfir O © 746-6917
479 Pare Jean-Guy © 749-2122
OKEE ST INTERSECTS
482 Labossiere Richd © 745-2305
483 Lamirande Robt A © 749-9098
486 Allan Robt M © 749-1419
487 Bolger Clarence © 745-3145
490 Sabourin Ernest © 749-8169
491 Paquette Fernand © 749-0346
494 Scott Omer © 745-1678
495 Algozino Saml © 749-0716
498 Levesque Ernest © 749-2674
502 Kaluski Peter © 746-1353
503 Archambault Marcel © 746-8371
506 Mahoney Wm L © 746-1839
508 No Return
510 Bourgeois Ronald © 744-2188
511 Perras Rheal © 745-6364
512 Mc Ewen Melville W © 749-4765
516 Garrow Viola M © 746-4525
520 Kuffner Joan © 749-8839
524 Leduc Lucien © 749-2036
534 Surette R F © 746-2970
535 Richard Andre © 741-4566
538 Seguin Yvan © 749-2739
539 Gauthier Francois H © 746-6687
542 Day Bernard L © 749-4265
543 Tierney Ivan M © 746-0455
Can Beaulac Herve © 746-2883
547 Rochon Jean M © 746-0150
550 Sigouin Douglas P ©
551 Hunter Robt © 746-0781
555 Charron Jean-Paul ©
556 Hartnett Michel 745-8544
559 Hotte J Aurele © 749-2628
560 Lauzon Donat J 745-3022
563 Lavigne Armand J © 746-0264

649

566 Mayer Richard © 745-1713
567★Carisso Guy
570 Milner Robt I © 746-1138
571 Proulx Bernadette © 746-1484
574 Larocque Frances Mrs © 749-1206
575 Moncion Henri © 746-4936
578 Bergevin Geo E © 746-2491
579 Carriere Yvon © 746-4712
582 Hurd J © 741-0813
583 Nass Wm L © 746-8013
586 Lalonde Claude © 745-5839
587 Armstrong Bernard © 745-4643
590 Reid Todd R 749-5536
591★Mc Connell Keith © 746-0276
596★Montgomery Philip D 746-7682
597 Baldrate Fredk © 749-2262
602 Bertrand Geo ©

617 Spearman Gerald E @ 746-1882
619 Danjaw Olga @ 745-7619

DONALD ST INTERSECTS

647 Carisse Andre @ 746-3680
651 Pilon Rheal J @ 749-3517
655 Horne Robt J @ 749-2527
659 Paskevicius Albinas @ 745-8910
663 Boyer Guy G @ 745-7933
667 Dube Roger @ 745-4714
671 Marquis David @ 749-1275
675 Alarie Rudolph @ 746-2088
679 Williams Reginald @ 749-3047
683 Dugas Maurice @ 749-0408
687 Pomerleau Regent @ 749-0339
690 Brown Lyle 745-1412
692 Legault Claire 741-0194
693 Corneau Marcel 745-3927
694 Leger Guy 746-2126
696 Craig James C 746-6149
697 Njolstad Per 745-6363
698★Dagenais Garry
699 Olive Wm 745-8193
700 Mc Hugh Patk 746-5061
702★Danis Denis 746-3761
703 Faulkner Roy 749-8278
705 Burke Clifford J 749-1896
707 Sharpe Lilian 749-2132
709 Lepine Robt 745-0945
713★Dunlop Warren 745-3629
715 Smith-Doiron Marcel 745-8986

QUEEN MARY ST INTERSECTS

727 Campbell Kenneth 746-5635
729★Mombourquette Paul 746-9848
733 Anderson Carol 746-5980
735 Brunet Jean-Guy 745-1069
737 Stevenson Robt 749-1942
739 Mullins Geo
743★Quarrington Richd 746-4167
745 Hanna Wm R 746-4596

PRINCE ALBERT INTERSECTS

725 Queen Mary Court Apartments
1 Tremblay Edgar
2 Scharf Sarah M 745-5901
3★Caudreau Y
4 Berthelot Violet Mrs 749-4167
5 Pruner Geo 745-7510
6★Sarazin Agnes
7★Denis Viateur 749-8202
8★Floyd Richd
9 Martin Anne G 746-3128
10 Osborne Alden 745-2083
11 Quintal Doria 746-2841
12 Comrie Mabel O Mrs 745-3686
13 Cameron Christina 746-8542
14★Lachance D
15★Wilson R C
16 Labelle Antoinette Mrs
17 Danis Josephine
18 Taylor Kate G Mrs 745-4651
19 Wetherilt Doris Mrs 749-6463
20 Bartsch Arth W 745-8595
21 Chenevert Bella 745-4216
22 De Rinzy S D
23★Legault Omer 741-7198
24 Vacant
25★Hemke Bruno 741-1106
26 Williams Elsie M Mrs 745-3535
27 Froment Agnes Mrs
28 Massie Marie L Mrs 746-9749
29★Ducharme M

1013 No Return
1018 Esso Gas Bar 746-6515
Imperial Car Wash 746-6515
1021 Bytown Lumber Co Ltd 745-6825
1050 Lepage & Robillard Ltd furn 745-1559
1061 Vacant
1065 Valley Luncheonette restr 741-9155
CYRVIE RD INTERSECTS

OKEE ENDS
567 Poulin Raoul © 749-8195
568 Lowe Eric L © 746-1066
571 Walsh Ivan V © 749-9775
572 Dube Leo J © 746-6717
575*Proulx Roland A © 741-7490
576 Watters Keith J © 746-7470
579 Villeneuve Aurele © 746-8990
580 Neville Rufus V © 749-8590
583 Desjardins Edw J © 749-4421
584*Buhain Dante © 741-3514
588 Grainger Garnet E © 749-2984
ALESTHER INTERSECTS
598 Burton Edley A © 746-6054
599 St Georges Emile © 745-1253
602 No Return
603 Shaw Myrtle © 749-5416
605*Jodoin Robt 749-3658
*Lavergne Laurent 746-6995
606 Racette Viola
609 Ladas Joan P 745-6972
Brunard Rita Mrs 749-4362
ST LAURENT INTERSECTS
610 St Louis Lucien E 746-1743

Report ID: 24053100257 - 06/14/2024
www.erisinfo.com

1976 PRINCE ALBERT STREET

SOURCE: MIGHTS

4 James Thos A 745-4976
519 Gutoski John 746-6535
523 Jolicoeur Raymond 746-5046
527★Delaney Wm 746-5492
BERNARD INTERSECTS
540 Apartments
1 Taylor Wm H 745-1268
2★Mc Kinnell David 749-9135
3 Ballard Mary 749-6335
4★Clarke S
548 Apartments
1 Nichol Arth
2 Brosseau Paul 749-8048
3 Proulx Lionel 749-9849
4★Levecque Andrew 746-7708
553 Hutchingame Maynard 749-5114
554 Apartments
1★Cormack Daisy 746-1725
2 Cameron Pearl Mrs 741-1304
3 Crosier Edw
4★Smith Doiron R 746-1631
555 Wilkinson Lorne J 749-3840
559★Bernique Leo 749-9369
561 Laird Edw 745-8872
562 Apartments
1 Colbourne Walter 741-0927
2 Ryan Edgar 745-6388
3 Ricard Paul 749-5628
4 Dormer Henry J 745-5224
567 Fish Dora Mrs 746-1663
568 Apartments
1 Davidson Nellie Mrs 745-7589
2 Champagne Leon 745-0636
3 Richardson Bertha Mrs 749-2347
4 Robitaille Leo 745-3267
569 Villeneuve Donald 741-5157
573 Julien Lionel C 745-4897
574 Apartments
1 Olson Victor 749-0396
2★Saumure R
3★Perkins Edna 745-6992
4★Mella James 745-6666
575 Villeneuve Gerard 745-2611
579 Labelle Raymond D 749-0691
580 Apartments
1 Clelland J
2 Cousineau Parise Mrs 745-3056
3 Mc Arthur Paul 749-0834
4 Mills David 746-7535
581 Mongeon Gerard 745-5103
586 Apartments
1★Robertson E
2 Grey Mary Mrs 745-5444
3 Bertrand Armand 749-9086
4 Warden Violet
587 Lavigueur Roger J 746-0862
589★Rodier Robt
592 Apartments
1 Hamilton Maria Mrs 746-1317
2★Chene Herve 749-8297
3 Sadler Frank 741-2562
4 Phillips Wesley 749-2519
597 Vacant
598 Apartments
1★Lefebvre Laurent 749-8615
2 Parent Albert E 749-5794
3★Ronayne Hugh 741-9987
4★Randall Geo
599 Moyneur Edw 746-9485

1976 QUEEN MARY STREET

SOURCE: MIGHTS

528 Manion
BERNARD BEGINS
556 Burden Robt 745-6609
557 Queen Mary Street School 749-1692
560 Page Richd © 745-1176
568 Lavictoire Jean-Marc 745-8753
570 Patafie Anthony 749-3433
578 Paquette Noel © 749-4161
579 Gauvin Paul E © 746-0495
580 Levesque Alicia Mrs © 745-4666
1★Spagnoli Lelio © 745-1144
581★Avon Irene 749-0963
582 Lefebvre Napoleon © 745-0189
591★Touchette Sandra 746-1642
592 Decarie Roger © 745-1335
ALESTHER INTERSECTS

★David Joy B
968 St Laurent Bible Chapel 741-1255
969 No Return
972 Berube Lucille Mrs © 749-9805
Bisson John L 746-0840
973 Dino's Pizzeria Take Out 745-5692
976 Valiquette Marcel 745-8675
★Dea Yvette 749-4915
977★Bassila Yousef
980★Rochon Guy
★St Louis Michl
★Bottcher Ott 741-3544
DONALD ST ENDS
997 No Return
1006 Courchaine Jean Radio & TV Repairs 749-5330
Courchaine Jean A © 746-5902
1007 John's Sunoco Service Station 745-9668
1008 Courchaine Guy A © 741-1808
1012 Butler James 749-4846
1014 Graham Douglas 746-9409
1018 Mc Govern Leo 741-2691
1020 Beeler Arnold 741-1047
1021 Joanisse I G A 745-9865
1024 Zaroski Michl 749-1283
1025 Bank Of Nova Scotia The 745-0091
Sabourin Roger 741-5276
1029 Radio Shack 746-5029
1030 Proulx Andre 749-6157
1032★Simper Ian 749-2102
1033 International Paints 741-7112
1034 No Return
1036★Martin James
1037 Boutique De La Coiffure 746-3282
1040 Couvrette Rheal T 746-6669
1042 Hough Gary 746-0016
1045 Cleanorama coin dry cln & wash 741-2631
1046 Meagher Carl 749-3357
1048 Chagnon Anita 749-0681
1052 Pigeon-Roy Limited insurance & real estate 746-4383
1054 De Sousa Manuel Upholstering 746-6934
1055 K-Mart Department Stores dept store 746-4676
1056 Pigeon-Roy Ltd ofc
1060 Moon Palace Tavern Restaurant 745-1791
1070 A & W Drive-In (Ottawa) Ltd 741-4291
1076 Mac's Milk Ltd groceteria 745-6365
1091 Vacant

QUEEN MARY ENDS
1099 Parisien Ken Pianos Ltd 741-0111
CYRVILLE RD BEGINS
1110 Firestone Tire & Rubber Co Of Canada 745-7147

1115 Imperial Muffler 749-2157
1116 Saint Laurent Separate School 745-4344
COVENTRY RD ENDS
1125 Reed National Drapery 746-9550
OGILVIE ST BEGINS
1129 Unemployment Insurance Commission 993-2114
1133 I A C Limited finance 741-0222
Niagara Finance finance co 745-0378
1163 Kavanagh Texaco Serv 741-7734
1171 Budget Rent A Car Of Ottawa 746-9280
1177 Dodwell Film Services Ltd film rentals 746-7550
1179 Slack Shack Ltd men's wear 745-1439
[illegible] Tavern take out & restr 745-9178

STREET NOT LISTED

255

WOLFFDALE CRES —WEST NORTH THEN EAST FROM ALESTHER BACK TO SAME FIRST SOUTH OF DONALD

446 Douville Paul @ 746-0119
447 Muldoon Michl J @ 745-5910
450 Berube Emile @ 746-1304
451★Gleason R E 746-8936
454 Barry Kenneth J @ 746-4823
455 No Return
458 Courville Serge @ 749-0267
459 Dumont Theophile @ 746-1189
462 Desjardins Yvon @ 749-8336
463 Pigeon Claude @ 745-7246
466 Kossats James D @ 749-1715
467 Leblanc J Ronald @ 745-1611

1976 WOLFFDALE CRESCENT-B

SOURCE: MIGHTS

470 Lafleur Geo E ◎ 748-0258
471 Delorme Wilfred J ◎ 746-0764
475 Laprade Donald J 745-2281
478 Raposo P ◎ 746-6917
479 Pare Jean-Guy ◎ 749-2122
OKEE ST INTERSECTS
482 Labossiere Richd ◎ 745-2305
483 Lamirande Robt A ◎ 749-9098
486 Allan Robt M ◎ 749-1419
487 Bolger Clarence ◎ 745-3145
490 Sabourin Ernest ◎ 749-8169
491 Paquette Fernand ◎ 749-0346
494 Scott Omer E ◎ 745-1678
495 Algozino Saml ◎ 749-0716
498 Levesque Ernest ◎ 749-2674
502 Kaluski Peter ◎ 746-1353
503 Archambault Marcel ◎ 746-8371
506 Mahoney Wm L ◎ 746-1839
508 Laschawski Victor ◎ 749-4612
510 Davies Harold W Rev 749-4637
511 Perras Rheal ◎ 745-6364
512 Mc Ewen Melville W ◎ 749-4765
516 Garrow Viola M ◎ 746-4525
520 Kuffner Donald F ◎ 749-8839
524 Leduc Lucien ◎ 749-2036
534 Surette Roy ◎ 746-2970
535 Richard Andre ◎ 741-4566
538 Seguin Yvan ◎ 749-2739
539 Gauthier Francois H ◎ 746-6687
542 Day Bernard L ◎ 749-4265
543 Tierney Ivan M ◎ 746-0455
546 Saint Denis Gertrude Mrs ◎ 749-7243
547 Rochon Jean M ◎ 746-0150
550 Sigouin Douglas ◎
551 Hunter Robt ◎ 746-0781
555 Tremblay Gerard ◎ 745-7551
556 Lavergne Fernand Mrs ◎ 749-0347
559 Hotte J Aurele ◎ 749-2628
560 Lauzon Donat J ◎ 745-3022
563 Lavigne Armand J ◎ 746-0264
566 Miller Charles ◎ 749-3952
567 Manseau Berthe
570 Milner Robt I ◎ 746-1138
571 Proulx Bernadette ◎ 746-1484
574 Larocque Blumer ◎ 749-1206
575 Moncion Henri ◎ 746-4996
578 Bergevin Geo E ◎ 746-2494
579 Schultz Robt ◎ 741-0627
582 Hurd James E ◎ 741-0813
583 Nass Wm L ◎ 746-8013
586 Lalonde Claude ◎ 745-5839
587 Armstrong Bernard P ◎ 745-4643
590 Reid Todd R C ◎ 749-5536
591 Landry Lucille Mrs ◎ 746-0276
596 Young Robt H ◎ 746-5057
597 Baldrate Fredk ◎ 749-2262
602 Bertrand Geo ◎ 741-1777

1971 ALESTHER STREET

SOURCE: MIGHTS

615 Turpin Euclide ◎ 749-4825
619 Danjaw Olga ◎ 745-7619
DONALD INTERSECTS
647 No Return
651 Pilon Rheal J ◎ 749-3517
655 Horne Robt J ◎ 749-2527
659 Paskevicius Albinas ◎ 746-6956
663 Boyer Guy G ◎ 745-7933
667 Helmstaedt Herwart 746-3414
671 Marquis David ◎ 749-1275
675 Alarie Rudolph ◎ 746-2088
679 Williams Reginald ◎ 749-3047
683 Dugas Maurice ◎ 749-0408
687 Pomerleau Regent ◎ 749-0339
690 Brown Lyle 745-1412
692 Lachance Joseph 749-9513
693 Andersen Ole 749-8753
694 Niman Robt 745-6625
696 Craig James C 746-6149
697 Jolstad Per 745-6363
698 Edgerton Lloyd H 745-3365
699 Plouffe Vital R 749-5778
700 Bourne Ellen 746-8544
702 Nielsen Anton 745-1761
703 Fauteux Roger V 749-5789
705 Burke Clifford J 749-1896
707 Sharpe Fred C 749-2132
709 Papai Julius 749-9286
713 Delorme Andre 749-6371
715 Barry Jack R 745-2352
QUEEN MARY INTERSECTS
727 Clouthier Bruce R 749-4897
729 Proud Theresa 746-4580
733 No Return
735 Brunet Jean G 745-1069
737 Stevenson Robt 749-1942
739 Mullins Geo 745-3744
743 White Arth E 746-1248
745 Hanna Wm R 746-4596

ALEUTIAN DR

1971 BERNARD STREET

SOURCE: MIGHTS

PRINCE ALBERT INTERSECTS
725 QUEEN MARY COURT APARTMENTS
1 Hamilton Marguerite 745-7420
2 Scharf Sarah M Mrs 745-5901
3 Johnson Robt G 745-5121
4 Corey Edith M Mrs 749-3322
5 Pruner Geo 745-7510
6 Aumond Martha 745-4644
7 Tyson Jean Mrs 745-1527
8 Doyle Raymond R 749-7394
9 Martin Anne G 746-3128
10 Houlahan Agens 749-3155
11 Quintal Doria 746-2841
12 Comrie Mabel O Mrs 745-3686
13 Cameron Christina 746-8542
14 Balkwill Robena Mrs
15 Arnold Charlotte Mrs 745-3452
16 Howse Gladys I Mrs 745-4357
17 Kimber Ezillah H Mrs 745-4290
18 Taylor Kate G Mrs 745-4651
19 Redford Margt 745-5439
20 Ayers Marjorie Mrs 745-3422
21 Cheneverti Bella 745-4216
22 No Return
23 Stuart Wm 749-3272
24 Smith Mary Mrs
25 Donovan Victoria 749-1967
26 Williams Elsie M Mrs 745-3535

1971 CYRVILLE ROAD

SOURCE: MIGHTS

1013 Yamaha Music Course 745-7072
Arrow Transfer 745-3612
Keyboard Services piano reprs

1017 No Return
1018 Imperial Car Wash 746-6515
Esso Gas Bar 746-6515

1021 Bytown Lumber Co Ltd 745-6825
1050 Lepage & Robillard Ltd furn 745-1559
1057 Gloucester Township Fire Station No 3 822-2343

1971 DONALD STREET

SOURCE: MIGHTS

OKEE ENDS
567 Poulin Raoul © 749-8195
568 Lowe Eric L © 746-1066
571 Walsh Ivan V © 749-9775
572 No Return
575 St George Marguerite Mrs © 746-6969
576 Watters Keith J © 749-5542
579 Villeneuve Aurele © 746-8990
580 Neville Rufus V © 749-8590
583 Desjardins Eddy © 749-4421
584 Geitzler Eric F © 749-0841
588 Grainger Garnet E © 749-2984
ALESTHER INTERSECTS
598 Burton E Allen © 746-6054
599 St Georges Emile © 745-1253
602 Barnaby Bernard 749-4614
603 Shaw Myrtle © 749-5416
605 1 Gauthier Jean-Paul 745-6584
2 Paquette Pierre G 745-8834
3 Belanger Mona 745-5067
606 Racette Marcel M 746-8441
609 1 Ladas Chas
2 Brassard Rita Mrs 749-4362
3 Gorley Peter
ST LAURENT INTERSECTS
610 Darwen J G 745-1713

1971 PRINCE ALBERT STREET-A

SOURCE: MIGHTS

4 James Thos A 745-4976
519 Gutoski John 746-6535
523 Jolicoeur Raymond 746-5046
527 Armstrong Edw G 749-7552
BERNARD INTERSECTS
540 Apartments
1 Taylor Wm H 745-1268
2 Shaver Blanche Mrs 749-8491
3 Packham Percy B 749-3970
4 Belanger Emile 745-3225

548 Apartments
1 Lepine Alma Mrs
2 Lefebvre Marie B 746-5512
3 Proulx Lionel 749-9849
4 Cairns Wm J 749-0805

553 Matton Orland R 746-8389

554 Apartments
1 McCormack Joseph A 746-1725
2 Hunter Lorenzo 745-1200
3 Warner G Percy 746-4963
4 Dickinson Geo H 745-1783

555 Wilkinson Lorne J 745-7214
559 Shelaga Peter 745-5803
561 Laird Edw 745-8872

PRINCE ALBERT-Contd

562 Apartments
1 Myers Arth H 745-2460
2 Ryan Edgar 745-6388
3 Parrington James 745-2358
4 Dormer Henry J
567 Fish Dora Mrs 746-1663
568 Apartments
1. Davidson Alf 745-7589
2 Perkins Chas W 745-0497
3 Richardson Wm 749-2347
4 Robitaille Leo 745-3267
569 Brule Gerard E 746-1498
573 Julien Lionel C 745-4897
574 Apartments
1 Olson Victor 749-0396
2 Lee Raymond 746-0842
3 Potter James R 749-1769
4 No Return
575 Lamoureux Horace X
579 Labelle Raymond D 749-0691
580 Apartments
1 Martel Jean B 746-4276
2 Cousineau Parise Mrs 745-3066
3 McArthur Paul 749-0834
4 Mills David 746-7535
581 Mongeon Gerard 745-5103
586 Apartments
1 Melville Alex 749-4278
2 Grey Mary Mrs 745-5444
3 Thompson Margt Mrs 745-4707
4 Warden Alf
587 Lavigueur Roger J 746-0862
589 Easey Andrew R 745-9713
592 Apartments
1 Hamilton Curtis W 746-1317
2 Lacelle Emile 749-4338
3 Burton Ernest 745-5639
4 Grant Finlay 745-3583
597 Mason Robt T
598 Apartments
1 Paquette Ambrose 749-3538
2 Parent Albert E 749-5794
3 Mayotte Albert D 749-3562
4 Baldry Raymond 745-8633
599 Staples John L 745-2876

520 Tapp Michl 746-8683
524 Cousineau Conrad P 746-6409
528 Gregoire Gaetan 745-5258
BERNARD BEGINS
556 Bellefeuille Roger A 749-0196
557 Queen Mary St School 749-1692
560 Diloretto Dominique © 745-3242
568 Lavictoire Jean-Marc 745-8753
570 Patafie Anthony 749-3433
578 Paquette Noel © 749-4161
579 Gauvin Paul E © 746-0495
580 Levesque Alicia Mrs © 745-4566
581 Grant Gilles © 749-4595
582 Lefebvre Napoleon © 745-0189
591 Lanthier Gerard J P 749-4912
592 Lafleur Armand 745-3495
ALESTHER INTERSECTS

3 Davis Geo V 746-1640
973 Dino's Pizzeria Take Out restr 745-5692
976 2 Easton Edw G 746-7360
3 Couture Claude 746-2435
977 Vacant
980 1 Mayers Birchmore 746-5431
2 Littleford Joseph N 745-4841
3 Bottcher Otto 745-2607
DONALD ENDS
997 Woas Gerry Shell Serv
999 No Return
1006 Courchaine Jean A radio & tv serv 749-5330
1007 John's Sunoco Serv Sta 745-9668
1008 Courchaine Guy A 745-4963
1012 Butler James 749-4846
1014 Laughren John 746-6101
1018 Snell Ethel 749-9041
1020 Charron Godfrey E 749-4411
1021 Joanisse IGA gro 745-9865
1024 Zaroski Michl
1025 Bank of Nova Scotia The
1026 Denis Oscar G 749-8135
1029 Piano & Organ Studio Ltd 746-0030
1030 Curry Patk K J 749-9966
1032 Campbell Richd E
1033 Allied Radio Shack Ltd 746-5029
1034 Gagnon Richd O 749-2732
1035 No Return
1036 Vezina Oscar J 746-0666
1037 Boutique de la Coiffure beauty salon 746-3282
1040 Couvrette Rheal T 746-6669
1042 MacKarney John 749-8663
1045 Cleanorama dry clnrs & lndry
1046 Labelle John W 749-2303
1048 Chagnon Rorer 749-0681
1052 Pigeon-Roy Ltd ins 746-4383
1054 De Sousa Manuel Upholstering 746-6934
1055 K-Mart (Div S S Kresge Co Ltd) 746-4676

1056 American Air Filter of Can Ltd 746-4788
Cercle D'Economie de la Future Menagere
Ltd kitchen specialties 745-1402
1060 Moon Palace Take-Out Food 745-1791
1070 A & W Drive In of Canada Ltd restr 749-2762
1076 Mac's Milk Ltd 745-6365
1091 Scott Serv Sta 746-6092
QUEEN MARY ENDS
1099 Parisien Ken Piano Studios Ltd sls & serv 745-7071
CYRVILLE RD BEGINS
1110 Firestone Tire & Rubber Co of Canada Ltd
745-7147
1116 St Laurent Separate School 745-4344
COVENTRY RD ENDS
1124-1310 St Laurent Shopping Centre 745-6859
Fairweather Co Ltd women's, children's &
men's wear 745-9861
Freiman A J Ltd dept store 232-6464
Antoine Beauty Salons A J Freiman Ltd 745-6851
Heritage Restr 745-0355
Pennington's Large Size Shop ladies wear 745-9453
Ottawa Leather Goods Ltd 749-1668
International Musicland Ltd 746-3913
Bata Shoe Store 746-8670
Toy World Ltd 745-9809
Evans & Kert Ltd artist's materials 745-7089
Hill Irene Ltd women's specialties 745-1309
Fines Flowers Ltd Florist 745-9491
St Laurent Shoe Renew shoe reprs 745-1417
St Laurent Barber Shop 749-2544
Guaranty Trust Co of Canada 745-1588
Wool Fair 749-1760
Art Centre The 745-0613
Canadian Imperial Bank of Commerce 745-2193
Dominion Stores Ltd 745-7313
Lighting Unlimited Co Ltd lighting equip 746-5009
Jordan Wines Ltd 745-6515
Boutique D'Elegance 745-5912
Studio B leather goods 746-8678
Ottawa Stereo-Hi-Fi-Centre 745-0653
Liturgica Ltd religious goods 745-1537
Mandarin Crafts east asian crafts 749-4106
Boutique Nocturne lingerie 746-8262
Maheu O & Sons Ltd carpets & draperies 745-0414
Bittner's Meat & Delicatessen 745-9584
Emil of Switzerland Ltd 746-6711
St Laurent Salon hairdressing 746-6711
Fenton's Bakery 746-6423
Laura Secord
Nelms Geo H Ltd optician 746-6418
Black's Cameras Ltd 745-9710
Fisher E R Ltd men & boys' wear 749-5353
Smith W H & Son Ltd books 745-9817
Dalmys Ladies Ready To-Wear Ltd 745-9624
Peoples Credit Jewellers Ltd 745-9804
Riopelle Fabric Centre Ltd 746-8432
Kinney Shoes of Canada 745-9758
Simpson-Sears Ltd 746-4311
Allstate Insurance Co of Canada 746-6361
Feller Joe Ltd men's clo 236-7111
McIntosh & Watts Ltd china ware 745-9189
Pierre L'Artisan Inc gifts 749-4611
Streeter & Quarles Ltd sporting goods 745-2104
Van Leeuwen Boomkamp Ltd furn & gifts 745-2283
Odean St Laurent Theatres 745-0341
Shoppers Drug Mart Ltd 745-7015
Cosmopolitan Travel 745-0381
Kiddie Kobbler Ltd children's shoes 746-6411
Golden Dolphin Bath Boutique bath rm accessories
745-9688
Au Coin Des Petits Inc children's wear 749-2426
Reitman's Inc ladies wear 746-8344
Armstrong & Richardson Ltd shoes 749-3729
May Co Ltd women's apparel 749-2307
Birks Henry & Sons Ltd jwlrs 745-7186
Fifth Av Stores Ltd women's apparel 749-2434
Montreal Draperies Inc draperies 745-9111
Co-Operators Insurance Assn of Guelph 236-0781
Parker Clean clns & dyers 749-2254
Sub Post Office #80
Computel Systems Ltd 746-4353
Stauffer System Reducing Salon Ltd 746-7331
1127 Joseph's Tailoring 745-1076
OGILVIE BEGINS
1133 Nielsen Joseph P ◎ 749-5425
1137 Kendall Osmond K ◎ 746-0960
1163 St Laurent Texaco Serv 749-4908

1971 STATELY PRIVATE

SOURCE: MIGHTS

STREET NOT LISTED

1971 WOLFFDALE CRESCENT-A

SOURCE: MIGHTS

WOLFFDALE CRES
WEST, NORTH THEN EAST FROM ALESTHER BACK TO SAME, FIRST SOUTH OF DONALD

ALESTHER INTERSECTS
446 Douville Paul ◎746-0119
447 Muldoon Michl J ◎745-5910
450 Berrube Emile ◎746-1304
451 Gleason R Mrs ◎746-8936
454 Barry Kenneth J ◎746-4823
455 Dubue Jean P ◎749-5660
458 Courville Serge ◎749-0267
459 Dumont Theophile ◎746-1189
462 Desjardins Yvon ◎749-8336
463 Pigeon Claude ◎745-7246
466 No Return
467 Leblanc J Ronald ◎745-1611
470 Lafleur Geo E ◎749-0258
471 Delorme Wilfred J ◎746-0764
475 Laprade Donald J 745-2281
478 Page Beatrice Mrs ◎745-5625
479 Pare Jean-Guy ◎749-2122

OKEE INTERSECTS
482 Labossiere Richd ◎745-2305
483 Lamirande Robt A ◎749-9098
486 Allan Robt M ◎749-1419
487 Bolger Clarence ◎745-3145
490 Sabourin Ernest ◎749-8169
491 Paquette Fernand 749-0346
494 Scott Omer E ◎745-1678
495 Algozino Saml ◎749-0716
498 Horton Donald E ◎
502 Kaluski Peter ◎746-1353

1971 WOLFFDALE CRESCENT-B

SOURCE: MIGHTS

WOLFFDALE CRES-Contd

503 Archambault Marcel ◎746-8371
506 Mahoney Wm L ◎746-1839
508 Laschawski Victor ◎749-4612
510 Potter David Rev 749-4637
511 Salter Fredk T ◎749-3037
512 McEwen Melville W ◎749-4765
516 Garrow Wm E ◎746-4525
520 Kuffner Donald F ◎749-8839
524 Leduc Lucien ◎749-2036
529 No Return
530 Vacant
534 Surette Roy ◎746-2970
535 Clauson Fred M ◎746-1157
538 Seguin Yvan 749-2739
539 Gauthier Francois H ◎746-6687
542 Day Bernard L ◎749-4265
543 Tierney Ivan M ◎746-0455
546 St Denis Gertrude Mrs ◎749-7243
547 Rochon Jean M ◎746-0150
550 Sigouin Douglas ◎745-0871
551 Hunter Robt ◎746-0781
555 Tremblay Gerard ◎745-7551
556 Lavergne Fernande Mrs 749-0347
559 Hotte J Aurele ◎749-2628
560 Lauzon Donat J ◎745-3022
563 Lavigne Armand J 746-0264
566 Barbeau Victor W ◎
567 Kroon Cornelis W ◎745-0882
570 Milner Robt I ◎746-1138
571 Proulx Oliver ◎746-1138
574 Larocque Blumer ◎749-1206
575 Moncion Henri ◎746-4996
578 Bergevin Geo E ◎746-2494
579 Horler Robt C ◎746-1376
582 Hurd James E ◎749-4624
583 Nass Wm L ◎746-8013
586 Crew Alf ◎749-3398
587 Armstrong Bernard P ◎745-4643
590 Reid Todd R C ◎749-5536
591 Landry Lucille Mrs ◎746-0276
596 Roy Orest Z ◎745-4975
597 Baldrate Fredk ◎749-2262
602 Bertrand Armand N ◎749-9086

1966 ALESTHER STREET-A

SOURCE: MIGHTS

576♦ROBIN G RAYMOND (BEGLEY)
610♦LAROCQUE DOMINIQUE L (VIOLET)
690 OLIVE WILLIAM J (MARY)
692 BROWN LYLE (GLADYS)
694 BECKER WILLARD G (FLORENCE)
696 CRAIG JAMES C (MURIEL)
698 EDGERTON LLOYD M H (DOREEN)
700 BOURNE DONALD (ELLEN)
702 LAUZON RUDY J A (MARION)
<> QUEEN MARY CROSSES

1966 ALESTHER STREET-B

SOURCE: MIGHTS

611*SPEARMAN GERALD E (MARION)	746-1882
615*TURPIN EUCLIDE (ROMEA)	749-4825
619*GOULET ROBERT A (LOIS)	746-4174
<> DONALD CROSSES	
647 CARDINAL GILBERT (ANNETTE)	749-1096
651*PILON RHEAL J (RITA)	749-3517
655*HORNE ROBT J (MARGT)	749-2527
659*PASKEVICIUS ALBINAS (ALE)	746-6956
663*BOYER GUY G (JOAN)	745-7933
667*MCGEE PATK (DORIS)	745-4933
671*MARQUIS DAVID (ESTELLE)	749-1275
675*PHARAND JEAN P (MABEL)	745-3697
679*WILLIAMS REGINALD J (MARGT)	749-3047
683*DUGAS MAURICE (LUCIENNE)	749-0408
687*BOILEAU YVON J (LILLIAN)	749-7272
693 ANDERSEN OLE (EVA)	749-8753
697 ROUSSEAU GERALD B (JEANNINE)	749-0342
699 PLOUFFE VITAL R (CECILE)	749-5778
703 FAUTEUX ROGER V (JOYCE)	749-5789
705 BURKE CLIFFORD J (ELVIRA)	749-1896
707 SHARPE FRED C (LILIAN)	749-2132
709 PAPAI JULIUS (MARY)	749-9286
713 GROVES JAMES J (RITA)	745-3993
715 SHIRES WALTER F (GEORGINA)	745-3732
<> QUEEN MARY CROSSES	
727 DUBUE ARMAND J (PAULINE)	749-2594
729 PROUD EVERETT C (THERESA)	746-4580
733 MORRIS HUGH P (THERESA)	745-6124
735 O'GRADY KENNETH J (CLAUDETTE)	749-1874
737 CHENETTE LESLIE J (ALICE)	749-0358
739 MELLOR ROBERT E (EDNA F)	745-5707
743 WHITE ARTHUR E (RITA)	746-1248
745 HANNA WM R (GRACE)	746-4596

1966 BERNARD STREET

SOURCE: MIGHTS

725 QUEEN MARY COURT APARTMENTS

1	TATTERSALL GRACE MRS	749-9880
2	SCHARF SARAH M MRS	745-5901
3	MASSIE MARIE L	745-9749
4	COREY EDITH M MRS	749-3322
5	DUCHARME MARGARET A MRS	746-6207
6	AUMOND MARTHA MRS	745-4644
7	TYSON JEAN MRS	745-1527
8	STINSON EVA L MRS	745-5241
9	GERVAIS IRENE R MRS	745-2532
10	CLARKE VIOLET MRS	746-6637
11	LEBLANC BEATRICE MRS	745-6154
12	COMRIE MABEL O MRS	745-3686
13	CAMERON CHRISTINA	746-8542
14	BALKWILL ROBENA MRS	
15	ARNOLD CHARLOTTE MRS	745-3452
16	HOWSE GLADYS I MRS	745-4357
17	KIMBER EZILLAH H MRS	745-4290
18	WILLEMS MATHILDE C MRS	746-0740
19	GRAHAM T KIRBY	749-0340
20	AYERS MARJORIE MRS	745-3422
21	BALLANTYNE BARBARA MRS	745-3525
22	EMERSON ANNIE MRS	749-2797
23	STUART WM	749-3272
24	SMITH MARY MRS	
25	MCCARTHY DANL L	749-3554
26	WILLIAMS ELSIE M MRS	745-3535
27	FROMENT AGNES MRS	
28	BROWN MINNIE MRS	745-4536
29	RIDEOUT SARAH	
30	LARKIN LENA F MRS	
31	GROULX BERTHA	745-5655
32	REID G J	745-7278
33	DONOVAN ANNE A MRS	746-4978
34	MOYNEUR BLANCHE N MRS	745-4090
35	HARRISON BERTHA MRS	745-5661
36	BERTRAND ANNE MRS	746-6190
37	BENNETT EDYTHE C	749-3538
38	HARRIS CATHERINE S	
39	SMITH WM A	749-4057
40	HALL OLIVE MRS	745-6983
41	ANDREWS EDITH A MRS	
42	GIROUARD EDITH MRS	745-3354
43	THATCHER ELIZTH MRS	749-7674
44	WILKINSON MARGT P MRS	745-6450
45	BENDER MINNIE W G MRS	745-2945
46	REGEHR MARIA I MRS	749-4107
47	DINELLE MARIE R MRS	745-4738
48	CLAPP ROSE MRS	745-3401
49	MACKENZIE GRACE S	745-2921
50	KENNEDY ESTELLE	749-9972
51	HAMMOND MAUD L MRS	749-4672
52	DOW MARY A MRS	749-8375
53	GLAVIN HAZEL MRS	745-3612
54	BAXTER JOSEPHINE MRS	749-9866
55	GIBSON AMELIA F MRS	746-0195
56	PARK ISABELLA MRS	745-3933
57	MCCOMB MARY MRS	749-0659
58	HILL GEORGINA MRS	749-4711
59	GRAHAM BEATRICE MRS	746-8941
60	LOGAN GEO A	746-4713
61	STEVENSON JAMES M	745-1314
62	YOUNG ANN MRS	749-6362
63	BORTHWICK A BERTHA MRS	749-2163
64	TUDOR ELSIE MRS	749-8203
65	BOMFORD MAUD M MRS	
66	BURKE JANE MRS	749-7920
67	MCNAUGHTON ANNIE C MRS	746-1818
68	BURROWS LILY MRS	745-7276
69	BANKS BEATRICE MRS	745-6038
70	CHURCH ELIZTH MRS	745-4790
71	SAUVE EDELMA MRS	749-1030
72	CLAYTON ANNE MRS	745-3595
73	QUINLIVAN MARY MRS	
74	THOMSON ELIZTH MRS	745-4173
75	GRIEVES ELIZTH C	745-3330
76	WATSON JEAN B MRS	749-4555
77	HAMILTON MARGARET MRS	745-7420
78	HEMPHILL HELEN MRS	749-1228
79	LAUZON WINNIFRED MRS	745-6980
80	NICOLAIFF BERTHA D MRS	745-6227
81	DOLIGHAN AGNES B	745-3693
82	PATERSON BARBARA MRS	746-8255
83	CUDDIE SUSAN MRS	745-6758
84	WITHER NANCY MRS	
85	WILKINSON CELESTE M MRS	745-4470
86	PILLER ELIZTH MRS	
87	RANGER MARIE R MRS	745-5689
88	BOUCHER MAYME MRS	745-7209
89	CRAIG EVA MRS	745-4652
90	LAFONTAINE GERMAINE MRS	749-0889
91	JOHNSON THERESA MRS	749-3988
92	RALPH EUNICE E MRS	746-6993
93	FALLIS ROSE M MRS	746-0690
94	YOUNG LYDIA E MRS	746-8071
95	JOHNSON BESSIE MRS	746-0734
96	DONALDSON IRENE MRS	749-9879
97	REDFORD MARGARET	
98	MILLER MARY MRS	745-6074
99	JACK GEORGINA E MRS	745-6074
100	WHITE MARGT MRS	749-4657
101	SIMPSON MARY	746-0426
102	BROWN MABEL MRS	745-4261
103	BELANGER JEANNINE	745-5249
104	CHARBONNEAU MARY	745-3892
105	LECKIE JANET MRS	746-8246
106	RYAN NORA E MRS	745-6441
107	LAFORTUNE ARMANDINE MRS	749-9518
108	HUSON ELIZTH C B MRS	745-2855
109	CUTHBERT LILIAN B MRS	745-4512
110	THATCHER ALICE E MRS	745-6453

<> PRINCE ALBERT CROSSES

1966 CYRVILLE ROAD

SOURCE: MIGHTS

STREET NOT LISTED

1966 DONALD STREET

SOURCE: MIGHTS

<> OKEE ENDS
568*LOWE ERIC L (SARAH A) 746-1066
572*NOFFKE CARL A (NORMA) 746-8093
576*WATTERS KEITH J (RITA) 749-5542
580*NEVILLE RUFUS V (ETHEL) 749-1196
584*GEITZLER ERIC F (WINNIFRED) 749-0841
588*GRAINGER GARNET E (JOAN) 749-2984
<> ALESTHER CROSSES
598*BURTON E ALLEN (REINA) 746-6054
602 PARENT BENOIT (PIERRETTE) 749-8734
606 STOKES KENNETH A (JOYCE) 745-6410
610 DARWEN J G (LOLA) 745-1713
614 -

<<<<<<<<<<<<<<< >>>>>>>>>>>>>>>

	4	DALY THOMAS E (JANE)	746-0974
518	1	DEREPENTIGNY REGINA MRS	749-2510
	2	PROULX ALBERT (MARIE D)	745-1484
	3	CAMERON HAROLD (ELIZTH)	745-3565
	4	JAMES THOS A (MURIEL E)	745-4976
<>	BERNARD CROSSES		
540	1	TAYLOR WM H (FAIREDDA)	745-1268
	2	SCHLIEVERT IDA MRS	746-6625
	3	CARRIER JOSEPH W (MARY)	745-3728
	4	BELANGER EMILE (ALIDA)	745-3225
548	1	LEPINE ALPHONSE (ALMA)	749-8101
	2	CAMPBELL LAURA E MRS	746-6757

	3	PROULX LIONEL (ALEXANDRINE)	
	4	CAIRNS WM J (MARY A)	
554	1	MCCORMACK JOSEPH A (DAISY)	746-1725
	2	HISELER CLARENCE A (A PEARL)	745-4672
	3	WARNER PERCY G (EDITH)	746-4963
	4	DICKINSON GEORGE H (LILLIAN)	745-1783
562	1	MYERS ARTHUR H (GERTRUDE)	745-2460
	2	DE RINZY M MRS	745-1872
	3	PARRINGTON JAS (ELIZTH)	745-2358
	4	DORMER HENRY J (EMILY)	745-5224
568	1	HEINE FRANK B (RUTH)	749-2490
	2	BUCHANAN JAS G	745-3973
	3	COGHLAN WM J (ELSIE)	746-6341
	4	ROBITAILLE LEO (ROSE)	745-3267
574	1	DEFALQUE LEON E (VALEDA)	745-1649
	2	HORTON WINNIFRED V	749-6201
	2	WARREN EVELINE MRS	
	3	POTTER JAMES R (FANNY)	749-1769
	4	JOBSON ROBT J (LOUISA)	746-8903
580	1	MARTEL JEAN B (BEATRICE)	746-4273
	2	COUSINEAU EUGENE B (PARISE)	745-3066
	3	BUCK GEO F (MAY)	749-7206
	4	MURRAY ALEX L (MYRIAM)	
586	1	MOORE WILFRED (VIOLET)	745-5589
	2	GREY RUFUS W (MARY)	745-5444
	3	THOMPSON MARGT MRS	745-4707
	4	DESORMEAUX ALDEGE (M REINE)	746-6537
592	1	VACANT	
	2	TAGGART JAMES (CHRISTINE)	745-2963
	3	LEONARD THOS E (FLORENCE)	749-8725
	4	GRANT FINLAY (CATHERINE)	745-3583
598	1	PAQUETTE AMBROSE (DORA)	749-8590
	2	HAMILTON MARGT MRS	
	3	MAYOTTE ALBT D (DONALDA)	749-3562
	4	BURTON JOHN S (MABEL)	749-8028

1966 PRINCE ALBERT STREET-C

SOURCE: MIGHTS

	4 POLLOCK JAMES N (LOIS)	746-4842
511	FERGUSON KEITH G (LAVERNA)	746-0454
515	REID DOUGLAS K (GRACE)	746-4537
519	ORR HAROLD W (MARY)	749-1011
523	WEGELIN GASPARD F (MARIE)	745-3266
527	ARMSTRONG EDWARD G (STELLA J)	749-7552
<>	BERNARD CROSSES	
553	MATTON ORLAND R (CLAIRE)	746-8389
555	WILKINSON LORNE J (LEONA)	745-7214
559	SHELAGA PETER (MAVIS)	745-5803
561	LAIRD EDWARD (BERTHA)	745-5622
567	FISH SYDNEY (ESME)	
569	BRULE GERARD E (ELLEN)	746-1498
573	JULIEN LIONEL C (JEAN)	745-4897
575	LAMOUREUX HORACE X (AUDREY)	
579	LABELLE RAYMOND D (EVELYN)	749-5895
581	DALE HAZEL MRS	
587	LAVIGUEUR ROGER J (THERESA)	746-4083
589	EASEY ANDREW R (ALICE)	746-1127
597	MASON ROBERT T (MERLE)	
599	STAPLES JOHN L (JEAN)	749-4282

PRINCE CHARLES RD- 13 NORTH-WEST FROM

1966 QUEEN MARY STREET-A

SOURCE: MIGHTS

524	LABELLE J T MARCEL (GEORGETTE)	746-8575
528	JOINER EDWD W (JOAN)	745-1961
<>	BERNARD COMMENCES	
556	BELLEFEUILLE ROGER A (CARMEN)	749-0196
560*	DILORETTO DOMINIQUE (LUCIENNE)	745-3242
568	GRENON ROGER (GRACE)	745-5604
570	PATAFIE ANTHONY (THERESA)	749-3433
578	TURPIN GILBERT	745-6602
580	MITCHELL KENNETH W (BARBARA)	
582*	HAGERMAN ELWOOD D (JANET)	746-4280
592	LAFLEUR ARMAND (M THERESE)	745-5377
<>	ALESTHER CROSSES	

<<<<<<<<<<<<<<<< >>>>>>>>>>>>>>>

1966 QUEEN MARY STREET-B

SOURCE: MIGHTS

465	MITCHELL JACK L (JEANNETTE)	749-5625
557	QUEEN MARY ST SCHOOL	749-1692
579	*GAUVIN PAUL (ELIZTH)	746-0495
581	*GRANT GILLES (SUZANNE)	749-4595
	QUIROUETTE MARCEL	
591	DELAMUNT GERALD (VELMA)	749-4854
<>	ALESTHER CROSSES	
625	*BRAULT LUCIENNE MRS	746-8453

1966 SAINT LAURENT BOULEVARD-A

SOURCE: MIGHTS

	(RITA)	
980	1 PROULX FRANCOIS	746-0522
	(JULIETTE)	
	2 LAFRANCE LEON (YVONNE)	749-2961
	3 THOMAS JOHN H	745-3036
	(FRANCES)	
<>	DONALD ENDS	
1006	COURCHAINE JEAN A (ALINE)	749-5330
	RADIO AND TV SERVICE	
1008	COURCHAINE GUY A (BERTHE)	745-4963
1012	NICKERSON CALEB (EVELYN)	749-1265
1014	LAUGHREN JOHN (JUNE)	746-6101
1018	MILLIONS NORMAN (DOROTHY)	746-8324
1020	CHARRON GODFREY E	749-4411
	(LAURETTE)	
1024	DAVIES L CHRISTOPHER (LOLA)	749-6694
1026	ETHIER JACQUES (IRENE)	745-9348
1030	FROBEL LORRAINE	745-2078
1032	VACHON ROBT (DENISE)	745-6255
1034	DOW RALPH A (FRANCES)	746-1992
1036	VEZINA OSCAR (ALINE)	746-0666
1040	COUVRETTE RHEAL T	746-6669
	(BEATRICE)	
1042	LEDUC ANTHONY (JOSEPHA)	749-8689
1046	GRAY JAMES B (FRANCES)	746-1333
1048	CHAGNON ROGER (ANITA)	749-0681
1056	SHIPMAN THOS REAL ESTATE	745-7041
1060	MOON PALACE TAKE-OUT FOOD	745-1791
	*ANG DONALD (GEM)	745-7041
1064	D & R DRIVE-IN TAKE OUT	745-3329
	FOOD	
1076	DESOUSA UPHOLSTERING	746-6934
1090	BURTON SIGNS	745-5019
<>	QUEEN MARY ENDS	
1100	GIROUX CLEMENT (HENRIETTE)	749-6089
1102	GIROUX GUY J A (CLAIRE)	749-8740
1116	ST LAURENT SEPARATE SCHOOL	745-4344
1126	FOUNDATION CO OF CANADA LTD	746-4017
	BLDG CONTRS	
<>	COVENTRY RD ENDS	
1194	VACANT	
1196	VACANT	

1966 SAINT LAURENT BOULEVARD-B

SOURCE: MIGHTS

	4 WARREN STEVE	
973	GOLDEN CITY RESTAURANT	749-0386
977	IRELAND DOUGLAS	
	IRELAND GEO	
991	*GOULET HENRY N (IRENE)	746-0173
997	SCOTT OMER E SERV STN	746-6092
1025	*NASS WM (LEONA)	746-8013
1025	A ABBOTT ROY W (IRIS)	745-3547
1035	JOHN'S SUNOCO SERVICE STATION	749-1663
1043	1 BOLDUC GUY D (CARMEN)	749-8847
	2 CONNORS REGD P (MADELEINE)	
	CAPITAL MASONRY LTD	749-5457
1053	UNION TILE & MARBLE LTD	745-1505
1061	THOMSON'S AL FINA STATION SERVICE STATION	749-1675
1067	JAUVIN BROS, TRUCK BODIES AND EQUIP MFRS	745-9446
1091	ROLLY SERVICE STATION	746-0875
1099	PARISIEN KEN PIANO STUDIOS LTD SLS & SERV	745-7071
<>	CYRVILLE RD COMMENCES	
1127	GAUTHIER LUCIEN J M (FLORETTE G)	749-6139
1133	*NIELSEN JOHN P (ELIZTH)	749-5425
1137	*KENDALL OSMOND K (OLIVE)	746-0960
<>	OGILVIE COMMENCES	
1145	*MAISONNEUVE RODGER (ALINE)	746-6946
	PRINCESS DAIRY BAR	
1163	-	

1966 STATELY PRIVATE

SOURCE: MIGHTS

STREET NOT LISTED

1966 WOLFFDALE CRESCENT

SOURCE: MIGHTS

WOLFFDALE AV- 7 EAST FROM HOLLY TO ALESTHER, SECOND SOUTH OF DONALD.

<<<<<<<<<<<<<<<< >>>>>>>>>>>>>>>

534*HEISLER ELORED (DOROTHY) 749-4501
538*SPURR PHILIP R (PAMELA) 746-6217
542*DAY BERNARD L (PEARL) 749-4265
546*ST DENIS GERTRUDE MRS 749-7243
550 DUHAMEL ROGER G (JOSEPHINE) 746-0923
556*LAVERGNE ROGER J (FERNANDE) 749-0347
560*LAUZON DONAT J (FERNANDE) 745-3022
566*WEST JAMES T (STELLA) 746-1174
570*MILNER ROBT I (VERONA) 746-1138
574*LAROCQUE BLUMER (FRANCES) 749-1206
578*KANIK JOSEPH (ANGELA) 746-4481
582*LABELLE HENRY C (BEATRICE) 746-6972
586*CREW ALFRED (EUREVA) 749-3398
590*REID TODD R (IVY) 749-5536
596*ROY OREST Z (ANN) 745-4975
602*BERTRAND ARMAND N (IRENE) 749-9086

<<<<<<<<<<<<<<<< >>>>>>>>>>>>>>>

535*CLAUSON FRED H (OLGA) 746-1157
539*GAUTHIER FRANCOIS H 746-6687
543*TIERNEY IVAN M (ANNETTE) 746-0455
547*ROCHON JEAN M (EDNA) 746-0150
551*HUNTER ROBT (BLANCHE) 746-0781
555 -
559*HOTTE J AURELE (RITA) 749-2628
563*LAVIGNE ARMAND J (JEANNETTE) 746-0264
567*HOWLETT JOHN (MURIEL) 746-6035
571*PROULX OLIVER 746-1484
575*MONCION HENRI (JEANNINE) 746-4996
579*HORLER ROBT C (PATRICIA) 746-1376
583 -
587*ARMSTRONG BERNARD P (LUCILLE) 745-4643
591*LANDRY LUCILLE MRS 746-0276
597*BALDRATE FREDERICK (ANNETTE) 749-2262

1960 ALESTHER STREET

SOURCE: MIGHTS

619*Goulet Robert A (Lois) SH 6-4174
647 Loshny Vladamere (Irene) SH 9-2242
651*Pilon Rheal (Rita) SH 9-3517
655*Horne Robt J (Margt) SH 9-2527
659*Paskevicius Albinas (Ale) SH 6-6956
663*Matthews John R (Eva) SH 9-3350
667 Goldsmith Chas W (Ruth) SH 6-1328
671 Dube Gaston R (Patricia) SH 9-0281
675*McQuarrie John L (Mary E) SH 9-2939
679*Williams Reginald J (Margt) SH 9-3047
683*Parent Paul D (Alice) SH 9-2938
687*Jutras J Rene (Claire) SH 9-2503

SOUTH SIDE

1960 BERNARD STREET

SOURCE: MIGHTS

NO LISTING FOUND

1960 CYRVILLE ROAD

SOURCE: MIGHTS

STREET NOT LISTED

1960 DONALD STREET

SOURCE: MIGHTS

9-0735
567*Tamasi Joseph N (Dorothy) SH 9-0208
571*Walsh Ivan (Estelle) SH 9-9775
575*St George Sylva (Margaret) SH 6-6969
579*Lepage Paul (Jeanne) SH 5-1236
583*Desjardins Edwd (Eva) SH 9-4421
◆ Alesther crosses
599 Cooke James W (Muriel) SH 9-2210
603*Patenaude Roland (Ellen) SH 6-4184

SOUTH SIDE .....

1960 PRINCE ALBERT STREET

SOURCE: MIGHTS

4 Pallster John W SH 9-1111
518 1 Wright Philemon G (Isabel) SH 6-0374
2 —
3 Simpson Margt Mrs SH 6-8255
4 DeReprentigny Regina SH 9-7910
◆ Bernard crosses
540 1 McComb Wm (Mary) SH 9-0659
2 Greenslade Frank (Rose) SH 9-4912
3 Hewitt Jacob A (Etta) SH 9-0995
4 Quinn Hugh A (Anna) SH 5-3048
548 1 Rayner Percy A (Hilda) SH 9-1659
2 Park John J (Isabella) SH 5-3933
3 Darby Alfred (Susan) SH 5-1155
4 Cairns Wm J (Mary A)
554 1 Laurin Dalma (Kathleen) SH 5-1642
2 Brookes Geo W (Florence)
3 Chapman Robt N (Lillian) SH 5-3106
4 McNeil Emmett (Aurelia) SH 9-9035
562 1 Williams James E (Marjorie) SH 9-3916
2 de Rinzy M Mrs
3 Parrington Jas (Elizth) SH 5-2358
4 Dormer Henry J (Emily) SH 5-1810
568 1 Tang Chas (Ida) SH 9-8159
2 Buchanan Jas G (Mary B) SH 5-3973
3 Coghlan Wm (Elsie) SH 6-6341
4 Robitaille Leo (Rose) SH 5-3267
574 1 Defalque Leon E (Valeda) SH 5-1649
2 Wynne Fred C (Mae) SH 9-5626
3 Potter James R (Fanny) SH 9-1769
4 Jobson Robert J (Louise) SH 6-8903
580 1 Gunville Valeda SH 9-8348
2 McDonald Margaret Mrs SH 6-1123
3 Buck Geo F (Violet) SH 9-7206
4 Chenevert Hector (Bella) SH 9-0863
586 1 Cougle Harry C (Mae) SH 9-9810
2 Mulvey Michael (Celesta) SH 5-1908
3 Dobie Percy P (Ava) SH 6-1791
4 Pearson Danial A (Mary) SH 9-7316
592 1 Martin Fredk J (Anna)
2 Tapp Jos G (Annie) SH 6-4111
3 Leonard Thos E (Florence) SH 9-5827
4 Grant Finlay (Catherine) SH 5-3583
598 1 Doherty Clifford E (Kathleen) SH 5-1990
2 Hamilton Harold R (Marguerite) SH 6-1518
3 Cairncross Jas (Florence) SH 5-1887
4 Burton John S (Mabel) SH 9-8028

459 Derowin James C (Marjorie) SH 9-1607
463 McKay Kenneth D (Lydia) SH 6-0996
465 Mitchell Jack L (Jeannette) SH 9-5625
557 Queen Mary St School SH 9-1692
579*Gauvin Paul (Elizth) SH 6-0495
581*Mallette John (Yvonne) SH 6-0866

SOUTH SIDE .....

6-8975
528 Boileau Emile (Adrienne) SH 9-8612
♠ Bernard commences
560*Mallette Geo (Doris) SH 9-1228
578 Amyot Morris (Pauline) SH 9-9565
580*Mallette Jos C (Emma) SH 6-0673
582 Hagerman Elwood D (Jean) SH 6-4280
592*de'Leseseleuc Guy (Yvette) SH 9-3956

Report ID: 24053100257 - 06/14/2024
www.erisinfo.com

4 Schuler Paul (Monica)
973 Nanking Restaurant SH 9-0905
977*Fong John SH 9-0905
991*Goulet Henry N (Irene)
Castle Height Confectionery
997 Shell Service Station SH 6-6092
1025*Nass Wm (Leona) SH 6-8013
Abbott Roy W (Iris)
1035 Giguere Service Station SH 5-2303
1043*Dokken Einar (Hilda) SH 6-8850
1053 Union Tile & Marble Ltd SH 5-1505-6
1061 Lavigne Service Station
1091 Michaels Service Station SH 9-4761

◆ Cyrville rd commences

1127*Landry Arthur (Lucielle) SH 6-0276
1133*Neilsen John P (Elizth) SH 9-5676
1137*Kendall Osmond K (Olive) SH 6-0960

◆ Ogilvie commences

1145*Maisonneuve Rodger (Aline) SH 6-6946
1177*Cote Paul J (Carmen) SH 6-6662
Jubinville Edgar (Solange)

3 Cotsey Jos P (Mildred) SH 9-9459
968 Evangel Chael
Harrison Margaret SH 9-6027

◆ Donald ends

1006 Herbert Barry V (Noela) SH 9-7004
1008 Cregan Leonard (Evelyn) SH 6-4089
1012 Sheppard Robt (Margt) SH 9-4203
1014 Levesque Jacques B (Denise) SH 6-0623
1018 Scrim Horace (Catherine) SH 9-4934
1020 Murray K Ross Elizth) SH 5-1743
1024 Crew Alfred E (Eureva) SH 9-3398
1026 Baker E Barry (Greta) SH 9-7177
1030 Berry Kenneth E (Kathleen M) SH 5-4239
1032 Pedneault Yvon J P (Hazel) SH 9-9532
1034 Johnston Wm (Ethel) SH 9-2809
1036 Coe Earle W (Marjorie) SH 5-4300
1040 Proctor Leslie (Catherine) SH 6-6280
1042 Vacant
1046 Smale Wm R (Edna) SH 9-2855
1048 Steele Roland H Grace) SH 9-2906
1060*LeRoux Raoul (Aurore) SH 6-8026
1076*Brazeau Aurele (Emeriza) SH 9-1613
1082 Vacant

◆ Queen Mary ends

1090 —
1098*Leury Joseph (Lourda) floor covering SH 6-8673
1100 Brunet Gaston G (Adrianne) SH 9-2773
1102 Vacant
1116 St Laurent Separate School SH 5-4344
1126*Seal Daniel SH 6-1027
1194*Schnobb Peter (Irene) SH 9-1036

Report ID: 24053100257 - 06/14/2024
www.erisinfo.com

1960 STATELY PRIVATE

SOURCE: MIGHTS

STREET NOT LISTED

1960 WOLFFDALE CRESCENT-A

SOURCE: MIGHTS

NORTH SIDE .....

535*Clauson Fred M (Olga) SH 6-1157
539*Dunning R Wm L (Joyce) SH 6-1471
543*Wooster Geo A (Jean) SH 9-7572
547*Rochon Jean M (Edna) SH 6-0150
551*Hunter Robt (Blanche) SH 6-0781
555*Pownall Vernon (Jean) SH 9-3306

1960 WOLFFDALE CRESCENT-B

SOURCE: MIGHTS

559*Polec Bernard P (Joyce) SH 9-9863
563*Jarvis Albert J (Delight) SH 9-2572
567 Brown R Farrell (Charlene) SH 6-8704
571*Proulx Oliver SH 6-1484
575*Moncion Henri (Jeannine) SH 6-4996
579*Phillippe Oscar (Annie) SH 9-2911
583*Levesque Guy (Rita) SH 9-4231
587*Doyle John (Kathleen) SH 9-2339
591*Leblanc Camille (Noella) SH 9-3785
595*Baldrate Fred (Annette) SH 9-2269

SOUTH SIDE .....
534*Wentzell Jessen D (Heather) SH 9-4905
538*Everson Thos (Norma) SH 6-6132
542*Day Bernard L (Pearl) SH 9-4265
546*St Denis Ernest M (Gertude) SH 9-7243
550*Foster Kenneth C (Mary) SH 6-6353
556*Lavergne Roger (Fernande) SH 9-0347
560*Samuels Solomon (Helen) SH 6-4959
566 Gibbs Peter J (Joyce) SH 5-4356
570*Milner Robt I (Verona) SH 6-1138
574*Larocque Bloomer (Frances) SH 9-1206
578*Hochster Rolf (Marcia) SH 6-1310
582*Labelle Henry C (Beatrice) SH 6-6972
586*Parker Orville J (Lolande) SH 6-0486
590*Reid Todd R (Ivy) SH 9-5536
596*Olien Lloyd C (Elizth) SH 6-6942
602*Bertrand Armand (Irene) SH 9-9086

1955 ALESTHER STREET

SOURCE: MIGHTS

RANGE NOT LISTED

Report ID: 24053100257 - 06/14/2024
www.erisinfo.com

1955 BERNARD STREET

SOURCE: MIGHTS

STREET NOT LISTED

1955 CYRVILLE ROAD

SOURCE: MIGHTS

STREET NOT LISTED

[illegible] Carl A (Norma)
576*Hardie James B (Blanche)
580*Neville Rufus (Ethel)
584*Wright Anthony J (Sheila)
588*Grainger Garnet E (Joan)
598*Burton E Allen (Reina)
602*Leblond J E Lou (Regina)
606 —
610*Holmes Albert H (Vivian)
614*Gauthier Riel (Roberta)

537*Bourgault Gerard G (Colombe)
543*Kennedy Dorwin E (Elenora)
547*Noel Roger (Jeannette)
549*Elias Eli (Jeanne)
553*Gadbois Pierre (Charlotte)
559*Smith Donald W (Leona)
603*Patenaude Roland (Ellen)

SOUTH SIDE

1955 PRINCE ALBERT STREET

SOURCE: MIGHTS

RANGE NOT LISTED

1955 QUEEN MARY STREET-A

SOURCE: MIGHTS

453 Schultz Gerald E (Kathleen)
455 Conway Arthur S (Lillian)
459 Franklyne Gerald F (Marjorie)
♦ Frances crosses
553 Mayer Alex (Germaine)
Mallette Leo (Cecile)
Giroux Imelda Mrs
557 Welsh John (Mary)
579 Gauvin Paul (Elizth)
581 Mallette John (Yvonne)

SOUTH SIDE

1955 QUEEN MARY STREET-B

SOURCE: MIGHTS

452 Blyth Ross W (Muriel)
454 Coderre Frank P (Blanche)
458 O'Connell William J D (Yolande)
°Connelly Jerry
560°Mallette Geo (Doris)
578 Simpson Robt T (Joan)
580°Mallette Jos C (Emma)
582°Charbonneau Jean P (Colomb)
592°de'Leseseleuc Guy (Yvette)

[redacted]

1955 SAINT LAURENT BOULEVARD

SOURCE: MIGHTS

RANGE NOT LISTED

1955 STATELY PRIVATE

SOURCE: MIGHTS

STREET NOT LISTED

1955 WOLFFDALE CRESCENT

SOURCE: MIGHTS

RANGE NOT LISTED

1950 ALESTHER STREET

SOURCE: MIGHTS

STREET NOT LISTED

1950 BERNARD STREET

SOURCE: MIGHTS

STREET NOT LISTED

1950 CYRVILLE ROAD

SOURCE: MIGHTS

STREET NOT LISTED

1950 DONALD STREET

SOURCE: MIGHTS

RANGE NOT LISTED

1950 PRINCE ALBERT STREET

SOURCE: MIGHTS

RANGE NOT LISTED

1950 QUEEN MARY STREET

SOURCE: MIGHTS

RANGE NOT LISTED

1950 SAINT LAURENT BOULEVARD

SOURCE: MIGHTS

RANGE NOT LISTED

1950 STATELY PRIVATE

SOURCE: MIGHTS

STREET NOT LISTED

1950 WOLFFDALE CRESCENT

SOURCE: MIGHTS

STREET NOT LISTED

APPENDIX G

TSSA Records

RE: TSSA request - 1052 St. Laurent Blvd Ottawa Ontario

Public Information Services <publicinformationservices@tssa.org>

Tue 6/25/2024 11:18 AM

To:Mohit Bhargav <mohit.bhargav@gemtec.ca>

Hello ,

RECORD FOUND IN CURRENT DATABASE:

- We confirm that there are **fuels records** in our database at the subject address(es).

Inventory Number	Address	City	Province	Postal Code	Reason Code	Asset Class / Inventory Context	Asset Type / Inventory Item
64505593	1021 ST. LAURENT BLVD	OTTAWA	ON	K1K 3B1	Dismantled	Propane	FS CYLINDER EXCHANGE

Inventory Number	Address	City	Province	Postal Code	Reason Code	Asset Class / Inventory Context	Asset Type / Inventory Item
64686986	1021 CYRVILLE RD	OTTAWA	ON	K1J 7S3	Active	Propane	FS CYLINDER EXCHANGE

This is not a confirmation that there are no records in the archives. For a further search in our archives, please go to the **TSSA Client Portal** to complete an Application for Release of Public Information.

Please refer to How to Submit a Public Information Request (tssa.org) for instructions.

The associated fee must be paid via credit card (Visa or MasterCard).

Once all steps have been successfully completed you will receive your payment receipt via email.

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.

If you have any questions or concerns, please do not hesitate to contact our Public Information Release team at publicinformationservices@tssa.org.

Kind regards,

Slavka Zahrebelny | Public Information & Records Agent

Public Information

345 Carlingview Drive

Toronto, Ontario M9W 6N9

Tel: +1 416-734-3585 | Fax: +1 416-734-6242 | E-Mail: szahrebelny@tssa.org

www.tssa.org

Winner of 2024 5-Star Safety Cultures Award

From: Mohit Bhargav <mohit.bhargav@gemtec.ca>
Sent: Tuesday, June 25, 2024 8:37 AM
To: Public Information Services <publicinformationservices@tssa.org>
Subject: TSSA request - 1052 St. Laurent Blvd Ottawa Ontario

[CAUTION]: This email originated outside the organisation.
Please do not click links or open attachments unless you recognise the source of this email and know the content is safe.

Hi,

Can you please do a search in fuels database for the following civic addresses??

- 1012, 1052, 1060, 1064, 1076, 1021, 1091, 1099 St. Laurent Boulevard
- 693 Alesther St
- 1021 Cyrville Rd

In Ottawa, Ontario.

Thank you.

Mohit Bhargav, MScE, EIT
Junior Environmental Scientist
Ottawa, ON
tel: 613.836.1422 / toll-free: 1.877.243.6832
mobile: 506.897.0427 / fax: 613.836.9731

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

CAUTION: This email is not from someone with an @gemtec.ca email address. Do not click links or open attachments that you do not trust.

Outlook

RE: TSSA request (Fuels Database)

From Public Information Services <publicinformationservices@tssa.org>
Date Thu 7/31/2025 10:28 AM
To Mohit Bhargav <mohit.bhargav@gemtec.ca>

NO RECORD FOUND IN CURRENT DATABASE

Hello,

Thank you for your request for confirmation of public information. TSSA has performed a preliminary search of TSSA's current database.

- We confirm that there are no records in our current database of any fuel storage tanks at the subject address(es).

Accessing the applications

1. Click Request a Public Record - TSSA and click "need a copy of a document"
2. Select the appropriate application, download it, complete it in full and save it (Note: you will have to upload the application)
3. Proceed to page 3 of the application and click the "TSSA Service Prepayment Portal" link under payment options (the link will take you the secure site where you can pay for the request via credit card)

Accessing the Service Prepayment Portal

1. Select new or existing customer (*if you are an existing customer, you will need your account number & postal code to access your account)
2. Under "Program Area" select **Public Information** and click continue
3. Enter application form number (found on the bottom left corner of the application form) and click continue
4. Complete the primary contact information section
5. Complete the fee section
6. Upload your completed application
7. Upload supporting documents (if required) and click continue

Once all steps have been successfully completed you will receive your payment receipt via email.

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.
If you have any questions or concerns, please do not hesitate to contact our Public Information Release team at publicinformationservices@tssa.org.

Kind regards,

From: Mohit Bhargav <mohit.bhargav@gemtec.ca>
Sent: Thursday, July 31, 2025 9:06 AM
To: Public Information Services <publicinformationservices@tssa.org>
Subject: TSSA request (Fuels Database)

[CAUTION]: This email originated outside the organisation.
Please do not click links or open attachments unless you recognise the source of this email and know the content is safe.

Hi,

Can you please complete a TSSA search (fuels database) for the following addresses?

- 1054 St-Laurent Blvd
- 1056 St-Laurent Blvd

In Ottawa, Ontario.

Thank you.

Mohit Bhargav, MScE, P.Eng.
Environmental Engineer
Ottawa, ON
506.897.0427 | www.gemtec.ca

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

CAUTION: This email is not from someone with an @gemtec.ca email address. Do not click links or open attachments that you do not trust.

APPENDIX H

FOI Records

Ministry of the Environment, Conservation and Parks

Corporate Services Branch
40 St. Clair Avenue West
Toronto ON M4V 1M2

Ministère de l'Environnement, de la Protection de la nature et des Parcs

Direction des services ministériels
40, avenue St. Clair Ouest
Toronto ON M4V 1M2

Ontario

June 12, 2025

Mr. Mohit Bhargav
GEMTEC Consulting
32 Steacie Drive
Kanata, Ontario K2K 2A9
mohit.bhargav@gemtec.ca

Dear Mohit Bhargav:

RE: **MECP FOI A-2025-03848, Your Reference 103499.002 – Decision Letter**

This letter is in response to your request made pursuant to the Freedom of Information and Protection of Privacy Act (the Act) relating to:

1052, 1060, 1064 St. Laurent Boulevard Ottawa

Timeframe: Jan 1, 1985 to June 9, 2025

After a thorough search through the ministry files, no records were located responsive to your request. The official responsible for making the access decision on your request is the undersigned. This file is now closed.

You may request a review of my decision within 30 days from the date of this letter by contacting the Information and Privacy Commissioner/Ontario at http://www.ipc.on.ca. Please note there may be a fee associated with submitting the appeal.

If you have any questions, please contact Shannon Neita at shannon.neita@ontario.ca.

Yours truly,

Shannon Neita

for
Josephine DeSouza
Manager, Access and Privacy Office

APPENDIX I

Historic Land Use Inventory

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	SOURCE_UPDATE_SORTED	QAQC	YEAR	YEAR_1	ST_NUM	ST_NAME	ST_SUFFIX	ST_DIR	MUNICIPALITY	ST_NUM2017	ST_NAME2017	ST_SUFFIX2017	ST_DIR2017	POSTAL_CODE2017	PIN2017	MUNICIPALITY2017	NAICS	SIC	COMMENTS	STORAGE_TANK	SHAPE_AREA	SHAPE_LEN
13732	CLEAN-O-RAMA DRY CLEANERS AND LAUNDRY	Laundries and Cleaners	1970-M	1	1970		1045.000000000000	ST. LAURENT	BLVD		OTTAWA	1045	ST LAURENT	BLVD			042650043	OTTAWA					36744.962976900897047	802.513236351665000
13734	FIRESTONE TIRE AND RUBBER COMPANY OF CANADA	Motor Vehicle Repair Shops	1970-1980-M+	1	1970-1980		1104.000000000000	ST. LAURENT	BLVD		OTTAWA	1104	ST LAURENT	BLVD			042540096	OTTAWA					9588.286748546121089	629.106640973444087
13840	GERRY WOAS SERVICE STATION	Gasoline Service Stations	1970-M	1	1970		997.000000000000	ST. LAURENT	BLVD		OTTAWA	997	ST LAURENT	BLVD			042650001	OTTAWA					1396.016067938560127	153.921499535855020
13841	GULF SELF SERVE	Gasoline Service Stations	1980-M	1	1980		1018.000000000000	CYRVILLE	RD		OTTAWA	1018	CYRVILLE	RD			042650006	OTTAWA					1957.239941239070049	200.709143568930017
14763	OSTCO CARPET IMPROVEMENTS INC	Laundries and Cleaners	2001-ES; 2005-SelectPhone	1	2005	c. 2001; c. 2005	579.000000000000	QUEEN MARY	ST			579	QUEEN MARY	ST		K1K1V9	042530225	OLD OTTAWA	238330; 561740				512.766745900893966	92.653559762292801
14807	BROWNS CLEANERS	Laundries and Cleaners	2012-ES	1	2012	ES 2012	1020.000000000000	ST LAURENT	BLVD			1012	ST LAURENT	BLVD		K1K3B4	042530280	OLD OTTAWA	812320				5282.505761860590610	374.543927957065023
14808	STAR PLAY	Appliance, Television, Radio and Stereo Stores	2001-ES	1	2001	c. 2001	1020.000000000000	ST LAURENT	BLVD		OTTAWA	1012	ST LAURENT	BLVD		K1K3B4	042530280	OLD OTTAWA	443110				5282.505761860590610	374.543927957065023
14895	ONE STOP LAUNDROMAT AND DRY CLEANERS	Dry Cleaners	1990-CD	1	1990	CD 1990	1045.000000000000	ST LAURENT	BLVD			1021	ST LAURENT	BLVD		K1K3B1	042650043	OLD OTTAWA					36744.962976900897047	802.513236351665000
14896	PARTSOURCE	Retail trade	2006-ES; 2012-ES	1	2006-2012	ES 2006; ES 2012	1091.000000000000	ST LAURENT	BLVD			1021	ST LAURENT	BLVD		K1K3B1	042650043	OLD OTTAWA	441310				36744.962976900897047	802.513236351665000
14897	ULTRALUX	Lumber and Building Materials, Wholesale	2001-ES	1	2001	c. 2001	1033.000000000000	ST LAURENT	BLVD		OTTAWA	1021	ST LAURENT	BLVD		K1K3B1	042650043	OLD OTTAWA	416340				36744.962976900897047	802.513236351665000
14898	UNNAMED SERIVCE STATION	Motor Vehicle Repair Shops	1956-FIP-256-2022; 1956-M; 1957-M; 1963-M	1	1956-1963	c. 1956-1963	1099.000000000000	ST LAURENT	BLVD		OTTAWA	1021	ST LAURENT	BLVD		K1K3B1	042650043	OLD OTTAWA	447110; 447190; 811112; 811119; 811121; 811199	633; 635		4 UST	36744.962976900897047	802.513236351665000
14899	BROWN'S CLEANERS	Laundries and Cleaners	1970-M; 1980-M	1	1970-1980	c. 1970; c. 1980	1045.000000000000	ST LAURENT	BLVD		OTTAWA	1021	ST LAURENT	BLVD		K1K3B1	042650043	OLD OTTAWA	561740; 812310; 812320; 812330	972			36744.962976900897047	802.513236351665000
14900	GASOLINE SERVICE STATION	Gasoline Service Station	1956-FIP-256-2022A	1	1956	1956	1107.000000000000	ST LAURENT	BLVD			1091	ST LAURENT	BLVD		K1K3B1	042650038	OLD OTTAWA				3 UST	2267.503019631490133	202.020882401919010
15022	ST LAURENT TIRE AND AUTO SERVICE	Tire and Auto Service	1990-CD	1	1990	CD 1990	1110.000000000000	ST LAURENT	BLVD			1116	ST LAURENT	BLVD		K1K3B6	042540096	OLD OTTAWA					9588.286748546121089	629.106640973444087
15023	OGILVIE MOTORS LTD	Retail/Car Dealership	2001-ES; 2006-ES; 2012-ES	1	2001-2012	ES 2001; ES 2006; ES 2012	1110.000000000000	ST LAURENT	BLVD			1116	ST LAURENT	BLVD		K1K3B6	042540096	OLD OTTAWA	441110				9588.286748546121089	629.106640973444087
15024	UNNAMED SERIVCE STATION	Motor Vehicle Repair Shops	1954-M; 1955-M; 1956-FIP-256-2022; 1957-M; 1960-M; 1963-M; 1970-M; 1980-M	1	1948-1980	c. 1948-1963; c. 1970-1980+	1104.000000000000	ST LAURENT	BLVD		OTTAWA	1116	ST LAURENT	BLVD		K1K3B6	042540096	OLD OTTAWA	811112; 811119; 811121	635			9588.286748546121089	629.106640973444087
15025	MERCEDES-BENZ CANADA INC	Automobile Dealers-New Cars	2017-SalesGenie	1	2017	SalesGenie 2017					OTTAWA	1116	ST LAURENT	BLVD		K1K3B6	042540096	OLD OTTAWA	44111001	5511-02			9588.286748546121089	629.106640973444087

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	SOURCE_UPDATE_SORTED	QAQC	YEAR	YEAR_1	ST_NUM	ST_NAME	ST_SUFFIX	ST_DIR	MUNICIPALITY	ST_NUM2017	ST_NAME2017	ST_SUFFIX2017	ST_DIR2017	POSTAL_CODE2017	PIN2017	MUNICIPALITY2017	NAICS	SIC	COMMENTS	STORAGE_TANK	SHAPE_AREA	SHAPE_LEN
15026	SMART	Automobile Dealers-New Cars	2017-SalesGenie	1	2017	SalesGenie 2017					OTTAWA	1116	ST LAURENT	BLVD		K1K3B6	042540096	OLD OTTAWA	44111001	5511-02			9588.286748546121089	629.106640973444087
15264	B & B RADIATOR	Motor Vehicle Repair Shops	CityofGloucester-File#15-317-Subject:CyrvilleRealty-Box254	2	1982	c. 1982	0	OGILVIE	RD		OTTAWA	1137	ST LAURENT	BLVD			042650011	OLD OTTAWA	811112; 811119; 811121	635			2549.471136887850207	264.945039464329966
16847	SHELL SERVICE STATION	Gasoline Service Stations	1960-M; 1970-M	1	1960-1970	c. 1960; c. 1970	997.0000000000000000	ST LAURENT	BLVD		OTTAWA	997	ST LAURENT	BLVD		K1K3B1	042650001	OLD OTTAWA	447110; 447190; 811199	633			1396.016067938560127	153.921499535855020
16848	SUNOCO INC	Gasoline Service Stations	1990-CD; 2001-ES; 2005-PropertyAssessment; 2006-ES; 2012-ES	1	1970-2012	1970-2012	1007.0000000000000000	ST LAURENT	BLVD		GLOUCESTER	1007	ST LAURENT	BLVD		K1K3B1	042650002	OLD OTTAWA	447110; 447190; 811112; 811119; 811121; 811199	633; 635			2969.834069830490080	218.258824435169998
16963	PETRO-CANADA	Service Stations-Gasoline & Oil	2001-ES; 2006-ES; 2012-ES; 2017-SalesGenie	1	2001-2017	2001-2017					OTTAWA	1007	ST LAURENT	BLVD		K1K3B1	042650002	OLD OTTAWA	44719005	5541-01			2969.834069830490080	218.258824435169998
16964	PETRO CANADA SERVICE STATION	Gas Station	1990-CD; 2001-ES; 2006-ES; 2012-ES; 2017-SalesGenie	1	1990-2017	1990-2017	1018.0000000000000000	CYRVILLE	RD			1018	CYRVILLE	RD		K1J7S4	042650006	OLD OTTAWA					1957.239941239070049	200.709143568930017
16965	RENAUD HUBERT LIMITED	Gasoline Service Stations	1956-FIP-256-2023; 1956-M; 1957-M; 1960-M; 1963-M; 1970-M; 1980-M; 2005-PropertyAssessment	1	1956-2005	1956-2005	1018.0000000000000000	CYRVILLE	RD		OTTAWA	1018	CYRVILLE	RD		K1J7S4	042650006	OLD OTTAWA	447110; 447190; 811112; 811119; 811121; 811199	633; 635		4 UST	1957.239941239070049	200.709143568930017
17243	PERFORMANCE MOTORS OTTAWA	Auto Motors	1990-CD	1	1990	CD 1990	1064.0000000000000000	ST LAURENT	BLVD			1064	ST LAURENT	BLVD		K1K3B4	042530272	OLD OTTAWA					2166.762926305820201	190.072184194668012
17244	MIDAS AUTO SERVICE EXPERTS	Other/Automotive Garage	1990-CD; 2006-ES; 2012-ES; 2017-SalesGenie	1	1990-2017	ES 2006; ES 2012	1064.0000000000000000	ST LAURENT	BLVD			1064	ST LAURENT	BLVD		K1K3B4	042530272	OLD OTTAWA	811111				2166.762926305820201	190.072184194668012
17245	STAN BERNARD AUTOMOTIVE LIMITED	Gasoline Service Stations	2005-PropertyAssessment	1	2005	c. 2001; c. 2005	1064.0000000000000000	ST LAURENT	BLVD		OTTAWA	1064	ST LAURENT	BLVD		K1K3B4	042530272	OLD OTTAWA	811111; 811112; 811119; 811121; 811199				2166.762926305820201	190.072184194668012
17246	PERFORMANCE MOTORS	Motor Vehicle Repair Shops	1980-M	1	1980	c. 1980	1070.0000000000000000	ST LAURENT	BLVD		OTTAWA	1076	ST LAURENT	BLVD		K1K3B4	042530281	OLD OTTAWA	811112; 811119; 811121	635			661.309386899039964	119.502518838903015
17839	AALTO COMPUTERS	Appliance, Television, Radio and Stereo Stores	2001-ES	1	2001	c. 2001	1253.0000000000000000	DONALD	ST		OTTAWA	1235	DONALD	ST		K1J8W3	042660069	GLOUCESTER	443110				30866.024793949000014	793.279143714662041
17877	MICHAELS SERVICE STATION	Gasoline Service Stations	1960-M	1	1960		1091.0000000000000000	ST. LAURENT	BLVD		OTTAWA	1091	ST LAURENT	BLVD			042650043	OTTAWA					2525.374660582020169	205.103960838874997
17878	LAVIGNE SERVICE STATION	Gasoline Service Stations	1960-M	1	1960		1035.0000000000000000	ST. LAURENT	BLVD		OTTAWA	1035	ST LAURENT	BLVD			042650043	OTTAWA					2525.374660859869891	205.103960847833008
17879	GIGUERE SERVICE STATION	Gasoline Service Stations	1960-M; 1970-M; 1980-M	1	1960	c. 1960	1035.0000000000000000	ST LAURENT	BLVD		OTTAWA	1021	ST LAURENT	BLVD		K1K3B1	042650043	OLD OTTAWA	447110; 447190; 811199	633			2525.374660859869891	205.103960847833008
17880	SCOTT'S SERVICE STATION	Gasoline Service Stations	1960-M; 1970-M; 1980-M; 1997-TownshipofGloucester-40-15-508	1	1960-1980	c. 1960; c. 1970; c. 1978-1980	1091.0000000000000000	ST LAURENT	BLVD		OTTAWA	1021	ST LAURENT	BLVD		K1K3B1	042650043	OLD OTTAWA	447110; 447190; 811112; 811119; 811121; 811199	633; 635			2525.374660859869891	205.103960847833008
17881	MIDAS MUFFLER SHOP	Gasoline Service Stations	1978-1980-M	1	1978-1980		1091.0000000000000000	ST. LAURENT	BLVD		OTTAWA	1091	ST LAURENT	BLVD			042650043	OTTAWA					2525.374660859869891	205.103960847833008

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	TANK_LOCATION	TANK_CONTENT	TANK_SIZE	TANK_TYPE	TANK_STATUS	SOURCE	INSTALLED_ST_NUM	INSTALLED_ST_NAME	INSTALLED_ST_ABR	INSTALLED_ST_DIR	COMMENT_	MTM_X	MTM_Y	IMAGE_MAP	IMAGE_CERTAINTY	IMAGE_MAP_2	TANK_MATERIAL	TANK_ID	TANK_LEAKING	TANK_REMOVED	REMOVED_DATE	DATE_INSTALLED	NATURE_OF_BUSINESS	SCANNED_DRAWING	TEMPRECORDID	CAPACITY_UOM	MUNICIPALITY	POSTCODE
1005	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	1099	ST.LAURENT	BLVD		historical address - 1099 St. Laurent Blvd. 23/03/21 - Location updated based on historical aerial imagery and 1956 fire insurance plan image Volume2_256.jpg.	372236.073072589992080	5032263.869394470006227	Volume2_256.jpg	1													
1006	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	1099	ST.LAURENT	BLVD		historical address - 1099 St. Laurent Blvd. 23/03/21 - Location updated based on historical aerial imagery and 1956 fire insurance plan image Volume2_256.jpg.	372231.985534770006780	5032262.461561329662800	Volume2_256.jpg	1													
1007	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	1099	ST.LAURENT	BLVD		historical address - 1099 St. Laurent Blvd. 23/03/21 - Location updated based on historical aerial imagery and 1956 fire insurance plan image Volume2_256.jpg.	372228.535402850015089	5032260.517730159685016	Volume2_256.jpg	1													
1008	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	1107	ST.LAURENT	BLVD		historical address - 1107 St. Laurent Blvd. 23/03/22 - Location updated based on the 1956 fire insurance plan image Volume2_256.jpg.	372244.029296730004717	5032196.850004619918764	Volume2_256.jpg	1													
1009	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	1107	ST.LAURENT	BLVD		historical address - 1107 St. Laurent Blvd. 23/03/22 - Location updated based on the 1956 fire insurance plan image Volume2_256.jpg.	372245.678485070005991	5032193.095373569987714	Volume2_256.jpg	1													
1010	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	1107	ST.LAURENT	BLVD		historical address - 1107 St. Laurent Blvd. 23/03/22 - Location updated based on the 1956 fire insurance plan image Volume2_256.jpg.	372247.540698610013351	5032188.913842620328069	Volume2_256.jpg	1													
1011	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	46	CYRVILLE	RD		historical address - 46 Cyrville Rd. 23/03/22 - Location updated based on fire insurance plan image Volume2_256.jpg.	372284.170198499981780	5032089.347817010246217	Volume2_256.jpg	1													
1012	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	46	CYRVILLE	RD		historical address - 46 Cyrville Rd. 23/03/22 - Location updated based on fire insurance plan image Volume2_256.jpg.	372280.995213310001418	5032085.378988330252469	Volume2_256.jpg	1													
1013	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	46	CYRVILLE	RD		historical address - 46 Cyrville Rd. 23/03/22 - Location updated based on fire insurance plan image Volume2_256.jpg.	372279.010828259983100	5032080.616468610242009	Volume2_256.jpg	1													
1014	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	46	CYRVILLE	RD		historical address - 46 Cyrville Rd. 23/03/22 - Location updated based on fire insurance plan image Volume2_256.jpg.	372279.804512100003194	5032075.854015460237861	Volume2_256.jpg	1													
1283			UST	fuel oil				ROW	1091	ST LAURENT	BLVD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 3 tanks. Pump island removed between 1965 & 1991.	372241.086214600014500	5032174.155619760043919		2			ST7957					4 tanks					
1320			UST	fuel oil				ROW	1091	ST LAURENT	BLVD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 3 tanks. Pump island removed between 1965 & 1991.	372241.098945520003326	5032174.155055450275540		2			ST7908					3 tanks					
1440			UST	fuel oil				ROW	1018	CRYVILLE	RD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 4 tanks.	372281.690399169980083	5032082.367551079951227		2			ST7395					4 tanks					
1441			UST	fuel oil				ROW	1018	CRYVILLE	RD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 4 tanks.	372281.690399169980083	5032082.367551079951227		2			ST7396					4 tanks					
1442			UST	fuel oil				ROW	1018	CRYVILLE	RD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 4 tanks.	372281.690399169980083	5032082.367551079951227		2			ST7397					4 tanks					
1443			UST	fuel oil				ROW	1018	CRYVILLE	RD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 4 tanks.	372281.690399169980083	5032082.367551079951227		2			ST7398					4 tanks					

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	TANK_LOCATION	TANK_CONTENT	TANK_SIZE	TANK_TYPE	TANK_STATUS	SOURCE	INSTALLED_ST_NUM	INSTALLED_ST_NAME	INSTALLED_ST_ABR	INSTALLED_ST_DIR	COMMENT_	MTM_X	MTM_Y	IMAGE_MAP	IMAGE_CERTAINTY	IMAGE_MAP_2	TANK_MATERIAL	TANK_ID	TANK_LEAKING	TANK_REMOVED	REMOVED_DATE	DATE_INSTALLED	NATURE_OF_BUSINESS	SCANNED_DRAWING	TEMPRECORDID	CAPACITY_UOM	MUNICIPALITY	POSTCODE
1562			UST	fuel oil				ROW	1091	ST LAURENT	BLVD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 3 tanks. Pump island removed between 1965 & 1991.	372241.098945520003326	5032174.155055450275540		2			ST7865					3 tanks					
1802	6434118 CANADA INC O/A SUNOCO	Gasoline Station - Self Serve	UST	gasoline	50000.000000000000000	Licensed	Active	TSSA	1007	ST LAURENT	BLVD		23/05/04 Location Updated, further update not possible. Moved ontop of tanks area based on activity name, project polygon layer, date installed, 1999 & 2002 imagery.	372168.830765959981363	5032398.218011659570038		2		Fiberglass (FRP)	ST8833				1997						
1803	6434118 CANADA INC O/A SUNOCO	Gasoline Station - Self Serve	UST	gasoline	50000.000000000000000	Licensed	Active	TSSA	1007	ST LAURENT	BLVD		23/05/04 Location Updated, further update not possible. Moved ontop of tanks area based on activity name, project polygon layer, date installed, 1999 & 2002 imagery.	372168.830765959981363	5032398.218011659570038		2		Fiberglass (FRP)	ST8834				1997						
1804	6434118 CANADA INC O/A SUNOCO	Gasoline Station - Self Serve	UST	gasoline	50000.000000000000000	Licensed	Active	TSSA	1007	ST LAURENT	BLVD		23/05/04 Location Updated, further update not possible. Moved ontop of tanks area based on activity name, project polygon layer, date installed, 1999 & 2002 imagery.	372168.830765959981363	5032398.218011659570038		2		Fiberglass (FRP)	ST8835				1997						
1817			UST	fuel oil				ROW	1091	ST LAURENT	BLVD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 4 tanks. Gas station removed between 1965 & 1976.	372222.613440289977007	5032220.742065760307014		2			ST7822					3 tanks					
1876			UST	fuel oil				ROW	1091	ST LAURENT	BLVD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 4 tanks. Gas station removed between 1965 & 1976.	372222.626171860028990	5032220.741431370377541		2			ST8007					4 tanks					
3040	ST MICHAEL'S SEPARATE SCHOOL		UST	fuel oil	9080.000000000000000	Permit		Bylaw No. 304-60 VAH6100: 0056 - P2488	741	BERNARD	ST		address verified from dwg & geoottawa, St Michael's Separate School - Bernard St. 22/07/27 - Location updated based on historic aerial imagery and plan image FR300-VAH6100-0056_003.jpg.	371974.734231050009839	5032005.972878010012209	FR300-VAH6100-0056_003.jpg	1			ST3908				29/09/1969		Yes				
3160	CANADIAN PETROFINA		not specified	gasoline	9080.000000000000000	Permit		Bylaw No. 8022 - P838, 839, 840	1021	ST LAURENT	BLVD		address verified from 1960 city directory 1061 st laurent blvd historic address, St Laurent Blvd	372175.808749150019139	5032322.451659680344164		2			ST2784				18/04/1955	4 - 2000 gal gas tank 1 - 1000 gal fuel tank; & 1 - 500 waste oil tank					
3161	CANADIAN PETROFINA		not specified	fuel oil	4540.000000000000000	Permit		Bylaw No. 8022 - P838, 839, 840	1021	ST LAURENT	BLVD		address verified from 1960 city directory 1061 st laurent blvd historic address, St Laurent Blvd.	372175.808749150019139	5032322.451659680344164		2			ST2874				18/04/1955	4 - 2000 gal gas tank 1 - 1000 gal fuel tank; & 1 - 500 waste oil tank					
3162	CANADIAN PETROFINA		not specified	waste oil	2270.000000000000000	Permit		Bylaw No. 8022 - P838, 839, 840	1021	ST LAURENT	BLVD		address verified from 1960 city directory 1061 st laurent blvd historic address, St Laurent Blvd.	372175.808749150019139	5032322.451659680344164		2			ST2963				18/04/1955	4 - 2000 gal gas tank 1 - 1000 gal fuel tank; & 1 - 500 waste oil tank					
3178	SUN OIL CO LTD		UST	gasoline	22700.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6000; STLA 01007 - P2770	1007	ST LAURENT	BLVD		23/03/22 - Location updated based on plan image FR300-VAH6000-STLA 01007_005.jpg.	372167.426732480002102	5032402.295302400365472	FR300-VAH6000-STLA 01007_005.jpg	1			ST5339	N	N				Yes				
3179	SUN OIL CO LTD		UST	fuel oil	2270.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6000; STLA 01007 - P2770	1007	ST LAURENT	BLVD		23/03/22 - Location updated based on FR300-VAH6000-STLA 01007_005.jpg.	372173.179894839995541	5032435.262234490364790	FR300-VAH6000-STLA 01007_005.jpg	1			ST5682	N	N		24785		Yes				
3180	SUN OIL		not specified	gasoline	18160.000000000000000	Permit		Bylaw No. 8022 - P1175, 1176, 1177	1007	ST LAURENT	BLVD		1025 & 1043 st laurent incorrect address, St Laurent Blvd.	372177.070143770019058	5032317.647228839807212		2			ST1556				17/06/1957	3 - 4000 gal gasoline tanks 1 - 1000 gal fuel oil tank; & 1 - 1000 gal waste oil tank					
3181	SUN OIL		not specified	gasoline	18160.000000000000000	Permit		Bylaw No. 8022 - P1175, 1176, 1177	1007	ST LAURENT	BLVD		1025 & 1043 st laurent incorrect address, St Laurent Blvd.	372177.082804089994170	5032317.646663670428097		2			ST2284				17/06/1957	3 - 4000 gal gasoline tanks 1 - 1000 gal fuel oil tank; & 1 - 1000 gal waste oil tank					
3182	SUN OIL		not specified	gasoline	18160.000000000000000	Permit		Bylaw No. 8022 - P1175, 1176, 1177	1007	ST LAURENT	BLVD		1025 & 1043 st laurent incorrect address, St Laurent Blvd.	372177.082804089994170	5032317.646663670428097		2			ST2627				17/06/1957	3 - 4000 gal gasoline tanks 1 - 1000 gal fuel oil tank; & 1 - 1000 gal waste oil tank					
3183	SUN OIL		not specified	fuel oil	4540.000000000000000	Permit		Bylaw No. 8022 - P1175, 1176, 1177	1007	ST LAURENT	BLVD		1025 & 1043 st laurent incorrect address, St Laurent Blvd.	372177.082804089994170	5032317.646663670428097		2			ST2704				17/06/1957	3 - 4000 gal gasoline tanks 1 - 1000 gal fuel oil tank; & 1 - 1000 gal waste oil tank					
3184	SUN OIL		not specified	waste oil	4540.000000000000000	Permit		Bylaw No. 8022 - P1175, 1176, 1177	1007	ST LAURENT	BLVD		1025 & 1043 st laurent incorrect address, St Laurent Blvd.	372177.082804089994170	5032317.646663670428097		2			ST2923				17/06/1957	3 - 4000 gal gasoline tanks 1 - 1000 gal fuel oil tank; & 1 - 1000 gal waste oil tank					

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	TANK_LOCATION	TANK_CONTENT	TANK_SIZE	TANK_TYPE	TANK_STATUS	SOURCE	INSTALLED_ST_NUM	INSTALLED_ST_NAME	INSTALLED_ST_ABR	INSTALLED_ST_DIR	COMMENT_	MTM_X	MTM_Y	IMAGE_MAP	IMAGE_CERTAINTY	IMAGE_MAP_2	TANK_MATERIAL	TANK_ID	TANK_LEAKING	TANK_REMOVED	REMOVED_DATE	DATE_INSTALLED	NATURE_OF_BUSINESS	SCANNED_DRAWING	TEMPRECORDID	CAPACITY_UOM	MUNICIPALITY	POSTCODE
3300	SHELL CANADA LTD		UST	waste oil	4540.000000000000000	Permit		Bylaw No. 304-60 VAH6000; STLA 00997 - P2300	997	ST LAURENT	BLVD		22/03/21 - Location updated based on aerial imagery and plan image FR300-VAH6000-STLA 00997_002.jpg.	372154.477049809996970	5032436.861960629932582	FR300-VAH6000-STLA 00997_002.jpg	1			ST4738				24239		Yes					
3301	SHELL CANADA LTD		UST	gasoline	22700.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6000; STLA 00997 - P2300	997	ST LAURENT	BLVD		22/03/21 - Location updated based on aerial imagery and plan image FR300-VAH6000-STLA 00997_002.jpg.	372143.832489130028989	5032455.209287559613585	FR300-VAH6000-STLA 00997_002.jpg	1			ST1555	N	N		20824	2 - 5000 gasoline tank 2 - 1000 fuel oil tank	Yes					
3302	SHELL CANADA LTD		UST	gasoline	22700.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6000; STLA 00997 - P2300	997	ST LAURENT	BLVD		22/03/21 - Location updated based on aerial imagery and plan image FR300-VAH6000-STLA 00997_002.jpg.	372142.230772480019368	5032454.204340949654579	FR300-VAH6000-STLA 00997_002.jpg	1			ST2283	N	N		20824	2 - 5000 gasoline tank 2 - 1000 fuel oil tank	Yes					
3303	SHELL CANADA LTD		UST	fuel oil	4540.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6000; STLA 00997 - P2300	997	ST LAURENT	BLVD		22/03/21 - Location updated based on aerial imagery and plan image FR300-VAH6000-STLA 00997_002.jpg.	372147.527498350013047	5032454.351330850273371	FR300-VAH6000-STLA 00997_002.jpg	1			ST2409	N	N		20824	2 - 5000 gasoline tank 2 - 1000 fuel oil tank	Yes					
3304	J CYR - CHAMPLAIN OIL		not specified	gasoline	4540.000000000000000	Permit		Bylaw No. 8022 - P775	1018	CYRVILLE	RD		listed as 1953 assessment, rideau ward vol 4 - 14-410-4, st laurent east side, south of cyrville rd, St Laurent & Cyrville. 22/03/24 - Point Confirmed, no further update possible based on the information provided.	372304.826332400029059	5032065.703132930211723	FR300-VAH6100-0299_002.jpg	2			ST1557				19914	2 - 1000 gasoline						
3305	J CYR - CHAMPLAIN OIL		not specified	gasoline	4540.000000000000000	Permit		Bylaw No. 8022 - P775	1018	CYRVILLE	RD		listed as 1953 assessment, rideau ward vol 4 - 14-410-4, st laurent east side, south of cyrville rd, St Laurent & Cyrville. 22/03/24 - Point Confirmed, no further update possible based on the information provided.	372304.826332400029059	5032065.703132930211723	FR300-VAH6100-0299_002.jpg	2			ST2285				19914	2 - 1000 gasoline						
3306			UST	gasoline	22700.000000000000000	Permit		Bylaw No. 304-60 - P - none issued	1018	CYRVILLE	RD		22/03/24 - Point Confirmed, no further update possible based on the information provided.	372304.839064289990347	5032065.702498669736087	FR300-VAH6100-0299_002.jpg	2			ST4503				19/11/1975							
3307	GULF OIL CANADA LTD		UST	gasoline	36320.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0299 - Pnone issued	1018	CYRVILLE	RD		23/03/24 - Location updated based on historic aerial imagery and plan image FR300-VAH6100-0299_002.jpg.	372280.421814710018225	5032079.313338509760797	FR300-VAH6100-0299_002.jpg	1			ST4502	N	N		19/08/1976		Yes					
3308			UST	gasoline	22700.000000000000000	Permit		Bylaw No. 304-60 - P - none issued	1018	CYRVILLE	RD		22/03/24 - Point Confirmed, no further update possible based on the information provided.	372304.839064289990347	5032065.702498669736087	FR300-VAH6100-0299_002.jpg	2			ST5068				19/11/1975							
3351	GULF OIL CANADA LTD		UST	gasoline	36320.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0299 - Pnone issued	1018	CYRVILLE	RD		23/03/24 - Location updated based on historic aerial imagery and plan image FR300-VAH6100-0299_002.jpg.	372283.785279150004499	5032078.844039569608867	FR300-VAH6100-0299_002.jpg	1			ST5067	N	N		19/08/1976		Yes					
3352	ST MICHAEL'S SEPARATE SCHOOL		UST	fuel oil	9080.000000000000000	Existing	Not active-removed	Bylaw No. 304-60 VAH6100; 0056 - P2488	741	BERNARD	ST		address verified from dwg & geoottawa, St Michael's Separate School - Bernard St. 22/07/27 - Location updated based on historic aerial imagery and plan image FR300-VAH6100-0056_003.jpg.	371974.734231050009839	5032005.972878010012209	FR300-VAH6100-0056_003.jpg	1			ST5776	Y	Y	25475			Yes				
3523	GULF OIL CANADA LTD		UST	gasoline	36320.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0299 - Pnone issued	1018	CYRVILLE	RD		23/03/24 - Location updated based on historic aerial imagery and plan image FR300-VAH6100-0299_002.jpg.	372286.757576400006656	5032078.452952830120921	FR300-VAH6100-0299_002.jpg	1			ST5340	N	N		19/08/1976		Yes					
3524	GULF OIL CANADA LTD		UST	gasoline	27240.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0299 - Pnone issued	1018	CYRVILLE	RD		23/03/24 - Location updated based on historic aerial imagery and plan image FR300-VAH6100-0299_002.jpg.	372289.417071459989529	5032077.748937670141459	FR300-VAH6100-0299_002.jpg	1			ST5503	N	N		19/08/1976		Yes					
3525	SUPERTEST PETROLEUM CORP LTD		UST	gasoline	22700.000000000000000	Permit		Bylaw No. 304-60 VAH6100; 0342 - P2420	1091	ST LAURENT	BLVD		address verified from dwg & geoottawa dwg shows septic tank & tile field;, St Laurent & Cyrville Rd. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372250.748619480000343	5032173.439605819992721	FR300-VAH6100-0342_005.jpg	1			ST4506				15/07/1968		Yes					
3526	SUPERTEST PETROLEUM CORP LTD		UST	gasoline	18160.000000000000000	Permit		Bylaw No. 304-60 VAH6100; 0342 - P2420	1091	ST LAURENT	BLVD		address verified from dwg & geoottawa dwg shows septic tank & tile field;, St Laurent & Cyrville Rd. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372251.624655820021871	5032170.429725349880755	FR300-VAH6100-0342_005.jpg	1			ST5070				15/07/1968		Yes					
3527	SUPERTEST PETROLEUM CORP LTD		UST	gasoline	9080.000000000000000	Existing	Not active-removed	Bylaw No. 304-60 VAH6100; 0342 - P2420	1091	ST LAURENT	BLVD		address verified from dwg & geoottawa dwg shows septic tank & tile field;, St Laurent & Cyrville Rd. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372246.540353760006838	5032186.073614140041173	FR300-VAH6100-0342_005.jpg	1	FR300-VAH6000-STLA 01091_002.jpg		ST1558	Y	Y	25034	19/12/1955	3 - 2000 gal gas tanks	Yes					
3528	SUPERTEST PETROLEUM CORP LTD		UST	gasoline	9080.000000000000000	Existing	Not active-removed	Bylaw No. 304-60 VAH6100; 0342 - P2420	1091	ST LAURENT	BLVD		address verified from dwg & geoottawa dwg shows septic tank & tile field;, St Laurent & Cyrville Rd. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372247.400777100003324	5032182.788405540399253	FR300-VAH6100-0342_005.jpg	1	FR300-VAH6000-STLA 01091_002.jpg		ST2286	Y	Y	25034	19/12/1955	3 - 2000 gal gas tanks	Yes					

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	TANK_LOCATION	TANK_CONTENT	TANK_SIZE	TANK_TYPE	TANK_STATUS	SOURCE	INSTALLED_ST_NUM	INSTALLED_ST_NAME	INSTALLED_ST_ABR	INSTALLED_ST_DIR	COMMENT_	MTM_X	MTM_Y	IMAGE_MAP	IMAGE_CERTAINTY	IMAGE_MAP_2	TANK_MATERIAL	TANK_ID	TANK_LEAKING	TANK_REMOVED	REMOVED_DATE	DATE_INSTALLED	NATURE_OF_BUSINESS	SCANNED_DRAWING	TEMPRECORDID	CAPACITY_UOM	MUNICIPALITY	POSTCODE
3529	SUPERTEST PETROLEUM CORP LTD		UST	gasoline	9080.000000000000000	Existing	Not active-removed	Bylaw No. 304-60 VAH6100; 0342 - P2420	1091	ST LAURENT	BLVD		address verified from dwg & geoottawa dwg shows septic tank & tile field;, St Laurent & Cyrville Rd. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372248.652302369999234	5032179.581450490280986	FR300-VAH6100-0342_005.jpg	1	FR300-VAH6000-STLA 01091_002.jpg		ST2628	Y	Y	25034	19/12/1955	3 - 2000 gal gas tanks	Yes				
3609	QUEEN MARY ST PUBLIC SCHOOL		UST	fuel oil	22700.000000000000000	Permit		Bylaw No. 8022 - P1563	557	QUEEN MARY	ST		23/08/30 Final review, further update not possible, cannot locate reference material to verify tank location and FIP does not indicate tank locations. Activity name correct based on Volume2-255.jpg & 1965 imagery. Need Permit 1563 for further details.	371919.245957910025027	5032185.627617809921503		2			ST0403				17/08/1959	1 - 5000 gal fuel oil UST					
3822	SHELL CANADA LTD		UST	waste oil	4540.000000000000000	Existing	Not active-removed	Bylaw No. 304-60 VAH6000; STLA 00997 - P2300	997	ST LAURENT	BLVD		22/03/21 - Location updated based on aerial imagery and plan image FR300-VAH6000-STLA 00997_002.jpg.	372155.765832110017072	5032434.047055039554834	FR300-VAH6000-STLA 00997_002.jpg	1			ST7100	N	Y re-installed on site				Yes				
3823	SHELL		not specified	fuel oil	4540.000000000000000	Permit		Bylaw No. 8022 - P1130, 1131, 1132, 1133	997	ST LAURENT	BLVD		1005 st laurent blvd historic address, Service Stn - 1005 St Laurent Blvd. 22/03/21 - Location updated based on aerial imagery and plan image FR300-VAH6000-STLA 00997_002.jpg.	372155.778563240019139	5032434.046420539729297	FR300-VAH6000-STLA 00997_002.jpg	2			ST2684				20824	2 - 5000 gasoline tank 2 - 1000 fuel oil tank					
3824	IMPERIAL OIL - H RENAUD		UST	gasoline	22700.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0371 - P2399	1018	CYRVILLE	RD		dwg shows existing tanks to be removed but new tanks not installed at this permit address verified from dwg & geoottawa, St Laurent Blvd & Cyrville Rd.23/03/24 - Location updated based on historic aerial imagery and plan image FR300-VAH6100-0299_002.jpg.	372311.005683799972758	5032058.898027679882944	FR300-VAH6100-0299_002.jpg	1			ST6119	N	N				Yes				
3851	SUN OIL CO LTD		UST	gasoline	22700.000000000000000	Permit		Bylaw No. 304-60 VAH6000; STLA 01007 - P2770	1007	ST LAURENT	BLVD		23/03/22 - Location updated based on plan image FR300-VAH6000-STLA 01007_005.jpg.	372164.410157039994374	5032409.602907359600067	FR300-VAH6000-STLA 01007_005.jpg	1			ST4501				24785		Yes				
3852	SUN OIL CO LTD		UST	gasoline	22700.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6000; STLA 01007 - P2770	1007	ST LAURENT	BLVD		23/03/22 - Location updated based on plan image FR300-VAH6000-STLA 01007_005.jpg.	372165.287784030020703	5032407.482027400285006	FR300-VAH6000-STLA 01007_005.jpg	1			ST4500	N	N		24785		Yes				
3853	SUN OIL CO LTD		UST	gasoline	22700.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6000; STLA 01007 - P2770	1007	ST LAURENT	BLVD		23/03/22 - Location updated based on plan image FR300-VAH6000-STLA 01007_005.jpg.	372166.500606609974056	5032404.927510749548674	FR300-VAH6000-STLA 01007_005.jpg	1			ST5066	N	N		24785		Yes				
3871	IMPERIAL OIL - H RENAUD		UST	gasoline	18160.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0371 - P2399	1018	CYRVILLE	RD		dwg shows existing tanks to be removed but new tanks not installed at this permit address verified from dwg & geoottawa, St Laurent Blvd & Cyrville Rd. 23/03/24 - Location updated based on historic aerial imagery and plan image FR300-VAH6100-0299_002.jpg.	372308.424423029995523	5032058.350482449866831	FR300-VAH6100-0299_002.jpg	1			ST6540	N	N				Yes				
3872	SUPERTEST PETROLEUM CORP LTD		UST	gasoline	13620.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0342 - P2420	1091	ST LAURENT	BLVD		address verified from dwg & geoottawa dwg shows septic tank & tile field;, St Laurent & Cyrville Rd. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372249.825609379971866	5032176.765489820390940	FR300-VAH6100-0342_005.jpg	1			ST5881	N	N				Yes				
3873	SUPERTEST PETROLEUM CORP LTD		UST	fuel oil	2270.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0342 - P2420	1091	ST LAURENT	BLVD		address verified from dwg & geoottawa dwg shows septic tank & tile field;, St Laurent & Cyrville Rd. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372261.161154380009975	5032183.802143439650536	FR300-VAH6100-0342_005.jpg	1	FR300-VAH6000-STLA 01091_002.jpg		ST6921	N	N				Yes				
3874	SUPERTEST PETROLEUM CORP LTD		UST (beneath bldg)	waste oil	2270.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6100; 0342 - P2420	1091	ST LAURENT	BLVD		address verified from dwg & geoottawa dwg shows septic tank & tile field;, St Laurent & Cyrville Rd. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372257.356604899978265	5032193.814218309707940	FR300-VAH6100-0342_005.jpg	1	FR300-VAH6000-STLA 01091_002.jpg		ST7244	N	N				Yes				
3875	CANADIAN PETROFINA		not specified	gasoline	9080.000000000000000	Permit		Bylaw No. 8022 - P838, 839, 840	1021	ST LAURENT	BLVD		address verified from 1960 city directory 1061 st laurent blvd historic address, St Laurent Blvd.	372175.808749150019139	5032322.451659680344164		2			ST1559				18/04/1955	4 - 2000 gal gas tank 1 - 1000 gal fuel tank; & 1 - 500 waste oil tank					
3876	CANADIAN PETROFINA		not specified	gasoline	9080.000000000000000	Permit		Bylaw No. 8022 - P838, 839, 840	1021	ST LAURENT	BLVD		address verified from 1960 city directory 1061 st laurent blvd historic address, St Laurent Blvd.	372175.808749150019139	5032322.451659680344164		2			ST2287				18/04/1955	4 - 2000 gal gas tank 1 - 1000 gal fuel tank; & 1 - 500 waste oil tank					
7524	<Null>	<Null>		gasoline	0	<Null>	<Null>	GW Study 2004	<Null>	<Null>	<Null>	<Null>	1018 CYRVILLE RD. 23/03/22 - Point reviewed, no further update possible based on the information provided.	372303.299980150011834	5032072.399979759939015		3							<Null>	<Null>		2043.000000000000000	<Null>	GLOUCESTER	K1J 7S4
7680	ERIC ROY	Gasoline Station-SS		gasoline	35000.000000000000000	Licenced	Previous	GW Study 2004	1018	CYRVILLE	RD	<Null>	1018 CYRVILLE RD. 23/11/22 Location Updated, further update not possible. Moved ontop of tanks area based on address, municiapl address point layer, source study year, 2002 & 2005 imagery.	372288.642747630015947	5032079.616871559992433		2							19830401	Retail		406.000000000000000	L	GLOUCESTER	K1J 7S4

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	TANK_LOCATION	TANK_CONTENT	TANK_SIZE	TANK_TYPE	TANK_STATUS	SOURCE	INSTALLED_ST_NUM	INSTALLED_ST_NAME	INSTALLED_ST_ABR	INSTALLED_ST_DIR	COMMENT_	MTM_X	MTM_Y	IMAGE_MAP	IMAGE_CERTAINTY	IMAGE_MAP_2	TANK_MATERIAL	TANK_ID	TANK_LEAKING	TANK_REMOVED	REMOVED_DATE	DATE_INSTALLED	NATURE_OF_BUSINESS	SCANNED_DRAWING	TEMPRECORDID	CAPACITY_UOM	MUNICIPALITY	POSTCODE
8530	SUNOCO GAS BAR - M ROUFAEL INC	Gasoline Station-SS		gasoline	36000.000000000000000	Licenced	Previous	GW Study 2004	1007	ST LAURENT	BLVD	<Null>	1007 ST LAURENT BLVD. 23/05/04 Location Updated, further update not possible. Moved ontop of tanks area based on activity name, project polygon layer, date installed, 1991 & 1999 imagery. 1 of 2 pump island areas removed between 1991 & 1999.	372163.317968729999848	5032394.707460169680417		2							19830401	Retail		2399.00000000000000	L	OTTAWA	K1K 3B1
8580	SUNOCO GAS BAR - M ROUFAEL INC	Gasoline Station-SS		gasoline	24000.000000000000000	Licenced	Previous	GW Study 2004	1007	ST LAURENT	BLVD	<Null>	1007 ST LAURENT BLVD. 23/05/04 Location Updated, further update not possible. Moved ontop of tanks area based on activity name, project polygon layer, date installed, 1991 & 1999 imagery. 1 of 2 pump island areas removed between 1991 & 1999.	372163.317980449995957	5032394.272898520343006		2							19830401	Retail		2400.00000000000000	L	OTTAWA	K1K 3B1
8581	SUNOCO GAS BAR - M ROUFAEL INC	Gasoline Station-SS		gasoline	36000.000000000000000	Licenced	Previous	GW Study 2004	1007	ST LAURENT	BLVD	<Null>	1007 ST LAURENT BLVD. 23/05/04 Location Updated, further update not possible. Moved ontop of tanks area based on activity name, project polygon layer, date installed, 1991 & 1999 imagery. 1 of 2 pump island areas removed between 1991 & 1999.	372163.317974589997903	5032394.490179340355098		2							19830401	Retail		2401.00000000000000	L	OTTAWA	K1K 3B1
8582	SUNOCO GAS BAR - M ROUFAEL INC	Gasoline Station-SS		diesel	24000.000000000000000	Licenced	Current	GW Study 2004	1007	ST LAURENT	BLVD	<Null>	1007 ST LAURENT BLVD. 23/05/04 Location Updated, further update not possible. Moved ontop of tanks area based on activity name, project polygon layer, date installed, 1991 & 1999 imagery. 1 of 2 pump island areas removed between 1991 & 1999.	372163.100745700008702	5032394.490166730247438		2							19830401	Retail		2402.00000000000000	L	OTTAWA	K1K 3B1
8637	ERIC ROY	Gasoline Station-SS		gasoline	25000.000000000000000	Licenced	Previous	GW Study 2004	1018	CYRVILLE	RD	<Null>	1018 CYRVILLE RD. 23/11/22 Location Updated, further update not possible. Moved ontop of tanks area based on address, municiapl address point layer, source study year, 2002 & 2005 imagery.	372288.642747630015947	5032079.616871559992433		2							19830401	Retail		2320.00000000000000	L	GLOUCESTER	K1J 7S4
8638	ERIC ROY	Gasoline Station-SS		gasoline	25000.000000000000000	Licenced	Previous	GW Study 2004	1018	CYRVILLE	RD	<Null>	1018 CYRVILLE RD. 23/11/22 Location Updated, further update not possible. Moved ontop of tanks area based on address, municiapl address point layer, source study year, 2002 & 2005 imagery.	372288.642747630015947	5032079.616871559992433		2							19830401	Retail		2321.00000000000000	L	GLOUCESTER	K1J 7S4
8639	ERIC ROY	Gasoline Station-SS		diesel	25000.000000000000000	Licenced	Current	GW Study 2004	1018	CYRVILLE	RD	<Null>	1018 CYRVILLE RD. 23/11/22 Location Updated, further update not possible. Moved ontop of tanks area based on address, municiapl address point layer, source study year, 2002 & 2005 imagery.	372288.642747630015947	5032079.616871559992433		2							19830401	Retail		2322.00000000000000	L	GLOUCESTER	K1J 7S4
8674	CANADIAN PETROFINA		not specified	gasoline	9080.000000000000000	Permit		Bylaw No. 8022 - P838, 839, 840	1021	ST LAURENT	BLVD		address verified from 1960 city directory 1061 st laurent blvd historic address, St Laurent Blvd.	372175.808749150019139	5032322.451659680344164		2			ST2629				18/04/1955	4 - 2000 gal gas tank 1 - 1000 gal fuel tank; & 1 - 500 waste oil tank						
8844	SUN OIL CO LTD		UST	waste oil	2270.000000000000000	Existing	Active	Bylaw No. 304-60 VAH6000; STLA 01007 - P2770	1007	ST LAURENT	BLVD		23/03/22 - Location updated based on plan image FR300-VAH6000-STLA 01007_005.jpg.	372160.250111390021630	5032430.818543829955161	FR300-VAH6000-STLA 01007_005.jpg	1			ST5540	N	N		22/02/1974		Yes				
8846	SUPERTEST PETROLEUM CORPORATION LTD		UST	gasoline	22700.000000000000000	Permit		Bylaw No. 304-60 VAH6000; STLA 01091 - P1916	1091	ST LAURENT	BLVD		dwg shows septic tank & tile field, 1091 St Laurent Blvd Pt lots 27 & 28 Plan Cyrville Ottawa. 23/03/22 - Location updated based on plan image FR300-VAH6100-0342_005.jpg.	372250.761351149994880	5032173.438971470110118	FR300-VAH6000-STLA 01091_002.jpg	1			ST4505				22835		Yes				
8976			UST	fuel oil				ROW	1091	ST LAURENT	BLVD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 4 tanks. Gas station removed between 1965 & 1976.	372222.638832380005624	5032220.740866280160844		2			ST7982					4 tanks						
9323			UST	fuel oil				ROW	1091	ST LAURENT	BLVD		23/11/22 Location Updated, further update not possible. Moved ontop of pump island based on address & 1958 imagery. Suspect the exact tank location was the same that shown on Volume2-256.jpg based on a group of 4 tanks. Gas station removed between 1965 & 1976.	372222.651563949999399	5032220.740231879986823		2			ST7932					4 tanks						
9443	GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1956	1099	ST.LAURENT	BLVD		historical address - 1099 St. Laurent Blvd. 23/03/21 - Location updated based on historical aerial imagery and 1956 fire insurance plan image Volume2_256.jpg.	372224.885394659999292	5032259.388069310225546	Volume2_256.jpg	1														
9660	ERIC ROY	Gasoline Station-SS		gasoline	35000.000000000000000	Licenced	Previous	GW Study 2004	1018	CYRVILLE	RD	<Null>	1018 CYRVILLE RD. 23/11/22 Location Updated, further update not possible. Moved ontop of tanks area based on address, municiapl address point layer, source study year, 2002 & 2005 imagery.	372288.642747630015947	5032079.616871559992433		2							19830401	Retail		2319.00000000000000	L	GLOUCESTER	K1J 7S4

HLUI SUMMARY REPORT
LINEAR FEATURES

OBJECTID	SOURCE	FEATURE	YEAR	COMMENT_	NAME	SHAPE_LEN
61	Enbridge	Gas Pipeline				540.615068662468047

HISTORIC LAND USE INVENTORY (HLUI) - REPORT REFERENCE MAP - 1052, 1060, 1064 ST-LAURENT



APPENDIX J

Aerial Photographs

HISTORICAL AERIALS

Project Property: Phase One Environmental Site Assessment - St. Laurent Boulevard Properties
1052, 1060 and 1064 St. Laurent Boulevard
Ottawa ON K1K 3B4

Project No: 103499.002

Requested By: GEMTEC Consulting Engineers and Scientists Limited (Ontario)

Order No: 24102901203

Date Completed: June 09,2025

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
1945	National Air Photo Library	10,000	
1933	National Air Photo Library	10,000	
1920	Decade Coverage Unavailable	10,000	

Year: 1945
Source: NAPL
Scale: 10,000
Comment:

Address: 1052, 1060 and 1064 St. Laurent Boulevard,
Ottawa, ON
Approx Center: -75.63922509,45.4267135

Order No: 24102901203

ERIS

250
Meters



Year: 1933
Source: NAPL
Scale: 10,000
Comment:

Address: 1052, 1060 and 1064 St. Laurent Boulevard,
Ottawa, ON
Approx Center: -75.63922509,45.4267135

Order No: 24102901203

ERIS

HISTORICAL AERIALS

Project Property: Phase I Environmental Site Assessment - 1052 St. Laurent Boulevard, Ottawa, Ontario
1052 St. Laurent Blvd
Ottawa ON K1K 3B4

Project No: 103499.001

Requested By: GEMTEC Consulting Engineers and Scientists Limited (Ontario)

Order No: 24051600078

Date Completed: May 17,2024

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
2023	Maxar Technologies	10,000	
1983	National Air Photo Library	10,000	

Year: 2023
Source: MAXAR
Scale: 10,000
Comment:

Address: 1052 St. Laurent Blvd, Ottawa, ON
Approx Center: -75.6392004,45.4269691

Order No: 24051600078

ERIS

250
Meters

Year: 1983
Source: NAPL
Scale: 10,000
Comment:

Address: 1052 St. Laurent Blvd, Ottawa, ON
Approx Center: -75.6392004,45.4269691

Order No: 24051600078

ERIS

APPENDIX K

Site Photographs

Photo 1 - Looking northwest towards the structure at 1052 St. Laurent Boulevard.

Photo 2 - Looking west towards the east building line of structure at 1052 St. Laurent Boulevard.

Photo 3 - Looking west inside the Pawn Shop located at 1052 St. Laurent Boulevard.

Photo 4 - Looking north towards a sump pit inside the basement of 1052 St. Laurent Boulevard.

Photo 5 - Looking east towards the natural gas meter for 1052 St. Laurent Boulevard.

Photo 6 - Looking west towards the west building line where two pipes (likely vent pipe and fill pipe) were located.

Photo 7 - Looking west towards the east building line of 1060 St. Laurent Boulevard.

Photo 8 - Looking east towards the parking area for 1060 St. Laurent Boulevard beyond which lies St. Laurent Boulevard and the commercial properties at 1021 St. Laurent Boulevard.

Photo 9 - Looking north and towards a monitoring well installed at the Site as part of GEMTEC's 2024 intrusive investigation.



Photo 10 - Looking west and an inside view of the restaurant at 1060 St. Laurent Boulevard.

Photo 11 - Looking west/southwest at the sump pit located in the basement of 1060 St. Laurent Boulevard.

Photo 12 - Looking east from between 1060 St. Laurent Boulevard and 1064 St. Laurent Boulevard. Natural gas meter for 1060 St. Laurent Boulevard is to the left.

Photo 13 - Looking northwest towards the automotive shop/garage at 1064 St. Laurent Boulevard.

Photo 14 - Looking north/northwest towards the catch basin at 1064 St. Laurent Boulevard.

Photo 15 - Looking southeast towards St. Laurent Boulevard.

Photo 16 - Looking west along St. Laurent Boulevard.

Photo 17 - Looking southeast towards the natural gas meter and air conditioning unit for 1064 St. Laurent Boulevard.

Photo 18 - Looking south along the western building line of 1064 St. Laurent Boulevard. Several tires were stored along the building line.

Photo 19 - Looking south/southeast towards the floor drains which discharge into the oil water separator at 1064 St. Laurent Boulevard.

Photo 20 - Looking south towards the west building line of 1064 St. Laurent Boulevard. Waste oil AST and work bench tank can be seen along the building line.

Photo 21 - Looking southwest towards the waste disposal area for 1064 St. Laurent Boulevard.

Photo 22 - Looking southeast towards the parking area for 1064 St. Laurent Boulevard.

Photo 23 - Looking northwest towards the commercial property located to the north of the Site at 1012 St. Laurent Boulevard.

Photo 24 - Looking east towards the St. Laurent Boulevard and the commercial properties located across ST. Laurent Boulevard.

experience • knowledge • integrity



civil	civil
geotechnical	géotechnique
environmental	environnement
structural	structures
field services	surveillance de chantier
materials testing	service de laboratoire des matériaux

expérience • connaissance • intégrité