September 4, 2026
File: PE5066-LET.06

Claridge Homes
210 Gladstone Avenue
Ottawa, Ontario
K2P 0Y6

PATERSON GROUP
Consulting Engineers
9 Auriga Drive
Ottawa, Ontario
K2E 7T9
Tel: (613) 226-7381

Geotechnical Engineering
Environmental Engineering
Hydrogeology
Materials Testing
Building Science
Rural Development Design
Temporary Shoring Design
Retaining Wall Design
Noise and Vibration Studies

patersongroup.ca

Attention: **Victoria St. Pierre**

Subject: **Phase I - Environmental Site Assessment Update**
Part of 1500 Merivale Road
Ottawa, Ontario

Further to your request, Paterson Group (Paterson) conducted a Phase I - Environmental Site Assessment (Phase I ESA) Update for part of 1500 Merivale Road, in the City of Ottawa (Phase I ESA Property). This updates previous Phase I ESAs conducted for the Phase I ESA and is intended to meet the requirements of a Phase I ESA Update, as per the Ministry of the Environment, Conservation and Parks (MECP) Standard Ontario Regulation (O.Reg.) 153/04: Records of Site Condition, as amended, under the Environmental Protection Act. This report is to be read in conjunction with the previous reports.

Site Information

The Phase I ESA Property is located on the south side of Baseline Road, approximately 150 m east of the Clyde Avenue and Baseline Road intersection, in the City of Ottawa, Ontario, which is shown on Figure 1 - Key Plan, following the body of this report.

The Phase I ESA Property is situated in an urban setting consisting of commercial land uses. The western portion of the Phase I ESA Property addressed 1380 Baseline Road is currently occupied by an automotive repair shop. The central portion addressed 1374 Baseline Road is currently occupied by a single storey restaurant building. The remainder the Phase I Property is used as a parking lot or is vacant.

Previous Engineering Reports

The following reports were reviewed prior to conducting this assessment:

- ❑ "Phase I Environmental Site Assessment, 1468, 1476, 1476A, 1478, 1490, 1492 and 1500 Merivale Road and 1366, 1380 and 1386 Baseline Road, Ottawa, Ontario", prepared by Pinchin Environmental Limited (Pinchin), November, 2012.

Pinchin completed a Phase I ESA on a larger parcel, which included the current Phase I property November 2012. Pinchin identified fifteen (15) APECs on the larger parcel, one of which is present on the current Phase I property. . Based on the results of the Phase I ESA Pinchin determined that a Phase II ESA should be conducted.

- ❑ "Phase II Environmental Site Assessment, Merivale and Baseline Road, Ottawa, Ontario", prepared by Pinchin, January 2014.

Based on the recommendations made in the Phase I ESA and the presence of fifteen APECs on the on the larger parcel, a Phase II ESA was conducted between March 2013 and January 2014. Five boreholes, including two monitoring wells were installed on the current Phase I property. No impacted soil or groundwater was identified on the Phase I property. 'Phase I Environmental Site Assessment, 1500 Merivale Road, Ottawa Ontario', prepared by Paterson Group, dated August 1, 2017.

The Phase I ESA was carried out for a larger parcel of land that includes the Phase I Property. Based on the findings of the Phase I ESA, two APECs were identified on the Phase I Property. These APECs are listed as follows:

APEC #1 – An existing automotive service garage (1380 Baseline Road), located in the western portion of the Phase I Property.

APEC #2 – Fill material of unknown quality, located within the Phase I Property.

Based on the findings of the assessment, a Phase II ESA was recommended to assess the aforementioned APECs. The 2017 Phase I ESA also identified PCAs within the Phase I study area but were deemed not to pose a potential environmental concern due to their distance or their cross or down-gradient orientation to the Phase I Property.

- ❑ 'Phase I Environmental Site Assessment, 1374 Baseline Road, Ontario', prepared by CIMA+, dated October 2019.

  The Phase I-ESA identified the following potential environmental concerns:

  - ❒ The presence of on-site fill material of unknown quality and the use of salt during snow clearing in the parking lot;
  - ❒ The service garage located on 1366 Baseline Road;

- ❒ The use of salt during snow clearing on the Phase I Property and Baseline Road.

Based on the presence of these potential environmental concerns, it was recommended that a Phase II-ESA be conducted

- ❑ 'Phase II Environmental Site Assessment, 1374 Baseline Road, Ontario', prepared by Patersom, dated November 28, 2019.

  Four boreholes (BH1 through BH4), including three monitoring wells were drilled to assess the previously identified APECs.On November 5, 2019.

  Five soil samples were submitted for laboratory analysis of petroleum hydrocarbons (PHCs), sodium adsorption ratio, electrical conductivity and metals. No detectable PHC (F2-F4) concentrations were identified in the soil sample analysed. PHC F1 and BTEX was not analysed as part of the sampling program. All detected metal and PAH parameter concentrations comply with the MECP Table 7 standards. The sodium adsorption ratio identified in the soil samples analysed complies with the MECP Table 7 standards. The electrical conductivity identified in the soil sample analysed from BH2 was in excess of the MECP Table 7 standards. The electrical conductivity identified in the soil samples analysed from BH3 and BH4 complies with the MECP Table 7 standards.

  Groundwater samples were collected from the monitoring wells installed in BH1, BH2 and BH3 on November 14, 2019. The water samples were submitted for a combination of the following parameters: PHC (F1-F4), BTEX, chlorides, metals or PAHs. No unusual visual or olfactory observations were noted regarding the groundwater obtained from any of the boreholes.

  No detectable BTEX, PHC or PAH concentrations were identified in the groundwater samples analysed. The detected metal and chloride concentrations identified in the groundwater samples analysed comply with the MECP Table 7 standards.

- ❑ "Phase I Environmental Site Assessment Update, 1500 Merivale Road, Ottawa, Ontario", prepared by Paterson Group, November 1, 2022.

  The Phase I ESA was conducted for a large piece of land including the Phase I Property. The Phase I ESA Update confirmed the findings of the 2017 Phase I ESA. The Phase I Property had not changed significantly since the time of the 2017 Phase I ESA and no new environmental

Historical Review and Records Update

Ministry of the Environment, Conservation and Parks (MECP) Instruments

A request was submitted to the MECP Freedom of Information (FOI) office for information with respect to certificates of approval, permits to take water, certificates of property use or any other similar MECP issued instruments for the Phase I Property. A response from the MECP had not been received prior to the issuance of this report.

Based on a review of the ERIS report, no significant new information is expected within the FOI submission.

MECP Submissions

A request was submitted to the MECP FOI office for information with respect to reports related to environmental conditions for the Phase I Property. At the time of issuance of this report, a response from the MECP had not been received. A copy of the response will be forwarded to the client, should it contain any pertinent information.

Based on a review of the ERIS report, no significant new information is expected within the FOI submission.

MECP Incident Reports

A request was submitted to the MECP FOI office for information with respect to records concerning environmental incidents, orders, offences, spills, discharges of contaminants or inspections maintained by the MECP for the site or adjacent properties. At the time of issuance of this report, a response from the MECP had not been received. A copy of the response will be forwarded to the client, should it contain any pertinent information.

Based on a review of the ERIS report, no significant new information is expected within the FOI submission.

MECP Waste Management Records

A request was submitted to the MECP FOI office for information with respect to waste management records. At the time of issuance of this report, a response from the MECP had not been received. A copy of the response will be forwarded to the client, should it contain any pertinent information.

Based on a review of the ERIS report, no significant new information is expected within the FOI submission.

MECP Brownfields Environmental Site Registry

A search of the MECP Brownfields Environmental Site Registry was conducted as part of this assessment. No Records of Site Condition (RSCs) were identified in the database for the Phase I-ESA Property.

Two RSCs were identified for properties situated within the Phase I Study Area:

- *1357 Baseline Road (RSC #66519 – December 2009)*

According to the RSC, approximately 360 m^3 of contaminated soil and 15,700 L of contaminated groundwater was removed from this property as part of a remediation program, conducted in tandem with site redevelopment activities in 2009. Based on its separation distance (230 m northwest), as well as its cross-gradient orientation with respect to anticipated groundwater flow to the east, this property is not considered to pose an environmental concern to the Phase I-ESA Property.

- *1460 Merivale Road (RSC#2181 – September 2005)*

According to the RSC, approximately 550 m^3 of contaminated soil and 8,000 L of contaminated groundwater was removed from this property as part of a petroleum storage tank removal in 2005.

The specific location of the tank removal program was not identified in the RSC, however, based on aerial photographs from the time of the tank removal program, it is our opinion that the tank was located on the northernmost portion of the 1460 Merivale Road property (former retail fuel outlet), approximately 305 m northeast of the Phase I-ESA Property (outside of the Phase I Study Area). As a result, the retail fuel outlet on the northernmost portion of the 1460 Merivale Road property has not been considered a PCA as part of this assessment.

Technical Standards and Safety Authority (TSSA)

The TSSA Fuels Safety Branch in Toronto was contacted electronically as part of this assessment, to inquire about current and former fuel storage tanks, spills, and historical incidents for the Phase I-ESA Property as well as the neighbouring properties within the Phase I Study Area.

The response from the TSSA indicated that no records were identified associated with the Phase I-ESA Property. A total of sixteen (16) records were identified on the property addressed 1460 Merivale Road. These records pertain to the gas station that is located approximately 185 m to the east of the Phase I Property. Due to its separation distance , this property is not considered to pose a potential environmental concern to the Phase I Property. A copy of the correspondence with the TSSA is included in Appendix 2.

City of Ottawa Historical Land Use Inventory (HLUI)

A requisition was sent to the City of Ottawa's Historical Land Use Inventory (HLUI 2005) as part of the 2022 Phase I ESA Update for the larger 1500 Merivale Road property. The HLUI response from the 2022 Phase I-ESA Update was reviewed as part of this assessment. One historical activity was identified for the Phase I-ESA Property, and it pertains to the existing auto repair shop that is located at 1380 Baseline Road.

A total of 99 activities were identified for properties within the Phase I Study Area. The off-site PCAs identified during the review of the HLUI response within the Phase I Study Area are summarized in Table 3.

Table 3 – Potentially Contaminating Activities
City of Ottawa Historical Land Use Inventory (HLUI) Search Results

Address	Potentially Contaminating Activity (years listed in HLUI database)	Distance / Orientation from Site	Area of Potential Environmental Concern (Y/ N)
1380 Baseline Road (now part of 1500 Merivale Road)	Existing Automotive Service Garage (1990-2017)	On-Site	Y
1480 Merivale Road	Former Automotive Service Garage (1970-1980)	145 m South	N
1486 Merivale Road	Former Automotive Service Garage (1960-2017)	155 m South	N
8-10 Kimway Crescent (now part of 1500 Merivale Road)	Former Machine Shop (1965)	85 m South	N
1464 Merivale Road (now part of 1500 Merivale Road)	Former Dry Cleaner (1960-1980)	85 m South	N
1468 Merivale Road (now part of 1500 Merivale Road)	Former Retail Fuel Outlet (1990)	85 m South	N
1490 Merivale Road (now part of 1500 Merivale Road)	Former Transport Office with One Associated UST (1956-1965)	140 m South	N
1377 Clyde Avenue	Existing Automotive Service Garage and Private Fuel Outlet (1970-2017)	75 m Southwest	N
1375 Clyde Avenue	Former Retail Fuel Outlet and Automotive Service Garage (1960-2004)	65 m Southwest	N
1453 Merivale Road	Existing Automotive Service Garage (2001-2017) and Former Retail Fuel Outlet (1961-1998)	190 m Southeast	N
1432 Baseline Road	Former Automotive Service Garage (1960-1970) and Existing Retail Fuel Outlet (1960-2017)	100 m West	N
1357 Baseline Road	Former High School with One Associated UST (N/L)	40 m North	N

Notes:
- N/L – years not listed in HLUI database

The remaining records identified in the HLUI response are not considered to represent potential environmental concerns based on the listed property uses and/or the separation distance to the Phase I-ESA Property.

The current automotive service garage that is located at the western portion of the Phase I Property addressed 1380 Baseline Road identified during the review of the HLUI response, is considered to represent an APEC on the Phase I-ESA Property. The remaining PCAs identified during the review of the HLUI response are not considered to represent APECs on the Phase I-ESA Property based on their respective separation distances and/or down- or cross- gradient orientations with respect to the Phase I-ESA Property.

It should be noted that civic addresses have changed over the years and those listed above may not currently exist. The respective distances of the above noted activities from the Phase I-ESA Property were determined using FIPs and the City of Ottawa electronic mapping website.

A copy of the HLUI response is provided in Appendix 2.

Environmental Risk Information Service (ERIS) Report

An Environmental Risk Information Services (ERIS) report, dated February 20, 2026, was acquired for the Phase I-ESA Property and reviewed as part of this assessment. The ERIS report includes information that would normally be obtained through the MECP FOI, MECP well records search as well as several other records (i.e., incident reports, waste generators, etc.). The complete ERIS report has been included in Appendix 2.

- *On-Site Records:*

Although the ERIS Report indicates that there are twenty-six (26) records on the Phase I-ESA Property, only five records fall within the Phase I Property. Two records of monitoring wells were identified on the Phase I Property. These well records are associated with the previous investigations that have been conducted on the Phase I-ESA Property and are not considered to be representative of a new environmental concern. Two ERIS Historical Searches were also identified on the Phase I Property. One borehole record was also identified on the Phase I Property.

A certificate of approval, dated April of 1998, was identified for the Phase I-ESA Property pertaining to an approval for municipal sewage works. This certificate of approval is not considered to represent an environmental concern.

- *Off-Site Records:*

A total of 336 records from various databases were identified for surrounding properties within a 250m radius of the Phase I-ESA Property (18 of which are previous ERIS searches).

The ERIS report identified 101 Waste Generator records for properties within the Phase I Study Area, several of which are associated with the property addressed 1460 Merivale Road, approximately 60 m north of the Phase I-ESA Property and its former/existing function as a grocery store, dental centre and retail store. Although there are waste generator records associated with the existing multi-use commercial building on the 1460 Merivale Road property, it is our opinion that this property does not represent an environmental concern to the Phase I-ESA Property.

The ERIS report identified many records for current fuel oil tanks, historic fuel oil tanks, historic fuel outlets and existing fuel outlets. All of which are associated with previously identified historic/existing automotive service garages and/or retail fuel outlets. As a result, no additional PCAs were identified during the review of the ERIS report with regard to the fuel storage and fuel outlet records.

The ERIS report identified additional waste generator records and various fuel storage tank and fuel outlet records for the property addressed 1460 Merivale Road (associated with an existing retail fuel outlet). The 1460 Merivale Road property is located immediately east of the Phase I-ESA Property, however, based on aerial photographs and FIPs from the dates listed in the associated records, the retail fuel outlet on the northernmost portion of the 1460 Merivale Road property was located approximately 260 m east of the Phase I-ESA Property, outside of the Phase I Study Area for this assessment. As a result, the retail fuel outlet on the northernmost portion of the 1460 Merivale Road property has not been considered a PCA as part of this assessment.

The ERIS report identified Ontario spill, fuel oil spills and leaks and pipeline incident records for properties within the Phase I Study Area. The spill and incident records consist of minimal (or unknown quantities of) leaks/spills of hydraulic oil, heating oil, natural gas, diesel, refrigerant gas, cooking oil, gasoline and/or motor oil, occurring at properties a minimum of 60 m from the Phase I-ESA Property. Based on the listed description of the spills and incidents (minimal quantity and/or not a substance of concern), the respective separation distance, the down/cross-gradient orientation with respect to the anticipated groundwater flow to the southeast and/or the unknown specific location, these records are not considered to pose an environmental concern to the Phase I-ESA Property. Moreover, the majority of the spill and incident records that list diesel, gasoline, and/or motor oil, pertain to former/existing automotive service garages or retail fuel outlets previously identified as PCAs throughout this assessment.

Based the ERIS report, no other PCAs were identified within the Phase I Study Area.

MECP Water Well Records

A search of the MECPs website was conducted on March 15, 2024, for all drilled well records within a 250 m radius of the Phase I-ESA Property. Two well records were identified for the Phase I-ESA Property.

All of which pertain to monitoring wells installed in 2020. These well records are associated with the previous investigations that have been conducted on the Phase I-ESA Property and are not considered to be representative of a new PCA.

The search identified 42 well records for surrounding properties within the Phase I Study Area, they pertain to monitoring wells and domestic/commercial water supply wells. The records for the domestic/commercial supply wells indicate that they were all installed in 1961 or earlier. Based on the significant development within the Phase I Study Area since the installation of the domestic/commercial supply wells and the presence of City of Ottawa municipal water services within the Phase I Study Area, it is our opinion that domestic supply wells are no longer in use by properties within the Phase I Study Area.

The remaining well records identified within the Phase I Study Area pertain to well abandonment records or contain no pertinent information. The remaining well records contain no pertinent information besides that they were installed in

Based on the reviewed well records, overburden in the vicinity of the Phase I-ESA Property consists of clay and/or sand with boulders. Bedrock consisting of limestone, was generally encountered at an average depth of approximately 5.5 to 11.3 m below ground surface. The aforementioned well records are provided in Appendix 2.

Aerial Photographs

The latest aerial photograph reviewed as part of the 2022 Phase I ESA Update was from 2019. A review of the 2022 aerial photograph shows no significant changes to the Phase I Property since the 2019 aerial photograph. Surrounding properties remain largely unchanged since the time of the 2019 aerial photograph with the exception of a property northwest of the Phase I property appears to consist of an early construction staging area associated with the development of the property. A copy of the 2022 aerial photograph has been appended to this report.

Property Owner Representative Interview

The tenant of 1380 Baseline Road was available to answer questions during the site visit. He mentioned that the property is used for car maintenance. He indicated that the waste oil is collected and sent to Mr. Lube regularly and no waste oil storage is taking place on the Phase I Property.

The tenant of 1374 Baseline Road was available to answer questions during the site visit. He indicated that this property has always been used as a restaurant and he was not aware of any potential environmental concerns on this portion of the Phase I Property.

Site Reconnaissance

One site visit was conducted on March 12, 2026. Mr. Mohammed Ramadan from the Environmental Department of Paterson Group conducted the site inspection. In addition to the site, the uses of neighbouring properties within the Phase I Study Area were also assessed at the time of the site visits.

Exterior Assessment

The parcel that is part of 1500 Merivale Road (eastern and southern portions of the Phase I Property) is vacant undeveloped land with trees and vegetation covering the site surface.

The parcel addressed 1380 Baseline Road is occupied by a single-storey auto repair garage. The building, constructed in the 1990s, has a poured concrete foundation and is finished on the exterior with concrete blocks, in addition to a flat tar and gravel roof. The building is heated and cooled via natural gas-fired roof top units.

The parcel addressed 1374 Baseline Road is occupied by a single-storey restaurant with a full basement level. The northern portion of the building was constructed in 1958 while an addition south of the original building was constructed in 1985. The building has a poured concrete foundation and is finished on the exterior with stucco, in addition to a flat tar and gravel roof on the southern portion of the building and sloped asphalt shingle roof on the northern portion of the building. The building is heated via natural gas-fired furnace located in the basement of the building.

Site drainage consists of infiltration and sheet flow to catch basins located in the on-site parking lot and adjacent roadways. The site topography sloped down to the south, while the regional topography slopes down to the southwest.

No evidence of underground storage tanks (USTs), aboveground storage tanks (ASTs) or chemical storage was observed on the exterior of the Phase I Property at the time of the site inspection.

No environmental concerns were noted with respect to waste management practices on the Phase I Property. Used tires and miscellaneous items were observed to be stored in the southern portion of the property addressed 1380 Baseline Road.

No underground structures, drains, pits or sumps were observed on the exterior of the Phase I Property at the time of the site visit.

No evidence of current or former railway or spur lines was observed on the Phase I Property at the time of the site visit. The above-noted site features are shown on Drawing PE5066-1 - Site Plan.

Interior Assessment

1380 Baseline Road

A general assessment of the interior of the subject building is as follows:

- ❑ The floors throughout consisted of ceramic tiles and concrete;
- ❑ The walls consisted of concrete or drywall;
- ❑ The ceilings consisted of suspended tiles, drywall and/or plaster;
- ❑ Lighting throughout the building was provided by LED and incandescent fixtures.

Hazardous Building Materials

Based on the age of the subject building (c. 1990s), asbestos-containing materials are not expected to be present within the subject building.

Based on the age of the subject building (c. 1990s), lead-based paints are not expected to be present within the subject building.

Based on the age of the subject building (c. 1990s), UFFIs are not expected to be present within the subject building.

Other Potential Environmental Concerns

- ❑ **Fuels and Chemical Storage**

  Several new motor oil products were observed within the subject building. No staining was observed around those products.

  Chemical products observed inside the garage appeared to be limited to domestically available oil products, greases, and lubricants stored properly in their original containers.

  Several spill stains were observed within the subject building at the time of the site inspection.

- ❑ **Wastewater Discharges**

  Wastewater from the subject buildings, consisting of wash water and sewage, is discharged into the City of Ottawa sanitary sewer system. No environmental concerns were identified with respect to wastewater discharges at the Phase I Property at the time of the site inspection.

A floor drain leads to the oil/water separator was observed in the Phase I Property at the time of the site visit. No water was observed in the floor drain, and the oil/water separator was not accessible at the time of the site visit.

- **Ozone Depleting Substances (ODSs)**

  Potential sources of ODSs observed in the subject building include fire extinguishers, several refrigerators, a commercial sized freezer, and air conditioning units. These appliances appeared to be in good condition at the time of the site inspection and should be regularly serviced by a license contractor.

1374 Baseline Road

A general assessment of the interior of the subject building is as follows:

- The floors throughout consisted of hardwood, ceramic tiles and concrete;
- The walls consisted of concrete or drywall;
- The ceilings consisted of suspended tiles, drywall and/or plaster;
- Lighting throughout the building was provided by LED and incandescent fixtures.

Hazardous Building Materials

Based on the age of the residential structure (c. 1958 and 1985), asbestos containing building materials may be present within the building. Potential ACMs observed at the time of the site inspection include drywall joint compound, stucco and the plaster finishes. These building materials were observed to be in good condition at the time of the site inspection and do not represent an immediate concern.

Based on the age of the subject building (c. 1958 and 1985), lead-based paints may be potentially present on any original or older painted surfaces. The painted surfaces within the buildings were generally observed to be in good condition at the time of the site inspection.

No signs indicating the presence of UFFI were observed during the site inspection. However, the wall cavities were not inspected to verify the insulation type.

Other Potential Environmental Concerns

- **Fuels and Chemical Storage**

  No aboveground fuel storage tanks or signs of underground fuel storage tanks were observed within any of subject buildings at the time of the site inspection.

Chemical products identified in the residential building were observed to be limited to domestically available cleaning products, stored properly in their original containers.

- **Wastewater Discharges**

  Wastewater from the residential building (wash water and sewage) is discharged into the City of Ottawa sanitary sewer system. Roof drainage is discharged via surface run-off towards catch basins located on Baseline Road, which drain into the City of Ottawa storm water sewer system and infiltration in the landscaped areas. No concerns were identified with respect to wastewater discharge on the Phase I Property.

- **Ozone Depleting Substances (ODSs)**

  Potential sources of ODSs observed in the subject building include fire extinguishers, several refrigerators, a commercial sized freezer, and air conditioning units. These appliances appeared to be in good condition at the time of the site inspection and should be regularly serviced by a license contractor.

Neighbouring Properties

An inspection of the neighbouring properties was conducted from publicly accessible roadways at the time of the site inspection. Land use adjacent to the Phase I Property was as follows:

- North – Baseline Road, followed by commercial retail plaza;
- South – Vacant land, followed by Merivale Road;
- East – Commercial retail plaza;
- West – Restaurant, followed by vacant lands and a retail fuel outlet.

The retail fuel outlet addressed 1432 Baseline Road (approximately 100 m west of the Phase I Property) and the auto repair garage addressed 1442 Baseline Road (approximately 160 m west of the Phase I Property) are not considered to pose a potential environmental concern to the Phase I Property. Current land use and PCAs identified within the Phase I Study Area are presented on Drawing PE5066-2 – Surrounding Land Use Plan, appended to this report.

Phase I Conceptual Site Model

Geological and Hydrogeological Setting

Based on the available mapping information, the bedrock within the area of the Phase I Property consists of interbedded limestone and dolomite of the Gull River Formation,

whereas the surficial geology consists of glacial till plains with an overburden thickness ranging from approximately 0 m to 10 m.

Based on the information obtained from previous subsurface investigations, the groundwater is anticipated to be encountered within the underlying bedrock unit and flow in a southeasterly direction towards the Rideau River.

Existing Buildings and Structures

The southern portion of the Phase I Property is vacant, with a one storey auto service garage and a one storey restaurant building located within the northern portion of the Phase I Property, adjacent to Baseline Road.

Water Bodies and Areas of Natural and Scientific Interest

No water bodies or areas of natural and scientific interest are known to exist within the Phase I study area. The nearest named water body with respect to the Phase I Property is the Rideau River, located approximately 2.6 km to the southeast.

Drinking Water Wells

Based on the availability of municipal services, no drinking water wells are expected to be currently in use within the Phase I study area.

Neighbouring Land Use

The neighbouring lands within the Phase I study area consist primarily of residential and commercial properties, with occasional community and institutional uses.

Potentially Contaminating Activities and Areas of Potential Environmental Concern

The PCAs considered to result in APECs on the Phase I Property have been summarized below.

APEC #1 – An existing automotive service garage (1380 Baseline Road), located in the western portion of the Phase I Property.

APEC #2 – Fill material of unknown quality, located within the Phase I Property.

Additional PCAs identified within the Phase I Study Area were identified as shown on Drawing PE5066-1 – Surrounding Land Use and are not considered to have the potential to impact the Phase I Property, based on their separation distance and/or down/cross-gradient orientation with respect to the Phase I Property.

Contaminants of Potential Concern (CPCs)

The following Contaminants of Potential Concern (CPCs) were identified with respect to the Phase II Property:

- ❒ Benzene, Toluene, Ethylbenzene, and Xylenes (BTEX);
- ❒ Petroleum Hydrocarbons, fractions 1 - 4 (PHCs F_1-F_4);
- ❒ Metals (including Mercury and Hexavalent Chromium).

These CPCs have the potential to be present in the soil matrix and/or the groundwater situated beneath the Phase I Property.

Underground Utilities

The Phase I Property is situated in a municipally serviced area. Underground utility services on the property include natural gas, water, hydro electric power and sewer services.

Assessment of Uncertainty and/or Absence of Information

The information available for review as part of the preparation of this Phase I-ESA Update is considered to be sufficient to conclude that there are APECs on the Phase I ESA Property. A variety of independent sources were consulted as part of this assessment, and as such, the conclusions of this report are not affected by uncertainty which may be present with respect to the individual sources.

Conclusions

A review of more recent historical information, in combination with personal interviews and a site inspection, generally confirmed the findings presented in the previous 2022 Phase I ESA Update. The Phase I Property has not changed significantly since the time of the previous 2022 Phase I ESA and no new environmental concerns were identified as part of this assessment. A Phase II ESA has been prepared under a separate cover for the Phase I ESA property.

Statement of Limitations

This Phase I - Environmental Site Assessment Update report has been prepared in general accordance with O.Reg. 153/04, as amended. The conclusions presented herein are based on information gathered from a historical review and field inspection program.

The findings of the Phase I ESA Update are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as local, provincial, and federal agencies and was limited within the scope-of-work, time, and budget of the project herein.

Should any conditions be encountered at the Phase I property and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Claridge Homes. Permission and notification from Claridge Homes and this firm will be required to release this report to any other party.

We trust that this submission satisfies your current requirements. Should you have any questions, please contact the undersigned.

Paterson Group Inc.





Michael Beaudoin, P.Eng., Q.P.ESA

Attachments:

- ❑ Figure 1 - Key Plan
- ❑ Aerial Photograph (2022)
- ❑ Drawing PE5066-1 - Site Plan
- ❑ Drawing PE5066-2 – Surrounding Land Use Plan
- ❑ TSSA Correspondence
- ❑ HLUI Response
- ❑ ERIS Report

1405 BASELINE ROAD
COMMERCIAL

1357 BASELINE ROAD
COMMERCIAL

1345 BASELINE ROAD
COMMERCIAL

BASELINE ROAD

ASPHALT CONCRETE
PARKING

APEC 2

1380 BASELINE ROAD
COMMERCIAL
(AUTO REPAIR GARAGE)

1374 BASELINE ROAD
COMMERCIAL
(RESTAURANT)

ASPHALT CONCRETE
PARKING

1384 BASELINE ROAD
COMMERCIAL

APEC 1

PART OF 1366 BASELINE ROAD
(UNDER CONSTRUCTION)

1375 CLYDE AVENUE
COMMERCIAL

TREED

TREED

1460 MERIVALE ROAD
COMMERCIAL

1366 BASELINE ROAD
TREED

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN :

ID #	PCA ID	DESCRIPTION
1	30	FILL MATERIAL OF UNKNOWN QUALITY
2	28	AUTO REPAIR GARAGE

LEGEND:

PHASE I, II AND RSC PROPERTY BOUNDARY

SCALE: 1:750

0 10 20 30 50m

PATERSON GROUP
9 AURIGA DRIVE
OTTAWA, ON
K2E 7T9
TEL: (613) 226-7381

NO.	REVISIONS	DATE	INITIAL

CLARIDGE HOMES

PHASE I - ENVIRONMENTAL SITE ASSESSMENT
1380, 1374 BASELINE ROAD, AND PARTS OF 1366 BASELINE ROAD
OTTAWA, ONTARIO


Title:

SITE PLAN

Scale: 1:750	Date: 04/2026
Drawn by: GK	Report No.: PE5066-1
Checked by: MR	Dwg. No.: PE5066-19
Approved by: MSD	Revision No.:

11x17

p:\autocad drawings\environmental\pe50xx\pe5066\pe5066-19 site plan.dwg



POTENTIALLY CONTAMINATING ACTIVITIES :

ID #	PCA ID	ADDRESS	DESCRIPTION
1	30	ON-SITE	FILL MATERIAL OF UNKNOWN QUALITY
2	52	ON-SITE	AUTO REPAIR SHOP
3	28	1383 CLYDE AVENUE	FORMER IBM PRINTERS
4	30	1377 CLYDE AVENUE	AUTOMOTIVE SERVICE GARAGE
5	30	1432 BASELINE ROAD	RETAIL FUEL OUTLET
6	30	1442 BASELINE ROAD	FORMER RETAIL FUEL OUTLET
7	28	1308 BASELINE ROAD	RETAIL FUEL OUTLET
8	30	450 MERIVALE ROAD	FORMER GARAGE
9	N/A	1482 MERIVALE ROAD	FORMER GARAGE AND SERVICE STATION
10	30	1486 MERIVALE ROAD	FORMER SERVICE GARAGE AND SWAN'S GARAGE
11	52 / 28	1375-1377 CLYDE AVE.	EXISTING AUTOMOTIVE SERVICE GARAGE & PRIVATE FUEL OUTLET
12	30	ON-SITE	FORMER POSSIBLE AUTOMOTIVE SERVICE GARAGE
13	28	ON-SITE	FORMER HEATING OIL UNDERGROUND STORAGE TANK
14	N/A	8-10 KIMWAY CRES.	FORMER MACHINE SHOP
15	28	1464-1468 MERIVALE ROAD	FORMER RETAIL FUEL OUTLET AND FORMER DRY CLEANERS
16	28	1492 MERIVALE RD.	FORMER TRANSPORT OFFICE WITH ONE ASSOCIATED UNDERGROUND STORAGE TANK
17	28 / N/A	1357 BASELINE RD.	FORMER HIGH SCHOOL WITH AN ASSOCIATED UNDERGROUND STORAGE TANK AND KNOWN IMPACTED SOIL AND GROUNDWATER

PATERSON GROUP
9 AURIGA DRIVE
OTTAWA, ON
K2E 7T9
TEL: (613) 226-7381

NO.	REVISIONS	DATE	INITIAL

CLARIDGE HOMES

PHASE I - ENVIRONMENTAL SITE ASSESSMENT
1380, 1374 BASELINE ROAD, AND PARTS OF 1366 BASELINE ROAD
OTTAWA, ONTARIO

Title:

SURROUNDING LAND USE PLAN

Scale: 1:750	Date: 04/2026
Drawn by: GK	Report No.: PE5066-1
Checked by: MR	Dwg. No.: PE5066-20
Approved by: MSD	Revision No.:

11x17

p:\autocad drawings\environmental\pe50xx\pe5066\pe5066-20 surrounding land use plan.dwg




FIGURE 1

KEY PLAN

PATERSON GROUP



AERIAL PHOTOGRAPH
2019

PATERSON GROUP

DATABASE REPORT

Project Property:	*Phase I ESA* *1500 Merivale Road* *Nepean ON K2C 0A9*
Project No:	*P.O. 65179/PE5066*
Report Type:	*Standard Report*
Order No:	*26022000176*
Requested by:	*Paterson Group Inc.*
Date Completed:	*February 20, 2026*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....10
Executive Summary: Summary By Data Source.....35
Map.....66
Aerial.....67
Topographic Map.....68
Detail Report.....69
Unplottable Summary.....354
Unplottable Report.....358
Appendix: Database Descriptions.....404
Definitions.....415

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*Phase I ESA* *1500 Merivale Road Nepean ON K2C 0A9*
Project No:	*P.O. 65179/PE5066*

Coordinates:

Latitude:	*45.3619654*
Longitude:	*-75.7369652*
UTM Northing:	*5,023,425.58*
UTM Easting:	*442,282.76*
UTM Zone:	*18T*

Elevation: *328 FT*
99.91 M

Order Information:

Order No:	*26022000176*
Date Requested:	*February 20, 2026*
Requested by:	*Paterson Group Inc.*
Report Type:	*Standard Report*

Historical/Products:

ERIS Xplorer *ERIS Xplorer*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Within 0.25 km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	3	3
CA	Certificates of Approval	Y	1	4	5
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	21	21
EASR	Environmental Activity and Sector Registry	Y	1	3	4
EBR	Environmental Registry	Y	1	0	1
ECA	Environmental Compliance Approval	Y	1	5	6
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	4	16	20
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EOR	Environmental Offenders Registry	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
ESNR	Excess Soil Registry	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	18	18
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	11	11
FSTH	Fuel Storage Tank - Historic	Y	0	6	6
GEN	Ontario Regulation 347 Waste Generators Summary	Y	5	96	101
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0

Database	Name	Searched	Project Property	Within 0.25 km	Total
HBAR	Historical Business Activity Risk	Y	0	2	2
HINC	TSSA Historic Incidents	Y	0	0	0
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	3	3
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NOC	Notice of Contamination List	Y	0	0	0
NPCB	National PCB Inventory	Y	1	0	1
NPR2	National Pollutant Release Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory - Historic	Y	0	0	0
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	49	49
PFAS	Ontario PFAS Spills	Y	0	0	0
PFCH	NPRI Reporters - PFAS Substances	Y	0	0	0
PFHA	Potential PFAS Handlers from NPRI	Y	0	0	0
PINC	Pipeline Incidents	Y	0	1	1
PPHA	Potential PFAS Handlers from EASR	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	0	10	10
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	1	0	1
RSC	Record of Site Condition	Y	0	2	2
RST	Retail Fuel Storage Tanks	Y	0	10	10
SCT	Scott's Manufacturing Directories	Y	1	4	5
SPL	Ontario Spills	Y	0	19	19
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0

Database	Name	Searched	Project Property	Within 0.25 km	Total
VAR	***Variances for Abandonment of Underground Storage Tanks***	*Y*	*0*	*0*	*0*
WDS	***Waste Disposal Sites - MOE CA Inventory***	*Y*	*0*	*0*	*0*
WDSH	***Waste Disposal Sites - MOE 1991 Historical Approval Inventory***	*Y*	*0*	*0*	*0*
WMS	***Waste Management Site***	*Y*	*0*	*0*	*0*
WWIS	***Water Well Information System***	*Y*	*10*	*32*	*42*
		Total:	*26*	*315*	*341*

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
12	CA	CTVGlobemedia Inc.	1500 Merivale Rd Ottawa ON	SSW/131.8	-1.03	69
12	EASR	CLARIDGE HOMES (BASELINE PAHSE 1) LIMITED PARTNERSHIP	1500 Merivale RD Ottawa ON K2C 0A9	SSW/131.8	-1.03	69
12	EBR	CTVGlobemedia Inc.	1500 Merivale Road Ottawa K2E 6Z5 CITY OF OTTAWA ON	SSW/131.8	-1.03	69
12	ECA	CTVGlobemedia Inc.	1500 Merivale Rd Ottawa ON K2E 6Z5	SSW/131.8	-1.03	70
12	EHS		1500 Merivale Road Ottawa ON	SSW/131.8	-1.03	70
12	EHS		1500 Merivale Road Nepean ON K2E 6Z5	SSW/131.8	-1.03	70
12	EHS		1490 and 1500 Merivale Road Nepean ON K2E 6Z5	SSW/131.8	-1.03	70
12	GEN	NATION'S CAPITAL TELEVISION INCORPORATED	CJOH-TV 1500 MERIVALE ROAD NEPEAN ON K2E 6Z5	SSW/131.8	-1.03	71
12	GEN	NATION'S CAPITAL TELEVISION INC. 28-832	CJOH-TV 1500 MERIVALE ROAD NEPEAN ON K2E 6Z5	SSW/131.8	-1.03	71

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
12	GEN	Aim Group	1500 Merivale Ottawa ON	SSW/131.8	-1.03	71
12	GEN	Aim Environmental Group	1500 Merivale Road Ottawa ON	SSW/131.8	-1.03	72
12	GEN	Aim Environmental Group	1500 Merivale Road Ottawa ON	SSW/131.8	-1.03	72
12	NPCB	CJOH TV	1500 MERIVALE RD. OTTAWA ON	SSW/131.8	-1.03	72
12	REC	BBS ONTARIO INCORPORATED	CJOH-TV 1500 MERIVALE ROAD NEPEAN ON K2E 6Z5	SSW/131.8	-1.03	72
12	SCT	Warrenty Communications Inc.	1500 Merivale Rd Ottawa ON K2E 6Z5	SSW/131.8	-1.03	73
27	WWIS		1500 MERIVALE RD. Ottawa ON ***Well ID:*** 7207631	SE/183.2	-1.34	73
34	EHS		Part of 1500 Merivale Road Nepean ON K2E 6Z5	SE/190.2	-1.03	76
35	WWIS		1500 MERRIVALE RD. ON ***Well ID:*** 7053696	SE/191.1	-1.03	77

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
40	WWIS		1500 MERIVALE RD. Ottawa ON ***Well ID:*** 7207634	SE/200.2	-1.03	80
43	WWIS		1500 MERIVALE RD. ON ***Well ID:*** 7207630	SE/202.1	-1.34	83
49	WWIS		1500 MERIVALE RD. Ottawa ON ***Well ID:*** 7207632	SE/209.3	-1.03	87
50	WWIS		1500 MERIVALE ROAD Ottawa ON ***Well ID:*** 7207637	SSW/210.0	-1.03	90
51	WWIS		1500 MERIVALE RD OTTAWA ON ***Well ID:*** 7210900	SSE/210.4	-1.03	93
57	WWIS		1500 MERIVALE RD. Ottawa ON ***Well ID:*** 7207633	SE/213.5	-1.03	96
58	WWIS		1500 MERIVALE RD OTTAWA ON ***Well ID:*** 7210888	SE/214.2	-1.03	99
70	WWIS		1500 MERIVALE RD. Ottawa ON ***Well ID:*** 7207636	S/244.6	-1.03	102

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	WWIS		ON **Well ID:** 7362775	NNW/16.8	-0.03	106
2	EHS		1374 Baseline Rd Ottawa ON K2C0A9	NNW/30.2	-0.03	106
2	EHS		1374 Baseline Road Ottawa ON K2C 0A9	NNW/30.2	-0.03	107
3	EHS		Kimway Cres Ottawa ON	SE/42.9	-1.09	107
4	WWIS		lot 35 con A ON **Well ID:** 1504614	WSW/62.0	-0.03	107
5	CA	TDL GROUP LIMITED	1384 BASELINE ROAD (SWM) OTTAWA ON K2C 0A9	WSW/71.4	-0.03	110
6	BORE		ON	W/72.2	-0.03	110
7	WWIS		ON **Well ID:** 1507864	W/72.2	-0.03	111
8	GEN	Capital Dentistry Group Ltd.	1365 Baseline Road Ottawa ON	NNW/94.0	-0.03	114
9	WWIS		ON **Well ID:** 1507863	W/103.0	-0.03	115
10	ECA	Smart (Ottawa SW Senior Residences) PropCo GP Inc. as general partner for and on	behalf of Ottawa SW PropCo LP 1357 Baseline Rd Ottawa ON L4K 5Z5	N/124.0	-0.03	118
10	EHS		1357 Baseline Road Ottawa ON K2C 0A8	N/124.0	-0.03	118

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	GEN	OTTAWA BOARD OF EDUCATION	LAURENTIAN HIGH SCHOOL, 1357 BASELINERD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8	N/124.0	-0.03	118
10	GEN	THE OTTAWA BOARD OF EDUCATION	LAURENTIAN HIGH SCHOOL,1357 BASELINE RD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8	N/124.0	-0.03	119
10	GEN	OTTAWA BOARD OF EDUCATION	LAURENTIAN HIGH SCHOOL 1357 BASELINE ROAD OTTAWA ON K2C 0A8	N/124.0	-0.03	119
10	GEN	THE OTTAWA BOARD OF EDUCATION 29-550	LAURENTIAN HIGH SCHOOL,1357 BASELINE RD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8	N/124.0	-0.03	120
10	GEN	OTTAWA-CARLETON DISTRICT SCHOOL BOARD	LAURENTIAN HIGH SCHOOL 1357 BASELINE ROAD OTTAWA ON K2C 0A8	N/124.0	-0.03	121
10	GEN	Ottawa-Carleton District School Board	Laurention H.S. Public School 1357 Baseline Road Ottawa ON K2C 0A8	N/124.0	-0.03	122
10	GEN	OTTAWA-CARLETON DISTRICT SCHOOL BOARD	1357 BASELINE ROAD OTTAWA ON	N/124.0	-0.03	122
10	GEN	CLYDESDALE SHOPPING CENTERS LTD	1357 BASELINE ROAD OTTAWA ON	N/124.0	-0.03	124
10	RSC	Clydesdale Shopping Centres Limited	1357 BASELINE RD ON OTTAWA ON	N/124.0	-0.03	124
10	SPL	OTTAWA BOARD OF EDUCATION	1357 BASELINE ROAD OTTAWA CITY ON K2C 0A8	N/124.0	-0.03	124
10	SPL	Walmart Canada Corp.	1357 Baseline Rd Ottawa ON	N/124.0	-0.03	125
11	BORE		ON	W/124.3	-0.72	126

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
13	EHS		1365 -1385 Baseline Road Ottawa ON	NW/145.1	-0.03	127
14	CA	Loblaw Properties Limited	1460 Merivale Road Ottawa ON	ENE/145.2	-1.03	128
14	CA	Loblaw Properties Limited	1460 Merivale Road Ottawa ON	ENE/145.2	-1.03	128
14	DTNK	MAC'S CONVENIENCE STORES INC**	1460 MERIVALE RD NEPEAN ON K2E 5P2	ENE/145.2	-1.03	128
14	DTNK	SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON K2E 5P2	ENE/145.2	-1.03	129
14	DTNK	SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON K2E 5P2	ENE/145.2	-1.03	129
14	DTNK	SUNYS ENERGY INC ATTN RAFAH SHOOMAN	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	130
14	DTNK	SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	131
14	DTNK	SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	131
14	DTNK	SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	132
14	DTNK	SUNYS ENERGY INC ATTN RAFAH SHOOMAN	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	132
14	ECA	Loblaw Properties Limited	1460 Merivale Road Ottawa ON M4T 2S5	ENE/145.2	-1.03	133
14	ECA	Loblaw Properties Limited	1460 Merivale Road Ottawa ON L6Y 5S5	ENE/145.2	-1.03	133

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	EHS		1460 Merivale Road Ottawa ON	ENE/145.2	-1.03	134
14	EHS		1460 Merivale Rd Ottawa ON K2C 0A9	ENE/145.2	-1.03	134
14	EXP	SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	134
14	EXP	SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	134
14	EXP	SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	135
14	EXP	SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	135
14	EXP	SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	135
14	EXP	SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON	ENE/145.2	-1.03	135
14	FST	BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE/145.2	-1.03	136
14	FST	BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE/145.2	-1.03	136
14	FST	BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE/145.2	-1.03	136
14	FSTH	LOBLAW PROPERTIES LTD GASBAR DIV	1460 MERIVALE RD OTTAWA ON	ENE/145.2	-1.03	136
14	FSTH	LOBLAW PROPERTIES LTD AT THE PUMPS GASBAR DIV	1460 MERIVALE RD OTTAWA ON	ENE/145.2	-1.03	137

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	GEN	LOBLAWS SUPERMARKETS LTD. 24-850	1460 MERIVALE ROAD NEPEAN ON K2E 5P2	ENE/145.2	-1.03	137
14	GEN	LOBLAWS SUPERMARKETS LTD	1460 MERIVALE ROAD NEPEAN ON K2E 5P2	ENE/145.2	-1.03	137
14	GEN	LOBLAWS SUPERMARKETS LIMITED	1460 MERIVALE ROAD NEPEAN ON K2E 5P2	ENE/145.2	-1.03	138
14	GEN	SPORTS EXPERTS #51	1460 MERIVALE RD. NEPEAN ON K2E 5P2	ENE/145.2	-1.03	138
14	GEN	SPORTS EXPERTS #51 34-397	1460 MERIVALE RD. NEPEAN ON K2E 5P2	ENE/145.2	-1.03	139
14	GEN	SPORTS EXPERTS #51	1460 MERIVALE ROAD NEPEAN ON K2E 5P2	ENE/145.2	-1.03	139
14	GEN	SHOPPERS DRUG MART	1460 MERIVALE ROAD OTTAWA ON K2E 5P2	ENE/145.2	-1.03	139
14	GEN	SJL HOLDINGS LIMITED	1460 MERIVALE ROAD OTTAWA ON K2E 5N9	ENE/145.2	-1.03	140
14	GEN	FCR MANAGEMENT SERVICES	1460 MERIVALE ROAD OTTAWA ON K2E 5P2	ENE/145.2	-1.03	140
14	GEN	Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	141
14	GEN	Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	141
14	GEN	Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	143
14	GEN	Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	143

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	GEN	Merivale Dental Centre	1460 Meivale Road Unit 4B Ottawa ON K2E5P2	ENE/145.2	-1.03	146
14	GEN	Merivale Dental Centre	1460 Meivale Road Unit 4B Ottawa ON K2E5P2	ENE/145.2	-1.03	146
14	GEN	Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	146
14	GEN	BG FUELS GAS BARS 4281	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	149
14	GEN	Merivale Dental Centre	1460 Meivale Road Unit 4B Ottawa ON K2E5P2	ENE/145.2	-1.03	149
14	GEN	Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	151
14	GEN	BG FUELS GAS BARS 4281	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	154
14	GEN	BG Fuels	1460 Merivale Road Ottawa ON	ENE/145.2	-1.03	154
14	GEN	Loblaws Inc.	1460 Merivale Road Ottawa ON	ENE/145.2	-1.03	157
14	GEN	BG Fuels	1460 Merivale Road Ottawa ON	ENE/145.2	-1.03	167
14	INC	BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE/145.2	-1.03	168
14	INC	BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE/145.2	-1.03	169
14	INC	BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE/145.2	-1.03	169

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	PES	LOBLAWS LIMITED C.O.B. AS "LOBLAWS" 082-8	1460 MERIVALE ROAD OTTAWA ON	ENE/145.2	-1.03	170
14	PES	LOBLAWS SUPERMARKETS LTD.	1460 MERIVALE ROAD OTTAWA ON K2J 3W6	ENE/145.2	-1.03	171
14	PES	LOBLAWS SUPERMARKETS LTD #1082	1460 MERIVALE RD OTTAWA ON K2E 5P2	ENE/145.2	-1.03	171
14	PES	SHOPPERS DRUG MART #627	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	171
14	PES	LOBLAWS SUPERMARKETS LTD #1082	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	172
14	PES	SHOPPERS DRUG MART #627	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	172
14	PES	SHOPPERS DRUG MART #627	1460 MERIVALE RD OTTAWA ON K2E 5P2	ENE/145.2	-1.03	172
14	PES	LOBLAWS SUPERMARKETS LIMITED	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	173
14	PES	LOBLAWS SUPERMARKETS LTD.	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	173
14	PES	LOBLAWS SUPERMARKETS LTD #1021	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	174
14	PES	LOBLAWS SUPERMARKETS LTD.	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	174
14	PES	LOBLAWS INC. STORE #1095	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	174
14	PES	LOBLAWS SUPERMARKETS LIMITED 1174	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	175

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	PES	LOBLAWS INC #1212	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	175
14	PES	LOBLAWS INC. # 1003	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	175
14	PES	ZEHRS MARKETS	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	176
14	PES	LOBLAWS SUPERMARKETS #1027	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE/145.2	-1.03	176
14	PES	LOBLAWS SUPERMARKETS #1064	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE/145.2	-1.03	177
14	PES	LOBLAWS SUPERMARKETS #1090	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE/145.2	-1.03	177
14	PES	LOBLAWS SUPERMARKETS LTD. STORE #1099	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE/145.2	-1.03	177
14	PES	LOBLAWS SUPERMARKETS #1127	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE/145.2	-1.03	178
14	PES	LOBLAWS SUPERMARKET #1170	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE/145.2	-1.03	178
14	PES	LOBLAW SUPERMARKET #1200	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	178
14	PES	LOBLAWS SUPERMARKETS LTD. STORE #1208	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	179
14	PES	LOBLAWS SUPERMARKETS LTD #1082	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	179
14	PES	ZEHRS MARKETS	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	180

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	PES	ZEHRS MARKETS #539	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	180
14	PES	ZEHRS MARKETS	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	180
14	PES	LOBLAWS SUPERMARKET #1032	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	181
14	PES	LOBLAWS SUPERMARKETS #1194	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	181
14	PES	LOBLAWS SUPERMARKETS LTD #1188	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	182
14	PES	LOBLAWS SUPERMARKETS LTD #1082	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE/145.2	-1.03	182
14	PRT	C CORP (ONTARIO) INC ATTN ACCOUNTS PAYABLE	1460 MERIVALE RD NEPEAN ON K2E5P2	ENE/145.2	-1.03	182
14	PRT	SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON K2E5P2	ENE/145.2	-1.03	182
14	PRT	SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON K2E5P2	ENE/145.2	-1.03	183
14	PRT		1460 MERIVALE RD. NEPEAN, ONT. ON	ENE/145.2	-1.03	183
14	RSC	Reno Realty Holdings Limited	1460 Merivale Road Ottawa, Ontario, K2E 5P2 OTTAWA ON	ENE/145.2	-1.03	183
14	RST	SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON K2E5P2	ENE/145.2	-1.03	183
14	SPL	NATIONAL GROCERIES COMPANY LTD	1460 MERIVALE RD OTTAWA CITY ON	ENE/145.2	-1.03	184

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	SPL	NATIONAL GROCERIES COMPANY LTD	1460 MERIVALE RD OTTAWA CITY ON	ENE/145.2	-1.03	185
14	SPL	Loblaws Companies East	1460 Merivale Rd. Ottawa ON	ENE/145.2	-1.03	186
14	SPL	Parson Refrigeration (1985) Ltd.	1460 Merivale Rd Ottawa ON	ENE/145.2	-1.03	187
14	SPL	Loblaws Inc.	1460 Merivale Road Ottawa ON K2E 5P2	ENE/145.2	-1.03	188
14	SPL	Loblaw Companies Limited	1460 Merivale Road Ottawa ON	ENE/145.2	-1.03	188
14	SPL	Seaboard Transport	1460 Merivale Rd Ottawa ON K2E 5P2	ENE/145.2	-1.03	189
14	SPL		1460 Merivale, Ottawa OTTAWA ON	ENE/145.2	-1.03	190
15	EHS		1308, 1330 and 1350 Baseline Road and 1460 Merivale Road, Ottawa, ON Nepean ON K2E 5N9	ENE/167.1	-2.49	191
16	EASR	Ottawa SW Propco LP	1405 Baseline RD Ottawa ON K2C 3G1	WNW/167.5	-1.03	192
17	WWIS		1331 CLYDE AVE. Ottawa ON ***Well ID:*** 7207624	WSW/170.6	-1.00	192
18	WWIS		1331 CLYDE AVE. Ottawa ON ***Well ID:*** 7207625	WSW/170.6	-1.03	194
19	DTNK	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	1400 BASELINE RD OTTAWA ON K2C 0A9	SW/171.6	-1.03	196
19	DTNK	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	197

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
19	DTNK	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	197
19	EXP	CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	198
19	EXP	CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	198
19	EXP	CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	198
19	EXP	CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	199
19	EXP	CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	199
19	EXP	CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	199
19	EXP	CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW/171.6	-1.03	199
19	GEN	DUPONT CONTRACTING	1400 BASELINE RD OTTAWA ON K2C 0A9	SW/171.6	-1.03	200
19	PRT	CANADIAN TIRE CORP LTD PETROLEUM DIVISION - SUSAN	1400 BASELINE RD OTTAWA ON K2C 0A9	SW/171.6	-1.03	200
20	WWIS		ON ***Well ID:*** 7479650	WSW/172.7	-1.00	200
21	EHS		1460 Merivale Road Nepean ON K2E 5N9	ENE/175.7	-2.49	201
22	WWIS		ON ***Well ID:*** 7479648	WSW/177.0	-1.00	201

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
23	WWIS		lot 35 con A ON ***Well ID:*** 1504637	SE/177.9	-2.06	202
24	DTNK	1332717 ONTARIO INC T/P PETRO CANADA	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	205
24	DTNK	1332717 ONTARIO INC T/P PETRO CANADA	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	205
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	206
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	206
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	206
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	207
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	207
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	207
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW/180.6	-1.00	207
24	FSTH	6133487 CANADA INC O/A GAS STN	1432 BASELINE RD OTTAWA ON K2C 0A9	WSW/180.6	-1.00	207
24	FSTH	1332717 ONTARIO INC T/P PETRO CANADA	1432 BASELINE RD OTTAWA ON K2C 0A9	WSW/180.6	-1.00	208
24	GEN	Suncor Energy Products Partnership	1432 Baseline Road Ottawa ON K2C 0A9	WSW/180.6	-1.00	209

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
24	GEN	Suncor Energy Product Partnership	1432 Baseline Road Ottawa ON	WSW/180.6	-1.00	210
24	HBAR	Erler's Service Station	1432 Baseline Rd Ottawa ON	WSW/180.6	-1.00	211
24	PINC	ENBRIDGE GAS INC	1432 BASELINE RD,,OTTAWA,ON,K2C 0A9,CA ON	WSW/180.6	-1.00	211
24	PRT	PETRO CANADA NEIGHBOURS	1432 BASELINE RD NEPEAN ON K2C 0A9	WSW/180.6	-1.00	211
24	RST	NEIGHBOUR'S PETRO-CANADA	1432 BASE LINE RD OTTAWA ON K2C0A9	WSW/180.6	-1.00	211
24	RST	NEIGHBOUR'S PETRO-CANADA	1432 BASELINE RD OTTAWA ON K2C 0A9	WSW/180.6	-1.00	212
24	RST	PETRO-CANADA	1432 BASELINE RD OTTAWA ON K2C 0A9	WSW/180.6	-1.00	212
24	RST	PETRO-CANADA	1432 BASELINE RD OTTAWA ON K2C0A9	WSW/180.6	-1.00	212
24	SPL	PETRO-CANADA	1432 BASELINE RD. AT CLYDE SERVICE STATION OTTAWA CITY ON K2C 0A9	WSW/180.6	-1.00	212
24	SPL	Petro-Canada	1432 Baseline Road, Ottawa ON K2C 0A9	WSW/180.6	-1.00	213
24	SPL		1432 Baseline Road, Ottawa, ON, Canada OTTAWA ON	WSW/180.6	-1.00	214
25	EHS		1432 BASELINE ROAD Ottawa, Ontario ON K2C 0A9	WSW/180.6	-1.00	215
26	WWIS		lot 35 con A ON ***Well ID:*** 1504638	SE/181.5	-1.34	215

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
28	WWIS		ON **Well ID:** 7474014	WSW/183.3	-1.00	218
29	WWIS		lot 35 con A ON **Well ID:** 1504627	E/184.8	-3.03	219
30	WWIS		ON **Well ID:** 7242904	ESE/187.4	-2.06	221
31	EHS		Clyde Ave Ottawa ON	W/188.0	-0.95	222
32	WWIS		1331 CLYDE AVE. Ottawa ON **Well ID:** 7207626	WSW/188.1	-1.00	222
33	DTNK	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	1375 CLYDE AV NEPEAN ON	SW/188.7	-1.03	224
33	ECA	1375 CLYDE STORAGE GP CORPORATION	1375 Clyde Ave Ottawa ON K1H 8K3	SW/188.7	-1.03	225
33	EHS		1375 Clyde Avenue Ottawa ON	SW/188.7	-1.03	225
33	GEN	Savers, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW/188.7	-1.03	225
33	GEN	Value Village Stores, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW/188.7	-1.03	226
33	GEN	Value Village Stores, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW/188.7	-1.03	227
33	GEN	Value Village Stores, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW/188.7	-1.03	228
33	GEN	Value Village Stores, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW/188.7	-1.03	230

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
33	GEN	Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW/188.7	-1.03	231
33	GEN	Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW/188.7	-1.03	232
33	GEN	Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW/188.7	-1.03	233
33	GEN	Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW/188.7	-1.03	236
33	GEN	Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW/188.7	-1.03	238
33	GEN	Dymon Storage	1375 Clyde Ave Ottawa ON K2G 3H7	SW/188.7	-1.03	239
33	PES	CANADIAN TIRE STORE #258 GORDON C. REID LIMITED	1375 CLYDE AVENUE AT BASELINE OTTAWA ON	SW/188.7	-1.03	239
33	PES	CANADIAN TIRE STORE #258 /DES KEON LTD.	1375 CLYDE AVENUE NEPEAN ON K2G3H7	SW/188.7	-1.03	240
33	SCT	Motor Sports World	1375 Clyde Ave. Ottawa ON K2G3H7	SW/188.7	-1.03	240
33	SPL		Value Village Parking Lot, 1375 Clyde Ave. <UNOFFICIAL> Ottawa ON	SW/188.7	-1.03	241
33	SPL		1375 Clyde Avenue Ottawa, ON OTTAWA ON	SW/188.7	-1.03	242
36	WWIS		ON ***Well ID:*** 7473512	SE/193.4	-1.03	243
37	WWIS		1300 BASELINE RD Ottawa ON ***Well ID:*** 7187998	NE/195.8	-1.00	244

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
37	WWIS		1300 BASELINE RD Ottawa ON ***Well ID:*** 7187999	NE/195.8	-1.00	247
38	WWIS		ON ***Well ID:*** 7479649	WSW/198.7	-1.60	251
39	EASR	WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA	1375 BASELINE RD OTTAWA ON K2C 3G1	NW/200.1	-0.89	252
39	GEN	Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	252
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	252
39	GEN	Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	253
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	253
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON	NW/200.1	-0.89	253
39	GEN	Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON	NW/200.1	-0.89	254
39	GEN	Smile Shapers	1375 Baseline Rd Ottawa ON	NW/200.1	-0.89	255
39	GEN	Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW/200.1	-0.89	255
39	GEN	Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW/200.1	-0.89	255
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	256

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
39	GEN	Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON K2G3H7	NW/200.1	-0.89	257
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	257
39	GEN	Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW/200.1	-0.89	258
39	GEN	Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON K2G3H7	NW/200.1	-0.89	259
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	259
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	260
39	GEN	Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW/200.1	-0.89	262
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	262
39	GEN	Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW/200.1	-0.89	263
39	GEN	Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW/200.1	-0.89	264
39	GEN	Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW/200.1	-0.89	264
39	GEN	Walmart Canada	Store #1110, 1375 Baseline Road Ottawa ON	NW/200.1	-0.89	266
39	GEN	Simplii Environmental Corp Simplii Environmental Corp	1375 Baseline Rd Ottawa ON K2C 3G1	NW/200.1	-0.89	274

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
39	GEN	Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW/200.1	-0.89	275
39	GEN	Smile Shapers Dental Clinic	1375 Baseline Road Ottawa ON	NW/200.1	-0.89	278
39	PES	WAL-MART CANADA CORP. STORE #1110	1375 BASELINE RD OTTAWA ON K2C 3G1	NW/200.1	-0.89	278
39	PES	WAL-MART CANADA CORP. STORE #1110	1375 BASELINE RD OTTAWA ON K2C 3G1	NW/200.1	-0.89	279
39	PES	WAL-MART CANADA CORP. STORE #1110	1375 BASELINE RD OTTAWA ON K2C3G1	NW/200.1	-0.89	279
39	PES	WAL-MART CANADA CORP. STORE #1110	1375 BASELINE RD OTTAWA ON K2C3G1	NW/200.1	-0.89	279
39	PES		1375 BASELINE RD OTTAWA ON K2C 3G1	NW/200.1	-0.89	280
41	EHS		1345 Baseline Road Ottawa ON K2C 0A7	NNE/200.9	-1.03	280
42	WWIS		ON ***Well ID:*** 7474013	WSW/202.1	-1.73	280
44	DTNK	DONALD BELLS PETROLEUM LTD	1468 MERIVALE RD NEPEAN ON	ESE/203.8	-2.03	281
44	PRT	DONALD BELLS PETROLEUM LTD	1468 MERIVALE RD OTTAWA ON K2E 5P1	ESE/203.8	-2.03	282
45	GEN	Boy Scouts of Canada	1345 Baseline Road Ottawa ON K2C 0A7	NE/204.4	-1.03	282
45	GEN	Boy Scouts of Canada	1345 Baseline Road Ottawa ON K2C 0A7	NE/204.4	-1.03	283

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
45	SCT	Scouting Life	1345 Baseline Rd Unit 100 Ottawa ON K2C 0A7	NE/204.4	-1.03	283
45	SPL		1345 Baseline. Ottawa OTTAWA ON	NE/204.4	-1.03	284
46	WWIS		ON ***Well ID:*** 7474032	WSW/206.2	-2.08	285
47	CA	CHEESE PLUS PIZZA & SUBS	1478 MERIVALE ROAD NEPEAN CITY ON K2E 6Z5	SE/207.1	-1.03	285
48	WWIS		ON ***Well ID:*** 7473508	SE/209.0	-1.03	286
52	EHS		1377 Clyde Avenue 1377 Clyde Avenue ON K2G 3H7	SSW/211.9	-1.08	286
52	FST	FRISBY TIRE CO (1974) LTD	1377 CLYDE AV NEPEAN ON	SSW/211.9	-1.08	287
52	FSTH	FRISBY TIRE CO (1974) LTD	1377 CLYDE AV NEPEAN ON K2G 3H7	SSW/211.9	-1.08	287
52	FSTH	FRISBY TIRE CO (1974) LTD	1377 CLYDE AV NEPEAN ON K2G 3H7	SSW/211.9	-1.08	287
52	PRT	FRISBY TIRE CO (1974) LTD	1377 CLYDE AV NEPEAN ON K2G 3H7	SSW/211.9	-1.08	288
52	SCT	Kal Tire	1377 Clyde Ave. Nepean ON K2G3H7	SSW/211.9	-1.08	288
52	SPL	FRISBEE TIRE	1377 CLYDE NEPEAN CITY ON K2G 3H7	SSW/211.9	-1.08	289
53	WWIS		1345 BASELINE ROAD Ottawa ON ***Well ID:*** 7413944	NE/212.4	-1.73	290

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
54	WWIS		ON **Well ID:** 7473511	SE/213.1	-1.03	293
55	WWIS		lot 35 con A ON **Well ID:** 1504629	WSW/213.2	-2.15	293
56	ECA	Nortel Networks Corporation	Skyline- Tower VI Ottawa ON K1Y 4H7	NE/213.5	-1.73	296
59	WWIS		1490 MERRIVALE ROAD OTTAWA ON **Well ID:** 7046663	SSE/217.9	-1.03	296
60	WWIS		ON **Well ID:** 7473513	SE/217.9	-1.03	299
61	WWIS		ON **Well ID:** 7473510	SE/220.4	-1.03	300
62	WWIS		lot 35 con A ON **Well ID:** 1504634	ESE/220.9	-1.34	301
63	WWIS		lot 35 con A ON **Well ID:** 1504632	ESE/228.0	-1.34	304
64	WWIS		lot 35 con A ON **Well ID:** 1504611	SSE/233.8	-1.03	306
65	GEN	5010560 Ontario Inc	1486 Merivale Road Ottawa ON K2E 6Z5	SSE/234.7	-1.03	309
66	RST	SWAN'S GARAGE	1486 MERIVALE RD NEPEAN ON K2E 6Z5	SSE/235.1	-1.03	310
66	RST	SWAN'S GARAGE	1486 MERIVALE RD NEPEAN ON K2E6Z5	SSE/235.1	-1.03	310
67	WWIS		1442 BASELINE RD. OTTAWA ON **Well ID:** 7267376	WSW/243.8	-2.34	310

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
68	GEN	A. M. Pharmacare Limited	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE/244.0	-1.34	313
68	GEN	A. M. Pharmacare Limited (629)	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE/244.0	-1.34	314
68	GEN	A. M. Pharmacare Limited	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE/244.0	-1.34	314
68	GEN	A. M. Pharmacare Limited	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE/244.0	-1.34	314
68	GEN	Shohdy Gana pharmacy inc.	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE/244.0	-1.34	315
68	GEN	SHOPPERS DRUG MART #952	1469 MERIVALE ROAD Ottawa ON	ESE/244.0	-1.34	315
68	PES	TRENT E JAY ADOTHECARY LTD	1469 MERIVALE RD OTTAWA ON K2E5N9	ESE/244.0	-1.34	319
68	PES	A.M. PHARMACARE LIMITED	1469 MERIVALE ROAD OTTAWA ON K2E5N9	ESE/244.0	-1.34	319
68	PES	TRENT E JAY ADOTHECARY LTD	1469 MERIVALE RD OTTAWA ON K2E5N9	ESE/244.0	-1.34	320
68	PES	A.M. PHARMACARE LIMITED	1469 MERIVALE ROAD OTTAWA ON K2E 5N9	ESE/244.0	-1.34	320
68	PES	SHOPPERS DRUG MART #627	1469 MERIVALE RD OTTAWA ON K2E5N9	ESE/244.0	-1.34	320
68	PES	A.M. PHARMACARE LIMITED	1469 MERIVALE ROAD OTTAWA ON K2E5N9	ESE/244.0	-1.34	321
68	PES	TRENT E JAY APOTHECARY LTD	1469 MERIVALE RD OTTAWA ON K2E5N9	ESE/244.0	-1.34	321

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
69	EASR	CLYDESDALE SHOPPING CENTRES LIMITED	1331 CLYDE AVENUE OTTAWA ON K2C 0A8	WNW/244.3	-2.03	322
69	GEN	Stantec	1331 Clyde Unit 400 Ottawa ON K2C 3G4	WNW/244.3	-2.03	322
69	GEN	Stantec	1331 Clyde Unit 400 Ottawa ON K2C 3G4	WNW/244.3	-2.03	323
69	GEN	Kroon Electric Corp	1331 Clyde Avenue Ottawa ON K2C 3G4	WNW/244.3	-2.03	324
69	GEN	Stantec Consulting Ltd.	1331 Clyde Avenue, Unit 400 Ottawa ON K2C 3G4	WNW/244.3	-2.03	325
69	GEN	Stantec Consulting Ltd.	1331 Clyde Avenue, Unit 400 Ottawa ON	WNW/244.3	-2.03	326
69	SCT	Versaterm Public Safety Inc	1331 Clyde Ave. Ottawa ON K2C3G4	WNW/244.3	-2.03	331
71	WWIS		lot 35 con A ON ***Well ID:*** 1504618	SE/244.7	-1.03	333
72	BORE		ON	WSW/245.8	-2.04	335
73	EHS		1465 Merivale Rd Ottawa ON K2E5N9	ESE/246.3	-2.06	336
73	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 907	1465 MERIVALE ROAD, UNIT 13 OTTAWA ON K2E5N9	ESE/246.3	-2.06	336
73	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 907	1465 Merivale Road, Unit 13 Ottawa ON K2E 5N9	ESE/246.3	-2.06	337
73	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 907	1465 MERIVALE ROAD, UNIT 13 OTTAWA ON K2E5N9	ESE/246.3	-2.06	337

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	SPL	Parson Refrigeration (1985) Ltd.	1465 Meriville Road Ottawa ON	ESE/246.3	-2.06	338
74	DTNK	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON K2C 0B2	WSW/248.7	-1.95	339
74	DTNK	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	339
74	DTNK	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	340
74	DTNK	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	340
74	DTNK	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	341
74	DTNK	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	342
74	EHS		1442 Baseline Rd Ottawa ON K2C0B2	WSW/248.7	-1.95	342
74	EXP	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	342
74	EXP	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	343
74	EXP	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	343
74	EXP	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	343
74	EXP	1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW/248.7	-1.95	343

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	344
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	344
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	345
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	345
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	346
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON	WSW/248.7	-1.95	346
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	347
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	347
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	348
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	348
74	GEN	Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW/248.7	-1.95	349
74	HBAR	Lewis Esso Service	1442 Baseline Rd Ottawa ON	WSW/248.7	-1.95	351
74	PRT	T & P ESSO C/O TED DESROSIERS	1442 BASELINE RD NEPEAN ON K2C 0B2	WSW/248.7	-1.95	351

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
74	PRT	SCOTTS ESSO RICHARD SCOTT	1442 BASELINE RD NEPEAN ON K2C3Z4	WSW/248.7	-1.95	351
74	RST	MR LUBE	1442 BASELINE RD OTTAWA ON K2C 0B2	WSW/248.7	-1.95	352
74	RST	MR LUBE	1442 BASELINE RD OTTAWA ON K2C0B2	WSW/248.7	-1.95	352
74	RST	MR LUBE	1442 BASELINE RD OTTAWA ON K2C0B2	WSW/248.7	-1.95	352
74	SPL	Mr. Lube<UNOFFICIAL>	1442 Baseline Road Ottawa ON	WSW/248.7	-1.95	352

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 3 BORE site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
	ON	W	72.15	6
	ON	W	124.29	11
	ON	WSW	245.83	72

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 5 CA site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
TDL GROUP LIMITED	1384 BASELINE ROAD (SWM) OTTAWA ON K2C 0A9	WSW	71.39	5
CTVGlobemedia Inc.	1500 Merivale Rd Ottawa ON	SSW	131.82	12
Loblaw Properties Limited	1460 Merivale Road Ottawa ON	ENE	145.21	14
Loblaw Properties Limited	1460 Merivale Road Ottawa ON	ENE	145.21	14
CHEESE PLUS PIZZA & SUBS	1478 MERIVALE ROAD NEPEAN CITY ON K2E 6Z5	SE	207.12	47

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 21 DTNK site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
MAC'S CONVENIENCE STORES INC**	1460 MERIVALE RD NEPEAN ON K2E 5P2	ENE	145.21	14
SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON K2E 5P2	ENE	145.21	14
SUNYS ENERGY INC ATTN RAFAH SHOOMAN	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS ENERGY INC ATTN RAFAH SHOOMAN	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON K2E 5P2	ENE	145.21	14
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	1400 BASELINE RD OTTAWA ON K2C 0A9	SW	171.56	19
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	1400 BASELINE RD OTTAWA ON	SW	171.56	19
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	1400 BASELINE RD OTTAWA ON	SW	171.56	19

1332717 ONTARIO INC T/P PETRO CANADA	1432 BASELINE RD OTTAWA ON	WSW	180.60	24
1332717 ONTARIO INC T/P PETRO CANADA	1432 BASELINE RD OTTAWA ON	WSW	180.60	24
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	1375 CLYDE AV NEPEAN ON	SW	188.75	33
DONALD BELLS PETROLEUM LTD	1468 MERIVALE RD NEPEAN ON	ESE	203.80	44
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON K2C 0B2	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011 - Jan 31, 2026 has found that there are 4 EASR site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key

CLARIDGE HOMES (BASELINE PAHSE 1) LIMITED PARTNERSHIP	1500 Merivale RD Ottawa ON K2C 0A9	SSW	131.82	12
Ottawa SW Propco LP	1405 Baseline RD Ottawa ON K2C 3G1	WNW	167.53	16
WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA	1375 BASELINE RD OTTAWA ON K2C 3G1	NW	200.05	39
CLYDESDALE SHOPPING CENTRES LIMITED	1331 CLYDE AVENUE OTTAWA ON K2C 0A8	WNW	244.27	69

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Dec 31, 2025 has found that there are 1 EBR site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
CTVGlobemedia Inc.	1500 Merivale Road Ottawa K2E 6Z5 CITY OF OTTAWA ON	SSW	131.82	12

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011 - Jan 31, 2026 has found that there are 6 ECA site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Smart (Ottawa SW Senior Residences) PropCo GP Inc. as general partner for and on	behalf of Ottawa SW PropCo LP 1357 Baseline Rd Ottawa ON L4K 5Z5	N	123.95	10
CTVGlobemedia Inc.	1500 Merivale Rd Ottawa ON K2E 6Z5	SSW	131.82	12
Loblaw Properties Limited	1460 Merivale Road Ottawa ON L6Y 5S5	ENE	145.21	14
Loblaw Properties Limited	1460 Merivale Road Ottawa ON M4T 2S5	ENE	145.21	14

1375 CLYDE STORAGE GP CORPORATION	1375 Clyde Ave Ottawa ON K1H 8K3	SW	188.75	33
Nortel Networks Corporation	Skyline- Tower VI Ottawa ON K1Y 4H7	NE	213.49	56

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Nov 30, 2025 has found that there are 20 EHS site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
	1374 Baseline Road Ottawa ON K2C 0A9	NNW	30.20	2
	1374 Baseline Rd Ottawa ON K2C0A9	NNW	30.20	2
	Kimway Cres Ottawa ON	SE	42.89	3
	1357 Baseline Road Ottawa ON K2C 0A8	N	123.95	10
	1500 Merivale Road Ottawa ON	SSW	131.82	12
	1500 Merivale Road Nepean ON K2E 6Z5	SSW	131.82	12
	1490 and 1500 Merivale Road Nepean ON K2E 6Z5	SSW	131.82	12
	1365 -1385 Baseline Road Ottawa ON	NW	145.09	13
	1460 Merivale Road Ottawa ON	ENE	145.21	14

1460 Merivale Rd Ottawa ON K2C 0A9	ENE	145.21	14
1308, 1330 and 1350 Baseline Road and 1460 Merivale Road, Ottawa, ON Nepean ON K2E 5N9	ENE	167.07	15
1460 Merivale Road Nepean ON K2E 5N9	ENE	175.73	21
1432 BASELINE ROAD Ottawa, Ontario ON K2C 0A9	WSW	180.63	25
Clyde Ave Ottawa ON	W	188.04	31
1375 Clyde Avenue Ottawa ON	SW	188.75	33
Part of 1500 Merivale Road Nepean ON K2E 6Z5	SE	190.23	34
1345 Baseline Road Ottawa ON K2C 0A7	NNE	200.87	41
1377 Clyde Avenue 1377 Clyde Avenue ON K2G 3H7	SSW	211.92	52
1465 Merivale Rd Ottawa ON K2E5N9	ESE	246.26	73
1442 Baseline Rd Ottawa ON K2C0B2	WSW	248.66	74

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Oct 2023 has found that there are 18 EXP site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
SUNYS ENERGY INC	1460 MERIVALE RD NEPEAN ON	ENE	145.21	14
CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW	171.56	19
CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW	171.56	19
CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW	171.56	19
CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW	171.56	19
CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW	171.56	19
CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW	171.56	19

CANADIAN TIRE CORPORATION LIMITED	1400 BASELINE RD OTTAWA ON	SW	171.56	19
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74
1117063 ONTARIO INC	1442 BASELINE RD OTTAWA ON	WSW	248.66	74

FST - Fuel Storage Tank

A search of the FST database, dated Oct 2023 has found that there are 11 FST site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE	145.21	14
BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE	145.21	14
BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE	145.21	14
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW	180.60	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW	180.60	24

SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW	180.60	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW	180.60	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW	180.60	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW	180.60	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1432 BASELINE RD OTTAWA ON	WSW	180.60	24
FRISBY TIRE CO (1974) LTD	1377 CLYDE AV NEPEAN ON	SSW	211.92	52

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 6 FSTH site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
LOBLAW PROPERTIES LTD AT THE PUMPS GASBAR DIV	1460 MERIVALE RD OTTAWA ON	ENE	145.21	14
LOBLAW PROPERTIES LTD GASBAR DIV	1460 MERIVALE RD OTTAWA ON	ENE	145.21	14
6133487 CANADA INC O/A GAS STN	1432 BASELINE RD OTTAWA ON K2C 0A9	WSW	180.60	24
1332717 ONTARIO INC T/P PETRO CANADA	1432 BASELINE RD OTTAWA ON K2C 0A9	WSW	180.60	24

FRISBY TIRE CO (1974) LTD	1377 CLYDE AV NEPEAN ON K2G 3H7	SSW	211.92	52
FRISBY TIRE CO (1974) LTD	1377 CLYDE AV NEPEAN ON K2G 3H7	SSW	211.92	52

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Mar 31, 2025 has found that there are 101 GEN site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Capital Dentistry Group Ltd.	1365 Baseline Road Ottawa ON	NNW	93.96	8
OTTAWA BOARD OF EDUCATION	LAURENTIAN HIGH SCHOOL, 1357 BASELINERD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8	N	123.95	10
THE OTTAWA BOARD OF EDUCATION	LAURENTIAN HIGH SCHOOL,1357 BASELINE RD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8	N	123.95	10
OTTAWA BOARD OF EDUCATION	LAURENTIAN HIGH SCHOOL 1357 BASELINE ROAD OTTAWA ON K2C 0A8	N	123.95	10
THE OTTAWA BOARD OF EDUCATION 29-550	LAURENTIAN HIGH SCHOOL,1357 BASELINE RD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8	N	123.95	10
OTTAWA-CARLETON DISTRICT SCHOOL BOARD	LAURENTIAN HIGH SCHOOL 1357 BASELINE ROAD OTTAWA ON K2C 0A8	N	123.95	10
Ottawa-Carleton District School Board	Laurention H.S. Public School 1357 Baseline Road Ottawa ON K2C 0A8	N	123.95	10
OTTAWA-CARLETON DISTRICT SCHOOL BOARD	1357 BASELINE ROAD OTTAWA ON	N	123.95	10
CLYDESDALE SHOPPING CENTERS LTD	1357 BASELINE ROAD OTTAWA ON	N	123.95	10

NATION'S CAPITAL TELEVISION INCORPORATED	CJOH-TV 1500 MERIVALE ROAD NEPEAN ON K2E 6Z5	SSW	131.82	12
NATION'S CAPITAL TELEVISION INC. 28-832	CJOH-TV 1500 MERIVALE ROAD NEPEAN ON K2E 6Z5	SSW	131.82	12
Aim Group	1500 Merivale Ottawa ON	SSW	131.82	12
Aim Environmental Group	1500 Merivale Road Ottawa ON	SSW	131.82	12
Aim Environmental Group	1500 Merivale Road Ottawa ON	SSW	131.82	12
LOBLAWS SUPERMARKETS LTD. 24-850	1460 MERIVALE ROAD NEPEAN ON K2E 5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD	1460 MERIVALE ROAD NEPEAN ON K2E 5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LIMITED	1460 MERIVALE ROAD NEPEAN ON K2E 5P2	ENE	145.21	14
SPORTS EXPERTS #51	1460 MERIVALE RD. NEPEAN ON K2E 5P2	ENE	145.21	14
SPORTS EXPERTS #51 34-397	1460 MERIVALE RD. NEPEAN ON K2E 5P2	ENE	145.21	14
SPORTS EXPERTS #51	1460 MERIVALE ROAD NEPEAN ON K2E 5P2	ENE	145.21	14
SHOPPERS DRUG MART	1460 MERIVALE ROAD OTTAWA ON K2E 5P2	ENE	145.21	14

SJL HOLDINGS LIMITED	1460 MERIVALE ROAD OTTAWA ON K2E 5N9	ENE	145.21	14
FCR MANAGEMENT SERVICES	1460 MERIVALE ROAD OTTAWA ON K2E 5P2	ENE	145.21	14
Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14
Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14
Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14
Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14
Merivale Dental Centre	1460 Meivale Road Unit 4B Ottawa ON K2E5P2	ENE	145.21	14
Merivale Dental Centre	1460 Meivale Road Unit 4B Ottawa ON K2E5P2	ENE	145.21	14
Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14
BG FUELS GAS BARS 4281	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14
Merivale Dental Centre	1460 Meivale Road Unit 4B Ottawa ON K2E5P2	ENE	145.21	14
Loblaw Properties Ltd.	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14
BG FUELS GAS BARS 4281	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14

BG Fuels	1460 Merivale Road Ottawa ON	ENE	145.21	14
Loblaws Inc.	1460 Merivale Road Ottawa ON	ENE	145.21	14
BG Fuels	1460 Merivale Road Ottawa ON	ENE	145.21	14
DUPONT CONTRACTING	1400 BASELINE RD OTTAWA ON K2C 0A9	SW	171.56	19
Suncor Energy Products Partnership	1432 Baseline Road Ottawa ON K2C 0A9	WSW	180.60	24
Suncor Energy Product Partnership	1432 Baseline Road Ottawa ON	WSW	180.60	24
Savers, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW	188.75	33
Value Village Stores, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW	188.75	33
Value Village Stores, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW	188.75	33
Value Village Stores, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW	188.75	33
Value Village Stores, Inc.	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW	188.75	33
Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW	188.75	33

Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON	SW	188.75	33
Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW	188.75	33
Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW	188.75	33
Value Village Stores	1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	SW	188.75	33
Dymon Storage	1375 Clyde Ave Ottawa ON K2G 3H7	SW	188.75	33
Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON K2G3H7	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW	200.05	39
Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39

Walmart Canada	Store #1110, 1375 Baseline Road Ottawa ON	NW	200.05	39
Simplii Environmental Corp Simplii Environmental Corp	1375 Baseline Rd Ottawa ON K2C 3G1	NW	200.05	39
Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW	200.05	39
Smile Shapers Dental Clinic	1375 Baseline Road Ottawa ON	NW	200.05	39
Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON	NW	200.05	39
Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON	NW	200.05	39
Smile Shapers	1375 Baseline Rd Ottawa ON	NW	200.05	39
Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW	200.05	39

Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Caremedics Clyde Baseline Inc	1375 Baseline Road Ottawa ON K2G3H7	NW	200.05	39
Walmart Canada Corp.	1375 Baseline Road Ottawa ON K2C 3G1	NW	200.05	39
Smile Shapers	1375 Baseline Rd Ottawa ON K2C3G1	NW	200.05	39
Boy Scouts of Canada	1345 Baseline Road Ottawa ON K2C 0A7	NE	204.39	45
Boy Scouts of Canada	1345 Baseline Road Ottawa ON K2C 0A7	NE	204.39	45
5010560 Ontario Inc	1486 Merivale Road Ottawa ON K2E 6Z5	SSE	234.74	65
A. M. Pharmacare Limited	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE	243.96	68
A. M. Pharmacare Limited (629)	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE	243.96	68
A. M. Pharmacare Limited	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE	243.96	68
A. M. Pharmacare Limited	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE	243.96	68
Shohdy Gana pharmacy inc.	1469 MERIVALE ROAD Ottawa ON K2E 5N9	ESE	243.96	68

SHOPPERS DRUG MART #952	1469 MERIVALE ROAD Ottawa ON	ESE	243.96	68
Stantec	1331 Clyde Unit 400 Ottawa ON K2C 3G4	WNW	244.27	69
Stantec	1331 Clyde Unit 400 Ottawa ON K2C 3G4	WNW	244.27	69
Kroon Electric Corp	1331 Clyde Avenue Ottawa ON K2C 3G4	WNW	244.27	69
Stantec Consulting Ltd.	1331 Clyde Avenue, Unit 400 Ottawa ON K2C 3G4	WNW	244.27	69
Stantec Consulting Ltd.	1331 Clyde Avenue, Unit 400 Ottawa ON	WNW	244.27	69
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON	WSW	248.66	74

Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74
Imperial Oil	1442 Baseline Road Ottawa ON K2C 0B2	WSW	248.66	74

HBAR - Historical Business Activity Risk

A search of the HBAR database, dated 1920s - 1960 has found that there are 2 HBAR site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Erler's Service Station	1432 Baseline Rd Ottawa ON	WSW	180.60	24
Lewis Esso Service	1442 Baseline Rd Ottawa ON	WSW	248.66	74

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated Oct 2023 has found that there are 3 INC site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE	145.21	14
BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE	145.21	14

BCP IV SERVICE STATION LP O/A BG FUELS	1460 MERIVALE RD OTTAWA ON	ENE	145.21	14

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 1 NPCB site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
CJOH TV	1500 MERIVALE RD. OTTAWA ON	SSW	131.82	12

PES - Pesticide Register

A search of the PES database, dated Oct 2011 - Jan 31, 2026 has found that there are 49 PES site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
LOBLAWS LIMITED C.O.B. AS "LOBLAWS" 082-8	1460 MERIVALE ROAD OTTAWA ON	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD.	1460 MERIVALE ROAD OTTAWA ON K2J 3W6	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD #1082	1460 MERIVALE RD OTTAWA ON K2E 5P2	ENE	145.21	14
SHOPPERS DRUG MART #627	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD #1082	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
SHOPPERS DRUG MART #627	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
SHOPPERS DRUG MART #627	1460 MERIVALE RD OTTAWA ON K2E 5P2	ENE	145.21	14

LOBLAWS SUPERMARKETS LIMITED	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD.	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD #1021	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD.	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS INC. STORE #1095	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LIMITED 1174	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS INC #1212	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS INC. # 1003	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
ZEHRS MARKETS	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS #1027	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE	145.21	14
LOBLAWS SUPERMARKETS #1064	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE	145.21	14
LOBLAWS SUPERMARKETS #1090	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD. STORE #1099	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE	145.21	14

LOBLAWS SUPERMARKETS #1127	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE	145.21	14
LOBLAWS SUPERMARKET #1170	1460 MERIVALE RD OTTAWA ON K2E1P5	ENE	145.21	14
LOBLAW SUPERMARKET #1200	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD. STORE #1208	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD #1082	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
ZEHRS MARKETS	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
ZEHRS MARKETS #539	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
ZEHRS MARKETS	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKET #1032	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS #1194	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD #1188	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14
LOBLAWS SUPERMARKETS LTD #1082	1460 MERIVALE RD OTTAWA ON K2E5P2	ENE	145.21	14

CANADIAN TIRE STORE #258 GORDON C. REID LIMITED	1375 CLYDE AVENUE AT BASELINE OTTAWA ON	SW	188.75	33
CANADIAN TIRE STORE #258 /DES KEON LTD.	1375 CLYDE AVENUE NEPEAN ON K2G3H7	SW	188.75	33
WAL-MART CANADA CORP. STORE #1110	1375 BASELINE RD OTTAWA ON K2C 3G1	NW	200.05	39
WAL-MART CANADA CORP. STORE #1110	1375 BASELINE RD OTTAWA ON K2C 3G1	NW	200.05	39
WAL-MART CANADA CORP. STORE #1110	1375 BASELINE RD OTTAWA ON K2C3G1	NW	200.05	39
WAL-MART CANADA CORP. STORE #1110	1375 BASELINE RD OTTAWA ON K2C3G1	NW	200.05	39
	1375 BASELINE RD OTTAWA ON K2C 3G1	NW	200.05	39
TRENT E JAY ADOTHECARY LTD	1469 MERIVALE RD OTTAWA ON K2E5N9	ESE	243.96	68
A.M. PHARMACARE LIMITED	1469 MERIVALE ROAD OTTAWA ON K2E5N9	ESE	243.96	68
TRENT E JAY ADOTHECARY LTD	1469 MERIVALE RD OTTAWA ON K2E5N9	ESE	243.96	68
A.M. PHARMACARE LIMITED	1469 MERIVALE ROAD OTTAWA ON K2E 5N9	ESE	243.96	68
SHOPPERS DRUG MART #627	1469 MERIVALE RD OTTAWA ON K2E5N9	ESE	243.96	68
A.M. PHARMACARE LIMITED	1469 MERIVALE ROAD OTTAWA ON K2E5N9	ESE	243.96	68

TRENT E JAY APOTHECARY LTD	1469 MERIVALE RD OTTAWA ON K2E5N9	ESE	243.96	68
METRO ONTARIO INC O/A METRO/FOOD BASICS # 907	1465 MERIVALE ROAD, UNIT 13 OTTAWA ON K2E5N9	ESE	246.26	73
METRO ONTARIO INC O/A METRO/FOOD BASICS # 907	1465 Merivale Road, Unit 13 Ottawa ON K2E 5N9	ESE	246.26	73
METRO ONTARIO INC O/A METRO/FOOD BASICS # 907	1465 MERIVALE ROAD, UNIT 13 OTTAWA ON K2E5N9	ESE	246.26	73

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 1 PINC site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
ENBRIDGE GAS INC	1432 BASELINE RD,,OTTAWA,ON, K2C 0A9,CA ON	WSW	180.60	24

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 10 PRT site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON K2E5P2	ENE	145.21	14
SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON K2E5P2	ENE	145.21	14
	1460 MERIVALE RD. NEPEAN, ONT. ON	ENE	145.21	14
C CORP (ONTARIO) INC ATTN ACCOUNTS PAYABLE	1460 MERIVALE RD NEPEAN ON K2E5P2	ENE	145.21	14

CANADIAN TIRE CORP LTD PETROLEUM DIVISION - SUSAN	1400 BASELINE RD OTTAWA ON K2C 0A9	SW	171.56	19
PETRO CANADA NEIGHBOURS	1432 BASELINE RD NEPEAN ON K2C 0A9	WSW	180.60	24
DONALD BELLS PETROLEUM LTD	1468 MERIVALE RD OTTAWA ON K2E 5P1	ESE	203.80	44
FRISBY TIRE CO (1974) LTD	1377 CLYDE AV NEPEAN ON K2G 3H7	SSW	211.92	52
T & P ESSO C/O TED DESROSIERS	1442 BASELINE RD NEPEAN ON K2C 0B2	WSW	248.66	74
SCOTTS ESSO RICHARD SCOTT	1442 BASELINE RD NEPEAN ON K2C3Z4	WSW	248.66	74

REC - Ontario Regulation 347 Waste Receivers Summary

A search of the REC database, dated 1986-1990, 1992-2021 has found that there are 1 REC site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
BBS ONTARIO INCORPORATED	CJOH-TV 1500 MERIVALE ROAD NEPEAN ON K2E 6Z5	SSW	131.82	12

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004 - 31 Jan, 2026 has found that there are 2 RSC site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Clydesdale Shopping Centres Limited	1357 BASELINE RD ON OTTAWA ON	N	123.95	10
Reno Realty Holdings Limited	1460 Merivale Road Ottawa, Ontario, K2E 5P2 OTTAWA ON	ENE	145.21	14

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Apr 30, 2025 has found that there are 10 RST site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
SUNYS PETROLEUM INC	1460 MERIVALE RD NEPEAN ON K2E5P2	ENE	145.21	14
PETRO-CANADA	1432 BASELINE RD OTTAWA ON K2C0A9	WSW	180.60	24
NEIGHBOUR'S PETRO-CANADA	1432 BASELINE RD OTTAWA ON K2C 0A9	WSW	180.60	24
NEIGHBOUR'S PETRO-CANADA	1432 BASE LINE RD OTTAWA ON K2C0A9	WSW	180.60	24
PETRO-CANADA	1432 BASELINE RD OTTAWA ON K2C 0A9	WSW	180.60	24
SWAN'S GARAGE	1486 MERIVALE RD NEPEAN ON K2E 6Z5	SSE	235.10	66
SWAN'S GARAGE	1486 MERIVALE RD NEPEAN ON K2E6Z5	SSE	235.10	66
MR LUBE	1442 BASELINE RD OTTAWA ON K2C0B2	WSW	248.66	74
MR LUBE	1442 BASELINE RD OTTAWA ON K2C 0B2	WSW	248.66	74
MR LUBE	1442 BASELINE RD OTTAWA ON K2C0B2	WSW	248.66	74

SCT - Scott's Manufacturing Directories

A search of the SCT database, dated 1992-Mar 2011; Feb 2025 has found that there are 5 SCT site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Warrenty Communications Inc.	1500 Merivale Rd Ottawa ON K2E 6Z5	SSW	131.82	12
Motor Sports World	1375 Clyde Ave. Ottawa ON K2G3H7	SW	188.75	33
Scouting Life	1345 Baseline Rd Unit 100 Ottawa ON K2C 0A7	NE	204.39	45
Kal Tire	1377 Clyde Ave. Nepean ON K2G3H7	SSW	211.92	52
Versaterm Public Safety Inc	1331 Clyde Ave. Ottawa ON K2C3G4	WNW	244.27	69

SPL - Ontario Spills

A search of the SPL database, dated 1988-Dec 2025 has found that there are 19 SPL site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
OTTAWA BOARD OF EDUCATION	1357 BASELINE ROAD OTTAWA CITY ON K2C 0A8	N	123.95	10
Walmart Canada Corp.	1357 Baseline Rd Ottawa ON	N	123.95	10
Parson Refrigeration (1985) Ltd.	1460 Merivale Rd Ottawa ON	ENE	145.21	14
Loblaws Inc.	1460 Merivale Road Ottawa ON K2E 5P2	ENE	145.21	14

Loblaw Companies Limited	1460 Merivale Road Ottawa ON	ENE	145.21	14
Seaboard Transport	1460 Merivale Rd Ottawa ON K2E 5P2	ENE	145.21	14
	1460 Merivale, Ottawa OTTAWA ON	ENE	145.21	14
Loblaws Companies East	1460 Merivale Rd. Ottawa ON	ENE	145.21	14
NATIONAL GROCERIES COMPANY LTD	1460 MERIVALE RD OTTAWA CITY ON	ENE	145.21	14
NATIONAL GROCERIES COMPANY LTD	1460 MERIVALE RD OTTAWA CITY ON	ENE	145.21	14
PETRO-CANADA	1432 BASELINE RD. AT CLYDE SERVICE STATION OTTAWA CITY ON K2C 0A9	WSW	180.60	24
Petro-Canada	1432 Baseline Road, Ottawa ON K2C 0A9	WSW	180.60	24
	1432 Baseline Road, Ottawa, ON, Canada OTTAWA ON	WSW	180.60	24
	Value Village Parking Lot, 1375 Clyde Ave.<UNOFFICIAL> Ottawa ON	SW	188.75	33
	1375 Clyde Avenue Ottawa, ON OTTAWA ON	SW	188.75	33
	1345 Baseline. Ottawa OTTAWA ON	NE	204.39	45
FRISBEE TIRE	1377 CLYDE NEPEAN CITY ON K2G 3H7	SSW	211.92	52

Parson Refrigeration (1985) Ltd.	1465 Meriville Road Ottawa ON	ESE	246.26	73
Mr. Lube<UNOFFICIAL>	1442 Baseline Road Ottawa ON	WSW	248.66	74

WWIS - Water Well Information System

A search of the WWIS database, dated Jul 31, 2025 has found that there are 42 WWIS site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
	ON ***Well ID:*** 7362775	NNW	16.85	1
	lot 35 con A ON ***Well ID:*** 1504614	WSW	61.96	4
	ON ***Well ID:*** 1507864	W	72.15	7
	ON ***Well ID:*** 1507863	W	102.96	9
	1331 CLYDE AVE. Ottawa ON ***Well ID:*** 7207624	WSW	170.60	17
	1331 CLYDE AVE. Ottawa ON ***Well ID:*** 7207625	WSW	170.64	18
	ON ***Well ID:*** 7479650	WSW	172.68	20
	ON ***Well ID:*** 7479648	WSW	176.96	22

lot 35 con A ON ***Well ID:*** 1504637	SE	177.88	**23**
lot 35 con A ON ***Well ID:*** 1504638	SE	181.54	**26**
1500 MERIVALE RD. Ottawa ON ***Well ID:*** 7207631	SE	183.22	**27**
 ON ***Well ID:*** 7474014	WSW	183.29	**28**
lot 35 con A ON ***Well ID:*** 1504627	E	184.83	**29**
 ON ***Well ID:*** 7242904	ESE	187.36	**30**
1331 CLYDE AVE. Ottawa ON ***Well ID:*** 7207626	WSW	188.12	**32**
1500 MERRIVALE RD. ON ***Well ID:*** 7053696	SE	191.14	**35**
 ON ***Well ID:*** 7473512	SE	193.38	**36**
1300 BASELINE RD Ottawa ON ***Well ID:*** 7187998	NE	195.81	**37**
1300 BASELINE RD Ottawa ON ***Well ID:*** 7187999	NE	195.81	**37**
 ON ***Well ID:*** 7479649	WSW	198.69	**38**
1500 MERIVALE RD. Ottawa ON	SE	200.17	**40**

Well ID: 7207634

ON	WSW	202.09	42

Well ID: 7474013

1500 MERIVALE RD. ON	SE	202.14	43

Well ID: 7207630

ON	WSW	206.25	46

Well ID: 7474032

ON	SE	209.03	48

Well ID: 7473508

1500 MERIVALE RD. Ottawa ON	SE	209.26	49

Well ID: 7207632

1500 MERIVALE ROAD Ottawa ON	SSW	210.00	50

Well ID: 7207637

1500 MERIVALE RD OTTAWA ON	SSE	210.39	51

Well ID: 7210900

1345 BASELINE ROAD Ottawa ON	NE	212.41	53

Well ID: 7413944

ON	SE	213.06	54

Well ID: 7473511

lot 35 con A ON	WSW	213.24	55

Well ID: 1504629


1500 MERIVALE RD. Ottawa ON	SE	213.50	57

Well ID: 7207633

1500 MERIVALE RD OTTAWA ON	SE	214.21	58

Well ID: 7210888

1490 MERRIVALE ROAD OTTAWA ON ***Well ID:*** 7046663	SSE	217.91	**59**
ON ***Well ID:*** 7473513	SE	217.93	**60**
ON ***Well ID:*** 7473510	SE	220.42	**61**
lot 35 con A ON ***Well ID:*** 1504634	ESE	220.95	**62**
lot 35 con A ON ***Well ID:*** 1504632	ESE	228.00	**63**
lot 35 con A ON ***Well ID:*** 1504611	SSE	233.79	**64**
1442 BASELINE RD. OTTAWA ON ***Well ID:*** 7267376	WSW	243.78	**67**
1500 MERIVALE RD. Ottawa ON ***Well ID:*** 7207636	S	244.65	**70**
lot 35 con A ON ***Well ID:*** 1504618	SE	244.69	**71**



Map: 0.25 Kilometer Radius

Order Number: 26022000176


Address: 1500 Merivale Road, Nepean, ON

ERIS

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Aerial


Year: 2025

Order Number: 26022000176

Address: 1500 Merivale Road, Nepean, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Address: 1500 Merivale Road, ON

Source: ESRI World Topographic Map

Order Number: 26022000176

ERIS

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	1 of 15	SSW/131.8	98.9 / -1.03	CTVGlobemedia Inc. 1500 Merivale Rd Ottawa ON	CA

Certificate #: 4641-7WKHL8
Application Year: 2009
Issue Date: 11/24/2009
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	2 of 15	SSW/131.8	98.9 / -1.03	CLARIDGE HOMES (BASELINE PAHSE 1) LIMITED PARTNERSHIP 1500 Merivale RD Ottawa ON K2C 0A9	EASR

Approval No: R-009-1339841166
Status: REGISTERED
Date: January 6, 2026
Record Type: EASR
Link Source: MOFA
Project Type: Water Taking - Construction Dewatering
Full Address:
MOE District: Ottawa
Municipality: Ottawa
Latitude: 45.36055556
Longitude: -75.73694444
Geometry X:
Geometry Y:
Approval Type: EASR-Water Taking - Construction Dewatering
SWP Area Name: Rideau Valley
PDF NAICS Code:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=4387304
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	3 of 15	SSW/131.8	98.9 / -1.03	CTVGlobemedia Inc. 1500 Merivale Road Ottawa K2E 6Z5 CITY OF OTTAWA ON	EBR

EBR Registry No: 010-7874
Ministry Ref No: 2097-7VYNC3
Notice Type: Instrument Decision
Section:
Notice Stage:
Act 1:
Act 2:
Site Location Map:
Decision Posted:
Exception Posted:
Bulletin Posted:
Appeal Posted:
Notice Date: November 30, 2009
Proposal Date: September 23, 2009
Year: 2009
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Company Name: CTVGlobemedia Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1500 Merivale Road, Ottawa Ontario, Canada K2E 6Z5
Comment Period:
URL:
Summary:

Site Location Details:

1500 Merivale Road Ottawa K2E 6Z5 CITY OF OTTAWA

---

12 | 4 of 15 | SSW/131.8 | 98.9 / -1.03 | **CTVGlobemedia Inc.**
1500 Merivale Rd
Ottawa ON K2E 6Z5 | ECA

Approval No: 4641-7WKHL8
Approval Date: 2009-11-24
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: CTVGlobemedia Inc.
Address: 1500 Merivale Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2097-7VYNC3-14.pdf
PDF Site Location:
MOE District: Ottawa
City:
Longitude: -75.73666
Latitude: 45.3606
Geometry X:
Geometry Y:

---

12 | 5 of 15 | SSW/131.8 | 98.9 / -1.03 | **1500 Merivale Road**
Ottawa ON | EHS

Order No: 20071030033
Status: C
Report Type: CAN - Custom Report
Report Date: 11/8/2007
Date Received: 10/30/2007
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps And /or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State:
Search Radius (km): 0.25
X: -75.736641
Y: 45.358807

---

12 | 6 of 15 | SSW/131.8 | 98.9 / -1.03 | **1500 Merivale Road**
Nepean ON K2E 6Z5 | EHS

Order No: 21092700446
Status: C
Report Type: Standard Report
Report Date: 30-SEP-21
Date Received: 27-SEP-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.7372243
Y: 45.360793

---

12 | 7 of 15 | SSW/131.8 | 98.9 / -1.03 | **1490 and 1500 Merivale Road**
Nepean ON K2E 6Z5 | EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No: 20300800342
Status: C
Report Type: Custom Report
Report Date: 13-OCT-20
Date Received: 08-OCT-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.7372243
Y: 45.360793

12	8 of 15	SSW/131.8	98.9 / -1.03	NATION'S CAPITAL TELEVISION INCORPORATED CJOH-TV 1500 MERIVALE ROAD NEPEAN ON K2E 6Z5	GEN

Generator Info

Generator No: ON1540500
Approval Years: 92,93,97,98,99,00,01,02,03,04
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: TV BROADCASTING

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4812

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

12	9 of 15	SSW/131.8	98.9 / -1.03	NATION'S CAPITAL TELEVISION INC. 28-832 CJOH-TV 1500 MERIVALE ROAD NEPEAN ON K2E 6Z5	GEN

Generator Info

Generator No: ON1540500
Approval Years: 94,95,96
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: TV BROADCASTING

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4812

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

12	10 of 15	SSW/131.8	98.9 / -1.03	Aim Group 1500 Merivale Ottawa ON	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON5935599	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	562910
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	*11 of 15*	*SSW/131.8*	*98.9 / -1.03*	***Aim Environmental Group*** ***1500 Merivale Road*** ***Ottawa ON***	***GEN***

Generator Info

Generator No:	ON2846570	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	541620
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	*12 of 15*	*SSW/131.8*	*98.9 / -1.03*	***Aim Environmental Group*** ***1500 Merivale Road*** ***Ottawa ON***	***GEN***

Generator Info

Generator No:	ON2846570	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	541620
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Environmental Consulting Services		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	*13 of 15*	*SSW/131.8*	*98.9 / -1.03*	***CJOH TV*** ***1500 MERIVALE RD.*** ***OTTAWA ON***	***NPCB***

Company Code:	O3263
Industry:	TELEPHONE.TELECOMMUNICATION
Site Status:	DELETED FEDERAL SITES
Transaction Date:	10/9/1996
Inspection Date:	5/9/1996

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	*14 of 15*	*SSW/131.8*	*98.9 / -1.03*	***BBS ONTARIO INCORPORATED*** ***CJOH-TV 1500 MERIVALE ROAD*** ***NEPEAN ON K2E 6Z5***	***REC***

ID:		***Province In:***	ONTARIO
Company ID:		***Province Out:***	
Receiver No:	402-92A003	***County Out:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin: | **Mail Addr:**
Choice of Contact: | **Site PO Box:**
Rec Div:
Rec Op Div:
Rec Op Name:
Site Bldg:
Facility Type: PCB STORAGE SITE
Approval Yrs: 1995; 1996; 1997; 1998; 1999; 2000; 2001; 2002; 2003; 2004; 2005; 2006; 2007; 2008

1999 Receiver Waste Information Details

Waste Code: 243
Waste Desc: PCB'S

12	15 of 15	SSW/131.8	98.9 / -1.03	Warrenty Communications Inc. 1500 Merivale Rd Ottawa ON K2E 6Z5	SCT

Scott S ID: 19190793
Latitude:
Longitude:

Historical Details

Established: 1993
Plant Size (ft²):
Employment: 8

Historical Details

Description: Periodical Publishers
SIC/NAICS Code: 511120

27	1 of 1	SE/183.2	98.6 / -1.34	1500 MERIVALE RD. Ottawa ON	WWIS

Well ID: 7207631
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z173585
Tag: A150758
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 09/12/2013
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1004561999
Tag No: A150758

Depth (m):	4.57	**Contractor:**	7241
Year Completed:	2013	**Latitude:**	45.3607552276947
Well Completed Dt:	08/06/2013	**Longitude:**	-75.7353759860333
Audit No:	Z173585	**Point Y:**	45.360755221023055
Path:		**Point X:**	-75.73537582420795

Bore Hole Information

Bore Hole ID:	1004561999	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442406.00
Code OB Desc:		**North83:**	5023290.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/06/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004597590
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 85
Material 2 Desc: SOFT
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004597593
Layer: 4
Color: 2
General Color: GREY
Material 1: 34
Material 1 Desc: TILL
Material 2: 73
Material 2 Desc: HARD
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 3.0999999046325684
Formation End Depth: 4.570000171661377
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	1004597591
Layer:	2
Color:	2
General Color:	GREY
Material 1:	34
Material 1 Desc:	TILL
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	68
Material 3 Desc:	DRY
Formation Top Depth:	0.6100000143051147
Formation End Depth:	1.8300000429153442
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597592
Layer:	3
Color:	2
General Color:	GREY
Material 1:	34
Material 1 Desc:	TILL
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	1.8300000429153442
Formation End Depth:	3.0999999046325684
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004597601
Layer:	1
Plug From:	
Plug To:	0.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004597602
Layer:	2
Plug From:	0.0
Plug To:	1.2200000286102295
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004597603
Layer:	3
Plug From:	1.2200000286102295
Plug To:	4.570000171661377
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004597600

Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004597589
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004597596
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004597597
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 4.570000171661377
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004597595
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004597594
Diameter: 8.25
Depth From: 0.0
Depth To: 4.570000171661377
Hole Depth UOM: m
Hole Diameter UOM: cm

---

34 | ***1 of 1*** | ***SE/190.2*** | ***98.9 / -1.03*** | ***Part of 1500 Merivale Road Nepean ON K2E 6Z5*** | ***EHS***

Order No: 24030800575
Status: C
Report Type: Standard Report
Report Date: 13-MAR-24
Date Received: 08-MAR-24
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.7358795

Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Y: 45.3604337

---

35 | **1 of 1** | **SE/191.1** | **98.9 / -1.03** | **1500 MERRIVALE RD. ON** | **WWIS**

Well ID:	7053696	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	0	**Date Received:**	12/13/2007
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z61709	**Contractor:**	7241
Tag:	A063281	**Form Version:**	4
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: OTTAWA CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/705\7053696.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/23/2007
Year Completed:	2007
Depth (m):	4.57
Latitude:	45.3604371637772
Longitude:	-75.7358442893362
Point X:	-75.73584412751548
Point Y:	45.360437157161584
Path:	705\7053696.pdf

Bore Hole Information

Bore Hole ID:	23053696	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442369.00
Code OB Desc:		**North83:**	5023255.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	11/23/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID:	1001488198
Layer:	3
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	2.4000000953674316
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1001488197
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	0.30000001192092896
Formation End Depth:	2.4000000953674316
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1001488196
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	28
Material 3 Desc:	SAND
Formation Top Depth:	0.0
Formation End Depth:	0.30000001192092896
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1001488201
Layer:	2
Plug From:	0.30000001192092896
Plug To:	1.2200000286102295
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID: 1001488202
Layer: 3
Plug From: 1.2200000286102295
Plug To: 4.570000171661377
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1001488200
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1001488207
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: GEOPROBE

Pipe Information

Pipe ID: 1001488194
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1001488204
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.5
Casing Diameter: 3.809999942779541
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1001488205
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1001488195
Pump Set At:
Static Level:
Final Level After Pumping:

Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1001488203
Layer: 1
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1001488199
Diameter: 8.890000343322754
Depth From:
Depth To: 4.570000171661377
Hole Depth UOM: m
Hole Diameter UOM: cm

---

40 | ***1 of 1*** | ***SE/200.2*** | ***98.9 / -1.03*** | ***1500 MERIVALE RD. Ottawa ON*** | ***WWIS***

Well ID: 7207634
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z173589
Tag: A150755
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 09/12/2013
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1004562008
Depth (m): 3.96
Year Completed: 2013
Well Completed Dt: 08/06/2013
Audit No: Z173589

Tag No: A150755
Contractor: 7241
Latitude: 45.3603379925219
Longitude: -75.7358685401487
Point Y: 45.3603379860658

Path:		***Point X:***	-75.73586837843526

Bore Hole Information

Bore Hole ID:	1004562008	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442367.00
Code OB Desc:		***North83:***	5023244.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/06/2013	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004597639
Layer:	4
Color:	2
General Color:	GREY
Material 1:	34
Material 1 Desc:	TILL
Material 2:	73
Material 2 Desc:	HARD
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	3.0999999046325684
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597638
Layer:	3
Color:	2
General Color:	GREY
Material 1:	34
Material 1 Desc:	TILL
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	1.8300000429153442
Formation End Depth:	3.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597636
Layer:	1
Color:	8
General Color:	BLACK

Material 1: 02
Material 1 Desc: TOPSOIL
Material 2: 77
Material 2 Desc: LOOSE
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004597637
Layer: 2
Color: 2
General Color: GREY
Material 1: 34
Material 1 Desc: TILL
Material 2: 85
Material 2 Desc: SOFT
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 0.3100000023841858
Formation End Depth: 1.8300000429153442
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597647
Layer: 1
Plug From: 0.9100000262260437
Plug To: 0.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597648
Layer: 2
Plug From: 0.0
Plug To: 0.6100000143051147
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597649
Layer: 3
Plug From: 0.6100000143051147
Plug To: 3.9600000381469727
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004597646
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID:	1004597635
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004597642
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004597643
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.829999923706055

Water Details

Water ID:	1004597641
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004597640
Diameter:	8.25
Depth From:	0.0
Depth To:	3.9600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

43 ***1 of 1*** ***SE/202.1*** ***98.6 / -1.34*** ***1500 MERIVALE RD. ON*** ***WWIS***

Well ID:	7207630	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	09/12/2013
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z173584	***Contractor:***	7241
Tag:	A150759	***Form Version:***	7

Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1004561996	**Tag No:**	A150759
Depth (m):	5.49	**Contractor:**	7241
Year Completed:	2013	**Latitude:**	45.3606666187919
Well Completed Dt:	08/06/2013	**Longitude:**	-75.7351577776541
Audit No:	Z173584	**Point Y:**	45.36066661223745
Path:		**Point X:**	-75.7351576163187

Bore Hole Information

Bore Hole ID:	1004561996	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442423.00
Code OB Desc:		**North83:**	5023280.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/06/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004597577
Layer:	3
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	1.8300000429153442
Formation End Depth:	3.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597575
Layer:	1

Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 85
Material 2 Desc: SOFT
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004597578
Layer: 4
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 3.0999999046325684
Formation End Depth: 5.489999771118164
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004597576
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.6100000143051147
Formation End Depth: 1.8300000429153442
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597586
Layer: 1
Plug From:
Plug To: 0.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597587
Layer: 2
Plug From: 0.0
Plug To: 2.140000104904175

Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597588
Layer: 3
Plug From: 2.140000104904175
Plug To: 5.489999771118164
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004597585
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004597574
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004597581
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.440000057220459
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004597582
Layer: 1
Slot: 10
Screen Top Depth: 2.440000057220459
Screen End Depth: 5.489999771118164
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004597580
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Hole ID: 1004597579
Diameter: 8.25
Depth From: 0.0
Depth To: 5.489999771118164
Hole Depth UOM: m
Hole Diameter UOM: cm

---

49 | **1 of 1** | **SE/209.3** | **98.9 / -1.03** | **1500 MERIVALE RD. Ottawa ON** | **WWIS**

Well ID: 7207632
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z173586
Tag: A150757
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 09/12/2013
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1004562002
Depth (m): 3.96
Year Completed: 2013
Well Completed Dt: 08/06/2013
Audit No: Z173586
Path:

Tag No: A150757
Contractor: 7241
Latitude: 45.3603304723033
Longitude: -75.7356386153053
Point Y: 45.36033046534064
Point X: -75.73563845291848

Bore Hole Information

Bore Hole ID: 1004562002
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 08/06/2013
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 442385.00
North83: 5023243.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004597607
Layer: 3
Color: 2
General Color: GREY
Material 1: 34
Material 1 Desc: TILL
Material 2:
Material 2 Desc:
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 1.5
Formation End Depth: 1.8300000429153442
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004597608
Layer: 4
Color: 2
General Color: GREY
Material 1: 34
Material 1 Desc: TILL
Material 2: 73
Material 2 Desc: HARD
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 1.8300000429153442
Formation End Depth: 3.9600000381469727
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004597605
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 85
Material 2 Desc: SOFT
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 0.0
Formation End Depth: 0.9100000262260437
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004597606
Layer: 2
Color: 2
General Color: GREY
Material 1: 34
Material 1 Desc: TILL
Material 2: 73
Material 2 Desc: HARD
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 0.9100000262260437

Formation End Depth: 1.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597617
Layer: 2
Plug From: 0.0
Plug To: 0.6100000143051147
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597618
Layer: 3
Plug From: 0.6100000143051147
Plug To: 3.9600000381469727
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597616
Layer: 1
Plug From: 0.8100000023841858
Plug To: 0.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004597615
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004597604
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004597611
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.9100000262260437
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004597612

Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004597610
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004597609
Diameter:	8.25
Depth From:	0.0
Depth To:	3.9600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

50 | ***1 of 1*** | ***SSW/210.0*** | ***98.9 / -1.03*** | ***1500 MERIVALE ROAD Ottawa ON*** | ***WWIS***

Well ID:	7207637	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	09/12/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z168655	**Contractor:**	7241
Tag:	A116687	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1004562017	**Tag No:**	A116687
Depth (m):	6.1	**Contractor:**	7241
Year Completed:	2013	**Latitude:**	45.3601029312932
Well Completed Dt:	08/06/2013	**Longitude:**	-75.737423205455
Audit No:	Z168655	**Point Y:**	45.360102924008196
Path:		**Point X:**	-75.73742304369333

Bore Hole Information

Bore Hole ID:	1004562017	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442245.00
Code OB Desc:		**North83:**	5023219.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/06/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004597680
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597681
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597682
Layer:	3
Color:	2
General Color:	GREY
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	

Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 1.2200000286102295
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597691
Layer: 1
Plug From: 0.0
Plug To: 2.740000009536743
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597692
Layer: 2
Plug From: 2.740000009536743
Plug To: 6.099999904632568
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004597690
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1004597679
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004597686
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004597687
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm

Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004597685
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004597683
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 1.5199999809265137
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004597684
Diameter: 7.619999885559082
Depth From: 1.5199999809265137
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

---

51 | ***1 of 1*** | ***SSE/210.4*** | ***98.9 / -1.03*** | ***1500 MERIVALE RD OTTAWA ON*** | ***WWIS***

Well ID:	7210900	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	11/12/2013
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z177957	***Contractor:***	7241
Tag:	A154248	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	

Municipality: NEPEAN TOWNSHIP
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7210900.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/03/2013
Year Completed: 2013
Depth (m): 4.27
Latitude: 45.3601560056896

Longitude: -75.7361726165087
Point X: -75.73617245537868
Point Y: 45.36015599900123
Path: 721\7210900.pdf

Bore Hole Information

Bore Hole ID:	1004627080	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442343.00
Code OB Desc:		**North83:**	5023224.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/03/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004883207
Layer: 3
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 28
Material 2 Desc: SAND
Material 3: 06
Material 3 Desc: SILT
Formation Top Depth: 0.9100000262260437
Formation End Depth: 4.269999980926514
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004883205
Layer: 1
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 73
Material 2 Desc: HARD
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004883206

Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.3100000023841858
Formation End Depth: 0.9100000262260437
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004883215
Layer: 1
Plug From: 0.0
Plug To: 1.2200000286102295
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004883216
Layer: 2
Plug From: 1.2200000286102295
Plug To: 4.269999980926514
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004883214
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004883204
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004883210
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.2200000286102295
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004883211

Layer:	1
Slot:	10
Screen Top Depth:	1.2200000286102295
Screen End Depth:	4.269999980926514
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004883209
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004883208
Diameter:	8.25
Depth From:	0.0
Depth To:	4.269999980926514
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

57 | ***1 of 1*** | ***SE/213.5*** | ***98.9 / -1.03*** | ***1500 MERIVALE RD. Ottawa ON*** | ***WWIS***

Well ID:	7207633	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	09/12/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z173588	**Contractor:**	7241
Tag:	A150756	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1004562005	**Tag No:**	A150756
Depth (m):	5.49	**Contractor:**	7241
Year Completed:	2013	**Latitude:**	45.3602579739817
Well Completed Dt:	08/06/2013	**Longitude:**	-75.7357142847908
Audit No:	Z173588	**Point Y:**	45.36025796723657
Path:		**Point X:**	-75.73571412338585

Bore Hole Information

Bore Hole ID:	1004562005	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442379.00
Code OB Desc:		**North83:**	5023235.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/06/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004597622
Layer:	3
Color:	2
General Color:	GREY
Material 1:	34
Material 1 Desc:	TILL
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	1.8300000429153442
Formation End Depth:	3.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597623
Layer:	4
Color:	2
General Color:	GREY
Material 1:	34
Material 1 Desc:	TILL
Material 2:	73
Material 2 Desc:	HARD
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	3.0999999046325684
Formation End Depth:	5.489999771118164
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597620
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND

Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.9100000262260437
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004597621
Layer: 2
Color: 2
General Color: GREY
Material 1: 34
Material 1 Desc: TILL
Material 2: 73
Material 2 Desc: HARD
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 0.9100000262260437
Formation End Depth: 1.8300000429153442
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597634
Layer: 4
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597631
Layer: 1
Plug From: 0.9100000262260437
Plug To: 0.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597633
Layer: 3
Plug From: 2.140000104904175
Plug To: 5.489999771118164
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004597632
Layer: 2
Plug From: 0.0
Plug To: 2.140000104904175
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004597630
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004597619
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004597626
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.440000057220459
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004597627
Layer: 1
Slot: 10
Screen Top Depth: 2.440000057220459
Screen End Depth: 5.489999771118164
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004597625
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004597624
Diameter: 8.25
Depth From: 0.0
Depth To: 5.489999771118164
Hole Depth UOM: m
Hole Diameter UOM: cm

---

58 | ***1 of 1*** | ***SE/214.2*** | ***98.9 / -1.03*** | ***1500 MERIVALE RD OTTAWA ON*** | ***WWIS***

Well ID: 7210888
Construction Date:
Use 1st: Monitoring and Test Hole
Flowing (Y/N):
Flow Rate:
Data Entry Status:

Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	11/12/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z177956	**Contractor:**	7241
Tag:	A154298	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NEPEAN TOWNSHIP
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7210888.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/03/2013
Year Completed: 2013
Depth (m): 5.79
Latitude: 45.3602947165359
Longitude: -75.7355998473963
Point X: -75.73559968523998
Point Y: 45.36029470989362
Path: 721\7210888.pdf

Bore Hole Information

Bore Hole ID:	1004626925	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442388.00
Code OB Desc:		**North83:**	5023239.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/03/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004883018
Layer: 1
Color: 8
General Color: BLACK
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 73
Material 2 Desc: HARD
Material 3:
Material 3 Desc:

Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004883019
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.3100000023841858
Formation End Depth: 1.8300000429153442
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004883020
Layer: 3
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 28
Material 3 Desc: SAND
Formation Top Depth: 1.8300000429153442
Formation End Depth: 5.789999961853027
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004883029
Layer: 2
Plug From: 2.440000057220459
Plug To: 5.789999961853027
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004883028
Layer: 1
Plug From: 0.0
Plug To: 2.440000057220459
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004883027
Method Construction Code: D
Method Construction: Direct Push

Other Method Construction:

Pipe Information

Pipe ID: 1004883017
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004883023
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.740000009536743
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004883024
Layer: 1
Slot: 10
Screen Top Depth: 2.7899999618530273
Screen End Depth: 3.7899999618530273
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004883022
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004883021
Diameter: 8.25
Depth From: 0.0
Depth To: 5.789999961853027
Hole Depth UOM: m
Hole Diameter UOM: cm

---

70 | ***1 of 1*** | ***S/244.6*** | ***98.9 / -1.03*** | ***1500 MERIVALE RD. Ottawa ON*** | ***WWIS***

Well ID: 7207636
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 09/12/2013
Selected Flag: TRUE
Abandonment Rec:

Audit No:	Z173596	**Contractor:**	7241
Tag:	A106706	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1004562014	**Tag No:**	A106706
Depth (m):	6.1	**Contractor:**	7241
Year Completed:	2013	**Latitude:**	45.3597635451018
Well Completed Dt:	08/07/2013	**Longitude:**	-75.737010218722
Audit No:	Z173596	**Point Y:**	45.359763538175045
Path:		**Point X:**	-75.73701005688179

Bore Hole Information

Bore Hole ID:	1004562014	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442277.00
Code OB Desc:		**North83:**	5023181.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/07/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004597666
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.3100000023841858
Formation End Depth:	2.130000114440918
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597667
Layer:	3
Color:	2
General Color:	GREY
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	74
Material 2 Desc:	LAYERED
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	2.130000114440918
Formation End Depth:	6.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004597665
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004597677
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.740000009536743
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004597678
Layer:	3
Plug From:	2.740000009536743
Plug To:	6.099999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004597676
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004597675

Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1004597664
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004597671
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004597672
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004597670
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004597668
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 3.0999999046325684
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004597669
Diameter: 7.619999885559082
Depth From: 3.0999999046325684
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	NNW/16.8	99.9 / -0.03	ON	WWIS

Well ID: 7362775
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C47878
Tag: A267645
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 07/16/2020
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7328
Form Version: 8
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/736\7362775.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/05/2019
Year Completed: 2019
Depth (m):
Latitude: 45.3621128690483
Longitude: -75.7370151854978
Point X: -75.73701502346613
Point Y: 45.362112862156536
Path: 736\7362775.pdf

Bore Hole Information

Bore Hole ID: 1008376522
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/05/2019
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 442279.00
North83: 5023442.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 2	NNW/30.2	99.9 / -0.03	1374 Baseline Rd Ottawa ON K2C0A9	EHS

Order No: 20150903023
Status: C

Nearest Intersection:
Municipality:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	09-SEP-15	**Search Radius (km):**	.25
Date Received:	03-SEP-15	**X:**	-75.737033
Previous Site Name:		**Y:**	45.362233
Lot/Building Size:			
Additional Info Ordered:			

---

2 | **2 of 2** | **NNW/30.2** | **99.9 / -0.03** | **1374 Baseline Road Ottawa ON K2C 0A9** | **EHS**

Order No:	20190911012	**Nearest Intersection:**	
Status:	C	**Municipality:**	Ottawa
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	17-SEP-19	**Search Radius (km):**	.25
Date Received:	11-SEP-19	**X:**	-75.737033
Previous Site Name:		**Y:**	45.362233
Lot/Building Size:	10,247.23 ft² (0.235 ac)		
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

---

3 | **1 of 1** | **SE/42.9** | **98.8 / -1.09** | **Kimway Cres Ottawa ON** | **EHS**

Order No:	20120608027	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	15-JUN-12	**Search Radius (km):**	.25
Date Received:	08-JUN-12	**X:**	-75.736611
Previous Site Name:		**Y:**	45.361671
Lot/Building Size:			
Additional Info Ordered:			

---

4 | **1 of 1** | **WSW/62.0** | **99.9 / -0.03** | **lot 35 con A ON** | **WWIS**

Well ID:	1504614	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Public	**Data Entry Status:**	
Use 2nd:	Domestic	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	01/30/1956
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	3566
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	035
Depth to Bedrock:		**Concession:**	A
Well Depth:		**Concession Name:**	RF
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504614.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/05/1955

Year Completed:	1955
Depth (m):	41.7576
Latitude:	45.3616588577032
Longitude:	-75.7376260083008
Point X:	-75.73762584625442
Point Y:	45.36165885128133
Path:	150\1504614.pdf

Bore Hole Information

Bore Hole ID:	10026657	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442230.70
Code OB Desc:		**North83:**	5023392.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	10/05/1955	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:	
Location Source Date:	
Improvement Location Source:	
Improvement Location Method:	
Source Revision Comment:	
Supplier Comment:	

Overburden and Bedrock Materials Interval

Formation ID:	930999969
Layer:	1
Color:	3
General Color:	BLUE
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	40.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930999970
Layer:	2
Color:	8
General Color:	BLACK
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	40.0
Formation End Depth:	137.0
Formation End Depth UOM:	ft

Method of Construction & Well

Use

Method Construction ID:	961504614
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10575227
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930046042
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	18.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930046043
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	137.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991504614
Pump Set At:	
Static Level:	27.0
Final Level After Pumping:	37.0
Recommended Pump Depth:	
Pumping Rate:	12.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933457908
Layer:	3

Kind Code: 1
Kind: FRESH
Water Found Depth: 135.0
Water Found Depth UOM: ft

Water Details

Water ID: 933457906
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 60.0
Water Found Depth UOM: ft

Water Details

Water ID: 933457907
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 100.0
Water Found Depth UOM: ft

---

5 | **1 of 1** | **WSW/71.4** | **99.9 / -0.03** | **TDL GROUP LIMITED**
1384 BASELINE ROAD (SWM)
OTTAWA ON K2C 0A9 | **CA**

Certificate #: 3-0191-98-
Application Year: 98
Issue Date: 4/15/1998
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

6 | **1 of 1** | **W/72.2** | **99.9 / -0.03** | **ON** | **BORE**

Borehole ID: 612619
OGF ID: 215513925
Status:
Type: Borehole
Use:
Completion Date: FEB-1953
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 68.6
Depth Ref: Ground Surface
Depth Elev:
Drill Method:
Orig Ground Elev m: 94.5
Elev Reliabil Note:
DEM Ground Elev m: 101
Concession:
Location D:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 45.361929
Longitude DD: -75.737885
UTM Zone: 18
Easting: 442211
Northing: 5023422
Location Accuracy:
Accuracy: Not Applicable

Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218391841	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND.		

Geology Stratum ID:	218391842	**Mat Consistency:**	Compact
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	68.6	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Limestone	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	LIMESTONE. GREY. 0006003.0 FEET. FEET.FF. TILL. LOOSE TO COMPACT. SAND. LOOSE TO CO **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:		**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 05127 NTS_Sheet:		
Confiden 1:			

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

7 **1 of 1** **W/72.2** **99.9 / -0.03** **ON** **WWIS**

Well ID:	1507864	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Public	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	04/17/1953
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	3725
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON

Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1507864.pdf

Additional Detail(s) (Map)

Well Completed Date:	02/17/1953
Year Completed:	1953
Depth (m):	68.58
Latitude:	45.3619272265142
Longitude:	-75.7378848667048
Point X:	-75.73788470557652
Point Y:	45.36192721998371
Path:	150\1507864.pdf

Bore Hole Information

Bore Hole ID:	10029899	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442210.70
Code OB Desc:		**North83:**	5023422.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	9
Date Completed:	02/17/1953	**UTMRC Desc:**	unknown UTM
Remarks:		**Location Method:**	p9
Location Method Desc:	Original Pre1985 UTM Rel Code 9: unknown UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931008227
Layer:	1
Color:	
General Color:	
Material 1:	09
Material 1 Desc:	MEDIUM SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931008228
Layer:	2
Color:	2
General Color:	GREY
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	10.0
Formation End Depth:	225.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961507864
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10578469
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930052454
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	16.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930052455
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	225.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991507864
Pump Set At:	
Static Level:	35.0
Final Level After Pumping:	35.0
Recommended Pump Depth:	
Pumping Rate:	5.0

Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933462145
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 150.0
Water Found Depth UOM: ft

Water Details

Water ID: 933462144
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 60.0
Water Found Depth UOM: ft

8	***1 of 1***	***NNW/94.0***	***99.9 / -0.03***	***Capital Dentistry Group Ltd.*** ***1365 Baseline Road*** ***Ottawa ON***	***GEN***

Generator Info (as of Dec 2024)

Generator No: ON001055226
Generator Company Name: Capital Dentistry Group Ltd.
Street: 1365 Baseline Road
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1A 0C5
Waste Class: 312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

Generator Info (as of Apr 2025)

Generator Company Name: Capital Dentistry Group Ltd.
Generator Site Address: 1365 Baseline Road
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K1A 0C5
Waste Class: 312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

Waste Characteristic Decoded:

P - Pathological

---

9 ***1 of 1*** ***W/103.0*** ***99.9 / -0.03*** ***ON*** ***WWIS***

Well ID:	1507863	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	04/17/1953
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	3566
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1507863.pdf

Additional Detail(s) (Map)

Well Completed Date:	02/04/1953
Year Completed:	1953
Depth (m):	49.3776
Latitude:	45.3618347452751
Longitude:	-75.7382667202229
Point X:	-75.73826655862385
Point Y:	45.3618347382418
Path:	150\1507863.pdf

Bore Hole Information

Bore Hole ID:	10029898	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442180.70
Code OB Desc:		***North83:***	5023412.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	02/04/1953	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5
Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931008224
Layer:	1
Color:	
General Color:	
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931008226
Layer:	3
Color:	
General Color:	
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	5.0
Formation End Depth:	162.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931008225
Layer:	2
Color:	
General Color:	
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	1.0
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961507863
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID: 10578468
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930052453
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 162.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930052452
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 16.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991507863
Pump Set At:
Static Level: 14.0
Final Level After Pumping: 50.0
Recommended Pump Depth:
Pumping Rate: 4.0
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933462141
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 125.0
Water Found Depth UOM: ft

Water Details

Water ID: 933462143
Layer: 3

Kind Code: 1
Kind: FRESH
Water Found Depth: 162.0
Water Found Depth UOM: ft

Water Details

Water ID: 933462142
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 150.0
Water Found Depth UOM: ft

---

10 | ***1 of 13*** | ***N/124.0*** | ***99.9 / -0.03*** | ***Smart (Ottawa SW Senior Residences) PropCo GP Inc. as general partner for and on behalf of Ottawa SW PropCo LP 1357 Baseline Rd Ottawa ON L4K 5Z5*** | ***ECA***

Approval No: 5238-BZERN9
Approval Date: 2021-04-05
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
MOE District: Ottawa
City:
Longitude: -75.73853
Latitude: 45.363409
Geometry X: -8431174.593
Geometry Y: 5678915.3896
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Smart (Ottawa SW Senior Residences) PropCo GP Inc. as general partner for and on behalf of Ottawa SW PropCo LP
Address: 1357 Baseline Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7885-BZ5P4M-14.pdf
PDF Site Location:

---

10 | ***2 of 13*** | ***N/124.0*** | ***99.9 / -0.03*** | ***1357 Baseline Road Ottawa ON K2C 0A8*** | ***EHS***

Order No: 20061220018
Status: C
Report Type: Complete Report
Report Date: 1/3/2007
Date Received: 12/20/2006
Previous Site Name:
Lot/Building Size: 180,000 ft2
Additional Info Ordered: City Directory
Nearest Intersection: Clyde
Municipality: Ottawa
Client Prov/State: ON
Search Radius (km): 0.3
X: -75.738564
Y: 45.363242

---

10 | ***3 of 13*** | ***N/124.0*** | ***99.9 / -0.03*** | ***OTTAWA BOARD OF EDUCATION LAURENTIAN HIGH SCHOOL, 1357 BASELINERD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8*** | ***GEN***

Generator Info

Generator No: ON0375213
Approval Years: 86,87,88,89
Status:
PO Box No:
Country:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 8511

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Phone No Admin:
SIC Description: ELEMT./SECON. EDUC.

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

10 | ***4 of 13*** | ***N/124.0*** | ***99.9 / -0.03*** | ***THE OTTAWA BOARD OF EDUCATION LAURENTIAN HIGH SCHOOL,1357 BASELINE RD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8*** | ***GEN***

Generator Info

Generator No: ON0375213
Approval Years: 90
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ELEMT./SECON. EDUC.
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 8511

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

10 | ***5 of 13*** | ***N/124.0*** | ***99.9 / -0.03*** | ***OTTAWA BOARD OF EDUCATION LAURENTIAN HIGH SCHOOL 1357 BASELINE ROAD OTTAWA ON K2C 0A8*** | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON0375213	***Choice of Contact:***	
Approval Years:	92,93,97	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	8511
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELEMT./SECON. EDUC.		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

10	***6 of 13***	***N/124.0***	***99.9 / -0.03***	***THE OTTAWA BOARD OF EDUCATION 29-550 LAURENTIAN HIGH SCHOOL,1357 BASELINE RD C/O 330 GILMOUR ST. OTTAWA ON K2C 0A8***	***GEN***

Generator Info

Generator No:	ON0375213	***Choice of Contact:***	
Approval Years:	94,95,96	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	8511
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELEMT./SECON. EDUC.		

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	7 of 13	N/124.0	99.9 / -0.03	***OTTAWA-CARLETON DISTRICT SCHOOL BOARD*** ***LAURENTIAN HIGH SCHOOL 1357 BASELINE ROAD*** ***OTTAWA ON K2C 0A8***	GEN

Generator Info

Generator No: ON0375213
Approval Years: 98,99,00,01,02,03,04,05,06
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ELEMT./SECON. EDUC.
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 8511

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	8 of 13	N/124.0	99.9 / -0.03	Ottawa-Carleton District School Board Laurention H.S. Public School 1357 Baseline Road Ottawa ON K2C 0A8	GEN

Generator Info

Generator No: ON8259530
Approval Years: 02,03,04
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	9 of 13	N/124.0	99.9 / -0.03	OTTAWA-CARLETON DISTRICT SCHOOL BOARD 1357 BASELINE ROAD OTTAWA ON	GEN

Generator Info

Generator No: ON4014760
Approval Years: 2009

Choice of Contact:
Contaminated Fac:

Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Elementary and Secondary Schools

MHSW Facility:
SIC Code: 611110

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	10 of 13	N/124.0	99.9 / -0.03	CLYDESDALE SHOPPING CENTERS LTD 1357 BASELINE ROAD OTTAWA ON	GEN

Generator Info

Generator No:	ON8712328	***Choice of Contact:***	
Approval Years:	2009	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	611110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Elementary and Secondary Schools		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	11 of 13	N/124.0	99.9 / -0.03	Clydesdale Shopping Centres Limited 1357 BASELINE RD ON OTTAWA ON	RSC

RSC No:	66519	***X:***	-75.73861440273001
RA No:		***Y:***	45.36333572362545
Status:	FILED	***Latitude:***	45.36333572
Filing Date:		***Longitude:***	-75.7386144
Date Ack:		***UTM Coordinates:***	
Date Returned:		***Latitude Longitude:***	
Approval Date:	December 9, 2009	***Accuracy Estimate:***	
Cert Date:		***Measurement Method:***	
Cert Prop Use No:		***Mailing Address:***	
Curr Property Use:		***Telephone:***	
Intended Prop Use:		***Fax:***	
Restoration Type:		***Email:***	
Soil Type:		***Postal Code:***	K2C 0A8
Criteria:		***Ministry District:***	
Stratified (Y/N):		***MOE District:***	Ottawa
Audit (Y/N):		***SWP Area Name:***	Rideau Valley
Entire Leg Prop. (Y/N):		***Qual Person Name:***	Mark S D'Arcy
CPU Issu Sect 1686:		***Consultant:***	
Business Name:	Clydesdale Shopping Centres Limited		
Address:	1357 BASELINE RD ON		
Legal Desc:			
Site Pin:	03998-0087 (LT)		
Asmt Roll No:			
Project Type:	PRE2011		
Approval Type:	RSC based on Phase One and Two ESAs		
Applicable Standards:			
PDF Link:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=66519		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	12 of 13	N/124.0	99.9 / -0.03	OTTAWA BOARD OF EDUCATION 1357 BASELINE ROAD OTTAWA CITY ON K2C 0A8	SPL

Ref No:	83617	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	4/2/1993	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	

MOE Reported Dt:	4/5/1993	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	OTTAWA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	UNKNOWN		
Incident Preceding Spill:			
Incident Reason:	UNKNOWN		
Incident Summary:	LAURENTIAN HIGH SCHOOL- BLACK OIL SEEPING INTO BOILER ROOM FROM SUBSOIL.		
Environment Impact:	CONFIRMED		
Health Env Consequence:			
Nature of Impact:	Soil contamination		
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			
Source Sector Type:			
Conservtn Auth Name:			
Primary Watershed:			
Quaternary Watershed:			
Offsite Impacts:			
Waterbody Impacted:			

10	13 of 13	N/124.0	99.9 / -0.03	**Walmart Canada Corp.** **1357 Baseline Rd** **Ottawa ON**	SPL

Ref No:	1087-B8CK8M	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2019/01/12	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2019/01/12	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	
Site No:	NA		

MOE Response:	No
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Ottawa
Nearest Watercourse:	
Site Name:	Walmart Parking Lot<UNOFFICIAL>
Site Address:	1357 Baseline Rd
Site Region:	Eastern
Site Municipality:	Ottawa
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	5023726.9
Easting:	442638.35
Entity Operating Name:	
Client Name:	Walmart Canada Corp.
Client Type:	Corporation
Source Type:	Motor Vehicle
Incident Cause:	
Incident Preceding Spill:	Fire/Explosion
Incident Reason:	Other
Incident Summary:	Walmart Ottawa - coolant/oil to parking lot
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 %
Contaminant Qty 1:	0
Contaminant Unit:	%
Contaminant Code:	27
Contaminant Name:	COOLANT N.O.S.
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

11 **1 of 1** **W/124.3** **99.2 / -0.72** **ON** **BORE**

Borehole ID:	612615	**Inclin FLG:**	No
OGF ID:	215513921	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:	11.9	**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.361745
Total Depth m:	-999	**Longitude DD:**	-75.738521
Depth Ref:	Ground Surface	**UTM Zone:**	18

Depth Elev:		**Easting:**	442161
Drill Method:		**Northing:**	5023402
Orig Ground Elev m:	97.5	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	100		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218391833	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	30.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND.		

Geology Stratum ID:	218391834	**Mat Consistency:**	Compact
Top Depth:	30.5	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Limestone	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK. ROCK. WATER STABLE AT 281.0 FEET.FF. TILL. LOOSE TO COMPACT. SAND. LOOSE TO CO **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 051230 NTS_Sheet: 31G05B		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

13 | ***1 of 1*** | ***NW/145.1*** | ***99.9 / -0.03*** | ***1365 -1385 Baseline Road Ottawa ON*** | ***EHS***

Order No:	20130705008	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	11-JUL-13	**Search Radius (km):**	.25

Date Received: 05-JUL-13
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
X: -75.738154
Y: 45.362967

---

14 *1 of 97* *ENE/145.2* *98.9 / -1.03* **Loblaw Properties Limited** **CA**
1460 Merivale Road
Ottawa ON

Certificate #: 6321-6HWJW3
Application Year: 2005
Issue Date: 12/1/2005
Approval Type: Industrial Sewage Works
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

14 *2 of 97* *ENE/145.2* *98.9 / -1.03* **Loblaw Properties Limited** **CA**
1460 Merivale Road
Ottawa ON

Certificate #: 7379-6R9QFV
Application Year: 2006
Issue Date: 7/26/2006
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

14 *3 of 97* *ENE/145.2* *98.9 / -1.03* **MAC'S CONVENIENCE STORES INC**** **DTNK**
1460 MERIVALE RD
NEPEAN ON K2E 5P2

Delisted Expired Fuel Safety Facilities

Instance No: 10060021
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Expired Date: 7/1/1990
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:

Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

14	*4 of 97*	*ENE/145.2*	*98.9 / -1.03*	***SUNYS PETROLEUM INC*** ***1460 MERIVALE RD*** ***NEPEAN ON K2E 5P2***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9883687 ***Expired Date:*** 1/22/1992
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: ***Facility Location:***
Instance Type: FS Facility ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

14	*5 of 97*	*ENE/145.2*	*98.9 / -1.03*	***SUNYS ENERGY INC*** ***1460 MERIVALE RD*** ***NEPEAN ON K2E 5P2***	***DTNK***

Delisted Expired Fuel Safety

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facilities

Instance No:	10142288	***Expired Date:***	6/6/2009
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:		***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

14	***6 of 97***	***ENE/145.2***	***98.9 / -1.03***	***SUNYS ENERGY INC ATTN RAFAH SHOOMAN*** ***1460 MERIVALE RD*** ***NEPEAN ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10078622	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	11634	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Refill Cntr - Motor Fill
Original Source: EXP
Record Date: Up to Mar 2012

---

14 | ***7 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***SUNYS PETROLEUM INC***
1460 MERIVALE RD
NEPEAN ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11321127
Status: EXPIRED
Instance ID: 77929
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

14 | ***8 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***SUNYS ENERGY INC***
1460 MERIVALE RD
NEPEAN ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11410746
Status: EXPIRED
Instance ID: 83536
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

14	*9 of 97*	*ENE/145.2*	*98.9 / -1.03*	***SUNYS ENERGY INC*** ***1460 MERIVALE RD*** ***NEPEAN ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11410766
Status: EXPIRED
Instance ID: 83387
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

14	*10 of 97*	*ENE/145.2*	*98.9 / -1.03*	***SUNYS ENERGY INC ATTN RAFAH SHOOMAN*** ***1460 MERIVALE RD*** ***NEPEAN ON***	***DTNK***

Delisted Expired Fuel Safety

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facilities

Instance No:	11259572	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	75340	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Tank		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

14	***11 of 97***	***ENE/145.2***	***98.9 / -1.03***	***Loblaw Properties Limited*** ***1460 Merivale Road*** ***Ottawa ON M4T 2S5***	***ECA***

Approval No:	6321-6HWJW3	***MOE District:***	Ottawa
Approval Date:	2005-12-01	***City:***	
Status:	Revoked and/or Replaced	***Longitude:***	-75.735054
Record Type:	ECA	***Latitude:***	45.362366
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Rideau Valley	***Geometry Y:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Loblaw Properties Limited		
Address:	1460 Merivale Road		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4122-6H4Q9R-14.pdf		
PDF Site Location:			

14	***12 of 97***	***ENE/145.2***	***98.9 / -1.03***	***Loblaw Properties Limited*** ***1460 Merivale Road*** ***Ottawa ON L6Y 5S5***	***ECA***

Approval No:	7379-6R9QFV	***MOE District:***	Ottawa
Approval Date:	2006-07-26	***City:***	
Status:	Approved	***Longitude:***	-75.735054
Record Type:	ECA	***Latitude:***	45.362366
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Rideau Valley	***Geometry Y:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Loblaw Properties Limited		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Address: 1460 Merivale Road
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9060-6QSKT4-14.pdf
PDF Site Location:

---

14 | **13 of 97** | **ENE/145.2** | **98.9 / -1.03** | **1460 Merivale Road Ottawa ON** | **EHS**

Order No: 20160616198
Status: C
Report Type: Standard Report
Report Date: 23-JUN-16
Date Received: 16-JUN-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.734129
Y: 45.36342

---

14 | **14 of 97** | **ENE/145.2** | **98.9 / -1.03** | **1460 Merivale Rd Ottawa ON K2C 0A9** | **EHS**

Order No: 20161124064
Status: C
Report Type: Standard Report
Report Date: 01-DEC-16
Date Received: 24-NOV-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory

Nearest Intersection:
Municipality: Ottawa
Client Prov/State: ON
Search Radius (km): .25
X: -75.73336
Y: 45.362937

---

14 | **15 of 97** | **ENE/145.2** | **98.9 / -1.03** | **SUNYS ENERGY INC 1460 MERIVALE RD NEPEAN ON** | **EXP**

Inventory No: 11410689
Inventory Status: EXPIRED
Installation Year: 1991
Capacity: 45000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

14 | **16 of 97** | **ENE/145.2** | **98.9 / -1.03** | **SUNYS PETROLEUM INC 1460 MERIVALE RD NEPEAN ON** | **EXP**

Inventory No: 11092256
Inventory Status: EXPIRED
Installation Year: 1992
Capacity: 44500
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Diesel

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	17 of 97	ENE/145.2	98.9 / -1.03	SUNYS ENERGY INC 1460 MERIVALE RD NEPEAN ON	EXP

Inventory No: 11410728
Inventory Status: EXPIRED
Installation Year: 1991
Capacity: 25000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS ETHANOL
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	18 of 97	ENE/145.2	98.9 / -1.03	SUNYS ENERGY INC 1460 MERIVALE RD NEPEAN ON	EXP

Inventory No: 11410708
Inventory Status: EXPIRED
Installation Year: 1991
Capacity: 25000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	19 of 97	ENE/145.2	98.9 / -1.03	SUNYS PETROLEUM INC 1460 MERIVALE RD NEPEAN ON	EXP

Inventory No: 11092244
Inventory Status: EXPIRED
Installation Year: 1992
Capacity: 25000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	20 of 97	ENE/145.2	98.9 / -1.03	SUNYS PETROLEUM INC 1460 MERIVALE RD NEPEAN ON	EXP

Inventory No: 11092228
Inventory Status: EXPIRED
Installation Year: 1992
Capacity: 25000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Previous Fuel Type: Gasoline

---

14 ***21 of 97*** ***ENE/145.2*** ***98.9 / -1.03*** ***BCP IV SERVICE STATION LP O/A BG FUELS*** ***FST***
1460 MERIVALE RD
OTTAWA ON

Inventory No:	35312412	***Tank Material:***	Fiberglass (FRP)
Inventory Status:	active	***Corrosion Protect:***	Fiberglass
Installation Year:	2005	***Overfill Protection:***	
Capacity:	65000	***Inventory Context:***	FS Liquid Fuel
Capacity Unit:	L	***Inventory Item:***	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS compartment 45,000L regular; 20,000L premium		

---

14 ***22 of 97*** ***ENE/145.2*** ***98.9 / -1.03*** ***BCP IV SERVICE STATION LP O/A BG FUELS*** ***FST***
1460 MERIVALE RD
OTTAWA ON

Inventory No:	35312413	***Tank Material:***	Fiberglass (FRP)
Inventory Status:	active	***Corrosion Protect:***	Fiberglass
Installation Year:	2005	***Overfill Protection:***	
Capacity:	65000	***Inventory Context:***	FS Liquid Fuel
Capacity Unit:	L	***Inventory Item:***	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS; compartment 45,000L regular; 20,000L diesel		

---

14 ***23 of 97*** ***ENE/145.2*** ***98.9 / -1.03*** ***BCP IV SERVICE STATION LP O/A BG FUELS*** ***FST***
1460 MERIVALE RD
OTTAWA ON

Inventory No:	35210393	***Tank Material:***	
Inventory Status:	Active	***Corrosion Protect:***	
Installation Year:		***Overfill Protection:***	
Capacity:	130000	***Inventory Context:***	Liquid Fuels
Capacity Unit:	L	***Inventory Item:***	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			
Description:			

---

14 ***24 of 97*** ***ENE/145.2*** ***98.9 / -1.03*** ***LOBLAW PROPERTIES LTD GASBAR DIV*** ***FSTH***
1460 MERIVALE RD
OTTAWA ON

License Issue Date:	11/1/2006
Tank Status:	Licensed
Tank Status As Of:	August 2007
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	2005

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Corrosion Protection:
Capacity: 65000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2005
Corrosion Protection:
Capacity: 65000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

14	25 of 97	ENE/145.2	98.9 / -1.03	LOBLAW PROPERTIES LTD AT THE PUMPS GASBAR DIV 1460 MERIVALE RD OTTAWA ON	FSTH

License Issue Date: 11/1/2006 3:23:00 PM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 2005
Corrosion Protection:
Capacity: 65000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2005
Corrosion Protection:
Capacity: 65000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

14	26 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD. 24-850 1460 MERIVALE ROAD NEPEAN ON K2E 5P2	GEN

Generator Info

Generator No: ON0270302
Approval Years: 92,93,94,95,96
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: GROCERY FOOD STORES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6011

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

14	27 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD 1460 MERIVALE ROAD NEPEAN ON K2E 5P2	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON0270302	***Choice of Contact:***	
Approval Years:	97	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6011
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	GROCERY FOOD STORES		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	28 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LIMITED 1460 MERIVALE ROAD NEPEAN ON K2E 5P2	GEN

Generator Info

Generator No:	ON0270302	***Choice of Contact:***	
Approval Years:	98,99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6011
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	GROCERY FOOD STORES		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	29 of 97	ENE/145.2	98.9 / -1.03	SPORTS EXPERTS #51 1460 MERIVALE RD. NEPEAN ON K2E 5P2	GEN

Generator Info

Generator No:	ON1050300	***Choice of Contact:***	
Approval Years:	88,89,90	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6541
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	SPORTING GOODS STORE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	30 of 97	ENE/145.2	98.9 / -1.03	SPORTS EXPERTS #51 34-397 1460 MERIVALE RD. NEPEAN ON K2E 5P2	GEN

Generator Info

Generator No:	ON1050300	**Choice of Contact:**	
Approval Years:	92,93,94,95,96,97,98	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6541
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	SPORTING GOODS STORE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	31 of 97	ENE/145.2	98.9 / -1.03	SPORTS EXPERTS #51 1460 MERIVALE ROAD NEPEAN ON K2E 5P2	GEN

Generator Info

Generator No:	ON1050300	**Choice of Contact:**	
Approval Years:	99,00,01	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6541
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	SPORTING GOODS STORE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	32 of 97	ENE/145.2	98.9 / -1.03	SHOPPERS DRUG MART 1460 MERIVALE ROAD OTTAWA ON K2E 5P2	GEN

Generator Info

Generator No:	ON2530727	**Choice of Contact:**	
Approval Years:	99,00,01	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6031
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHARMACIES		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

14 | ***33 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***SJL HOLDINGS LIMITED***
1460 MERIVALE ROAD
OTTAWA ON K2E 5N9 | ***GEN***

Generator Info

Generator No: ON3996858
Approval Years: 05
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Other Gasoline Stations

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 447190

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

14 | ***34 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***FCR MANAGEMENT SERVICES***
1460 MERIVALE ROAD
OTTAWA ON K2E 5P2 | ***GEN***

Generator Info

Generator No: ON4132932
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Miscellaneous General Merchandise Stores

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 452999

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	35 of 97	ENE/145.2	98.9 / -1.03	Loblaw Properties Ltd. 1460 Merivale Road Ottawa ON K2E 5P2	GEN

Generator Info

Generator No:	ON8192732	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	445110
Country:	Canada		
Co Admin:	Kelly West		
Phone No Admin:	519-647-3729 Ext.		
SIC Description:	SUPERMARKETS AND OTHER GROCERY (EXCEPT CONVENIENCE) STORES		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	36 of 97	ENE/145.2	98.9 / -1.03	Loblaw Properties Ltd. 1460 Merivale Road Ottawa ON K2E 5P2	GEN

Generator Info

Generator No:	ON8192732	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	445110
Country:	Canada		
Co Admin:	Craig Hudak		
Phone No Admin:	9055957544 Ext.		
SIC Description:	SUPERMARKETS AND OTHER GROCERY (EXCEPT CONVENIENCE) STORES		

Waste Detail(s)

Waste Class:	269
Waste Class Name:	NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

14 **37 of 97** **ENE/145.2** **98.9 / -1.03** **Loblaw Properties Ltd.**
1460 Merivale Road
Ottawa ON K2E 5P2 **GEN**

Generator Info

Generator No: ON8192732
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Kelly West
Phone No Admin: 519-647-3729 Ext.
SIC Description: SUPERMARKETS AND OTHER GROCERY (EXCEPT CONVENIENCE) STORES
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 445110

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

14 **38 of 97** **ENE/145.2** **98.9 / -1.03** **Loblaw Properties Ltd.**
1460 Merivale Road
Ottawa ON K2E 5P2 **GEN**

Generator Info

Generator No: ON8192732
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 261 B
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 148 I

Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 261 I
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 242 L
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 261 L
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 262 C
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 242 T
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 269 L
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	39 of 97	ENE/145.2	98.9 / -1.03	Merivale Dental Centre 1460 Meivale Road Unit 4B Ottawa ON K2E5P2	GEN

Generator Info

Generator No:	ON5017008	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 146 P
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	40 of 97	ENE/145.2	98.9 / -1.03	Merivale Dental Centre 1460 Meivale Road Unit 4B Ottawa ON K2E5P2	GEN

Generator Info

Generator No:	ON5017008	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 146 P
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	41 of 97	ENE/145.2	98.9 / -1.03	Loblaw Properties Ltd. 1460 Merivale Road Ottawa ON K2E 5P2	GEN

Generator Info

Generator No:	ON8192732	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		

Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 261 B
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 242 T
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 242 L
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 262 C
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 261 I
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 261 L

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 269 L
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

14	***42 of 97***	***ENE/145.2***	***98.9 / -1.03***	***BG FUELS GAS BARS 4281*** ***1460 Merivale Road*** ***Ottawa ON K2E 5P2***	***GEN***

Generator Info

Generator No:	ON5276265	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

14	***43 of 97***	***ENE/145.2***	***98.9 / -1.03***	***Merivale Dental Centre*** ***1460 Meivale Road Unit 4B*** ***Ottawa ON K2E5P2***	***GEN***

Generator Info

Generator No:	ON5017008	***Choice of Contact:***	
Approval Years:	As of Jan 2021	***Contaminated Fac:***	

Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	146 P
Waste Class Name:	Other specified inorganic sludges, slurries or solids

2017 Generator Info

Gen No:	ON5017008	***Choice of Contact:***	CO_ADMIN
ID:	19898	***Phone No Official:***	613.224.1391 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613.224.1393 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Merivale Dental Centre		
Gen Div:			
Gen Op Name:	Merivale Dental Centre		
Gen Op Div:			
Site Adrs1:	1460 Meivale Road		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 4B		
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E5P2		
Site Country:	Canada		
Co Official:	Kendra March		
Co Admin:	Kendra March		

2018 Generator Info

Gen No:	ON5017008	***Choice of Contact:***	CO_ADMIN
ID:	20008	***Phone No Official:***	613.224.1391 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613.224.1393 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621390	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Merivale Dental Centre		
Gen Div:			
Gen Op Name:	Merivale Dental Centre		
Gen Op Div:			
Site Adrs1:	1460 Meivale Road		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 4B		
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E5P2		
Site Country:	Canada		
Co Official:	Kendra March		
Co Admin:	Kendra March		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2019 Generator Info

Gen No:	ON5017008	***Choice of Contact:***	CO_ADMIN
ID:	20030	***Phone No Official:***	613.224.1391 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613.224.1393 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Merivale Dental Centre		
Gen Div:			
Gen Op Name:	Merivale Dental Centre		
Gen Op Div:			
Site Adrs1:	1460 Meivale Road		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 4B		
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E5P2		
Site Country:	Canada		
Co Official:	Kendra March		
Co Admin:	Kendra March		

2020 Generator Info

Gen No:	ON5017008	***Choice of Contact:***	CO_ADMIN
ID:	19757	***Phone No Official:***	613.224.1391 Ext.
Contaminated Fac:	N	***Phone No Admin:***	613.224.1393 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Merivale Dental Centre		
Gen Div:			
Gen Op Name:	Merivale Dental Centre		
Gen Op Div:			
Site Adrs1:	1460 Meivale Road		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 4B		
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E5P2		
Site Country:	Canada		
Co Official:	Kendra March		
Co Admin:	Kendra March		

14	***44 of 97***	***ENE/145.2***	***98.9 / -1.03***	***Loblaw Properties Ltd.*** ***1460 Merivale Road*** ***Ottawa ON K2E 5P2***	***GEN***

Generator Info

Generator No:	ON8192732	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			

Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 269 L
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 261 L

Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 242 L
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 242 T
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 261 B
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 262 C
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 261 I
Waste Class Name: Pharmaceuticals

14	***45 of 97***	***ENE/145.2***	***98.9 / -1.03***	***BG FUELS GAS BARS 4281*** ***1460 Merivale Road*** ***Ottawa ON K2E 5P2***	***GEN***

Generator Info

Generator No:	ON5276265	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

14	***46 of 97***	***ENE/145.2***	***98.9 / -1.03***	***BG Fuels*** ***1460 Merivale Road*** ***Ottawa ON***	***GEN***

Generator Info

Generator No:	ON5276265	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	148 I
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	221 L
Waste Class Name:	LIGHT FUELS

Generator Info (as of Dec 2024)

Generator No:	ON5276265
Generator Company Name:	BG Fuels
Street:	1460 Merivale Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K2E5P2
Waste Class:	221 L,221 L,148 I

Waste Class Decoded:

221 - LIGHT FUELS; 221 - LIGHT FUELS; 148 - INORGANIC LABORATORY CHEMICALS

Generator Info (as of Apr 2025)

Generator Company Name:	BG Fuels
Generator Site Address:	1460 Merivale Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K2E5P2
Waste Class:	221 L, 221 L, 148 I

Waste Class Decoded:

221 - LIGHT FUELS; 221 - LIGHT FUELS; 148 - INORGANIC LABORATORY CHEMICALS

Waste Characteristic Decoded:

L - Liquid Industrial Waste; L - Liquid Industrial Waste; I - Ignitable

2019 Generator Info

Gen No:	ON5276265	***Choice of Contact:***	CO_ADMIN
ID:	21086	***Phone No Official:***	437-317-3573 Ext.
Contaminated Fac:	N	***Phone No Admin:***	437-317-3563 Ext.

MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	447110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	BG FUELS GAS BARS 4281		
Gen Div:			
Gen Op Name:	BG FUELS GAS BARS 4281		
Gen Op Div:			
Site Adrs1:	1460 Merivale Road		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E 5P2		
Site Country:	Canada		
Co Official:	Gus Prokos		
Co Admin:	Hanna Rajput		

2019 Generator Manifest

ID:	44869	***Sum Received Qty:***	24328.0
Generator No:	ON5276265	***Waste Class Name:***	LIGHT FUELS
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	L	***District:***	402
Waste Code:	221		

2020 Generator Info

Gen No:	ON5276265	***Choice of Contact:***	CO_ADMIN
ID:	20832	***Phone No Official:***	437-317-3573 Ext.
Contaminated Fac:	N	***Phone No Admin:***	437-317-3563 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	447110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	BG FUELS GAS BARS 4281		
Gen Div:			
Gen Op Name:	BG FUELS GAS BARS 4281		
Gen Op Div:			
Site Adrs1:	1460 Merivale Road		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E 5P2		
Site Country:	Canada		
Co Official:	Gus Prokos		
Co Admin:	Hanna Rajput		

2020 Generator Manifest

ID:	41481	***Sum Received Qty:***	26.0
Generator No:	ON5276265	***Waste Class Name:***	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	I	***District:***	402
Waste Code:	148		

2020 Generator Manifest

ID:	41482	**Sum Received Qty:**	6590.0
Generator No:	ON5276265	**Waste Class Name:**	LIGHT FUELS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	402
Waste Code:	221		

2020 Generator Manifest

ID:	41483	**Sum Received Qty:**	9300.0
Generator No:	ON5276265	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	402
Waste Code:	251		

2021 Generator Info

Gen No:	ON5276265	**Choice of Contact:**	CO_ADMIN
ID:	21006	**Phone No Official:**	437-317-3573 Ext.
Contaminated Fac:	N	**Phone No Admin:**	437-317-3563 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	447110	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			

Gen Name:	BCP IV Service Station LPGAS BARS 4281
Gen Div:	
Gen Op Name:	BCP IV Service Station LP GAS BARS 4281
Gen Op Div:	
Site Adrs1:	1460 Merivale Road
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K2E 5P2
Site Country:	Canada
Co Official:	Gus Prokos
Co Admin:	Hanna Rajput

---

14 | ***47 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***Loblaws Inc.***
1460 Merivale Road
Ottawa ON | ***GEN***

Generator Info

Generator No:	ON8192732	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	242 L
Waste Class Name:	HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 242 T
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 262 C
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 261 I
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 269 L
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 148 A
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 261 B
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 263 C
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 269 T
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 261 L
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Generator Info (as of Dec 2024)

Generator No: ON8192732
Generator Company Name: Loblaws Inc.
Street: 1460 Merivale Road
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K2E 5N9
Waste Class: 148 C, 251 L, 312 P, 112 C, 122 C, 145 I, 145 L, 146 T, 148 A, 148 I, 212 I, 212 L, 242 L, 242 T, 252 L, 261 A, 261 B, 261 I, 261 L, 262 C, 262 L, 263 A, 263 C, 263 L, 269 L, 269 T, 331 I, 243 D

Waste Class Decoded:

148 - INORGANIC LABORATORY CHEMICALS; 251 - OIL SKIMMINGS & SLUDGES; 312 - PATHOLOGICAL WASTES; 112 - ACID WASTE - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 145 - PAINT/PIGMENT/COATING RESIDUES; 146 - OTHER SPECIFIED INORGANICS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS; 212 - ALIPHATIC SOLVENTS; 242 - HALOGENATED PESTICIDES; 242 - HALOGENATED PESTICIDES; 252 - WASTE OILS & LUBRICANTS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 262 - DETERGENTS/SOAPS; 262 - DETERGENTS/SOAPS; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 269 - NON-HALOGENATED PESTICIDES; 269 - NON-HALOGENATED PESTICIDES; 331 - WASTE COMPRESSED GASES; 243 - PCBS

Generator Info (as of Dec 2024)

Generator No: ON8192732
Generator Company Name: Loblaws Inc.
Street: 1460 Merivale Road
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K2E 5N9
Waste Class: 251 L,243 D,312 P,112 C,122 C,145 I,145 L,146 T,148 A,148 I,212 I,212 L,242 L,242 T,252 L,261 A,261 B,261 I, 261 L,262 C,262 L,263 A,263 C,263 L,269 L,269 T,331 I,148 C

Waste Class Decoded:

251 - OIL SKIMMINGS & SLUDGES; 243 - PCBS; 312 - PATHOLOGICAL WASTES; 112 - ACID WASTE - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 145 - PAINT/PIGMENT/COATING RESIDUES; 146 - OTHER SPECIFIED INORGANICS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS; 212 - ALIPHATIC SOLVENTS; 242 - HALOGENATED PESTICIDES; 242 - HALOGENATED PESTICIDES; 252 - WASTE OILS & LUBRICANTS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 262 - DETERGENTS/SOAPS; 262 - DETERGENTS/SOAPS; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC

LABORATORY CHEMICALS; 269 - NON-HALOGENATED PESTICIDES; 269 - NON-HALOGENATED PESTICIDES; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS

Generator Info (as of Apr 2025)

Generator Company Name:	Loblaws Inc.
Generator Site Address:	1460 Merivale Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K2E 5N9
Waste Class:	243 D, 251 L, 312 P, 112 C, 122 C, 145 I, 145 L, 146 T, 148 A, 148 I, 212 I, 212 L, 242 L, 242 T, 252 L, 261 A, 261 B, 261 I, 261 L, 262 C, 262 L, 263 A, 263 C, 263 L, 269 L, 269 T, 331 I, 148 C

Waste Class Decoded:

243 - PCBS; 251 - OIL SKIMMINGS & SLUDGES; 312 - PATHOLOGICAL WASTES; 112 - ACID WASTE - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 145 - PAINT/PIGMENT/COATING RESIDUES; 146 - OTHER SPECIFIED INORGANICS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 212 - ALIPHATIC SOLVENTS; 212 - ALIPHATIC SOLVENTS; 242 - HALOGENATED PESTICIDES; 242 - HALOGENATED PESTICIDES; 252 - WASTE OILS & LUBRICANTS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS; 262 - DETERGENTS/SOAPS; 262 - DETERGENTS/SOAPS; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 269 - NON-HALOGENATED PESTICIDES; 269 - NON-HALOGENATED PESTICIDES; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS

Waste Characteristic Decoded:

D - PCB Waste; L - Liquid Industrial Waste; P - Pathological; C - Corrosive; C - Corrosive; I - Ignitable; L - Liquid Industrial Waste; T - Leachate Toxic; A - Acutely Hazardous Waste Chem.; I - Ignitable; I - Ignitable; L - Liquid Industrial Waste; L - Liquid Industrial Waste; T - Leachate Toxic; L - Liquid Industrial Waste; A - Acutely Hazardous Waste Chem.; B - Hazardous Waste Chemical; I - Ignitable; L - Liquid Industrial Waste; C - Corrosive; L - Liquid Industrial Waste; A - Acutely Hazardous Waste Chem.; C - Corrosive; L - Liquid Industrial Waste; L - Liquid Industrial Waste; T - Leachate Toxic; I - Ignitable; C - Corrosive

2017 Generator Info

Gen No:	ON8192732	***Choice of Contact:***	CO_OFFICIAL
ID:	32069	***Phone No Official:***	905-459-2500 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9055957544 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	445110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			

Gen Name:	Loblaw Properties Ltd.
Gen Div:	
Gen Op Name:	Loblaw Properties Ltd. c/o Minotaur Stormwater
Gen Op Div:	
Site Adrs1:	1460 Merivale Road
Site Bldg:	1082
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K2E 5P2
Site Country:	Canada
Co Official:	Dan Romano
Co Admin:	Craig Hudak

2017 Generator Manifest

ID:	59520	***Sum Received Qty:***	39.0

Generator No:	ON8192732	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	8
Waste Char:	A	**District:**	402
Waste Code:	148		

2017 Generator Manifest

ID:	59524	**Sum Received Qty:**	25.0
Generator No:	ON8192732	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	030	**Count Manifests:**	4
Waste Char:	I	**District:**	402
Waste Code:	331		

2017 Generator Manifest

ID:	59521	**Sum Received Qty:**	16.0
Generator No:	ON8192732	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	3
Waste Char:	A	**District:**	402
Waste Code:	263		

2017 Generator Manifest

ID:	59519	**Sum Received Qty:**	4.0
Generator No:	ON8192732	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	T	**District:**	402
Waste Code:	146		

2017 Generator Manifest

ID:	59523	**Sum Received Qty:**	8.4
Generator No:	ON8192732	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	P	**District:**	402
Waste Code:	312		

2017 Generator Manifest

ID:	59522	**Sum Received Qty:**	86.0
Generator No:	ON8192732	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	4
Waste Char:	L	**District:**	402
Waste Code:	263		

2018 Generator Info

Gen No:	ON8192732	**Choice of Contact:**	CO_OFFICIAL
ID:	32666	**Phone No Official:**	905-459-2500 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	445110	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			
Gen Name:	Loblaw Properties Ltd.		
Gen Div:			
Gen Op Name:	Loblaw Properties Ltd. c/o Minotaur Stormwater		
Gen Op Div:			
Site Adrs1:	1460 Merivale Road		
Site Bldg:	1082		
Site Pobox:			

Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2E 5P2
Site Country: Canada
Co Official: Dan Romano
Co Admin:

2018 Generator Manifest

ID: 59775
Generator No: ON8192732
Receiver Type: 030
Waste Char: A
Waste Code: 148
Sum Received Qty: 9.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 3
District: 402

2018 Generator Manifest

ID: 59776
Generator No: ON8192732
Receiver Type: 030
Waste Char: I
Waste Code: 212
Sum Received Qty: 12.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 3
District: 402

2018 Generator Manifest

ID: 59778
Generator No: ON8192732
Receiver Type: 030
Waste Char: P
Waste Code: 312
Sum Received Qty: 6.6
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 1
District: 402

2018 Generator Manifest

ID: 59779
Generator No: ON8192732
Receiver Type: 030
Waste Char: I
Waste Code: 331
Sum Received Qty: 9.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 1
District: 402

2018 Generator Manifest

ID: 59777
Generator No: ON8192732
Receiver Type: 030
Waste Char: L
Waste Code: 263
Sum Received Qty: 173.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 2
District: 402

2019 Generator Info

Gen No: ON8192732
ID: 33036
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 445110
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-459-2500 Ext.
Phone No Admin:
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402
Gen Name: Loblaw Properties Ltd.
Gen Div:
Gen Op Name: Loblaw Properties Ltd. c/o Minotaur Stormwater

Gen Op Div:
Site Adrs1: 1460 Merivale Road
Site Bldg: 1082
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2E 5P2
Site Country: Canada
Co Official: Dan Romano
Co Admin:

2019 Generator Manifest

ID: 59746
Generator No: ON8192732
Receiver Type: 030
Waste Char: L
Waste Code: 263
Sum Received Qty: 120.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 4
District: 402

2019 Generator Manifest

ID: 59749
Generator No: ON8192732
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 2000.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 402

2019 Generator Manifest

ID: 59748
Generator No: ON8192732
Receiver Type: 030
Waste Char: I
Waste Code: 331
Sum Received Qty: 11.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 5
District: 402

2019 Generator Manifest

ID: 59743
Generator No: ON8192732
Receiver Type: 030
Waste Char: A
Waste Code: 148
Sum Received Qty: 23.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 5
District: 402

2019 Generator Manifest

ID: 59744
Generator No: ON8192732
Receiver Type: 030
Waste Char: I
Waste Code: 212
Sum Received Qty: 17.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 5
District: 402

2019 Generator Manifest

ID: 59745
Generator No: ON8192732
Receiver Type: 030
Waste Char: A
Waste Code: 261
Sum Received Qty: 1.0
Waste Class Name: PHARMACEUTICALS
Count Manifests: 1
District: 402

2019 Generator Manifest

ID:	59747	***Sum Received Qty:***	29.0
Generator No:	ON8192732	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	030	***Count Manifests:***	2
Waste Char:	P	***District:***	402
Waste Code:	312		

2020 Generator Info

Gen No:	ON8192732	***Choice of Contact:***	CO_OFFICIAL
ID:	32762	***Phone No Official:***	905-459-2500 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	445110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Loblaw Properties Ltd.		
Gen Div:			
Gen Op Name:	Loblaw Properties Ltd. c/o Minotaur Stormwater		
Gen Op Div:			
Site Adrs1:	1460 Merivale Road		
Site Bldg:	1082		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E 5P2		
Site Country:	Canada		
Co Official:	Morgan Lamprey		
Co Admin:			

2020 Generator Manifest

ID:	56039	***Sum Received Qty:***	10.8
Generator No:	ON8192732	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	P	***District:***	305
Waste Code:	312		

2020 Generator Manifest

ID:	56045	***Sum Received Qty:***	9.0
Generator No:	ON8192732	***Waste Class Name:***	WASTE COMPRESSED GASES
Receiver Type:	030	***Count Manifests:***	5
Waste Char:	I	***District:***	402
Waste Code:	331		

2020 Generator Manifest

ID:	56040	***Sum Received Qty:***	34.0
Generator No:	ON8192732	***Waste Class Name:***	INORGANIC LABORATORY CHEMICALS
Receiver Type:	030	***Count Manifests:***	5
Waste Char:	A	***District:***	402
Waste Code:	148		

2020 Generator Manifest

ID:	56041	***Sum Received Qty:***	19.0
Generator No:	ON8192732	***Waste Class Name:***	ALIPHATIC SOLVENTS

Receiver Type:	030	**Count Manifests:**	4
Waste Char:	I	**District:**	402
Waste Code:	212		

2020 Generator Manifest

ID:	56044	**Sum Received Qty:**	8.1
Generator No:	ON8192732	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	P	**District:**	402
Waste Code:	312		

2020 Generator Manifest

ID:	56042	**Sum Received Qty:**	234.0
Generator No:	ON8192732	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	4
Waste Char:	L	**District:**	402
Waste Code:	263		

2020 Generator Manifest

ID:	56043	**Sum Received Qty:**	2.0
Generator No:	ON8192732	**Waste Class Name:**	NON-HALOGENATED PESTICIDES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	T	**District:**	402
Waste Code:	269		

2021 Generator Info

Gen No:	ON8192732	**Choice of Contact:**	CO_OFFICIAL
ID:	33532	**Phone No Official:**	905-459-2500 Ext.
Contaminated Fac:	N	**Phone No Admin:**	416 569-8690 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	445110	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			

Gen Name:	Loblaw Properties Ltd.
Gen Div:	
Gen Op Name:	Loblaw Properties Ltd. c/o Minotaur Stormwater
Gen Op Div:	
Site Adrs1:	1460 Merivale Road
Site Bldg:	1082
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K2E 5P2
Site Country:	Canada
Co Official:	Morgan Lamprey
Co Admin:	MORGAN LAMPREY

2021 Generator Manifest

ID:	58364	**Sum Received Qty:**	162.0
Generator No:	ON8192732	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	4
Waste Char:	L	**District:**	402
Waste Code:	263		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2021 Generator Manifest

ID:	58366	***Sum Received Qty:***	8.0
Generator No:	ON8192732	***Waste Class Name:***	WASTE COMPRESSED GASES
Receiver Type:	030	***Count Manifests:***	3
Waste Char:	I	***District:***	402
Waste Code:	331		

2021 Generator Manifest

ID:	58363	***Sum Received Qty:***	18.0
Generator No:	ON8192732	***Waste Class Name:***	ALIPHATIC SOLVENTS
Receiver Type:	030	***Count Manifests:***	3
Waste Char:	I	***District:***	402
Waste Code:	212		

2021 Generator Manifest

ID:	58362	***Sum Received Qty:***	17.0
Generator No:	ON8192732	***Waste Class Name:***	INORGANIC LABORATORY CHEMICALS
Receiver Type:	030	***Count Manifests:***	4
Waste Char:	A	***District:***	402
Waste Code:	148		

2021 Generator Manifest

ID:	58365	***Sum Received Qty:***	14.65
Generator No:	ON8192732	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	030	***Count Manifests:***	1
Waste Char:	P	***District:***	402
Waste Code:	312		

14	***48 of 97***	***ENE/145.2***	***98.9 / -1.03***	***BG Fuels*** ***1460 Merivale Road*** ***Ottawa ON***	***GEN***

Generator Info (as of Dec 2024)

Generator No:	ON001070939
Generator Company Name:	BG Fuels
Street:	1460 Merivale Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K2E 5N9
Waste Class:	221 L,221 L,148 I

Waste Class Decoded:

221 - LIGHT FUELS; 221 - LIGHT FUELS; 148 - INORGANIC LABORATORY CHEMICALS

Generator Info (as of Apr 2025)

Generator Company Name:	BG Fuels
Generator Site Address:	1460 Merivale Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K2E 5N9

Waste Class: 221 L, 221 L, 148 I

Waste Class Decoded:

221 - LIGHT FUELS; 221 - LIGHT FUELS; 148 - INORGANIC LABORATORY CHEMICALS

Waste Characteristic Decoded:

L - Liquid Industrial Waste; L - Liquid Industrial Waste; I - Ignitable

---

14 | ***49 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***BCP IV SERVICE STATION LP O/A BG FUELS***
1460 MERIVALE RD
OTTAWA ON | ***INC***

Incident No:	2187158	***Any Health Impact:***	
Incident ID:		***Any Enviro Impact:***	
Instance No:	35210393	***Service Intrp:***	
Status Code:		***Was Prop Damaged:***	
Incident Status:	Closed by Program	***Reside App. Type:***	
Incident Severity:		***Commer App. Type:***	
Task No:		***Indus App. Type:***	
Attribute Category:	FS-Incident	***Institut App. Type:***	
Context:		***Depth Ground Cover:***	
Date of Occurrence:	11/7/2017	***Operation Pressure:***	
Time of Occurrence:		***Equipment Type:***	
Occr Insp Start Dt:		***Equipment Model:***	
Incident Creat On:	11/7/2017	***Serial No:***	
Instance Creat Dt:		***Cylinder Capacity:***	
Instance Install Dt:		***Cylinder Cap Units:***	
Approx Quant Rel:		***Cylinder Mat Type:***	
Tank Capacity:		***Pump Flow Rate Cap:***	
Fuels Occur Type:	Discovery of a Petroleum Product	***Contam. Migrated:***	
Occur Type Rpt:	Liquid Petroleum Spill	***Near Body of Water:***	
Occur Category:		***Drainage System:***	
Fuel Type Involved:	Gasoline	***Sub Surface Contam:***	
Fuel Type Reported:	Heating Fuel	***Tank Material Type:***	
Enforcement Policy:		***Tank Storage Type:***	
Prc Escalation Req:		***Tank Location Type:***	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	1460 MERIVALE RD		
Invent Postal Code:	K2E 5P2		
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:	SITE COMPLAIND OF FUEL IN DROP SUMP		
Operation Type Involved:	Retail Fuel Station (FS, SS, Multifunctional)		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	50 of 97	ENE/145.2	98.9 / -1.03	BCP IV SERVICE STATION LP O/A BG FUELS 1460 MERIVALE RD OTTAWA ON	INC

Incident No:	1254148	**Any Health Impact:**	
Incident ID:		**Any Enviro Impact:**	
Instance No:	35210393	**Service Intrp:**	
Status Code:		**Was Prop Damaged:**	
Incident Status:	Non Mandated	**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:		**Indus App. Type:**	
Attribute Category:	FS-Near Miss	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	
Date of Occurrence:	9/27/2013	**Operation Pressure:**	
Time of Occurrence:		**Equipment Type:**	
Occr Insp Start Dt:		**Equipment Model:**	
Incident Creat On:	9/27/2013	**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Discovery of a Petroleum Product	**Contam. Migrated:**	
Occur Type Rpt:	Leak	**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Gasoline	**Sub Surface Contam:**	
Fuel Type Reported:	Transportation Fuel	**Tank Material Type:**	
Enforcement Policy:		**Tank Storage Type:**	
Prc Escalation Req:		**Tank Location Type:**	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	1460 MERIVALE RD		
Invent Postal Code:	K2E 5P2		
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:	seen stain on asfault		
Operation Type Involved:	Retail Fuel Station (FS, SS, Multifunctional)		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	51 of 97	ENE/145.2	98.9 / -1.03	BCP IV SERVICE STATION LP O/A BG FUELS 1460 MERIVALE RD OTTAWA ON	INC

Incident No:	1255018	**Any Health Impact:**	
Incident ID:		**Any Enviro Impact:**	
Instance No:	35210393	**Service Intrp:**	
Status Code:		**Was Prop Damaged:**	
Incident Status:	Cancelled	**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:		**Indus App. Type:**	
Attribute Category:	FS-Near Miss	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	

Date of Occurrence:	9/30/2013	**Operation Pressure:**	
Time of Occurrence:		**Equipment Type:**	
Occr Insp Start Dt:		**Equipment Model:**	
Incident Creat On:	9/30/2013	**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:		**Contam. Migrated:**	
Occur Type Rpt:	Leak	**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:		**Sub Surface Contam:**	
Fuel Type Reported:	Transportation Fuel	**Tank Material Type:**	
Enforcement Policy:		**Tank Storage Type:**	
Prc Escalation Req:		**Tank Location Type:**	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	1460 MERIVALE RD		
Invent Postal Code:	K2E 5P2		
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:			
Operation Type Involved:	Retail Fuel Station (FS, SS, Multifunctional)		

14	***52 of 97***	***ENE/145.2***	***98.9 / -1.03***	***LOBLAWS LIMITED C.O.B. AS "LOBLAWS" 082-8*** ***1460 MERIVALE ROAD*** ***OTTAWA ON***	***PES***

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	53 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD. 1460 MERIVALE ROAD OTTAWA ON K2J 3W6	PES

Detail Licence No:		Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Vendor	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	54 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD #1082 1460 MERIVALE RD OTTAWA ON K2E 5P2	PES

Detail Licence No:	23-01-10216-0	Operator Box:	
Licence No:	10216	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Limited Vendor	Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:	0	Oper Concession:	
Latitude:		Operator Region:	4
Longitude:		Operator District:	
Lot:		Operator County:	15
Concession:		Op Municipality:	
Region:	4	Post Office Box:	
District:		MOE District:	
County:	15	SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	55 of 97	ENE/145.2	98.9 / -1.03	SHOPPERS DRUG MART #627 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Limited Vendor	Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Concession:				Op Municipality:	
Region:				Post Office Box:	
District:				MOE District:	
County:				SWP Area Name:	
Trade Name:					
PDF URL:					

14	56 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD #1082 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Vendor	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

14	57 of 97	ENE/145.2	98.9 / -1.03	SHOPPERS DRUG MART #627 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Vendor	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

14	58 of 97	ENE/145.2	98.9 / -1.03	SHOPPERS DRUG MART #627 1460 MERIVALE RD OTTAWA ON K2E 5P2	PES

Detail Licence No:	23-01-13266-0	Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	

Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	LIMITED	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

14 | ***59 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***LOBLAWS SUPERMARKETS LIMITED***
1460 MERIVALE RD
OTTAWA ON K2E5P2 | ***PES***

Detail Licence No:	23-01-00578-0	**Operator Box:**	
Licence No:	00578	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	
Lot:		**Operator County:**	62
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

14 | ***60 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***LOBLAWS SUPERMARKETS LTD.***
1460 MERIVALE RD
OTTAWA ON K2E5P2 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	17548	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	613
Licence Type:		**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	61 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD #1021 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		Operator Box:	
Licence No:	17549	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	613
Licence Type:		Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	62 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD. 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		Operator Box:	
Licence No:	17550	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	613
Licence Type:		Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	63 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS INC. STORE #1095 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:	23-01-08606-0	Operator Box:	
Licence No:	08606	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	613
Licence Type:	Limited Vendor	Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:	0	Oper Concession:	
Latitude:		Operator Region:	4

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Longitude:		**Operator District:**	
Lot:		**Operator County:**	15
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

14 | **64 of 97** | **ENE/145.2** | **98.9 / -1.03** | **LOBLAWS SUPERMARKETS LIMITED 1174**
1460 MERIVALE RD
OTTAWA ON K2E5P2 | **PES**

Detail Licence No:	23-01-08689-0	**Operator Box:**	
Licence No:	08689	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	
Lot:		**Operator County:**	62
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

14 | **65 of 97** | **ENE/145.2** | **98.9 / -1.03** | **LOBLAWS INC #1212**
1460 MERIVALE RD
OTTAWA ON K2E5P2 | **PES**

Detail Licence No:	23-01-11623-0	**Operator Box:**	
Licence No:	11623	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	
Lot:		**Operator County:**	62
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

14 | **66 of 97** | **ENE/145.2** | **98.9 / -1.03** | **LOBLAWS INC. # 1003**
1460 MERIVALE RD
OTTAWA ON K2E5P2 | **PES**

Detail Licence No:	23-01-11823-0	**Operator Box:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence No:	11823	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	1
Lot:		**Operator County:**	49
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

14 | ***67 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***ZEHRS MARKETS***
1460 MERIVALE RD
OTTAWA ON K2E5P2 | ***PES***

Detail Licence No:	23-01-09804-0	**Operator Box:**	
Licence No:	09804	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	519
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	2
Longitude:		**Operator District:**	
Lot:		**Operator County:**	13
Concession:		**Op Municipality:**	
Region:	2	**Post Office Box:**	
District:		**MOE District:**	
County:	13	**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

14 | ***68 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***LOBLAWS SUPERMARKETS #1027***
1460 MERIVALE RD
OTTAWA ON K2E1P5 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	17162	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	613
Licence Type:		**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
PDF URL:					

14	69 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS #1064 1460 MERIVALE RD OTTAWA ON K2E1P5	PES

Detail Licence No:		Operator Box:	
Licence No:	17163	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	613
Licence Type:		Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

14	70 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS #1090 1460 MERIVALE RD OTTAWA ON K2E1P5	PES

Detail Licence No:		Operator Box:	
Licence No:	17164	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	613
Licence Type:		Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

14	71 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD. STORE #1099 1460 MERIVALE RD OTTAWA ON K2E1P5	PES

Detail Licence No:		Operator Box:	
Licence No:	17165	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	613
Licence Type:		Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

14 | ***72 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***LOBLAWS SUPERMARKETS #1127***
1460 MERIVALE RD
OTTAWA ON K2E1P5 | ***PES***

Detail Licence No:
Licence No: 17166
Status:
Approval Date:
Report Source:
Licence Type:
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

14 | ***73 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***LOBLAWS SUPERMARKET #1170***
1460 MERIVALE RD
OTTAWA ON K2E1P5 | ***PES***

Detail Licence No:
Licence No: 17167
Status:
Approval Date:
Report Source:
Licence Type:
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

14 | ***74 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***LOBLAW SUPERMARKET #1200***
1460 MERIVALE RD
OTTAWA ON K2E5P2 | ***PES***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail Licence No:				Operator Box:	
Licence No:	17168			Operator Class:	
Status:				Operator No:	
Approval Date:				Operator Type:	
Report Source:				Oper Area Code:	613
Licence Type:				Oper Phone No:	
Licence Type Code:	23			Operator Ext:	
Licence Class:	01			Operator Lot:	
Licence Control:				Oper Concession:	
Latitude:				Operator Region:	
Longitude:				Operator District:	
Lot:				Operator County:	
Concession:				Op Municipality:	
Region:				Post Office Box:	
District:				MOE District:	
County:				SWP Area Name:	
Trade Name:					
PDF URL:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	75 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD. STORE #1208 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:				Operator Box:	
Licence No:	17169			Operator Class:	
Status:				Operator No:	
Approval Date:				Operator Type:	
Report Source:				Oper Area Code:	613
Licence Type:				Oper Phone No:	
Licence Type Code:	23			Operator Ext:	
Licence Class:	01			Operator Lot:	
Licence Control:				Oper Concession:	
Latitude:				Operator Region:	
Longitude:				Operator District:	
Lot:				Operator County:	
Concession:				Op Municipality:	
Region:				Post Office Box:	
District:				MOE District:	
County:				SWP Area Name:	
Trade Name:					
PDF URL:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	76 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD #1082 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:				Operator Box:	
Licence No:	10216			Operator Class:	
Status:				Operator No:	
Approval Date:				Operator Type:	
Report Source:	Legacy Licenses (Excluding TS)			Oper Area Code:	613
Licence Type:	Limited Vendor			Oper Phone No:	2266005
Licence Type Code:	23			Operator Ext:	
Licence Class:	01			Operator Lot:	
Licence Control:	0			Oper Concession:	
Latitude:				Operator Region:	4
Longitude:				Operator District:	
Lot:				Operator County:	15
Concession:				Op Municipality:	
Region:	4			Post Office Box:	
District:				MOE District:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
County:	15			SWP Area Name:	
Trade Name:					
PDF URL:					

14	77 of 97	ENE/145.2	98.9 / -1.03	ZEHRS MARKETS 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		Operator Box:	
Licence No:	17841	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:		Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

14	78 of 97	ENE/145.2	98.9 / -1.03	ZEHRS MARKETS #539 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		Operator Box:	
Licence No:	17842	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:		Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

14	79 of 97	ENE/145.2	98.9 / -1.03	ZEHRS MARKETS 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		Operator Box:	
Licence No:	17843	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:		Oper Phone No:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Type Code:	23		Operator Ext:	
Licence Class:	01		Operator Lot:	
Licence Control:			Oper Concession:	
Latitude:			Operator Region:	
Longitude:			Operator District:	
Lot:			Operator County:	
Concession:			Op Municipality:	
Region:			Post Office Box:	
District:			MOE District:	
County:			SWP Area Name:	
Trade Name:				
PDF URL:				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	80 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKET #1032 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:			Operator Box:	
Licence No:	16850		Operator Class:	
Status:			Operator No:	
Approval Date:			Operator Type:	
Report Source:			Oper Area Code:	905
Licence Type:			Oper Phone No:	
Licence Type Code:	23		Operator Ext:	
Licence Class:	01		Operator Lot:	
Licence Control:			Oper Concession:	
Latitude:			Operator Region:	
Longitude:			Operator District:	
Lot:			Operator County:	
Concession:			Op Municipality:	
Region:			Post Office Box:	
District:			MOE District:	
County:			SWP Area Name:	
Trade Name:				
PDF URL:				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	81 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS #1194 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:			Operator Box:	
Licence No:	16851		Operator Class:	
Status:			Operator No:	
Approval Date:			Operator Type:	
Report Source:			Oper Area Code:	613
Licence Type:			Oper Phone No:	
Licence Type Code:	23		Operator Ext:	
Licence Class:	01		Operator Lot:	
Licence Control:			Oper Concession:	
Latitude:			Operator Region:	
Longitude:			Operator District:	
Lot:			Operator County:	
Concession:			Op Municipality:	
Region:			Post Office Box:	
District:			MOE District:	
County:			SWP Area Name:	
Trade Name:				
PDF URL:				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	82 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD #1188 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:	23-01-11038-0	**Operator Box:**	
Licence No:	11038	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	4
Longitude:		**Operator District:**	
Lot:		**Operator County:**	15
Concession:		**Op Municipality:**	
Region:	4	**Post Office Box:**	
District:		**MOE District:**	
County:	56	**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	83 of 97	ENE/145.2	98.9 / -1.03	LOBLAWS SUPERMARKETS LTD #1082 1460 MERIVALE RD OTTAWA ON K2E5P2	PES

Detail Licence No:		**Operator Box:**	
Licence No:	10216	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Retail Vendor Class 03	**Oper Phone No:**	2266005
Licence Type Code:	21	**Operator Ext:**	
Licence Class:	03	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	84 of 97	ENE/145.2	98.9 / -1.03	C CORP (ONTARIO) INC ATTN ACCOUNTS PAYABLE 1460 MERIVALE RD NEPEAN ON K2E5P2	PRT

Location ID:	18792
Type:	retail
Expiry Date:	1991-06-30
Capacity (L):	0
Licence #:	0050971001

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	85 of 97	ENE/145.2	98.9 / -1.03	SUNYS PETROLEUM INC 1460 MERIVALE RD NEPEAN ON K2E5P2	PRT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Location ID:		18792			
Type:		retail			
Expiry Date:		1995-05-31			
Capacity (L):		2000			
Licence #:		0076420132			
14	86 of 97	ENE/145.2	98.9 / -1.03	SUNYS PETROLEUM INC 1460 MERIVALE RD NEPEAN ON K2E5P2	PRT
Location ID:		18792			
Type:		retail			
Expiry Date:		1995-12-31			
Capacity (L):		94500			
Licence #:		0076342534			
14	87 of 97	ENE/145.2	98.9 / -1.03	1460 MERIVALE RD. NEPEAN, ONT. ON	PRT
Location ID:		9657			
Type:		retail			
Expiry Date:					
Capacity (L):					
Licence #:					
14	88 of 97	ENE/145.2	98.9 / -1.03	Reno Realty Holdings Limited 1460 Merivale Road Ottawa, Ontario, K2E 5P2 OTTAWA ON	RSC

RSC No:	2181	**X:**	-75.73481539325748
RA No:		**Y:**	45.360848848120774
Status:	FILED	**Latitude:**	45.36084885
Filing Date:		**Longitude:**	-75.73481539
Date Ack:		**UTM Coordinates:**	
Date Returned:		**Latitude Longitude:**	
Approval Date:	September 6, 2005	**Accuracy Estimate:**	
Cert Date:		**Measurement Method:**	
Cert Prop Use No:		**Mailing Address:**	
Curr Property Use:		**Telephone:**	
Intended Prop Use:		**Fax:**	
Restoration Type:		**Email:**	
Soil Type:		**Postal Code:**	
Criteria:		**Ministry District:**	
Stratified (Y/N):		**MOE District:**	Ottawa
Audit (Y/N):		**SWP Area Name:**	Rideau Valley
Entire Leg Prop. (Y/N):		**Qual Person Name:**	Jane A Yaraskavitch
CPU Issu Sect 1686:		**Consultant:**	

Business Name:	Reno Realty Holdings Limited
Address:	1460 Merivale Road Ottawa, Ontario, K2E 5P2
Legal Desc:	
Site Pin:	04686-0011 (LT) (PINS for RSC portion of property are 04686-0011 and 04686-0012)
Asmt Roll No:	
Project Type:	PRE2011
Approval Type:	RSC based on Phase One and Two ESAs
Applicable Standards:	
PDF Link:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2181

14	89 of 97	ENE/145.2	98.9 / -1.03	SUNYS PETROLEUM INC 1460 MERIVALE RD	RST

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				NEPEAN ON K2E5P2	

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 6132262132
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	90 of 97	ENE/145.2	98.9 / -1.03	NATIONAL GROCERIES COMPANY LTD 1460 MERIVALE RD OTTAWA CITY ON	SPL

Ref No: 225207
Year:
Incident Dt: 5/12/2002
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/12/2000
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: NATIONAL GROCERIES: 30 L DIESEL SPILLED TO CUSTOME RS YARD. CLEAN UP STARTE
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

14 | ***91 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***NATIONAL GROCERIES COMPANY LTD***
1460 MERIVALE RD
OTTAWA CITY ON | ***SPL***

Ref No:	234800	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	8/5/2002	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	8/5/2002	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: NATIONAL GROCERIES:SMALL QUANT DIESEL TO ASPHALT FROM TRAILER, CLEANED UP.
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Offsite Impacts:
Waterbody Impacted:

---

14 | ***92 of 97*** | ***ENE/145.2*** | ***98.9 / -1.03*** | ***Loblaws Companies East*** | ***SPL***

1460 Merivale Rd.
Ottawa ON

Ref No:	4344-5V7QNB	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	1/2/2004	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	Gases/Particulate
MOE Reported Dt:	1/14/2004	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	LOBLAWS # 082<UNOFFICIAL>		
Site Address:			
Site Region:	Eastern		
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Loblaws Companies East		
Client Type:			
Source Type:			
Incident Cause:	Cooling System Leak		
Incident Preceding Spill:			
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	Loblaws - 300 lbs. R404A added to system.		
Environment Impact:	Not Anticipated		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:	38		
Contaminant Name:	REFRIGERANT GAS, N.O.S.		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Air		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Other		
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			
Source Sector Type:			
Conservtn Auth Name:			
Primary Watershed:			
Quaternary Watershed:			
Offsite Impacts:			
Waterbody Impacted:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	93 of 97	ENE/145.2	98.9 / -1.03	Parson Refrigeration (1985) Ltd. 1460 Merivale Rd Ottawa ON	SPL

Ref No:	2372-7THUJE	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	6/30/2009	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	1460 Merivale Road		
Site Address:			
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	NA		
Easting:	NA		
Entity Operating Name:			
Client Name:	Parson Refrigeration (1985) Ltd.		
Client Type:			
Source Type:			
Incident Cause:	Pipe Or Hose Leak		
Incident Preceding Spill:			
Incident Reason:	Spill		
Incident Summary:	Loblaws: 113 kg of R408A to atm		
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:	113 kg		
Contaminant Qty 1:	113		
Contaminant Unit:	kg		
Contaminant Code:			
Contaminant Name:	REFRIGERANT GAS, N.O.S.		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Other		
SAC Action Class:	Air Spills - Gases and Vapours		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			
Source Sector Type:			
Conservtn Auth Name:			
Primary Watershed:			
Quaternary Watershed:			
Offsite Impacts:			
Waterbody Impacted:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	94 of 97	ENE/145.2	98.9 / -1.03	Loblaws Inc. 1460 Merivale Road Ottawa ON K2E 5P2	SPL

Ref No:	3548-8QVNCC	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	25-JAN-12	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	26-JAN-12	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	

Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Loblaws<UNOFFICIAL>
Site Address: 1460 Merivale Road
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Loblaws Inc.
Client Type:
Source Type:
Incident Cause: Discharge or Emission to Air
Incident Preceding Spill:
Incident Reason: Spill
Incident Summary: Loblaws: 275 pounds of R507 to atm
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code: 38
Contaminant Name: REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	95 of 97	ENE/145.2	98.9 / -1.03	Loblaw Companies Limited 1460 Merivale Road Ottawa ON	SPL

Ref No:	6161-ALJRPN	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	4/18/2017	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/18/2017	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	Loblaw<UNOFFICIAL>		
Site Address:	1460 Merivale Road		
Site Region:	Eastern		
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	5023265		
Easting:	442422		
Entity Operating Name:			
Client Name:	Loblaw Companies Limited		
Client Type:	Corporation		
Source Type:	Container/Drum/Tote		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Incident Reason:	Corrosion		
Incident Summary:	Loblaw: cooking grease to asphalt, manhole, clng		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	0 other - see incident description		
Contaminant Qty 1:	0		
Contaminant Unit:	other - see incident description		
Contaminant Code:	16		
Contaminant Name:	COOKING OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	n/a		
Receiving Medium:	Land		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Miscellaneous Communal		
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			
Source Sector Type:			
Conservtn Auth Name:			
Primary Watershed:			
Quaternary Watershed:			
Offsite Impacts:			
Waterbody Impacted:			

14	96 of 97	ENE/145.2	98.9 / -1.03	**Seaboard Transport** **1460 Merivale Rd** **Ottawa ON K2E 5P2**	SPL

Ref No:	7624-ASVJWP	**Municipality No:**	
Year:		**Nature of Damage:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Dt:	2017/11/01	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2017/11/07	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	

Site No: 8599-6H4QAA
MOE Response: No
Site County/District: NA
Site Geo Ref Meth: NA
Site District Office: Ottawa
Nearest Watercourse:
Site Name: 1460 Merivale Road
Site Address: 1460 Merivale Rd
Site Region: Eastern
Site Municipality: Ottawa
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Entity Operating Name:
Client Name: Seaboard Transport
Client Type: Corporation
Source Type: Truck - Transport/Hauling
Incident Cause:
Incident Preceding Spill: Overflow/Surcharge
Incident Reason: Operator/Human Error
Incident Summary: Seaboard Transport: gasoline UST overfilled at Loblaws
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 12
Contaminant Name: GASOLINE
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1203
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

14	97 of 97	ENE/145.2	98.9 / -1.03	1460 Merivale, Ottawa OTTAWA ON	SPL

Ref No:	1-4NCLKB	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2/9/2024 5:13:15 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2/9/2024 5:13:15 PM	**Impact to Health:**	
Dt Document Closed:	2/12/2024 8:22:14 AM	**Agency Involved:**	

Site No:	
MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Ottawa District Office
Nearest Watercourse:	cb
Site Name:	
Site Address:	1460 Merivale, Ottawa
Site Region:	
Site Municipality:	OTTAWA
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	Motor Vehicle
Incident Cause:	
Incident Preceding Spill:	Accident/Collision
Incident Reason:	Improper operation
Incident Summary:	Ottawa 311 - MVA, Unknown amount of motor liquid spilled to ground, cb impacted
Environment Impact:	
Health Env Consequence:	Low
Nature of Impact:	
Contaminant Qty:	1 litre (L)
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	GLYCOL/WATER SOLUTION
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	Transportation
Property 2nd Watershed:	Lower Ottawa
Property Tertiary Watershed:	02KF - Central Ottawa - Mississippi
Sector Type:	PRIVATE HOUSEHOLDS
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00003791672"],"wkts":["POINT (-75.7353518000 45.3619299000)"],"creation_date":"2024-02-09"}
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

---

15 | ***1 of 1*** | ***ENE/167.1*** | ***97.4 / -2.49*** | ***1308, 1330 and 1350 Baseline Road and 1460 Merivale Road, Ottawa, ON Nepean ON K2E 5N9*** | ***EHS***

Order No:	20190910305	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	18-SEP-19	**Search Radius (km):**	.15
Date Received:	10-SEP-19	**X:**	-75.734927
Previous Site Name:		**Y:**	45.362409
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

16 | **1 of 1** | **WNW/167.5** | **98.9 / -1.03** | **Ottawa SW Propco LP**
1405 Baseline RD
Ottawa ON K2C 3G1 | **EASR**

Approval No:	R-009-1177619341	**MOE District:**	Ottawa
Status:	REGISTERED	**Municipality:**	Ottawa
Date:	May 10, 2022	**Latitude:**	45.36222222
Record Type:	EASR	**Longitude:**	-75.73944444
Link Source:	MOFA	**Geometry X:**	
Project Type:	Water Taking - Construction Dewatering	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Water Taking - Construction Dewatering		
SWP Area Name:	Rideau Valley		
PDF NAICS Code:			
PDF URL:	httpss://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2637701		
PDF Site Location:			

17 | **1 of 1** | **WSW/170.6** | **98.9 / -1.00** | **1331 CLYDE AVE.**
Ottawa ON | **WWIS**

Well ID:	7207624	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	09/12/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z176282	**Contractor:**	7241
Tag:	A119309	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7207624.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/13/2013
Year Completed:	2013
Depth (m):	
Latitude:	45.3613262776323
Longitude:	-75.7389457706133
Point X:	-75.7389456093383
Point Y:	45.36132627146771
Path:	720\7207624.pdf

Bore Hole Information

Bore Hole ID:	1004561978	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442127.00

Code OB Desc:		***North83:***	5023356.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	07/13/2013	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004597511
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004597512
Layer:	2
Plug From:	0.5
Plug To:	37.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004597510
Method Construction Code:	
Method Construction:	
Other Method Construction:	

Pipe Information

Pipe ID:	1004597503
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004597507
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004597508

Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1004597506
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004597505
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

18 ***1 of 1*** ***WSW/170.6*** ***98.9 / -1.03*** ***1331 CLYDE AVE. Ottawa ON*** ***WWIS***

Well ID:	7207625	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	09/12/2013
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z176272	***Contractor:***	7241
Tag:	A145222	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7207625.pdf

Additional Detail(s) (Map)

Well Completed Date: 02/13/2013
Year Completed: 2013
Depth (m):
Latitude: 45.3612008473353
Longitude: -75.7388547590721
Point X: -75.73885459746441
Point Y: 45.361200840109106

Path: 720\7207625.pdf

Bore Hole Information

Bore Hole ID: 1004561981
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/13/2013
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 442134.00
North83: 5023342.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004597521
Layer: 1
Plug From: 0.0
Plug To: 0.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004597522
Layer: 2
Plug From: 0.5
Plug To: 32.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004597520
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1004597513
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004597517
Layer:
Material:
Open Hole or Material:
Depth From:

Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004597518
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1004597516
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004597515
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

19 | ***1 of 12*** | ***SW/171.6*** | ***98.9 / -1.03*** | ***CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr*****
1400 BASELINE RD
OTTAWA ON K2C 0A9 | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10299067
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:

Expired Date: 5/25/2002
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

19	*2 of 12*	*SW/171.6*	*98.9 / -1.03*	***CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr***** ***1400 BASELINE RD*** ***OTTAWA ON***	*DTNK*

Delisted Expired Fuel Safety Facilities

Instance No: 11607953
Status: EXPIRED
Instance ID: 93740
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

19	*3 of 12*	*SW/171.6*	*98.9 / -1.03*	***CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr***** ***1400 BASELINE RD*** ***OTTAWA ON***	*DTNK*

Delisted Expired Fuel Safety Facilities

Instance No: 11607965
Status: EXPIRED
Instance ID: 93743

Expired Date:
Max Hazard Rank:
Facility Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

19 | ***4 of 12*** | ***SW/171.6*** | ***98.9 / -1.03*** | ***CANADIAN TIRE CORPORATION LIMITED*** ***1400 BASELINE RD*** ***OTTAWA ON*** | ***EXP***

Inventory No: 11607923
Inventory Status: EXPIRED
Installation Year: 1970
Capacity: 45000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Internally Lined
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

19 | ***5 of 12*** | ***SW/171.6*** | ***98.9 / -1.03*** | ***CANADIAN TIRE CORPORATION LIMITED*** ***1400 BASELINE RD*** ***OTTAWA ON*** | ***EXP***

Inventory No: 11607940
Inventory Status: EXPIRED
Installation Year: 1970
Capacity: 45000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Internally Lined
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

19 | ***6 of 12*** | ***SW/171.6*** | ***98.9 / -1.03*** | ***CANADIAN TIRE CORPORATION LIMITED*** ***1400 BASELINE RD*** ***OTTAWA ON*** | ***EXP***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory No:	11607905	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	1970	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	LICENCED UNDERGROUND TANKS		
Previous Fuel Type:	Gasoline		

---

19 | ***7 of 12*** | ***SW/171.6*** | ***98.9 / -1.03*** | ***CANADIAN TIRE CORPORATION LIMITED 1400 BASELINE RD OTTAWA ON*** | ***EXP***

Inventory No:	11607914	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	1970	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	LICENCED UNDERGROUND TANKS		
Previous Fuel Type:	Gasoline		

---

19 | ***8 of 12*** | ***SW/171.6*** | ***98.9 / -1.03*** | ***CANADIAN TIRE CORPORATION LIMITED 1400 BASELINE RD OTTAWA ON*** | ***EXP***

Inventory No:	11607918	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Fiberglass
Installation Year:	1992	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	LICENCED UNDERGROUND TANKS		
Previous Fuel Type:	Gasoline		

---

19 | ***9 of 12*** | ***SW/171.6*** | ***98.9 / -1.03*** | ***CANADIAN TIRE CORPORATION LIMITED 1400 BASELINE RD OTTAWA ON*** | ***EXP***

Inventory No:	11607899	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	1970	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	LICENCED UNDERGROUND TANKS		
Previous Fuel Type:	Gasoline		

---

19 | ***10 of 12*** | ***SW/171.6*** | ***98.9 / -1.03*** | ***CANADIAN TIRE CORPORATION LIMITED 1400 BASELINE RD OTTAWA ON*** | ***EXP***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory No: 11607888
Inventory Status: EXPIRED
Installation Year: 1970
Capacity: 45000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Internally Lined
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

19 | **11 of 12** | **SW/171.6** | **98.9 / -1.03** | **GEN**

DUPONT CONTRACTING
1400 BASELINE RD
OTTAWA ON K2C 0A9

Generator Info

Generator No: ON7678511
Approval Years: 04
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Environmental Consulting Services
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 541620

---

19 | **12 of 12** | **SW/171.6** | **98.9 / -1.03** | **PRT**

CANADIAN TIRE CORP LTD PETROLEUM DIVISION - SUSAN
1400 BASELINE RD
OTTAWA ON K2C 0A9

Location ID: 10858
Type: retail
Expiry Date: 1995-06-30
Capacity (L): 109104
Licence #: 0012228008

---

20 | **1 of 1** | **WSW/172.7** | **98.9 / -1.00** | **WWIS**

ON

Well ID: 7479650
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z428689
Tag: A366101
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 06/17/2024
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Site Info:

Additional Detail(s) (Map)

Bore Hole ID:	1010365449	***Tag No:***	A366101
Depth (m):		***Contractor:***	7241
Year Completed:	2024	***Latitude:***	45.3612633559961
Well Completed Dt:	02/23/2024	***Longitude:***	-75.738932183095
Audit No:	Z428689	***Point Y:***	45.3612633491108
Path:		***Point X:***	-75.73893202143115

Bore Hole Information

Bore Hole ID:	1010365449	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442128.00
Code OB Desc:		***North83:***	5023349.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	02/23/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

21 ***1 of 1*** ***ENE/175.7*** ***97.4 / -2.49*** ***1460 Merivale Road Nepean ON K2E 5N9*** ***EHS***

Order No:	20181015178	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	26-OCT-18	***Search Radius (km):***	.25
Date Received:	15-OCT-18	***X:***	-75.734814
Previous Site Name:		***Y:***	45.362415
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

---

22 ***1 of 1*** ***WSW/177.0*** ***98.9 / -1.00*** ***ON*** ***WWIS***

Well ID:	7479648	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	06/17/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z428690	***Contractor:***	7241
Tag:	A366107	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	

Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1010365443	**Tag No:**	A366107
Depth (m):		**Contractor:**	7241
Year Completed:	2024	**Latitude:**	45.3611644319349
Well Completed Dt:	02/23/2024	**Longitude:**	-75.7389181269425
Audit No:	Z428690	**Point Y:**	45.36116442499375
Path:		**Point X:**	-75.73891796550495

Bore Hole Information

Bore Hole ID:	1010365443	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442129.00
Code OB Desc:		**North83:**	5023338.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/23/2024	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	1 of 1	SE/177.9	97.8 / -2.06	lot 35 con A ON	WWIS

Well ID:	1504637	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Commerical	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	07/04/1961
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1301
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	035
Depth to Bedrock:		**Concession:**	A
Well Depth:		**Concession Name:**	RF
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504637.pdf

Additional Detail(s) (Map)

Well Completed Date:	06/22/1961
Year Completed:	1961

Depth (m): 80.772
Latitude: 45.3608636213929
Longitude: -75.7353173792374
Point X: -75.73531721723073
Point Y: 45.36086361435496
Path: 150\1504637.pdf

Bore Hole Information

Bore Hole ID: 10026680
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/22/1961
Remarks:
Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 442410.70
North83: 5023302.00
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931000025
Layer: 2
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 28.0
Formation End Depth: 265.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931000024
Layer: 1
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2: 13
Material 2 Desc: BOULDERS
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 28.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961504637
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10575250
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930046090
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 30.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930046091
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 265.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991504637
Pump Set At:
Static Level: 10.0
Final Level After Pumping: 265.0
Recommended Pump Depth: 265.0
Pumping Rate: 10.0
Flowing Rate:
Recommended Pump Rate: 3.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 45
Flowing: No

Water Details

Water ID: 933457935
Layer: 1
Kind Code: 1

Kind:	FRESH
Water Found Depth:	265.0
Water Found Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	1 of 23	WSW/180.6	98.9 / -1.00	1332717 ONTARIO INC T/P PETRO CANADA 1432 BASELINE RD OTTAWA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11577128	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	91589	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	2 of 23	WSW/180.6	98.9 / -1.00	1332717 ONTARIO INC T/P PETRO CANADA 1432 BASELINE RD OTTAWA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11585530	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	91911	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

24 ***3 of 23*** ***WSW/180.6*** ***98.9 / -1.00*** ***SUNCOR ENERGY PRODUCTS PARTNERSHIP***
1432 BASELINE RD
OTTAWA ON
FST

Inventory No: 10868577
Inventory Status: active
Installation Year: 1991
Capacity: 35000
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

24 ***4 of 23*** ***WSW/180.6*** ***98.9 / -1.00*** ***SUNCOR ENERGY PRODUCTS PARTNERSHIP***
1432 BASELINE RD
OTTAWA ON
FST

Inventory No: 11322321
Inventory Status: active
Installation Year: 1991
Capacity: 35000
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

24 ***5 of 23*** ***WSW/180.6*** ***98.9 / -1.00*** ***SUNCOR ENERGY PRODUCTS PARTNERSHIP***
1432 BASELINE RD
OTTAWA ON
FST

Inventory No: 11322298
Inventory Status: active
Installation Year: 1991
Capacity: 35000
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	6 of 23	WSW/180.6	98.9 / -1.00	SUNCOR ENERGY PRODUCTS PARTNERSHIP 1432 BASELINE RD OTTAWA ON	FST

Inventory No:	11577112	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1991	**Overfill Protection:**	
Capacity:	35000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	7 of 23	WSW/180.6	98.9 / -1.00	SUNCOR ENERGY PRODUCTS PARTNERSHIP 1432 BASELINE RD OTTAWA ON	FST

Inventory No:	70001747	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2021	**Overfill Protection:**	
Capacity:	100000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	8 of 23	WSW/180.6	98.9 / -1.00	SUNCOR ENERGY PRODUCTS PARTNERSHIP 1432 BASELINE RD OTTAWA ON	FST

Inventory No:	70001748	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2021	**Overfill Protection:**	
Capacity:	100000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	Split: 50k prem, 50K diesel		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	9 of 23	WSW/180.6	98.9 / -1.00	SUNCOR ENERGY PRODUCTS PARTNERSHIP 1432 BASELINE RD OTTAWA ON	FST

Inventory No:	9833910	**Tank Material:**	
Inventory Status:	Active	**Corrosion Protect:**	
Installation Year:		**Overfill Protection:**	
Capacity:	200000	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			
Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	10 of 23	WSW/180.6	98.9 / -1.00	6133487 CANADA INC O/A GAS STN 1432 BASELINE RD OTTAWA ON K2C 0A9	FSTH

License Issue Date: 3/13/2006
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Not-Active
Year of Installation:
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	11 of 23	WSW/180.6	98.9 / -1.00	1332717 ONTARIO INC T/P PETRO CANADA 1432 BASELINE RD OTTAWA ON K2C 0A9	FSTH

License Issue Date: 3/14/2008 12:32:00 PM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active

Year of Installation:	1988
Corrosion Protection:	
Capacity:	35000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1988
Corrosion Protection:	
Capacity:	35000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1988
Corrosion Protection:	
Capacity:	35000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1999
Corrosion Protection:	
Capacity:	35000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Diesel

24	**12 of 23**	**WSW/180.6**	**98.9 / -1.00**	**Suncor Energy Products Partnership** **1432 Baseline Road** **Ottawa ON K2C 0A9**	**GEN**

Generator Info

Generator No:	ON6471549	**Choice of Contact:**	
Approval Years:	As of Nov 2021	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class:	221 L
Waste Class Name:	Light fuels

2021 Generator Info

Gen No:	ON6471549	**Choice of Contact:**	CO_ADMIN
ID:	26156	**Phone No Official:**	905-804-5734 Ext.
Contaminated Fac:	N	**Phone No Admin:**	4162099562 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	447110	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			
Gen Name:	Suncor Energy Products Partnership		
Gen Div:			
Gen Op Name:	Suncor Energy Products Partnership		

Gen Op Div:
Site Adrs1: 1432 Baseline Road
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 0A9
Site Country: Canada
Co Official: Amir Jashanica
Co Admin: Siratha Siratha Chhan

2021 Generator Manifest

ID: 49283
Generator No: ON6471549
Receiver Type: 035
Waste Char: L
Waste Code: 221
Sum Received Qty: 155340.0
Waste Class Name: LIGHT FUELS
Count Manifests: 10
District: 402

2021 Generator Manifest

ID: 49282
Generator No: ON6471549
Receiver Type: 035
Waste Char: L
Waste Code: 221
Sum Received Qty: 12190.0
Waste Class Name: LIGHT FUELS
Count Manifests: 1
District: 305

24	13 of 23	WSW/180.6	98.9 / -1.00	Suncor Energy Product Partnership 1432 Baseline Road Ottawa ON	GEN

Generator Info (as of Dec 2024)

Generator No: ON001064426
Generator Company Name: Suncor Energy Product Partnership
Street: 1432 Baseline Road
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K2C 0A9
Waste Class: 221 L

Waste Class Decoded:

221 - LIGHT FUELS

Generator Info (as of Apr 2025)

Generator Company Name: Suncor Energy Product Partnership
Generator Site Address: 1432 Baseline Road
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K2C 0A9
Waste Class: 221 L

Waste Class Decoded:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

221 - LIGHT FUELS

Waste Characteristic Decoded:

L - Liquid Industrial Waste

---

24 ***14 of 23*** ***WSW/180.6*** ***98.9 / -1.00*** ***Erler's Service Station*** ***HBAR***
1432 Baseline Rd
Ottawa ON

Province: ON
Year: 1960
Source: Mights

---

24 ***15 of 23*** ***WSW/180.6*** ***98.9 / -1.00*** ***ENBRIDGE GAS INC*** ***PINC***
1432 BASELINE RD,,OTTAWA,ON,K2C 0A9,CA
ON

Incident Id:
Incident No: 3082884
Incident Reported Dt: 7/21/2021
Type: FS-Pipeline Incident
Status Code:
Tank Status: Non Mandated
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: ENBRIDGE GAS INC
Incident Address: 1432 BASELINE RD,,OTTAWA,ON,K2C 0A9,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

---

24 ***16 of 23*** ***WSW/180.6*** ***98.9 / -1.00*** ***PETRO CANADA NEIGHBOURS*** ***PRT***
1432 BASELINE RD
NEPEAN ON K2C 0A9

Location ID: 9577
Type: retail
Expiry Date: 1994-10-31
Capacity (L): 28650
Licence #: 0076340355

---

24 ***17 of 23*** ***WSW/180.6*** ***98.9 / -1.00*** ***NEIGHBOUR'S PETRO-CANADA*** ***RST***
1432 BASE LINE RD
OTTAWA ON K2C0A9

Headcode: 1186800

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 6132261219
List Name:
Description:

---

24 | **18 of 23** | **WSW/180.6** | **98.9 / -1.00** | **NEIGHBOUR'S PETRO-CANADA**
1432 BASELINE RD
OTTAWA ON K2C 0A9 | **RST**

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 6132261219
List Name:
Description:

---

24 | **19 of 23** | **WSW/180.6** | **98.9 / -1.00** | **PETRO-CANADA**
1432 BASELINE RD
OTTAWA ON K2C 0A9 | **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

---

24 | **20 of 23** | **WSW/180.6** | **98.9 / -1.00** | **PETRO-CANADA**
1432 BASELINE RD
OTTAWA ON K2C0A9 | **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 6132261219
List Name:
Description:

---

24 | **21 of 23** | **WSW/180.6** | **98.9 / -1.00** | **PETRO-CANADA**
1432 BASELINE RD. AT CLYDE SERVICE STATION
OTTAWA CITY ON K2C 0A9 | **SPL**

Ref No: 18151
Year:
Incident Dt: 10/6/1988
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/6/1988
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:

Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: BACKENTRY, PETRO CANADA SERV. STN. -42 L. GASOLINE TO GROUND.
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

24	22 of 23	WSW/180.6	98.9 / -1.00	Petro-Canada 1432 Baseline Road, Ottawa ON K2C 0A9	SPL

Ref No: 6014-7JZNSZ
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/1/2008
Dt Document Closed: 12/19/2008
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Ottawa
Nearest Watercourse:
Site Name: Petro Canada Gas Station<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Entity Operating Name:	
Client Name:	Petro-Canada
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	
Incident Summary:	2L of fuel to CB
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Other Impact(s)
Contaminant Qty:	20 L
Contaminant Qty 1:	20
Contaminant Unit:	L
Contaminant Code:	13
Contaminant Name:	FUEL (N.O.S.)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Storage Depot
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	23 of 23	WSW/180.6	98.9 / -1.00	1432 Baseline Road, Ottawa, ON, Canada OTTAWA ON	SPL

Ref No:	1-103Q0B	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	7/20/2021 4:12:45 PM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	7/20/2021 5:55:02 PM	***Impact to Health:***	0 No Impact
Dt Document Closed:	9/23/2021 8:52:46 AM	***Agency Involved:***	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	1432 Baseline Road, Ottawa, ON, Canada		
Site Region:			
Site Municipality:	OTTAWA		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:	Pipeline/Components		

Incident Cause:	
Incident Preceding Spill:	Weather Event
Incident Reason:	Severe weather (Specify)
Incident Summary:	FSB: 1" plastic IP line strike, made safe & repaired.
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see notes
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	METHANE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Activity Preceding Spill:	Construction or repair
Property 2nd Watershed:	Central Ottawa
Property Tertiary Watershed:	02KF-Central Ottawa - Mississippi
Sector Type:	NATURAL GAS DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00003947174"],"wkts":["POINT (-75.7390965000 45.3611753000)","POINT (-75.7390965000 45.3611753000)"],"creation_date":"2021-07-20"}
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

---

25 | ***1 of 1*** | ***WSW/180.6*** | ***98.9 / -1.00*** | ***1432 BASELINE ROAD Ottawa, Ontario ON K2C 0A9*** | ***EHS***

Order No:	24040400542	**Nearest Intersection:**	
Status:	C	**Municipality:**	OTTAWA
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	09-APR-24	**Search Radius (km):**	.3
Date Received:	04-APR-24	**X:**	-75.73904675
Previous Site Name:		**Y:**	45.36126536
Lot/Building Size:	2713.52 m2		
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

---

26 | ***1 of 1*** | ***SE/181.5*** | ***98.6 / -1.34*** | ***lot 35 con A ON*** | ***WWIS***

Well ID:	1504638	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Commerical	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	07/04/1961
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1301
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	035
Depth to Bedrock:		**Concession:**	A
Well Depth:		**Concession Name:**	RF
Overburden/Bedrock:		**Easting NAD83:**	

Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504638.pdf

Additional Detail(s) (Map)

Well Completed Date: 06/27/1961
Year Completed: 1961
Depth (m): 60.96
Latitude: 45.3607732042608
Longitude: -75.7353800494056
Point X: -75.73537988728512
Point Y: 45.360773197384844
Path: 150\1504638.pdf

Bore Hole Information

Bore Hole ID: 10026681
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/27/1961
Remarks:
Elevation:
Elevrc:
Zone: 18
East83: 442405.70
North83: 5023292.00
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5
Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931000026
Layer: 1
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2: 13
Material 2 Desc: BOULDERS
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 28.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931000027
Layer: 2
Color: 2
General Color: GREY

Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 28.0
Formation End Depth: 200.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961504638
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10575251
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930046092
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 30.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930046093
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 200.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991504638
Pump Set At:
Static Level: 10.0
Final Level After Pumping: 200.0
Recommended Pump Depth: 190.0
Pumping Rate: 10.0
Flowing Rate:
Recommended Pump Rate: 5.0
Levels UOM: ft
Rate UOM: GPM

Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	15
Flowing:	No

Water Details

Water ID:	933457936
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	200.0
Water Found Depth UOM:	ft

28 ***1 of 1*** ***WSW/183.3*** ***98.9 / -1.00*** ***ON*** ***WWIS***

Well ID:	7474014	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	03/22/2024
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z425473	**Contractor:**	7241
Tag:	A400140	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1010284935	**Tag No:**	A400140
Depth (m):		**Contractor:**	7241
Year Completed:	2024	**Latitude:**	45.3613520402511
Well Completed Dt:	02/15/2024	**Longitude:**	-75.73913763224
Audit No:	Z425473	**Point Y:**	45.3613520333348
Path:		**Point X:**	-75.73913747055262

Bore Hole Information

Bore Hole ID:	1010284935	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442112.00
Code OB Desc:		**North83:**	5023359.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/15/2024	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

---

29 | **1 of 1** | **E/184.8** | **96.9 / -3.03** | **lot 35 con A ON** | **WWIS**

Well ID:	1504627	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Commerical	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	10/28/1957
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1301
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	035
Depth to Bedrock:		**Concession:**	A
Well Depth:		**Concession Name:**	RF
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NEPEAN TOWNSHIP
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504627.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/25/1957
Year Completed: 1957
Depth (m): 64.6176
Latitude: 45.3622182320826
Longitude: -75.7346326538969
Point X: -75.73463249268707
Point Y: 45.36221822503715
Path: 150\1504627.pdf

Bore Hole Information

Bore Hole ID:	10026670	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442465.70
Code OB Desc:		**North83:**	5023452.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	09/25/1957	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	931000002
Layer:	2
Color:	
General Color:	
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	212.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931000001
Layer:	1
Color:	
General Color:	
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961504627
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10575240
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930046070
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	212.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930046069
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	22.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991504627
Pump Set At:	
Static Level:	25.0
Final Level After Pumping:	80.0
Recommended Pump Depth:	
Pumping Rate:	25.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933457925
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	80.0
Water Found Depth UOM:	ft

---

30 ***1 of 1*** ***ESE/187.4*** ***97.8 / -2.06*** ***ON*** ***WWIS***

Well ID:	7242904	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	06/11/2015
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	C21266	***Contractor:***	1844
Tag:	A142515	***Form Version:***	8
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1005405708	***Tag No:***	A142515
Depth (m):		***Contractor:***	1844
Year Completed:	2013	***Latitude:***	45.3609462952052
Well Completed Dt:	04/11/2013	***Longitude:***	-75.7350592532014
Audit No:	C21266	***Point Y:***	45.360946288359706
Path:		***Point X:***	-75.73505909090393

Bore Hole Information

Bore Hole ID:	1005405708	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442431.00
Code OB Desc:		***North83:***	5023311.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	04/11/2013	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

31 ***1 of 1*** ***W/188.0*** ***99.0 / -0.95*** ***Clyde Ave Ottawa ON*** ***EHS***

Order No:	20190404015	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	RSC Report (Urban)	***Client Prov/State:***	ON
Report Date:	09-APR-19	***Search Radius (km):***	.3
Date Received:	04-APR-19	***X:***	-75.739317
Previous Site Name:		***Y:***	45.362306
Lot/Building Size:			
Additional Info Ordered:			

---

32 ***1 of 1*** ***WSW/188.1*** ***98.9 / -1.00*** ***1331 CLYDE AVE. Ottawa ON*** ***WWIS***

Well ID:	7207626	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	09/12/2013
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z176273	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	

Municipality: OTTAWA CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7207626.pdf

Additional Detail(s) (Map)

Well Completed Date: 07/13/2013
Year Completed: 2013
Depth (m):
Latitude: 45.361118602846
Longitude: -75.7390452139969
Point X: -75.73904505192661
Point Y: 45.36111859631282
Path: 720\7207626.pdf

Bore Hole Information

Bore Hole ID: 1004561984
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 07/13/2013
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 442119.00
North83: 5023333.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004597532
Layer: 2
Plug From: 0.5
Plug To: 42.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004597531
Layer: 1
Plug From: 0.0
Plug To: 0.5
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004597530
Method Construction Code:
Method Construction:
Other Method Construction:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Pipe Information

Pipe ID: 1004597523
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004597527
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004597528
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1004597526
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004597525
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

33	1 of 19	SW/188.7	98.9 / -1.03	***CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr***** ***1375 CLYDE AV*** ***NEPEAN ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10133984
Status: EXPIRED
Instance ID: 12529
Expired Date:
Max Hazard Rank:
Facility Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Cylr Handling Facility		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

---

33 | ***2 of 19*** | ***SW/188.7*** | ***98.9 / -1.03*** | ***1375 CLYDE STORAGE GP CORPORATION*** | ***ECA***

1375 Clyde Ave
Ottawa ON K1H 8K3

Approval No:	7167-CPHHHC	**MOE District:**	Ottawa
Approval Date:	March 3, 2023	**City:**	
Status:	Approved	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	-8431269.2146000024
SWP Area Name:	Rideau Valley	**Geometry Y:**	5678525.6415000027
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	1375 CLYDE STORAGE GP CORPORATION		
Address:	1375 Clyde Ave		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3872-CNTN6P-14.pdf		
PDF Site Location:	1375 Clyde Avenue Ottawa, Ontario		

---

33 | ***3 of 19*** | ***SW/188.7*** | ***98.9 / -1.03*** | ***1375 Clyde Avenue*** | ***EHS***

Ottawa ON

Order No:	20120419018	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Site Report	**Client Prov/State:**	MA
Report Date:	4/20/2012 11:17:22 AM	**Search Radius (km):**	0.25
Date Received:	4/19/2012 11:16:35 AM	**X:**	-75.73915
Previous Site Name:		**Y:**	45.360758
Lot/Building Size:			
Additional Info Ordered:			

---

33 | ***4 of 19*** | ***SW/188.7*** | ***98.9 / -1.03*** | ***Savers, Inc.*** | ***GEN***

1375 CLYDE AVE. STORE #2081
OTTAWA ON

Generator Info

Generator No:	ON3033254	***Choice of Contact:***	
Approval Years:	06	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	448199
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Clothing Stores		

Waste Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	242
Waste Class Name:	HALOGENATED PESTICIDES

33	***5 of 19***	***SW/188.7***	***98.9 / -1.03***	***Value Village Stores, Inc.*** ***1375 CLYDE AVE. STORE #2081*** ***OTTAWA ON K2G 3H7***	***GEN***

Generator Info

Generator No:	ON3033254	***Choice of Contact:***	
Approval Years:	07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	

PO Box No: ***SIC Code:*** 448199
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Clothing Stores

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

33	***6 of 19***	***SW/188.7***	***98.9 / -1.03***	***Value Village Stores, Inc.*** ***1375 CLYDE AVE. STORE #2081*** ***OTTAWA ON***	***GEN***

Generator Info

Generator No: ON3033254
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Clothing Stores

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 448199

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

33	7 of 19	SW/188.7	98.9 / -1.03	***Value Village Stores, Inc.*** ***1375 CLYDE AVE. STORE #2081***	GEN

OTTAWA ON

Generator Info

Generator No:	ON3033254	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	448199
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Clothing Stores		

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 312

Waste Class Name: PATHOLOGICAL WASTES

---

33 | **8 of 19** | **SW/188.7** | **98.9 / -1.03** | **Value Village Stores, Inc.**
1375 CLYDE AVE. STORE #2081
OTTAWA ON | **GEN**

Generator Info

Generator No:	ON3033254	**Choice of Contact:**	
Approval Years:	2011	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	448199
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Clothing Stores		

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

---

33 | ***9 of 19*** | ***SW/188.7*** | ***98.9 / -1.03*** | ***Value Village Stores***
1375 CLYDE AVE. STORE #2081
OTTAWA ON K2G 3H7 | ***GEN***

Generator Info

Generator No: ON3033254
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Clothing Stores

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 448199

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

33 | ***10 of 19*** | ***SW/188.7*** | ***98.9 / -1.03*** | ***Value Village Stores***
1375 CLYDE AVE. STORE #2081
OTTAWA ON | ***GEN***

Generator Info

Generator No: ON3033254
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ALL OTHER CLOTHING STORES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 448199

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

33 | **11 of 19** | **SW/188.7** | **98.9 / -1.03** | **Value Village Stores**
1375 CLYDE AVE. STORE #2081
OTTAWA ON K2G 3H7 | **GEN**

Generator Info

Generator No:	ON3033254	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	448199
Country:	Canada		
Co Admin:			
Phone No Admin:			

SIC Description: ALL OTHER CLOTHING STORES

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

2017 Generator Info

Gen No: ON3033254
ID: 12309
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 448199
NAICS Code2:
NAICS Code3:

Choice of Contact: CO_OFFICIAL
Phone No Official: 615-773-8600 Ext.
Phone No Admin:
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Gen Name:	Value Village Stores
Gen Div:	
Gen Op Name:	VALUE VILLAGE STORE #2081
Gen Op Div:	
Site Adrs1:	1375 CLYDE AVE.
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	STORE #2081
Site City:	OTTAWA
Province Out:	
Site Postal Code:	K2G 3H7
Site Country:	Canada
Co Official:	RANDY RAINES
Co Admin:	

2017 Generator Manifest

ID:	34257	**Sum Received Qty:**	8.0
Generator No:	ON3033254	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	L	**District:**	402
Waste Code:	252		

2017 Generator Manifest

ID:	34259	**Sum Received Qty:**	13.0
Generator No:	ON3033254	**Waste Class Name:**	PHARMACEUTICALS
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	L	**District:**	402
Waste Code:	261		

2017 Generator Manifest

ID:	34258	**Sum Received Qty:**	3.0
Generator No:	ON3033254	**Waste Class Name:**	PHARMACEUTICALS
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	A	**District:**	402
Waste Code:	261		

2017 Generator Manifest

ID:	34261	**Sum Received Qty:**	133.0
Generator No:	ON3033254	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	A	**District:**	402
Waste Code:	263		

2017 Generator Manifest

ID:	34254	**Sum Received Qty:**	43.0
Generator No:	ON3033254	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	T	**District:**	402
Waste Code:	146		

2017 Generator Manifest

ID:	34255	**Sum Received Qty:**	41.0
Generator No:	ON3033254	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	6

Waste Char:	A	**District:**	402
Waste Code:	148		

2017 Generator Manifest

ID:	34253	**Sum Received Qty:**	65.0
Generator No:	ON3033254	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	L	**District:**	402
Waste Code:	145		

2017 Generator Manifest

ID:	34264	**Sum Received Qty:**	17.0
Generator No:	ON3033254	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	030	**Count Manifests:**	4
Waste Char:	L	**District:**	402
Waste Code:	331		

2017 Generator Manifest

ID:	34256	**Sum Received Qty:**	13.0
Generator No:	ON3033254	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	I	**District:**	402
Waste Code:	212		

2017 Generator Manifest

ID:	34260	**Sum Received Qty:**	334.0
Generator No:	ON3033254	**Waste Class Name:**	DETERGENTS/SOAPS
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	L	**District:**	402
Waste Code:	262		

2017 Generator Manifest

ID:	34262	**Sum Received Qty:**	7.0
Generator No:	ON3033254	**Waste Class Name:**	NON-HALOGENATED PESTICIDES
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	T	**District:**	402
Waste Code:	269		

2017 Generator Manifest

ID:	34263	**Sum Received Qty:**	99.0
Generator No:	ON3033254	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	030	**Count Manifests:**	5
Waste Char:	I	**District:**	402
Waste Code:	331		

33 ***12 of 19*** ***SW/188.7*** ***98.9 / -1.03*** ***Value Village Stores*** ***GEN***
1375 CLYDE AVE. STORE #2081
OTTAWA ON K2G 3H7

Generator Info

Generator No:	ON3033254	**Choice of Contact:**	CO_OFFICIAL

Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	448199
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	ALL OTHER CLOTHING STORES		

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	13 of 19	SW/188.7	98.9 / -1.03	Value Village Stores 1375 CLYDE AVE. STORE #2081 OTTAWA ON K2G 3H7	GEN

Generator Info

Generator No:	ON3033254	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	448199
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	ALL OTHER CLOTHING STORES		

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

33 | ***14 of 19*** | ***SW/188.7*** | ***98.9 / -1.03*** | ***Dymon Storage***
1375 Clyde Ave
Ottawa ON K2G 3H7 | ***GEN***

Generator Info

Generator No: ON8676143
Approval Years: As of Oct 2019
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

2019 Generator Info

Gen No: ON8676143
ID: 35007
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 236210
NAICS Code2:
NAICS Code3:
Gen Name: Dymon Storage
Gen Div:
Gen Op Name: Dymon Storage
Gen Op Div:
Site Adrs1: 1375 Clyde Ave
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2G 3H7
Site Country: Canada
Co Official: Dave Bilmer
Co Admin:

Choice of Contact: CO_OFFICIAL
Phone No Official: 613-222-399 Ext.
Phone No Admin:
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2019 Generator Manifest

ID: 62082
Generator No: ON8676143
Receiver Type: 035
Waste Char: L
Waste Code: 221

Sum Received Qty: 11480.0
Waste Class Name: LIGHT FUELS
Count Manifests: 1
District: 402

---

33 | ***15 of 19*** | ***SW/188.7*** | ***98.9 / -1.03*** | ***CANADIAN TIRE STORE #258 GORDON C. REID LIMITED*** | ***PES***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				1375 CLYDE AVENUE AT BASELINE OTTAWA ON	

Detail Licence No:		Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Vendor	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	16 of 19	SW/188.7	98.9 / -1.03	CANADIAN TIRE STORE #258 /DES KEON LTD. 1375 CLYDE AVENUE NEPEAN ON K2G3H7	PES

Detail Licence No:		Operator Box:	
Licence No:	05654	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:	Legacy Licenses (Excluding TS)	Oper Area Code:	613
Licence Type:	Retail Vendor Class 03	Oper Phone No:	2249330
Licence Type Code:	21	Operator Ext:	
Licence Class:	03	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	17 of 19	SW/188.7	98.9 / -1.03	Motor Sports World 1375 Clyde Ave. Ottawa ON K2G3H7	SCT

Scott S ID:	302451046
Latitude:	45.3605
Longitude:	-75.7383

Details

Bus Type 1:	Distributor	Employee Count:	7
Bus Type 2:	Manufacturer	Square Footage:	0
Bus Type 3:	Manufacturer's Sales Office	Estimated Sales:	$1-5 Million
Product Cat 1:	ATV dealer	Export Indicator:	
Product Cat 2:	Boat dealer	Export Country 1:	
Product Cat 3:	Motor scooter dealer	Export Country 2:	
Product Cat 4:	Motorcycle dealer	Export Country 3:	

Product Cat 5:	Motorcycle shop	**Export Country 4:**	
Product Cat 6:	Motorsports store	**Export Country 5:**	
Product Cat 7:	Snowmobile dealer	**Export Country 6:**	
Product Cat 8:	Suzuki dealer	**Geocoded by:**	Address
Company Name:	Motor Sports World		
Address Line 1:	1375 Clyde Ave.		
Address Line 2:			
City:	Ottawa		
Province:	ON		
Postal Code:	K2G3H7		
Census Division:	Ottawa; ON		
Metro Area:	Ottawa/Hull		
Year Established:	1994		
Head Office Indicator:			
Parent Company Nm:			
Parent Cmpny Addr 1:			
Parent Cmpny Addr 2:			
Parent Cmpny City:			
Parent Cmpny Prov:			
Parent Cmpy PC:			
Parent Cmpy Cntry:			
Head Office Nm:			
H Office Addr Line 1:			
H Office Addr Line 2:			
Head Office City:			
Head Office Province:			
Head Office PC:			
Head Office Cntry:			
Telephone:	873-408-5164		
Fax:			
Website:	https://www.motorsportsworld.com/?utm_source=google		
Pri NAICS Desc:	441220-Motorcycle; Boat and Other Motor Vehicle Dealers		
NAICS Code 1:	336612-Boat Building		
NAICS Code 2:	417990-All Other Machinery; Equipment and Supplies		
NAICS Code 3:	419120-Wholesale Trade Agents and Brokers		
NAICS Code 4:	441220-Motorcycle; Boat and Other Motor Vehicle De		
NAICS Code 5:	451119-All Other Sporting Goods Stores		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	18 of 19	SW/188.7	98.9 / -1.03	**Value Village Parking Lot, 1375 Clyde Ave. <UNOFFICIAL> Ottawa ON**	SPL

Ref No:	5713-6CPSMH	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	5/24/2005	**Discharger Report:**	0
Dt MOE Arvl on Scn:		**Material Group:**	Oil
MOE Reported Dt:	5/24/2005	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa		
Nearest Watercourse:			
Site Name:	Value Village Parking Lot, 1375 Clyde Ave.<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			

Client Name:	
Client Type:	
Source Type:	
Incident Cause:	Pipe Or Hose Leak
Incident Preceding Spill:	
Incident Reason:	Equipment Failure
Incident Summary:	Canadian Waste-30 L hydraulic oil to parking lot
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	L
Contaminant Code:	
Contaminant Name:	HYDRAULIC OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other Motor Vehicle
SAC Action Class:	Spills to Land
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

33	19 of 19	SW/188.7	98.9 / -1.03	1375 Clyde Avenue Ottawa, ON OTTAWA ON	SPL

Ref No:	1-3RUS3Y	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	8/24/2023 11:09:09 PM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	8/25/2023 8:49:09 AM	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	1375 Clyde Avenue Ottawa, ON		
Site Region:			
Site Municipality:	OTTAWA		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:			

Incident Preceding Spill:	Line Strike
Incident Reason:	
Incident Summary:	Enbridge: 1 ¼" PL IP Ottawa - made safe
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Activity Preceding Spill:	
Property 2nd Watershed:	Lower Ottawa
Property Tertiary Watershed:	02KF;02KE - Lower Madawaska;Central Ottawa - Mississippi
Sector Type:	NATURAL GAS DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00004008620"],"wkts":["POINT (-75.7384163000 45.3603962000)"],"creation_date":"2023-08-25"}
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

36 ***1 of 1*** ***SE/193.4*** ***98.9 / -1.03*** ***ON*** ***WWIS***

Well ID:	7473512	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	03/15/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z278660	***Contractor:***	7328
Tag:	A398258	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1010282724	***Tag No:***	A398258
Depth (m):		***Contractor:***	7328
Year Completed:	2024	***Latitude:***	45.3604192448048
Well Completed Dt:	01/30/2024	***Longitude:***	-75.7358312888445
Audit No:	Z278660	***Point Y:***	45.360419238131506
Path:		***Point X:***	-75.73583112710251

Bore Hole Information

Bore Hole ID:	1010282724	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442370.00
Code OB Desc:		***North83:***	5023253.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/30/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

37 ***1 of 2*** ***NE/195.8*** ***98.9 / -1.00*** ***1300 BASELINE RD Ottawa ON*** ***WWIS***

Well ID:	7187998	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Test Hole	***Date Received:***	09/24/2012
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z156781	***Contractor:***	7241
Tag:	A112809	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/718\7187998.pdf

Additional Detail(s) (Map)

Well Completed Date:	08/10/2012
Year Completed:	2012
Depth (m):	9.14
Latitude:	45.3632761387269
Longitude:	-75.7352937269479
Point X:	-75.73529356529089
Point Y:	45.3632761322143
Path:	718\7187998.pdf

Bore Hole Information

Bore Hole ID:	1004164239	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18

Code OB:		***East83:***	442415.00
Code OB Desc:		***North83:***	5023570.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/10/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004447835
Layer:	2
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.15000000596046448
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004447837
Layer:	4
Color:	2
General Color:	GREY
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	71
Material 2 Desc:	FRACTURED
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	2.740000009536743
Formation End Depth:	9.140000343322754
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004447836
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	28
Material 3 Desc:	SAND
Formation Top Depth:	0.3100000023841858
Formation End Depth:	2.740000009536743

Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004447834
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.0
Formation End Depth: 0.15000000596046448
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004447848
Layer: 3
Plug From: 4.269999980926514
Plug To: 9.140000343322754
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004447846
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004447847
Layer: 2
Plug From: 0.3100000023841858
Plug To: 4.269999980926514
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004447845
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1004447833
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1004447841
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	4.570000171661377
Casing Diameter:	3.819999933242798
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004447842
Layer:	1
Slot:	10
Screen Top Depth:	4.570000171661377
Screen End Depth:	9.140000343322754
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.03000020980835

Water Details

Water ID:	1004447840
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004447838
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	3.0999999046325684
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1004447839
Diameter:	7.619999885559082
Depth From:	3.0999999046325684
Depth To:	9.140000343322754
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

37 ***2 of 2*** ***NE/195.8*** ***98.9 / -1.00*** ***1300 BASELINE RD Ottawa ON*** ***WWIS***

Well ID:	7187999	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Test Hole	***Date Received:***	09/24/2012
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	

Audit No:	Z156782	**Contractor:**	7241
Tag:	A112808	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/718\7187999.pdf

Additional Detail(s) (Map)

Well Completed Date:	08/10/2012
Year Completed:	2012
Depth (m):	9.14
Latitude:	45.3632761387269
Longitude:	-75.7352937269479
Point X:	-75.73529356529089
Point Y:	45.3632761322143
Path:	718\7187999.pdf

Bore Hole Information

Bore Hole ID:	1004164242	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442415.00
Code OB Desc:		**North83:**	5023570.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/10/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004447853
Layer:	4
Color:	2
General Color:	GREY
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	71
Material 2 Desc:	FRACTURED
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	2.740000009536743
Formation End Depth:	9.140000343322754
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004447850
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	
Material 2 Desc:	
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	0.0
Formation End Depth:	0.15000000596046448
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004447851
Layer:	2
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.15000000596046448
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004447852
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	28
Material 3 Desc:	SAND
Formation Top Depth:	0.3100000023841858
Formation End Depth:	2.740000009536743
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004447864
Layer:	2
Plug From:	0.3100000023841858
Plug To:	4.269999980926514
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID: 1004447862
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004447865
Layer: 3
Plug From: 4.269999980926514
Plug To: 9.140000343322754
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004447863
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004447861
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1004447849
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004447857
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 4.570000171661377
Casing Diameter: 4.820000171661377
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004447858
Layer: 1
Slot: 10
Screen Top Depth: 4.570000171661377
Screen End Depth: 9.140000343322754
Screen Material: 5
Screen Depth UOM: m

Screen Diameter UOM: cm
Screen Diameter: 4.03000020980835

Water Details

Water ID: 1004447856
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004447855
Diameter: 7.619999885559082
Depth From: 3.0999999046325684
Depth To: 9.140000343322754
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004447854
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 3.0999999046325684
Hole Depth UOM: m
Hole Diameter UOM: cm

---

38 **1 of 1** **WSW/198.7** **98.3 / -1.60** **ON** **WWIS**

Well ID: 7479649
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z428573
Tag: A366106
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 06/17/2024
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1010365446
Depth (m):
Year Completed: 2024
Well Completed Dt: 02/23/2024
Audit No: Z428573
Path:

Tag No: A366106
Contractor: 7241
Latitude: 45.3610370190706
Longitude: -75.7391335302123
Point Y: 45.36103701198564
Point X: -75.7391333679748

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole Information

Bore Hole ID:	1010365446	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442112.00
Code OB Desc:		***North83:***	5023324.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	02/23/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

39	*1 of 31*	*NW/200.1*	*99.0 / -0.89*	***WAL-MART CANADA CORP/LA COMPAGNIE*** ***WAL-MART DU CANADA*** ***1375 BASELINE RD*** ***OTTAWA ON K2C 3G1***	***EASR***

Approval No:	R-003-7540795139	***MOE District:***	Ottawa
Status:	REGISTERED	***Municipality:***	OTTAWA
Date:	2015-11-16	***Latitude:***	45.36222222
Record Type:	EASR	***Longitude:***	-75.73833333
Link Source:	MOFA	***Geometry X:***	
Project Type:	Heating System	***Geometry Y:***	
Full Address:			
Approval Type:	EASR-Heating System		
SWP Area Name:	Rideau Valley		
PDF NAICS Code:			
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2017919		
PDF Site Location:			

39	*2 of 31*	*NW/200.1*	*99.0 / -0.89*	***Caremedics Clyde Baseline Inc*** ***1375 Baseline Road*** ***Ottawa ON K2C 3G1***	***GEN***

Generator Info

Generator No:	ON5950647	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

39	*3 of 31*	*NW/200.1*	*99.0 / -0.89*	***Walmart Canada Corp.*** ***1375 Baseline Road*** ***Ottawa ON K2C 3G1***	***GEN***

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON5683698
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 453999

---

39 | ***4 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Caremedics Clyde Baseline Inc*** ***1375 Baseline Road*** ***Ottawa ON K2C 3G1*** | ***GEN***

Generator Info

Generator No: ON5950647
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Offices of Physicians
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621110

---

39 | ***5 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Walmart Canada Corp.*** ***1375 Baseline Road*** ***Ottawa ON K2C 3G1*** | ***GEN***

Generator Info

Generator No: ON5683698
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Miscellaneous Store Retailers (except Beer and Wine-Making Supplies Stores)
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 453999

---

39 | ***6 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Walmart Canada Corp.*** ***1375 Baseline Road*** ***Ottawa ON*** | ***GEN***

Generator Info

Generator No: ON5683698
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 453999

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

39 | ***7 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Caremedics Clyde Baseline Inc***
1375 Baseline Road
Ottawa ON | ***GEN***

Generator Info

Generator No: ON5950647
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: OFFICES OF PHYSICIANS

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621110

Waste Detail(s)

Waste Class: 312

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		PATHOLOGICAL WASTES			

39	8 of 31	NW/200.1	99.0 / -0.89	**Smile Shapers** **1375 Baseline Rd** **Ottawa ON**	GEN

Generator Info

Generator No:	ON4948320	**Choice of Contact:**	
Approval Years:	2013	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	621210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	OFFICES OF DENTISTS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

39	9 of 31	NW/200.1	99.0 / -0.89	**Smile Shapers** **1375 Baseline Rd** **Ottawa ON K2C3G1**	GEN

Generator Info

Generator No:	ON4948320	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	621210
Country:	Canada		
Co Admin:	Tania Atanassova		
Phone No Admin:	6132265559 Ext.		
SIC Description:	OFFICES OF DENTISTS		

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

39	10 of 31	NW/200.1	99.0 / -0.89	**Smile Shapers** **1375 Baseline Rd** **Ottawa ON K2C3G1**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON4948320	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621210
Country:	Canada		
Co Admin:	Chandan Advani		
Phone No Admin:	6132265559 Ext.		
SIC Description:	OFFICES OF DENTISTS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

39	***11 of 31***	***NW/200.1***	***99.0 / -0.89***	***Walmart Canada Corp.*** ***1375 Baseline Road*** ***Ottawa ON K2C 3G1***	***GEN***

Generator Info

Generator No:	ON5683698	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	453999
Country:	Canada		
Co Admin:	Vincent Feng		
Phone No Admin:	905-821-2111 Ext.75212		
SIC Description:	ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)		

Waste Detail(s)

Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

39 | ***12 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Caremedics Clyde Baseline Inc***
1375 Baseline Road
Ottawa ON K2G3H7 | ***GEN***

Generator Info

Generator No: ON5950647
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Sarah Germain
Phone No Admin: 6136273901 Ext.
SIC Description: OFFICES OF PHYSICIANS

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

39 | ***13 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Walmart Canada Corp.***
1375 Baseline Road
Ottawa ON K2C 3G1 | ***GEN***

Generator Info

Generator No: ON5683698
Approval Years: 2016
Status:
PO Box No:

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 453999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Co Admin: Jason Fries
Phone No Admin: 905-821-2111 Ext.75127
SIC Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

39	*14 of 31*	*NW/200.1*	*99.0 / -0.89*	***Smile Shapers*** ***1375 Baseline Rd*** ***Ottawa ON K2C3G1***	***GEN***

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON4948320
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Janice Titus
Phone No Admin: 6137919301 Ext.
SIC Description: OFFICES OF DENTISTS
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621210

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

39 | ***15 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Caremedics Clyde Baseline Inc*** ***1375 Baseline Road*** ***Ottawa ON K2G3H7*** | ***GEN***

Generator Info

Generator No: ON5950647
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Sarah Germain
Phone No Admin: 6136273901 Ext.
SIC Description: OFFICES OF PHYSICIANS
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

39 | ***16 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Walmart Canada Corp.*** ***1375 Baseline Road*** ***Ottawa ON K2C 3G1*** | ***GEN***

Generator Info

Generator No: ON5683698
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Vincent Feng
Phone No Admin: 905-821-2111 Ext.75212
SIC Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 453999

Waste Detail(s)

Waste Class: 122

Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

39 | ***17 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Walmart Canada Corp.***
1375 Baseline Road
Ottawa ON K2C 3G1 | ***GEN***

Generator Info

Generator No: ON5683698
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	18 of 31	NW/200.1	99.0 / -0.89	Smile Shapers 1375 Baseline Rd Ottawa ON K2C3G1	GEN

Generator Info

Generator No:	ON4948320	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	Pharmaceuticals

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	19 of 31	NW/200.1	99.0 / -0.89	Walmart Canada Corp. 1375 Baseline Road Ottawa ON K2C 3G1	GEN

Generator Info

Generator No:	ON5683698	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	148 I
Waste Class Name:	Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class:	263 I
Waste Class Name:	Misc. waste organic chemicals

Waste Detail(s)

Waste Class:	242 A
Waste Class Name:	Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 261 L
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

39	*20 of 31*	*NW/200.1*	*99.0 / -0.89*	***Smile Shapers*** ***1375 Baseline Rd*** ***Ottawa ON K2C3G1***	***GEN***

Generator Info

Generator No: ON4948320 ***Choice of Contact:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

---

39 | ***21 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Smile Shapers***
1375 Baseline Rd
Ottawa ON K2C3G1 | ***GEN***

Generator Info

Generator No: ON4948320
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

39 | ***22 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Walmart Canada Corp.***
1375 Baseline Road
Ottawa ON K2C 3G1 | ***GEN***

Generator Info

Generator No: ON5683698
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 261 L
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

39 | ***23 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Walmart Canada***
Store #1110, 1375 Baseline Road
Ottawa ON | ***GEN***

Generator Info

Generator No: ON5683698
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 242 A
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 261 L
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Generator Info (as of Dec 2024)

Generator No: ON5683698
Generator Company Name: Walmart Canada
Street: Store #1110, 1375 Baseline Road
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K2C3G1
Waste Class: 252 L,112 C,122 C,145 I,148 C,148 T,242 A,263 I,331 I,312 P,148 I,261 L,261 A

Waste Class Decoded:

252 - WASTE OILS & LUBRICANTS; 112 - ACID WASTE - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 242 - HALOGENATED PESTICIDES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 312 - PATHOLOGICAL WASTES; 148 - INORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS

Generator Info (as of Apr 2025)

Generator Company Name: Walmart Canada
Generator Site Address: Store #1110, 1375 Baseline Road
City: Ottawa
Province State: Ontario

Country: Canada
Postal Code: K2C3G1
Waste Class: 252 L, 112 C, 122 C, 145 I, 148 C, 148 T, 242 A, 263 I, 331 I, 312 P, 148 I, 261 L, 261 A

Waste Class Decoded:

252 - WASTE OILS & LUBRICANTS; 112 - ACID WASTE - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 242 - HALOGENATED PESTICIDES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 312 - PATHOLOGICAL WASTES; 148 - INORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 261 - PHARMACEUTICALS

Waste Characteristic Decoded:

L - Liquid Industrial Waste; C - Corrosive; C - Corrosive; I - Ignitable; C - Corrosive; T - Leachate Toxic; A - Acutely Hazardous Waste Chem.; I - Ignitable; I - Ignitable; P - Pathological; I - Ignitable; L - Liquid Industrial Waste; A - Acutely Hazardous Waste Chem.

2017 Generator Info

Gen No: ON5683698
ID: 22459
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 452110
NAICS Code2:
NAICS Code3:
Gen Name: Walmart Canada Corp.
Gen Div:
Gen Op Name: Walmart Canada Corp.
Gen Op Div:
Site Adrs1: 1375 Baseline Road
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 3G1
Site Country: Canada
Co Official: Terry Yee
Co Admin: Karon Cross

Choice of Contact: CO_OFFICIAL
Phone No Official: 905-821-2111 Ext.78027
Phone No Admin: 905-821-2111 Ext.71183
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2017 Generator Manifest

ID: 47272
Generator No: ON5683698
Receiver Type: 035
Waste Char: I
Waste Code: 263

Sum Received Qty: 700.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 5
District: 201

2017 Generator Manifest

ID: 47269
Generator No: ON5683698
Receiver Type: 035
Waste Char: C
Waste Code: 122

Sum Received Qty: 70.0
Waste Class Name: ALKALINE WASTES - OTHER METALS
Count Manifests: 3
District: 201

2017 Generator Manifest

ID: 47271
Generator No: ON5683698

Sum Received Qty: 140.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Receiver Type: 035
Waste Char: I
Waste Code: 148
Count Manifests: 4
District: 201

2017 Generator Manifest

ID: 47270
Generator No: ON5683698
Receiver Type: 035
Waste Char: C
Waste Code: 148
Sum Received Qty: 190.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 4
District: 201

2017 Generator Manifest

ID: 47273
Generator No: ON5683698
Receiver Type: 035
Waste Char: I
Waste Code: 331
Sum Received Qty: 500.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 5
District: 201

2018 Generator Info

Gen No: ON5683698
ID: 22675
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 452110
NAICS Code2:
NAICS Code3:
Gen Name: Walmart Canada Corp.
Gen Div:
Gen Op Name: Walmart Canada Corp.
Gen Op Div:
Site Adrs1: 1375 Baseline Road
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 3G1
Site Country: Canada
Co Official: Terry Yee
Co Admin: Don Berezowski
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-821-2111 Ext.78027
Phone No Admin: 905-821-2111 Ext.71265
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2018 Generator Manifest

ID: 47171
Generator No: ON5683698
Receiver Type: 035
Waste Char: I
Waste Code: 263
Sum Received Qty: 1600.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 6
District: 201

2018 Generator Manifest

ID: 47169
Generator No: ON5683698
Receiver Type: 035
Waste Char: I
Waste Code: 148
Sum Received Qty: 150.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 4
District: 201

2018 Generator Manifest

ID: 47168
Generator No: ON5683698
Receiver Type: 035
Waste Char: C
Waste Code: 148

Sum Received Qty: 270.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 3
District: 201

2018 Generator Manifest

ID: 47170
Generator No: ON5683698
Receiver Type: 035
Waste Char: A
Waste Code: 242

Sum Received Qty: 90.0
Waste Class Name: HALOGENATED PESTICIDES
Count Manifests: 4
District: 201

2018 Generator Manifest

ID: 47167
Generator No: ON5683698
Receiver Type: 035
Waste Char: C
Waste Code: 122

Sum Received Qty: 70.0
Waste Class Name: ALKALINE WASTES - OTHER METALS
Count Manifests: 3
District: 201

2018 Generator Manifest

ID: 47172
Generator No: ON5683698
Receiver Type: 035
Waste Char: I
Waste Code: 331

Sum Received Qty: 711.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 8
District: 201

2019 Generator Info

Gen No: ON5683698
ID: 22754
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 452110
NAICS Code2:
NAICS Code3:
Gen Name: Walmart Canada Corp.
Gen Div:
Gen Op Name: Walmart Canada Corp.
Gen Op Div:
Site Adrs1: 1375 Baseline Road
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 3G1
Site Country: Canada
Co Official: Terry Yee
Co Admin: Don Berezowski

Choice of Contact: CO_OFFICIAL
Phone No Official: 905-821-2111 Ext.78027
Phone No Admin: 905-821-2111 Ext.71265
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2019 Generator Manifest

ID: 46857
Generator No: ON5683698
Receiver Type: 035

Sum Received Qty: 340.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 5

Waste Char:	C	***District:***	201
Waste Code:	148		

2019 Generator Manifest

ID:	46859	***Sum Received Qty:***	20.0
Generator No:	ON5683698	***Waste Class Name:***	HALOGENATED PESTICIDES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	A	***District:***	201
Waste Code:	242		

2019 Generator Manifest

ID:	46861	***Sum Received Qty:***	630.0
Generator No:	ON5683698	***Waste Class Name:***	WASTE COMPRESSED GASES
Receiver Type:	035	***Count Manifests:***	7
Waste Char:	I	***District:***	201
Waste Code:	331		

2019 Generator Manifest

ID:	46858	***Sum Received Qty:***	210.0
Generator No:	ON5683698	***Waste Class Name:***	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	***Count Manifests:***	5
Waste Char:	I	***District:***	201
Waste Code:	148		

2019 Generator Manifest

ID:	46856	***Sum Received Qty:***	70.0
Generator No:	ON5683698	***Waste Class Name:***	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	***Count Manifests:***	3
Waste Char:	C	***District:***	201
Waste Code:	122		

2019 Generator Manifest

ID:	46860	***Sum Received Qty:***	750.0
Generator No:	ON5683698	***Waste Class Name:***	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	***Count Manifests:***	6
Waste Char:	I	***District:***	201
Waste Code:	263		

2020 Generator Info

Gen No:	ON5683698	***Choice of Contact:***	CO_OFFICIAL
ID:	22486	***Phone No Official:***	905-821-2111 Ext.78027
Contaminated Fac:	N	***Phone No Admin:***	905-821-2111 Ext.71265
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	452110	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Walmart Canada Corp.		
Gen Div:			
Gen Op Name:	Walmart Canada Corp.		
Gen Op Div:			
Site Adrs1:	1375 Baseline Road		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			

Site City:	Ottawa
Province Out:	
Site Postal Code:	K2C 3G1
Site Country:	Canada
Co Official:	Terry Yee
Co Admin:	Don Berezowski

2020 Generator Manifest

ID:	43496	**Sum Received Qty:**	2.0
Generator No:	ON5683698	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	I	**District:**	402
Waste Code:	148		

2020 Generator Manifest

ID:	43498	**Sum Received Qty:**	463.0
Generator No:	ON5683698	**Waste Class Name:**	PHARMACEUTICALS
Receiver Type:	030	**Count Manifests:**	3
Waste Char:	L	**District:**	402
Waste Code:	261		

2020 Generator Manifest

ID:	43499	**Sum Received Qty:**	89.0
Generator No:	ON5683698	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	4
Waste Char:	I	**District:**	402
Waste Code:	263		

2020 Generator Manifest

ID:	43492	**Sum Received Qty:**	150.0
Generator No:	ON5683698	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	I	**District:**	201
Waste Code:	148		

2020 Generator Manifest

ID:	43495	**Sum Received Qty:**	39.0
Generator No:	ON5683698	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	5
Waste Char:	C	**District:**	402
Waste Code:	148		

2020 Generator Manifest

ID:	43497	**Sum Received Qty:**	12.0
Generator No:	ON5683698	**Waste Class Name:**	HALOGENATED PESTICIDES
Receiver Type:	030	**Count Manifests:**	2
Waste Char:	A	**District:**	402
Waste Code:	242		

2020 Generator Manifest

ID:	43493	**Sum Received Qty:**	500.0
Generator No:	ON5683698	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	3

Waste Char:	I	**District:**	201
Waste Code:	263		

2020 Generator Manifest

ID:	43490	**Sum Received Qty:**	20.0
Generator No:	ON5683698	**Waste Class Name:**	ACID WASTE - HEAVY METALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	C	**District:**	201
Waste Code:	112		

2020 Generator Manifest

ID:	43491	**Sum Received Qty:**	200.0
Generator No:	ON5683698	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	C	**District:**	201
Waste Code:	148		

2020 Generator Manifest

ID:	43494	**Sum Received Qty:**	300.0
Generator No:	ON5683698	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	I	**District:**	201
Waste Code:	331		

2020 Generator Manifest

ID:	43500	**Sum Received Qty:**	100.0
Generator No:	ON5683698	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	030	**Count Manifests:**	9
Waste Char:	I	**District:**	402
Waste Code:	331		

2021 Generator Info

Gen No:	ON5683698	**Choice of Contact:**	CO_OFFICIAL
ID:	22763	**Phone No Official:**	905-821-2111 Ext.78027
Contaminated Fac:	N	**Phone No Admin:**	905-821-2111 Ext.71265
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	452110	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			

Gen Name:	Walmart Canada Corp.
Gen Div:	
Gen Op Name:	Walmart Canada Corp.
Gen Op Div:	
Site Adrs1:	1375 Baseline Road
Site Bldg:	Store #1110
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Ottawa
Province Out:	
Site Postal Code:	K2C 3G1
Site Country:	Canada
Co Official:	Terry Yee
Co Admin:	Don Berezowski

2021 Generator Manifest

ID: 45121
Generator No: ON5683698
Receiver Type: 030
Waste Char: L
Waste Code: 261

Sum Received Qty: 929.0
Waste Class Name: PHARMACEUTICALS
Count Manifests: 6
District: 402

2021 Generator Manifest

ID: 45119
Generator No: ON5683698
Receiver Type: 030
Waste Char: C
Waste Code: 148

Sum Received Qty: 25.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 6
District: 402

2021 Generator Manifest

ID: 45123
Generator No: ON5683698
Receiver Type: 030
Waste Char: I
Waste Code: 331

Sum Received Qty: 183.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 16
District: 402

2021 Generator Manifest

ID: 45120
Generator No: ON5683698
Receiver Type: 030
Waste Char: A
Waste Code: 242

Sum Received Qty: 14.0
Waste Class Name: HALOGENATED PESTICIDES
Count Manifests: 4
District: 402

2021 Generator Manifest

ID: 45122
Generator No: ON5683698
Receiver Type: 030
Waste Char: I
Waste Code: 263

Sum Received Qty: 104.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 7
District: 402

---

39 | ***24 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Simplii Environmental Corp Simplii Environmental Corp 1375 Baseline Rd Ottawa ON K2C 3G1*** | ***GEN***

Generator Info

Generator No: ON5568882
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

---

39 | ***25 of 31*** | ***NW/200.1*** | ***99.0 / -0.89*** | ***Smile Shapers***
1375 Baseline Rd
Ottawa ON K2C3G1 | ***GEN***

Generator Info

Generator No: ON4948320
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

2017 Generator Info

Gen No: ON4948320
ID: 19620
Contaminated Fac: N

Choice of Contact: CO_OFFICIAL
Phone No Official: 6132265559 Ext.
Phone No Admin: 6132265559 Ext.

MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Smile Shapers		
Gen Div:			
Gen Op Name:	Smile Shapers		
Gen Op Div:			
Site Adrs1:	1375 Baseline Rd		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2C3G1		
Site Country:	Canada		
Co Official:	Sandra Gould		
Co Admin:	Tania Atanassova		

2018 Generator Info

Gen No:	ON4948320	***Choice of Contact:***	CO_OFFICIAL
ID:	19729	***Phone No Official:***	6132265559 Ext.
Contaminated Fac:	N	***Phone No Admin:***	6132265559 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Smile Shapers		
Gen Div:			
Gen Op Name:	Smile Shapers		
Gen Op Div:			
Site Adrs1:	1375 Baseline Rd		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2C3G1		
Site Country:	Canada		
Co Official:	Sandra Gould		
Co Admin:	Tania Atanassova		

2018 Generator Manifest

ID:	43518	***Sum Received Qty:***	8.0
Generator No:	ON4948320	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	P	***District:***	306
Waste Code:	312		

2019 Generator Info

Gen No:	ON4948320	***Choice of Contact:***	CO_OFFICIAL
ID:	19736	***Phone No Official:***	6132265559 Ext.
Contaminated Fac:	N	***Phone No Admin:***	6132265559 Ext.
MHSW Facility:	N	***County Ont:***	OTTAWA CARLTON (RM)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	402
NAICS Code3:			
Gen Name:	Smile Shapers		

Gen Div:
Gen Op Name: Smile Shapers
Gen Op Div:
Site Adrs1: 1375 Baseline Rd
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C3G1
Site Country: Canada
Co Official: Sandra Gould
Co Admin: Tania Atanassova

2020 Generator Info

Gen No: ON4948320
ID: 19451
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621210
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 6132265559 Ext.
Phone No Admin: 6132265559 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Gen Name: Smile Shapers
Gen Div:
Gen Op Name: Smile Shapers
Gen Op Div:
Site Adrs1: 1375 Baseline Rd
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C3G1
Site Country: Canada
Co Official: Patricia Chorianopoulos
Co Admin: Vanessa Pierre

2021 Generator Info

Gen No: ON4948320
ID: 19589
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621210
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_ADMIN
Phone No Official: 6132265559 Ext.
Phone No Admin: 6132265559 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Gen Name: Smile Shapers
Gen Div:
Gen Op Name: Smile Shapers
Gen Op Div:
Site Adrs1: 1375 Baseline Rd
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C3G1
Site Country: Canada
Co Official: Dakota Vankessel
Co Admin: Dakota Vankessel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	26 of 31	NW/200.1	99.0 / -0.89	Smile Shapers Dental Clinic 1375 Baseline Road Ottawa ON	GEN

Generator Info (as of Dec 2024)

Generator No:	ON001057219
Generator Company Name:	Smile Shapers Dental Clinic
Street:	1375 Baseline Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K2C 3G1
Waste Class:	312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

Generator Info (as of Apr 2025)

Generator Company Name:	Smile Shapers Dental Clinic
Generator Site Address:	1375 Baseline Road
City:	Ottawa
Province State:	Ontario
Country:	Canada
Postal Code:	K2C 3G1
Waste Class:	312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

Waste Characteristic Decoded:

P - Pathological

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	27 of 31	NW/200.1	99.0 / -0.89	WAL-MART CANADA CORP. STORE #1110 1375 BASELINE RD OTTAWA ON K2C 3G1	PES

Detail Licence No:		***Operator Box:***	
Licence No:		***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:		***Oper Area Code:***	
Licence Type:	Vendor	***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PDF URL:

---

39 **28 of 31** **NW/200.1** **99.0 / -0.89** **WAL-MART CANADA CORP. STORE #1110** **PES**
1375 BASELINE RD
OTTAWA ON K2C 3G1

Detail Licence No:	23-01-15810-0	**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	LIMITED	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

39 **29 of 31** **NW/200.1** **99.0 / -0.89** **WAL-MART CANADA CORP. STORE #1110** **PES**
1375 BASELINE RD
OTTAWA ON K2C3G1

Detail Licence No:		**Operator Box:**	
Licence No:	17889	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	2242664
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

39 **30 of 31** **NW/200.1** **99.0 / -0.89** **WAL-MART CANADA CORP. STORE #1110** **PES**
1375 BASELINE RD
OTTAWA ON K2C3G1

Detail Licence No:		**Operator Box:**	
Licence No:	15810	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	2242664
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	

Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

39 | **31 of 31** | **NW/200.1** | **99.0 / -0.89** | **1375 BASELINE RD OTTAWA ON K2C 3G1** | **PES**

Detail Licence No:		**Operator Box:**	
Licence No:	L-232-3128651814	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2021-04-27	**Operator Type:**	
Report Source:	PEST-Limited Vendor	**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	45.36222222	**Operator Region:**	
Longitude:	-75.73833333	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Ottawa
County:		**SWP Area Name:**	Rideau Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2391769		

---

41 | **1 of 1** | **NNE/200.9** | **98.9 / -1.03** | **1345 Baseline Road Ottawa ON K2C 0A7** | **EHS**

Order No:	22011300636	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	18-JAN-22	**Search Radius (km):**	.25
Date Received:	13-JAN-22	**X:**	-75.7362823
Previous Site Name:		**Y:**	45.3637082
Lot/Building Size:			
Additional Info Ordered:			

---

42 | **1 of 1** | **WSW/202.1** | **98.2 / -1.73** | **ON** | **WWIS**

Well ID:	7474013	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	03/22/2024
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z425474	**Contractor:**	7241
Tag:	A366198	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	

Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1010284932	**Tag No:**	A366198
Depth (m):		**Contractor:**	7241
Year Completed:	2024	**Latitude:**	45.361233792873
Well Completed Dt:	02/15/2024	**Longitude:**	-75.7393276183274
Audit No:	Z425474	**Point Y:**	45.36123378621871
Path:		**Point X:**	-75.73932745609746

Bore Hole Information

Bore Hole ID:	1010284932	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442097.00
Code OB Desc:		**North83:**	5023346.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/15/2024	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	1 of 2	ESE/203.8	97.9 / -2.03	**DONALD BELLS PETROLEUM LTD** **1468 MERIVALE RD** **NEPEAN ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9460197	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	381187	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			

TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Gasoline Station - Full Serve
Original Source: EXP
Record Date: Up to Mar 2012

---

44 | ***2 of 2*** | ***ESE/203.8*** | ***97.9 / -2.03*** | ***DONALD BELLS PETROLEUM LTD*** ***1468 MERIVALE RD*** ***OTTAWA ON K2E 5P1*** | ***PRT***

Location ID: 11007
Type: retail
Expiry Date: 1994-01-31
Capacity (L): 0
Licence #: 0011040007

---

45 | ***1 of 4*** | ***NE/204.4*** | ***98.9 / -1.03*** | ***Boy Scouts of Canada*** ***1345 Baseline Road*** ***Ottawa ON K2C 0A7*** | ***GEN***

Generator Info

Generator No: ON7118797
Approval Years: 06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Schools and Instruction

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 611690

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	2 of 4	NE/204.4	98.9 / -1.03	Boy Scouts of Canada 1345 Baseline Road Ottawa ON K2C 0A7	GEN

Generator Info

Generator No:	ON7118797	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	611690
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Schools and Instruction		

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	3 of 4	NE/204.4	98.9 / -1.03	Scouting Life 1345 Baseline Rd Unit 100 Ottawa ON K2C 0A7	SCT

Scott S ID: 36245894
Latitude:
Longitude:

Historical Details

Established:
Plant Size (ft²):
Employment:

Historical Details

Description: Periodical Publishers
SIC/NAICS Code: 511120

---

45 | **4 of 4** | **NE/204.4** | **98.9 / -1.03** | **1345 Baseline. Ottawa OTTAWA ON** | **SPL**

Ref No: 1-3NWG9S
Year:
Incident Dt: 7/23/2023 8:30:55 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/23/2023 9:08:55 PM
Dt Document Closed: 8/3/2023 9:11:11 AM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Ottawa District Office
Nearest Watercourse:
Site Name:
Site Address: 1345 Baseline. Ottawa
Site Region:
Site Municipality: OTTAWA
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type: Motor Vehicle
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Equipment failure/malfunction
Incident Summary: OC Transpo: 1 L coolant to road
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 1 litre (L)
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: COOLANT (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill: Normal operations
Property 2nd Watershed: Lower Ottawa
Property Tertiary Watershed: 02KF;02KE - Lower Madawaska;Central Ottawa - Mississippi
Sector Type: AUTOMOTIVE PARTS AND ACCESSORIES STORES
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00003837567"],"wkts":["POINT (-75.7364271000 45.3638991000)"],"creation_date":"2023-07-23"}
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
46	1 of 1	WSW/206.2	97.8 / -2.08	ON	WWIS

Well ID:	7474032	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	03/22/2024
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z425472	**Contractor:**	7241
Tag:	A366194	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1010284989	**Tag No:**	A366194
Depth (m):		**Contractor:**	7241
Year Completed:	2024	**Latitude:**	45.3610900311229
Well Completed Dt:	02/15/2024	**Longitude:**	-75.7392874407891
Audit No:	Z425472	**Point Y:**	45.36109002430512
Path:		**Point X:**	-75.7392872789719

Bore Hole Information

Bore Hole ID:	1010284989	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442100.00
Code OB Desc:		**North83:**	5023330.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/15/2024	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	1 of 1	SE/207.1	98.9 / -1.03	CHEESE PLUS PIZZA & SUBS 1478 MERIVALE ROAD NEPEAN CITY ON K2E 6Z5	CA

Certificate #:	8-4127-96-
Application Year:	96
Issue Date:	6/12/1996
Approval Type:	Industrial air
Status:	Approved
Application Type:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: COMMERCIAL KITCHEN EXHAUST HOOD
Contaminants: Odour/Fumes
Emission Control: Panel Filter

---

48 | **1 of 1** | **SE/209.0** | **98.9 / -1.03** | **ON** | **WWIS**

Well ID:	7473508	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	03/15/2024
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z278656	**Contractor:**	7328
Tag:	A398259	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NEPEAN TOWNSHIP
Site Info:

Additional Detail(s) (Map)

Bore Hole ID:	1010282712	**Tag No:**	A398259
Depth (m):		**Contractor:**	7328
Year Completed:	2024	**Latitude:**	45.360284646852
Well Completed Dt:	01/26/2024	**Longitude:**	-75.7357657031953
Audit No:	Z278656	**Point Y:**	45.36028464040263
Path:		**Point X:**	-75.73576554113677

Bore Hole Information

Bore Hole ID:	1010282712	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442375.00
Code OB Desc:		**North83:**	5023238.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/26/2024	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

---

52 | **1 of 7** | **SSW/211.9** | **98.8 / -1.08** | **1377 Clyde Avenue** | **EHS**

1377 Clyde Avenue ON K2G 3H7

Order No:	23021000348	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	15-FEB-23	***Search Radius (km):***	.25
Date Received:	10-FEB-23	***X:***	-75.7381144
Previous Site Name:		***Y:***	45.3602385
Lot/Building Size:			
Additional Info Ordered:			

---

52 ***2 of 7*** ***SSW/211.9*** ***98.8 / -1.08*** ***FRISBY TIRE CO (1974) LTD*** ***FST***
1377 CLYDE AV
NEPEAN ON

Inventory No:	10868878	***Tank Material:***	Steel
Inventory Status:	Active	***Corrosion Protect:***	Sacrificial anode
Installation Year:		***Overfill Protection:***	
Capacity:		***Inventory Context:***	FS Liquid Fuel Tank
Capacity Unit:		***Inventory Item:***	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:			

---

52 ***3 of 7*** ***SSW/211.9*** ***98.8 / -1.08*** ***FRISBY TIRE CO (1974) LTD*** ***FSTH***
1377 CLYDE AV
NEPEAN ON K2G 3H7

License Issue Date:	12/10/1990
Tank Status:	Licensed
Tank Status As Of:	August 2007
Operation Type:	Private Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	1974
Corrosion Protection:	
Capacity:	10000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

---

52 ***4 of 7*** ***SSW/211.9*** ***98.8 / -1.08*** ***FRISBY TIRE CO (1974) LTD*** ***FSTH***
1377 CLYDE AV
NEPEAN ON K2G 3H7

License Issue Date:	12/10/1990
Tank Status:	Licensed
Tank Status As Of:	December 2008
Operation Type:	Private Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	1974
Corrosion Protection:	
Capacity:	10000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	5 of 7	SSW/211.9	98.8 / -1.08	FRISBY TIRE CO (1974) LTD 1377 CLYDE AV NEPEAN ON K2G 3H7	PRT

Location ID: 9592
Type: private
Expiry Date:
Capacity (L): 10000.00
Licence #: 0001047413

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	6 of 7	SSW/211.9	98.8 / -1.08	Kal Tire 1377 Clyde Ave. Nepean ON K2G3H7	SCT

Scott S ID: 59470189
Latitude: 45.3601178
Longitude: -75.738632

Details

Bus Type 1: Construction
Bus Type 2: Distributor
Bus Type 3: Manufacturer's Sales Office
Product Cat 1: Auto repair shop
Product Cat 2: Brake shop
Product Cat 3: Car battery store
Product Cat 4: Car repair and maintenance service
Product Cat 5: Mechanic
Product Cat 6: Oil change service
Product Cat 7: Tire dealer: automotive
Product Cat 8: Tire repair shop
Company Name: Kal Tire
Address Line 1: 1377 Clyde Ave.
Address Line 2:
City: Nepean
Province: ON
Postal Code: K2G3H7
Census Division: Ottawa; ON
Metro Area:
Year Established: 1920
Head Office Indicator: Y
Parent Company Nm:
Parent Cmpny Addr 1:
Parent Cmpny Addr 2:
Parent Cmpny City:
Parent Cmpny Prov:
Parent Cmpy PC:
Parent Cmpy Cntry:
Head Office Nm:
H Office Addr Line 1:
H Office Addr Line 2:
Head Office City:
Head Office Province:
Head Office PC:
Head Office Cntry:
Telephone: 613-224-2200
Fax: 613-224-3782
Website: https://www.kaltire.com/en/stores/locations/?StoreID=830
Pri NAICS Desc: 811199-All Other Automotive Repair and Maintenance
NAICS Code 1: 238190-Other Foundation; Structure and Building Ex

Employee Count: 90
Square Footage: 0
Estimated Sales: $50-75 Million
Export Indicator:
Export Country 1:
Export Country 2:
Export Country 3:
Export Country 4:
Export Country 5:
Export Country 6:
Geocoded by: Address

NAICS Code 2:	415210-Tire Merchant Wholesalers
NAICS Code 3:	441110-New Car Dealers
NAICS Code 4:	441310-Automotive Parts and Accessories Stores
NAICS Code 5:	441320-Tire Dealers

52 **7 of 7** **SSW/211.9** **98.8 / -1.08** **FRISBEE TIRE** **SPL**
1377 CLYDE
NEPEAN CITY ON K2G 3H7

Ref No:	38849	**Municipality No:**	20104
Year:		**Nature of Damage:**	
Incident Dt:	8/3/1990	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/3/1990	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	M.O.E.

Site No:	
MOE Response:	
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	NEPEAN CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	ABOVE-GROUND TANK LEAK
Incident Preceding Spill:	
Incident Reason:	UNKNOWN
Incident Summary:	FRISBEE TIRE-USED MOTOR OIL TO GROUND.
Environment Impact:	CONFIRMED
Health Env Consequence:	
Nature of Impact:	Soil contamination
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
53	1 of 1	NE/212.4	98.2 / -1.73	1345 BASELINE ROAD Ottawa ON	WWIS

Well ID: 7413944
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z363657
Tag: A329754
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 03/28/2022
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7328
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/741\7413944.pdf

Additional Detail(s) (Map)

Well Completed Date: 02/05/2022
Year Completed: 2022
Depth (m): 2.749296
Latitude: 45.3635452527492
Longitude: -75.7354376712671
Point X: -75.73543750946487
Point Y: 45.363545246215914
Path: 741\7413944.pdf

Bore Hole Information

Bore Hole ID: 1008986267
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/05/2022
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 442404.00
North83: 5023600.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1010624673

Layer: 2
Color:
General Color:
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 1.3200000524520874
Formation End Depth: 9.020000457763672
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1010624672
Layer: 1
Color:
General Color:
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 1.3200000524520874
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1010625256
Layer: 1
Plug From: 0.0
Plug To: 5.699999809265137
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1010625886
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: HSA

Pipe Information

Pipe ID: 1010589040
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1010626202
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 6.0

Casing Diameter: 3.180000066757202
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1010626391
Layer: 1
Slot: 10
Screen Top Depth: 6.0
Screen End Depth: 9.020000457763672
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: Inch
Screen Diameter: 3.890000104904175

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1010626828
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1010626550
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 2.630000114440918
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1010625603
Diameter: 7.619999885559082
Depth From: 1.3200000524520874
Depth To: 9.020000457763672
Hole Depth UOM: ft
Hole Diameter UOM: Inch

Hole Diameter

Hole ID: 1010625602
Diameter: 20.299999237060547
Depth From: 0.0
Depth To: 1.3200000524520874
Hole Depth UOM: ft
Hole Diameter UOM: Inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

54 **1 of 1** **SE/213.1** **98.9 / -1.03** **ON** **WWIS**

Well ID:	7473511	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	03/15/2024
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z278657	**Contractor:**	7328
Tag:	A398257	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1010282721	**Tag No:**	A398257
Depth (m):		**Contractor:**	7328
Year Completed:	2024	**Latitude:**	45.3602487266428
Well Completed Dt:	01/26/2024	**Longitude:**	-75.7357524694426
Audit No:	Z278657	**Point Y:**	45.36024872018497
Path:		**Point X:**	-75.73575230716342

Bore Hole Information

Bore Hole ID:	1010282721	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442376.00
Code OB Desc:		**North83:**	5023234.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/26/2024	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

55 **1 of 1** **WSW/213.2** **97.8 / -2.15** **lot 35 con A ON** **WWIS**

Well ID:	1504629	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Commerical	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	10/28/1958
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	

Audit No:		**Contractor:**	3566
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	035
Depth to Bedrock:		**Concession:**	A
Well Depth:		**Concession Name:**	RF
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504629.pdf

Additional Detail(s) (Map)

Well Completed Date:	04/21/1958
Year Completed:	1958
Depth (m):	22.86
Latitude:	45.3607047154178
Longitude:	-75.7390181192607
Point X:	-75.7390179569851
Point Y:	45.36070470807472
Path:	150\1504629.pdf

Bore Hole Information

Bore Hole ID:	10026672	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442120.70
Code OB Desc:		**North83:**	5023287.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	04/21/1958	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931000007
Layer:	2
Color:	
General Color:	
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	8.0
Formation End Depth:	75.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931000006
Layer:	1
Color:	
General Color:	
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	8.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961504629
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10575242
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930046073
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	21.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930046074
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	75.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991504629
Pump Set At:	

Static Level:	8.0
Final Level After Pumping:	25.0
Recommended Pump Depth:	
Pumping Rate:	5.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933457927
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	75.0
Water Found Depth UOM:	ft

---

56 | ***1 of 1*** | ***NE/213.5*** | ***98.2 / -1.73*** | ***Nortel Networks Corporation***
Skyline- Tower VI
Ottawa ON K1Y 4H7 | ***ECA***

Approval No:	5258-4NASH3	**MOE District:**	Ottawa
Approval Date:	2000-08-28	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-75.735306
Record Type:	ECA	**Latitude:**	45.36349
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Nortel Networks Corporation		
Address:	Skyline- Tower VI		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2022-4MKNWW-14.pdf		
PDF Site Location:			

---

59 | ***1 of 1*** | ***SSE/217.9*** | ***98.9 / -1.03*** | ***1490 MERRIVALE ROAD***
OTTAWA ON | ***WWIS***

Well ID:	7046663	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	07/17/2007
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z66267	**Contractor:**	7241
Tag:	A056689	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	

Clear/Cloudy:
UTM Reliability:
Municipality: OTTAWA CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7046663.pdf

Additional Detail(s) (Map)

Well Completed Date: 06/11/2007
Year Completed: 2007
Depth (m): 3.66
Latitude: 45.3600465991913
Longitude: -75.7363882557299
Point X: -75.73638809410383
Point Y: 45.360046592505896
Path: 704\7046663.pdf

Bore Hole Information

Bore Hole ID: 23046663
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/11/2007
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 442326.00
North83: 5023212.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 30246663
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.6100000143051147
Formation End Depth: 1.0299999713897705
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 30346663
Layer: 3
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY

Material 2: 06
Material 2 Desc: SILT
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 1.0299999713897705
Formation End Depth: 3.6600000858306885
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 30146663
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 28
Material 2 Desc: SAND
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44001374
Layer: 3
Plug From: 1.8300000429153442
Plug To: 3.6600000858306885
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44001375
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44001373
Layer: 2
Plug From: 0.30000001192092896
Plug To: 1.8300000429153442
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 25946663
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 29046663
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 42146663
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.130000114440918
Casing Diameter: 3.809999942779541
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 43146663
Layer: 1
Slot: 10
Screen Top Depth: 2.130000114440918
Screen End Depth: 3.6600000858306885
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 3.6700000762939453

Hole Diameter

Hole ID: 46000828
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 3.6600000858306885
Hole Depth UOM: m
Hole Diameter UOM: cm

---

60 **1 of 1** **SE/217.9** **98.9 / -1.03** **ON** **WWIS**

Well ID: 7473513
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z278659
Tag: A398257
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 03/15/2024
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7328
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID:	1010282727	***Tag No:***	A398257
Depth (m):		***Contractor:***	7328
Year Completed:	2024	***Latitude:***	45.3602770442044
Well Completed Dt:	01/29/2024	***Longitude:***	-75.735548545688
Audit No:	Z278659	***Point Y:***	45.36027703698399
Path:		***Point X:***	-75.7355483842692

Bore Hole Information

Bore Hole ID:	1010282727	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442392.00
Code OB Desc:		***North83:***	5023237.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/29/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

61 ***1 of 1*** ***SE/220.4*** ***98.9 / -1.03*** ***ON*** ***WWIS***

Well ID:	7473510	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	03/15/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z278658	***Contractor:***	7328
Tag:	A398256	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1010282718	***Tag No:***	A398256
Depth (m):		***Contractor:***	7328
Year Completed:	2024	***Latitude:***	45.3602408773038
Well Completed Dt:	01/29/2024	***Longitude:***	-75.7355736133768
Audit No:	Z278658	***Point Y:***	45.36024086996454
Path:		***Point X:***	-75.73557345175196

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole Information

Bore Hole ID:	1010282718	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442390.00
Code OB Desc:		***North83:***	5023233.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/29/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

62	*1 of 1*	*ESE/220.9*	*98.6 / -1.34*	*lot 35 con A ON*	*WWIS*

Well ID:	1504634	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Commerical	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	04/06/1960
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	1802
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	035
Depth to Bedrock:		***Concession:***	A
Well Depth:		***Concession Name:***	RF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504634.pdf

Additional Detail(s) (Map)

Well Completed Date:	03/22/1960
Year Completed:	1960
Depth (m):	27.432
Latitude:	45.3606868958052
Longitude:	-75.7348043592803
Point X:	-75.73480419764176
Point Y:	45.36068688931208
Path:	150\1504634.pdf

Bore Hole Information

Bore Hole ID:	10026677	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442450.70
Code OB Desc:		***North83:***	5023282.00

Open Hole: ***Org CS:***
Cluster Kind: ***UTMRC:*** 5
Date Completed: 03/22/1960 ***UTMRC Desc:*** margin of error : 100 m - 300 m
Remarks: ***Location Method:*** p5
Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931000016
Layer: 1
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931000017
Layer: 2
Color:
General Color:
Material 1: 13
Material 1 Desc: BOULDERS
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 30.0
Formation End Depth: 37.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931000018
Layer: 3
Color:
General Color:
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 37.0
Formation End Depth: 90.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:	961504634
Method Construction Code:	7
Method Construction:	Diamond
Other Method Construction:	

Pipe Information

Pipe ID:	10575247
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930046085
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	90.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930046084
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	39.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991504634
Pump Set At:	
Static Level:	10.0
Final Level After Pumping:	90.0
Recommended Pump Depth:	90.0
Pumping Rate:	84.0
Flowing Rate:	
Recommended Pump Rate:	84.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	0
Pumping Duration MIN:	30
Flowing:	No

Water Details

Water ID:	933457932
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	89.0
Water Found Depth UOM:	ft

63 **1 of 1** **ESE/228.0** **98.6 / -1.34** **lot 35 con A ON** **WWIS**

Well ID:	1504632	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	01/19/1960
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1301
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	035
Depth to Bedrock:		**Concession:**	A
Well Depth:		**Concession Name:**	RF
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504632.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/07/1959
Year Completed:	1959
Depth (m):	39.0144
Latitude:	45.3606423034056
Longitude:	-75.7347399407546
Point X:	-75.73473977947785
Point Y:	45.36064229611383
Path:	150\1504632.pdf

Bore Hole Information

Bore Hole ID:	10026675	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	442455.70
Code OB Desc:		**North83:**	5023277.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	09/07/1959	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931000012
Layer:	1
Color:	
General Color:	
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	30.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931000013
Layer:	2
Color:	
General Color:	
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	30.0
Formation End Depth:	128.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961504632
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10575245
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930046080
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	36.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930046081
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	128.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991504632
Pump Set At:	
Static Level:	20.0
Final Level After Pumping:	24.0
Recommended Pump Depth:	24.0
Pumping Rate:	6.0
Flowing Rate:	
Recommended Pump Rate:	6.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933457930
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	100.0
Water Found Depth UOM:	ft

---

64 | ***1 of 1*** | ***SSE/233.8*** | ***98.9 / -1.03*** | ***lot 35 con A ON*** | ***WWIS***

Well ID:	1504611	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Commerical	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	10/20/1955
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	1301
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	035
Depth to Bedrock:		***Concession:***	A
Well Depth:		***Concession Name:***	RF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		

Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504611.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/08/1955
Year Completed: 1955
Depth (m): 32.3088
Latitude: 45.3600048628921
Longitude: -75.7358808202133
Point X: -75.73588065842938
Point Y: 45.36000485623105
Path: 150\1504611.pdf

Bore Hole Information

Bore Hole ID:	10026654	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442365.70
Code OB Desc:		***North83:***	5023207.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	09/08/1955	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 930999963
Layer: 1
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 21.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930999964
Layer: 2
Color:
General Color:
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:

Material 3:
Material 3 Desc:
Formation Top Depth: 21.0
Formation End Depth: 106.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961504611
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10575224
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930046037
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 106.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930046036
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 28.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 991504611
Pump Set At:
Static Level: 20.0
Final Level After Pumping: 25.0
Recommended Pump Depth:
Pumping Rate: 6.0
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0

Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933457903
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 60.0
Water Found Depth UOM: ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
65	1 of 1	SSE/234.7	98.9 / -1.03	5010560 Ontario Inc 1486 Merivale Road Ottawa ON K2E 6Z5	GEN

Generator Info

Generator No: ON9674045
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

2021 Generator Info

Gen No: ON9674045
ID: 39909
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 811111
NAICS Code2:
NAICS Code3:
Gen Name: 5010560 Ontario Inc
Gen Div:
Gen Op Name: Swan's Garage
Gen Op Div:
Site Adrs1: 1486 Merivale Road
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2E 6Z5
Site Country: Canada
Co Official: Robert Swan
Co Admin: Sylvain Yelle
Choice of Contact: CO_OFFICIAL
Phone No Official: 613-226-2452 Ext.
Phone No Admin: 613-746-0514 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2021 Generator Manifest

ID: 66227
Sum Received Qty: 2000.0

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No:	ON9674045	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	402
Waste Code:	252		

---

66 **1 of 2** **SSE/235.1** **98.9 / -1.03** **SWAN'S GARAGE**
1486 MERIVALE RD
NEPEAN ON K2E 6Z5 **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

---

66 **2 of 2** **SSE/235.1** **98.9 / -1.03** **SWAN'S GARAGE**
1486 MERIVALE RD
NEPEAN ON K2E6Z5 **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 6132262452
List Name:
Description:

---

67 **1 of 1** **WSW/243.8** **97.6 / -2.34** **1442 BASELINE RD.**
OTTAWA ON **WWIS**

Well ID:	7267376	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	07/21/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z229760	**Contractor:**	7241
Tag:	A191212	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/726\7267376.pdf

Additional Detail(s) (Map)

Well Completed Date:	06/13/2016
Year Completed:	2016
Depth (m):	5.03
Latitude:	45.3612659921112
Longitude:	-75.7399153839787
Point X:	-75.73991522269209
Point Y:	45.36126598498871
Path:	726\7267376.pdf

Bore Hole Information

Bore Hole ID:	1006164619	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442051.00
Code OB Desc:		***North83:***	5023350.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	06/13/2016	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006172427
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.5199999809265137
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006172428
Layer:	3
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	12
Material 2 Desc:	STONES
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	1.5199999809265137
Formation End Depth:	5.03000020980835
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006172426
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	27

Material 1 Desc: OTHER
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006172436
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006172437
Layer: 2
Plug From: 0.12999999523162842
Plug To: 1.5199999809265137
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006172438
Layer: 3
Plug From: 1.5199999809265137
Plug To: 5.03000020980835
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006172435
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1006172425
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006172431
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.9800000190734863
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006172432
Layer: 1
Slot: 10
Screen Top Depth: 1.9800000190734863
Screen End Depth: 5.03000020980835
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03000020980835

Water Details

Water ID: 1006172430
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006172429
Diameter: 15.239999771118164
Depth From: 0.0
Depth To: 5.03000020980835
Hole Depth UOM: m
Hole Diameter UOM: cm

---

68 | ***1 of 13*** | ***ESE/244.0*** | ***98.6 / -1.34*** | ***A. M. Pharmacare Limited***
1469 MERIVALE ROAD
Ottawa ON K2E 5N9 | ***GEN***

Generator Info

Generator No: ON6550058
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Nastran Najafi-Fard
Phone No Admin: 416-493-1220 Ext.3218
SIC Description: 446110

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 446110

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	2 of 13	ESE/244.0	98.6 / -1.34	A. M. Pharmacare Limited (629) 1469 MERIVALE ROAD Ottawa ON K2E 5N9	GEN

Generator Info

Generator No:	ON6550058	**Choice of Contact:**	CO_ADMIN
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	446110
Country:	Canada		
Co Admin:	Nastran Najafi-Fard		
Phone No Admin:	416-493-1220 Ext.3218		
SIC Description:	446110		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	3 of 13	ESE/244.0	98.6 / -1.34	A. M. Pharmacare Limited 1469 MERIVALE ROAD Ottawa ON K2E 5N9	GEN

Generator Info

Generator No:	ON6550058	**Choice of Contact:**	
Approval Years:	As of Dec 2018	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	Pharmaceuticals

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	4 of 13	ESE/244.0	98.6 / -1.34	A. M. Pharmacare Limited 1469 MERIVALE ROAD Ottawa ON K2E 5N9	GEN

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON6550058
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	5 of 13	ESE/244.0	98.6 / -1.34	Shohdy Gana pharmacy inc. 1469 MERIVALE ROAD Ottawa ON K2E 5N9	GEN

Generator Info

Generator No: ON6550058
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	6 of 13	ESE/244.0	98.6 / -1.34	SHOPPERS DRUG MART #952 1469 MERIVALE ROAD Ottawa ON	GEN

Generator Info

Generator No: ON6550058
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Generator Info (as of Dec 2024)

Generator No: ON6550058
Generator Company Name: SHOPPERS DRUG MART #952
Street: 1469 MERIVALE ROAD
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K2E5N9
Waste Class: 312 P,261 A

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

Generator Info (as of Apr 2025)

Generator Company Name: SHOPPERS DRUG MART #952
Generator Site Address: 1469 MERIVALE ROAD
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K2E5N9
Waste Class: 312 P, 261 A

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

Waste Characteristic Decoded:

P - Pathological; A - Acutely Hazardous Waste Chem.

2017 Generator Info

Gen No: ON6550058
ID: 25774
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 446110
NAICS Code2:
NAICS Code3:
Gen Name: A. M. Pharmacare Limited
Gen Div:
Gen Op Name: Shoppers Drug Mart 627
Gen Op Div:
Choice of Contact: CO_ADMIN
Phone No Official: 613-224-7270 Ext.
Phone No Admin: 416-493-1220 Ext.3218
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Site Adrs1: 1469 MERIVALE ROAD
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2E 5N9
Site Country: Canada
Co Official: Amira Abdalla
Co Admin: Nastran Najafi-Fard

2017 Generator Manifest

ID: 51498
Generator No: ON6550058
Receiver Type: 030
Waste Char: P
Waste Code: 312
Sum Received Qty: 12.9
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 2
District: 402

2018 Generator Info

Gen No: ON6550058
ID: 26100
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 446110
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_ADMIN
Phone No Official: 613-224-7270 Ext.
Phone No Admin: 416-493-1220 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402
Gen Name: A. M. Pharmacare Limited
Gen Div:
Gen Op Name: Shoppers Drug Mart 627
Gen Op Div:
Site Adrs1: 1469 MERIVALE ROAD
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2E 5N9
Site Country: Canada
Co Official: Amira Abdalla
Co Admin: Pharmacy Operations Development

2019 Generator Info

Gen No: ON6550058
ID: 26327
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 446110
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_ADMIN
Phone No Official: 613-224-7270 Ext.
Phone No Admin: 416-493-1220 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402
Gen Name: A. M. Pharmacare Limited
Gen Div:
Gen Op Name: Shoppers Drug Mart 627
Gen Op Div:
Site Adrs1: 1469 MERIVALE ROAD
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:

Site City:	Ottawa
Province Out:	
Site Postal Code:	K2E 5N9
Site Country:	Canada
Co Official:	Amira Abdalla
Co Admin:	Pharmacy Operations Development

2019 Generator Manifest

ID:	51353	**Sum Received Qty:**	6.0
Generator No:	ON6550058	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	P	**District:**	402
Waste Code:	312		

2020 Generator Info

Gen No:	ON6550058	**Choice of Contact:**	CO_ADMIN
ID:	26066	**Phone No Official:**	613-224-7270 Ext.
Contaminated Fac:	N	**Phone No Admin:**	416-493-1220 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	446110	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			
Gen Name:	Shohdy Gana pharmacy inc.		
Gen Div:			
Gen Op Name:	Shoppers Drug Mart 627		
Gen Op Div:			
Site Adrs1:	1469 MERIVALE ROAD		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E 5N9		
Site Country:	Canada		
Co Official:	shohdy gana		
Co Admin:	Pharmacy Operations Development		

2020 Generator Manifest

ID:	47868	**Sum Received Qty:**	149.3
Generator No:	ON6550058	**Waste Class Name:**	PHARMACEUTICALS
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	P	**District:**	402
Waste Code:	261		

2020 Generator Manifest

ID:	47869	**Sum Received Qty:**	3.4
Generator No:	ON6550058	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	P	**District:**	402
Waste Code:	312		

2021 Generator Info

Gen No:	ON6550058	**Choice of Contact:**	CO_ADMIN
ID:	26517	**Phone No Official:**	613-224-7270 Ext.
Contaminated Fac:	N	**Phone No Admin:**	416-493-1220 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)

NAICS Code1:	446110	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			
Gen Name:	Shohdy Gana pharmacy inc.		
Gen Div:			
Gen Op Name:	Shoppers Drug Mart 627		
Gen Op Div:			
Site Adrs1:	1469 MERIVALE ROAD		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2E 5N9		
Site Country:	Canada		
Co Official:	shohdy gana		
Co Admin:	Pharmacy Operations Development		

2021 Generator Manifest

ID:	49747	**Sum Received Qty:**	7.44
Generator No:	ON6550058	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	P	**District:**	402
Waste Code:	312		

---

68 ***7 of 13*** ***ESE/244.0*** ***98.6 / -1.34*** ***TRENT E JAY ADOTHECARY LTD*** ***PES***
1469 MERIVALE RD
OTTAWA ON K2E5N9

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

68 ***8 of 13*** ***ESE/244.0*** ***98.6 / -1.34*** ***A.M. PHARMACARE LIMITED*** ***PES***
1469 MERIVALE ROAD
OTTAWA ON K2E5N9

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	Vendor
Report Source:		**Oper Area Code:**	
Licence Type:		**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

68	9 of 13	ESE/244.0	98.6 / -1.34	TRENT E JAY ADOTHECARY LTD 1469 MERIVALE RD OTTAWA ON K2E5N9	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

68	10 of 13	ESE/244.0	98.6 / -1.34	A.M. PHARMACARE LIMITED 1469 MERIVALE ROAD OTTAWA ON K2E 5N9	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

68	11 of 13	ESE/244.0	98.6 / -1.34	SHOPPERS DRUG MART #627 1469 MERIVALE RD OTTAWA ON K2E5N9	PES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail Licence No:		**Operator Box:**	
Licence No:	13266	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	2247270
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	12 of 13	ESE/244.0	98.6 / -1.34	A.M. PHARMACARE LIMITED 1469 MERIVALE ROAD OTTAWA ON K2E5N9	PES

Detail Licence No:		**Operator Box:**	
Licence No:	14567	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	2247270
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	13 of 13	ESE/244.0	98.6 / -1.34	TRENT E JAY APOTHECARY LTD 1469 MERIVALE RD OTTAWA ON K2E5N9	PES

Detail Licence No:		**Operator Box:**	
Licence No:	14238	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	2247270
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

County: **SWP Area Name:**
Trade Name:
PDF URL:

---

69 **1 of 7** **WNW/244.3** **97.9 / -2.03** **CLYDESDALE SHOPPING CENTRES LIMITED** **EASR**
1331 CLYDE AVENUE
OTTAWA ON K2C 0A8

Approval No: R-002-2135605079
Status: REGISTERED
Date: 2012-07-16
Record Type: EASR
Link Source: MOFA
Project Type: Standby Power System
Full Address:
Approval Type: EASR-Standby Power System
SWP Area Name:
PDF NAICS Code:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=1295
PDF Site Location:

MOE District:
Municipality: OTTAWA
Latitude:
Longitude:
Geometry X:
Geometry Y:

---

69 **2 of 7** **WNW/244.3** **97.9 / -2.03** **Stantec** **GEN**
1331 Clyde Unit 400
Ottawa ON K2C 3G4

Generator Info

Generator No: ON8419694
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

---

69 | ***3 of 7*** | ***WNW/244.3*** | ***97.9 / -2.03*** | ***Stantec***
1331 Clyde Unit 400
Ottawa ON K2C 3G4 | ***GEN***

Generator Info

Generator No: ON8419694
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

69	4 of 7	WNW/244.3	97.9 / -2.03	**Kroon Electric Corp** **1331 Clyde Avenue** **Ottawa ON K2C 3G4**	GEN

Generator Info

Generator No: ON5890467
Approval Years: As of Oct 2019
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

2019 Generator Info

Gen No: ON5890467
ID: 23607
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 531310
NAICS Code2:
NAICS Code3:
Gen Name: Kroon Electric Corp
Gen Div:
Gen Op Name: Kroon Electric Corp
Gen Op Div:
Site Adrs1: 1331 Clyde Avenue
Site Bldg: Laurentian Place
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 3G4
Site Country: Canada
Co Official: Daniel Laforge
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Official: 613-833-0020 Ext.
Phone No Admin:
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2019 Generator Manifest

ID: 47878
Generator No: ON5890467
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 225.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 2
District: 306

---

69 | ***5 of 7*** | ***WNW/244.3*** | ***97.9 / -2.03*** | ***Stantec Consulting Ltd.***
1331 Clyde Avenue, Unit 400
Ottawa ON K2C 3G4 | ***GEN***

Generator Info

Generator No: ON8419694
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

69	***6 of 7***	***WNW/244.3***	***97.9 / -2.03***	***Stantec Consulting Ltd.*** ***1331 Clyde Avenue, Unit 400*** ***Ottawa ON***	***GEN***

Generator Info

Generator No: ON8419694
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 148 R
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 267 C
Waste Class Name: ORGANIC ACIDS

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Generator Info (as of Dec 2024)

Generator No: ON8419694
Generator Company Name: Stantec Consulting Ltd.
Street: 1331 Clyde Avenue, Unit 400
City: Ottawa
Province State: Ontario

Country: Canada
Postal Code: K2C3G4
Waste Class: 148 C,112 C,122 C,331 I,267 C,263 I,148 L,148 T,148 R

Waste Class Decoded:

148 - INORGANIC LABORATORY CHEMICALS; 112 - ACID WASTE - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 331 - WASTE COMPRESSED GASES; 267 - ORGANIC ACIDS; 263 - ORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS

Generator Info (as of Apr 2025)

Generator Company Name: Stantec Consulting Ltd.
Generator Site Address: 1331 Clyde Avenue, Unit 400
City: Ottawa
Province State: Ontario
Country: Canada
Postal Code: K2C3G4
Waste Class: 148 C, 112 C, 122 C, 331 I, 267 C, 263 I, 148 L, 148 T, 148 R

Waste Class Decoded:

148 - INORGANIC LABORATORY CHEMICALS; 112 - ACID WASTE - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 331 - WASTE COMPRESSED GASES; 267 - ORGANIC ACIDS; 263 - ORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS

Waste Characteristic Decoded:

C - Corrosive; C - Corrosive; C - Corrosive; I - Ignitable; C - Corrosive; I - Ignitable; L - Liquid Industrial Waste; T - Leachate Toxic; R - Reactive

2017 Generator Info

Gen No: ON8419694
ID: 32987
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 541330
NAICS Code2:
NAICS Code3:
Gen Name: Stantec
Gen Div:
Gen Op Name: Stantec
Gen Op Div:
Site Adrs1: 1331 Clyde Unit 400
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 3G4
Site Country: Canada
Co Official: Andrew Potts
Co Admin: Brandon A McGee
Choice of Contact: CO_OFFICIAL
Phone No Official: 3439994568 Ext.
Phone No Admin: 6137391449 Ext.245
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2017 Generator Manifest

ID: 60601
Generator No: ON8419694
Receiver Type: 035
Sum Received Qty: 10.0
Waste Class Name: ALKALINE WASTES - OTHER METALS
Count Manifests: 1

Waste Char: C
Waste Code: 122
District: 402

2017 Generator Manifest

ID: 60600
Generator No: ON8419694
Receiver Type: 035
Waste Char: C
Waste Code: 112
Sum Received Qty: 1.0
Waste Class Name: ACID WASTE - HEAVY METALS
Count Manifests: 1
District: 402

2018 Generator Info

Gen No: ON8419694
ID: 33600
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 541330
NAICS Code2:
NAICS Code3:
Gen Name: Stantec
Gen Div:
Gen Op Name: Stantec
Gen Op Div:
Site Adrs1: 1331 Clyde Unit 400
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 3G4
Site Country: Canada
Co Official: Tarek Ghadieh
Co Admin: Zaker Mehrez
Choice of Contact: CO_OFFICIAL
Phone No Official: 6137386059 Ext.
Phone No Admin: 6137371573 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2018 Generator Manifest

ID: 60904
Generator No: ON8419694
Receiver Type: 035
Waste Char: I
Waste Code: 263
Sum Received Qty: 1.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 1
District: 402

2018 Generator Manifest

ID: 60905
Generator No: ON8419694
Receiver Type: 035
Waste Char: C
Waste Code: 267
Sum Received Qty: 1.0
Waste Class Name: ORGANIC ACIDS
Count Manifests: 1
District: 402

2018 Generator Manifest

ID: 60906
Generator No: ON8419694
Receiver Type: 035
Waste Char: I
Waste Code: 331
Sum Received Qty: 1.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 1
District: 402

2018 Generator Manifest

ID:	60903	**Sum Received Qty:**	10.0
Generator No:	ON8419694	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	402
Waste Code:	148		

2019 Generator Info

Gen No:	ON8419694	**Choice of Contact:**	CO_OFFICIAL
ID:	33995	**Phone No Official:**	6137386059 Ext.
Contaminated Fac:	N	**Phone No Admin:**	6137371573 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	541330	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			
Gen Name:	Stantec		
Gen Div:			
Gen Op Name:	Stantec		
Gen Op Div:			
Site Adrs1:	1331 Clyde Unit 400		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2C 3G4		
Site Country:	Canada		
Co Official:	Tarek Ghadieh		
Co Admin:	Zaker Mehrez		

2019 Generator Manifest

ID:	60792	**Sum Received Qty:**	1.0
Generator No:	ON8419694	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	R	**District:**	402
Waste Code:	148		

2019 Generator Manifest

ID:	60791	**Sum Received Qty:**	2.0
Generator No:	ON8419694	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	C	**District:**	402
Waste Code:	148		

2019 Generator Manifest

ID:	60793	**Sum Received Qty:**	1.0
Generator No:	ON8419694	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	T	**District:**	402
Waste Code:	148		

2019 Generator Manifest

ID:	60795	**Sum Received Qty:**	2.0
Generator No:	ON8419694	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	I	**District:**	402

Waste Code: 331

2019 Generator Manifest

ID: 60794
Generator No: ON8419694
Receiver Type: 035
Waste Char: I
Waste Code: 263
Sum Received Qty: 1.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 1
District: 402

2020 Generator Info

Gen No: ON8419694
ID: 33722
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 541330
NAICS Code2:
NAICS Code3:
Gen Name: Stantec Consulting Ltd.
Gen Div:
Gen Op Name: Stantec Consulting Ltd.
Gen Op Div:
Site Adrs1: 1331 Clyde Avenue, Unit 400
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 3G4
Site Country: Canada
Co Official: Tarek Ghadieh
Co Admin: Zaker Mehrez
Choice of Contact: CO_OFFICIAL
Phone No Official: 6137386059 Ext.
Phone No Admin: 6137371573 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2021 Generator Info

Gen No: ON8419694
ID: 34527
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 541330
NAICS Code2:
NAICS Code3:
Gen Name: Stantec Consulting Ltd.
Gen Div:
Gen Op Name: Stantec Consulting Ltd.
Gen Op Div:
Site Adrs1: 1331 Clyde Avenue, Unit 400
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 3G4
Site Country: Canada
Co Official: Tarek Ghadieh
Co Admin: Zaker Mehrez
Choice of Contact: CO_OFFICIAL
Phone No Official: 6137386059 Ext.
Phone No Admin: 6137371573 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

69	7 of 7	WNW/244.3	97.9 / -2.03	Versaterm Public Safety Inc 1331 Clyde Ave.	SCT

Ottawa ON K2C3G4

Scott S ID: 33871155
Latitude: 45.3630056
Longitude: -75.7400934

Details

Bus Type 1:	Manufacturer	***Employee Count:***	92
Bus Type 2:		***Square Footage:***	0
Bus Type 3:		***Estimated Sales:***	N/A
Product Cat 1:	Computer consultant	***Export Indicator:***	N
Product Cat 2:	Computers: mobile	***Export Country 1:***	
Product Cat 3:		***Export Country 2:***	
Product Cat 4:		***Export Country 3:***	
Product Cat 5:		***Export Country 4:***	
Product Cat 6:		***Export Country 5:***	
Product Cat 7:		***Export Country 6:***	
Product Cat 8:		***Geocoded by:***	Address

Company Name: Versaterm Public Safety Inc
Address Line 1: 1331 Clyde Ave.
Address Line 2:
City: Ottawa
Province: ON
Postal Code: K2C3G4
Census Division: Ottawa; ON
Metro Area: Ottawa/Hull
Year Established: 1977
Head Office Indicator: N
Parent Company Nm:
Parent Cmpny Addr 1:
Parent Cmpny Addr 2:
Parent Cmpny City:
Parent Cmpny Prov:
Parent Cmpy PC:
Parent Cmpy Cntry:
Head Office Nm:
H Office Addr Line 1:
H Office Addr Line 2:
Head Office City:
Head Office Province:
Head Office PC:
Head Office Cntry:
Telephone: 613-820-0311
Fax: 613-596-5884
Website: http://www.versaterm.com/
Pri NAICS Desc: 334110-Computer and Peripheral Equipment Manufacturing
NAICS Code 1: 334110-Computer and Peripheral Equipment Manufactu
NAICS Code 2: 334290-Other Communications Equipment Manufacturin
NAICS Code 3:
NAICS Code 4:
NAICS Code 5:

Historical Details

Established: 01-JUN-77
Plant Size (ft²):
Employment:

Historical Details

Description: Other Communications Equipment Manufacturing
SIC/NAICS Code: 334290

Historical Details

Description: Computer and Peripheral Equipment Manufacturing
SIC/NAICS Code: 334110

---

71 | ***1 of 1*** | ***SE/244.7*** | ***98.9 / -1.03*** | ***lot 35 con A ON*** | ***WWIS***

Well ID:	1504618	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Public	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	11/07/1956
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	1301
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	035
Depth to Bedrock:		***Concession:***	A
Well Depth:		***Concession Name:***	RF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	

Municipality: NEPEAN TOWNSHIP
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1504618.pdf

Additional Detail(s) (Map)

Well Completed Date: 06/21/1956
Year Completed: 1956
Depth (m): 38.1
Latitude: 45.3600985692006
Longitude: -75.7353074689422
Point X: -75.73530730708464
Point Y: 45.360098562327906
Path: 150\1504618.pdf

Bore Hole Information

Bore Hole ID:	10026661	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	442410.70
Code OB Desc:		***North83:***	5023217.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	06/21/1956	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	930999978
Layer:	1
Color:	
General Color:	
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	26.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930999979
Layer:	2
Color:	
General Color:	
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	26.0
Formation End Depth:	125.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961504618
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10575231
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930046050
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	26.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930046051
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	125.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	991504618
Pump Set At:	
Static Level:	6.0
Final Level After Pumping:	8.0
Recommended Pump Depth:	
Pumping Rate:	6.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	0
Pumping Duration MIN:	30
Flowing:	No

Water Details

Water ID:	933457912
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	40.0
Water Found Depth UOM:	ft

72 ***1 of 1*** ***WSW/245.8*** ***97.9 / -2.04*** ***ON*** ***BORE***

Borehole ID:	612607	**Inclin FLG:**	No
OGF ID:	215513913	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:	18.6	**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.360569
Total Depth m:	-999	**Longitude DD:**	-75.7394
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	442091
Drill Method:		**Northing:**	5023272
Orig Ground Elev m:	94.8	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	96		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218391807	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	4.6	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:	Boulders	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	CLAY.		

Geology Stratum ID:	218391808	***Mat Consistency:***	Firm
Top Depth:	4.6	***Material Moisture:***	
Bottom Depth:		***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Limestone	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	BEDROCK. STONE. 5000050. WATER STABLE AT 250.0 FEET.Y,FIRM. SILT. GREY,LOOSE,DENS **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 051150 NTS_Sheet: 31G05B		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	1 of 5	ESE/246.3	97.8 / -2.06	1465 Merivale Rd Ottawa ON K2E5N9	EHS

Order No:	20160615109	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	21-JUN-16	***Search Radius (km):***	.25
Date Received:	15-JUN-16	***X:***	-75.733442
Previous Site Name:		***Y:***	45.360635
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	2 of 5	ESE/246.3	97.8 / -2.06	METRO ONTARIO INC O/A METRO/FOOD BASICS # 907 1465 MERIVALE ROAD, UNIT 13	PES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				OTTAWA ON K2E5N9	

Detail Licence No:		Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Vendor	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	3 of 5	ESE/246.3	97.8 / -2.06	METRO ONTARIO INC O/A METRO/FOOD BASICS # 907 1465 Merivale Road, Unit 13 Ottawa ON K2E 5N9	PES

Detail Licence No:	23-01-15183-0	Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	LIMITED	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	4 of 5	ESE/246.3	97.8 / -2.06	METRO ONTARIO INC O/A METRO/FOOD BASICS # 907 1465 MERIVALE ROAD, UNIT 13 OTTAWA ON K2E5N9	PES

Detail Licence No:		Operator Box:	
Licence No:	15183	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:	Legacy Licenses (Excluding TS)	Oper Area Code:	613
Licence Type:	Limited Vendor	Oper Phone No:	
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Concession: **Op Municipality:**
Region: **Post Office Box:**
District: **MOE District:**
County: **SWP Area Name:**
Trade Name:
PDF URL:

---

73 **5 of 5** **ESE/246.3** **97.8 / -2.06** **Parson Refrigeration (1985) Ltd.**
1465 Meriville Road
Ottawa ON
SPL

Ref No: 4826-94QSD7 **Municipality No:**
Year: **Nature of Damage:**
Incident Dt: 08-FEB-13 **Discharger Report:**
Dt MOE Arvl on Scn: **Material Group:**
MOE Reported Dt: 08-FEB-13 **Impact to Health:**
Dt Document Closed: **Agency Involved:**
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Food Basics<UNOFFICIAL>
Site Address: 1465 Meriville Road
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Parson Refrigeration (1985) Ltd.
Client Type:
Source Type:
Incident Cause: Leak/Break
Incident Preceding Spill:
Incident Reason: Equipment Failure
Incident Summary: Food Basics: 300 lbs to atmosphere, repaired
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: 136 kg
Contaminant Qty 1: 136
Contaminant Unit: kg
Contaminant Code: 38
Contaminant Name: REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Valve/Fitting/Piping
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:

Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

74 | ***1 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1117063 ONTARIO INC*** ***1442 BASELINE RD*** ***OTTAWA ON K2C 0B2*** | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9483337
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 7/7/1995
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

74 | ***2 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1117063 ONTARIO INC*** ***1442 BASELINE RD*** ***OTTAWA ON*** | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10868629
Status: EXPIRED
Instance ID: 47316
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

74	*3 of 30*	*WSW/248.7*	*98.0 / -1.95*	***1117063 ONTARIO INC*** ***1442 BASELINE RD*** ***OTTAWA ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10868613
Status: EXPIRED
Instance ID: 47601
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012
Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

74	*4 of 30*	*WSW/248.7*	*98.0 / -1.95*	***1117063 ONTARIO INC*** ***1442 BASELINE RD*** ***OTTAWA ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10868661	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	47872	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	5 of 30	WSW/248.7	98.0 / -1.95	1117063 ONTARIO INC 1442 BASELINE RD OTTAWA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10868646	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	47790	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

74 | ***6 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1117063 ONTARIO INC***
1442 BASELINE RD
OTTAWA ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10868598
Status: EXPIRED
Instance ID: 47814
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

74 | ***7 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1442 Baseline Rd***
Ottawa ON K2C0B2 | ***EHS***

Order No: 20170405065
Status: C
Report Type: RSC Report (Urban)
Report Date: 12-APR-17
Date Received: 05-APR-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Searches; City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -75.739922
Y: 45.36077

---

74 | ***8 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1117063 ONTARIO INC***
1442 BASELINE RD
OTTAWA ON | ***EXP***

Inventory No: 10868606
Inventory Status: EXPIRED
Installation Year: 1980

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

74 | ***9 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1117063 ONTARIO INC 1442 BASELINE RD OTTAWA ON*** | ***EXP***

Inventory No: 10868589
Inventory Status: EXPIRED
Installation Year: 1980
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

74 | ***10 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1117063 ONTARIO INC 1442 BASELINE RD OTTAWA ON*** | ***EXP***

Inventory No: 10868637
Inventory Status: EXPIRED
Installation Year: 1980
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

74 | ***11 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1117063 ONTARIO INC 1442 BASELINE RD OTTAWA ON*** | ***EXP***

Inventory No: 10868652
Inventory Status: EXPIRED
Installation Year: 1980
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Diesel
Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

74 | ***12 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***1117063 ONTARIO INC 1442 BASELINE RD OTTAWA ON*** | ***EXP***

Inventory No: 10868622
Inventory Status: EXPIRED
Tank Material: Steel
Corrosion Protect: Impressed Current

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Installation Year: 1980
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

74	13 of 30	WSW/248.7	98.0 / -1.95	Imperial Oil 1442 Baseline Road Ottawa ON K2C 0B2	GEN

Generator Info

Generator No: ON9681915
Approval Years: 02,03,04,05,06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

74	14 of 30	WSW/248.7	98.0 / -1.95	Imperial Oil 1442 Baseline Road Ottawa ON K2C 0B2	GEN

Generator Info

Generator No: ON9681915
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Other Gasoline Stations
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 447190

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

74 **15 of 30** **WSW/248.7** **98.0 / -1.95** **Imperial Oil** **GEN**
1442 Baseline Road
Ottawa ON K2C 0B2

Generator Info

Generator No: ON9681915
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Other Gasoline Stations

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 447190

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

74 **16 of 30** **WSW/248.7** **98.0 / -1.95** **Imperial Oil** **GEN**
1442 Baseline Road
Ottawa ON K2C 0B2

Generator Info

Generator No: ON9681915
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Other Gasoline Stations

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 447190

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252

Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

74 **17 of 30** **WSW/248.7** **98.0 / -1.95** **Imperial Oil**
1442 Baseline Road
Ottawa ON K2C 0B2
GEN

Generator Info

Generator No: ON9681915
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Other Gasoline Stations

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 447190

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

74 **18 of 30** **WSW/248.7** **98.0 / -1.95** **Imperial Oil**
1442 Baseline Road
Ottawa ON
GEN

Generator Info

Generator No: ON9681915
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 447190

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

74 | ***19 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***Imperial Oil***
1442 Baseline Road
Ottawa ON K2C 0B2 | ***GEN***

Generator Info

Generator No: ON9681915
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Sandra Carrelas
Phone No Admin: 519-652-0099 Ext.
SIC Description: 447190

Choice of Contact: CO_ADMIN
Contaminated Fac: Yes
MHSW Facility: No
SIC Code: 447190

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

74 | ***20 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***Imperial Oil***
1442 Baseline Road
Ottawa ON K2C 0B2 | ***GEN***

Generator Info

Generator No: ON9681915
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Nicole Bradley
Phone No Admin: 519-652-0099 Ext.4301
SIC Description: 447190

Choice of Contact: CO_ADMIN
Contaminated Fac: Yes
MHSW Facility: No
SIC Code: 447190

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

74 ***21 of 30*** ***WSW/248.7*** ***98.0 / -1.95*** ***Imperial Oil***
1442 Baseline Road
Ottawa ON K2C 0B2 ***GEN***

Generator Info

Generator No: ON9681915
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Leah Dolinski
Phone No Admin: 905-569-4111 Ext.
SIC Description: 447190

Choice of Contact: CO_ADMIN
Contaminated Fac: Yes
MHSW Facility: No
SIC Code: 447190

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

74 ***22 of 30*** ***WSW/248.7*** ***98.0 / -1.95*** ***Imperial Oil***
1442 Baseline Road
Ottawa ON K2C 0B2 ***GEN***

Generator Info

Generator No: ON9681915
Approval Years: As of Dec 2018
Status: Registered
PO Box No:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

74 | ***23 of 30*** | ***WSW/248.7*** | ***98.0 / -1.95*** | ***Imperial Oil***
1442 Baseline Road
Ottawa ON K2C 0B2 | ***GEN***

Generator Info

Generator No: ON9681915
Approval Years: As of Oct 2019
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

2017 Generator Info

Gen No: ON9681915
ID: 37813
Contaminated Fac: Y
MHSW Facility: N
NAICS Code1: 447190
NAICS Code2:
NAICS Code3:
Gen Name: Imperial Oil
Gen Div:
Gen Op Name: Imperial Oil
Gen Op Div:
Site Adrs1: 1442 Baseline Road
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 0B2
Site Country: Canada
Co Official: Jack Crabtree
Co Admin: Sandra Carrelas

Choice of Contact: CO_ADMIN
Phone No Official: 587-476-1395 Ext.
Phone No Admin: 519-652-0099 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

2017 Generator Manifest

ID: 66688
Generator No: ON9681915
Receiver Type: 035
Waste Char: L
Waste Code: 221

Sum Received Qty: 50.0
Waste Class Name: LIGHT FUELS
Count Manifests: 1
District: 402

2018 Generator Info

Gen No: ON9681915
ID: 38568
Contaminated Fac: Y
MHSW Facility: N
NAICS Code1: 447190
NAICS Code2:
NAICS Code3:
Gen Name: Imperial Oil
Gen Div:
Gen Op Name: Imperial Oil
Gen Op Div:
Site Adrs1: 1442 Baseline Road
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Ottawa
Province Out:
Site Postal Code: K2C 0B2
Site Country: Canada
Co Official: Ruolin Shi
Co Admin: Sandra Carrelas

Choice of Contact: CO_ADMIN
Phone No Official: 587-476-2565 Ext.
Phone No Admin: 519-652-0099 Ext.
County Ont: OTTAWA CARLTON (RM)
County Out:
District: 402

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2018 Generator Manifest

ID:	67281	**Sum Received Qty:**	25.0
Generator No:	ON9681915	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	402
Waste Code:	251		

2019 Generator Info

Gen No:	ON9681915	**Choice of Contact:**	CO_ADMIN
ID:	39137	**Phone No Official:**	587-476-2565 Ext.
Contaminated Fac:	Y	**Phone No Admin:**	519-652-0099 Ext.
MHSW Facility:	N	**County Ont:**	OTTAWA CARLTON (RM)
NAICS Code1:	447190	**County Out:**	
NAICS Code2:		**District:**	402
NAICS Code3:			
Gen Name:	Imperial Oil		
Gen Div:			
Gen Op Name:	Imperial Oil		
Gen Op Div:			
Site Adrs1:	1442 Baseline Road		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Ottawa		
Province Out:			
Site Postal Code:	K2C 0B2		
Site Country:	Canada		
Co Official:	Ruolin Shi		
Co Admin:	Sandra Carrelas		

74	***24 of 30***	***WSW/248.7***	***98.0 / -1.95***	***Lewis Esso Service*** ***1442 Baseline Rd*** ***Ottawa ON***	***HBAR***

Province:	ON
Year:	1960
Source:	Mights

74	***25 of 30***	***WSW/248.7***	***98.0 / -1.95***	***T & P ESSO C/O TED DESROSIERS*** ***1442 BASELINE RD*** ***NEPEAN ON K2C 0B2***	***PRT***

Location ID:	9578
Type:	retail
Expiry Date:	1995-01-31
Capacity (L):	113500
Licence #:	0076344696

74	***26 of 30***	***WSW/248.7***	***98.0 / -1.95***	***SCOTTS ESSO RICHARD SCOTT*** ***1442 BASELINE RD*** ***NEPEAN ON K2C3Z4***	***PRT***

Location ID:	9578
Type:	retail
Expiry Date:	1995-09-30
Capacity (L):	113500
Licence #:	0076428754

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	27 of 30	WSW/248.7	98.0 / -1.95	MR LUBE 1442 BASELINE RD OTTAWA ON K2C 0B2	RST

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone:
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	28 of 30	WSW/248.7	98.0 / -1.95	MR LUBE 1442 BASELINE RD OTTAWA ON K2C0B2	RST

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone: 6132242991
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	29 of 30	WSW/248.7	98.0 / -1.95	MR LUBE 1442 BASELINE RD OTTAWA ON K2C0B2	RST

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone: 6132242991
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	30 of 30	WSW/248.7	98.0 / -1.95	Mr. Lube<UNOFFICIAL> 1442 Baseline Road Ottawa ON	SPL

Ref No: 2762-A8YW2V
Year:
Incident Dt: 2016/04/12
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/04/13
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Mr. Lube - 5 L motor oil spilled to paved surfaces.<UNOFFICIAL>
Site Address: 1442 Baseline Road
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 5023277
Easting: 442042
Entity Operating Name:
Client Name: Mr. Lube<UNOFFICIAL>
Client Type:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Source Type:	
Incident Cause:	
Incident Preceding Spill:	Operator/Human error
Incident Reason:	Operator/Human Error
Incident Summary:	Mr. Lube: est. 5 L motor oil spilled to paved surfaces.
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	5 L
Contaminant Qty 1:	5
Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	MOTOR OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

Unplottable Summary

Total: 72 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
AAGR		Lot 30 Con 2	City of Ottawa ON	
CA		Merivale Road	Nepean ON	
CA		Draft Plan 06T-99003-Clyde Avenue Holdings	Ottawa ON	
CA	ROYAL OTTAWA HOSPITAL	MERIVALE RD.	OTTAWA CITY ON	
CA	MINTO CONSTRUCTION LTD.	MERIVALE RD.	NEPEAN CITY ON	
CA	MINTO CONSTRUCTION LTD.	MERIVALE RD. EAST SIDE	NEPEAN CITY ON	
CA	TONY GRAHAM MOTORS (1980) LIMITED	MERIVALE RD. (SWM)	NEPEAN CITY ON	
CA	R.M. OF OTTAWA-CARLETON	BASELINE ROAD EXTENSION (SWM)	OTTAWA CITY ON	
CA	LONDON LIFE INS. CO. & BESNER VERED (198	LOT N,CON.A/RIDEAU FRONT	OTTAWA ON	
CA	SHELL CANADA PRODUCTS LIMITED	MERIVALE RD., BULK TANK FARM	NEPEAN CITY ON	
CA	JAMES STEWART	MERIVALE RD.	NEPEAN CITY ON	
CA	City of Nepean	MERIVALE RD./S.W.MGT	NEPEAN CITY ON	
CA	MID CANADA CONSTRUCTION LTD.	ACESS RD. W. OF MERIVALE RD.	NEPEAN CITY ON	
CA	JAMES STEWART	MERIVALE RD. STEWART FUELS	NEPEAN CITY ON	
CA	R.M. OF OTTAWA-CARLETON	MERIVALE RD. RECONT. WOODFIELD	NEPEAN CITY ON	
CA	J. PEREZ CONSTRUCTION LTD.	MERIVALE RD.	NEPEAN CITY ON	
CA	BELL-NORTHERN RESEARCH LIMITED	BASELINE ROAD	NEPEAN CITY ON	
CA	RON ENGINEERING & CONSTRUCTION LTD.	BASELINE RD.	OTTAWA CITY ON	

CA		Merivale Road	Nepean ON	
CA	Canadian Tire Real Estate Limited		Ottawa ON	
CA	Canadian Tire Real Estate Limited		Ottawa ON	
CA	Petro-Canada		Ottawa ON	
CA	Ottawa-Carleton District School Board		Ottawa ON	
CA	Canadian Tire Real Estate Limited		Ottawa ON	
CONV	Loblaw Companies Limited		Ottawa ON	
ECA	Petro-Canada Inc.		Ottawa ON	L6L 6N5
ECA	Ashcroft Developments Inc.	Draft Plan 06T-99003-Clyde Avenue Holdings	Ottawa ON	K2E 1A9
ECA	WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA		ON	
ECA	WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA		ON	
ECA	Ashcroft Developments Inc.	Draft Plan 06T-99003-Clyde Avenue Holdings	Ottawa ON	K2E 1A9
ECA	Canadian Tire Real Estate Limited		Ottawa ON	M4P 2V8
EHS		Baseline Rd	Ottawa ON	
GEN	Carmelo Idone	Rear Merivale Rd.	Ottawa ON	K1Z 6A5
GEN	7770251 CANADA INC	MERIVALE ROAD	OTTAWA ON	
HBAR	Sheridan Garage	w s Merivale rd	Ottawa ON	
HBAR	City View Garage	w s Merivale rd	Ottawa ON	
HBAR	Pinecrest Texaco Service Station	N S Baseline Rd	Ottawa ON	
HBAR	Imperial Oil Ltd		Ottawa ON	
HBAR	City View Garage	w s Merivale rd	Ottawa ON	
HBAR	City View Garage	w s Merivale rd	Ottawa ON	

HBAR	Sheridan Garage	w s Merivale rd	Ottawa ON	
NPCB	CJOH TV	BOX 5813; MERIVALE DEPOT	OTTAWA ON	K2C 3G6
PRT	SHELL CANADA PRODUCTS LTD	MERIVALE RD	OTTAWA ON	
PTTW	Corporation of the City of Ottawa	Lot 30, Concession 2RF, City of Ottawa (formerly City of Nepean) CITY OF OTTAWA	ON	
RST	CANADIAN TIRE PIT STOP & PROPANE		OTTAWA ON	K2H 5Z2
RST	CANADIAN TIRE PIT STOP & PROPANE		OTTAWA ON	K2H5Z2
RST	PETRO CANADA		NEPEAN ON	K2J4G5
SPL	City of Ottawa	CLYDE AVE NORTH OF MERIVALE RD<UNOFFICIAL>	Ottawa ON	
SPL	Esso Petroleum Canada, A Division of Imperial Oil Limited	Nepean	Ottawa ON	
SPL	PETRO-CANADA	TANK TRUCK (CARGO)	NEPEAN CITY ON	
SPL	PETRO-CANADA	BULK PLANT/TERMINAL	NEPEAN CITY ON	
SPL	PETRO-CANADA	SERVICE STATION	OTTAWA CITY ON	
SPL	IMPERIAL OIL	TANK TRUCK (CARGO)	NEPEAN CITY ON	
SPL	LOBLAWS		OTTAWA CITY ON	
SPL	TRANSPORT TRUCK	FROM CLYDE AVE/MERIVALE RD TO KIRKWOOD/ MERIVALE IN NEPEAN. MOTOR VEHICLE (OPERATING FLUID)	OTTAWA CITY ON	
SPL	NATIONAL GROCERIES COMPANY LTD		OTTAWA ON	
SPL	PETRO-CANADA	BULK PLANT/TERMINAL	NEPEAN CITY ON	
SPL	Loblaw Properties Limited	Loblaws	Ottawa ON	
WWIS		con A	ON	
WWIS		con 2	ON	
WWIS		con 2	ON	
WWIS		con 2	ON	

WWIS	con 2	ON
WWIS	con 2	ON
WWIS	con 2	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	lot 30 con 2	ON
WWIS	lot N con A	ON
WWIS	con A	ON
WWIS	con 1	ON

Unplottable Report

Site:
Lot 30 Con 2 City of Ottawa ON

Database: ***AAGR***

Type:	Quarry
Region/County:	Ottawa-Carleton
Township:	City of Ottawa
Concession:	2
Lot:	30
Size (ha):	3.7
Landuse:	
Comments:	

Site:
Merivale Road Nepean ON

Database: ***CA***

Certificate #:	6408-4PJHR7
Application Year:	00
Issue Date:	9/27/00
Approval Type:	Municipal & Private water
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	Corporation of the Regional Municipality of Ottawa-Carleton
Client Address:	111 Lisgar Street
Client City:	Ottawa
Client Postal Code:	K2P 2L7
Project Description:	Installation of watermains and appurtenances in Merivale Road from Amberwood Crescent to approximately 100 m north of Fallowfield Road.
Contaminants:	
Emission Control:	

Site:
Draft Plan 06T-99003-Clyde Avenue Holdings Ottawa ON

Database: ***CA***

Certificate #:	3108-4JQJ6L
Application Year:	00
Issue Date:	4/27/00
Approval Type:	Municipal & Private sewage
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	Ashcroft Developments Inc.
Client Address:	18 Antares Drive
Client City:	Nepean
Client Postal Code:	K2E 1A9
Project Description:	Construction of sanitary and storm sewers along Staten Way and Clyde Ave.
Contaminants:	
Emission Control:	

Site: ***ROYAL OTTAWA HOSPITAL***
MERIVALE RD. OTTAWA CITY ON

Database: ***CA***

Certificate #:	3-1424-85-006
Application Year:	85
Issue Date:	12/13/85
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	

Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MINTO CONSTRUCTION LTD.***
MERIVALE RD. NEPEAN CITY ON

Database: ***CA***

Certificate #: 3-0874-85-006
Application Year: 85
Issue Date: 8/14/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MINTO CONSTRUCTION LTD.***
MERIVALE RD. EAST SIDE NEPEAN CITY ON

Database: ***CA***

Certificate #: 7-0594-85-006
Application Year: 85
Issue Date: 7/25/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TONY GRAHAM MOTORS (1980) LIMITED***
MERIVALE RD. (SWM) NEPEAN CITY ON

Database: ***CA***

Certificate #: 3-1310-97-
Application Year: 97
Issue Date: 10/3/1997
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF OTTAWA-CARLETON***
BASELINE ROAD EXTENSION (SWM) OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-0701-96-

Application Year: 96
Issue Date: 9/4/1996
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***LONDON LIFE INS. CO. & BESNER VERED (198***
LOT N,CON.A/RIDEAU FRONT OTTAWA ON

Database: ***CA***

Certificate #: 3-1042-98-
Application Year: 98
Issue Date: 8/20/1998
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***SHELL CANADA PRODUCTS LIMITED***
MERIVALE RD., BULK TANK FARM NEPEAN CITY ON

Database: ***CA***

Certificate #: 4-0099-91-
Application Year: 91
Issue Date: 11/14/1991
Approval Type: Industrial wastewater
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: MODIFY OIL/WATER SEPARATOR
Contaminants:
Emission Control:

Site: ***JAMES STEWART***
MERIVALE RD. NEPEAN CITY ON

Database: ***CA***

Certificate #: 7-1585-88-
Application Year: 88
Issue Date: 10/6/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***City of Nepean***
MERIVALE RD./S.W.MGT NEPEAN CITY ON

Database: ***CA***

Certificate #: 3-1378-92-
Application Year: 92
Issue Date: 11/30/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MID CANADA CONSTRUCTION LTD.***
ACESS RD. W. OF MERIVALE RD. NEPEAN CITY ON

Database: ***CA***

Certificate #: 3-0198-89-
Application Year: 89
Issue Date: 2/17/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***JAMES STEWART***
MERIVALE RD. STEWART FUELS NEPEAN CITY ON

Database: ***CA***

Certificate #: 3-1845-88-
Application Year: 88
Issue Date: 10/6/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF OTTAWA-CARLETON***
MERIVALE RD. RECONT. WOODFIELD NEPEAN CITY ON

Database: ***CA***

Certificate #: 3-0317-88-
Application Year: 88
Issue Date: 3/17/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:

Project Description:
Contaminants:
Emission Control:

Site: ***J. PEREZ CONSTRUCTION LTD.***
MERIVALE RD. NEPEAN CITY ON

Database: ***CA***

Certificate #: 3-1266-86-
Application Year: 86
Issue Date: 9/10/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BELL-NORTHERN RESEARCH LIMITED***
BASELINE ROAD NEPEAN CITY ON

Database: ***CA***

Certificate #: 8-4088-88-
Application Year: 88
Issue Date: 8/17/1989
Approval Type: Industrial air
Status: Underwent 1st revision in 1989
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: FUME HOOD
Contaminants:
Emission Control: No Controls

Site: ***RON ENGINEERING & CONSTRUCTION LTD.***
BASELINE RD. OTTAWA CITY ON

Database: ***CA***

Certificate #: 8-4052-87-
Application Year: 87
Issue Date: 6/19/1987
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: FUMEHOOD
Contaminants:
Emission Control:

Site:
Merivale Road Nepean ON

Database: ***CA***

Certificate #: 0030-4N8JQX
Application Year: 00
Issue Date: 8/17/00
Approval Type: Municipal & Private water
Status: Approved

Application Type: New Certificate of Approval
Client Name: Corporation of the Regional Municipality of Ottawa-Carleton
Client Address: 111 Lisgar Street
Client City: Ottawa
Client Postal Code: K2P 2L7
Project Description: Installation of watermains on Merivale Road, Boyce Street
Contaminants:
Emission Control:

Site: ***Canadian Tire Real Estate Limited***
Ottawa ON

Database: ***CA***

Certificate #: 8928-6XKJW9
Application Year: 2007
Issue Date: 2/12/2007
Approval Type: Industrial Sewage Works
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Canadian Tire Real Estate Limited***
Ottawa ON

Database: ***CA***

Certificate #: 6332-769QGX
Application Year: 2007
Issue Date: 8/21/2007
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Petro-Canada***
Ottawa ON

Database: ***CA***

Certificate #: 5607-79YMZ8
Application Year: 2008
Issue Date: 2/12/2008
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Ottawa-Carleton District School Board***
Ottawa ON

Database: ***CA***

Certificate #: 3668-7ZNLYJ
Application Year: 2010
Issue Date: 2/11/2010
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Canadian Tire Real Estate Limited***
Ottawa ON

Database: ***CA***

Certificate #: 2877-73WH5F
Application Year: 2007
Issue Date: 6/7/2007
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Loblaw Companies Limited***
Ottawa ON

Database: ***CONV***

File No: 097267
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Location:
Region:
Ministry District:
Description: On April 19, 2011, Loblaw Companies Limited/Les Compagnies Loblaw Limitee pleaded guilty to one violation under the Environmental Protection Act for causing the discharge of a refrigerant into the air within a building or into the natural environment. The Court heard that the company owns and operates a property in Ottawa. The company uses a refrigeration contractor to install, maintain and service the equipment at this location. During such work, a release of refrigerant was reported to the ministry. The release was inside a building that was vented via exhaust fans to the natural environment. The refrigerant contains hydrochlorofluorocarbon and is considered an ozone depleting substance. The company was charged following an investigation by the ministry's Investigations and Enforcement Branch. The company was fined $30,000 plus a victim fine surcharge and was given 30 days to pay the fine.
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section:
Act/Regulation/Section: EPA

Date of Offence:
Date of Conviction:
Date Charged: April 19, 2011
Charge Disposition: fine, victim fine surcharge
Fine: $30,000
Synopsis:

Site: ***Petro-Canada Inc.***
Ottawa ON L6L 6N5

Database: ***ECA***

Approval No: 4810-4UMJP8
Approval Date: 2001-03-12
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Petro-Canada Inc.
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7825-4UCP9D-14.pdf
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Ashcroft Developments Inc.***
Draft Plan 06T-99003-Clyde Avenue Holdings Ottawa ON K2E 1A9

Database: ***ECA***

Approval No: 5670-4JQJJQ
Approval Date: 2000-04-27
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Business Name: Ashcroft Developments Inc.
Address: Draft Plan 06T-99003-Clyde Avenue Holdings
Full Address:
Full PDF Link:
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA***
ON

Database: ***ECA***

Approval No: R-003-3534187580
Approval Date: 2015-10-26
Status: Registered
Record Type:
Link Source:
SWP Area Name:
Approval Type:
Project Type: Heating System
Business Name: WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA
Address: 2277 RIVERSIDE OTTAWA
Full Address:
Full PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2017482
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA***
ON

Database: ***ECA***

Approval No: R-003-4538650974
Approval Date: 2015-11-12
Status: Registered

MOE District:
City:
Longitude:

Record Type:
Link Source:
SWP Area Name:
Approval Type:
Project Type: Heating System
Business Name: WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA
Address: 450 TERMINAL OTTAWA
Full Address:
Full PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2017799
PDF Site Location:
Latitude:
Geometry X:
Geometry Y:

Site: ***Ashcroft Developments Inc.***
Draft Plan 06T-99003-Clyde Avenue Holdings Ottawa ON K2E 1A9

Database: ***ECA***

Approval No: 3108-4JQJ6L
Approval Date: 2000-04-27
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Ashcroft Developments Inc.
Address: Draft Plan 06T-99003-Clyde Avenue Holdings
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1427-4J9PY2-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Canadian Tire Real Estate Limited***
Ottawa ON M4P 2V8

Database: ***ECA***

Approval No: 2877-73WH5F
Approval Date: 2007-06-07
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Canadian Tire Real Estate Limited
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1011-73VQQQ-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site:
Baseline Rd Ottawa ON

Database: ***EHS***

Order No: 20051017031
Status: C
Report Type: Site Report
Report Date: 10/18/2005
Date Received: 10/17/2005
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: QC
Search Radius (km): 0.25
X:
Y:

Site: ***Carmelo Idone***
Rear Merivale Rd. Ottawa ON K1Z 6A5

Database: ***GEN***

Generator Info

Generator No:	ON5601283	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	531120
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	LESSORS OF NON-RESIDENTIAL BUILDINGS (EXCEPT MINI-WAREHOUSES)		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Site: ***7770251 CANADA INC***
MERIVALE ROAD OTTAWA ON

Database: ***GEN***

Generator Info

Generator No:	ON6163455	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	812320
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)		

Waste Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

Site: ***Sheridan Garage***
w s Merivale rd Ottawa ON

Database: ***HBAR***

Province:	ON
Year:	1941
Source:	Mights

Site: ***City View Garage***
w s Merivale rd Ottawa ON

Database: ***HBAR***

Province:	ON
Year:	1936
Source:	Mights

Site: ***Pinecrest Texaco Service Station***
N S Baseline Rd Ottawa ON

Database: ***HBAR***

Province:	ON
Year:	1960
Source:	Mights

Site: ***Imperial Oil Ltd***
Ottawa ON

Database: ***HBAR***

Province: ON
Year: 1960
Source: Mights

Site: ***City View Garage***
w s Merivale rd Ottawa ON

Database: ***HBAR***

Province: ON
Year: 1931
Source: Mights

Site: ***City View Garage***
w s Merivale rd Ottawa ON

Database: ***HBAR***

Province: ON
Year: 1941
Source: Mights

Site: ***Sheridan Garage***
w s Merivale rd Ottawa ON

Database: ***HBAR***

Province: ON
Year: 1936
Source: Mights

Site: ***CJOH TV***
BOX 5813; MERIVALE DEPOT OTTAWA ON K2C 3G6

Database: ***NPCB***

Company Code: O3263
Industry: Telephone/Telecommunication
Site Status:
Transaction Date: 5/6/1993
Inspection Date: 3/30/1993

Site: ***SHELL CANADA PRODUCTS LTD***
MERIVALE RD OTTAWA ON

Database: ***PRT***

Location ID: 11000
Type: retail
Expiry Date: 1995-12-31
Capacity (L): 8280000
Licence #: 0022412017

Site: ***Corporation of the City of Ottawa***
Lot 30, Concession 2RF, City of Ottawa (formerly City of Nepean) CITY OF OTTAWA ON

Database: ***PTTW***

EBR Registry No: IA03E1588
Ministry Ref No: ER-0743-5SBP7D
Notice Type: Instrument Decision
Section:
Notice Stage:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (OWRA s. 34) - Permit to Take Water
Off Instrument Name:
Posted By:
Company Name: Corporation of the City of Ottawa

Decision Posted:
Exception Posted:
Bulletin Posted:
Appeal Posted:
Notice Date: February 19, 2004
Proposal Date: November 10, 2003
Year: 2003

Site Address:
Location Other:
Proponent Name:
Proponent Address: 1595 Telesat Court, Ottawa Ontario, K1G 3V5
Comment Period:
URL:
Summary:

Site Location Details:

Lot 30, Concession 2RF, City of Ottawa (formerly City of Nepean) CITY OF OTTAWA

Site: ***CANADIAN TIRE PIT STOP & PROPANE***
OTTAWA ON K2H 5Z2

Database: ***RST***

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone: 6138299488
List Name:
Description:

Site: ***CANADIAN TIRE PIT STOP & PROPANE***
OTTAWA ON K2H5Z2

Database: ***RST***

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone: 6138299488
List Name:
Description:

Site: ***PETRO CANADA***
NEPEAN ON K2J4G5

Database: ***RST***

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 6138438637
List Name:
Description:

Site: ***City of Ottawa***
CLYDE AVE NORTH OF MERIVALE RD<UNOFFICIAL> Ottawa ON

Database: ***SPL***

Ref No: 7104-5XGQVH
Year:
Incident Dt: 3/27/2004
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/27/2004
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Ottawa
Nearest Watercourse:
Site Name: CLYDE AVE NORTH OF MERIVALE RD<UNOFFICIAL>
Site Address:
Site Region: Eastern
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Chemical
Impact to Health:
Agency Involved:

Easting:
Entity Operating Name:
Client Name: City of Ottawa
Client Type:
Source Type:
Incident Cause: Pipe Or Hose Leak
Incident Preceding Spill:
Incident Reason: Unknown - Reason not determined
Incident Summary: OC Transpo - Antifreeze to Storm Sewer
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 2 L
Contaminant Qty 1:
Contaminant Unit: L
Contaminant Code: 24
Contaminant Name: ETHYLENE GLYCOL (ANTIFREEZE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Water
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Spill to Inland Watercourses
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***Esso Petroleum Canada, A Division of Imperial Oil Limited***
Nepean Ottawa ON

Database: ***SPL***

Ref No: 0874-78WNRU
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/13/2007
Dt Document Closed: 11/16/2007
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 1961 Merivale Rd<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Esso Petroleum Canada, A Division of Imperial Oil Limited
Client Type:
Source Type:
Incident Cause: Pipe Or Hose Leak
Incident Preceding Spill:
Incident Reason: Equipment Failure

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Oil
Impact to Health:
Agency Involved:

Incident Summary: Errentom Tanklines - 8L diesel to grd
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: soil contamiination
Contaminant Qty: 8 L
Contaminant Qty 1: 8
Contaminant Unit: L
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Tank Truck
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***PETRO-CANADA***
TANK TRUCK (CARGO) NEPEAN CITY ON

Database: ***SPL***

Ref No: 120683
Year:
Incident Dt: 11/11/1995
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/11/1995
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: NEPEAN CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: UNKNOWN
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: PETRO-CANADA TANK TRUCK- 50L GAS TO CONCRETE.DRIVRERROR.CLEANED.NO ENV IMP.
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:

Municipality No: 20104
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***PETRO-CANADA***
BULK PLANT/TERMINAL NEPEAN CITY ON

Database: ***SPL***

Ref No: 24453
Year:
Incident Dt: 8/29/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/29/1989
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: NEPEAN CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: CONTAINER OVERFLOW
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: PETRO CANADA - 315L GAS TO GROUND WHILE FILLING TANKER
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:

Municipality No: 20104
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***PETRO-CANADA***
SERVICE STATION OTTAWA CITY ON

Database: ***SPL***

Ref No:	30833	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	2/12/1990	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2/12/1990	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: OTHER CONTAINER LEAK
Incident Preceding Spill:
Incident Reason: CORROSION
Incident Summary: PETRO CANADA SERVICE STN.FURANCE OIL LEAK.
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:

Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***IMPERIAL OIL***
TANK TRUCK (CARGO) NEPEAN CITY ON

Database: ***SPL***

Ref No:	35439	***Municipality No:***	20104
Year:		***Nature of Damage:***	
Incident Dt:	5/29/1990	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	5/29/1990	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: NEPEAN CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: CONTAINER OVERFLOW
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: IMPERIAL OIL - 10 L GASO- LINE TO CONCRETE. CLEAN UP COMPLETED.
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***LOBLAWS***
OTTAWA CITY ON

Database: ***SPL***

Ref No:	49925	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	5/1/1991	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	5/1/1991	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	OTTAWA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Incident Reason:	OVERSTRESS/OVERPRESSURE		
Incident Summary:	LOBLAWS - HYDRAULIC OIL TO GROUND AND CATCHBASIN FROM BROKEN HOSE		
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Water course or lake		
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			
Source Sector Type:			
Conservtn Auth Name:			
Primary Watershed:			
Quaternary Watershed:			
Offsite Impacts:			
Waterbody Impacted:			

Site: ***TRANSPORT TRUCK***
FROM CLYDE AVE/MERIVALE RD TO KIRKWOOD/ MERIVALE IN NEPEAN. MOTOR VEHICLE (OPERATING FLUID)
OTTAWA CITY ON

Database: ***SPL***

Ref No:	86219	***Municipality No:***	20101
Year:		***Nature of Damage:***	
Incident Dt:	5/29/1993	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	5/29/1993	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			

MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: LAIDLAW WASTE- HYDRAULIC OIL FROM GARBAGE TRUCK TOASPHALT ALONG MERIVALE RD
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***NATIONAL GROCERIES COMPANY LTD***
OTTAWA ON

Database: ***SPL***

Ref No: 188079
Year:
Incident Dt: 10/6/2000
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/6/2000
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:

Municipality No: 20107
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site Municipality: OTTAWA
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: OTHER CAUSE (N.O.S.)
Incident Preceding Spill:
Incident Reason: OTHER
Incident Summary: NATIONAL GROCERS, OTTAWA DIESEL FL. FROM TRUCK CONTAINED , NO SEWERS
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***PETRO-CANADA***
BULK PLANT/TERMINAL NEPEAN CITY ON

Database: ***SPL***

Ref No: 133026
Year:
Incident Dt: 10/15/1996
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/15/1996
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: NEPEAN CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:

Municipality No: 20104
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: MCCR

Client Name:
Client Type:
Source Type:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: PETRO-CANADA - 5 L OF DIESEL FUEL TO PAVEMENT AT LOADING DOCK.
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact: Other
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***Loblaw Properties Limited***
Loblaws Ottawa ON

Database: ***SPL***

Ref No: 2287-7FNKE6
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/16/2008
Dt Document Closed: 9/8/2008
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Ottawa
Nearest Watercourse:
Site Name: Loblaws
Site Address:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Entity Operating Name:
Client Name: Loblaw Properties Limited
Client Type:
Source Type:
Incident Cause: Discharge or Emission to Air
Incident Preceding Spill:
Incident Reason: Equipment Failure - Malfunction of system components
Incident Summary: Loblaws, 625 lb of R22 released to atmosphere.
Environment Impact: Not Anticipated
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: 625 lb
Contaminant Qty 1: 625
Contaminant Unit: lb
Contaminant Code: 38
Contaminant Name: FREON R-22 (CFC)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***Database:*** ***WWIS***
con A ON

Well ID: 1532634
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Abandoned-Supply
Water Type:
Casing Material:
Audit No: 235222
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 01/17/2002
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4006
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: A
Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10523763
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/05/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Supplier Comment:

Method of Construction & Well Use

Method Construction ID: 961532634
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11072333
Casing No: 1
Comment:
Alt Name:

Site: ***Database:*** ***WWIS***
con 2 ON

Well ID: 1529331
Construction Date:
Use 1st: Commerical
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 169510
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 02/14/1997
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6844
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 02
Concession Name: OF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10050867
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/18/1996
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931072415
Layer: 2
Color: 2

General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 91
Material 2 Desc: WATER-BEARING
Material 3:
Material 3 Desc:
Formation Top Depth: 2.0
Formation End Depth: 19.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931072414
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 02
Material 2 Desc: TOPSOIL
Material 3: 01
Material 3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114304
Layer: 1
Plug From: 0.0
Plug To: 5.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114305
Layer: 2
Plug From: 5.0
Plug To: 19.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961529331
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10599437
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930088796
Layer: 1

Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	19.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	933326679
Layer:	1
Slot:	010
Screen Top Depth:	9.0
Screen End Depth:	19.0
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	933489270
Layer:	1
Kind Code:	5
Kind:	Not stated
Water Found Depth:	9.0
Water Found Depth UOM:	ft

Site:
con 2 ON

Database:
WWIS

Well ID:	1529332	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Commerical	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Observation Wells	***Date Received:***	02/14/1997
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	169509	***Contractor:***	6844
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	02
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	10050868	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	12/18/1996	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931072417
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 91
Material 2 Desc: WATER-BEARING
Material 3:
Material 3 Desc:
Formation Top Depth: 2.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931072416
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 02
Material 2 Desc: TOPSOIL
Material 3: 01
Material 3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114306
Layer: 1
Plug From: 0.0
Plug To: 3.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114307
Layer: 2
Plug From: 3.0
Plug To: 15.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961529332
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID:	10599438
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930088797
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	15.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	933326680
Layer:	1
Slot:	010
Screen Top Depth:	5.0
Screen End Depth:	15.0
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	933489271
Layer:	1
Kind Code:	5
Kind:	Not stated
Water Found Depth:	10.0
Water Found Depth UOM:	ft

Site:
con 2 ON

Database:
WWIS

Well ID:	1529333	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Commerical	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Observation Wells	***Date Received:***	02/14/1997
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	169508	***Contractor:***	6844
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	02
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID: 10050869
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/18/1996
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931072419
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 91
Material 2 Desc: WATER-BEARING
Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931072418
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 01
Material 3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114308
Layer: 1
Plug From: 0.0
Plug To: 5.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114310
Layer: 3
Plug From: 7.0

Plug To:	18.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933114309
Layer:	2
Plug From:	5.0
Plug To:	7.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	961529333
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10599439
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930088798
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	18.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	933326681
Layer:	1
Slot:	010
Screen Top Depth:	8.0
Screen End Depth:	18.0
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	933489272
Layer:	1
Kind Code:	5
Kind:	Not stated
Water Found Depth:	15.0
Water Found Depth UOM:	ft

Site:
con 2 ON

Database:
WWIS

Well ID: 1529560 ***Flowing (Y/N):***

Construction Date:
Use 1st: Commerical
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 169523
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 08/12/1997
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6844
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 02
Concession Name: OF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10051095
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 03/06/1997
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931073138
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 81
Material 2 Desc: SANDY
Material 3: 01
Material 3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931073139
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 12
Material 2 Desc: STONES

Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 12.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114574
Layer: 3
Plug From: 5.0
Plug To: 12.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114573
Layer: 2
Plug From: 3.0
Plug To: 5.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114572
Layer: 1
Plug From: 0.0
Plug To: 3.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961529560
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10599665
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930089190
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 12.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933326719
Layer: 1

Slot: 010
Screen Top Depth: 8.0
Screen End Depth: 13.0
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 933489562
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 8.0
Water Found Depth UOM: ft

Site:
con 2 ON

Database: ***WWIS***

Well ID: 1529561
Construction Date:
Use 1st: Commerical
Use 2nd: Municipal
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 169526
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 08/12/1997
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6844
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 02
Concession Name: OF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10051096
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/05/1997
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931073140
Layer: 1
Color: 6
General Color: BROWN

Material 1: 05
Material 1 Desc: CLAY
Material 2: 81
Material 2 Desc: SANDY
Material 3: 01
Material 3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931073141
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114575
Layer: 1
Plug From: 0.0
Plug To: 2.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114576
Layer: 2
Plug From: 2.0
Plug To: 4.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114577
Layer: 3
Plug From: 4.0
Plug To: 15.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961529561
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10599666

Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930089191
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 15.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933326720
Layer: 1
Slot: 010
Screen Top Depth: 5.0
Screen End Depth: 15.0
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 933489563
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 8.0
Water Found Depth UOM: ft

Site:
con 2 ON

Database:
WWIS

Well ID: 1529562
Construction Date:
Use 1st: Commerical
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 169530
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 08/12/1997
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6844
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 02
Concession Name: OF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10051097
DP2BR:
Spatial Status:

Elevation:
Elevrc:
Zone: 18

Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/04/1997
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931073143
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931073142
Layer: 1
Color: 6
General Color: BROWN
Material 1: 34
Material 1 Desc: TILL
Material 2: 81
Material 2 Desc: SANDY
Material 3: 11
Material 3 Desc: GRAVEL
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114578
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114579
Layer: 2
Plug From: 1.0
Plug To: 3.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933114580
Layer: 3
Plug From: 3.0
Plug To: 10.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961529562
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10599667
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930089192
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 10.0
Casing Diameter: 1.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933326721
Layer: 1
Slot: 010
Screen Top Depth: 5.0
Screen End Depth: 10.0
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.0

Water Details

Water ID: 933489564
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 8.0
Water Found Depth UOM: ft

Site:
con 1 ON

Database: ***WWIS***

Well ID: 1528855
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 02/21/1996

Water Type:
Casing Material:
Audit No: 135092
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Selected Flag: TRUE
Abandonment Rec:
Contractor: 6629
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 01
Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10050391
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/27/1995
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931071018
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 81
Material 2 Desc: SANDY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931071020
Layer: 3
Color: 2
General Color: GREY
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 55.0
Formation End Depth: 94.0

Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931071021
Layer: 4
Color: 2
General Color: GREY
Material 1: 18
Material 1 Desc: SANDSTONE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 94.0
Formation End Depth: 103.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931071019
Layer: 2
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 25.0
Formation End Depth: 55.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961528855
Method Construction Code: 4
Method Construction: Rotary (Air)
Other Method Construction:

Pipe Information

Pipe ID: 10598961
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930088072
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 58.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 991528855
Pump Set At:
Static Level: 30.0
Final Level After Pumping: 65.0
Recommended Pump Depth: 90.0
Pumping Rate: 10.0
Flowing Rate:
Recommended Pump Rate: 8.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method:
Pumping Duration HR: 1
Pumping Duration MIN: 15
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934658544
Test Type: Draw Down
Test Duration: 45
Test Level: 65.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934907069
Test Type: Draw Down
Test Duration: 60
Test Level: 65.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934105744
Test Type: Draw Down
Test Duration: 15
Test Level: 60.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934389369
Test Type: Draw Down
Test Duration: 30
Test Level: 65.0
Test Level UOM: ft

Water Details

Water ID: 933488725
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 97.0
Water Found Depth UOM: ft

Water Details

Water ID: 933488726
Layer: 3
Kind Code: 1
Kind: FRESH

Water Found Depth: 103.0
Water Found Depth UOM: ft

Water Details

Water ID: 933488724
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 85.0
Water Found Depth UOM: ft

Site:
con 1 ON

Database: ***WWIS***

Well ID: 1532635
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Abandoned-Quality
Water Type:
Casing Material:
Audit No: 235219
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 01/17/2002
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4006
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 01
Concession Name: OF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10523764
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/05/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Method of Construction & Well Use

Method Construction ID: 961532635
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11072334

Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database: ***WWIS***

Well ID: 1534064
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 248010
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 09/09/2003
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1119
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 01
Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10543179
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 08/12/2003
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Method of Construction & Well Use

Method Construction ID: 961534064
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 11091749
Casing No: 1
Comment:
Alt Name:

Site:
lot 30 con 2 ON

Database: ***WWIS***

Well ID: 7488502

Flowing (Y/N):

Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	10/15/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z434893	***Contractor:***	7241
Tag:	A399984	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	030
Depth to Bedrock:		***Concession:***	02
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010462355	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	441347.00
Code OB Desc:		***North83:***	5025119.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	07/14/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site: ***Database:*** ***WWIS***

lot N con A ON

Well ID:	7488296	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	10/09/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z433735	***Contractor:***	1844
Tag:	A388722	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	N
Depth to Bedrock:		***Concession:***	A
Well Depth:		***Concession Name:***	OF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010444541	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18

Code OB:		***East83:***	443718.00
Code OB Desc:		***North83:***	5024850.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/12/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site:

con A ON

Database: ***WWIS***

Well ID:	1527904	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Not Used	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Abandoned-Supply	***Date Received:***	04/26/1994
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	143953	***Contractor:***	6841
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	A
Well Depth:		***Concession Name:***	RF
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	10049459	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:		***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Method of Construction & Well Use

Method Construction ID:	961527904
Method Construction Code:	0
Method Construction:	Not Known
Other Method Construction:	

Pipe Information

Pipe ID: 10598029
Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database:
WWIS

Well ID: 1528250
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 151799
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 10/24/1994
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6844
Form Version: 1
Owner:
County: OTTAWA-CARLETON
Lot:
Concession: 01
Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10049789
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/11/1994
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931069085
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 78
Material 3 Desc: MEDIUM-GRAINED
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931069086
Layer: 2
Color: 6
General Color: BROWN
Material 1: 08
Material 1 Desc: FINE SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933113108
Layer: 1
Plug From: 1.0
Plug To: 4.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933113109
Layer: 2
Plug From: 4.0
Plug To: 5.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933113110
Layer: 3
Plug From: 5.0
Plug To: 10.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 961528250
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10598359
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930087025
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 10.0

Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933326510
Layer: 1
Slot: 100
Screen Top Depth: 5.0
Screen End Depth: 10.0
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 933487871
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 7.0
Water Found Depth UOM: ft

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Oct 2025

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-May 2025

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Apr 30, 2025

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2023

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Apr 30, 2025

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Nov 2025

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Aug 2025

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Dec 31, 2025

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database (ODHD) is offered by the Province of Ontario's Ministry of Mines. The dataset contains information for over 164,000 percussion, overburden, sonic and diamond-drill holes. The presence of assay results with cutoff values for gold, silver, copper, zinc, lead, nickel and platinum group elements is noted. Drill hole data are compiled from assessment files that have been submitted to the ministry in accordance with the Ontario Mining Act (OMA). Source assessment file numbers are captured for cross reference with the Ontario Assessment File Database (OAFD). Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Jul 2025

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011 - Jan 31, 2026

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Dec 31, 2025

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011 - Jan 31, 2026

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Nov 30, 2025

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Offenders Registry: Federal EOR

The Environmental Offenders Registry, enforced by Environment and Climate Change Canada and Parks Canada, tracks corporations convicted under specific federal environmental laws. The registry includes corporate convictions resulting from court proceedings. Court prosecutions are one of several enforcement measures used when violations or potential violations are detected. Other measures like tickets, warning letters, or compliance orders may also be employed to restore compliance. Although not affected by the Environmental Enforcement Act, convictions obtained by Environment and Climate Change Canada under the Species at Risk Act and the Pollution Prevention Provisions of the Fisheries Act are also included.

Government Publication Date: Nov 30, 2025

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment, Conservation and Parks (MECP). These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2024

Excess Soil Registry: Provincial ESNR

The Excess Soil Registry is made available by the Resource Productivity and Recovery Authority (RPRA). Excess soil is soil dug up mainly during construction and excavation activities that must be removed from the development site because it cannot or will not be reused. The Minister of the Environment, Conservation and Parks directed the RPRA to establish and maintain the Excess Soil Registry, enabling regulated parties to comply with registration and filing notice requirements, the ministry to access data, and the public to view information from those filings. From January 1, 2023, construction and development project leaders, as well as operators and owners of soil Reuse Sites, and Residential Development Soil Depot sites, must file notices detailing how excess soil is reused and disposed of in compliance with Ontario's Excess Soil Regulation.

Government Publication Date: Aug 31, 2025

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Oct 2025

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: Oct 31, 2021

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. As of January 1, 2023, businesses and institutions subject to the amended Reg. 347: General – Waste Management are required to report their activities and pay fees through Resource Productivity & Recovery Authority (RPRA) online Hazardous Waste Program Registry (HWPR) rather than the Hazardous Waste Information Network (HWIN) system previously operated by the Ministry of the Environment, Conservation and Parks (MECP). Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Mar 31, 2025

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Feb 2025

Historical Business Activity Risk: Federal HBAR

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this list does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including BC Directories, Hendersons, Mights, Sun Directories, Vernons, and Wrights; spanning roughly 1920s through 1960 depending on information available by city.

This list is currently limited to sites as reported in the following provinces: Alberta, British Columbia, Saskatchewan, Manitoba, New Brunswick, Nova Scotia, Ontario, and Quebec.

Government Publication Date: 1920s - 1960

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2025

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment Conservation and Parks (MECP) provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act. MECP publicly releases the Environmental Compliance Report (ECR) on the Ontario Data Catalogue. In Ontario, all facilities with regulated wastewater discharges or air emissions under the Ontario Water Resources Act and the Environmental Protection Act must monitor and report any cases where approved operating limits have been exceeded.

Government Publication Date: Dec 31, 2024

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Nov 30, 2025

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

Notice of Contamination List: Federal NOC

This dataset contains Notice of Contamination (NOC) submissions reported to the Canada Energy Regulator (CER), including the most recent annual update information where applicable. Regulated companies are required to submit an NOC when contamination is identified or encountered during any phase of a facility's lifecycle and confirmed through analytical sampling, or when contamination resulting from an incident cannot be remediated within 12 weeks of being reported to the CER. Blank values in the Annual Update Year and annual update fields indicate that the site has achieved remediation closure, has been identified as third-party contamination, or was reported recently and does not yet require an annual update.

Government Publication Date: Nov, 2025

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Feb 2024

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Dec 31, 2025

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the Ministry of Natural Resources (MNR) handed over to the Ontario Oil, Gas and Salt Resources (OGSR) Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database includes well owner/operator, location, permit issue date, and well cap date, license number, status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provided for each well record.

Government Publication Date: 1800-May 2025

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Dec 31, 2025

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011 - Jan 31, 2026

Ontario PFAS Spills: Provincial PFAS

This specific list of spills includes those incidents where one or more of the listed contaminants are identified in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA), is originally sourced from the Ministry of the Environment, Conservation and Parks spills related data. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Jun 2024; Aug 2024; Oct-Nov 2024

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Feb 2024

Potential PFAS Handlers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Feb 2024

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Potential PFAS Handlers from EASR: Provincial PPHA

The Ontario Environmental Activity and Sector Registry (EASR), described in Ontario Regulation 245/11, allows businesses with less complex operations - and hence not requiring an Environmental Compliance Approval - to register their activities with the Ontario Ministry of the Environment, Conservation and Parks (MECP). This list of potential PFAS handlers includes those EASR facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used.

Government Publication Date: Jun 30, 2024

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Dec 31, 2025

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004 - 31 Jan, 2026

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Apr 30, 2025

Scott's Manufacturing Directories: Private SCT

Scott's Directories is a data bank containing information on various manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, applicable NAICS Codes, and product categories are included in this database.

Government Publication Date: 1992-Mar 2011; Feb 2025

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Dec 2025

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2023

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2024

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011 - Jan 31, 2026

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Waste Management Site: Provincial WMS

This data contains Waste Disposal Site types collected by the Ministry of Natural Resource (MNR). The new data class brings over data from the Waste Management Information System (WMIS), which is an MS Access based database used by MNR to track Waste Management Sites. This was married with the spatial data from Waste Disposal Sites where possible. Different Waste Disposal Site types collected by the Ministry of Natural Resources include: compost disposal, hazardous waste disposal, household waste disposal, industrial waste disposal, septic drying bed, septic field, sewage disposal, tile bed, and transfer station. The data is currently under development, meaning the data is currently in the process of being created by the MNR.

Government Publication Date: April 30, 2025

Water Well Information System: Provincial WWIS

This database consists of information submitted by well contractors detailing locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table. The database is provided by the Ontario Ministry of Environment, Conservation and Parks.

Government Publication Date: Jul 31, 2025

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.