August 21, 2026
File: PE7604-LET.01R

Consulting Engineers
9 Auriga Drive
Ottawa, Ontario
K2E 7T9
Tel: (613) 226-7381

Geotechnical Engineering
Environmental Engineering
Hydrogeology
Materials Testing
Building Science
Rural Development Design
Retaining Wall Design
Noise and Vibration Studies

patersongroup.ca

Ottawa Footy Sevens c/o Mathieu Fleury
500 Sandhamn Private
Ottawa, Ontario
K1T 2Z6

Attention: **Mr. Mathieu Fleury**

Subject: **Phase I – Environmental Site Assessment Update**
Part of 349 Olmstead Street
Ottawa, Ontario

Dear Sir,

Further to your request, Paterson Group (Paterson) has carried out a Phase I Environmental Site Assessment (ESA) Update for the aforementioned property. This report updates a Phase I ESA entitled, *"Phase I Environmental Site Assessment, 349 Olmstead Street, Ottawa, Ontario"* prepared by EXP Services Inc. (exp), dated May 29, 2015.

This report is intended to meet the requirements for an updated Phase I ESA, as per Ontario Regulation (O. Reg.) 153/04, as amended, and is to be read in conjunction with the 2015 report.

Site Information

The Phase I Property consists of the eastern portion of the property addressed 349 Olmstead Street in the City of Ottawa, Ontario. This property is a rectangular parcel of land with an approximate area of 2.43 ha which is currently used as a soccer field and parking lot. Refer to Figure 1 – Key Plan, following the text of this letter, for site contextual information. The Phase I Property is located in a municipally serviced area. Surrounding properties consist of primarily residential, parkland and commercial uses.

Previous Engineering Reports

The following engineering reports were reviewed as part of this assessment:

- ❑ *"Phase I Environmental Site Assessment, 349 Olmstead Street, Ottawa, Ontario" prepared by EXP Services Inc. (exp), dated May 29, 2015.*

This Phase I ESA was prepared for a larger parcel of land than the one presented in the present Phase I ESA Update. The EXP subject site generally extended from Jeanne Mance Street to the north, to McArthur Avenue to the south, and from Olmstead Street on the west to the rear of the residential dwellings off of Lacasse to the east.

The historical research completed as part of the 2015 Phase I ESA indicated that 349 Olmstead Street was developed in 1949 and had always been used for institutional purposes. The portion of 349 Olmstead Street assessed in this Phase I ESA Updated was vacant until it was developed as a sports field circa 1970. The Phase I Property has been used as a sports field since that time.

Based on the findings of the assessment, no areas of potential environmental concerns were identified with respect to the historical or recent use of the Phase I Property, and as a result no further environmental investigation was recommended.

Historical Records Update

Environment Canada

A search of the National Pollutant Release Inventory (NPRI) database was conducted as part of this assessment. The Phase I Property was not listed in the NPRI database. No records of pollutant releases were listed in the database for properties located within the Phase I Study Area.

MECP Freedom of Information (FOI)

As part of this assessment requests were submitted to the MECP Freedom of Information office on June 19, 2026, for access to any pertinent environmental records associated with the Phase I Property. A response from the MECP was received August 20th, 2026. The records returned relate to several lead exceedances in drinking water samples and a waste generator record for light fuels. All the records returned pertain to the elementary school addressed 349 Olmstead Street, located west of the Phase I Property. The activities and incidents described in these records are not considered to pose a potential environmental concern to the Phase I Property.

A copy of the FOI records package has been appended to this report.

MECP Brownfields Environmental Site Registry

A search of the MECP Brownfields Environmental Site Registry was conducted for the Phase I Property and neighbouring properties within the Phase I Study Area. No Records of Site Condition (RSCs) were filed for the Phase I Property. One RSC was identified for the property addressed 320 McArthur Avenue, located approximately 170 m southeast of the Phase Property. This RSC was filed in 2005 by Paterson Group based on Phase I, Phase II, and remediation reports. Based on the RSC 1,500 cubic meters of soil was removed from the RSC property. No groundwater was identified as having been removed or remediated. Following the remediation this property complied with the selected full depth site condition standards with non-potable groundwater, course textured soils, for commercial property use.

Based on this information, no potential environmental concerns were identified which are considered to pose a potential environmental concern to the subject site.

OMNRF Areas of Natural and Scientific Interest (ANSI)

A search for ANSI sites situated within the Phase I Study Area was conducted electronically via the Ontario Ministry of Natural Resources and Forestry (OMNRF) website as part of this assessment. A review of the available mapping information did not identify any ANSI sites situated on the Phase I Property or within the Phase I Study Area.

Technical Standards and Safety Authority (TSSA)

As part of this Phase I ESA Update, the TSSA Fuels Safety Branch in Toronto was contacted electronically to inquire about current and former fuel storage tanks for the Phase I Property as well as the neighbouring properties within the Phase I Study Area.

A response from TSSA was received on June 19, 2026. This response identified three records associated with the properties addressed 235 McArthur Avenue and 349 Olmstead Street. Each record pertains to an FS appliance which is listed as active. These records are each considered to be associated with the elementary school which is located at the same municipal addresses as the Phase I Property but geographically located a minimum of 50 m west of the Phase I Property. Based on the separation distance and the inferred groundwater flow direction to the west, the TSSA records identified are not considered to pose a potential environmental concern to the Phase I Property.

City of Ottawa Historical Land Use Inventory (HLUI) Database

As part of this assessment, a requisition form was submitted to the City of Ottawa to request information from the City's Historical Land Use Inventory (HLUI) database for any environmental records pertaining to the Phase I Property, as well as any properties situated within the Phase I Study Area. A response from the City of Ottawa was received on July 23, 2026.

The response letter from the City of Ottawa indicated that the Sewer Use Program, and Solid Waste Services had no records relating to the Phase I Property. In addition, the Ottawa Public Health Department website returned no relevant results for the Phase I Property. The Environmental Remediation Unit identified that it has copies of a 2015 Phase I ESA completed on 349 Olmstead Street by exp. The findings of this report were discussed previously in this letter. The HLUI search also returned 12 point features and 38 area features within the Phase I study area.

None of the 12 point features identified pertain to the Phase I Property. Each of these records identify either previous or existing fuel storage activities on properties located within 250m of the Phase I Property. The nearest property identified where these fuel storage activities took place is a minimum of 50m from the Phase I Property. Based on the separation distances none of the point features identified in the HLUI results are considered to pose a potential environmental concern to the Phase I Property.

None of the 38 area features identified in the HLUI response pertain to the Phase I Property. Three area records were returned pertaining to properties adjacent to the Phase I Property. An automotive stereo and accessory retailer and installer was identified at 279 McArthur Avenue. It is understood that no automotive maintenance work takes place at this location and accordingly, these activities are not considered to pose a potential environmental concern to the Phase I Property. Records relating C G Plumbing and Heating Limited and Heritage Glass were returned for the properties addressed 360 and 364 Lacasse Avenue respectively. Both of these businesses were observed to operate out of former residential dwellings and neither property was identified as having associated waste generator records in the Environmental Risk Information Services report. Based on these findings and these properties downgradient orientation with respect to the Phase I Property, neither record identified in the HLUI are considered to pose a potential environmental concern to the Phase I Property.

All remaining records are considered to be sufficiently separated from the Phase I Property so as not to pose a potential environmental concern or represent an activity that inherently does not pose a potential environmental risk to soil and/or groundwater.

A copy of the HLUI response letter, summary report, and reference map has been included in Appendix 2.

Aerial Photographs

The most recent aerial photograph reviewed as part of the 2015 Phase I ESA was taken in 2014. At that time, the Phase I Property consisted of parkland which was used as a soccer field and running track while the surrounding lands were shown to be used for a combination of residential, institutional, and commercial purposes.

A more recent aerial photograph, taken in 2025, was reviewed as part of this assessment. At the time of this photograph, no significant changes were apparent with respect to the Phase I Property. A copy of the above referenced aerial photograph has appended to this report.

Well Records

A search of the MECPs website for all drilled well records within a 250 m radius of the Phase I Property was conducted as part of this assessment. No well records were identified on the Phase I Property.

The search identified eighty well records within the Phase I Study Area. These records pertain to wells installed between 1949 and 2023. The well installed in 1949 was for household purposes however, this area has since been redeveloped with a municipally serviced residential subdivision. The remaining wells were installed between 2008 and 2023. Based on this, and the prevalence of City water infrastructure in the area, no groundwater wells for domestic consumption are considered to be in use within the Phase I Study Area. No potential environmental concerns were identified with respect to the Ontario wells records.

ERIS Database Report

A database report, prepared by ERIS (Environmental Risk Information Services Ltd.), dated June 23, 2026, was acquired and reviewed as part of this assessment. This report provides a compilation of various provincial and federal environmental related records pertaining to any properties situated within the Phase I Study Area. The complete ERIS report has been included in Appendix 2.

The ERIS report identified 153 records within 250 m of the Phase I Property. Twenty-six of these records were for previous ERIS searches.

The ERIS Report identified 4 Delisted Fuel Tank records 6 Expired Fuels Safety Facilities records and 2 Private and Retail Fuel Storage Tanks records in the Phase I Study Area. These pertain to former fuel storage tanks located in excess of 70 m south of the Phase I Property at 148 McArthur and 256 McArthur Avenue. Based on the separation distance, these former fuel storage tanks are not considered to pose a potential environmental concern to the Phase I Property.

The ERIS Report identified 27 waste generator records for properties within 250 m of the Phase I Property. None of the waste generator records identified pertained to the Phase I Property. Waste generation records on the adjacent property to the west include waste oils, lab chemicals, waste lubricants, PCBs, and light fuels which are associated with the former high school and/or existing elementary school. Records on adjacent properties to the south include photoprocessing waste, pharmaceuticals, and pathological wastes pertaining to an animal hospital. Paints, solvents, and inorganic chemicals were identified as pertaining to a plumbing company located to the east of the Phase I Property. Based on the separation distances, the nature of the wastes generated and/or their downgradient orientation with respect to the Phase I Property, these waste generator records are not considered to pose a potential environmental concern. The remaining waste generators are considered sufficiently distant from the Phase I Property so as not to pose a potential environmental concern.

The ERIS Report identified 13 Historical Business Activity Risk records for properties in the Phase I Study Area. These records each pertain to automotive service garages and/or retail fuel outlets located in excess of 60 m south of the Phase I Property. Based on the separation distance none of the activities associated with these records are considered to pose a potential environmental concern to the Phase I Property.

The ERIS report identified one TSSA Historic Incident within 250 m of the Phase I Property. This incident was a leak of approximately 90L of furnace oil at 295 Frontenac Street, approximately 125 m north of the Phase I Property. Based on the separation distance and the downgradient orientation with respect to the Phase I Property, this former leak is not considered to pose a potential environmental concern to the Phase I Property.

The ERIS Report identified 3 Pesticide records for properties in the Phase I Study Area. These records pertain to properties located 60 m east and 60 m south of the Phase I Property respectively. They are not considered to pose a potential environmental concern based on their separation distances.

The ERIS Report identified 3 Manufacturing Directories records for properties in the Phase I Study Area. These records pertain to cabinet making, stain glass manufacturing, and relay manufacturing on properties separated from the Phase I Property by 20-60 m. Based on the nature of the activities and the separation distances these former activities are not

considered to pose a potential environmental concern based on their respective separation distances.

The ERIs Report identified 5 Spills records for properties in the Phase I Study Area. The first pertains to the aforementioned furnace oil leak at 295 Frontenac Street. The second pertains to a spill of raw sewage. Two more records pertain to small quantities of diesel fuel (3L) and coolant (1L) which were spilled to City of Ottawa catch basins. The final pertains to 20L of Hydraulic oil which was spilled to asphalt at Horizon-Jeunesse Elementary School. Based on the limited volumes of each of these spills and their separation distances to the Phase I Property, none of these spills are considered to pose a potential environmental concern to the Phase I property.

All remaining records are not considered to pose a potential environmental concern based on a combination of their separation distances, downgradient orientations with respect to the subject property and/or the nature of the recorded activity.

A copy of the ERIS report is provided in Appendix 2.

Property Owner Representative Interview

Mr. Claude Robineau, Project Manager – Construction Capital Services for Conseil des Écoles Catholiques du Centre-Est (CECCE), was contacted via email to respond to questions regarding the environmental history of the Phase I Property. Mr. Robineau was previously the Maintenance Supervisor for this property between 2009 and 2022. According to Mr. Robineau, CECCE has owned this property since the early 1980's. Mr. Robineau was not aware of any former uses of the Phase I Property other than as a soccer field and running track for the adjacent elementary school (formerly high school). Mr. Robineau was not aware of any existing or historical aboveground or underground fuel storage tanks on the Phase I Property. Mr. Robineau was not aware of any spills or environmental concerns associated with the Phase I Property or any neighbouring properties.

Site Reconnaissance

A visual inspection of the Phase I Property was carried out on July 9, 2026, by personnel from Paterson's environmental division. The site inspection included a review of the current use of the subject lands as well as the adjacent properties.

At the time of the site inspection, the Phase I Property was observed to be grassed sports fields which were vacant of any buildings or structures and a parking lot. The site topography is higher on the west and slopes downward to the east to the flat sprots field.

The regional topography slopes down towards the west in the general direction of the Rideau River. Water drainage on the Phase I Property occurs via infiltration.

At the time of the site inspection, no chemical products, aboveground fuel storage tanks (ASTs), or evidence indicating the presence of any underground fuel storage tanks (USTs), were observed anywhere on the Phase I Property. No hazardous materials, unidentified substances, spills, surficial staining, abnormal odours, stressed vegetation, waste materials, or any other indications of potential sub-surface contamination were observed anywhere on the Phase I Property.

Multiple pole mounted transformers were observed immediately adjacent to the east side of the Phase I Property (off-site). These were observed to be in good condition with no signs of spills or leaking in their vicinity.

Neighbouring Properties

A visual inspection of the neighbouring properties was conducted from publicly accessible roadways at the time of the site inspection. Land use adjacent to the subject site was recorded as follows:

North:	Residential dwellings followed by Blake Boulevard and further residential dwellings.
East:	Residential dwellings followed by Lacasse Avenue and further residential dwellings.
West:	An elementary school and parklands followed by Olmstead Street and residential dwellings.
South:	Residential dwellings, an animal hospital, and an automotive vehicle accessory installer.

No potential environmental concerns were identified with respect to the current use of the neighbouring properties within the Phase I Study Area.

Conclusion

A 2015 Phase I ESA was completed for the property addressed 349 Olmstead Street. This property is a larger parcel of land that encompasses the Phase I ESA Update Property. The property addressed 349 Olmstead Street was developed in 1949 and had always been used for institutional purposes. The Phase I ESA Update property was vacant until its initial development as a sports field circa 1970. The Phase I ESA Update Property has been used as a sports field since that time.

A review of more recent environmental records, in conjunction with a visual inspection of the property, generally confirmed the information and findings contained in the 2015 Phase I ESA report completed by exp. Since that time, no significant physical changes have been made to the Phase I Property and no new potential environmental concerns were identified with respect to the use of the site or the neighbouring properties. Based on the findings of this assessment, it is our opinion that **a Phase II – Environmental Site Assessment is not required for the Phase I Property.**

Statement of Limitations

This Phase I – Environmental Site Assessment report has been prepared in general accordance with O. Reg. 153/04, as amended, and CSA Z768-01 (as amended). The conclusions presented herein are based on information gathered from a limited historical review of readily available geological, historical, and regulatory information, as well as a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as local, provincial, and federal agencies, and was limited within the scope-of-work, time, and budget of the project herein. Should any conditions be encountered at the site and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Ottawa Footy Sevens and Conseil des Écoles Catholiques du Centre-Est. Permission and notification from the above noted parties and Paterson will be required prior to the release of this report to any other party.

We trust that this submission satisfies your current requirements. Should you have any questions please contact the undersigned.

Regards,

Paterson Group Inc.

Mark Bujaki, B.Sc. MBA

Adrian Menyhart, P.Eng., QP$_{ESA}$



Attachments

- ❑ Figure 1 – Key Plan
- ❑ Aerial Image (2025)
- ❑ MECP Freedom of Information (FOI)
- ❑ TSSA Correspondence
- ❑ ERIS Report
- ❑ HLUI
- ❑ PE7604-1 - Site Plan

Report Distribution


- ❑ Ottawa Footy Sevens c/o Mathieu Fleury
- ❑ Paterson Group Inc.



FIGURE 1

KEY PLAN

PATERSON GROUP



AERIAL PHOTOGRAPH
2025

PATERSON GROUP

Ontario

Hazardous Waste Information

These are historical waste records from the Hazardous Waste Information Network (HWIN) and System (HWIS), operated by the Ministry of the Environment, Conservation, and Parks. As of January 1, 2023, Resource Productivity and Recovery Authority's (RPRA) Hazardous Waste Program Registry has replaced HWIN.

Generator Details (HWIN)

Registration/Notification Number
ON7034415

Legal Company Name

Primary Name:	Elementary School Catholic Horizon-Jeunesse	Division Name:	N/A

Company Operating Name

Primary Name:	Elementary School Catholic Horizon-Jeunesse	Division Name:	N/A

Mailing Address

Division Building:	N/A	P.O. Box:	N/A
Address Line 1:	1125 TUPPER, UNIT 1	Address Line 2:	N/A
Town/City:	HAWKESBURY	Postal/Zip Code:	K6A 3T5
County (if in ON):	PRESCOTT & RUSSELL	Province/State (if in CAN/US):	ONTARIO
County (if outside ON):	N/A	Province/State (if outside CAN/US):	N/A

Site Location

Division Building:	Elementary School Catholic Horizon-Jeunesse	P.O. Box:	N/A
Address Line 1:	349 Olmstead Street	Address Line 2:	N/A
Town/City:	Ottawa	Postal/Zip Code:	K1L 7K2
County (if in ON):	OTTAWA CARLTON (RM)	Province/State (if in CAN/US):	ONTARIO
County (if outside ON):	N/A	Province/State (if outside CAN/US):	N/A

Inactive Waste Classes (ON7034415)

No inactive waste listings.

Active Waste Classes (ON7034415)

Active Off-Site Waste Classes

Waste Class	Hazardous Waste Number (per waste stream)	Reg.347 Schedules	Disposal Method	Part 2B required	Part 2B complete	Phsyical State	Off-Site	Status
221 - L	N/A					Liquid	Off-Site	Active

Pages 2 to / à 25

are not relevant

sont non pertinentes

INCIDENT REPORT

DW System

System Name: R243 HORIZON-JEUNSSE
System Address: 349 OLMSTEAD RUE VANIER ON K1L 1B1
District Office: Ottawa District
DWS #: 500007242
DWS Category: Designated Facility

DWS Owner

Owner Name: CONSEIL DES ECOLE CATHOLIQUE DU CENTRE-EST
Owner Mailing Address: 4000 LABELLE Rue GLOUCESTER ON Canada K1J 1A1
Owner Physical Address: 4000 LABELLE RUE GLOUCESTER ON Canada K1J 1A1
Owner Phone:
Owner Fax:
Owner Email:
Client Type: SCHOOL BOARD

MECP Information

Incident Report #: 1-1CES-1
Master Incident Report #:
AWQI #: 77058
Master AWQI #:
Date & Time Reported to MECP: Dec 13, 2007 09:45:52
Office Receiving Incident Report: SAC
Incident Info Received By: SAC
Incident Type: O.Reg. 243 Lead Exceedence
Referring Inspection Report #:
Incident Summary: R243 Lead Exceedance
MECP Response: No Field Response
Date & Time MECP Arrival:
Was an ERP called out? N
IDS Reference #:

Incident Description

Incident Date	Incident Description	Created By
Dec 13, 2007 09:45:17	R243 Lead Exceedance	SADMIN
Dec 18, 2007 09:25:54	Only the standing sample exceeded the 10 ug/L standard for lead: sample taken on Dec. 12/07 yielded 39.3 ug/L lead in the standing sample. no result was provided for the flushed sample. This school is located in the same building as Ecole Vision Jeunesse and day nursery Parascolaire Quatre Saisons - see correspondance attached to this incident for details of the shared services. This school was not sampled initially as the person in charge of lead in drinking water (Luc Poulin) thought this was not necessary. Sampling was carried out after I sent him the MOE's interpretation (from eRoom) of schools & day nurseries sharing the same water service line. This incident is recommended for closure. C. Villeneuve, Dec. 18/07.	VILLENCH

Parameter Table

Sample Collection Date	Sample Location	Details	Parameter	Unit	Verbal DWS Result	Verbal Lab Result	Written DWS Result	Written Lab Result	Chlorine Residual	Result mg/L
12/12/2007 00:00:00		Standing	Lead	MG/L				0.0393		

Offences

Suspected Violation(s)/Offence(s)

Caller/PO Information

Contact Name:
Telephone #:
Email Address:
Mailing Address:

Company:
Fax Number:

Provincial Officer

Name: Christine Villeneuve
Work Unit: Drinking Water Inspections Unit
Date: July 03, 2026
Signature:

Badge #: 1048
District/Area Office: Ottawa District

Supervisor

Name: James Mahoney
Work Unit: Drinking Water Inspections Unit
Date: July 03, 2026
Signature:

District/Area Office: Ottawa District

Page 29

is not relevant

est non pertinente

INCIDENT REPORT

DW System

System Name: R243 HORIZON-JEUNSSE
System Address: 349 OLMSTEAD RUE VANIER ON K1L 1B1
District Office: Ottawa District

DWS #: 500007242
DWS Category: Designated Facility

DWS Owner

Owner Name: CONSEIL DES ECOLE CATHOLIQUE DU CENTRE-EST
Owner Mailing Address: 4000 LABELLE Rue GLOUCESTER ON Canada K1J 1A1
Owner Physical Address: 4000 LABELLE RUE GLOUCESTER ON Canada K1J 1A1
Owner Phone:
Owner Fax:
Owner Email:
Client Type: SCHOOL BOARD

MECP Information

Incident Report #: 1-3JRE-3
Master Incident Report #:
AWQI #: 106763
Master AWQI #:
Date & Time Reported to MECP: Jun 29, 2012 09:31:27
Office Receiving Incident Report: SAC
Incident Info Received By: SAC
Incident Type: O.Reg. 243 Lead Exceedence
Referring Inspection Report #:
Incident Summary: R243 Lead Exceedance
MECP Response: No Field Response
Date & Time MECP Arrival:
Was an ERP called out? N
IDS Reference #:

Incident Description

Incident Date	Incident Description	Created By
Jun 29, 2012 09:31:27	R243 Lead Exceedance	SADMIN
Jul 03, 2012 21:45:40	CP - review lab notification; please note that lab notification has facility name of Horizon Jeunesse. Standing = 13µg/L, Flushed = 7.74 µg/L	PRIMEACH
Jul 18, 2013 15:21:44	CP - Reviewed lead sampling results for Jun 12 & June 2013. all samples returned < 10 µg/L. standing varied between 0.41 - 2.25 µg/L. flushed varied between 1.28 - 1.55 µg/L. no further action required and recommend closure.	PRIMEACH

Parameter Table

Sample Collection Date	Sample Location	Details	Parameter	Unit	Verbal DWS Result	Verbal Lab Result	Written DWS Result	Written Lab Result	Chlorine Residual	Result mg/L
06/21/2012 00:00:00			Lead	MG/L				0.0130		

Offences

Suspected Violation(s)/Offence(s)

Caller/PO Information

Contact Name:
Telephone #:
Email Address:
Mailing Address:

Company:
Fax Number:

Provincial Officer

Name: Charlie Primeau
Work Unit: Drinking Water Inspections Unit
Date: July 03, 2026
Signature:

Badge #: 1420
District/Area Office: Ottawa District

Supervisor

Name: James Mahoney
Work Unit: Drinking Water Inspections Unit
Date: July 03, 2026
Signature:

District/Area Office: Ottawa District

Page 33

is not relevant

est non pertinente

INCIDENT REPORT

DW System

System Name: R243 HORIZON-JEUNSSE
System Address: 349 OLMSTEAD RUE VANIER ON K1L 1B1
District Office: Ottawa District

DWS #: 500007242
DWS Category: Designated Facility

DWS Owner

Owner Name: CONSEIL DES ECOLE CATHOLIQUE DU CENTRE-EST
Owner Mailing Address: 4000 LABELLE Rue GLOUCESTER ON Canada K1J 1A1
Owner Physical Address: 4000 LABELLE RUE GLOUCESTER ON Canada K1J 1A1
Owner Phone:
Owner Fax:
Owner Email:
Client Type: SCHOOL BOARD

MECP Information

Incident Report #: 1-5RX0-4
Master Incident Report #:
AWQI #: 123570
Master AWQI #:
Date & Time Reported to MECP: May 13, 2015 13:37:45
Office Receiving Incident Report: SAC
Incident Info Received By: SAC
Incident Type: O.Reg. 243 Lead Exceedence
Referring Inspection Report #:
Incident Summary: R243 lead exceedance
MECP Response: No Field Response
Date & Time MECP Arrival:
Was an ERP called out? N
IDS Reference #:

Incident Description

Incident Date	Incident Description	Created By
May 13, 2015 13:37:45	R243 lead exceedance	SADMIN
Apr 17, 2019 08:38:14	A flushed plumbing sample taken on May 12, 20175 showed a lead concentration of 7.79 µg/L . The standing sample showed a lead concentration of 13.2 µg/L exceeding the lead standard. The Notice of Lead Exceedance Test Results was received on May 13, 2015. The local health unit was contacted on May 13, 2015. The reporting requirements by lab have been met. The Notice of Lead Exceedance Test Results has been attached to this incident. Due to the date of this incident, no further action required at this time. Incident recommended for closure.	BOURGONKA

Parameter Table

Sample Collection Date	Sample Location	Details	Parameter	Unit	Verbal DWS Result	Verbal Lab Result	Written DWS Result	Written Lab Result	Chlorine Residual	Result mg/L
05/12/2015 00:00:00			Lead	MG/L			0.0132	0.0132		

Offences

Suspected Violation(s)/Offence(s)

Caller/PO Information

Contact Name:
Telephone #:
Email Address:
Mailing Address:

Company:
Fax Number:

Provincial Officer

Name: Karine Bourgon
Work Unit: Drinking Water Inspections Unit
Date: July 03, 2026
Signature:

Badge #:
District/Area Office: Ottawa District

Supervisor

Name: Charlie Primeau
Work Unit: Drinking Water Inspections Unit
Date: July 03, 2026
Signature:

District/Area Office: Ottawa District

Page 37

is not relevant

est non pertinente

Ontario

Ministry of the Environment, Conservation and Parks

R243 HORIZON-JEUNSSE

Inspection Report

Site Number: 500007242
Inspection Number: 1-8F1P9
Date of Inspection:

OWNER INFORMATION:

Company Name: CONSEIL DES ECOLE CATHOLIQUE DU CENTRE-EST
Street Number: 4000 **Unit Identifier:**
Street Name: LABELLE RUE
City: GLOUCESTER
Province: ON **Postal Code:** K1J 1A1

CONTACT INFORMATION

INSPECTION DETAILS:

Site Name: R243 HORIZON-JEUNSSE
Site Address: 349 OLMSTEAD Rue VANIER ON K1L 1B1
County/District: OTTAWA
MECP District/Area Office: Ottawa District
Health Unit: CITY OF OTTAWA HEALTH DEPARTMENT
Conservation Authority:
MNR Office:
Site Number: 500007242
Inspection Type: Announced
Inspection Number: 1-8F1P9
Date of Inspection:
Date of Previous Inspection:

COMPONENTS DESCRIPTION

INSPECTION SUMMARY:

NON-COMPLIANCE WITH REGULATORY REQUIREMENTS AND ACTIONS REQUIRED

This section provides a summary of all non-compliance with regulatory requirements identified during the inspection period, as well as actions required to address these issues. Further details pertaining to these items can be found in the body of the inspection report.

Not Applicable

SUMMARY OF RECOMMENDATIONS AND BEST PRACTICE ISSUES

This section provides a summary of all recommendations and best practice issues identified during the inspection period. Details pertaining to these items can be found in the body of the inspection report. In the interest of continuous improvement in the interim, it is recommended that owners and operators develop an awareness of the following issues and consider measures to address them.

Not Applicable

SIGNATURES

Inspected By: Signature: (Provincial Officer)

Reviewed & Approved By: Signature: (Supervisor)

James Mahoney

Review & Approval Date:

Note: This inspection does not in any way suggest that there is or has been compliance with applicable legislation and regulations as they apply or may apply to this facility. It is, and remains, the responsibility of the owner and/or operating authority to ensure compliance with all applicable legislative and regulatory requirements.

Mark Bujaki

From: Public Information Services <publicinformationservices@tssa.org>
Sent: June 19, 2026 11:36 AM
To: Mark Bujaki
Subject: RE: PE7604 - Records Search Request

External Email: Do not click on links or open attachments unless you trust the sender.

Hello ,

RECORD FOUND IN CURRENT DATABASE:

- We confirm that there are **fuel records** in our database of at the subject address(es).

Inventory Number	Address	City	Province	Postal Code	Reason Code	Asset Class / Inventory Contex
44603368	235 MCART	OTTAWA	ON	K1L 6P3	Active	FS Appliance
Inventory Number	**Address**	**City**	**Province**	**Postal Code**	**Reason Code**	**Asset Class / Inventory Contex**
45205038	349 OLMST	VANIER	ON	K1L 1B1	Active	FS Appliance
45205218	349 OLMST	VANIER	ON	K1L 1B1	Active	FS Appliance

***NO OTHER RECORDS FOUND IN CURRENT DATABASE FOR THIS REQUEST**

For a further search in our archives, please go to the **TSSA Client Portal** to complete an Application for Release of Public Information. Please refer to Training (tssa.org) for instructions on how to use the portal. Please refer to How to Submit a Public Information Request (tssa.org) for instructions.

The associated fee must be paid via credit card (Visa or MasterCard).

Once all steps have been successfully completed you will receive your payment receipt via email.

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.

If you have any questions or concerns, please do not hesitate to contact our Public Information Release team at publicinformationservices@tssa.org.

Kind regards,

Aleena Tahir | Public Information & Records Agent
Public Information
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1 416-734-3546 | E-Mail: ATahir@tssa.org
www.tssa.org

From: Mark Bujaki <mbujaki@Patersongroup.ca>
Sent: Friday, June 19, 2026 8:28 AM
To: Public Information Services <publicinformationservices@tssa.org>
Subject: PE7604 - Records Search Request

⚠ External Email >

[⚠ **CAUTION]:** THIS EMAIL ORIGINATED OUTSIDE THE ORGANISATION.
DO NOT CLICK LINKS OR OPEN ATTACHMENTS UNLESS YOU KNOW THE SENDER AND ARE EXPECTING THIS EMAIL. PLEASE REPORT WITH THE PHISH REPORT BUTTON IF SUSPICIONS.

Hello,

Could you please complete a search of your records for underground/aboveground storage tanks for the following addresses located in Ottawa, Ontario.
Thank you,

235 McArthur Avenue

349 Olmstead Street

340 Lacasse Avenue
344 Lacasse Avenue
350 Lacasse Avenue
352 Lacasse Avenue
354 Lacasse Avenue

308 Blake Boulevard
292 Blake Boulevard
280 Blake Boulevard

PATERSON GROUP 70
SOLUTION ORIENTED ENGINEERING

MARK BUJAKI, B.Sc., MBA
Junior Environmental Scientist
Environmental Division
OFFICE: (613) 226-7381 ext. 335
DIRECT: (613) 299-4209
9 AURIGA DRIVE
OTTAWA ON K2E 7T9
mbujaki@patersongroup.ca
www.patersongroup.ca

BUILDING TRUST THROUGH QUALITY ENGINEERING SINCE 1956
OTTAWA • GREATER TORONTO AREA • NORTHERN ONTARIO

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied,

forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

DATABASE REPORT

Project Property:	*PE7604* *PE7604* *Ottawa ON*
Project No:	*66229*
Report Type:	*Standard Report*
Order No:	*26061900032*
Requested by:	*Paterson Group Inc.*
Date Completed:	*June 23, 2026*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....20
Map.....36
Aerial.....37
Topographic Map.....38
Detail Report.....39
Unplottable Summary.....217
Unplottable Report.....218
Appendix: Database Descriptions.....220
Definitions.....231

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*PE7604* *PE7604 Ottawa ON*
Project No:	*66229*

Coordinates:

Latitude:	*45.4328273*
Longitude:	*-75.6575618*
UTM Northing:	*5,031,244.13*
UTM Easting:	*448,565.76*
UTM Zone:	*18T*

Elevation:	*196 FT* *59.88 M*

Order Information:

Order No:	*26061900032*
Date Requested:	*June 19, 2026*
Requested by:	*Paterson Group Inc.*
Report Type:	*Standard Report*

Historical/Products:

ERIS Xplorer	*ERIS Xplorer*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Within 0.25 km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	2	2
CA	Certificates of Approval	Y	0	4	4
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	4	4
EASR	Environmental Activity and Sector Registry	Y	0	0	0
EBR	Environmental Registry	Y	0	3	3
ECA	Environmental Compliance Approval	Y	0	2	2
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	0	26	26
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EOR	Environmental Offenders Registry	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
ESNR	Excess Soil Registry	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	6	6
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	0	0
FSTH	Fuel Storage Tank - Historic	Y	0	0	0
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	27	27
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0

Database	Name	Searched	Project Property	Within 0.25 km	Total
HBAR	Historical Business Activity Risk	Y	0	13	13
HINC	TSSA Historic Incidents	Y	0	1	1
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	0	0
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NOC	Notice of Contamination List	Y	0	0	0
NPCB	National PCB Inventory	Y	0	0	0
NPR2	National Pollutant Release Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory - Historic	Y	0	0	0
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	3	3
PFAS	Ontario PFAS Spills	Y	0	0	0
PFCH	NPRI Reporters - PFAS Substances	Y	0	0	0
PFHA	Potential PFAS Handlers from NPRI	Y	0	0	0
PINC	Pipeline Incidents	Y	0	2	2
PPHA	Potential PFAS Handlers from EASR	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	0	2	2
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	0	0
RST	Retail Fuel Storage Tanks	Y	0	0	0
SCT	Scott's Manufacturing Directories	Y	0	3	3
SPL	Ontario Spills	Y	0	5	5
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0

Database	Name	Searched	Project Property	Within 0.25 km	Total
VAR	***Variances for Abandonment of Underground Storage Tanks***	*Y*	*0*	*0*	*0*
WDS	***Waste Disposal Sites - MOE CA Inventory***	*Y*	*0*	*0*	*0*
WDSH	***Waste Disposal Sites - MOE 1991 Historical Approval Inventory***	*Y*	*0*	*0*	*0*
WMS	***Waste Management Site***	*Y*	*0*	*0*	*0*
WWIS	***Water Well Information System***	*Y*	*0*	*50*	*50*
		Total:	*0*	*153*	*153*

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number

No records found in the selected databases for the project property.

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	GEN	OTTAWA BOARD (SEE & USE ON0426406)	ECOLE STE. ANDR'E-LAURENDEAU 235 MCARTHUR AVENUE OTTAWA ON ***Generator No.*	*Years Reported:*** ON0375219 | 98,97,96,95,94,93,92,90,89,88,87,86	W/38.8	0.00	39
1	SPL	s.21<UNOFFICIAL>	235 McArthur Avenue Ottawa ON K1L 6P3	W/38.8	0.00	40
2	GEN	DUBROFSKY, CHERYL; HARTMAN, HARRY; HARTMAN, MARI	348 Lacasse 344 Lacasse Ottawa ON ***Generator No.*	*Years Reported:*** ON8157375 | 11	ENE/66.6	0.00	41
3	EHS		280 Blake Boulevard Vanier ON K1L 6L7	NNW/88.1	0.00	42
4	WWIS		ON ***Well ID:*** 7368895	NNE/99.6	0.00	42
5	EHS		360 Lacasse Ave Ottawa ON Vanier ON K1L 7A9	ESE/101.6	0.00	43
6	EHS		296 Blake Boulevard Vanier ON K1L 6L7	NNE/102.6	0.00	43
7	EHS		308 Blake Blvd Ottawa ON K1L6L7	NE/110.7	0.00	43
8	GEN	Zenith Solutions Inc.	380 Lacasse Avenue Ottawa ON K1L 7A9 ***Generator No.*	*Years Reported:*** ON9333174 | 22	SE/112.7	0.00	44
9	SCT	Bench Dog Cabinets	364 Lacasse Ave Vanier ON K1L6L6	SE/114.5	0.00	45
9	SCT	Heritage Glass	364 Lacasse Ave Vanier ON K1L7A9	SE/114.5	0.00	45
10	GEN	OTTAWA (SEE&USE ON1285706) 29-417	ECOLE S. CATHOLIQUE ANDRE LAURENDEAU 235 AVENUE MCARTHUR VANIER ON K1N 7G9	WSW/122.5	0.00	46

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Generator No. **|** ***Years Reported:*** ON0426406	94,93,92,90,89,88			
10	GEN	Conseil des Úcoles catholiques du Centre-Est	235 Avenue McArthur Ottawa ON	WSW/122.5	0.00	47
			Generator No. **|** ***Years Reported:*** ON2970070	12,11,10,09		
10	GEN	CONSEIL DES ECOLES CATHOLIQUES DE LANGUE	235 AVENUE MCARTHUR VANIER ON K1L 6P3	WSW/122.5	0.00	48
			Generator No. **|** ***Years Reported:*** ON1285706	04,03,02,01,00,99,98,97,96,95,94,93,92		
11	GEN	Mr Pierre Larose	353 Lacasse Vanier ON K1L 7B1	E/123.0	-0.32	51
			Generator No. **|** ***Years Reported:*** ON8134889	04,03,02		
12	GEN	Pierre Seguin In Trust	345/347 Lacasse St Ottawa ON K1L 7B1	ENE/127.1	-0.20	52
			Generator No. **|** ***Years Reported:*** ON8554009	04,03,02		
13	PINC		355 Lacasse Avenue, Ottawa ON	E/128.2	-0.32	52
14	EHS		279 Blake Blvd Vanier ON K1L 6L6	N/130.4	0.00	53
15	GEN	EASTVIEW ANIMAL HOSPITAL	261 MCARTHUR STREET VANIER ON K1L 6P3	SSW/131.4	1.00	53
			Generator No. **|** ***Years Reported:*** ON1800400	01,00,99,98,97,96,95,94,93		
16	EHS		345-347 Lacasse Avenue Ottawa ON	ENE/132.2	-0.20	55
17	GEN	Ontario Petroleum Pump	310 Blake Blvd Ottawa ON	ENE/135.2	0.00	55
			Generator No. **|** ***Years Reported:*** ON4674220	08,07		
17	GEN	Ontario Petroleum Pump	310 Blake Blvd Ottawa ON	ENE/135.2	0.00	56
			Generator No. **|** ***Years Reported:*** ON2931558	12		
17	GEN	David Bunner	310 Blake Blvd Vanier ON K1L 6L5	ENE/135.2	0.00	56
			Generator No. **|** ***Years Reported:*** ON6377726	14		
17	GEN	David Bunner	310 Blake Blvd Vanier ON K1L 6L5	ENE/135.2	0.00	57
			Generator No. **|** ***Years Reported:*** ON4971167	16,15		
18	WWIS		ON	ENE/137.5	0.00	57

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7169780			
19	WWIS		310 BLAKE BLVD. OTTAWA ON ***Well ID:*** 7170716	ENE/137.7	0.00	58
20	GEN	Vanier Animal Hospital	257 McArthur Avenue Ottawa ON K1L 6P3 ***Generator No.*** **|** ***Years Reported:*** ON001064183 | 25,24	SW/138.9	1.00	61
21	EHS		257 Mcarthur Ave Ottawa ON K1L6P3	SW/139.3	1.00	62
22	EHS		285 Blake Boulevard Vanier ON K1L 6L6	N/143.7	0.00	63
23	WWIS		310 BLAKE BLVD. OTTAWA ON ***Well ID:*** 7170715	ENE/144.6	0.00	63
24	EHS		310-316 Blake Boulevard Vanier ON K1L 6L5	ENE/145.9	0.00	66
25	WWIS		310 BLAKE BLVD. 316 Ottawa ON ***Well ID:*** 7178879	ENE/146.0	0.00	66
26	PES	PESTROY INC./DUTCH JANITORIAL SERVICES LTD.	369 LACASSE AVENUE 8036 OTTAWA ON K1G 3H6	ESE/146.0	0.00	70
26	PES	PESTROY INC./AARBRU	369 LACASSE AVENUE OTTAWA ON K1H 6S6	ESE/146.0	0.00	70
27	EHS		310-316 Blake Blvd. Ottawa ON	NE/147.1	0.00	71
28	WWIS		MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221190	S/147.6	1.00	71
29	WWIS		310 BRAKE BLVD. OTTAWA ON ***Well ID:*** 7170717	ENE/148.5	0.00	73
30	WWIS		318-316 BLAKE BOULEVARD Ottawa ON	ENE/150.9	0.00	77

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7195008			
31	WWIS		310 BLAKE BLVD OTTAWA ON ***Well ID:*** 7257961	ENE/152.9	0.00	80
32	CA	R.M. OF OTTAWA-CARLETON	LACASSE AVE./BLAKE BLVD./LEWIS VANIER CITY ON	NE/153.6	0.00	83
33	WWIS		ON ***Well ID:*** 7195009	ENE/155.0	0.00	83
34	WWIS		256 MCAURTHUR AVE. Ottawa ON ***Well ID:*** 7221188	S/159.4	1.00	84
35	BORE		ON	W/159.6	0.00	86
36	EHS		349 Olmstead St Ottawa ON K1L1B1	W/160.4	0.00	88
36	GEN	AWD Contractors	349 Olmstead Street Ottawa ON K1L 7K2 ***Generator No.*** **|** ***Years Reported:*** ON001059319 | 25,23	W/160.4	0.00	89
36	GEN	Elementary School Catholic Horizon-Jeunesse	349 Olmstead Street Ottawa ON K1L 7K2 ***Generator No.*** **|** ***Years Reported:*** ON7034415 | 21	W/160.4	0.00	89
37	WWIS		292 Blake Blvd VANIER ON ***Well ID:*** 7358212	N/160.6	0.00	90
38	EHS		309 McArthur Avenue Ottawa ON	E/160.9	-1.00	93
38	HBAR	Downtown Motor Sales	309 McArthur av Eastview ON	E/160.9	-1.00	93
38	SPL	City of Ottawa	309 McArthur Ave Ottawa ON	E/160.9	-1.00	93
39	WWIS		310 BLAKE BLVD. Ottawa ON	ENE/162.3	-0.20	94

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7122676			
40	WWIS		297 Blake Boulevard Ottawa ON ***Well ID:*** 7359571	NNE/162.5	0.00	110
41	EHS		301 McArthur Avenue Vanier ON K1L 7B1	ESE/163.2	-0.69	113
42	EHS		307 McArthur Ave. Vanier ON K1L 6P1	E/163.4	-1.00	113
43	WWIS		252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221192	SSW/165.8	1.00	114
44	WWIS		ON ***Well ID:*** 7441841	NE/167.5	0.00	116
45	WWIS		lot 6 ON ***Well ID:*** 7433200	NE/170.0	0.00	117
46	WWIS		ON ***Well ID:*** 7452520	SSW/174.2	1.00	118
47	GEN	399497 Ont Ltd	280 Frontenac Street Ottawa ON K1L 6K9 ***Generator No.*** **|** ***Years Reported:*** ON5958491 | 20,19,18,17,16,15,14,13	NNW/175.3	0.00	118
48	WWIS		ON ***Well ID:*** 7441840	NE/176.2	0.00	120
49	WWIS		260 MCARTHUR AVENUE lot 7 OTTAWA ON ***Well ID:*** 7052573	S/178.7	1.00	121
50	CA	Bel-Air Lexus Toyota Inc.	280 McArthur Avenue Ottawa ON	SE/178.9	0.00	125
50	CA	Bel-Air Automobiles Inc.	280 McArthur Ave Ottawa ON	SE/178.9	0.00	125
50	EBR	Bel-Air Lexus Toyota Inc.	280 McArthur Avenue Ottawa Ontario K1L 6P2 Ottawa ON	SE/178.9	0.00	125

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
50	EBR	Bel-Air Lexus Toyota Inc.	280 McArthur Avenue Ottawa K1L 6P2 CITY OF OTTAWA ON	SE/178.9	0.00	126
50	EBR	Bel-Air Automobiles Inc.	280 McArthur Avenue Ottawa K1L 6P2 CITY OF OTTAWA ON	SE/178.9	0.00	126
50	ECA	Bel-Air Lexus Toyota Inc.	280 McArthur Avenue Ottawa ON K1L 6P2	SE/178.9	0.00	127
50	ECA	Bel-Air Automobiles Inc.	280 McArthur Ave Ottawa ON K1L 6P2	SE/178.9	0.00	127
50	EHS		280 Mcarthur Ave Ottawa ON K1L6P2	SE/178.9	0.00	128
50	GEN	GTA'S Finest Restoration Services (ottawa) Inc.	280 McArthur Ave Ottawa ON K1L 6P2 ***Generator No.*	*Years Reported:*** ON3895795 | 16	SE/178.9	0.00	128
50	HBAR	Alfred's White Rose Service	280 McArthur av Eastview ON	SE/178.9	0.00	128
50	HBAR	Bel-Air Automobiles	280 Mcarthur Av Ottawa ON	SE/178.9	0.00	128
51	WWIS		ON ***Well ID:*** 7273415	NE/179.8	0.00	129
52	HBAR	McArthur Av Shell Serv Sta	280 McArthur Av Vanier ON	SSE/181.1	0.69	132
52	HBAR	Bel-Air Toyota Automobile	280 Mcarthur Av Vanier ON	SSE/181.1	0.69	132
53	WWIS		252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221189	SSW/181.1	1.00	132
54	WWIS		252 MCARTHUR AVE. Ottawa ON	SSW/181.3	1.00	134

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7221195			
55	WWIS		lot 6 ON ***Well ID:*** 7429420	NE/182.0	0.00	137
56	GEN	Aristo Properties	315 Blake Blvd Ottawa ON K1L6L4 ***Generator No.*** **|** ***Years Reported:*** ON3230403 | 16,15	NE/182.6	0.00	137
57	WWIS		ON ***Well ID:*** 7441699	NE/182.9	0.00	138
58	EHS		311-315 Blake Boulveard Ottawa ON K1L 6L6	NE/183.6	0.00	139
59	CA	Bel-Air Automobiles Inc.	280 McArthur Ave Ottawa ON	SSE/184.3	-0.03	139
59	HBAR	Burnie's Shell Service Station	280 McArthur avenue Eastview ON	SSE/184.3	-0.03	140
60	WWIS		252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221193	SSW/184.9	1.00	140
61	WWIS		252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221191	SSW/185.0	1.00	142
62	WWIS		252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221194	SSW/186.9	1.00	144
63	EHS		292 Mcarthur Ave Ottawa ON K1L 6P2	SE/187.2	0.00	147
63	SCT	NUCLEONICS SCIENTIFIC DEVICES	292 MCARTHUR AVE VANIER ON K1L 6P2	SE/187.2	0.00	147
64	EHS		311 Blake Blvd Ottawa ON K1L6L4	NE/187.7	0.00	147
64	EHS		311 Blake Blvd Ottawa ON Ottawa ON K1L 6L6	NE/187.7	0.00	147

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	GEN	Aristo Properties	311 Blake Blvd Ottawa ON K1L 6L6 ***Generator No.* | *Years Reported:*** ON5424457 | 22	NE/187.7	0.00	147
65	WWIS		ON ***Well ID:*** 7445950	NE/187.8	0.00	148
66	WWIS		ON ***Well ID:*** 7273416	NNE/189.2	0.00	149
67	WWIS		ON ***Well ID:*** 7452518	SSW/191.2	1.00	152
68	WWIS		ON ***Well ID:*** 7452521	SSW/193.7	1.00	153
69	GEN	Aqua Drugs Limited	311 MCARTHUR AVENUE Suite 105 VANIER ON K1L 6P1 ***Generator No.* | *Years Reported:*** ON2532700 | 25,24,23,22,21,20,19,18,17,16,15,14,12,09,08,07,06,05,04,03,01,00,99	ESE/194.5	-1.00	154
70	WWIS		ON ***Well ID:*** 7273417	NE/194.8	0.00	161
71	EHS		311 Mcarthur Ave Ottawa ON K1L8M3	ESE/195.0	-1.00	164
71	EHS		311 McArthur Avenue Ottawa Ontario Vanier ON K1L 8M3	ESE/195.0	-1.00	165
71	GEN	CARE MEDICS	311 MCARTHUR AVE UNIT 103 OTTAWA ON K1L8M3 ***Generator No.* | *Years Reported:*** ON5595507 | 22,21,20,19,18,17,16,15,14,13,12,11,10	ESE/195.0	-1.00	165
72	WWIS		lot 6 ON ***Well ID:*** 7429419	NE/196.1	0.00	168
73	WWIS		ON ***Well ID:*** 7441838	NE/196.9	0.00	169
74	WWIS		315 BLAKE BLVD. OTTAWA ON	NE/199.2	0.00	170

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7250248			
75	WWIS		ON ***Well ID:*** 7273418	NE/201.1	0.00	173
76	WWIS		ON ***Well ID:*** 7441839	NE/202.3	0.00	176
77	WWIS		295 FRONTENAC ST. Ottawa ON ***Well ID:*** 7123751	N/209.1	0.00	177
78	HBAR	McArthur Road Auto Electric	300 McArthur av Ottawa ON	SE/209.4	0.00	180
78	HBAR	Thompson & Ray	300 McArthur av Ottawa ON	SE/209.4	0.00	180
79	WWIS		295 FRONTENAC ST. Ottawa ON ***Well ID:*** 7123752	N/210.8	0.00	181
80	WWIS		ON ***Well ID:*** 7429653	SSW/212.3	1.28	183
81	HBAR	Ontario Motor Sales	242 McArthur av Eastview ON	SW/213.1	1.00	184
82	WWIS		256 MCAURTHUR AVE. Ottawa ON ***Well ID:*** 7221187	S/214.2	1.00	184
83	HINC		295 FRONTENAC STREET OTTAWA ON	N/215.9	0.00	187
83	SPL	P.I. S 21(1)(f)	295 Frontenac St Ottawa ON	N/215.9	0.00	187
84	DTNK	CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR VANIER ON	SSW/216.5	1.28	188
84	DTNK	CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR VANIER ON	SSW/216.5	1.28	189

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
84	DTNK	CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR VANIER ON	SSW/216.5	1.28	189
84	EHS		256 McArthur Avenue Ottawa ON	SSW/216.5	1.28	190
84	EXP	CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR AVE VANIER ON	SSW/216.5	1.28	190
84	EXP	CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR AVE VANIER ON	SSW/216.5	1.28	190
84	GEN	CITY OF OTTAWA - RPAM	256 MCARTHUR AVE VANIER GARAGE VANIER ON K1L 6P4 ***Generator No.*	*Years Reported:* ON3617506 | 06	SSW/216.5	1.28	191
84	GEN	City of Ottawa Facility Operations Service	256 McArthur Avenue Ottawa ON K1L 6P4 ***Generator No.*	*Years Reported:* ON6974902 | 25,23,22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07	SSW/216.5	1.28	191
84	GEN	VANIER, CITY OF	256 MCARTHUR AVENUE VANIER ON K1L 6P4 ***Generator No.*	*Years Reported:* ON0619300 | 01,00,99,98,97,96,95,94,93,92,90,89,88,87,86	SSW/216.5	1.28	195
84	GEN	CITY OF OTTAWA	256 MCARTHER RD. OTTAWA ON K1P 1J1 ***Generator No.*	*Years Reported:* ON9196130 | 04,03,02	SSW/216.5	1.28	200
84	PRT	CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR VANIER ON K1L 6P4	SSW/216.5	1.28	201
85	SPL		327 Blakes Boulevard OTTAWA ON	NE/218.8	0.00	201
86	EHS		308 McArthur Avenue Ottawa ON K1L6P2	ESE/224.1	-1.00	202
87	WWIS		ON ***Well ID:*** 7452512	SSW/229.8	2.03	202
88	WWIS		ON	SSW/230.1	2.03	203

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7429652			
89	BORE		ON	SW/232.4	2.08	204
90	EHS		322-326 Frontenac Street Vanier ON K1L 6K7	NE/232.8	0.00	206
91	SPL		WB lane 313 McArthur Ave, Ottawa ON	ESE/233.9	-1.00	206
92	WWIS		ON ***Well ID:*** 7429651	S/234.0	2.03	207
93	EHS		252 McArthur Ave. Vanier ON K1L 6P4	SSW/235.1	2.03	208
94	WWIS		ON ***Well ID:*** 7452517	S/235.3	1.69	208
95	WWIS		ON ***Well ID:*** 7452519	S/235.9	2.03	209
96	DTNK	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	248 MCARTHUR AVE VANIER ON K1L 6P4	SSW/240.1	2.08	210
96	EXP	CANADIAN TIRE CORPORATION LIMITED	248 MCARTHUR AVE VANIER ON	SSW/240.1	2.08	210
96	EXP	CANADIAN TIRE CORPORATION LIMITED	248 MCARTHUR AVE VANIER ON	SSW/240.1	2.08	210
96	EXP	CANADIAN TIRE CORPORATION LIMITED	248 MCARTHUR AVE VANIER ON	SSW/240.1	2.08	211
96	EXP	CANADIAN TIRE CORPORATION LIMITED	248 MCARTHUR AVE VANIER ON	SSW/240.1	2.08	211
96	GEN	TOTH EQUITY LIMITED	248 McArthur Ave Vanier ON K1L6P4	SSW/240.1	2.08	211

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			***Generator No.*	*Years Reported:*** ON1497150 | 04,03,02		
96	HBAR	Romay Automotive Ltd	248 McArthur av Ottawa ON	SSW/240.1	2.08	212
96	HBAR	Romay Automotive Ltd	248 McArthur av Eastview ON	SSW/240.1	2.08	212
96	HBAR	Canadian Tire Corp Associate Store	248 Mcarthur Av Vanier ON	SSW/240.1	2.08	212
96	HBAR	Romay Automotive Ltd	248 McArthur av Eastview ON	SSW/240.1	2.08	212
96	PES	CANADIAN TIRE ROMAY AUTOMOTIVE LTD.	248 MCARTHUR AVENUE VANIER ON	SSW/240.1	2.08	213
96	PRT	CANADIAN TIRE CORP LTD PETROLEUM DIVISION - SUSAN	248 MCARTHUR AV VANIER ON K1L6P4	SSW/240.1	2.08	213
97	PINC	PIPELINE HIT 1/2"	280 RICHELIEU AVE,,VANIER,ON,K1L 6K3,CA ON	NNW/241.2	0.00	213
98	WWIS		ON ***Well ID:*** 7429650	S/244.7	1.69	214
99	EHS		335 Olmstead St Ottawa ON K1L7K2	WNW/246.0	0.00	214
100	WWIS		ON ***Well ID:*** 7452513	SSW/248.0	2.03	215
101	WWIS		ON ***Well ID:*** 7452511	S/249.6	1.69	215

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 2 BORE site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON	W	159.65	35
	ON	SW	232.42	89

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 4 CA site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
R.M. OF OTTAWA-CARLETON	LACASSE AVE./BLAKE BLVD./LEWIS VANIER CITY ON	NE	153.60	32
Bel-Air Automobiles Inc.	280 McArthur Ave Ottawa ON	SE	178.93	50
Bel-Air Lexus Toyota Inc.	280 McArthur Avenue Ottawa ON	SE	178.93	50

Lower Elevation	Address	Direction	Distance (m)	Map Key
Bel-Air Automobiles Inc.	280 McArthur Ave Ottawa ON	SSE	184.31	59

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 4 DTNK site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR VANIER ON	SSW	216.47	84
CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR VANIER ON	SSW	216.47	84
CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR VANIER ON	SSW	216.47	84
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	248 MCARTHUR AVE VANIER ON K1L 6P4	SSW	240.08	96

EBR - Environmental Registry

A search of the EBR database, dated 1994 - May 31, 2026 has found that there are 3 EBR site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Bel-Air Automobiles Inc.	280 McArthur Avenue Ottawa K1L 6P2 CITY OF OTTAWA ON	SE	178.93	50
Bel-Air Lexus Toyota Inc.	280 McArthur Avenue Ottawa K1L 6P2 CITY OF OTTAWA ON	SE	178.93	50
Bel-Air Lexus Toyota Inc.	280 McArthur Avenue Ottawa Ontario K1L 6P2 Ottawa ON	SE	178.93	50

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011 - Apr 30, 2026 has found that there are 2 ECA site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Bel-Air Automobiles Inc.	280 McArthur Ave Ottawa ON K1L 6P2	SE	178.93	50
Bel-Air Lexus Toyota Inc.	280 McArthur Avenue Ottawa ON K1L 6P2	SE	178.93	50

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Feb 28, 2026 has found that there are 26 EHS site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	280 Blake Boulevard Vanier ON K1L 6L7	NNW	88.13	3
	360 Lacasse Ave Ottawa ON Vanier ON K1L 7A9	ESE	101.60	5
	296 Blake Boulevard Vanier ON K1L 6L7	NNE	102.60	6
	308 Blake Blvd Ottawa ON K1L6L7	NE	110.67	7
	279 Blake Blvd Vanier ON K1L 6L6	N	130.42	14
	257 Mcarthur Ave Ottawa ON K1L6P3	SW	139.31	21
	285 Blake Boulevard Vanier ON K1L 6L6	N	143.70	22
	310-316 Blake Boulevard Vanier ON K1L 6L5	ENE	145.87	24
	310-316 Blake Blvd. Ottawa ON	NE	147.11	27
	349 Olmstead St Ottawa ON K1L1B1	W	160.39	36

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	280 Mcarthur Ave Ottawa ON K1L6P2	SE	178.93	50
	311-315 Blake Boulveard Ottawa ON K1L 6L6	NE	183.63	58
	292 Mcarthur Ave Ottawa ON K1L 6P2	SE	187.24	63
	311 Blake Blvd Ottawa ON K1L6L4	NE	187.69	64
	311 Blake Blvd Ottawa ON Ottawa ON K1L 6L6	NE	187.69	64
	256 McArthur Avenue Ottawa ON	SSW	216.47	84
	322-326 Frontenac Street Vanier ON K1L 6K7	NE	232.83	90
	252 McArthur Ave. Vanier ON K1L 6P4	SSW	235.12	93
	335 Olmstead St Ottawa ON K1L7K2	WNW	246.02	99

Lower Elevation	Address	Direction	Distance (m)	Map Key
	345-347 Lacasse Avenue Ottawa ON	ENE	132.23	16
	309 McArthur Avenue Ottawa ON	E	160.94	38

301 McArthur Avenue Vanier ON K1L 7B1	ESE	163.21	41
307 McArthur Ave. Vanier ON K1L 6P1	E	163.37	42
311 Mcarthur Ave Ottawa ON K1L8M3	ESE	195.02	71
311 McArthur Avenue Ottawa Ontario Vanier ON K1L 8M3	ESE	195.02	71
308 McArthur Avenue Ottawa ON K1L6P2	ESE	224.08	86

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Oct 2023 has found that there are 6 EXP site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR AVE VANIER ON	SSW	216.47	84
CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR AVE VANIER ON	SSW	216.47	84
CANADIAN TIRE CORPORATION LIMITED	248 MCARTHUR AVE VANIER ON	SSW	240.08	96
CANADIAN TIRE CORPORATION LIMITED	248 MCARTHUR AVE VANIER ON	SSW	240.08	96
CANADIAN TIRE CORPORATION LIMITED	248 MCARTHUR AVE VANIER ON	SSW	240.08	96

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
CANADIAN TIRE CORPORATION LIMITED	248 MCARTHUR AVE VANIER ON	SSW	240.08	96

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Sep 30, 2025 has found that there are 27 GEN site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
OTTAWA BOARD (SEE & USE ON0426406)	ECOLE STE. ANDR'E-LAURENDEAU 235 MCARTHUR AVENUE OTTAWA ON ***Generator No.*	*Years Reported:*** ON0375219 | 98,97,96,95,94,93,92,90,89,88,87,86	W	38.77	1
DUBROFSKY, CHERYL; HARTMAN, HARRY; HARTMAN, MARI	348 Lacasse 344 Lacasse Ottawa ON ***Generator No.*	*Years Reported:*** ON8157375 | 11	ENE	66.56	2
Zenith Solutions Inc.	380 Lacasse Avenue Ottawa ON K1L 7A9 ***Generator No.*	*Years Reported:*** ON9333174 | 22	SE	112.71	8
OTTAWA (SEE&USE ON1285706) 29-417	ECOLE S. CATHOLIQUE ANDRE LAURENDEAU 235 AVENUE MCARTHUR VANIER ON K1N 7G9 ***Generator No.*	*Years Reported:*** ON0426406 | 94,93,92,90,89,88	WSW	122.45	10
Conseil des Úcoles catholiques du Centre-Est	235 Avenue McArthur Ottawa ON ***Generator No.*	*Years Reported:*** ON2970070 | 12,11,10,09	WSW	122.45	10
CONSEIL DES ECOLES CATHOLIQUES DE LANGUE	235 AVENUE MCARTHUR VANIER ON K1L 6P3 ***Generator No.*	*Years Reported:*** ON1285706 | 04,03,02,01,00,99,98,97,96,95,94,93,92	WSW	122.45	10
EASTVIEW ANIMAL HOSPITAL	261 MCARTHUR STREET VANIER ON K1L 6P3 ***Generator No.*	*Years Reported:*** ON1800400 | 01,00,99,98,97,96,95,94,93	SSW	131.36	15
Ontario Petroleum Pump	310 Blake Blvd Ottawa ON ***Generator No.*	*Years Reported:*** ON4674220 | 08,07	ENE	135.22	17
Ontario Petroleum Pump	310 Blake Blvd Ottawa ON	ENE	135.22	17

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	Generator No.* | *Years Reported: ON2931558 | 12			
David Bunner	310 Blake Blvd Vanier ON K1L 6L5	ENE	135.22	17
	Generator No.* | *Years Reported: ON6377726 | 14			
David Bunner	310 Blake Blvd Vanier ON K1L 6L5	ENE	135.22	17
	Generator No.* | *Years Reported: ON4971167 | 16,15			
Vanier Animal Hospital	257 McArthur Avenue Ottawa ON K1L 6P3	SW	138.95	20
	Generator No.* | *Years Reported: ON001064183 | 25,24			
AWD Contractors	349 Olmstead Street Ottawa ON K1L 7K2	W	160.39	36
	Generator No.* | *Years Reported: ON001059319 | 25,23			
Elementary School Catholic Horizon-Jeunesse	349 Olmstead Street Ottawa ON K1L 7K2	W	160.39	36
	Generator No.* | *Years Reported: ON7034415 | 21			
399497 Ont Ltd	280 Frontenac Street Ottawa ON K1L 6K9	NNW	175.31	47
	Generator No.* | *Years Reported: ON5958491 | 20,19,18,17,16,15,14,13			
GTA'S Finest Restoration Services (ottawa) Inc.	280 McArthur Ave Ottawa ON K1L 6P2	SE	178.93	50
	Generator No.* | *Years Reported: ON3895795 | 16			
Aristo Properties	315 Blake Blvd Ottawa ON K1L6L4	NE	182.62	56
	Generator No.* | *Years Reported: ON3230403 | 16,15			
Aristo Properties	311 Blake Blvd Ottawa ON K1L 6L6	NE	187.69	64
	Generator No.* | *Years Reported: ON5424457 | 22			
CITY OF OTTAWA - RPAM	256 MCARTHUR AVE VANIER GARAGE VANIER ON K1L 6P4 ***Generator No.* | *Years Reported:*** ON3617506 | 06	SSW	216.47	84
City of Ottawa Facility Operations Service	256 McArthur Avenue Ottawa ON K1L 6P4	SSW	216.47	84
	Generator No.* | *Years Reported: ON6974902 | 25,23,22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07			

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
VANIER, CITY OF	256 MCARTHUR AVENUE VANIER ON K1L 6P4	SSW	216.47	84
	Generator No.* | *Years Reported: ON0619300 | 01,00,99,98,97,96,95,94,93,92,90,89,88,87,86			
CITY OF OTTAWA	256 MCARTHER RD. OTTAWA ON K1P 1J1	SSW	216.47	84
	Generator No.* | *Years Reported: ON9196130 | 04,03,02			
TOTH EQUITY LIMITED	248 McArthur Ave Vanier ON K1L6P4	SSW	240.08	96
	Generator No.* | *Years Reported: ON1497150 | 04,03,02			

Lower Elevation	Address	Direction	Distance (m)	Map Key
Mr Pierre Larose	353 Lacasse Vanier ON K1L 7B1	E	123.04	11
	Generator No.* | *Years Reported: ON8134889 | 04,03,02			
Pierre Seguin In Trust	345/347 Lacasse St Ottawa ON K1L 7B1	ENE	127.09	12
	Generator No.* | *Years Reported: ON8554009 | 04,03,02			
Aqua Drugs Limited	311 MCARTHUR AVENUE Suite 105 VANIER ON K1L 6P1	ESE	194.50	69
	Generator No.* | *Years Reported: ON2532700 | 25,24,23,22,21,20,19,18,17,16,15,14,12,09,08,07,06,05,04,03,01,00,99			
CARE MEDICS	311 MCARTHUR AVE UNIT 103 OTTAWA ON K1L8M3	ESE	195.02	71
	Generator No.* | *Years Reported: ON5595507 | 22,21,20,19,18,17,16,15,14,13,12,11,10			

HBAR - Historical Business Activity Risk

A search of the HBAR database, dated 1920s - 1990 has found that there are 13 HBAR site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Alfred's White Rose Service	280 McArthur av Eastview ON	SE	178.93	50
Bel-Air Automobiles	280 Mcarthur Av Ottawa ON	SE	178.93	50
McArthur Av Shell Serv Sta	280 McArthur Av Vanier ON	SSE	181.08	52

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Bel-Air Toyota Automobile	280 Mcarthur Av Vanier ON	SSE	181.08	52
McArthur Road Auto Electric	300 McArthur av Ottawa ON	SE	209.43	78
Thompson & Ray	300 McArthur av Ottawa ON	SE	209.43	78
Ontario Motor Sales	242 McArthur av Eastview ON	SW	213.14	81
Romay Automotive Ltd	248 McArthur av Ottawa ON	SSW	240.08	96
Romay Automotive Ltd	248 McArthur av Eastview ON	SSW	240.08	96
Canadian Tire Corp Associate Store	248 Mcarthur Av Vanier ON	SSW	240.08	96
Romay Automotive Ltd	248 McArthur av Eastview ON	SSW	240.08	96

Lower Elevation	Address	Direction	Distance (m)	Map Key
Downtown Motor Sales	309 McArthur av Eastview ON	E	160.94	38
Burnie's Shell Service Station	280 McArthur avenue Eastview ON	SSE	184.31	59

HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 1 HINC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	295 FRONTENAC STREET OTTAWA ON	N	215.86	83

PES - Pesticide Register

A search of the PES database, dated Oct 2011 - Apr 30, 2026 has found that there are 3 PES site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
PESTROY INC./DUTCH JANITORIAL SERVICES LTD.	369 LACASSE AVENUE 8036 OTTAWA ON K1G 3H6	ESE	146.00	26
PESTROY INC./AARBRU	369 LACASSE AVENUE OTTAWA ON K1H 6S6	ESE	146.00	26
CANADIAN TIRE ROMAY AUTOMOTIVE LTD.	248 MCARTHUR AVENUE VANIER ON	SSW	240.08	96

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 2 PINC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
PIPELINE HIT 1/2"	280 RICHELIEU AVE,,VANIER,ON, K1L 6K3,CA ON	NNW	241.21	97

Lower Elevation	Address	Direction	Distance (m)	Map Key
	355 Lacasse Avenue, Ottawa ON	E	128.19	13

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 2 PRT site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
CORPORATION OF THE CITY OF VANIER RAYMOND ROY	256 MCARTHUR VANIER ON K1L 6P4	SSW	216.47	84
CANADIAN TIRE CORP LTD PETROLEUM DIVISION - SUSAN	248 MCARTHUR AV VANIER ON K1L6P4	SSW	240.08	96

SCT - Scott's Manufacturing Directories

A search of the SCT database, dated 1992-Mar 2011; Feb 2025 has found that there are 3 SCT site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Bench Dog Cabinets	364 Lacasse Ave Vanier ON K1L6L6	SE	114.48	9
Heritage Glass	364 Lacasse Ave Vanier ON K1L7A9	SE	114.48	9
NUCLEONICS SCIENTIFIC DEVICES	292 MCARTHUR AVE VANIER ON K1L 6P2	SE	187.24	63

SPL - Ontario Spills

A search of the SPL database, dated 1988- Mar 2026 has found that there are 5 SPL site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
s.21<UNOFFICIAL>	235 McArthur Avenue Ottawa ON K1L 6P3	W	38.77	1
P.I. S 21(1)(f)	295 Frontenac St Ottawa ON	N	215.86	83
	327 Blakes Boulevard OTTAWA ON	NE	218.76	85

Lower Elevation	Address	Direction	Distance (m)	Map Key
City of Ottawa	309 McArthur Ave Ottawa ON	E	160.94	38
	WB lane 313 McArthur Ave, Ottawa ON	ESE	233.90	91

WWIS - Water Well Information System

A search of the WWIS database, dated Jul 31, 2025 has found that there are 50 WWIS site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON ***Well ID:*** 7368895	NNE	99.55	4
	ON ***Well ID:*** 7169780	ENE	137.54	18
	310 BLAKE BLVD. OTTAWA ON ***Well ID:*** 7170716	ENE	137.72	19
	310 BLAKE BLVD. OTTAWA ON ***Well ID:*** 7170715	ENE	144.63	23
	310 BLAKE BLVD. 316 Ottawa ON ***Well ID:*** 7178879	ENE	146.00	25
	MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221190	S	147.60	28
	310 BRAKE BLVD. OTTAWA ON ***Well ID:*** 7170717	ENE	148.51	29
	318-316 BLAKE BOULEVARD Ottawa ON ***Well ID:*** 7195008	ENE	150.91	30


Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	310 BLAKE BLVD OTTAWA ON ***Well ID:*** 7257961	ENE	152.94	31
	ON ***Well ID:*** 7195009	ENE	154.96	33
	256 MCAURTHUR AVE. Ottawa ON ***Well ID:*** 7221188	S	159.43	34
	292 Blake Blvd VANIER ON ***Well ID:*** 7358212	N	160.64	37
	297 Blake Boulevard Ottawa ON ***Well ID:*** 7359571	NNE	162.52	40
	252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221192	SSW	165.82	43
	ON ***Well ID:*** 7441841	NE	167.45	44
	lot 6 ON ***Well ID:*** 7433200	NE	170.04	45
	ON ***Well ID:*** 7452520	SSW	174.20	46
	ON ***Well ID:*** 7441840	NE	176.23	48
	260 MCARTHUR AVENUE lot 7 OTTAWA ON ***Well ID:*** 7052573	S	178.66	49
	ON	NE	179.77	51

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	Well ID: 7273415			
	252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221189	SSW	181.12	53
	252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221195	SSW	181.30	54
	lot 6 ON ***Well ID:*** 7429420	NE	182.02	55
	ON ***Well ID:*** 7441699	NE	182.91	57
	252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221193	SSW	184.88	60
	252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221191	SSW	184.95	61
	252 MCARTHUR AVE. Ottawa ON ***Well ID:*** 7221194	SSW	186.85	62
	ON ***Well ID:*** 7445950	NE	187.77	65
	ON ***Well ID:*** 7273416	NNE	189.20	66
	ON ***Well ID:*** 7452518	SSW	191.19	67
	ON ***Well ID:*** 7452521	SSW	193.74	68

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON ***Well ID:*** 7273417	NE	194.84	70
	lot 6 ON ***Well ID:*** 7429419	NE	196.11	72
	ON ***Well ID:*** 7441838	NE	196.94	73
	315 BLAKE BLVD. OTTAWA ON ***Well ID:*** 7250248	NE	199.16	74
	ON ***Well ID:*** 7273418	NE	201.10	75
	ON ***Well ID:*** 7441839	NE	202.26	76
	295 FRONTENAC ST. Ottawa ON ***Well ID:*** 7123751	N	209.05	77
	295 FRONTENAC ST. Ottawa ON ***Well ID:*** 7123752	N	210.77	79
	ON ***Well ID:*** 7429653	SSW	212.28	80
	256 MCAURTHUR AVE. Ottawa ON ***Well ID:*** 7221187	S	214.18	82
	ON ***Well ID:*** 7452512	SSW	229.78	87
	ON	SSW	230.09	88

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	Well ID: 7429652			
	ON	S	234.03	92
	Well ID: 7429651			
	ON	S	235.29	94
	Well ID: 7452517			
	ON	S	235.89	95
	Well ID: 7452519			
	ON	S	244.71	98
	Well ID: 7429650			
	ON	SSW	248.03	100
	Well ID: 7452513			
	ON	S	249.63	101
	Well ID: 7452511			

Lower Elevation	Address	Direction	Distance (m)	Map Key
	310 BLAKE BLVD. Ottawa ON	ENE	162.33	39
	Well ID: 7122676			



Map: 0.25 Kilometer Radius


Order Number: 26061900032

Address: PE7604, Ottawa, ON

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Aerial **Year: 2025**


Address: PE7604, Ottawa, ON

Source: ESRI World Imagery

Order Number: 26061900032

ERIS

© ERIS Information Limited Partnership



Topographic Map

Address: PE7604, ON

Source: ESRI World Topographic Map

Order Number: 26061900032

ERIS

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 2	W/38.8	59.9 / 0.00	OTTAWA BOARD (SEE & USE ON0426406) ECOLE STE. ANDR'E-LAURENDEAU 235 MCARTHUR AVENUE OTTAWA ON	GEN

Generator No.: ON0375219
Years Reported: 98,97,96,95,94,93,92,90,89,88,87,86

Alternate Locations

Generator No: ON0375219
Generator Nm: OTTAWA BOARD OF EDUCATION
Site Addr: ECOLE S. ANDR'E-LAURENDEAU, 235 AVENUE
City: OTTAWA
Reported Year(s): 87,86

Generator No: ON0375219
Generator Nm: OTTAWA BOARD (SEE & USE ON0426406)
Site Addr: ECOLE S. ANDR'E-LAURENDEAU, 235 AVENUE
City: OTTAWA
Reported Year(s): 90,89,88

Generator No: ON0375219
Generator Nm: OTTAWA BOARD (SEE & USE ON0426406)29-129
Site Addr: ECOLE S. ANDR'E-LAURENDEAU, 235 AVENUE
City: OTTAWA
Reported Year(s): 97,96,95,94,93,92

Generator No: ON0375219
Generator Nm: OTTAWA BOARD (SEE & USE ON0426406)
Site Addr: ECOLE STE. ANDR'E-LAURENDEAU
City: OTTAWA
Reported Year(s): 98

Waste Reported

Waste Class: 252 - WASTE OILS & LUBRICANTS
Reported Years: 89,88

Waste Class: 148 - INORGANIC LABORATORY CHEMICALS
Reported Years: 89,88,87,86

Waste Class: 263 - ORGANIC LABORATORY CHEMICALS
Reported Years: 89,88,87,86

1998 Generator Info

SIC Code: 8511 **SIC Description:** ELEMT./SECON. EDUC.

1997 Generator Info

SIC Code: 8511 **SIC Description:** ELEMT./SECON. EDUC.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

1996 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1995 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1994 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1993 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1992 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1990 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1989 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1988 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1988 Manifest Summary

Waste Code: 254 ***Waste Char Code:***
Waste Description: TRANSFER STATION OIL WASTES ***Waste Char Desc:***
Quantity (kg): 227.5 ***Waste Count:*** 1.0

1987 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1986 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1	*2 of 2*	*W/38.8*	*59.9 / 0.00*	***s.21<UNOFFICIAL>*** ***235 McArthur Avenue*** ***Ottawa ON K1L 6P3***	***SPL***

Ref No: 6076-BMSJ5C ***Municipality No:***
Year: ***Nature of Damage:***
Incident Dt: 2020/03/16 ***Discharger Report:***
Dt MOE Arvl on Scn: ***Material Group:***
MOE Reported Dt: 2020/03/17 ***Impact to Health:*** 0 - No Impact
Dt Document Closed: 2020/07/17 ***Agency Involved:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site No:	NA
MOE Response:	No
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Ottawa
Nearest Watercourse:	
Site Name:	Horizon-Jeunesse Elementary Catholic School<UNOFFICIAL>
Site Address:	235 McArthur Avenue
Site Region:	Eastern
Site Municipality:	Ottawa
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	5031089.43
Easting:	448382.15
Entity Operating Name:	
Client Name:	s.21<UNOFFICIAL>
Client Type:	
Source Type:	Valve/Fitting/Piping
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Equipment Failure
Incident Summary:	Richard Steel: 20 L hydraulic oil to asphalt
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	20 L
Contaminant Qty 1:	20
Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	HYDRAULIC OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	n/a
Contaminant UN No 1:	n/a
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

2	1 of 1	ENE/66.6	59.9 / 0.00	**DUBROFSKY, CHERYL; HARTMAN, HARRY; HARTMAN, MARI** **348 Lacasse 344 Lacasse** **Ottawa ON**	GEN

Generator No.:	ON8157375
Years Reported:	11

Alternate Locations

Generator No:	ON8157375
Generator Nm:	DUBROFSKY, CHERYL; HARTMAN, HARRY; HARTMAN, MARI

Site Addr: 348 LACASSE
City: OTTAWA
Reported Year(s): 11

2011 Generator Info

NAICS Code 1: 531210
NAICS 1 Description: Offices of Real Estate Agents and Brokers
Contaminated Facility: N
MHSW Facility: N

2011 Manifest Summary

Waste Code: 221
Waste Description: LIGHT FUELS
Quantity (kg): 2390
Waste Char Code: I
Waste Char Desc: IGNITABLE
Waste Count: 1

Waste Code: 221
Waste Description: LIGHT FUELS
Quantity (kg): 655
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 2

---

3 | **1 of 1** | **NNW/88.1** | **59.9 / 0.00** | **280 Blake Boulevard Vanier ON K1L 6L7** | **EHS**

Order No: 25032700228
Status: C
Report Type: Standard Express Report
Report Date: 28-MAR-25
Date Received: 27-MAR-25
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.6577323
Y: 45.4336114

---

4 | **1 of 1** | **NNE/99.6** | **59.9 / 0.00** | **ON** | **WWIS**

Well ID: 7368895
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C35503
Tag: A251386
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 09/29/2020
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1844
Form Version: 8
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/736\7368895.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/28/2020
Year Completed:	2020
Depth (m):	
Latitude:	45.4337095219224
Longitude:	-75.6573389018762
Point X:	-75.6573387397115
Point Y:	45.43370951538645
Path:	736\7368895.pdf

Bore Hole Information

Bore Hole ID:	1008472834	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448584.00
Code OB Desc:		**North83:**	5031342.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/28/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

5 | ***1 of 1*** | ***ESE/101.6*** | ***59.9 / 0.00*** | ***360 Lacasse Ave Ottawa ON Vanier ON K1L 7A9*** | ***EHS***

Order No:	23030800289	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	13-MAR-23	**Search Radius (km):**	.25
Date Received:	08-MAR-23	**X:**	-75.6565934
Previous Site Name:		**Y:**	45.4322179
Lot/Building Size:			
Additional Info Ordered:			

---

6 | ***1 of 1*** | ***NNE/102.6*** | ***59.9 / 0.00*** | ***296 Blake Boulevard Vanier ON K1L 6L7*** | ***EHS***

Order No:	20191002027	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	07-OCT-19	**Search Radius (km):**	.35
Date Received:	02-OCT-19	**X:**	-75.657272
Previous Site Name:		**Y:**	45.433728
Lot/Building Size:			
Additional Info Ordered:	City Directory; Aerial Photos		

---

7 | ***1 of 1*** | ***NE/110.7*** | ***59.9 / 0.00*** | ***308 Blake Blvd Ottawa ON K1L6L7*** | ***EHS***

Order No:	20160510027	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	13-MAY-16	**Search Radius (km):**	.25
Date Received:	10-MAY-16	**X:**	-75.656847
Previous Site Name:		**Y:**	45.433687

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Lot/Building Size:					
Additional Info Ordered:					
8	1 of 1	SE/112.7	59.9 / 0.00	Zenith Solutions Inc. 380 Lacasse Avenue Ottawa ON K1L 7A9	GEN

Generator No.: ON9333174
Years Reported: 22

Alternate Locations

Generator No: ON9333174
Generator Nm: ZENITH SOLUTIONS INC.
Site Addr: 380 LACASSE AVENUE
City: OTTAWA
Reported Year(s): 22

Waste Reported

Waste Class: 331 - WASTE COMPRESSED GASES
Reported Years: 22

Waste Class: 263 - ORGANIC LABORATORY CHEMICALS
Reported Years: 22

Waste Class: 148 - INORGANIC LABORATORY CHEMICALS
Reported Years: 22

Waste Class: 212 - ALIPHATIC SOLVENTS
Reported Years: 22

Waste Class: 145 - PAINT/PIGMENT/COATING RESIDUES
Reported Years: 22

2022 Generator Info

NAICS Code 1: 238220
NAICS 1 Description: Plumbing Heating and Air-Conditioning Contractors
Contaminated Fac: N
MHSW Facility: N

2022 Manifest Summary

Waste Code:	331	**Waste Char Code:**	I
Waste Description:	WASTE COMPRESSED GASES	**Waste Char Desc:**	IGNITABLE
Quantity (kg):	8.0	**Waste Count:**	1.0
Waste Code:	148	**Waste Char Code:**	C
Waste Description:	INORGANIC LABORATORY CHEMICALS	**Waste Char Desc:**	CORROSIVE
Quantity (kg):	85.0	**Waste Count:**	2.0
Waste Code:	145	**Waste Char Code:**	L
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	100.0	**Waste Count:**	1.0
Waste Code:	212	**Waste Char Code:**	L
Waste Description:	ALIPHATIC SOLVENTS	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	205.0	**Waste Count:**	1.0
Waste Code:	263	**Waste Char Code:**	L

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Description:	ORGANIC LABORATORY CHEMICALS	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	100.0	**Waste Count:**	1.0

9 **1 of 2** **SE/114.5** **59.9 / 0.00** **Bench Dog Cabinets**
364 Lacasse Ave
Vanier ON K1L6L6 **SCT**

Scott S ID:	302197792
Latitude:	45.4320747
Longitude:	-75.6565766

Details

Bus Type 1:	Manufacturer	**Employee Count:**	2
Bus Type 2:		**Square Footage:**	0
Bus Type 3:		**Estimated Sales:**	Under $1 Million
Product Cat 1:	Cabinet maker	**Export Indicator:**	
Product Cat 2:	Furniture maker	**Export Country 1:**	
Product Cat 3:		**Export Country 2:**	
Product Cat 4:		**Export Country 3:**	
Product Cat 5:		**Export Country 4:**	
Product Cat 6:		**Export Country 5:**	
Product Cat 7:		**Export Country 6:**	
Product Cat 8:		**Geocoded by:**	Address

Company Name:	Bench Dog Cabinets
Address Line 1:	364 Lacasse Ave
Address Line 2:	
City:	Vanier
Province:	ON
Postal Code:	K1L6L6
Census Division:	Ottawa; ON
Metro Area:	
Year Established:	2018
Head Office Indicator:	
Parent Company Nm:	
Parent Cmpny Addr 1:	
Parent Cmpny Addr 2:	
Parent Cmpny City:	
Parent Cmpny Prov:	
Parent Cmpy PC:	
Parent Cmpy Cntry:	
Head Office Nm:	
H Office Addr Line 1:	
H Office Addr Line 2:	
Head Office City:	
Head Office Province:	
Head Office PC:	
Head Office Cntry:	
Telephone:	613-842-7600
Fax:	
Website:	
Pri NAICS Desc:	337110-Wood Kitchen Cabinet and Counter Top Manufacturing
NAICS Code 1:	337110-Wood Kitchen Cabinet and Counter Top Manufa
NAICS Code 2:	
NAICS Code 3:	
NAICS Code 4:	
NAICS Code 5:	

9 **2 of 2** **SE/114.5** **59.9 / 0.00** **Heritage Glass**
364 Lacasse Ave
Vanier ON K1L7A9 **SCT**

Scott S ID:	301220577

Latitude:	45.4320747
Longitude:	-75.6565766

Details

Bus Type 1:	Manufacturer	**Employee Count:**	1
Bus Type 2:		**Square Footage:**	0
Bus Type 3:		**Estimated Sales:**	Under $1 Million
Product Cat 1:	Stained glass studio	**Export Indicator:**	
Product Cat 2:	Woodworker	**Export Country 1:**	
Product Cat 3:		**Export Country 2:**	
Product Cat 4:		**Export Country 3:**	
Product Cat 5:		**Export Country 4:**	
Product Cat 6:		**Export Country 5:**	
Product Cat 7:		**Export Country 6:**	
Product Cat 8:		**Geocoded by:**	Address

Company Name:	Heritage Glass
Address Line 1:	364 Lacasse Ave
Address Line 2:	
City:	Vanier
Province:	ON
Postal Code:	K1L7A9
Census Division:	Ottawa; ON
Metro Area:	
Year Established:	1992
Head Office Indicator:	
Parent Company Nm:	
Parent Cmpny Addr 1:	
Parent Cmpny Addr 2:	
Parent Cmpny City:	
Parent Cmpny Prov:	
Parent Cmpy PC:	
Parent Cmpy Cntry:	
Head Office Nm:	
H Office Addr Line 1:	
H Office Addr Line 2:	
Head Office City:	
Head Office Province:	
Head Office PC:	
Head Office Cntry:	
Telephone:	613-294-6077
Fax:	--
Website:	http://www.heritage-glass.ca/
Pri NAICS Desc:	416340-Paint; Glass and Wallpaper Merchant Wholesalers
NAICS Code 1:	327215-Glass Product Manufacturing from Purchased
NAICS Code 2:	
NAICS Code 3:	
NAICS Code 4:	
NAICS Code 5:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	1 of 3	WSW/122.5	59.9 / 0.00	OTTAWA (SEE&USE ON1285706) 29-417 ECOLE S. CATHOLIQUE ANDRE LAURENDEAU 235 AVENUE MCARTHUR VANIER ON K1N 7G9	GEN

Generator No.:	ON0426406
Years Reported:	94,93,92,90,89,88

Alternate Locations

Generator No:	ON0426406
Generator Nm:	OTTAWA R.C. SEPARATE SCHOOL BOARD
Site Addr:	ECOLE S. CATHOLIQUE ANDRE LAURENDEAU

City: VANIER
Reported Year(s): 89,88

Generator No: ON0426406
Generator Nm: OTTAWA (SEE&USE ON1285706)
Site Addr: ECOLE S. CATHOLIQUE ANDRE LAURENDEAU
City: VANIER
Reported Year(s): 90

Generator No: ON0426406
Generator Nm: OTTAWA (SEE&USE ON1285706) 29-417
Site Addr: ECOLE S. CATHOLIQUE ANDRE LAURENDEAU
City: VANIER
Reported Year(s): 94,93,92

1994 Generator Info

SIC Code: 0000 ***SIC Description:*** *** NOT DEFINED ***

1993 Generator Info

SIC Code: 0000 ***SIC Description:*** *** NOT DEFINED ***

1992 Generator Info

SIC Code: 0000 ***SIC Description:*** *** NOT DEFINED ***

1990 Generator Info

SIC Code: 0000 ***SIC Description:*** *** NOT DEFINED ***

1990 Manifest Summary

Waste Code: 252 ***Waste Char Code:***
Waste Description: WASTE OILS & LUBRICANTS ***Waste Char Desc:***
Quantity (kg): 410.0 ***Waste Count:*** 1.0

1989 Generator Info

SIC Code: 0000 ***SIC Description:*** *** NOT DEFINED ***

1988 Generator Info

SIC Code: 0000 ***SIC Description:*** *** NOT DEFINED ***

10	2 of 3	WSW/122.5	59.9 / 0.00	***Conseil des Úcoles catholiques du Centre-Est*** ***235 Avenue McArthur*** ***Ottawa ON***	GEN

Generator No.: ON2970070
Years Reported: 12,11,10,09

Alternate Locations

Generator No: ON2970070
Generator Nm: CONSEIL DES ÚCOLES CATHOLIQUES DU CENTRE-EST
Site Addr: 235 AVENUE MCARTHUR
City: OTTAWA

Reported Year(s): 12,11,10,09

Waste Reported

Waste Class: 253 - EMULSIFIED OILS
Reported Years: 12,11,10,09

2012 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Fac: N
MHSW Facility: N

2011 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Facility: N
MHSW Facility: N

2010 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Facility: N
MHSW Facility: N

2009 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Facility: N
MHSW Facility: N

2009 Manifest Summary

Waste Code:	253	**Waste Char Code:**	L
Waste Description:	EMULSIFIED OILS	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	2000	**Waste Count:**	1

10 | ***3 of 3*** | ***WSW/122.5*** | ***59.9 / 0.00*** | ***CONSEIL DES ECOLES CATHOLIQUES DE LANGUE***
235 AVENUE MCARTHUR
VANIER ON K1L 6P3 | ***GEN***

Generator No.: ON1285706
Years Reported: 04,03,02,01,00,99,98,97,96,95,94,93,92

Alternate Locations

Generator No: ON1285706
Generator Nm: CONSEIL DES ECOLES CATHOLIQUES DE LANGUE
Site Addr: 235 AVENUE MCARTHUR
City: VANIER
Reported Year(s): 04,03,02

Generator No: ON1285706
Generator Nm: CONSEIL DES ECOLES CATHOLIQUES DE LANGUE

Site Addr: ECOLE SECONDAIRE CATHOLIQUE
City: VANIER
Reported Year(s): 98,97,96,95,94,93,92

Generator No: ON1285706
Generator Nm: CONSEIL DES ECOLES CATHOLIQUES DE LANGUE
Site Addr: ANDRE-LAURENDEAU
City: VANIER
Reported Year(s): 00,99

Generator No: ON1285706
Generator Nm: CONSEIL DES ECOLES CATHOLIQUES DE LANGUE
Site Addr: ECOLE VISION JEUNESSE
City: VANIER
Reported Year(s): 01

Waste Reported

Waste Class: 252 - WASTE OILS & LUBRICANTS
Reported Years: 04,03,02,01,00,99,98,97,96,95,94,93,92

Waste Class: 213 - PETROLEUM DISTILLATES
Reported Years: 04,03,02,01,00,99,98,97,96,95,94

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 04,03,02,01,00,99,98,97,96,95,94,93,92

Waste Class: 148 - INORGANIC LABORATORY CHEMICALS
Reported Years: 04,03,02,01,00,99,98,97,96,95,94,93,92

Waste Class: 243 - PCBS
Reported Years: 01,00,99,98,97,96,95,94

Waste Class: 263 - ORGANIC LABORATORY CHEMICALS
Reported Years: 04,03,02,01,00,99,98,97,96,95,94,93,92

2004 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2003 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2002 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2001 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

2001 Manifest Summary

Waste Code:	148	***Waste Char Code:***	A
Waste Description:	INORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	54.0	***Waste Count:***	2
Waste Code:	263	***Waste Char Code:***	A
Waste Description:	ORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1.0	***Waste Count:***	1

2000 Generator Info

SIC Code:	8511	***SIC Description:***	ELEMT./SECON. EDUC.

1999 Generator Info

SIC Code:	8511	***SIC Description:***	ELEMT./SECON. EDUC.

1999 Manifest Summary

Waste Code:	252	***Waste Char Code:***	T
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	LEACHATE TOXIC
Quantity (kg):	160.0	***Waste Count:***	2
Waste Code:	213	***Waste Char Code:***	I
Waste Description:	PETROLEUM DISTILLATES	***Waste Char Desc:***	IGNITABLE
Quantity (kg):	160.0	***Waste Count:***	1
Waste Code:	263	***Waste Char Code:***	A
Waste Description:	ORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	75.0	***Waste Count:***	1
Waste Code:	148	***Waste Char Code:***	A
Waste Description:	INORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	120.0	***Waste Count:***	2

1998 Generator Info

SIC Code:	8511	***SIC Description:***	ELEMT./SECON. EDUC.

1998 Manifest Summary

Waste Code:	252	***Waste Char Code:***	T
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	LEACHATE TOXIC
Quantity (kg):	458.0	***Waste Count:***	1

1997 Generator Info

SIC Code:	8511	***SIC Description:***	ELEMT./SECON. EDUC.

1996 Generator Info

SIC Code:	8511	***SIC Description:***	ELEMT./SECON. EDUC.

1995 Generator Info

SIC Code:	8511	***SIC Description:***	ELEMT./SECON. EDUC.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

1994 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1993 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1992 Generator Info

SIC Code: 8511 ***SIC Description:*** ELEMT./SECON. EDUC.

1992 Manifest Summary

Waste Code: 252 ***Waste Char Code:***
Waste Description: WASTE OILS & LUBRICANTS ***Waste Char Desc:***
Quantity (kg): 368 ***Waste Count:*** 1

---

11 ***1 of 1*** ***E/123.0*** ***59.6 / -0.32*** ***Mr Pierre Larose*** ***GEN***
353 Lacasse
Vanier ON K1L 7B1

Generator No.: ON8134889
Years Reported: 04,03,02

Alternate Locations

Generator No: ON8134889
Generator Nm: MR PIERRE LAROSE
Site Addr: 353 LACASSE
City: VANIER
Reported Year(s): 04,03,02

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 04,03,02

2004 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2003 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2002 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	1 of 1	ENE/127.1	59.7 / -0.20	Pierre Seguin In Trust 345/347 Lacasse St Ottawa ON K1L 7B1	GEN

Generator No.: ON8554009
Years Reported: 04,03,02

Alternate Locations

Generator No: ON8554009
Generator Nm: PIERRE SEGUIN IN TRUST
Site Addr: 345/347 LACASSE ST
City: OTTAWA
Reported Year(s): 04,03,02

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 04,03,02

2004 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2003 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2002 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	1 of 1	E/128.2	59.6 / -0.32	355 Lacasse Avenue, Ottawa ON	PINC

Incident Id: 2653296
Incident No: 496978
Incident Reported Dt:
Type: FS-Pipeline Incident
Status Code: Pipeline Damage Reason Est
Tank Status: RC Established
Task No: 3158011
Spills Action Centre:
Fuel Type: Natural Gas
Fuel Occurrence Tp: Pipeline Strike
Date of Occurrence: 10/14/2010 0:00
Occurrence Start Dt: 2011/05/19
Depth: 35
Customer Acct Name:
Incident Address:

Pipe Material: Plastic
Fuel Category: Natural Gas
Health Impact: No
Environment Impact: No
Property Damage: Yes
Service Interrupt: Yes
Enforce Policy: Yes
Public Relation: No
Pipeline System:
PSIG: 40
Attribute Category: FS-Perform P-line Inc Invest
Regulator Location: Outside
Method Details: E-mail

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Operation Type: Construction Site (pipeline strike)
Pipeline Type: Service / Riser Distribution Pipeline
Regulator Type: Service Regulator (up to 60 psi intake)
Summary: 355 Lacasse Avenue, Ottawa - 1" Pipeline Hit
Reported By: Armstrong, Alan - Enbridge
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
Occurrence Desc: storm drain install
Damage Reason: Excavation practices not sufficient
Notes: DAMAGED WHILE BACKFILLING

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	1 of 1	N/130.4	59.9 / 0.00	279 Blake Blvd Vanier ON K1L 6L6	EHS

Order No: 20190813051
Status: C
Report Type: Custom Report
Report Date: 19-AUG-19
Date Received: 13-AUG-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .15
X: -75.657405
Y: 45.433996

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	1 of 1	SSW/131.4	60.9 / 1.00	EASTVIEW ANIMAL HOSPITAL 261 MCARTHUR STREET VANIER ON K1L 6P3	GEN

Generator No.: ON1800400
Years Reported: 01,00,99,98,97,96,95,94,93

Alternate Locations

Generator No: ON1800400
Generator Nm: EASTVIEW ANIMAL HOSPITAL
Site Addr: 261 MCARTHUR STREET
City: VANIER
Reported Year(s): 01,00,99,98,97,96,95,94,93

Waste Reported

Waste Class: 264 - PHOTOPROCESSING WASTES
Reported Years: 01,00,99,98,97,96,95,94,93

2001 Generator Info

SIC Code: 0211 **SIC Description:** VETERINARY SERVICE

2000 Generator Info

SIC Code: 0211 **SIC Description:** VETERINARY SERVICE

1999 Generator Info

SIC Code: 0211 **SIC Description:** VETERINARY SERVICE

1998 Generator Info

SIC Code: 0211 **SIC Description:** VETERINARY SERVICE

1998 Manifest Summary

Waste Code:	264	***Waste Char Code:***	C
Waste Description:	PHOTOPROCESSING WASTES	***Waste Char Desc:***	CORROSIVE
Quantity (kg):	40.0	***Waste Count:***	1
Waste Code:	264	***Waste Char Code:***	T
Waste Description:	PHOTOPROCESSING WASTES	***Waste Char Desc:***	LEACHATE TOXIC
Quantity (kg):	20.0	***Waste Count:***	1

1997 Generator Info

SIC Code:	0211	***SIC Description:***	VETERINARY SERVICE

1997 Manifest Summary

Waste Code:	264	***Waste Char Code:***	C
Waste Description:	PHOTOPROCESSING WASTES	***Waste Char Desc:***	CORROSIVE
Quantity (kg):	40.0	***Waste Count:***	1

1996 Generator Info

SIC Code:	0211	***SIC Description:***	VETERINARY SERVICE

1996 Manifest Summary

Waste Code:	264	***Waste Char Code:***	C
Waste Description:	PHOTOPROCESSING WASTES	***Waste Char Desc:***	CORROSIVE
Quantity (kg):	60	***Waste Count:***	1

1995 Generator Info

SIC Code:	0211	***SIC Description:***	VETERINARY SERVICE

1995 Manifest Summary

Waste Code:	264	***Waste Char Code:***	C
Waste Description:	PHOTOPROCESSING WASTES	***Waste Char Desc:***	CORROSIVE
Quantity (kg):	20	***Waste Count:***	1
Waste Code:	264	***Waste Char Code:***	T
Waste Description:	PHOTOPROCESSING WASTES	***Waste Char Desc:***	LEACHATE TOXIC
Quantity (kg):	20	***Waste Count:***	1
Waste Code:	264	***Waste Char Code:***	C
Waste Description:	PHOTOPROCESSING WASTES	***Waste Char Desc:***	CORROSIVE
Quantity (kg):	40	***Waste Count:***	1

1994 Generator Info

SIC Code:	0211	***SIC Description:***	VETERINARY SERVICE

1994 Manifest Summary

Waste Code:	264	***Waste Char Code:***	
Waste Description:	PHOTOPROCESSING WASTES	***Waste Char Desc:***	
Quantity (kg):	215.0	***Waste Count:***	4.0

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

1993 Generator Info

SIC Code: 0211 ***SIC Description:*** VETERINARY SERVICE

---

16 ***1 of 1*** ***ENE/132.2*** ***59.7 / -0.20*** ***345-347 Lacasse Avenue Ottawa ON*** ***EHS***

Order No: 20150225112
Status: C
Report Type: Custom Report
Report Date: 04-MAR-15
Date Received: 25-FEB-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.656008
Y: 45.433296

---

17 ***1 of 4*** ***ENE/135.2*** ***59.9 / 0.00*** ***Ontario Petroleum Pump 310 Blake Blvd Ottawa ON*** ***GEN***

Generator No.: ON4674220
Years Reported: 08,07

Alternate Locations

Generator No: ON4674220
Generator Nm: ONTARIO PETROLEUM PUMP
Site Addr: 310 BLAKE BLVD
City: OTTAWA
Reported Year(s): 08,07

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 08,07

2008 Generator Info

NAICS Code 1: 238990
NAICS 1 Description: All Other Specialty Trade Contractors
Contaminated Facility: N
MHSW Facility: N

2008 Manifest Summary

Waste Code: 221
Waste Description: LIGHT FUELS
Quantity (kg): 300.0

Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

2007 Generator Info

NAICS Code 1: 238990
NAICS 1 Description: All Other Specialty Trade Contractors
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2007 Manifest Summary

Waste Code:	221	***Waste Char Code:***	L
Waste Description:	LIGHT FUELS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	300.0	***Waste Count:***	1

---

17 ***2 of 4*** ***ENE/135.2*** ***59.9 / 0.00*** ***Ontario Petroleum Pump*** ***GEN***
310 Blake Blvd
Ottawa ON

Generator No.:	ON2931558
Years Reported:	12

Alternate Locations

Generator No:	ON2931558
Generator Nm:	ONTARIO PETROLEUM PUMP
Site Addr:	310 BLAKE BLVD
City:	OTTAWA
Reported Year(s):	12

2012 Generator Info

NAICS Code 1:	238990
NAICS 1 Description:	All Other Specialty Trade Contractors
Contaminated Fac:	N
MHSW Facility:	N

2012 Manifest Summary

Waste Code:	221	***Waste Char Code:***	L
Waste Description:	LIGHT FUELS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	410.0	***Waste Count:***	1

---

17 ***3 of 4*** ***ENE/135.2*** ***59.9 / 0.00*** ***David Bunner*** ***GEN***
310 Blake Blvd
Vanier ON K1L 6L5

Generator No.:	ON6377726
Years Reported:	14

Alternate Locations

Generator No:	ON6377726
Generator Nm:	DAVID BUNNER
Site Addr:	310 BLAKE BLVD
City:	VANIER
Reported Year(s):	14

Waste Reported

Waste Class:	221 - LIGHT FUELS
Reported Years:	14

2014 Generator Info

NAICS Code 1:	813990
NAICS 1 Description:	Other Membership Organizations
Contaminated Fac:	N

MHSW Facility: N

2014 Manifest Summary

Waste Code:	221	***Waste Char Code:***	L
Waste Description:	LIGHT FUELS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	314.0	***Waste Count:***	1

---

17 ***4 of 4*** ***ENE/135.2*** ***59.9 / 0.00*** ***David Bunner*** ***GEN***
310 Blake Blvd
Vanier ON K1L 6L5

Generator No.: ON4971167
Years Reported: 16,15

Alternate Locations

Generator No: ON4971167
Generator Nm: DAVID BUNNER
Site Addr: 310 BLAKE BLVD
City: VANIER
Reported Year(s): 16,15

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 16,15

2016 Generator Info

NAICS Code 1: 531111
NAICS 1 Description: Lessors of Residential Buildings and Dwellings (except Social Housing Projects)
Contaminated Fac: N
MHSW Facility: N

2016 Manifest Summary

Waste Code:	221	***Waste Char Code:***	L
Waste Description:	LIGHT FUELS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	10700.0	***Waste Count:***	1

2015 Generator Info

NAICS Code 1: 531111
NAICS 1 Description: Lessors of Residential Buildings and Dwellings (except Social Housing Projects)
Contaminated Fac: N
MHSW Facility: N

2015 Manifest Summary

Waste Code:	221	***Waste Char Code:***	L
Waste Description:	LIGHT FUELS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	950.0	***Waste Count:***	1

---

18 ***1 of 1*** ***ENE/137.5*** ***59.9 / 0.00*** ***ON*** ***WWIS***

Well ID: 7169780 ***Flowing (Y/N):***

Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	10/12/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	M10572	**Contractor:**	7241
Tag:	A106605	**Form Version:**	5
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	VANIER CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7169780.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/20/2011
Year Completed:	2011
Depth (m):	
Latitude:	45.4335991290857
Longitude:	-75.6561869974686
Point X:	-75.65618683490572
Point Y:	45.43359912214173
Path:	716\7169780.pdf

Bore Hole Information

Bore Hole ID:	1003578452	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448674.00
Code OB Desc:		**North83:**	5031329.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	09/20/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

19 **1 of 1** **ENE/137.7** **59.9 / 0.00** **310 BLAKE BLVD. OTTAWA ON** **WWIS**

Well ID:	7170716	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	11/01/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z140230	**Contractor:**	7241

Tag:	A106634	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	VANIER CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7170716.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/11/2011
Year Completed:	2011
Depth (m):	4.88
Latitude:	45.4335902018775
Longitude:	-75.6561741093126
Point X:	-75.65617394678137
Point Y:	45.43359019533753
Path:	717\7170716.pdf

Bore Hole Information

Bore Hole ID:	1003593220	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448675.00
Code OB Desc:		**North83:**	5031328.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/11/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003975475
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.6100000143051147
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1003975477
Layer:	3
Color:	8
General Color:	BLACK
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	3.0999999046325684
Formation End Depth:	4.880000114440918
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1003975476
Layer:	2
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.6100000143051147
Formation End Depth:	3.0999999046325684
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003975486
Layer:	2
Plug From:	0.3100000023841858
Plug To:	1.5
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003975485
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003975487
Layer:	3
Plug From:	1.5
Plug To:	4.880000114440918
Plug Depth UOM:	m

Method of Construction & Well

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Use

Method Construction ID: 1003975484
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1003975474
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003975480
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.8300000429153442
Casing Diameter: 3.450000047683716
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003975481
Layer: 1
Slot: 10
Screen Top Depth: 1.8300000429153442
Screen End Depth: 4.880000114440918
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.210000038146973

Water Details

Water ID: 1003975479
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1003975478
Diameter: 8.25
Depth From: 0.0
Depth To: 4.880000114440918
Hole Depth UOM: m
Hole Diameter UOM: cm

20	*1 of 1*	*SW/138.9*	*60.9 / 1.00*	***Vanier Animal Hospital*** ***257 McArthur Avenue*** ***Ottawa ON K1L 6P3***	*GEN*

Generator No.: ON001064183

Years Reported: 25,24

Alternate Locations

Generator No: ON001064183
Generator Nm: VANIER ANIMAL HOSPITAL
Site Addr: 257 MCARTHUR AVENUE
City: OTTAWA
Reported Year(s): 25,24

2025 Generator Info

Waste Reported

Waste Class: 261 - PHARMACEUTICALS
Reported Years: 24

Waste Class: 312 - PATHOLOGICAL WASTES
Reported Years: 24

2025 Waste Info

Waste Code: 261
Waste Description: Pharmaceuticals
Waste Char Cd: A
Waste Char Desc: Acutely Hazardous Waste Chem.

Waste Code: 312
Waste Description: Pathological Wastes
Waste Char Cd: P
Waste Char Desc: Pathological

2024 Generator Info

NAICS Code: 541940
NAICS Description: Veterinary Services
Contamin'd Fac: No
MHSW Facility: No

2024 Manifest Summary

Waste Code: 261
Waste Description: Pharmaceuticals
Qty Received (kg): 7
Waste Char Code: A
Waste Char Desc: Acutely Hazardous Waste Chem.
Waste Count: 1

Waste Code: 312
Waste Description: Pathological Wastes
Qty Received (kg): 22.099999999999998
Waste Char Code: P
Waste Char Desc: Pathological
Waste Count: 6

21	1 of 1	SW/139.3	60.9 / 1.00	257 Mcarthur Ave Ottawa ON K1L6P3	EHS

Order No: 20180319024
Status: C
Report Type: Standard Report
Report Date: 23-MAR-18
Date Received: 19-MAR-18
Previous Site Name:
Lot/Building Size: 7500 square feet
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.658333
Y: 45.431697

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	1 of 1	N/143.7	59.9 / 0.00	285 Blake Boulevard Vanier ON K1L 6L6	EHS

Order No:	21061000704	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	15-JUN-21	**Search Radius (km):**	.25
Date Received:	10-JUN-21	**X:**	-75.6577785
Previous Site Name:		**Y:**	45.4341117
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	1 of 1	ENE/144.6	59.9 / 0.00	310 BLAKE BLVD. OTTAWA ON	WWIS

Well ID:	7170715	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	11/01/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z140231	**Contractor:**	7241
Tag:	A106635	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	VANIER CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7170715.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/11/2011
Year Completed:	2011
Depth (m):	4.42
Latitude:	45.4335460798124
Longitude:	-75.6560201817512
Point X:	-75.65602001961392
Point Y:	45.43354607316033
Path:	717\7170715.pdf

Bore Hole Information

Bore Hole ID:	1003593218	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448687.00
Code OB Desc:		**North83:**	5031323.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/11/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1003975354
Layer: 2
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 28
Material 2 Desc: SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.3100000023841858
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003975356
Layer: 4
Color: 8
General Color: BLACK
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 71
Material 3 Desc: FRACTURED
Formation Top Depth: 2.440000057220459
Formation End Depth: 4.420000076293945
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003975353
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003975355
Layer: 3

Color:	8
General Color:	BLACK
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.6100000143051147
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003975365
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003975366
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.5899999141693115
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003975367
Layer:	3
Plug From:	2.5899999141693115
Plug To:	4.420000076293945
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1003975364
Method Construction Code:	7
Method Construction:	Diamond
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1003975352
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003975360
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0

Depth To:	2.890000104904175
Casing Diameter:	3.950000047683716
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003975361
Layer:	1
Slot:	10
Screen Top Depth:	2.890000104904175
Screen End Depth:	4.420000076293945
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.210000038146973

Water Details

Water ID:	1003975359
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1003975358
Diameter:	5.710000038146973
Depth From:	2.440000057220459
Depth To:	4.420000076293945
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1003975357
Diameter:	8.25
Depth From:	0.0
Depth To:	2.440000057220459
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

24 | ***1 of 1*** | ***ENE/145.9*** | ***59.9 / 0.00*** | ***310-316 Blake Boulevard Vanier ON K1L 6L5*** | ***EHS***

Order No:	21090100284	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	07-SEP-21	**Search Radius (km):**	.25
Date Received:	01-SEP-21	**X:**	-75.6561993
Previous Site Name:		**Y:**	45.4337237
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

---

25 | ***1 of 1*** | ***ENE/146.0*** | ***59.9 / 0.00*** | ***310 BLAKE BLVD. 316 Ottawa ON*** | ***WWIS***

Well ID:	7178879	**Flowing (Y/N):**	

Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	04/03/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z134651	**Contractor:**	6964
Tag:	A119045	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1003708025	**Tag No:**	A119045
Depth (m):	5.17	**Contractor:**	6964
Year Completed:	2011	**Latitude:**	45.4337072103203
Well Completed Dt:	11/28/2011	**Longitude:**	-75.6561754653402
Audit No:	Z134651	**Point Y:**	45.433707203110295
Path:		**Point X:**	-75.65617530322707

Bore Hole Information

Bore Hole ID:	1003708025	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448675.00
Code OB Desc:		**North83:**	5031341.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/28/2011	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004237190
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	12
Material 2 Desc:	STONES
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.10000000149011612
Formation End Depth:	0.75

Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004237191
Layer: 3
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 0.75
Formation End Depth: 2.450000047683716
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004237192
Layer: 4
Color:
General Color:
Material 1: 26
Material 1 Desc: ROCK
Material 2: 15
Material 2 Desc: LIMESTONE
Material 3:
Material 3 Desc:
Formation Top Depth: 2.450000047683716
Formation End Depth: 5.170000076293945
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004237189
Layer: 1
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.10000000149011612
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004237199
Layer: 1
Plug From: 0.0
Plug To: 2.799999952316284
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1004237200
Layer:	2
Plug From:	2.799999952316284
Plug To:	4.900000095367432
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004237198
Method Construction Code:	7
Method Construction:	Diamond
Other Method Construction:	

Pipe Information

Pipe ID:	1004237188
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004237196
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0999999046325684
Casing Diameter:	3.5
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004237197
Layer:	1
Slot:	10
Screen Top Depth:	3.0999999046325684
Screen End Depth:	4.900000095367432
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.099999904632568

Water Details

Water ID:	1004237195
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	3.8499999046325684
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004237194
Diameter:	5.599999904632568

Depth From: 2.5
Depth To: 5.170000076293945
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004237193
Diameter: 7.5
Depth From: 0.0
Depth To: 2.5
Hole Depth UOM: m
Hole Diameter UOM: cm

---

26 | **1 of 2** | **ESE/146.0** | **59.9 / 0.00** | **PESTROY INC./DUTCH JANITORIAL SERVICES LTD.**
369 LACASSE AVENUE 8036
OTTAWA ON K1G 3H6 | **PES**

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type:
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

26 | **2 of 2** | **ESE/146.0** | **59.9 / 0.00** | **PESTROY INC./AARBRU**
369 LACASSE AVENUE
OTTAWA ON K1H 6S6 | **PES**

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
27	1 of 1	NE/147.1	59.9 / 0.00	310-316 Blake Blvd. Ottawa ON	EHS

Order No:	20160809052	**Nearest Intersection:**	
Status:	C	**Municipality:**	Ottawa
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	15-AUG-16	**Search Radius (km):**	.25
Date Received:	09-AUG-16	**X:**	-75.656213
Previous Site Name:		**Y:**	45.43375
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	1 of 1	S/147.6	60.9 / 1.00	MCARTHUR AVE. Ottawa ON	WWIS

Well ID:	7221190	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	05/30/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z186815	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221190.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/01/2014
Year Completed:	2014
Depth (m):	
Latitude:	45.4315021553044
Longitude:	-75.6576968031593
Point X:	-75.65769664116577
Point Y:	45.431502148180854
Path:	722\7221190.pdf

Bore Hole Information

Bore Hole ID:	1004795858	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448554.00
Code OB Desc:		**North83:**	5031097.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/01/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1005169042
Layer: 2
Plug From: 0.9100000262260437
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005169041
Layer: 1
Plug From: 0.0
Plug To: 0.9100000262260437
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005169040
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005169033
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005169038
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.2200000286102295
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005169039
Layer: 1
Slot: 10
Screen Top Depth: 1.2200000286102295
Screen End Depth: 3.6600000858306885
Screen Material: 5
Screen Depth UOM: m

Screen Diameter UOM: cm
Screen Diameter: 6.03000020980835

Water Details

Water ID: 1005169037
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005169036
Diameter: 5.199999809265137
Depth From: 2.140000104904175
Depth To: 3.6600000858306885
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005169035
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 2.140000104904175
Hole Depth UOM: m
Hole Diameter UOM: cm

---

29 | **1 of 1** | **ENE/148.5** | **59.9 / 0.00** | **310 BRAKE BLVD. OTTAWA ON** | **WWIS**

Well ID: 7170717
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z140223
Tag: A106633
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: VANIER CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/01/2011
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7170717.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/13/2011
Year Completed: 2011
Depth (m): 4.88
Latitude: 45.4336448666831

Longitude: -75.6560596804591
Point X: -75.65605951761717
Point Y: 45.43364485992679
Path: 717\7170717.pdf

Bore Hole Information

Bore Hole ID: 1003593222
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/13/2011
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448684.00
North83: 5031334.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1003975538
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003975540
Layer: 3
Color: 8
General Color: BLACK
Material 1: 28
Material 1 Desc: SAND
Material 2: 06
Material 2 Desc: SILT
Material 3:
Material 3 Desc:
Formation Top Depth: 0.6100000143051147
Formation End Depth: 2.440000057220459
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003975541

Layer: 4
Color: 8
General Color: BLACK
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 71
Material 3 Desc: FRACTURED
Formation Top Depth: 2.440000057220459
Formation End Depth: 4.880000114440918
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003975539
Layer: 2
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 28
Material 2 Desc: SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.3100000023841858
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003975550
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003975551
Layer: 2
Plug From: 0.3100000023841858
Plug To: 2.740000009536743
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003975552
Layer: 3
Plug From: 2.740000009536743
Plug To: 4.880000114440918
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1003975549
Method Construction Code: 7

Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 1003975537
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003975545
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 3.1500000953674316
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003975546
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 4.880000114440918
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.210000038146973

Water Details

Water ID: 1003975544
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1003975543
Diameter: 5.710000038146973
Depth From: 2.440000057220459
Depth To: 4.880000114440918
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1003975542
Diameter: 8.25
Depth From: 0.0
Depth To: 2.440000057220459
Hole Depth UOM: m
Hole Diameter UOM: cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
30	1 of 1	ENE/150.9	59.9 / 0.00	318-316 BLAKE BOULEVARD Ottawa ON	WWIS

Well ID: 7195008
Construction Date:
Use 1st: Test Hole
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z150542
Tag: A119044
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 01/09/2013
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6964
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1004232708
Depth (m): 4.48
Year Completed: 2012
Well Completed Dt: 04/30/2012
Audit No: Z150542
Path:

Tag No: A119044
Contractor: 6964
Latitude: 45.4336450869603
Longitude: -75.6560213288877
Point Y: 45.43364507992742
Point X: -75.65602116675376

Bore Hole Information

Bore Hole ID: 1004232708
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/30/2012
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448687.00
North83: 5031334.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004754599
Layer: 1
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2:

Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.019999999552965164
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004754601
Layer: 3
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 81
Material 2 Desc: SANDY
Material 3: 06
Material 3 Desc: SILT
Formation Top Depth: 0.9100000262260437
Formation End Depth: 2.2799999713897705
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004754600
Layer: 2
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 06
Material 2 Desc: SILT
Material 3: 05
Material 3 Desc: CLAY
Formation Top Depth: 0.019999999552965164
Formation End Depth: 0.9100000262260437
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004754602
Layer: 4
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2: 17
Material 2 Desc: SHALE
Material 3: 26
Material 3 Desc: ROCK
Formation Top Depth: 2.2799999713897705
Formation End Depth: 4.480000019073486
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004754610

Layer: 1
Plug From: 0.0
Plug To: 2.9000000953674316
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004754611
Layer: 2
Plug From: 2.9000000953674316
Plug To: 4.480000019073486
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004754609
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 1004754598
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004754606
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.359999895095825
Casing Diameter: 3.5
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004754607
Layer: 1
Slot: 10
Screen Top Depth: 3.359999895095825
Screen End Depth: 4.480000019073486
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.099999904632568

Water Details

Water ID: 1004754605
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID:	1004754604
Diameter:	3.5999999046325684
Depth From:	2.299999952316284
Depth To:	4.480000019073486
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1004754603
Diameter:	7.5
Depth From:	0.0
Depth To:	2.299999952316284
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

31 ***1 of 1*** ***ENE/152.9*** ***59.9 / 0.00*** ***310 BLAKE BLVD OTTAWA ON*** ***WWIS***

Well ID:	7257961	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	02/17/2016
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z222323	***Contractor:***	7241
Tag:	A164320	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/725\7257961.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/22/2016
Year Completed:	2016
Depth (m):	4.57
Latitude:	45.4336005242264
Longitude:	-75.6559441043782
Point X:	-75.65594394221147
Point Y:	45.4336005171611
Path:	725\7257961.pdf

Bore Hole Information

Bore Hole ID:	1005888717	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448693.00

Code OB Desc:		***North83:***	5031329.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/22/2016	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005985378
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	08
Material 1 Desc:	FINE SAND
Material 2:	
Material 2 Desc:	
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.6100000143051147
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005985377
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.6100000143051147
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005985385
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005985386
Layer:	2
Plug From:	0.3100000023841858

Plug To: 2.7899999618530273
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005985387
Layer: 3
Plug From: 2.7899999618530273
Plug To: 4.570000171661377
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005985384
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005985376
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005985381
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005985382
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 4.570000171661377
Screen Material: 1
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03000020980835

Water Details

Water ID: 1005985380
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Hole Diameter

Hole ID:	1005985379
Diameter:	15.229999542236328
Depth From:	0.0
Depth To:	4.570000171661377
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

32 | ***1 of 1*** | ***NE/153.6*** | ***59.9 / 0.00*** | ***R.M. OF OTTAWA-CARLETON LACASSE AVE./BLAKE BLVD./LEWIS VANIER CITY ON*** | ***CA***

Certificate No:	7-0020-91-
Ref No:	
Contaminants:	
Application Year:	91
Issue Date:	1/25/1991
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Emission Control:	
Address:	

---

33 | ***1 of 1*** | ***ENE/155.0*** | ***59.9 / 0.00*** | ***ON*** | ***WWIS***

Well ID:	7195009	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	01/09/2013
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	C18261	***Contractor:***	6964
Tag:	A119044	***Form Version:***	8
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	VANIER CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7195009.pdf

Additional Detail(s) (Map)

Well Completed Date:	04/30/2012
Year Completed:	2012
Depth (m):	

Latitude:	45.4336454540602
Longitude:	-75.6559574096011
Point X:	-75.6559572480492
Point Y:	45.433645447435616
Path:	719\7195009.pdf

Bore Hole Information

Bore Hole ID:	1004232711	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448692.00
Code OB Desc:		**North83:**	5031334.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	04/30/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

34 | ***1 of 1*** | ***S/159.4*** | ***60.9 / 1.00*** | ***256 MCAURTHUR AVE. Ottawa ON*** | ***WWIS***

Well ID:	7221188	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	05/30/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z186816	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221188.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/01/2014
Year Completed:	2014
Depth (m):	
Latitude:	45.4313942947156
Longitude:	-75.6576699819462
Point X:	-75.65766982018437
Point Y:	45.43139428804202
Path:	722\7221188.pdf

Bore Hole Information

Bore Hole ID:	1004795852	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448556.00
Code OB Desc:		***North83:***	5031085.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	05/01/2014	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005169016
Layer:	1
Plug From:	0.0
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005169017
Layer:	2
Plug From:	0.9100000262260437
Plug To:	3.6600000858306885
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1005169015
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1005169008
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005169013
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.2200000286102295
Casing Diameter:	5.199999809265137
Casing Diameter UOM:	cm

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005169014
Layer: 1
Slot: 5
Screen Top Depth: 1.2200000286102295
Screen End Depth: 3.6600000858306885
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03000020980835

Water Details

Water ID: 1005169012
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005169010
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 2.140000104904175
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005169011
Diameter: 5.199999809265137
Depth From: 2.140000104904175
Depth To: 3.6600000858306885
Hole Depth UOM: m
Hole Diameter UOM: cm

---

35 ***1 of 1*** ***W/159.6*** ***59.9 / 0.00*** ***ON*** ***BORE***

Borehole ID: 613627
OGF ID: 215514863
Status:
Type: Borehole
Use:
Completion Date: SEP-1970
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 4.1
Depth Ref: Ground Surface
Depth Elev:
Drill Method:
Orig Ground Elev m: 64.4
Elev Reliabil Note:
DEM Ground Elev m: 63.5
Concession:
Location D:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 45.433158
Longitude DD: -75.659548
UTM Zone: 18
Easting: 448411
Northing: 5031282
Location Accuracy:
Accuracy: Not Applicable

Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218395884
Top Depth: 1.2
Bottom Depth: 1.7
Material Color:
Material 1:
Material 2: Sand
Material 3: Silt
Material 4: Shale
Gsc Material Description:
Stratum Description: ARTIFICIAL.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395882
Top Depth: .3
Bottom Depth: .8
Material Color:
Material 1:
Material 2: Sand
Material 3: Silt
Material 4: Bedrock
Gsc Material Description:
Stratum Description: ARTIFICIAL.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395887
Top Depth: 3
Bottom Depth: 3.9
Material Color:
Material 1: Bedrock
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: BEDROCK.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395885
Top Depth: 1.7
Bottom Depth: 2.1
Material Color: Red
Material 1: Shale
Material 2: Till
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SHALE. WEATHERED.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395883
Top Depth: .8
Bottom Depth: 1.2
Material Color:
Material 1:
Material 2: Sand
Material 3: Silt
Material 4: Bedrock
Gsc Material Description:
Stratum Description: ARTIFICIAL.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395888
Top Depth: 3.9
Bottom Depth: 4.1
Material Color:
Material 1: Bedrock
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:

Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: BEDROCK. 00010 008 00025 009 00040 010 00055 005 00070 007 000100450002502900 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395881
Top Depth: 0
Bottom Depth: .3
Material Color:
Material 1: Unknown
Material 2: Soil
Material 3: Sand
Material 4:
Gsc Material Description:
Stratum Description: UNSPECIFIED.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218395886
Top Depth: 2.1
Bottom Depth: 3
Material Color:
Material 1: Till
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: TILL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: H
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 061350 NTS_Sheet: 31G05G
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

36 | ***1 of 3*** | ***W/160.4*** | ***59.9 / 0.00*** | ***349 Olmstead St Ottawa ON K1L1B1*** | ***EHS***

Order No: 20150507018
Status: C
Report Type: Custom Report
Report Date: 13-MAY-15
Date Received: 07-MAY-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.658802
Y: 45.432535

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	2 of 3	W/160.4	59.9 / 0.00	AWD Contractors 349 Olmstead Street Ottawa ON K1L 7K2	GEN

Generator No.: ON001059319
Years Reported: 25,23

Alternate Locations

Generator No: ON001059319
Generator Nm: AWD CONTRACTORS
Site Addr: 349 OLMSTEAD STREET
City: OTTAWA
Reported Year(s): 25,23

2025 Generator Info

Waste Reported

Waste Class: 146 - OTHER SPECIFIED INORGANICS
Reported Years: 23

2025 Waste Info

Waste Code: 146
Waste Description: Other Specified Inorganics
Waste Char Cd: L
Waste Char Desc: Liquid Industrial Waste

2023 Generator Info

NAICS Code: 236210
NAICS Description: Industrial Building and Structure Construction
Contamin'd Fac: No
MHSW Facility: No

2023 Manifest Summary

Waste Code: 146
Waste Description: Other Specified Inorganics
Qty Received (kg): 23120
Waste Char Code: L
Waste Char Desc: Liquid Industrial Waste
Waste Count: 2

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	3 of 3	W/160.4	59.9 / 0.00	Elementary School Catholic Horizon-Jeunesse 349 Olmstead Street Ottawa ON K1L 7K2	GEN

Generator No.: ON7034415
Years Reported: 21

Alternate Locations

Generator No: ON7034415
Generator Nm: ELEMENTARY SCHOOL CATHOLIC HORIZON-JEUNESSE
Site Addr: 349 OLMSTEAD STREET
City: OTTAWA
Reported Year(s): 21

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 21

2021 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Fac: N
MHSW Facility: N

2021 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 2000.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

Waste Code: 221
Waste Description: LIGHT FUELS
Quantity (kg): 7450.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

---

37 | **1 of 1** | **N/160.6** | **59.9 / 0.00** | **292 Blake Blvd VANIER ON** | **WWIS**

Well ID: 7358212
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z322230
Tag: A259022
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: VANIER CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/15/2020
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7323
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7358212.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/27/2019
Year Completed: 2019
Depth (m): 2.1336
Latitude: 45.4342650597313
Longitude: -75.6577800364453
Point X: -75.65777987430631
Point Y: 45.434265052986824
Path: 735\7358212.pdf

Bore Hole Information

Bore Hole ID: 1008280383
DP2BR:
Spatial Status:
Elevation:
Elevrc:
Zone: 18

Code OB:		***East83:***	448550.00
Code OB Desc:		***North83:***	5031404.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	11/27/2019	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008387119
Layer:	2
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	5.0
Formation End Depth:	7.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008387118
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008388144
Layer:	1
Plug From:	0.0
Plug To:	2.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008388145
Layer:	2

Plug From: 2.0
Plug To: 7.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008389216
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1008386067
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008389643
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0
Casing Diameter: 2.0
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008390057
Layer: 1
Slot: .10
Screen Top Depth: 3.0
Screen End Depth: 7.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008390623
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1008388727
Diameter:	6.0
Depth From:	0.0
Depth To:	7.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

---

38 ***1 of 3*** ***E/160.9*** ***58.9 / -1.00*** ***309 McArthur Avenue Ottawa ON*** ***EHS***

Order No:	20031112010	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Site Report	***Client Prov/State:***	ON
Report Date:	11/13/03	***Search Radius (km):***	0.25
Date Received:	11/12/03	***X:***	-75.655533
Previous Site Name:		***Y:***	45.431837
Lot/Building Size:			
Additional Info Ordered:			

---

38 ***2 of 3*** ***E/160.9*** ***58.9 / -1.00*** ***Downtown Motor Sales 309 McArthur av Eastview ON*** ***HBAR***

Province:	ON
Year:	1964
Source:	Mights

---

38 ***3 of 3*** ***E/160.9*** ***58.9 / -1.00*** ***City of Ottawa 309 McArthur Ave Ottawa ON*** ***SPL***

Ref No:	4344-7QXPA2	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:		***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	4/9/2009	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Bernard Grandmaitre Arena		
Site Address:			
Site Region:			
Site Municipality:	Ottawa		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	NA		
Easting:	NA		
Entity Operating Name:			
Client Name:	City of Ottawa		
Client Type:			
Source Type:			
Incident Cause:	Other Discharges		

Incident Preceding Spill:	
Incident Reason:	Spill
Incident Summary:	City of Ottawa: Unkn Qty Diesel in CB, cln
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Other Impact(s)
Contaminant Qty:	3 L
Contaminant Qty 1:	3
Contaminant Unit:	L
Contaminant Code:	
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Sewer
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

39 ***1 of 1*** ***ENE/162.3*** ***59.7 / -0.20*** ***310 BLAKE BLVD. Ottawa ON*** ***WWIS***

Well ID:	7122676	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Test Hole	***Date Received:***	05/05/2009
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	M03142	***Contractor:***	6964
Tag:	A032194	***Form Version:***	5
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7122676.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/21/2008
Year Completed:	2008
Depth (m):	
Latitude:	45.4335989821987
Longitude:	-75.6562125651613

Point X: -75.65621240274687
Point Y: 45.43359897526441
Path: 712\7122676.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7122676.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/18/2008
Year Completed: 2008
Depth (m):
Latitude: 45.4334131253448
Longitude: -75.6556606709422
Point X: -75.65566050857787
Point Y: 45.43341311828004
Path: 712\7122676.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7122676.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/20/2008
Year Completed: 2008
Depth (m):
Latitude: 45.4336426632036
Longitude: -75.6564431961483
Point X: -75.65644303433609
Point Y: 45.43364265613822
Path: 712\7122676.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7122676.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/21/2008
Year Completed: 2008
Depth (m): 4.5
Latitude: 45.4334131253448
Longitude: -75.6556606709422
Point X: -75.65566050857787
Point Y: 45.43341311828004
Path: 712\7122676.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7122676.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/19/2008
Year Completed: 2008
Depth (m):
Latitude: 45.4335889531806
Longitude: -75.6563914346605
Point X: -75.65639127253283
Point Y: 45.433588945934495
Path: 712\7122676.pdf

Bore Hole Information

Bore Hole ID: 1002758532 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 18
Code OB: ***East83:***

Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 11/17/2008
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 1002758536
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002758535
Method Construction Code:
Method Construction:
Other Method Construction: DIAMOND DRILLING

Pipe Information

Pipe ID: 1002758537
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002758539
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.259999990463257
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002758538
Layer:
Slot:
Screen Top Depth: 2.259999990463257
Screen End Depth: 3.7799999713897705
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002758540
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002758534
Diameter: 5.0
Depth From:
Depth To: 3.7799999713897705
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002758541
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 11/18/2008
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 1002758545
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002758544
Method Construction Code:

Method Construction:
Other Method Construction: DIAMOND DRILLING

Pipe Information

Pipe ID: 1002758546
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002758548
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.0299999713897705
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002758547
Layer:
Slot:
Screen Top Depth: 2.0299999713897705
Screen End Depth: 3.559999942779541
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002758549
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002758543
Diameter: 5.0
Depth From:
Depth To: 3.559999942779541
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID:	1002758505	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448672.00
Code OB Desc:		***North83:***	5031329.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	11/21/2008	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002758509
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002758508
Method Construction Code:	
Method Construction:	
Other Method Construction:	DIAMOND DRILLING

Pipe Information

Pipe ID:	1002758510
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002758512
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	3.3499999046325684
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002758511
Layer:	
Slot:	

Screen Top Depth: 3.3499999046325684
Screen End Depth: 4.869999885559082
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002758513
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002758507
Diameter: 5.0
Depth From:
Depth To: 4.869999885559082
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002758550
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 11/20/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 18
East83: 448654.00
North83: 5031334.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002758554
Layer:
Plug From:
Plug To:

Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002758553
Method Construction Code:
Method Construction:
Other Method Construction: DIAMOND DRILLING

Pipe Information

Pipe ID: 1002758555
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002758557
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.300000190734863
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002758556
Layer:
Slot:
Screen Top Depth: 4.300000190734863
Screen End Depth: 5.510000228881836
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002758558
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002758552
Diameter: 5.0
Depth From:
Depth To: 5.510000228881836
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002758514
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 11/13/2008
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 1002758518
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002758517
Method Construction Code:
Method Construction:
Other Method Construction: DIAMOND DRILLING

Pipe Information

Pipe ID: 1002758519
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002758521
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.130000114440918
Casing Diameter:
Casing Diameter UOM:

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002758520
Layer:
Slot:
Screen Top Depth: 2.130000114440918
Screen End Depth: 3.6600000858306885
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002758522
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002758516
Diameter: 5.0
Depth From:
Depth To: 3.6600000858306885
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002758559
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 11/19/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448658.00
North83: 5031328.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID:	1002758563
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002758562
Method Construction Code:	
Method Construction:	
Other Method Construction:	DIAMOND DRILLING

Pipe Information

Pipe ID:	1002758564
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002758566
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	3.9600000381469727
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002758565
Layer:	
Slot:	
Screen Top Depth:	3.9600000381469727
Screen End Depth:	5.300000190734863
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002758567
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	

Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002758561
Diameter: 5.0
Depth From:
Depth To: 5.300000190734863
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002421536
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/21/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448715.00
North83: 5031308.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1002758570
Layer: 2
Color:
General Color:
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2: 26
Material 2 Desc: ROCK
Material 3:
Material 3 Desc:
Formation Top Depth: 3.0
Formation End Depth: 4.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002758569
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:

Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 3.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002758572
Layer: 1
Plug From: 0.0
Plug To: 3.2799999713897705
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002758573
Layer: 2
Plug From: 3.2799999713897705
Plug To: 4.5
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002758577
Method Construction Code: 9
Method Construction: Driving
Other Method Construction:

Pipe Information

Pipe ID: 1002758568
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002758574
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.5799999237060547
Casing Diameter: 3.5
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002758575
Layer: 1
Slot: 10
Screen Top Depth: 3.5799999237060547
Screen End Depth: 4.5
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm

Screen Diameter: 4.099999904632568

Hole Diameter

Hole ID: 1002758571
Diameter: 5.0
Depth From: 0.0
Depth To: 4.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002758496
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 11/18/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448715.00
North83: 5031308.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002758500
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002758499
Method Construction Code:
Method Construction:
Other Method Construction: DIAMOND DRILLING

Pipe Information

Pipe ID: 1002758501
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002758503
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:

Depth To: 3.5799999237060547
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002758502
Layer:
Slot:
Screen Top Depth: 3.5799999237060547
Screen End Depth: 4.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002758504
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002758498
Diameter: 5.0
Depth From:
Depth To: 4.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002758523
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 11/14/2008
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002758527
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002758526
Method Construction Code:
Method Construction:
Other Method Construction: DIAMOND DRILLING

Pipe Information

Pipe ID: 1002758528
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002758530
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.130000114440918
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002758529
Layer:
Slot:
Screen Top Depth: 2.130000114440918
Screen End Depth: 3.6600000858306885
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002758531
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:

Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002758525
Diameter: 5.0
Depth From:
Depth To: 3.6600000858306885
Hole Depth UOM: m
Hole Diameter UOM: cm

---

40 | ***1 of 1*** | ***NNE/162.5*** | ***59.9 / 0.00*** | ***297 Blake Boulevard Ottawa ON*** | ***WWIS***

Well ID: 7359571
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z231090
Tag: A251305
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/27/2020
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1844
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7359571.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/29/2020
Year Completed: 2020
Depth (m): 4.37
Latitude: 45.434259738355
Longitude: -75.6571407322847
Point X: -75.65714056958224
Point Y: 45.43425973135941
Path: 735\7359571.pdf

Bore Hole Information

Bore Hole ID: 1008287088
DP2BR:
Spatial Status:
Code OB:

Elevation:
Elevrc:
Zone: 18
East83: 448600.00

Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/29/2020
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

North83: 5031403.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008406647
Layer: 3
Color:
General Color:
Material 1: 12
Material 1 Desc: STONES
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 2.700000047683716
Formation End Depth: 3.049999952316284
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008406645
Layer: 1
Color:
General Color:
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008406646
Layer: 2
Color:
General Color:
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.30000001192092896
Formation End Depth: 2.700000047683716
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	1008406648
Layer:	4
Color:	8
General Color:	BLACK
Material 1:	34
Material 1 Desc:	TILL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	3.049999952316284
Formation End Depth:	4.369999885559082
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008406872
Layer:	1
Plug From:	0.30000001192092896
Plug To:	2.4000000953674316
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1008407120
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	

Pipe Information

Pipe ID:	1008406491
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008407196
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.15000000596046448
Depth To:	3.3499999046325684
Casing Diameter:	3.180000066757202
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008407333
Layer:	1
Slot:	25
Screen Top Depth:	3.3499999046325684
Screen End Depth:	4.369999885559082

Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 3.890000104904175

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008407461
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008407342
Layer: 1
Kind Code:
Kind:
Water Found Depth: 1.5299999713897705
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1008406981
Diameter: 8.890000343322754
Depth From: 0.0
Depth To: 4.369999885559082
Hole Depth UOM: m
Hole Diameter UOM: cm

---

41 | ***1 of 1*** | ***ESE/163.2*** | ***59.2 / -0.69*** | ***301 McArthur Avenue Vanier ON K1L 7B1*** | ***EHS***

Order No: 22032100773
Status: C
Report Type: Custom Report
Report Date: 24-MAR-22
Date Received: 21-MAR-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.6558258
Y: 45.4320123

---

42 | ***1 of 1*** | ***E/163.4*** | ***58.9 / -1.00*** | ***307 McArthur Ave. Vanier ON K1L 6P1*** | ***EHS***

Order No: 21060300605
Status: C
Report Type: Custom Report
Nearest Intersection:
Municipality:
Client Prov/State: ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	11-JUN-21	**Search Radius (km):**	.25
Date Received:	03-JUN-21	**X:**	-75.65547852
Previous Site Name:		**Y:**	45.43293146
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos		

43 **1 of 1** **SSW/165.8** **60.9 / 1.00** **252 MCARTHUR AVE. Ottawa ON** **WWIS**

Well ID:	7221192	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	05/30/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z186814	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221192.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/01/2014
Year Completed:	2014
Depth (m):	
Latitude:	45.4313654521877
Longitude:	-75.6579892517815
Point X:	-75.65798909031604
Point Y:	45.43136544517182
Path:	722\7221192.pdf

Bore Hole Information

Bore Hole ID:	1004795864	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448531.00
Code OB Desc:		**North83:**	5031082.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/01/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005169066
Layer:	1
Plug From:	0.0
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005169067
Layer:	2
Plug From:	0.9100000262260437
Plug To:	2.740000009536743
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1005169065
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1005169058
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005169063
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	
Casing Diameter:	3.450000047683716
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005169064
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Water Details

Water ID:	1005169062

Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005169061
Diameter: 3.450000047683716
Depth From: 2.140000104904175
Depth To: 2.740000009536743
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005169060
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 2.140000104904175
Hole Depth UOM: m
Hole Diameter UOM: cm

---

44 ***1 of 1*** ***NE/167.5*** ***59.9 / 0.00*** ***ON*** ***WWIS***

Well ID: 7441841
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z403009
Tag: A370994
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: VANIER CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 02/07/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1009384055
Depth (m):
Year Completed: 2023
Well Completed Dt: 01/16/2023
Audit No: Z403009
Path:

Tag No: A370994
Contractor: 7241
Latitude: 45.4341462586653
Longitude: -75.6565257437784
Point Y: 45.43414625227556
Point X: -75.65652558225405

Bore Hole Information

Bore Hole ID: 1009384055
DP2BR:
Spatial Status:

Elevation:
Elevrc:
Zone: 18

Code OB:		**East83:**	448648.00
Code OB Desc:		**North83:**	5031390.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/16/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

45 | ***1 of 1*** | ***NE/170.0*** | ***59.9 / 0.00*** | ***lot 6 ON*** | ***WWIS***

Well ID:	7433200	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	10/21/2022
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z385960	**Contractor:**	7241
Tag:	A359848	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	006
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	JG
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009262573	**Tag No:**	A359848
Depth (m):		**Contractor:**	7241
Year Completed:	2022	**Latitude:**	45.434102210551
Well Completed Dt:	09/30/2022	**Longitude:**	-75.6563590304721
Audit No:	Z385960	**Point Y:**	45.43410220428628
Path:		**Point X:**	-75.65635886757276

Bore Hole Information

Bore Hole ID:	1009262573	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448661.00
Code OB Desc:		**North83:**	5031385.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/30/2022	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			

Source Revision Comment:
Supplier Comment:

---

46 | **1 of 1** | **SSW/174.2** | **60.9 / 1.00** | **ON** | **WWIS**

Well ID:	7452520	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	06/21/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z408565	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009479588	**Tag No:**	
Depth (m):		**Contractor:**	7241
Year Completed:	2023	**Latitude:**	45.4312760347691
Well Completed Dt:	05/17/2023	**Longitude:**	-75.6578859393458
Audit No:	Z408565	**Point Y:**	45.43127602791089
Path:		**Point X:**	-75.65788577691369

Bore Hole Information

Bore Hole ID:	1009479588	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448539.00
Code OB Desc:		**North83:**	5031072.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/17/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

47 | **1 of 1** | **NNW/175.3** | **59.9 / 0.00** | **399497 Ont Ltd**
280 Frontenac Street
Ottawa ON K1L 6K9 | **GEN**

Generator No.:	ON5958491
Years Reported:	20,19,18,17,16,15,14,13

Alternate Locations

Generator No:	ON5958491
Generator Nm:	399497 ONT LTD
Site Addr:	280 FRONTENAC STREET
City:	OTTAWA
Reported Year(s):	20,19,18,17,16,15,14,13

Waste Reported

Waste Class:	145 - PAINT/PIGMENT/COATING RESIDUES
Reported Years:	20,19,18,17,16,15,14,13

2020 Generator Info

NAICS Code 1:	561799
NAICS 1 Description:	All Other Services to Buildings and Dwellings
Contaminated Fac:	N
MHSW Facility:	N

2019 Generator Info

NAICS Code 1:	561799
NAICS 1 Description:	All Other Services to Buildings and Dwellings
Contaminated Fac:	N
MHSW Facility:	N

2018 Generator Info

NAICS Code 1:	561799
NAICS 1 Description:	All Other Services to Buildings and Dwellings
Contaminated Fac:	N
MHSW Facility:	N

2018 Manifest Summary

Waste Code:	145	***Waste Char Code:***	L
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	430.0	***Waste Count:***	2
Waste Code:	145	***Waste Char Code:***	I
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	***Waste Char Desc:***	IGNITABLE
Quantity (kg):	100.0	***Waste Count:***	2

2017 Generator Info

NAICS Code 1:	561799
NAICS 1 Description:	All Other Services to Buildings and Dwellings
Contaminated Fac:	N
MHSW Facility:	N

2017 Manifest Summary

Waste Code:	145	***Waste Char Code:***	L
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	600.0	***Waste Count:***	1

2016 Generator Info

NAICS Code 1:	561799
NAICS 1 Description:	All Other Services to Buildings and Dwellings
Contaminated Fac:	N
MHSW Facility:	N

2015 Generator Info

NAICS Code 1:	561799
NAICS 1 Description:	All Other Services to Buildings and Dwellings
Contaminated Fac:	N
MHSW Facility:	N

2015 Manifest Summary

Waste Code:	145	**Waste Char Code:**	I
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	**Waste Char Desc:**	IGNITABLE
Quantity (kg):	80.0	**Waste Count:**	1
Waste Code:	145	**Waste Char Code:**	L
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	615.0	**Waste Count:**	2

2014 Generator Info

NAICS Code 1:	561799
NAICS 1 Description:	All Other Services to Buildings and Dwellings
Contaminated Fac:	N
MHSW Facility:	N

2013 Generator Info

NAICS Code 1:	561799
NAICS 1 Description:	All Other Services to Buildings and Dwellings
Contaminated Fac:	N
MHSW Facility:	N

2013 Manifest Summary

Waste Code:	145	**Waste Char Code:**	I
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	**Waste Char Desc:**	IGNITABLE
Quantity (kg):	60	**Waste Count:**	1
Waste Code:	145	**Waste Char Code:**	L
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	820	**Waste Count:**	1

---

48 ***1 of 1*** ***NE/176.2*** ***59.9 / 0.00*** ***ON*** ***WWIS***

Well ID:	7441840	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	02/07/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z403008	**Contractor:**	7241
Tag:	A370995	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	

Depth to Bedrock: ***Concession:***
Well Depth: ***Concession Name:***
Overburden/Bedrock: ***Easting NAD83:***
Pump Rate: ***Northing NAD83:***
Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: VANIER CITY
Site Info:

Additional Detail(s) (Map)

Bore Hole ID:	1009384049	***Tag No:***	A370995
Depth (m):		***Contractor:***	7241
Year Completed:	2023	***Latitude:***	45.4342362651449
Well Completed Dt:	01/16/2023	***Longitude:***	-75.656526787455
Audit No:	Z403008	***Point Y:***	45.43423625816514
Path:		***Point X:***	-75.65652662519011

Bore Hole Information

Bore Hole ID:	1009384049	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448648.00
Code OB Desc:		***North83:***	5031400.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/16/2023	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

49 ***1 of 1*** ***S/178.7*** ***60.9 / 1.00*** ***260 MCARTHUR AVENUE lot 7 OTTAWA ON*** ***WWIS***

Well ID:	7052573	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	11/22/2007
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z63812	***Contractor:***	1844
Tag:	A058362	***Form Version:***	4
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	007
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	VANIER CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/705\7052573.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/12/2007
Year Completed:	2007
Depth (m):	4.6
Latitude:	45.4312229879262
Longitude:	-75.6577191289334
Point X:	-75.65771896701179
Point Y:	45.431222981158704
Path:	705\7052573.pdf

Bore Hole Information

Bore Hole ID:	23052573	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448552.00
Code OB Desc:		***North83:***	5031066.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	10/12/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1000044345
Layer:	3
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	84
Material 2 Desc:	SILTY
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	1.7999999523162842
Formation End Depth:	3.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1000044344
Layer:	2
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.20000000298023224
Formation End Depth:	1.7999999523162842

Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1000044346
Layer: 4
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2: 06
Material 2 Desc: SILT
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 3.0999999046325684
Formation End Depth: 4.199999809265137
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1000044343
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.20000000298023224
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1000044347
Layer: 5
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 81
Material 2 Desc: SANDY
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 4.199999809265137
Formation End Depth: 4.599999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1000044349
Layer: 1
Plug From: 0.0
Plug To: 2.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:	1000044354
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	HSA

Pipe Information

Pipe ID:	1000044341
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1000044351
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	2.5
Casing Diameter:	51.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1000044352
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1000044342
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	0
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1000044350

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Layer: 1
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1000044348
Diameter: 20.0
Depth From:
Depth To: 4.5
Hole Depth UOM: m
Hole Diameter UOM: cm

---

50 | **1 of 11** | **SE/178.9** | **59.9 / 0.00** | **Bel-Air Lexus Toyota Inc.**
280 McArthur Avenue
Ottawa ON | **CA**

Certificate No: 8681-5J3TCV
Ref No:
Contaminants:
Application Year: 2003
Issue Date: 1/31/2003
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Emission Control:

Address:

---

50 | **2 of 11** | **SE/178.9** | **59.9 / 0.00** | **Bel-Air Automobiles Inc.**
280 McArthur Ave
Ottawa ON | **CA**

Certificate No: 4446-8JAJNZ
Ref No:
Contaminants:
Application Year: 2011
Issue Date: 6/30/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Emission Control:

Address:

---

50 | **3 of 11** | **SE/178.9** | **59.9 / 0.00** | **Bel-Air Lexus Toyota Inc.** | **EBR**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				280 McArthur Avenue Ottawa Ontario K1L 6P2 Ottawa ON	

EBR Registry No: IA02E0927
Ministry Ref No: 7451-5CRNBQ
Notice Type: Instrument Decision
Section:
Notice Stage:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Bel-Air Lexus Toyota Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 280 McArthur Avenue, Ottawa Ontario, K1L 6P2
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Bulletin Posted:
Appeal Posted:
Notice Date: February 03, 2003
Proposal Date: August 07, 2002
Year: 2002

Site Location Details:

280 McArthur Avenue Ottawa Ontario K1L 6P2 Ottawa

50	4 of 11	SE/178.9	59.9 / 0.00	**Bel-Air Lexus Toyota Inc.** **280 McArthur Avenue Ottawa K1L 6P2 CITY OF OTTAWA** **ON**	EBR

EBR Registry No: 011-1660
Ministry Ref No: 0550-8AZKZX
Notice Type: Instrument Decision
Section:
Notice Stage:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Bel-Air Lexus Toyota Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 280 McArthur avenue, Ottawa Ontario, Canada K1L 6P2
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Bulletin Posted:
Appeal Posted:
Notice Date: January 23, 2015
Proposal Date: November 11, 2010
Year: 2010

Site Location Details:

280 McArthur Avenue Ottawa K1L 6P2 CITY OF OTTAWA

50	5 of 11	SE/178.9	59.9 / 0.00	**Bel-Air Automobiles Inc.** **280 McArthur Avenue Ottawa K1L 6P2 CITY OF OTTAWA**	EBR

EBR Registry No: 011-2296
Ministry Ref No: 3365-8CLNAG
Notice Type: Instrument Decision
Section:
Notice Stage:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Bel-Air Automobiles Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 280 McArthur avenue, Ottawa Ontario, Canada K1L 6P2
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Bulletin Posted:
Appeal Posted:
Notice Date: July 06, 2011
Proposal Date: January 19, 2011
Year: 2011

Site Location Details:

280 McArthur Avenue Ottawa K1L 6P2 CITY OF OTTAWA

---

50 **6 of 11** **SE/178.9** **59.9 / 0.00** **Bel-Air Lexus Toyota Inc.**
280 McArthur Avenue
Ottawa ON K1L 6P2 **ECA**

Approval No: 8681-5J3TCV
Approval Date: 2003-01-31
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Bel-Air Lexus Toyota Inc.
Address: 280 McArthur Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7451-5CRNBQ-14.pdf
PDF Site Location:

MOE District: Ottawa
City:
Longitude: -75.65664
Latitude: 45.43131
Geometry X:
Geometry Y:

---

50 **7 of 11** **SE/178.9** **59.9 / 0.00** **Bel-Air Automobiles Inc.**
280 McArthur Ave
Ottawa ON K1L 6P2 **ECA**

Approval No: 4446-8JAJNZ
Approval Date: 2011-06-30
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Bel-Air Automobiles Inc.
Address: 280 McArthur Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3365-8CLNAG-14.pdf
PDF Site Location:

MOE District: Ottawa
City:
Longitude: -75.65664
Latitude: 45.43131
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	8 of 11	SE/178.9	59.9 / 0.00	280 Mcarthur Ave Ottawa ON K1L6P2	EHS

Order No: 20160926155
Status: C
Report Type: Standard Report
Report Date: 30-SEP-16
Date Received: 26-SEP-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.656643
Y: 45.4313

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	9 of 11	SE/178.9	59.9 / 0.00	GTA'S Finest Restoration Services (ottawa) Inc. 280 McArthur Ave Ottawa ON K1L 6P2	GEN

Generator No.: ON3895795
Years Reported: 16

Alternate Locations

Generator No: ON3895795
Generator Nm: GTA'S FINEST RESTORATION SERVICES (OTTAWA) INC.
Site Addr: 280 MCARTHUR AVE
City: OTTAWA
Reported Year(s): 16

Waste Reported

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 16

2016 Generator Info

NAICS Code 1: 562910
NAICS 1 Description: Remediation Services
Contaminated Fac: N
MHSW Facility: N

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	10 of 11	SE/178.9	59.9 / 0.00	Alfred's White Rose Service 280 McArthur av Eastview ON	HBAR

Province: ON
Year: 1964
Source: Mights

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	11 of 11	SE/178.9	59.9 / 0.00	Bel-Air Automobiles 280 Mcarthur Av Ottawa ON	HBAR

Province: ON
Year: 1987
Source: Polks

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	1 of 1	NE/179.8	59.9 / 0.00	ON	WWIS

Well ID:	7273415	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	10/17/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z214955	**Contractor:**	7241
Tag:	A190990	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/727\7273415.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/07/2016
Year Completed:	2016
Depth (m):	5.33
Latitude:	45.4342811214193
Longitude:	-75.6565528772941
Point X:	-75.65655271494843
Point Y:	45.434281114180536
Path:	727\7273415.pdf

Bore Hole Information

Bore Hole ID:	1006272840	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448646.00
Code OB Desc:		**North83:**	5031405.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/07/2016	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006422377
Layer:	1
Color:	6

General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422379
Layer:	3
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	3.3499999046325684
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422378
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.3100000023841858
Formation End Depth:	3.3499999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422380
Layer:	4
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	92
Material 3 Desc:	WEATHERED
Formation Top Depth:	4.570000171661377
Formation End Depth:	5.329999923706055
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006422390
Layer:	3
Plug From:	1.9800000190734863
Plug To:	5.329999923706055
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006422388
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006422389
Layer:	2
Plug From:	0.3100000023841858
Plug To:	1.9800000190734863
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1006422387
Method Construction Code:	5
Method Construction:	Air Percussion
Other Method Construction:	

Pipe Information

Pipe ID:	1006422376
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006422383
Layer:	1
Material:	7
Open Hole or Material:	OTHER
Depth From:	0.0
Depth To:	2.2799999713897705
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1006422384
Layer:	1
Slot:	10
Screen Top Depth:	2.2799999713897705
Screen End Depth:	5.329999923706055

Screen Material:	7
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1006422382
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1006422381
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	5.329999923706055
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

52 | ***1 of 2*** | ***SSE/181.1*** | ***60.6 / 0.69*** | ***McArthur Av Shell Serv Sta***
280 McArthur Av
Vanier ON | ***HBAR***

Province:	ON
Year:	1971
Source:	Mights

---

52 | ***2 of 2*** | ***SSE/181.1*** | ***60.6 / 0.69*** | ***Bel-Air Toyota Automobile***
280 Mcarthur Av
Vanier ON | ***HBAR***

Province:	ON
Year:	1987
Source:	Polks

---

53 | ***1 of 1*** | ***SSW/181.1*** | ***60.9 / 1.00*** | ***252 MCARTHUR AVE.***
Ottawa ON | ***WWIS***

Well ID:	7221189	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	05/30/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z187727	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: GLOUCESTER TOWNSHIP
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221189.pdf

Additional Detail(s) (Map)

Well Completed Date: 05/01/2014
Year Completed: 2014
Depth (m):
Latitude: 45.4312215890676
Longitude: -75.6579620117391
Point X: -75.6579618498246
Point Y: 45.43122158229807
Path: 722\7221189.pdf

Bore Hole Information

Bore Hole ID: 1004795855
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 05/01/2014
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448533.00
North83: 5031066.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1005169032
Layer: 2
Plug From: 0.9100000262260437
Plug To: 3.6600000858306885
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005169031
Layer: 1
Plug From: 0.0
Plug To: 0.9100000262260437
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005169030
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Pipe Information

Pipe ID: 1005169021
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005169026
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To:
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005169027
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 1005169025
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005169023
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 2.140000104904175
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005169024
Diameter: 5.199999809265137
Depth From: 2.140000104904175
Depth To: 3.6600000858306885
Hole Depth UOM: m
Hole Diameter UOM: cm

54	*1 of 1*	*SSW/181.3*	*60.9 / 1.00*	***252 MCARTHUR AVE.*** ***Ottawa ON***	***WWIS***

Well ID:	7221195	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	05/30/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z186811	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221195.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/01/2014
Year Completed:	2014
Depth (m):	
Latitude:	45.4312215154291
Longitude:	-75.6579747950442
Point X:	-75.65797463284686
Point Y:	45.43122150791073
Path:	722\7221195.pdf

Bore Hole Information

Bore Hole ID:	1004795873	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448532.00
Code OB Desc:		**North83:**	5031066.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/01/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005169117
Layer:	2
Plug From:	0.9100000262260437
Plug To:	2.740000009536743
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005169116
Layer:	1
Plug From:	0.0
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1005169115
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	HAND PULLED

Pipe Information

Pipe ID:	1005169107
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005169111
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.2200000286102295
Casing Diameter:	2.609999895095825
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005169112
Layer:	1
Slot:	10
Screen Top Depth:	1.2200000286102295
Screen End Depth:	2.740000009536743
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	3.3399999141693115

Water Details

Water ID:	1005169110
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1005169109
Diameter:	2.609999895095825

Depth From:	0.0
Depth To:	2.740000009536743
Hole Depth UOM:	m
Hole Diameter UOM:	cm

55 | **1 of 1** | **NE/182.0** | **59.9 / 0.00** | **lot 6 ON** | **WWIS**

Well ID:	7429420	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	09/22/2022
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z391860	**Contractor:**	7241
Tag:	A346621	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	006
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	JG
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009215329	**Tag No:**	A346621
Depth (m):		**Contractor:**	7241
Year Completed:	2022	**Latitude:**	45.4343080498779
Well Completed Dt:	07/13/2022	**Longitude:**	-75.6565659744164
Audit No:	Z391860	**Point Y:**	45.43430804302758
Path:		**Point X:**	-75.65656581237866

Bore Hole Information

Bore Hole ID:	1009215329	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448645.00
Code OB Desc:		**North83:**	5031408.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/13/2022	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

56 | **1 of 1** | **NE/182.6** | **59.9 / 0.00** | **Aristo Properties 315 Blake Blvd Ottawa ON K1L6L4** | **GEN**

Generator No.:	ON3230403
Years Reported:	16,15

Alternate Locations

Generator No:	ON3230403
Generator Nm:	ARISTO PROPERTIES
Site Addr:	315 BLAKE BLVD
City:	OTTAWA
Reported Year(s):	16,15

Waste Reported

Waste Class:	251 - OIL SKIMMINGS & SLUDGES
Reported Years:	16,15

2016 Generator Info

NAICS Code 1:	531310
NAICS 1 Description:	Real Estate Property Managers
Contaminated Fac:	N
MHSW Facility:	N

2015 Generator Info

NAICS Code 1:	531310
NAICS 1 Description:	Real Estate Property Managers
Contaminated Fac:	N
MHSW Facility:	N

2015 Manifest Summary

Waste Code:	251	***Waste Char Code:***	L
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	450.0	***Waste Count:***	1

---

57 ***1 of 1*** ***NE/182.9*** ***59.9 / 0.00*** ***ON*** ***WWIS***

Well ID:	7441699	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	01/16/2023
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z380383	***Contractor:***	7241
Tag:	A342593	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	VANIER CITY		
Site Info:			

Additional Detail(s) (Map)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1009383120	**Tag No:**	A342593
Depth (m):		**Contractor:**	7241
Year Completed:	2022	**Latitude:**	45.43429934316
Well Completed Dt:	07/08/2022	**Longitude:**	-75.6565147340279
Audit No:	Z380383	**Point Y:**	45.43429933633361
Path:		**Point X:**	-75.65651457159427

Bore Hole Information

Bore Hole ID:	1009383120	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448649.00
Code OB Desc:		**North83:**	5031407.00
Open Hole:		**Org CS:**	G83dd
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/08/2022	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	1 of 1	NE/183.6	59.9 / 0.00	311-315 Blake Boulveard Ottawa ON K1L 6L6	EHS

Order No:	22121200009	**Nearest Intersection:**	
Status:	C	**Municipality:**	Ottawa (Vanier)
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	15-DEC-22	**Search Radius (km):**	.3
Date Received:	12-DEC-22	**X:**	-75.65631124
Previous Site Name:	Apartments (circa 1950)	**Y:**	45.43422608
Lot/Building Size:			
Additional Info Ordered:	City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	1 of 2	SSE/184.3	59.8 / -0.03	Bel-Air Automobiles Inc. 280 McArthur Ave Ottawa ON	CA

Certificate No:	
Ref No:	0550-8AZKZX
Contaminants:	
Application Year:	2011
Issue Date:	
Approval Type:	Air
Status:	
Application Type:	
Client Name:	Bel-Air Automobiles Inc.
Client Address:	
Client City:	Ottawa
Client Postal Code:	
Project Description:	
Emission Control:	

Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	2 of 2	SSE/184.3	59.8 / -0.03	Burnie's Shell Service Station 280 McArthur avenue Eastview ON	HBAR

Province: ON
Year: 1967
Source: Mights

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
60	1 of 1	SSW/184.9	60.9 / 1.00	252 MCARTHUR AVE. Ottawa ON	WWIS

Well ID: 7221193
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z187726
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/30/2014
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221193.pdf

Additional Detail(s) (Map)

Well Completed Date: 05/01/2014
Year Completed: 2014
Depth (m):
Latitude: 45.4311856601041
Longitude: -75.6579488101023
Point X: -75.65794864819061
Point Y: 45.43118565292802
Path: 722\7221193.pdf

Bore Hole Information

Bore Hole ID: 1004795867
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 05/01/2014
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448534.00
North83: 5031062.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1005169084
Layer: 1
Plug From: 0.0
Plug To: 0.9100000262260437
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005169085
Layer: 2
Plug From: 0.9100000262260437
Plug To: 3.6600000858306885
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005169083
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005169074
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005169079
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To:
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005169080
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 1005169078
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005169076
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 2.130000114440918
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005169077
Diameter: 5.199999809265137
Depth From: 2.130000114440918
Depth To: 3.6600000858306885
Hole Depth UOM: m
Hole Diameter UOM: cm

---

61 **1 of 1** **SSW/185.0** **60.9 / 1.00** **252 MCARTHUR AVE.**
Ottawa ON
WWIS

Well ID: 7221191
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z186813
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/30/2014
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221191.pdf

Additional Detail(s) (Map)

Well Completed Date: 05/01/2014
Year Completed: 2014
Depth (m):
Latitude: 45.4312203370195
Longitude: -75.6581793279186
Point X: -75.65817916569459
Point Y: 45.43122033032093
Path: 722\7221191.pdf

Bore Hole Information

Bore Hole ID:	1004795861	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448516.00
Code OB Desc:		***North83:***	5031066.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	05/01/2014	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005169054
Layer:	2
Plug From:	0.9100000262260437
Plug To:	3.6600000858306885
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005169053
Layer:	1
Plug From:	0.0
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1005169052
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1005169043
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005169048
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	

Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005169049
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 1005169047
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005169046
Diameter: 5.260000228881836
Depth From: 2.140000104904175
Depth To: 3.059999942779541
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005169045
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 2.140000104904175
Hole Depth UOM: m
Hole Diameter UOM: cm

---

62 ***1 of 1*** ***SSW/186.9*** ***60.9 / 1.00*** ***252 MCARTHUR AVE. Ottawa ON*** ***WWIS***

Well ID: 7221194
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z187728
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/30/2014
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:

Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221194.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/01/2014
Year Completed:	2014
Depth (m):	
Latitude:	45.4311676588038
Longitude:	-75.6579486009367
Point X:	-75.65794843888476
Point Y:	45.43116765230152
Path:	722\7221194.pdf

Bore Hole Information

Bore Hole ID:	1004795870	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448534.00
Code OB Desc:		**North83:**	5031060.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/01/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005169099
Layer:	1
Plug From:	0.0
Plug To:	0.9100000262260437
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005169100
Layer:	2
Plug From:	0.9100000262260437
Plug To:	3.6600000858306885
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1005169098
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1005169089
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005169094
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	
Casing Diameter:	5.199999809265137
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005169095
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Water Details

Water ID:	1005169093
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1005169091
Diameter:	10.920000076293945
Depth From:	0.0
Depth To:	2.130000114440918
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1005169092
Diameter:	5.199999809265137
Depth From:	2.130000114440918
Depth To:	3.6600000858306885
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
63	1 of 2	SE/187.2	59.9 / 0.00	292 Mcarthur Ave Ottawa ON K1L 6P2	EHS

Order No: 20130125025
Status: C
Report Type: Standard Report
Report Date: 05-FEB-13
Date Received: 25-JAN-13
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.656257
Y: 45.431325

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
63	2 of 2	SE/187.2	59.9 / 0.00	NUCLEONICS SCIENTIFIC DEVICES 292 MCARTHUR AVE VANIER ON K1L 6P2	SCT

Scott S ID:
Latitude:
Longitude:

Historical Details

Established: 1970
Plant Size (ft²):
Employment: 10

Historical Details

Description: RELAYS & INDUSTRIAL CONTROLS
SIC/NAICS Code: 3625

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	1 of 3	NE/187.7	59.9 / 0.00	311 Blake Blvd Ottawa ON K1L6L4	EHS

Order No: 20150508101
Status: C
Report Type: Custom Report
Report Date: 13-MAY-15
Date Received: 08-MAY-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.6563
Y: 45.434341

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	2 of 3	NE/187.7	59.9 / 0.00	311 Blake Blvd Ottawa ON Ottawa ON K1L 6L6	EHS

Order No: 24061800144
Status: C
Report Type: Standard Report
Report Date: 21-JUN-24
Date Received: 18-JUN-24
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.6564013
Y: 45.434306

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	3 of 3	NE/187.7	59.9 / 0.00	Aristo Properties 311 Blake Blvd Ottawa ON K1L 6L6	GEN

Generator No.: ON5424457
Years Reported: 22

Alternate Locations

Generator No: ON5424457
Generator Nm: ARISTO PROPERTIES
Site Addr: 311 BLAKE BLVD
City: OTTAWA
Reported Year(s): 22

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 22

2022 Generator Info

NAICS Code 1: 541620
NAICS 1 Description: Environmental Consulting Services
Contaminated Fac: N
MHSW Facility: N

2022 Manifest Summary

Waste Code: 221
Waste Description: LIGHT FUELS
Quantity (kg): 790.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1.0

---

65 ***1 of 1*** ***NE/187.8*** ***59.9 / 0.00*** ***ON*** ***WWIS***

Well ID: 7445950
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z402972
Tag: A371064
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: OTTAWA CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 03/15/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1009427421
Depth (m):
Year Completed: 2023
Well Completed Dt: 01/27/2023
Audit No: Z402972
Tag No: A371064
Contractor: 7241
Latitude: 45.4341489030415
Longitude: -75.6560655208604
Point Y: 45.43414889604182

Path: ***Point X:*** -75.65606535931674

Bore Hole Information

Bore Hole ID:	1009427421	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448684.00
Code OB Desc:		***North83:***	5031390.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/27/2023	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

66 ***1 of 1*** ***NNE/189.2*** ***59.9 / 0.00*** ***ON*** ***WWIS***

Well ID:	7273416	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	10/17/2016
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z214956	***Contractor:***	7241
Tag:	A190989	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/727\7273416.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/07/2016
Year Completed:	2016
Depth (m):	5.33
Latitude:	45.4343712013796
Longitude:	-75.6565411369989
Point X:	-75.65654097486222
Point Y:	45.43437119423822
Path:	727\7273416.pdf

Bore Hole Information

Bore Hole ID:	1006272846	***Elevation:***	
DP2BR:		***Elevrc:***	

Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448647.00
Code OB Desc:		***North83:***	5031415.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	09/07/2016	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006422406
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422409
Layer:	4
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	92
Material 3 Desc:	WEATHERED
Formation Top Depth:	4.570000171661377
Formation End Depth:	5.329999923706055
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422408
Layer:	3
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	3.3499999046325684

Formation End Depth: 4.570000171661377
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006422407
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.3100000023841858
Formation End Depth: 3.3499999046325684
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006422417
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006422419
Layer: 3
Plug From: 1.9800000190734863
Plug To: 5.329999923706055
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006422418
Layer: 2
Plug From: 0.3100000023841858
Plug To: 1.9800000190734863
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006422416
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1006422405
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1006422412
Layer:	1
Material:	7
Open Hole or Material:	OTHER
Depth From:	0.0
Depth To:	2.2799999713897705
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1006422413
Layer:	1
Slot:	10
Screen Top Depth:	2.2799999713897705
Screen End Depth:	5.329999923706055
Screen Material:	7
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1006422411
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1006422410
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	5.329999923706055
Hole Depth UOM:	m
Hole Diameter UOM:	cm

67 ***1 of 1*** ***SSW/191.2*** ***60.9 / 1.00*** ***ON*** ***WWIS***

Well ID:	7452518	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	06/21/2023
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z408566	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	

Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: OTTAWA CITY
Site Info:

Additional Detail(s) (Map)

Bore Hole ID: 1009479582 ***Tag No:***
Depth (m): ***Contractor:*** 7241
Year Completed: 2023 ***Latitude:*** 45.4311574797923
Well Completed Dt: 05/17/2023 ***Longitude:*** -75.6581530290024
Audit No: Z408566 ***Point Y:*** 45.431157473134235
Path: ***Point X:*** -75.65815286663039

Bore Hole Information

Bore Hole ID: 1009479582 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 18
Code OB: ***East83:*** 448518.00
Code OB Desc: ***North83:*** 5031059.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 05/17/2023 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

---

68 ***1 of 1*** ***SSW/193.7*** ***60.9 / 1.00*** ***ON*** ***WWIS***

Well ID: 7452521 ***Flowing (Y/N):***
Construction Date: ***Flow Rate:***
Use 1st: ***Data Entry Status:*** Yes
Use 2nd: ***Data Src:***
Final Well Status: ***Date Received:*** 06/21/2023
Water Type: ***Selected Flag:*** TRUE
Casing Material: ***Abandonment Rec:*** Yes
Audit No: Z408564 ***Contractor:*** 7241
Tag: ***Form Version:*** 7
Constructn Method: ***Owner:***
Elevation (m): ***County:*** OTTAWA-CARLETON
Elevatn Reliabilty: ***Lot:***
Depth to Bedrock: ***Concession:***
Well Depth: ***Concession Name:***
Overburden/Bedrock: ***Easting NAD83:***
Pump Rate: ***Northing NAD83:***
Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: OTTAWA CITY
Site Info:

Additional Detail(s) (Map)

Bore Hole ID: 1009479591 ***Tag No:***
Depth (m): ***Contractor:*** 7241
Year Completed: 2023 ***Latitude:*** 45.4311480371628

Well Completed Dt:	05/17/2023	**Longitude:**	-75.658229624115
Audit No:	Z408564	**Point Y:**	45.43114803027483
Path:		**Point X:**	-75.6582294623568

Bore Hole Information

Bore Hole ID:	1009479591	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448512.00
Code OB Desc:		**North83:**	5031058.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/17/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

69	*1 of 1*	*ESE/194.5*	*58.9 / -1.00*	***Aqua Drugs Limited*** ***311 MCARTHUR AVENUE Suite 105*** ***VANIER ON K1L 6P1***	***GEN***

Generator No.:	ON2532700
Years Reported:	25,24,23,22,21,20,19,18,17,16,15,14,12,09,08,07,06,05,04,03,01,00,99

Alternate Locations

Generator No:	ON2532700
Generator Nm:	PARKWAY PHARMACY
Site Addr:	311 MCARTHUR AVENUE
City:	VANIER
Reported Year(s):	01,00,99

Generator No:	ON2532700
Generator Nm:	ONTARIO ADDICTION TREATMENT CENTRE
Site Addr:	CATP OTTAWA, 311 MCARTHUR AVENUE
City:	VANIER
Reported Year(s):	25,24,23

Generator No:	ON2532700
Generator Nm:	AQUA DRUGS
Site Addr:	311 MCARTHUR AVENUE
City:	VANIER
Reported Year(s):	17,16,15

Generator No:	ON2532700
Generator Nm:	PARKWAY PHARMACY
Site Addr:	68235 ONTARIO LIMITED
City:	VANIER
Reported Year(s):	09,08,07,06,05,04,03

Generator No:	ON2532700
Generator Nm:	AQUA DRUGS LIMITED
Site Addr:	311 MCARTHUR AVENUE
City:	VANIER
Reported Year(s):	22,21,20,19,18

Generator No:	ON2532700

Generator Nm: DEDICATED NATIONAL PHARMACY INC.
Site Addr: 311 MCARTHUR AVENUE
City: VANIER
Reported Year(s): 14,12

2025 Generator Info

Waste Reported

Waste Class: 312 - PATHOLOGICAL WASTES
Reported Years: 24,23,22,21,20,19,18,17,16,15,14,12,09,08,07,06,05,01,00,99

Waste Class: 261 - PHARMACEUTICALS
Reported Years: 24,23,22,21,20,19,18,17,16,15,14,12,09,08,07,06,05,01,00,99

2025 Waste Info

Waste Code: 261
Waste Description: Pharmaceuticals
Waste Char Cd: A
Waste Char Desc: Acutely Hazardous Waste Chem.

Waste Code: 312
Waste Description: Pathological Wastes
Waste Char Cd: P
Waste Char Desc: Pathological

2024 Generator Info

NAICS Code: 414510
NAICS Description: Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contamin'd Fac: No
MHSW Facility: No

2024 Manifest Summary

Waste Code: 261
Waste Description: Pharmaceuticals
Qty Received (kg): 2610.8199999999997
Waste Char Code: A
Waste Char Desc: Acutely Hazardous Waste Chem.
Waste Count: 47

Waste Code: 261
Waste Description: Pharmaceuticals
Qty Received (kg): 163.46
Waste Char Code: A
Waste Char Desc: Acutely Hazardous Waste Chem.
Waste Count: 1

Waste Code: 312
Waste Description: Pathological Wastes
Qty Received (kg): 34.2
Waste Char Code: P
Waste Char Desc: Pathological
Waste Count: 12

2023 Generator Info

NAICS Code: 414510
NAICS Description: Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contamin'd Fac: No
MHSW Facility: No

2023 Manifest Summary

Waste Code: 312
Waste Description: Pathological Wastes
Qty Received (kg): 33.68
Waste Char Code: P
Waste Char Desc: Pathological
Waste Count: 1

Waste Code: 261
Waste Description: Pharmaceuticals
Waste Char Code: A
Waste Char Desc: Acutely Hazardous Waste Chem.

Qty Received (kg):	1430.0600000000002	***Waste Count:***	23
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	Pharmaceuticals	***Waste Char Desc:***	Acutely Hazardous Waste Chem.
Qty Received (kg):	0	***Waste Count:***	1
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	Pharmaceuticals	***Waste Char Desc:***	Acutely Hazardous Waste Chem.
Qty Received (kg):	760.7599999999999	***Waste Count:***	9
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	Pathological Wastes	***Waste Char Desc:***	Pathological
Qty Received (kg):	1	***Waste Count:***	1

2022 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2022 Manifest Summary

Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	182.59	***Waste Count:***	2.0
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1618.47	***Waste Count:***	19.0
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	97.75	***Waste Count:***	1.0

2021 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2021 Manifest Summary

Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	97.08	***Waste Count:***	1
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	173.77	***Waste Count:***	7
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1674.61	***Waste Count:***	22

2020 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2020 Manifest Summary

Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	66.0	***Waste Count:***	1
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	65.4	***Waste Count:***	9
Waste Code:	261	***Waste Char Code:***	P
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	219.8	***Waste Count:***	1
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	11.1	***Waste Count:***	1
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	258.2	***Waste Count:***	3
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1382.6	***Waste Count:***	10

2019 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2019 Manifest Summary

Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1542.0	***Waste Count:***	10
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	26.0	***Waste Count:***	1
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	120.0	***Waste Count:***	2
Waste Code:	261	***Waste Char Code:***	P
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	231.0	***Waste Count:***	2
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	306.0	***Waste Count:***	2

2018 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2018 Manifest Summary

Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1862.56	***Waste Count:***	11
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	206.54	***Waste Count:***	4
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	26.0	***Waste Count:***	2

2017 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2017 Manifest Summary

Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1821.12	***Waste Count:***	12
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	38.7	***Waste Count:***	4
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	35.0	***Waste Count:***	2

2016 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2016 Manifest Summary

Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1040.68	***Waste Count:***	11
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	130.0	***Waste Count:***	1
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	184.6	***Waste Count:***	2
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	20.82	***Waste Count:***	1
Waste Code:	261	***Waste Char Code:***	A

Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	54.0	***Waste Count:***	1

2015 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2015 Manifest Summary

Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	341.1	***Waste Count:***	3
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	21.5	***Waste Count:***	1
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	1091.2	***Waste Count:***	10

2014 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2014 Manifest Summary

Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	140.7	***Waste Count:***	1
Waste Code:	261	***Waste Char Code:***	A
Waste Description:	PHARMACEUTICALS	***Waste Char Desc:***	ACUTELY HAZARDOUS WASTE CHEM.
Quantity (kg):	574.28	***Waste Count:***	6
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	30.3	***Waste Count:***	3

2012 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Fac:	N
MHSW Facility:	N

2009 Generator Info

NAICS Code 1:	414510
NAICS 1 Description:	Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Facility:	N
MHSW Facility:	N

2008 Generator Info

NAICS Code 1: 414510
NAICS 1 Description: Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Facility: N
MHSW Facility: N

2008 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 88.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 1

Waste Code: 261
Waste Description: PHARMACEUTICALS
Quantity (kg): 51.0
Waste Char Code: A
Waste Char Desc: ACUTELY HAZARDOUS WASTE CHEM.
Waste Count: 1

2007 Generator Info

NAICS Code 1: 414510
NAICS 1 Description: Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Facility:
MHSW Facility:

2007 Manifest Summary

Waste Code: 261
Waste Description: PHARMACEUTICALS
Quantity (kg): 51.0
Waste Char Code: A
Waste Char Desc: ACUTELY HAZARDOUS WASTE CHEM.
Waste Count: 1

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 88.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 1

2006 Generator Info

NAICS Code 1: 414510
NAICS 1 Description: Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Facility:
MHSW Facility:

2006 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 140.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 2

Waste Code: 261
Waste Description: PHARMACEUTICALS
Quantity (kg): 160.0
Waste Char Code: A
Waste Char Desc: ACUTELY HAZARDOUS WASTE CHEM.
Waste Count: 2

2005 Generator Info

NAICS Code 1: 414510
NAICS 1 Description: Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Facility:
MHSW Facility:

2004 Generator Info

NAICS Code 1: 414510

NAICS 1 Description: Pharmaceuticals and Pharmacy Supplies Wholesaler-Distributors
Contaminated Facility:
MHSW Facility:

2003 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2001 Generator Info

SIC Code: 6031 **SIC Description:** PHARMACIES

2000 Generator Info

SIC Code: 6031 **SIC Description:** PHARMACIES

1999 Generator Info

SIC Code: 6031 **SIC Description:** PHARMACIES

---

70 **1 of 1** **NE/194.8** **59.9 / 0.00** **ON** **WWIS**

Well ID:	7273417	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	10/17/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z214957	**Contractor:**	7241
Tag:	A190988	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: GLOUCESTER TOWNSHIP
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/727\7273417.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/07/2016
Year Completed: 2016
Depth (m): 5.33
Latitude: 45.434327740959
Longitude: -75.6562721509327
Point X: -75.65627198881636
Point Y: 45.43432773392625
Path: 727\7273417.pdf

Bore Hole Information

Bore Hole ID:	1006272849	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448668.00
Code OB Desc:		***North83:***	5031410.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	09/07/2016	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006422435
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422437
Layer:	3
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	3.0999999046325684
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422438
Layer:	4
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	

Material 2 Desc:
Material 3: 92
Material 3 Desc: WEATHERED
Formation Top Depth: 4.570000171661377
Formation End Depth: 5.329999923706055
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006422436
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.3100000023841858
Formation End Depth: 3.0999999046325684
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006422448
Layer: 3
Plug From: 1.9800000190734863
Plug To: 5.329999923706055
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006422446
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006422447
Layer: 2
Plug From: 0.3100000023841858
Plug To: 1.9800000190734863
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006422445
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1006422434
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006422441
Layer: 1
Material: 7
Open Hole or Material: OTHER
Depth From: 0.0
Depth To: 2.2799999713897705
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006422442
Layer: 1
Slot: 10
Screen Top Depth: 2.2799999713897705
Screen End Depth: 5.329999923706055
Screen Material: 7
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1006422440
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006422439
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 5.329999923706055
Hole Depth UOM: m
Hole Diameter UOM: cm

---

71 | **1 of 3** | **ESE/195.0** | **58.9 / -1.00** | **311 Mcarthur Ave Ottawa ON K1L8M3** | **EHS**

Order No: 20130729020
Status: C
Report Type: Custom Report
Report Date: 02-AUG-13
Date Received: 29-JUL-13
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.655275
Y: 45.432128

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
71	2 of 3	ESE/195.0	58.9 / -1.00	311 McArthur Avenue Ottawa Ontario Vanier ON K1L 8M3	EHS

Order No: 20181116019
Status: C
Report Type: Standard Report
Report Date: 21-NOV-18
Date Received: 16-NOV-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.655321
Y: 45.431986

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
71	3 of 3	ESE/195.0	58.9 / -1.00	CARE MEDICS 311 MCARTHUR AVE UNIT 103 OTTAWA ON K1L8M3	GEN

Generator No.: ON5595507
Years Reported: 22,21,20,19,18,17,16,15,14,13,12,11,10

Alternate Locations

Generator No: ON5595507
Generator Nm: CARE MEDICS
Site Addr: 311 MCARTHUR AVE
City: OTTAWA
Reported Year(s): 22,21,20,19,18,17,16,15,14,13,12,11,10

Waste Reported

Waste Class: 312 - PATHOLOGICAL WASTES
Reported Years: 22,21,20,19,18,17,16,15,14,13,12,11,10

2022 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2022 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 19.29

Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 3.0

2021 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2021 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 25.13

Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 4

2020 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2020 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 3.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 1

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 17.42
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 2

2019 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2019 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 32.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 5

2018 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2018 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 21.2
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 4

2017 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2017 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 17.7
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 4

2016 Generator Info

NAICS Code 1: 621110

NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2016 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 27.04
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 3

2015 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2015 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 16.86
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 3

2014 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2014 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 27.2
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 4

2013 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2013 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 31
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 3

2012 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Fac: N
MHSW Facility: N

2012 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	15.0	**Waste Count:**	2
Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	12.4	**Waste Count:**	2

2011 Generator Info

NAICS Code 1:	621110
NAICS 1 Description:	Offices of Physicians
Contaminated Facility:	N
MHSW Facility:	N

2011 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	23	**Waste Count:**	4

2010 Generator Info

NAICS Code 1:	621110
NAICS 1 Description:	Offices of Physicians
Contaminated Facility:	N
MHSW Facility:	N

2010 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	40	**Waste Count:**	3

---

72 | ***1 of 1*** | ***NE/196.1*** | ***59.9 / 0.00*** | ***lot 6 ON*** | ***WWIS***

Well ID:	7429419	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	09/22/2022
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z391861	**Contractor:**	7241
Tag:	A346622	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	006
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	JG
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/742\7429419.pdf

Additional Detail(s) (Map)

Well Completed Date: 07/13/2022
Year Completed: 2022
Depth (m):
Latitude: 45.4343723034584
Longitude: -75.6563493766962
Point X: -75.6563492151553
Point Y: 45.43437229611828
Path: 742\7429419.pdf

Bore Hole Information

Bore Hole ID: 1009215326
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 07/13/2022
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448662.00
North83: 5031415.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

---

73 **1 of 1** **NE/196.9** **59.9 / 0.00** **ON** **WWIS**

Well ID: 7441838
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z403006
Tag: A370997
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: VANIER CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 02/07/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1009384040
Depth (m):
Year Completed: 2023
Well Completed Dt: 01/17/2023
Audit No: Z403006
Path:

Tag No: A370997
Contractor: 7241
Latitude: 45.4343102537946
Longitude: -75.6561824542297
Point Y: 45.43431024742051
Point X: -75.6561822920665

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole Information

Bore Hole ID:	1009384040	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448675.00
Code OB Desc:		***North83:***	5031408.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/17/2023	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

74 ***1 of 1*** ***NE/199.2*** ***59.9 / 0.00*** ***315 BLAKE BLVD. OTTAWA ON*** ***WWIS***

Well ID:	7250248	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	10/16/2015
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z214865	***Contractor:***	7241
Tag:	A186561	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/725\7250248.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/03/2015
Year Completed:	2015
Depth (m):	6.71
Latitude:	45.4343283285331
Longitude:	-75.6561698788456
Point X:	-75.65616971655346
Point Y:	45.434328322058356
Path:	725\7250248.pdf

Bore Hole Information

Bore Hole ID:	1005746907	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448676.00
Code OB Desc:		***North83:***	5031410.00

Open Hole:
Cluster Kind:
Date Completed: 09/03/2015
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005777718
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 0.6100000143051147
Formation End Depth: 3.0999999046325684
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005777717
Layer: 1
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 77
Material 2 Desc: LOOSE
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005777719
Layer: 3
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 3.0999999046325684
Formation End Depth: 6.710000038146973
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1005777729
Layer:	2
Plug From:	0.3100000023841858
Plug To:	3.0999999046325684
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005777728
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005777730
Layer:	3
Plug From:	3.0999999046325684
Plug To:	6.710000038146973
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1005777727
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005777716
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005777723
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.6600000858306885
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005777724
Layer:	1
Slot:	10
Screen Top Depth:	3.6600000858306885

Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1005777722
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005777721
Diameter: 5.710000038146973
Depth From: 3.0999999046325684
Depth To: 6.710000038146973
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005777720
Diameter: 8.25
Depth From: 0.0
Depth To: 3.0999999046325684
Hole Depth UOM: m
Hole Diameter UOM: cm

---

75 **1 of 1** **NE/201.1** **59.9 / 0.00** **ON** **WWIS**

Well ID:	7273418	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	10/17/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z214958	**Contractor:**	7241
Tag:	A190987	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/727\7273418.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/07/2016

Year Completed:	2016
Depth (m):	5.33
Latitude:	45.4343374760608
Longitude:	-75.6561444151309
Point X:	-75.65614425291609
Point Y:	45.434337469374064
Path:	727\7273418.pdf

Bore Hole Information

Bore Hole ID:	1006272852	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448678.00
Code OB Desc:		**North83:**	5031411.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/07/2016	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc:	on Water Well Record
Elevrc Desc:	
Location Source Date:	
Improvement Location Source:	
Improvement Location Method:	
Source Revision Comment:	
Supplier Comment:	

Overburden and Bedrock Materials Interval

Formation ID:	1006422466
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.3100000023841858
Formation End Depth:	3.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422465
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock

Materials Interval

Formation ID:	1006422467
Layer:	3
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	3.0999999046325684
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006422468
Layer:	4
Color:	8
General Color:	BLACK
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	92
Material 3 Desc:	WEATHERED
Formation Top Depth:	4.570000171661377
Formation End Depth:	5.329999923706055
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006422476
Layer:	3
Plug From:	1.9800000190734863
Plug To:	5.329999923706055
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006422474
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006422475
Layer:	2
Plug From:	0.3100000023841858
Plug To:	1.9800000190734863
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID: 1006422473
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1006422464
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006422471
Layer: 1
Material: 7
Open Hole or Material: OTHER
Depth From: 0.0
Depth To: 2.2799999713897705
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006422472
Layer: 1
Slot: 10
Screen Top Depth: 2.2799999713897705
Screen End Depth: 5.329999923706055
Screen Material: 7
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1006422470
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006422469
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 5.329999923706055
Hole Depth UOM: m
Hole Diameter UOM: cm

---

76 | ***1 of 1*** | ***NE/202.3*** | ***59.9 / 0.00*** | ***ON*** | ***WWIS***

Well ID: 7441839
Construction Date:
Use 1st:
Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes

Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	02/07/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z403007	**Contractor:**	7241
Tag:	A370996	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	VANIER CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009384043	**Tag No:**	A370996
Depth (m):		**Contractor:**	7241
Year Completed:	2023	**Latitude:**	45.4343731848897
Well Completed Dt:	01/17/2023	**Longitude:**	-75.6561959684461
Audit No:	Z403007	**Point Y:**	45.43437317800054
Path:		**Point X:**	-75.6561958063118

Bore Hole Information

Bore Hole ID:	1009384043	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448674.00
Code OB Desc:		**North83:**	5031415.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/17/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

77	1 of 1	N/209.1	59.9 / 0.00	295 FRONTENAC ST. Ottawa ON	WWIS

Well ID:	7123751	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	06/08/2009
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z93050	**Contractor:**	7241
Tag:	A080413	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	

Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7123751.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/07/2009
Year Completed:	2009
Depth (m):	2.44
Latitude:	45.4346998873159
Longitude:	-75.657299260266
Point X:	-75.65729909788544
Point Y:	45.434699879990944
Path:	712\7123751.pdf

Bore Hole Information

Bore Hole ID:	1002448804	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448588.00
Code OB Desc:		**North83:**	5031452.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/07/2009	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1002598249
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	17
Material 2 Desc:	SHALE
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	1.2200000286102295
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1002598248
Layer:	2
Color:	6

General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	05
Material 3 Desc:	CLAY
Formation Top Depth:	0.30000001192092896
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1002598247
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.30000001192092896
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002598251
Layer:	1
Plug From:	0.0
Plug To:	0.6000000238418579
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002598252
Layer:	2
Plug From:	0.6000000238418579
Plug To:	2.440000057220459
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1002598258
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1002598246
Casing No:	0
Comment:	
Alt Name:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Construction Record - Casing

Casing ID:	1002598254
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	3.450000047683716
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002598255
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	2.440000057220459
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.210000038146973

Water Details

Water ID:	1002598253
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1002598250
Diameter:	6.03000020980835
Depth From:	0.0
Depth To:	2.440000057220459
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	*1 of 2*	*SE/209.4*	*59.9 / 0.00*	***McArthur Road Auto Electric*** ***300 McArthur av*** ***Ottawa ON***	HBAR

Province:	ON
Year:	1955
Source:	Mights

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	*2 of 2*	*SE/209.4*	*59.9 / 0.00*	***Thompson & Ray*** ***300 McArthur av*** ***Ottawa ON***	HBAR

Province:	ON
Year:	1950
Source:	Mights

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	1 of 1	N/210.8	59.9 / 0.00	295 FRONTENAC ST. Ottawa ON	WWIS

Well ID:	7123752	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	06/08/2009
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z93054	**Contractor:**	7241
Tag:	A080415	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7123752.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/07/2009
Year Completed:	2009
Depth (m):	2.8
Latitude:	45.4347093293435
Longitude:	-75.6572226601929
Point X:	-75.65722249766745
Point Y:	45.43470932225604
Path:	712\7123752.pdf

Bore Hole Information

Bore Hole ID:	1002448987	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448594.00
Code OB Desc:		**North83:**	5031453.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/07/2009	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1002598263
Layer:	2
Color:	6
General Color:	BROWN

Material 1: 28
Material 1 Desc: SAND
Material 2: 17
Material 2 Desc: SHALE
Material 3: 05
Material 3 Desc: CLAY
Formation Top Depth: 0.6100000143051147
Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002598262
Layer: 1
Color: 8
General Color: BLACK
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002598264
Layer: 3
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 17
Material 2 Desc: SHALE
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 1.5
Formation End Depth: 2.799999952316284
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002598267
Layer: 2
Plug From: 0.6100000143051147
Plug To: 2.799999952316284
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002598266
Layer: 1
Plug From: 0.0
Plug To: 0.6100000143051147
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:	1002598273
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1002598261
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002598269
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.699999988079071
Casing Diameter:	3.450000047683716
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002598270
Layer:	1
Slot:	10
Screen Top Depth:	0.699999988079071
Screen End Depth:	2.799999952316284
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.210000038146973

Water Details

Water ID:	1002598268
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1002598265
Diameter:	5.710000038146973
Depth From:	0.0
Depth To:	2.799999952316284
Hole Depth UOM:	m
Hole Diameter UOM:	cm

80	***1 of 1***	***SSW/212.3***	***61.2 / 1.28***	***ON***	***WWIS***

Well ID: 7429653 ***Flowing (Y/N):***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z385919
Tag: A357205
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: GLOUCESTER TOWNSHIP
Site Info:

Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 09/22/2022
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1009215179
Depth (m):
Year Completed: 2022
Well Completed Dt: 08/26/2022
Audit No: Z385919
Path:

Tag No: A357205
Contractor: 7241
Latitude: 45.4309509067679
Longitude: -75.6580739234048
Point Y: 45.43095090045844
Point X: -75.65807376103024

Bore Hole Information

Bore Hole ID: 1009215179
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 08/26/2022
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 448524.00
North83: 5031036.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

81	1 of 1	SW/213.1	60.9 / 1.00	**Ontario Motor Sales** **242 McArthur av** **Eastview ON**	HBAR

Province: ON
Year: 1964
Source: Mights

82	1 of 1	S/214.2	60.9 / 1.00	**256 MCAURTHUR AVE.** **Ottawa ON**	WWIS

Well ID: 7221187
Construction Date:
Use 1st: Monitoring and Test Hole

Flowing (Y/N):
Flow Rate:
Data Entry Status:

Use 2nd:	0	**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	05/30/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z186812	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: GLOUCESTER TOWNSHIP
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7221187.pdf

Additional Detail(s) (Map)

Well Completed Date: 05/01/2014
Year Completed: 2014
Depth (m):
Latitude: 45.4308996269284
Longitude: -75.6576003161948
Point X: -75.65760015410252
Point Y: 45.43089962042577
Path: 722\7221187.pdf

Bore Hole Information

Bore Hole ID:	1004795803	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448561.00
Code OB Desc:		**North83:**	5031030.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/01/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1005169006
Layer: 1
Plug From: 0.0
Plug To: 0.9100000262260437
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005169007
Layer: 2
Plug From: 0.9100000262260437
Plug To: 3.6600000858306885
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005169005
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005168996
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005169001
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005169002
Layer: 1
Slot: 5
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03000020980835

Water Details

Water ID: 1005169000
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005168998
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 2.140000104904175
Hole Depth UOM: m

Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005168999
Diameter: 5.199999809265137
Depth From: 2.140000104904175
Depth To: 3.6600000858306885
Hole Depth UOM: m
Hole Diameter UOM: cm

---

83 ***1 of 2*** ***N/215.9*** ***59.9 / 0.00*** ***295 FRONTENAC STREET OTTAWA ON*** ***HINC***

External File Num: FS INC 0904-02147
Fuel Occurrence Type: Leak
Date of Occurrence: 4/24/2009
Fuel Type Involved: Fuel Oil
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Multi-unit Residential
Service Interruptions: No
Property Damage: No
Fuel Life Cycle Stage: Utilization
Root Cause: Root Cause: Equipment/Material/Component:Yes Procedures:No Maintenance:No Design:No Training:No Management:Yes Human Factors:Yes
Reported Details:
Fuel Category: Liquid Fuel
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Ottawa
Approx. Quant. Rel: 90
Nearby body of water: No
Enter Drainage Syst.: Unknown
Approx. Quant. Unit: Liters
Environmental Impact: AST next to the building leaked oil for an unknown time.

---

83 ***2 of 2*** ***N/215.9*** ***59.9 / 0.00*** ***P.I. S 21(1)(f) 295 Frontenac St Ottawa ON*** ***SPL***

Ref No: 8328-7REVJE
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/24/2009
Dt Document Closed:
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: P.I. S 21(1)(f) Residence
Site Address:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Easting:	NA
Entity Operating Name:	
Client Name:	P.I. S 21(1)(f)
Client Type:	
Source Type:	
Incident Cause:	Tank (Above Ground) Leak
Incident Preceding Spill:	
Incident Reason:	Spill
Incident Summary:	Environmental Solutions, 90L Furnace oil contd
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Soil Contamination
Contaminant Qty:	90 L
Contaminant Qty 1:	90
Contaminant Unit:	L
Contaminant Code:	
Contaminant Name:	FURNACE OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

84	***1 of 11***	***SSW/216.5***	***61.2 / 1.28***	***CORPORATION OF THE CITY OF VANIER*** ***RAYMOND ROY*** ***256 MCARTHUR*** ***VANIER ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10112879	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	12215	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			

TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: Fuels Safety Private Fuel Outlet - Self Serve
Original Source: EXP
Record Date: Up to Mar 2012

---

84 | ***2 of 11*** | ***SSW/216.5*** | ***61.2 / 1.28*** | ***CORPORATION OF THE CITY OF VANIER***
RAYMOND ROY
256 MCARTHUR
VANIER ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11300712
Status: EXPIRED
Instance ID: 76492
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

84 | ***3 of 11*** | ***SSW/216.5*** | ***61.2 / 1.28*** | ***CORPORATION OF THE CITY OF VANIER***
RAYMOND ROY
256 MCARTHUR
VANIER ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11300669
Status: EXPIRED
Instance ID: 76949

Expired Date:
Max Hazard Rank:
Facility Location:

Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

84 **4 of 11** **SSW/216.5** **61.2 / 1.28** **256 McArthur Avenue**
Ottawa ON **EHS**

Order No:	20031112012	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Site Report	**Client Prov/State:**	ON
Report Date:	11/13/03	**Search Radius (km):**	0.25
Date Received:	11/12/03	**X:**	-75.658554
Previous Site Name:		**Y:**	45.431419
Lot/Building Size:			
Additional Info Ordered:			

84 **5 of 11** **SSW/216.5** **61.2 / 1.28** **CORPORATION OF THE CITY OF VANIER**
RAYMOND ROY
256 MCARTHUR AVE
VANIER ON **EXP**

Inventory No:	11300690	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	1975	**Overfill Protection:**	
Capacity:	9000	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:			
Previous Fuel Type:	Diesel		

84 **6 of 11** **SSW/216.5** **61.2 / 1.28** **CORPORATION OF THE CITY OF VANIER**
RAYMOND ROY
256 MCARTHUR AVE
VANIER ON **EXP**

Inventory No:	11300646	**Tank Material:**	Steel

Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	1975	**Overfill Protection:**	
Capacity:	4500	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:			
Previous Fuel Type:	Gasoline		

84 | ***7 of 11*** | ***SSW/216.5*** | ***61.2 / 1.28*** | ***CITY OF OTTAWA - RPAM***
256 MCARTHUR AVE VANIER GARAGE
VANIER ON K1L 6P4 | ***GEN***

Generator No.: ON3617506
Years Reported: 06

Alternate Locations

Generator No: ON3617506
Generator Nm: CITY OF OTTAWA - RPAM
Site Addr: 256 MCARTHUR AVE
City: VANIER
Reported Year(s): 06

Waste Reported

Waste Class: 252 - WASTE OILS & LUBRICANTS
Reported Years: 06

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 06

2006 Generator Info

NAICS Code 1: 811119
NAICS 1 Description: Other Automotive Mechanical and Electrical Repair and Maintenance
Contaminated Facility:
MHSW Facility:

2006 Manifest Summary

Waste Code:	252	**Waste Char Code:**	L
Waste Description:	WASTE OILS & LUBRICANTS	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	906.0	**Waste Count:**	1

84 | ***8 of 11*** | ***SSW/216.5*** | ***61.2 / 1.28*** | ***City of Ottawa Facility Operations Service***
256 McArthur Avenue
Ottawa ON K1L 6P4 | ***GEN***

Generator No.: ON6974902
Years Reported: 25,23,22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07

Alternate Locations

Generator No: ON6974902
Generator Nm: CITY OF OTTAWA FACILITY OPERATIONS SERVICE
Site Addr: 256 MCARTHUR AVENUE
City: OTTAWA

Reported Year(s): 25,23

Generator No: ON6974902
Generator Nm: CITY OF OTTAWA
Site Addr: 256 MCARTHUR
City: OTTAWA
Reported Year(s): 22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07

2025 Generator Info

Waste Reported

Waste Class: 252 - WASTE OILS & LUBRICANTS
Reported Years: 22,21,20,19,18,17,16,15,14,13,12,11,10,09

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 23,22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07

2025 Waste Info

Waste Code: 251
Waste Description: Oil Skimmings & Sludges
Waste Char Cd: L
Waste Char Desc: Liquid Industrial Waste

Waste Code: 252
Waste Description: Waste Oils & Lubricants
Waste Char Cd: L
Waste Char Desc: Liquid Industrial Waste

2023 Generator Info

NAICS Code: 913910
NAICS Description: Other Local Municipal and Regional Public Administration
Contamin'd Fac: No
MHSW Facility: No

2023 Manifest Summary

Waste Code: 251
Waste Description: Oil Skimmings & Sludges
Qty Received (kg): 2500
Waste Char Code: L
Waste Char Desc: Liquid Industrial Waste
Waste Count: 1

2022 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Fac: N
MHSW Facility: N

2022 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 6800.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1.0

2021 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Fac: N
MHSW Facility: N

2020 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Fac: N
MHSW Facility: N

2019 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Fac: N
MHSW Facility: N

2019 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 2000.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 2

2018 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Fac: N
MHSW Facility: N

2018 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 2400.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

2017 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Fac: N
MHSW Facility: N

2017 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 1300.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

2016 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Fac: N
MHSW Facility: N

2016 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE

Quantity (kg):	2240.0	***Waste Count:***	1

2015 Generator Info

NAICS Code 1:	913910
NAICS 1 Description:	Other Local Municipal and Regional Public Administration
Contaminated Fac:	N
MHSW Facility:	N

2015 Manifest Summary

Waste Code:	251	***Waste Char Code:***	L
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	3185.0	***Waste Count:***	1

2014 Generator Info

NAICS Code 1:	913910
NAICS 1 Description:	Other Local Municipal and Regional Public Administration
Contaminated Fac:	N
MHSW Facility:	N

2014 Manifest Summary

Waste Code:	252	***Waste Char Code:***	L
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	360.0	***Waste Count:***	1
Waste Code:	251	***Waste Char Code:***	L
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	6691.0	***Waste Count:***	2

2013 Generator Info

NAICS Code 1:	913910
NAICS 1 Description:	Other Local Municipal and Regional Public Administration
Contaminated Fac:	N
MHSW Facility:	N

2013 Manifest Summary

Waste Code:	251	***Waste Char Code:***	L
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	4330	***Waste Count:***	3

2012 Generator Info

NAICS Code 1:	913910
NAICS 1 Description:	Other Local Municipal and Regional Public Administration
Contaminated Fac:	N
MHSW Facility:	N

2012 Manifest Summary

Waste Code:	251	***Waste Char Code:***	L
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	75.0	***Waste Count:***	1

2011 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Facility: N
MHSW Facility: N

2010 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Facility: N
MHSW Facility: N

2009 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Facility: N
MHSW Facility: N

2009 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 15
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS
Quantity (kg): 2255
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 2

2008 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Facility: N
MHSW Facility: N

2008 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 150.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

2007 Generator Info

NAICS Code 1: 913910
NAICS 1 Description: Other Local Municipal and Regional Public Administration
Contaminated Facility:
MHSW Facility:

2007 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 150.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

84	*9 of 11*	*SSW/216.5*	*61.2 / 1.28*	***VANIER, CITY OF*** ***256 MCARTHUR AVENUE***	***GEN***

VANIER ON K1L 6P4

Generator No.: ON0619300
Years Reported: 01,00,99,98,97,96,95,94,93,92,90,89,88,87,86

Alternate Locations

Generator No: ON0619300
Generator Nm: VANIER, CITY OF
Site Addr: 256 MCARTHUR AVENUE
City: VANIER
Reported Year(s): 01,00,99,90,89,88,87,86

Generator No: ON0619300
Generator Nm: VANIER, CITY OF 40-078
Site Addr: 256 MCARTHUR AVENUE
City: VANIER
Reported Year(s): 98,97,96,95,94,93,92

Waste Reported

Waste Class: 212 - ALIPHATIC SOLVENTS
Reported Years: 01,00,99,98,97,96,95,94,93,92

Waste Class: 221 - LIGHT FUELS
Reported Years: 01,00,99,98,97,96,95,94,93

Waste Class: 252 - WASTE OILS & LUBRICANTS
Reported Years: 01,00,99,98,97,96,95,94,93,92,90,89,88,87,86

Waste Class: 145 - PAINT/PIGMENT/COATING RESIDUES
Reported Years: 01,00,99,98,97,96,95,94,93,92

Waste Class: 213 - PETROLEUM DISTILLATES
Reported Years: 01,00,99,98,97,96,95,94,93,92

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 01,00,99,98,97,96,95,94,93

2001 Generator Info

SIC Code: 8371 ***SIC Description:*** TRANSPORTATION ADMIN.

2001 Manifest Summary

Waste Code: 251 ***Waste Char Code:*** L
Waste Description: OIL SKIMMINGS & SLUDGES ***Waste Char Desc:*** LIQUID INDUSTRIAL WASTE
Quantity (kg): 8700.0 ***Waste Count:*** 5

Waste Code: 252 ***Waste Char Code:*** L
Waste Description: WASTE OILS & LUBRICANTS ***Waste Char Desc:*** LIQUID INDUSTRIAL WASTE
Quantity (kg): 1200.0 ***Waste Count:*** 1

2000 Generator Info

SIC Code: 8371 ***SIC Description:*** TRANSPORTATION ADMIN.

2000 Manifest Summary

Waste Code: 221 ***Waste Char Code:*** I

Waste Description:	LIGHT FUELS	***Waste Char Desc:***	IGNITABLE
Quantity (kg):	820.0	***Waste Count:***	1
Waste Code:	251	***Waste Char Code:***	L
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	5378.0	***Waste Count:***	3

1999 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN.

1999 Manifest Summary

Waste Code:	145	***Waste Char Code:***	H
Waste Description:	PAINT/PIGMENT/COATING RESIDUES	***Waste Char Desc:***	HAZARDOUS INDUSTRIAL WASTE
Quantity (kg):	661.0	***Waste Count:***	4
Waste Code:	252	***Waste Char Code:***	L
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	5032.0	***Waste Count:***	4
Waste Code:	252	***Waste Char Code:***	L
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	796.0	***Waste Count:***	1
Waste Code:	112	***Waste Char Code:***	C
Waste Description:	ACID WASTE - HEAVY METALS	***Waste Char Desc:***	CORROSIVE
Quantity (kg):	20.0	***Waste Count:***	1

1998 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN.

1998 Manifest Summary

Waste Code:	252	***Waste Char Code:***	L
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	1251.25	***Waste Count:***	1

1997 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN.

1997 Manifest Summary

Waste Code:	221	***Waste Char Code:***	I
Waste Description:	LIGHT FUELS	***Waste Char Desc:***	IGNITABLE
Quantity (kg):	113.75	***Waste Count:***	1
Waste Code:	252	***Waste Char Code:***	L
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	568.75	***Waste Count:***	1

1996 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN.

1996 Manifest Summary

Waste Code:	252	**Waste Char Code:**	L
Waste Description:	WASTE OILS & LUBRICANTS	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	683	**Waste Count:**	1

1995 Generator Info

SIC Code:	8371	**SIC Description:**	TRANSPORTATION ADMIN.

1995 Manifest Summary

Waste Code:	212	**Waste Char Code:**	L
Waste Description:	ALIPHATIC SOLVENTS	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	135	**Waste Count:**	1
Waste Code:	252	**Waste Char Code:**	L
Waste Description:	WASTE OILS & LUBRICANTS	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	455	**Waste Count:**	1

1994 Generator Info

SIC Code:	8371	**SIC Description:**	TRANSPORTATION ADMIN

1994 Manifest Summary

Waste Code:	212	**Waste Char Code:**	
Waste Description:	ALIPHATIC SOLVENTS	**Waste Char Desc:**	
Quantity (kg):	91.0	**Waste Count:**	1.0
Waste Code:	213	**Waste Char Code:**	
Waste Description:	PETROLEUM DISTILLATES	**Waste Char Desc:**	
Quantity (kg):	180.0	**Waste Count:**	6.0
Waste Code:	252	**Waste Char Code:**	
Waste Description:	WASTE OILS & LUBRICANTS	**Waste Char Desc:**	
Quantity (kg):	1365.0	**Waste Count:**	2.0

1993 Generator Info

SIC Code:	8371	**SIC Description:**	TRANSPORTATION ADMIN

1993 Manifest Summary

Waste Code:	212	**Waste Char Code:**	
Waste Description:	ALIPHATIC SOLVENTS	**Waste Char Desc:**	
Quantity (kg):	250.25	**Waste Count:**	2.0
Waste Code:	252	**Waste Char Code:**	
Waste Description:	WASTE OILS & LUBRICANTS	**Waste Char Desc:**	
Quantity (kg):	1592.5	**Waste Count:**	2.0
Waste Code:	221	**Waste Char Code:**	
Waste Description:	LIGHT FUELS	**Waste Char Desc:**	
Quantity (kg):	682.5	**Waste Count:**	1.0
Waste Code:	213	**Waste Char Code:**	
Waste Description:	PETROLEUM DISTILLATES	**Waste Char Desc:**	
Quantity (kg):	210.0	**Waste Count:**	6.0

1992 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN

1992 Manifest Summary

Waste Code:	252	***Waste Char Code:***	
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	
Quantity (kg):	800	***Waste Count:***	1
Waste Code:	213	***Waste Char Code:***	
Waste Description:	PETROLEUM DISTILLATES	***Waste Char Desc:***	
Quantity (kg):	150	***Waste Count:***	5
Waste Code:	252	***Waste Char Code:***	
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	
Quantity (kg):	800	***Waste Count:***	1

1990 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN

1990 Manifest Summary

Waste Code:	252	***Waste Char Code:***	
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	
Quantity (kg):	800.8	***Waste Count:***	1.0
Waste Code:	213	***Waste Char Code:***	
Waste Description:	PETROLEUM DISTILLATES	***Waste Char Desc:***	
Quantity (kg):	220.0	***Waste Count:***	4.0

1989 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN

1989 Manifest Summary

Waste Code:	213	***Waste Char Code:***	
Waste Description:	PETROLEUM DISTILLATES	***Waste Char Desc:***	
Quantity (kg):	190.0	***Waste Count:***	4.0
Waste Code:	252	***Waste Char Code:***	
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	
Quantity (kg):	1801.8	***Waste Count:***	2.0

1988 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN

1988 Manifest Summary

Waste Code:	252	***Waste Char Code:***	
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	
Quantity (kg):	800.8	***Waste Count:***	1.0
Waste Code:	213	***Waste Char Code:***	
Waste Description:	PETROLEUM DISTILLATES	***Waste Char Desc:***	
Quantity (kg):	160.0	***Waste Count:***	4.0
Waste Code:	212	***Waste Char Code:***	
Waste Description:	ALIPHATIC SOLVENTS	***Waste Char Desc:***	

Quantity (kg):	910.0	***Waste Count:***	1.0

1987 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN

1987 Manifest Summary

Waste Code:	252	***Waste Char Code:***	
Waste Description:	WASTE OILS & LUBRICANTS	***Waste Char Desc:***	
Quantity (kg):	801	***Waste Count:***	1.0

1986 Generator Info

SIC Code:	8371	***SIC Description:***	TRANSPORTATION ADMIN.

84 ***10 of 11*** ***SSW/216.5*** ***61.2 / 1.28*** ***CITY OF OTTAWA***
256 MCARTHER RD.
OTTAWA ON K1P 1J1 ***GEN***

Generator No.:	ON9196130
Years Reported:	04,03,02

Alternate Locations

Generator No:	ON9196130
Generator Nm:	CITY OF OTTAWA
Site Addr:	256 MCARTHER RD.
City:	OTTAWA
Reported Year(s):	04,03,02

Waste Reported

Waste Class:	251 - OIL SKIMMINGS & SLUDGES
Reported Years:	04,03,02
Waste Class:	221 - LIGHT FUELS
Reported Years:	04,03,02

2004 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2003 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2002 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

2002 Manifest Summary

Waste Code:	221	***Waste Char Code:***	L
Waste Description:	LIGHT FUELS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	714.0	***Waste Count:***	1

---

84 ***11 of 11*** ***SSW/216.5*** ***61.2 / 1.28*** ***CORPORATION OF THE CITY OF VANIER*** ***PRT***
RAYMOND ROY
256 MCARTHUR
VANIER ON K1L 6P4

Location ID:	29277
Type:	private
Expiry Date:	
Capacity (L):	13620.00
Licence #:	0076434612

---

85 ***1 of 1*** ***NE/218.8*** ***59.9 / 0.00*** ***327 Blakes Boulevard*** ***SPL***
OTTAWA ON

Ref No:	1-1IG34T	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	12/29/2021 7:00:00 PM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	12/29/2021 11:25:26 PM	***Impact to Health:***	0 No Impact
Dt Document Closed:	3/22/2022 12:32:20 PM	***Agency Involved:***	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	327 Blakes Boulevard		
Site Region:			
Site Municipality:	OTTAWA		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:	Unknown / N/A		
Incident Cause:			
Incident Preceding Spill:	Unknown / N/A		
Incident Reason:	Unknown		
Incident Summary:	City of Ottawa- odour in storm sewer		
Environment Impact:	1 Minor Impact		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	10 litre (L)		
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:	SEWAGE, ODOUR		
Contaminant Limit 1:			
Contam Limit Freq 1:			

Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill: Unknown
Property 2nd Watershed: Lower Ottawa
Property Tertiary Watershed: 02LA-Rideau
Sector Type:
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00003991132"],"wkts":["POINT (-75.6556579000 45.4342350000)"],"creation_date":"2021-12-29"}
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

86 | **1 of 1** | **ESE/224.1** | **58.9 / -1.00** | **308 McArthur Avenue Ottawa ON K1L6P2** | **EHS**

Order No: 20091130015
Status: C
Report Type: Standard Report
Report Date: 12/9/2009
Date Received: 11/30/2009
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: St. Laurent Blvd/McArthur Avenue
Municipality: Ottawa
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.655305
Y: 45.431585

---

87 | **1 of 1** | **SSW/229.8** | **61.9 / 2.03** | **ON** | **WWIS**

Well ID: 7452512
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z408567
Tag: A35706
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: OTTAWA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 06/21/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1009479564
Depth (m):
Year Completed: 2023
Well Completed Dt: 05/17/2023
Audit No: Z408567

Tag No: A35706
Contractor: 7241
Latitude: 45.4307889687091
Longitude: -75.6580592573722
Point Y: 45.43078896202326

Path:		**Point X:**	-75.65805909515352

Bore Hole Information

Bore Hole ID:	1009479564	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448525.00
Code OB Desc:		**North83:**	5031018.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/17/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

88 | ***1 of 1*** | ***SSW/230.1*** | ***61.9 / 2.03*** | ***ON*** | ***WWIS***

Well ID:	7429652	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	09/22/2022
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z385918	**Contractor:**	7241
Tag:	A357206	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/742\7429652.pdf

Additional Detail(s) (Map)

Well Completed Date:	08/26/2022
Year Completed:	2022
Depth (m):	
Latitude:	45.4307802626393
Longitude:	-75.6580080199523
Point X:	-75.65800785796237
Point Y:	45.430780256047164
Path:	742\7429652.pdf

Bore Hole Information

Bore Hole ID:	1009215176	**Elevation:**	
DP2BR:		**Elevrc:**	

Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448529.00
Code OB Desc:		**North83:**	5031017.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/26/2022	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

89 | ***1 of 1*** | ***SW/232.4*** | ***62.0 / 2.08*** | ***ON*** | ***BORE***

Borehole ID:	613593	**Inclin FLG:**	No
OGF ID:	215514836	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:	JUN-1972	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.431001
Total Depth m:	4.7	**Longitude DD:**	-75.659011
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	448451
Drill Method:		**Northing:**	5031042
Orig Ground Elev m:	64.5	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	63.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218395749	**Mat Consistency:**	Dense
Top Depth:	2.3	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Shale	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	TILL. WEATHERED,LOOSE,DENSE.		

Geology Stratum ID:	218395750	**Mat Consistency:**	Dense
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	3.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Shale	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	TILL. VERY DENSE.		

Geology Stratum ID:	218395751	**Mat Consistency:**	Dense

Top Depth:	3.8	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: TILL. VERY DENSE. 00010 020 00025 020 00050 020 00075 012 00100 009 00125 01 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218395747	**Mat Consistency:**	Dense
Top Depth:	.8	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: SAND. LOOSE,DENSE.

Geology Stratum ID:	218395745	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:		**Geologic Formation:**	
Material 2:	Fill	**Geologic Group:**	
Material 3:	Asphalt	**Geologic Period:**	
Material 4:	Bedrock	**Depositional Gen:**	

Gsc Material Description:
Stratum Description: ARTIFICIAL.

Geology Stratum ID:	218395746	**Mat Consistency:**	
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:		**Geologic Formation:**	
Material 2:	Fill	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Silt	**Depositional Gen:**	

Gsc Material Description:
Stratum Description: ARTIFICIAL.

Geology Stratum ID:	218395748	**Mat Consistency:**	Loose
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	2.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: SAND. VERY LOOSE.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 061010 NTS_Sheet: 31G05G
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

90 ***1 of 1*** ***NE/232.8*** ***59.9 / 0.00*** ***322-326 Frontenac Street Vanier ON K1L 6K7*** ***EHS***

Order No:	25030400888	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	07-MAR-25	***Search Radius (km):***	.25
Date Received:	04-MAR-25	***X:***	-75.6558711
Previous Site Name:		***Y:***	45.4345521
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

91 ***1 of 1*** ***ESE/233.9*** ***58.9 / -1.00*** ***WB lane 313 McArthur Ave, Ottawa ON*** ***SPL***

Ref No:	1-1DENSY	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	11/3/2021 5:33:00 AM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	11/3/2021 6:31:00 AM	***Impact to Health:***	0 No Impact
Dt Document Closed:	12/1/2021 9:57:31 AM	***Agency Involved:***	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Ottawa District Office		
Nearest Watercourse:	catchbasin		
Site Name:			
Site Address:	WB lane 313 McArthur Ave, Ottawa		
Site Region:			
Site Municipality:	OTTAWA		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Incident Reason:			
Incident Summary:	Coolant to CB - OC Transpo, Ottawa		
Environment Impact:	1 Minor Impact		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	1 litre (L)		
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			

Contaminant Name:	COOLANT (N.O.S.)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Surface Water
Activity Preceding Spill:	
Property 2nd Watershed:	Lower Ottawa
Property Tertiary Watershed:	02KF - Central Ottawa - Mississippi
Sector Type:	URBAN TRANSIT SYSTEMS
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00003966958"],"wkts":["POINT (-75.6550053000 45.4319639000)"],"creation_date":"2021-11-03"}
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

92 **1 of 1** **S/234.0** **61.9 / 2.03** **ON** **WWIS**

Well ID:	7429651	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	09/22/2022
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z385917	**Contractor:**	7241
Tag:	A357207	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/742\7429651.pdf

Additional Detail(s) (Map)

Well Completed Date:	08/26/2022
Year Completed:	2022
Depth (m):	
Latitude:	45.4307357748461
Longitude:	-75.6579180146315
Point X:	-75.65791785309275
Point Y:	45.43073576792845
Path:	742\7429651.pdf

Bore Hole Information

Bore Hole ID:	1009215173	**Elevation:**	
DP2BR:		**Elevrc:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Spatial Status:				**Zone:**	18
Code OB:				**East83:**	448536.00
Code OB Desc:				**North83:**	5031012.00
Open Hole:				**Org CS:**	UTM83
Cluster Kind:				**UTMRC:**	4
Date Completed:	08/26/2022			**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:				**Location Method:**	wwr
Location Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					

93	1 of 1	SSW/235.1	61.9 / 2.03	252 McArthur Ave. Vanier ON K1L 6P4	EHS

Order No:	21060300597	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	11-JUN-21	**Search Radius (km):**	.25
Date Received:	03-JUN-21	**X:**	-75.65798737
Previous Site Name:		**Y:**	45.43073232
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos		

94	1 of 1	S/235.3	61.6 / 1.69	ON	WWIS

Well ID:	7452517	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	06/21/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z408568	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009479579	**Tag No:**	
Depth (m):		**Contractor:**	7241
Year Completed:	2023	**Latitude:**	45.4307103188525
Well Completed Dt:	05/17/2023	**Longitude:**	-75.6576492539136
Audit No:	Z408568	**Point Y:**	45.43071031189906
Path:		**Point X:**	-75.6576490916241

Bore Hole Information

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1009479579	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448557.00
Code OB Desc:		**North83:**	5031009.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/17/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

95 | ***1 of 1*** | ***S/235.9*** | ***61.9 / 2.03*** | ***ON*** | ***WWIS***

Well ID:	7452519	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	06/21/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z408572	**Contractor:**	7241
Tag:	A357207	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009479585	**Tag No:**	A357207
Depth (m):		**Contractor:**	7241
Year Completed:	2023	**Latitude:**	45.4307178471757
Well Completed Dt:	05/17/2023	**Longitude:**	-75.6579050222875
Audit No:	Z408572	**Point Y:**	45.43071784028567
Path:		**Point X:**	-75.6579048598663

Bore Hole Information

Bore Hole ID:	1009479585	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448537.00
Code OB Desc:		**North83:**	5031010.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/17/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

---

96 | ***1 of 12*** | ***SSW/240.1*** | ***62.0 / 2.08*** | ***CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr*****
248 MCARTHUR AVE
VANIER ON K1L 6P4 | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9954712
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 4/23/1992
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

96 | ***2 of 12*** | ***SSW/240.1*** | ***62.0 / 2.08*** | ***CANADIAN TIRE CORPORATION LIMITED***
248 MCARTHUR AVE
VANIER ON | ***EXP***

Inventory No: 11114983
Inventory Status: EXPIRED
Installation Year: 1992
Capacity: 22730
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

96 | ***3 of 12*** | ***SSW/240.1*** | ***62.0 / 2.08*** | ***CANADIAN TIRE CORPORATION LIMITED*** | ***EXP***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				248 MCARTHUR AVE VANIER ON	

Inventory No: 11114940
Inventory Status: EXPIRED
Installation Year: 1992
Capacity: 31822
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	4 of 12	SSW/240.1	62.0 / 2.08	CANADIAN TIRE CORPORATION LIMITED 248 MCARTHUR AVE VANIER ON	EXP

Inventory No: 11114957
Inventory Status: EXPIRED
Installation Year: 1992
Capacity: 31822
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	5 of 12	SSW/240.1	62.0 / 2.08	CANADIAN TIRE CORPORATION LIMITED 248 MCARTHUR AVE VANIER ON	EXP

Inventory No: 11114968
Inventory Status: EXPIRED
Installation Year: 1992
Capacity: 22730
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	6 of 12	SSW/240.1	62.0 / 2.08	TOTH EQUITY LIMITED 248 McArthur Ave Vanier ON K1L6P4	GEN

Generator No.: ON1497150
Years Reported: 04,03,02

Alternate Locations

Generator No: ON1497150
Generator Nm: TOTH EQUITY LIMITED
Site Addr: 248 MCARTHUR AVE
City: VANIER
Reported Year(s): 04,03,02

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 04,03,02

2004 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2003 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

2002 Generator Info

NAICS Code 1:
NAICS 1 Description:
Contaminated Facility:
MHSW Facility:

96	*7 of 12*	*SSW/240.1*	*62.0 / 2.08*	***Romay Automotive Ltd*** ***248 McArthur av*** ***Ottawa ON***	***HBAR***

Province: ON
Year: 1960
Source: Mights

96	*8 of 12*	*SSW/240.1*	*62.0 / 2.08*	***Romay Automotive Ltd*** ***248 McArthur av*** ***Eastview ON***	***HBAR***

Province: ON
Year: 1967
Source: Mights

96	*9 of 12*	*SSW/240.1*	*62.0 / 2.08*	***Canadian Tire Corp Associate Store*** ***248 Mcarthur Av*** ***Vanier ON***	***HBAR***

Province: ON
Year: 1987
Source: Polks

96	*10 of 12*	*SSW/240.1*	*62.0 / 2.08*	***Romay Automotive Ltd*** ***248 McArthur av*** ***Eastview ON***	***HBAR***

Province: ON
Year: 1964
Source: Mights

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	11 of 12	SSW/240.1	62.0 / 2.08	CANADIAN TIRE ROMAY AUTOMOTIVE LTD. 248 MCARTHUR AVENUE VANIER ON	PES

Detail Licence No:		Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Vendor	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	12 of 12	SSW/240.1	62.0 / 2.08	CANADIAN TIRE CORP LTD PETROLEUM DIVISION - SUSAN 248 MCARTHUR AV VANIER ON K1L6P4	PRT

Location ID:	20054
Type:	retail
Expiry Date:	1993-04-30
Capacity (L):	109104
Licence #:	0076361724

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	1 of 1	NNW/241.2	59.9 / 0.00	PIPELINE HIT 1/2" 280 RICHELIEU AVE,,VANIER,ON,K1L 6K3,CA ON	PINC

Incident Id:		Pipe Material:	
Incident No:	1404528	Fuel Category:	
Incident Reported Dt:	5/28/2014	Health Impact:	
Type:	FS-Pipeline Incident	Environment Impact:	
Status Code:		Property Damage:	
Tank Status:	Pipeline Damage Reason Est	Service Interrupt:	
Task No:		Enforce Policy:	
Spills Action Centre:		Public Relation:	
Fuel Type:		Pipeline System:	
Fuel Occurrence Tp:		PSIG:	
Date of Occurrence:		Attribute Category:	
Occurrence Start Dt:		Regulator Location:	
Depth:		Method Details:	
Customer Acct Name:	PIPELINE HIT 1/2"		
Incident Address:	280 RICHELIEU AVE,,VANIER,ON,K1L 6K3,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			

Occurrence Desc:
Damage Reason:
Notes:

---

98 | ***1 of 1*** | ***S/244.7*** | ***61.6 / 1.69*** | ***ON*** | ***WWIS***

Well ID:	7429650	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	09/22/2022
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z385916	***Contractor:***	7241
Tag:	A357208	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	GLOUCESTER TOWNSHIP		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009215170	***Tag No:***	A357208
Depth (m):		***Contractor:***	7241
Year Completed:	2022	***Latitude:***	45.4306287241282
Well Completed Dt:	08/06/2022	***Longitude:***	-75.6577505784903
Audit No:	Z385916	***Point Y:***	45.430628717029684
Path:		***Point X:***	-75.65775041617158

Bore Hole Information

Bore Hole ID:	1009215170	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448549.00
Code OB Desc:		***North83:***	5031000.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/06/2022	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

99 | ***1 of 1*** | ***WNW/246.0*** | ***59.9 / 0.00*** | ***335 Olmstead St Ottawa ON K1L7K2*** | ***EHS***

Order No:	20140806032	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	12-AUG-14	**Search Radius (km):**	.25
Date Received:	06-AUG-14	**X:**	-75.660456
Previous Site Name:		**Y:**	45.433694
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

100 *1 of 1* *SSW/248.0* *61.9 / 2.03* *ON* **WWIS**

Well ID:	7452513	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	06/21/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z408573	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009479567	**Tag No:**	
Depth (m):		**Contractor:**	7241
Year Completed:	2023	**Latitude:**	45.4306440007571
Well Completed Dt:	05/17/2023	**Longitude:**	-75.6582237650621
Audit No:	Z408573	**Point Y:**	45.430643994466365
Path:		**Point X:**	-75.65822360269091

Bore Hole Information

Bore Hole ID:	1009479567	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	448512.00
Code OB Desc:		**North83:**	5031002.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/17/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

101 *1 of 1* *S/249.6* *61.6 / 1.69* *ON* **WWIS**

Well ID:	7452511	**Flowing (Y/N):**	

Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	06/21/2023
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z408569	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1009479561	***Tag No:***	
Depth (m):		***Contractor:***	7241
Year Completed:	2023	***Latitude:***	45.4305837944836
Well Completed Dt:	05/17/2023	***Longitude:***	-75.6577372725828
Audit No:	Z408569	***Point Y:***	45.430583786875175
Path:		***Point X:***	-75.65773711123212

Bore Hole Information

Bore Hole ID:	1009479561	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	448550.00
Code OB Desc:		***North83:***	5030995.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	05/17/2023	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Unplottable Summary

Total: 3 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	OTTAWA CITY	BLAKE BLVD.	OTTAWA CITY ON	
CA	R.M. OF OTTAWA-CARLETON	JEANNE MANCE ST./ST. ANNE AVE.	VANIER CITY ON	
CA	VANIER CITY	LAFONTAINE STREET	VANIER CITY ON	

Unplottable Report

Site: ***OTTAWA CITY***
BLAKE BLVD. OTTAWA CITY ON

Database: ***CA***

Certificate No: 3-1669-89-
Ref No:
Contaminants:
Application Year: 89
Issue Date: 8/15/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Emission Control:

Address:

Site: ***R.M. OF OTTAWA-CARLETON***
JEANNE MANCE ST./ST. ANNE AVE. VANIER CITY ON

Database: ***CA***

Certificate No: 7-1623-89-
Ref No:
Contaminants:
Application Year: 89
Issue Date: 10/3/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Emission Control:

Address:

Site: ***VANIER CITY***
LAFONTAINE STREET VANIER CITY ON

Database: ***CA***

Certificate No: 3-0195-96-
Ref No:
Contaminants:
Application Year: 96
Issue Date: 4/1/1996
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:

Project Description:
Emission Control:

Address:

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Oct 2025

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-May 2025

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Apr 30, 2025

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2024

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Apr 30, 2025

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 - May 2026

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-May 2026

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - May 31, 2026

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database (ODHD) is offered by the Province of Ontario's Ministry of Mines. The dataset contains information for over 164,000 percussion, overburden, sonic and diamond-drill holes. The presence of assay results with cutoff values for gold, silver, copper, zinc, lead, nickel and platinum group elements is noted. Drill hole data are compiled from assessment files that have been submitted to the ministry in accordance with the Ontario Mining Act (OMA). Source assessment file numbers are captured for cross reference with the Ontario Assessment File Database (OAFD). Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Jul 2025

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011 - Apr 30, 2026

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - May 31, 2026

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011 - Apr 30, 2026

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Feb 28, 2026

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Offenders Registry: Federal EOR

The Environmental Offenders Registry, enforced by Environment and Climate Change Canada and Parks Canada, tracks corporations convicted under specific federal environmental laws. The registry includes corporate convictions resulting from court proceedings. Court prosecutions are one of several enforcement measures used when violations or potential violations are detected. Other measures like tickets, warning letters, or compliance orders may also be employed to restore compliance. Although not affected by the Environmental Enforcement Act, convictions obtained by Environment and Climate Change Canada under the Species at Risk Act and the Pollution Prevention Provisions of the Fisheries Act are also included.

Government Publication Date: Feb 28, 2026

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment, Conservation and Parks (MECP). These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2025

Excess Soil Registry: Provincial ESNR

The Excess Soil Registry is made available by the Resource Productivity and Recovery Authority (RPRA). Excess soil is soil dug up mainly during construction and excavation activities that must be removed from the development site because it cannot or will not be reused. The Minister of the Environment, Conservation and Parks directed the RPRA to establish and maintain the Excess Soil Registry, enabling regulated parties to comply with registration and filing notice requirements, the ministry to access data, and the public to view information from those filings. From January 1, 2023, construction and development project leaders, as well as operators and owners of soil Reuse Sites, and Residential Development Soil Depot sites, must file notices detailing how excess soil is reused and disposed of in compliance with Ontario's Excess Soil Regulation.

Government Publication Date: Oct 31, 2025

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Feb 2026

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada (DFO) maintains an inventory of aboveground & underground fuel storage tanks located on DFO property or controlled by the DFO. The DFO provided 2019 data. Environment and Climate Change Canada (ECCC) provided the 2024 data on owned and regulated storage tank systems, as required from the Canadian Environmental Protection Act (CEPA) and its associated regulations. The ECCC might have information pertaining to non-regulated tanks or ones which are not owned and operated by DFO.

Government Publication Date: 1964-Mar 2025

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: 31 Mar, 2025

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. As of January 1, 2023, businesses and institutions subject to the amended Reg. 347: General – Waste Management are required to report their activities and pay fees through Resource Productivity & Recovery Authority (RPRA) online Hazardous Waste Program Registry (HWPR) rather than the Hazardous Waste Information Network (HWIN) system previously operated by the Ministry of the Environment, Conservation and Parks (MECP). Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Sep 30, 2025

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Jan 2026

Historical Business Activity Risk: Federal HBAR

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this list does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including BC Directories, Hendersons, Mights, Sun Directories, Vernons, and Wrights; spanning roughly 1920s through 1990 depending on information available by city.

This list is currently limited to sites as reported in the following provinces: Alberta, British Columbia, Saskatchewan, Manitoba, New Brunswick, Nova Scotia, Ontario, and Quebec.

Government Publication Date: 1920s - 1990

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Jan 2026

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment Conservation and Parks (MECP) provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act. MECP publicly releases the Environmental Compliance Report (ECR) on the Ontario Data Catalogue. In Ontario, all facilities with regulated wastewater discharges or air emissions under the Ontario Water Resources Act and the Environmental Protection Act must monitor and report any cases where approved operating limits have been exceeded.

Government Publication Date: Dec 31, 2024

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Feb 28, 2026

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

Notice of Contamination List: Federal NOC

This dataset contains Notice of Contamination (NOC) submissions reported to the Canada Energy Regulator (CER), including the most recent annual update information where applicable. Regulated companies are required to submit an NOC when contamination is identified or encountered during any phase of a facility's lifecycle and confirmed through analytical sampling, or when contamination resulting from an incident cannot be remediated within 12 weeks of being reported to the CER. Blank values in the Annual Update Year and annual update fields indicate that the site has achieved remediation closure, has been identified as third-party contamination, or was reported recently and does not yet require an annual update.

Government Publication Date: Nov, 2025

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Feb 2024

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Feb 28, 2025

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the Ministry of Natural Resources (MNR) handed over to the Ontario Oil, Gas and Salt Resources (OGSR) Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database includes well owner/operator, location, permit issue date, and well cap date, license number, status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provided for each well record.

Government Publication Date: 1800-May 2025

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - May 31, 2026

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011 - Apr 30, 2026

Ontario PFAS Spills: Provincial PFAS

This specific list of spills includes those incidents where one or more of the listed contaminants are identified in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA), is originally sourced from the Ministry of the Environment, Conservation and Parks spills related data. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988- May 2026

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Feb 2024

Potential PFAS Handlers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Feb 2024

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Potential PFAS Handlers from EASR: Provincial PPHA

The Ontario Environmental Activity and Sector Registry (EASR), described in Ontario Regulation 245/11, allows businesses with less complex operations - and hence not requiring an Environmental Compliance Approval - to register their activities with the Ontario Ministry of the Environment, Conservation and Parks (MECP). This list of potential PFAS handlers includes those EASR facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used.

Government Publication Date: Feb 28, 2026

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - May 31, 2026

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2022

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004 - 31 May, 2026

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Apr 30, 2025

Scott's Manufacturing Directories: Private SCT

Scott's Directories is a data bank containing information on various manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, applicable NAICS Codes, and product categories are included in this database.

Government Publication Date: 1992-Mar 2011; Feb 2025

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988- Mar 2026

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2024

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Dec 2025

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011 - Apr 30, 2026

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Waste Management Site: Provincial WMS

This data contains Waste Disposal Site types collected by the Ministry of Natural Resource (MNR). The new data class brings over data from the Waste Management Information System (WMIS), which is an MS Access based database used by MNR to track Waste Management Sites. This was married with the spatial data from Waste Disposal Sites where possible. Different Waste Disposal Site types collected by the Ministry of Natural Resources include: compost disposal, hazardous waste disposal, household waste disposal, industrial waste disposal, septic drying bed, septic field, sewage disposal, tile bed, and transfer station. The data is currently under development, meaning the data is currently in the process of being created by the MNR.

Government Publication Date: April 30, 2025

Water Well Information System: Provincial WWIS

This database consists of information submitted by well contractors detailing locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table. The database is provided by the Ontario Ministry of Environment, Conservation and Parks.

Government Publication Date: Jul 31, 2025

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

File Number: D06-03-26-0097

July 23, 2026

Mark Bujaki
Paterson Group

Sent via email Apmbujaki@patersongroup.ca

Dear Mark,

Re: Information Request
349 Olmstead Street Ottawa, Ontario ("Subject Property")

Internal Department Circulation:

The Planning, Development and Building Services Department has the following information in response to your request for information regarding the Subject Property:

- **Environmental Remediation Unit:** The City's Environmental Remediation Unit (ERU) has copies of the following environmental reports for the property:
    - exp, 2015. 349 Olmstead Street - Phase I ESA. 29May2015

  Please contact ERU-UAE@ottawa.ca to request copies of the reports if required. To submit requests for information under the Municipal Freedom of Information and Protection of Privacy Act, please visit https://ottawa.ca/en/city-hall/open-transparent-andaccountable-government/access-information-and-protection-privacy/accessinformation

- **Sewer Use Program:** The City's Sewer Use Program has found no information found pertaining to the subject property.

- **Solid Waste Services:** No information found pertaining to the subject property

- **Ottawa Public Health - Environmental Health:** all public inspection results are publicly available on the Ottawa Public Health website: https://www.ottawapublichealth.ca/en/public-health-services/public-health-inspections.aspx

Documents Provided:

HLUI Summary Report and HLUI Map

The HLUI Summary Report Excel spreadsheet identifies HLUI area, point and line features within 250 metres of the Subject Property, as shown on the provided HLUI Map

PDF. Within 500 metres of the Subject Property, landfills and Environmental Risk Management Area (ERMA) are also identified if applicable.

For more information on how to interpret the HLUI data identified in the attached excel sheet ('349 Olmstead – HLUI Summary report.xlsx'), please refer to the Overview and User Guide."

Additional information may be obtained by contacting:

Ontario's Environmental Registry

The Environmental Registry found at https://ero.ontario.ca/ contains "public notices" about environmental matters being proposed by all government ministries covered by the Environmental Bill of Rights. The public notices may contain information about proposed new laws, regulations, policies and programs or about proposals to change or eliminate existing ones. By using keys words i.e. name of proponent/owner and the address one can ascertain if there is any information on the proponent and address under the following categories: Ministry, keywords, notice types, Notice Status, Acts, Instruments and published date (all years).

The Ontario Land Registry Office

Registration of real property is recorded in the Ontario Land Registry Office through the Land Titles Act or the Registry Act. Documents relating to title and other agreements that may affect your property are available to the public for a fee. It is recommended that a property search at the Land Registry Office be included in any investigation as to the historic use of your property. The City of Ottawa cannot comment on any documents to which it is not a party.

Court House
161 Elgin Street 4th Floor
Ottawa ON K2P 2K1
Tel: (613) 239-1230
Fax: (613) 239-1422

Ottawa Public Health

Ottawa Public Health inspects many different types of establishments. To view inspection results, please visit the Ottawa Public Health website: Public Health Inspections - Ottawa Public Health

Please note that Ottawa Public Health is not the lead agency on land use contamination in the City of Ottawa – contact the Ministry of Environment Conservation and Parks (MECP) for further information.

Please note, as per the HLUI Disclaimer, that the information contained in the HLUI database has been compiled from publicly available records and other sources of

information. The HLUI may contain erroneous information given that the records used as sources of information may be flawed. For instance, changes in municipal addresses over time may introduce error. Accordingly, all information from the HLUI database is provided on an "as is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in responding to the request.

Furthermore, the HLUI database and the results of this search in no way confirm the presence or absence of contamination or pollution of any kind. This information is provided on the assumption that it will not be relied upon by any person for any purpose whatsoever. The City of Ottawa denies all liability to any persons attempting to rely on any information provided from the HLUI database.

Please note that in responding to your request, the City of Ottawa does not guarantee or comment on the environmental condition of the Subject Property. You may wish to contact the Ontario Ministry of Environment and Climate Change for additional information.

If you have any further questions or comments, please contact HLUI@ottawa.ca.

Sincerely,

Kaatje Yates


Student Planner | Étudiante en Urbanism
Development Review | Examen des projets d'aménagement
Planning, Development and Building Services | Services de la planification, de l'aménagement et du bâtiment

Enclosures: (2)

1. HLUI Map
2. HLUI Summary Report

cc: File no. D06-03-26-0097

HISTORIC LAND USE INVENTORY (HLUI) - REPORT REFERENCE MAP



HLUI SUMMARY REPORT
AREA FEATURES


OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	SOURCE_UPDATE_SORTED	QAQC	YEAR	YEAR_1	ST_NUM	ST_NAME	ST_SUFFIX	MUNICIPALITY	ST_NUM2017	ST_NAME2017	ST_SUFFIX2017	POSTAL_CODE2017	PIN2017	MUNICIPALITY2017	NAICS	SIC	COMMENTS	Shape_Length	Shape_Area
10936	SPINS LAUNDRYMART	Other services (except public administration)	2012-ES	1			320	MCARTHUR	AVE		320	MCARTHUR	AVE	K1L5G2	42470270	VANIER	812310			15368.02378	569.7775304
13652	CANADIAN TIRE CORP	Motor Vehicle Repair Shops	1966-1998-M	1	1966-1998		242	MCARTHUR	AVE	VANIER	242	MCARTHUR	AVE		42480082	VANIER				14249.10023	603.2835768
14381	PLAZA GULF SERVICE STATION	Motor Vehicle Repair Shops	1980-M	1	1980		330	MCARTHUR	AVE	VANIER	330	MCARTHUR	AVE	K1L6N8	42470260	Vanier				926.1347915	121.9144486
17106	CATP	Wholesale trade	2016-PID	1	2016	PID2016	311	MCARTHUR	AVE	VANIER	311	MCARTHUR	AVE	K1L8M3	42400048	VANIER	414510			2624.489047	220.0596206
17237	CITY OF VANIER	Motor Vehicle Repair Shops	1994-PID	1	1994	c. 1994	256	MCARTHUR	AVE	VANIER	252	MCARTHUR	AVE	K1L6P4	42480086	VANIER	811112; 811119; 811121; 913910	635; 835	Generator #ON0619300 (waste generator)	8210.792103	411.8132809
13745	PLAZA SHOE REPAIR	Recreational Vehicle Dealers (where servicing is present)	2001-ES	1	2001		320	MCARTHUR	AVE		320	MCARTHUR	AVE		42470270					15368.02378	569.7775304
17194	SERVIT UP	Public Passenger Transit Systems Industries	2001-ES	1	2001	c. 2001	306	MCARTHUR	AVE	OTTAWA	294	MCARTHUR	AVE	K1L6P2	42470229	VANIER	488990			1559.370447	158.9269135
17198	BA SERVICE STATION	Gasoline Service Stations	1961-M; 1966-M; 1971-M; 1976-M; 1981-M; 1982-M; 1986-M; 1990-M; 1996-CDMPI	1	1956-1996	c. 1961-1990	320	MCARTHUR	AVE	OTTAWA	330	MCARTHUR	AVE	K1L6N8	42470260	VANIER	447110; 447190; 811199	633	#NAME?	926.1347915	121.9144486
17202	NETTOYEUR A SEC EXTRA DRY CLEANERS	Laundries and Cleaners	2000-PID; 2001-ES	1	1961-2001	c. 1961-1998; c. 2000; c. 2001	320	MCARTHUR	AVE	VANIER	320	MCARTHUR	AVE	K1L5G2	42470270	VANIER	561740; 812310; 812320; 812330	972		15368.02378	569.7775304
14633	IMPRIMERIE RENAUD	Men'S and Boys' Clothing Industries	2001-ES	1	2001	c. 2001	219	JEANNE MANCE	ST	OTTAWA	336	OLMSTEAD	ST	K1L7K3	42380064	VANIER	323113			325.1132788	73.14669858
17196	BAROUD AUTO REPAIR	Automobile Repairing & Service	2017-SalesGenie	1	2017	SalesGenie 2017				VANIER	294	MCARTHUR	AVE	K1L6P2	42470229	VANIER	81111104	7538-01		1559.370447	158.9269135
14771	TOTH EQUITY LIMITED	Motor Vehicles, Wholesale	2003-PID	1	2003	c. 2003	248	MCARTHUR	AVE	VANIER	248	MCARTHUR	AVE	K1L6P4	42480082	VANIER	811111			14249.10023	603.2835768
16904	95661 CANADA LIMITED	Motor Vehicle Repair Shops	2005-PropertyAssessment	1	2005	c. 2001; c. 2005	280	MCARTHUR	AVE	VANIER	280	MCARTHUR	AVE	K1L6P2	42470099	VANIER	811111; 811112; 811119; 811121; 811199			1659.770683	172.7350657
12808	OTTAWA IRON WORKS	Primary Steel Industries	1951-M; 1956-M; 1961-M; 1966-M; 1971-M; 1976-M; 1981-M; 1982-M; 1986-M; 1990-M; 1994-PID	1	1951-1994	c. 1951-1971	256	MCARTHUR	AVE	VANIER	252	MCARTHUR	AVE	K1L6P4	42480086	VANIER	331110; 331221; 331514; 332311; 332319; 332420; 332710; 333619; 336310; 336350; 493120; 493130; 493190	291; 302; 308; 479		8210.792103	411.8132809
14770	ONTARIO MOTOR SALES	Motor Vehicle Repair Shops	1966-M; 1971-M	2	1966-1971	c. 1956; c. 1966; c. 1966-1998	242	MCARTHUR	AVE	VANIER	248	MCARTHUR	AVE	K1L6P4	42480082	VANIER	811112; 811119; 811121	635		14249.10023	603.2835768
16872	BEL-AIR LEXUS TOYOTA COLISION CENTRE	Motor Vehicle Repair Shops	1990-CD; 2001-ES; 2005-SelectPhone; 2006-ES; 2012-ES; 2017-SalesGenie	1	1990-2017	CD 1990	280	MCARTHUR	AVE		280	MCARTHUR	AVE	K1L6P2	42470099	VANIER				1659.770683	172.7350657
16905	GERRY'S WHITE ROSE SERVICE STATION	Gasoline Service Stations	1966-M; 1971-M	1	1966-1971	c. 1966-1971	280	MCARTHUR	AVE	VANIER	280	MCARTHUR	AVE	K1L6P2	42470099	VANIER	447110; 447190; 811199	633		1659.770683	172.7350657

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	SOURCE_UPDATE_SORTED	QAQC	YEAR	YEAR_1	ST_NUM	ST_NAME	ST_SUFFIX	MUNICIPALITY	ST_NUM2017	ST_NAME2017	ST_SUFFIX2017	POSTAL_CODE2017	PIN2017	MUNICIPALITY2017	NAICS	SIC	COMMENTS	Shape_Length	Shape_Area
17077	CARE MEDICS	Hospitals	2001-ES; 2016-PID	1	2001-2016	c. 2001	311	MCARTHUR	AVE	OTTAWA	311	MCARTHUR	AVE	K1L8M3	42400048	VANIER	622111			2624.489047	220.0596206
17193	METER MAN AUTOMOTIVE CENTRE	Other services (except public administration)	2006-ES	1	2006	ES 2006	306	MCARTHUR	AVE		294	MCARTHUR	AVE	K1L6P2	42470229	VANIER	811111			1559.370447	158.9269135
17201	KOMPUTER KORNER	Appliance, Television, Radio and Stereo Stores	2001-ES	1	2001	c. 2001	320	MCARTHUR	AVE	OTTAWA	320	MCARTHUR	AVE	K1L5G2	42470270	VANIER	443110			15368.02378	569.7775304
10935	HERITAGE GLASS	Other services (except public administration)	2006-ES	1			364	LACASSE	AVE		364	LACASSE	AVE	K1L7A9	42400015	VANIER	811490			720.4144396	110.3047235
13688	ROMAY AUTOMOTIVE LTD	Motor Vehicle Repair Shops	1956-M	1	1956		242	MCARTHUR	AVE	VANIER	242	MCARTHUR	AVE		42480082	VANIER				14249.10023	603.2835768
13936	ECONOFORMS	Commercial Printing Industries	2005-SelectPhone	1	2005		219	JEANNE MANCE	ST		336	OLMSTEAD	ST	K1L7K3	42380064	Vanier				325.1132788	73.14669858
13937	RENAUD PRINTERS	Commercial Printing Industries	1956-1998-M	1	1956-1998		219	JEANNE MANCE	ST		336	OLMSTEAD	ST	K1L7K3	42380064	Vanier				325.1132788	73.14669858
17076	DAUPHIN PHOTO	Photographers	2005-SelectPhone	1	2005	c. 2005	301	MCARTHUR	AVE		295	MCARTHUR	AVE	K1L6P1	42400024	VANIER	541920			1193.234963	136.2386008
17195	THOMPSON & RAY GARAGE	Motor Vehicle Repair Shops	1951-M	1	1951	c. 1951	300	MCARTHUR	AVE	VANIER	294	MCARTHUR	AVE	K1L6P2	42470229	VANIER	811112; 811119; 811121	635		1559.370447	158.9269135
17199	CRETE ROGER LTD	Dry Cleaners	1990-CD	1	1990	CD 1990	320	MCARTHUR	AVE		320	MCARTHUR	AVE	K1L5G2	42470270	VANIER				15368.02378	569.7775304
17871	MR MASON	Concrete Contractors	2017-SalesGenie	1	2017	SalesGenie 2017				Ottawa	2413	STEVENICH	AVE		41160085		23811001	1771-05		354.9786291	82.78891051
14341	ALLAN LARCH LIMITED	Interior and Finishing Work	2001-ES; 2005-SelectPhone	1	2001-2005		280	FRONTENAC	AVE		280	FRONTENAC	ST	K1L6K9	42390209	Vanier				537.5554795	93.19350489
17197	PETRO CANADA	Gas Station	1980-M; 1990-CD; 1994-PID	1	1990-1994	CD 1990	330	MCARTHUR	AVE		330	MCARTHUR	AVE	K1L6N8	42470260	VANIER				926.1347915	121.9144486
13746	ROGER CRETE CLEANERS	Laundries and Cleaners	1961-1998-M	1	1961-1998		320	MCARTHUR	AVE	VANIER	320	MCARTHUR	AVE		42470270	VANIER				15368.02378	569.7775304
13931	C G PLUMBING & HEATING LIMITED	Mechanical Specialty Work	2001-ES; 2005-SelectPhone	1	2001-2005		360	LACASSE	AVE		360	LACASSE	AVE	K1L7A9	42400016	Vanier				716.1423461	110.1681429
14632	ECHELLE SCREEN PRINTING	Commercial Printing Industries	1956-M; 1961-M; 1966-M; 1971-M; 1976-M; 1981-M; 1982-M; 1986-M; 1990-M; 1996-CDMP; 1998-SC; 2005-SelectPhone	1	1956-2005	c. 1956-1998; c. 2005	219	JEANNE MANCE	ST		336	OLMSTEAD	ST	K1L7K3	42380064	VANIER	323114; 323115; 323116; 323119; 323120; 812921	281; 282		325.1132788	73.14669858
14641	LANGLOIS SOUND PERFORMANCE & DETAILING	Appliance, Television, Radio and Stereo Stores	2001-ES; 2005-PropertyAssessment; 2006-ES; 2012-ES	1	2001-2005	c. 2001	279	MCARTHUR	AVE	OTTAWA	279	MCARTHUR	AVE	K1L6P3	42400010	VANIER	443110			422.5317591	88.68298287
14772	FEDERAL APPLIANCES LIMITED	Major Appliance Industry (Electric and Non Electric)	1956-M; 1966-M; 1971-M; 1976-M; 1981-M; 1982-M; 1986-M; 1990-M; 1996-CDMPI	1	1956	c. 1956	248	MCARTHUR	AVE	VANIER	248	MCARTHUR	AVE	K1L6P4	42480082	VANIER	335223	332		14249.10023	603.2835768
16906	GTA'S FINEST RESTORATION OTTAWA	Administrative and support, waste management and remediation services	2016-PID	1	2016	PID2016	280	MCARTHUR	AVE	OTTAWA	280	MCARTHUR	AVE	K1L6P2	42470099	VANIER	562910			1659.770683	172.7350657
17200	GRAPH COMPUTER DESIGN & TYPESETTING	Platemaking, Typesetting and Bindery Industry	1990-M; 1996-CDMPI	1	1990-1996	c. 1990	320	MCARTHUR	AVE	OTTAWA	320	MCARTHUR	AVE	K1L5G2	42470270	VANIER	323120; 812921	282		15368.02378	569.7775304

HLUI SUMMARY REPORT
AREA FEATURES

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	SOURCE_UPDATE_SORTED	QAQC	YEAR	YEAR_1	ST_NUM	ST_NAME	ST_SUFFIX	MUNICIPALITY	ST_NUM2017	ST_NAME2017	ST_SUFFIX2017	POSTAL_CODE2017	PIN2017	MUNICIPALITY2017	NAICS	SIC	COMMENTS	Shape_Length	Shape_Area
17238	CITY OF OTTAWA	General Administrative Services	2003-PID; 2016-PID	1	2003-2016	c. 2001; c. 2003	256	MCARTHUR	AVE	OTTAWA	252	MCARTHUR	AVE	K1L6P4	42480086	VANIER	913910			8210.792103	411.8132809

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	TANK_LOCATION	TANK_CONTENT	TANK_SIZE	TANK_TYPE	TANK_STATUS	SOURCE	INSTALLED_ST_NUM	INSTALLED_ST_NAME	INSTALLED_ST_ABR	INSTALLED_ST_DIR	COMMENT	MTM_X	MTM_Y	IMAGE_MAP	IMAGE_CERTAINTY	DATE_INSTALLED	NATURE_OF_BUSINESS	TEMPREcordID	CAPACITY_UOM	MUNICIPALITY	POSTCODE
228	GARAGE	Garage	UST					FIP1948	300	MCARTHUR	RD		historical address - 300 McArthur Rd. 22/02/03 Location Updated. Moved ontop of building based on activity name, Volume2-245-4.jpg & 1958 imagery.	370856.4605	5032738.063	245.jpg	2						
229	GARAGE	Garage	UST					FIP1948	300	MCARTHUR	RD		historical address - 300 McArthur Rd. 22/02/03 Location Updated. Moved ontop of building based on activity name, Volume2-245-4.jpg & 1958 imagery.	370856.4605	5032738.063	245.jpg	2						
8895	TRUONG DINH	Gasoline Station-SS		gasoline	22700	Cancelled	Previous	GW Study 2004	330	MCARTHUR	RD	<Null>	330 MCARTHUR RD. 22/02/03 Location Updated. Moved ontop of tanks area based on 1991 imagery. Gas station removed between 1999 & 2002.	371004.8441	5032748.822		2	19830401	Retail	2118	L	VANIER	K1L 6N8
8896	TRUONG DINH	Gasoline Station-SS		gasoline	22700	Cancelled	Previous	GW Study 2004	330	MCARTHUR	RD	<Null>	330 MCARTHUR RD. 22/02/03 Location Updated. Moved ontop of tanks area based on 1991 imagery. Gas station removed between 1999 & 2002.	371004.8441	5032748.822		2	19830401	Retail	2119	L	VANIER	K1L 6N8
8897	TRUONG DINH	Gasoline Station-SS		gasoline	22700	Cancelled	Current	GW Study 2004	330	MCARTHUR	RD	<Null>	330 MCARTHUR RD. 22/02/03 Location Updated. Moved ontop of tanks area based on 1991 imagery. Gas station removed between 1999 & 2002.	371004.8441	5032748.822		2	19830401	Retail	2120	L	VANIER	K1L 6N8
8898	TRUONG DINH	Gasoline Station-SS		gasoline	22700	Cancelled	Current	GW Study 2004	330	MCARTHUR	RD	<Null>	330 MCARTHUR RD. 22/02/03 Location Updated. Moved ontop of tanks area based on 1991 imagery. Gas station removed between 1999 & 2002.	371004.8441	5032748.822		2	19830401	Retail	2121	L	VANIER	K1L 6N8
9113	CANADIAN TIRE CORP LTD.	Gasoline Station-SS		gasoline	31780	Cancelled	Current	GW Study 2004	248	MCARTHUR	AVE	<Null>	248 MCARTHUR AVE. 22/02/03 Location Updated, further update not possible. Moved ontop of building based on installed address, Volume2-244-3.jpg & 1958 imagery.	370610.2364	5032678.101		2	19830401	Retail	1960	L	VANIER	K1L 6P4
9114	CANADIAN TIRE CORP LTD.	Gasoline Station-SS		gasoline	31780	Cancelled	Current	GW Study 2004	248	MCARTHUR	AVE	<Null>	248 MCARTHUR AVE. 22/02/03 Location Updated, further update not possible. Moved ontop of building based on installed address, Volume2-244-3.jpg & 1958 imagery.	370610.2364	5032678.101		2	19830401	Retail	1961	L	VANIER	K1L 6P4
9115	CANADIAN TIRE CORP LTD.	Gasoline Station-SS		gasoline	22700	Cancelled	Current	GW Study 2004	248	MCARTHUR	AVE	<Null>	248 MCARTHUR AVE. 22/02/03 Location Updated, further update not possible. Moved ontop of building based on installed address, Volume2-244-3.jpg & 1958 imagery.	370610.2364	5032678.101		2	19830401	Retail	1962	L	VANIER	K1L 6P4
9116	CANADIAN TIRE CORP LTD.	Gasoline Station-SS		gasoline	22700	Cancelled	Current	GW Study 2004	248	MCARTHUR	AVE	<Null>	248 MCARTHUR AVE. 22/02/03 Location Updated, further update not possible. Moved ontop of building based on installed address, Volume2-244-3.jpg & 1958 imagery.	370610.2364	5032678.101		2	19830401	Retail	1963	L	VANIER	K1L 6P4
9172	CORPORATION OF THE CITY OF VANIER - RAYMOND ROY	Private Fuel Outlet		gasoline	4500	Licenced	Current	GW Study 2004	256	MCARTHUR	<Null>	<Null>	256 MCARTHUR. 22/02/03 Location Updated, further update not possible. Moved ontop of building based on installed address, Volume2-245-4.jpg & 1958 imagery.	370653.5398	5032705.74		2	19830401	Private	2264	L	VANIER	K1L 6P4
9173	CORPORATION OF THE CITY OF VANIER - RAYMOND ROY	Private Fuel Outlet		diesel	9000	Licenced	Current	GW Study 2004	256	MCARTHUR	<Null>	<Null>	256 MCARTHUR. 22/02/03 Location Updated, further update not possible. Moved ontop of building based on installed address, Volume2-245-4.jpg & 1958 imagery.	370653.5398	5032705.74		2	19830401	Private	2265	L	VANIER	K1L 6P4



PATERSON GROUP
9 AURIGA DRIVE
OTTAWA, ON
K2E 7T9
TEL: (613) 226-7381

NO.	REVISIONS	DATE	INITIAL

OTTAWA FOOTY SEVENS

PHASE I - ENVIRONMENTAL SITE ASSESSMENT UPDATE
349 OLMDSTEAD STREET

OTTAWA, **ONTARIO**

Title:

SITE PLAN

Scale: 1:1000	**Date:** 07/2026
Drawn by: YA	**Report No.:** PE7604-LET.01
Checked by: MSWB	**Dwg. No.:** PE7604-1
Approved by: AM	**Revision No.:**

11x17

p:\autocad drawings\environmental\pe7604\pe7604-1-site plan.dwg