

LOW IMPACT DEVELOPMENT (LID)
INFILTRATION GALLERY AT ROADWAY LOWPOINTS

SCALE: 1:200



LOW IMPACT DEVELOPMENT (LID)
INFILTRATION GALLERY AT FLOW–BY CATCH–BASINS

SCALE: 1:200

LOW IMPACT DEVELOPMENT (LID) INFILTRATION DATA							
INFILTRATION AREA I.D.	STRUCTURE(S) IN INFILTRATION AREA	LOCATION	STRUCTURE CONDITION	NO. OF PIPES IN INFILTRATION AREA	LENGTH OF EACH PIPE (m)	TOTAL LENGTH OF PIPE (m)	TRENCH WIDTH (m)
ROW-01	CB03, CB04	RIGHT-OF-WAY	PONDING	4	14.0	56.0	1.5
ROW-02	CB09, CB10	RIGHT-OF-WAY	PONDING	4	14.0	56.0	1.5
ROW-03	CB11, CB12	RIGHT-OF-WAY	PONDING	4	14.0	56.0	1.5
ROW-04	CB13, CB14	RIGHT-OF-WAY	PONDING	4	14.0	56.0	1.5
ROW-05	CB15, CB16, CB17	RIGHT-OF-WAY	PONDING	6	14.0	84.1	1.5
ROW-06	CB18, CB19	RIGHT-OF-WAY	PONDING	4	14.0	56.0	1.5
ROW-07	CB24, CB25	RIGHT-OF-WAY	PONDING	4	14.0	56.0	1.5
ROW-08	CB01, CB02	RIGHT-OF-WAY	FLOWBY	2	10.0	20.0	1.5
ROW-09	CB120, CB121	RIGHT-OF-WAY	FLOWBY	2	10.0	20.0	1.5
ROW-10	CB05, CB06	RIGHT-OF-WAY	FLOWBY	2	10.0	20.0	1.5
ROW-11	CB07, CB08	RIGHT-OF-WAY	FLOWBY	2	8.0	16.0	1.5
ROW-12	CB22, CB33	RIGHT-OF-WAY	FLOWBY	2	8.4	16.8	1.5
ROW-13	CB26, CB27	RIGHT-OF-WAY	FLOWBY	2	6.0	12.0	1.5
ROW-14	CB20, CB21	RIGHT-OF-WAY	FLOWBY	2	6.0	12.0	1.5
ROW-15	CB28, CB29	RIGHT-OF-WAY	FLOWBY	2	6.1	12.1	1.5
ROW-16	CB32, CB123	RIGHT-OF-WAY	FLOWBY	2	6.2	12.3	1.5
ROW-17	CB30, CB31	RIGHT-OF-WAY	FLOWBY	2	6.0	12.0	1.5
RY-01	CB78	REARYARD	-	1	107.4	107.4	0.85
RY-02	CB79	REARYARD	-	1	42.2	42.2	0.85
RY-03	CB51	REARYARD	-	1	73.4	73.4	0.85
RY-04	CB35	REARYARD	-	1	55.6	55.6	0.85
RY-05	CB36	REARYARD	-	1	49.6	49.6	0.85
RY-06	CB43	REARYARD	-	1	45.9	45.9	0.85
RY-07	CB83	REARYARD	-	1	112.8	112.8	0.85
RY-08	CB87	REARYARD	-	1	142.2	142.2	0.85
RY-09	CB57	REARYARD	-	1	100.5	100.5	0.85
RY-10	CB60	REARYARD	-	1	52.5	52.5	0.85
RY-11	CB58	REARYARD	-	1	52.7	52.7	0.85
RY-12	CB93	REARYARD	-	1	89.1	89.1	0.85
RY-13	CB100	REARYARD	-	1	175.2	175.2	0.85



SECTION OF TYPICAL LID INFILTRATION TRENCH

SCALE: 1:25



SECTION OF CATCH–BASIN WITH LID INFILTRATION TRENCH CONNECTION

SCALE: 1:25



SHOP DRAWINGS TO BE PROVIDED

PERFORATED TRASH SCREEN CAP

SCALE: N.T.S.

CAUTION

THE POSITION OF ALL POLE LINES, CONDUITS, WATERMAINS, SEWERS AND OTHER UNDERGROUND AND OVERGROUND UTILITIES AND STRUCTURES IS NOT NECESSARILY SHOWN ON THE CONTRACT DRAWINGS, AND WHERE SHOWN, THE ACCURACY OF THE POSITION OF SUCH UTILITIES AND STRUCTURES IS NOT GUARANTEED. BEFORE STARTING WORK, DETERMINE THE EXACT LOCATION OF ALL SUCH UTILITIES AND STRUCTURES AND ASSUME ALL LIABILITY FOR DAMAGE TO THEM.

JOB BENCH MARK JBM

TOP OF HEAD OF MAGNETIC NAIL SET IN SIDE OF CONCRETE SIGN BASE 0.2± ABOVE GRADE ELEVATION=120.77
NORTHING=5014575.29 EASTING=349007.23

TOPOGRAPHIC INFORMATION

PART OF LOT 12, CONCESSION 12, GEOGRAPHIC TOWNSHIP OF GOULBOURN, CITY OF OTTAWA.
TOPOGRAPHIC INFORMATION PROVIDED BY FAIRHALL MOFFATT & WOODLAND LIMITED O.L.S (TP388Z) SURVEY DATED JANUARY 14, 2020.
SITE GRID SYSTEM MTM NAD 83, ZONE 9,

REV	REVISION DESCRIPTION	DATE	BY	APPD

REV	REVISION DESCRIPTION	DATE	BY	APPD
1	ISSUED FOR APPROVAL	05/12/22	SAB	BMT

SCALE

NORTH

DESIGNED BY: LICENSED PROFESSIONAL ENGINEER J.L. FITZPATRICK 2022-05-12 PROVINCE OF ONTARIO

REVIEWED BY: LICENSED PROFESSIONAL ENGINEER B. M. THOMAS 2022-05-12 PROVINCE OF ONTARIO

OWNER: LATITUDE HOMES
1202 CARP ROAD
STITTSVILLE, ON. K2S 1B9

exp Services Inc.
t: +1.613.688.1899 | f: +1.613.225.7330
2650 Queensview Drive, Unit 100
Ottawa, ON K2B 8H6
Canada
www.exp.com
• BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

BASEPLAN	SK
DESIGN	JLF
CHECKED	BMT
CAD	SK
PROJECT MANAGER	JLF
APPROVED	BMT

PROJECT: HAZELDEAN HORIZONS
6171 HAZELDEAN ROAD
OTTAWA, ONTARIO.

TITLE: DETAIL SHEET 3
LOW IMPACT DEVELOPMENT DETAILS

PROJECT No.	258780
SURVEY	Z38800–FMW
DATE	24/07/20
DRAWING No.	C702