FINAL REPORT

Phase One Environmental Site Assessment

4639 Bank Street, Ottawa, Ontario

Submitted to:

Glenview Properties Inc.
190 O'Connor Street, 11th Floor
Ottawa, Ontario
K2P 1T6

Submitted by:

Golder Associates Ltd.
1931 Robertson Road Ottawa, Ontario, K2H 5B7 Canada

+1 613 592 9600

19128449

October 2019



Distribution List

1 copy	Glenview Properties Inc.
1 e-copy	Glenview Properties Inc.
1 e-copy	Golder Associates Ltd.

Executive Summary

The Executive Summary highlights key points from the report only; for complete information and findings, as well as the limitations, the reader should examine the complete report.

Golder Associates Ltd. (Golder) was retained by Glenview Properties Inc. (Glenview) to complete a Phase One Environmental Site Assessment (Phase One ESA) of the property located at 4639 Bank Street in Ottawa, Ontario (herein after referred to as the "Site" or "Phase One Property") as shown on Figure 1. For reporting purposes, Site north has been defined such that Bank Street has a north-south axis. At the time of the Site visit, conducted on August 23, 2019, the Site consisted of a 1.23-hectare parcel of vacant, undeveloped land that was overgrown with vegetation.

It is understood that the Phase One Property is proposed to be developed with residential buildings, there will be no change in the land use from less sensitive to more sensitive given that the Site has never been developed. As such, there is no mandatory requirement for an RSC to be filed for the Site.

The Phase One ESA was completed in accordance with Ontario Regulation (O. Reg. 153/04), as amended, and included a review of available current and historical information regarding the Site and surrounding properties, a Site reconnaissance, interviews, evaluation of readily available information, and reporting, subject to the limitations outlined in Section 9.0 of this report.

Given that no APECs were identified on the Site during the Phase One ESA, a Phase Two ESA is not recommended to be carried out at the Site at this time.

This Phase One ESA has not been completed to support a Record of Site Condition; however, should a Record of Site Condition need to be filed for the Site, the on-Site PCA associated with fill material on the Site will be considered to be represent APECs on the Phase One Property and a Phase Two ESA will be required to support to the submission of the Record of Site Condition.

Based on the information obtained as part of this Phase One ESA, none of the PCAs identified on the Site or off-Site were considered to represent an APEC on the Phase One Property. This Phase One ESA has not been completed to support a Record of Site Condition; however, should a Record of Site Condition need to be filed for the Site, the on-Site PCA (presence of fill material on the Site) will be considered to be represent an APEC on the Phase One Property and a Phase Two ESA will be required to support to the submission of the Record of Site Condition, should one be requested.

There were no material deviations to the Phase One ESA requirements set out in O.Reg. 153/04 that would cause uncertainty or absence of information that would affect the validity of the Phase One Conceptual Site Model or the findings of this Phase One ESA.

Table of Contents

EXECUTIVE SUMMARY ..... **i**

1.0 INTRODUCTION **1**

1.1 Phase One Property Information 1

2.0 SCOPE OF INVESTIGATION **1**

3.0 RECORDS REVIEW **2**

3.1 General 2

3.1.1 Phase One Study Area Determination 2

3.1.2 First Developed Use Determination 2

3.1.3 Fire Insurance Plans 2

3.1.4 Chain of Title 2

3.1.5 City Directories 2

3.1.6 Environmental Reports 2

3.2 Environmental Source Information 2

3.2.1 ERIS Report 2

3.2.2 Ministry of the Environment, Conservation and Parks 6

3.2.3 City of Ottawa 6

3.2.4 Ministry of Natural Resources and Forestry (MNRF) 6

3.2.5 Technical Standards and Safety Authority, Fuel Safety Division Records 7

3.3 Physical Setting Sources 7

3.3.1 Aerial Photographs 7

3.3.2 Topography, Hydrology and Geology 8

3.3.3 Fill Materials 9

3.3.4 Water Bodies and Areas of Natural Significance 9

3.3.5 Well Records 9

3.4 Site Operating Records 10

4.0 INTERVIEWS **10**

5.0 SITE RECONNAISSANCE 10

5.1 General Requirements 10

5.2 Specific Observations at Phase One Property 10

5.2.1 Enhanced Investigation Property 13

5.3 Surrounding Land Use 13

5.4 Written Description of Investigation 14

6.0 REVIEW AND EVALUATION OF INFORMATION 14

6.1 Current and Past Uses of the Site 14

6.2 Potentially Contaminating Activity 15

6.3 Areas of Potential Environmental Concern 17

6.4 Conceptual Site Model 17

6.4.1 Uncertainty and Absence of Information 18

7.0 CONCLUSIONS 18

7.1 Record of Site Condition Based on Phase One Environmental Site Assessment Alone 19

8.0 REFERENCES 19

9.0 LIMITATIONS AND USE OF REPORT 20

10.0 STATEMENT OF COMPLETION 20

11.0 CLOSURE 21

FIGURES

Figure 1: Key Plan

Figure 2: Site Plan

Figure 3: Topographic Map and Areas of Natural Significance

Figure 4: Surficial Geology

Figure 5: Bedrock Geology

Figure 6: Drift Thickness

Figure 7: Soil Survey Complex (Ontario Soils)

Figure 8: Physiography Map

APPENDICES

APPENDIX A
Regulatory Responses

APPENDIX B
ERIS Report, City Directories

APPENDIX C
Site Photographs

APPENDIX D
Aerial Photographs

1.0 INTRODUCTION

1.1 Phase One Property Information

Golder Associates Ltd. (Golder) was retained by Glenview Properties Inc. (Glenview) to conduct a Phase One Environmental Site Assessment (Phase One ESA) of the following properties:

Municipal Address	4639 Bank Street, Ottawa, Ontario
Property Identification Number	043450350
Legal Description	Parts 3 to 5, Lot 17, RP 4R22720, Concession 5, Gloucester

The Site location is provided on Figure 1. A Site plan is provided on Figure 2. For reporting purposes, Site north has been defined such that Bank Street has an east-west axis.

The contact information for the Site is:

	Company	Address	Contact Information
Vendor	Mr. and Mrs. Halpenny	N/A	Peter.Halpenny@outlook.com
Purchases	Glenview Properties Inc.	190 O'Connor Street, 11th Floor Ottawa, Ontario K2P 1T6	Jacob Shabinksy Office: 613-748-3700 ext. 227 Email: jshabinsky@glenview.ca

2.0 SCOPE OF INVESTIGATION

A Phase One ESA is a preliminary qualitative assessment of the environmental condition of a property, based on a review of current activities and historical information for the Site and a review of relevant and readily available environmental information for the surrounding properties located within a 250 metre (m) radius of the boundary of the Site (collectively referred to as the “Phase One Study Area”). The boundary of the Phase One Study Area is presented in Figure 2.

The objectives of the Phase One ESA are to:

1) Develop a preliminary determination of the likelihood that one or more contaminants have affected any land or water on, in, or under the Site.

2) Determine the need for a Phase Two Environment Site Assessment (ESA).

3) Provide a basis for carrying out a Phase Two ESA.

4) Provide adequate preliminary information about environmental conditions in the land or water on, in, or under the Site for the conduct of a risk assessment following completion of a Phase Two ESA.

5) Identify and report on evidence of actual and/or potential contamination on the Site from current and historical activities at the Site or from adjacent properties.

3.0 RECORDS REVIEW

3.1 General

3.1.1 Phase One Study Area Determination

For the purpose of this Phase One ESA, the Phase One Study Area is the area within a 250 m radius of the boundary of the Site. Based on Golder's review of the historical and current information compiled as part of this Phase One ESA for the area surrounding the Site and observations of neighbouring properties made during the Site visit, it was concluded that an assessment of information pertaining to properties within 250 m of the boundary of the Site was sufficient to achieve the objectives of the Phase One ESA.

3.1.2 First Developed Use Determination

Based on the information obtained in the documentation review (discussed in the next sections of this report) and information provided by the Site Representative, the Site has never been developed and has consisted of vacant land since at least 1945.

3.1.3 Fire Insurance Plans

Golder conducted a search of available Fire Insurance Plans (FIPs) for the Phase One Property and the surrounding properties within the Phase One Study Area. FIPs were not available for the Phase One Property or the Phase One Study Area.

3.1.4 Chain of Title

From Golder's review of aerial photography and other information, the Phase One Property has been vacant has never been developed and has been undeveloped, vacant land since at least 1945. Chain of Title information was not ordered as it was deemed that the other information from the records review would satisfy the objectives of the records search and that the information to be provided in a Chain of Title would not contribute additional environmental information relevant to the Phase One ESA.

3.1.5 City Directories

A significant amount of information for the Site and surrounding properties was obtained from the ERIS report, City of Ottawa Historical Land Use Inventory (HLUI) and aerial photographs discussed in Section 3.2.1, 3.2.3 and 3.3.1, respectively. As such, city directories for all the properties within the Phase One Study Area were no reviewed as they would not likely provide any further information.

3.1.6 Environmental Reports

There were no previous environmental investigation reports associated with the Site or surrounding properties within the Phase One Study Area available to Golder for review.

3.2 Environmental Source Information

3.2.1 ERIS Report

Golder contracted ERIS to conduct a search of environmental sources, including federal, provincial, and private sector databases, for information on the Phase One Property and Study Area. The ERIS report is provided in Appendix B.

The databases searched included the following:

Federal	Provincial	Private
■ Contaminated Sites on Federal Land ■ Dry Cleaning Facilities ■ Environmental Effects Monitoring ■ Environmental Issues Information System ■ Federal Convictions ■ Fisheries & Oceans Fuel Storage Tanks ■ Greenhouse Gas Emissions from Large Facilities ■ Indian & Northern Affairs Fuel Tanks ■ National Analysis of Trends in Emergencies System (NATES) ■ National Defence & Canadian Forces Fuel Storage Tanks ■ National Defence & Canadian Forces Spills ■ National Defence & Canadian Forces Waste Disposal Sites ■ National Energy Board Pipeline Incidents ■ National Energy Board Wells ■ National Environmental Emergencies System (NEES) ■ National PCB Inventory ■ National Pollutant Release Inventory ■ Parks Canada Fuel Storage Tanks ■ Transport Canada Fuel Storage Tanks	■ Abandoned Aggregate Inventory ■ Abandoned Inventory ■ Aggregate Mine Information System ■ Borehole ■ Certificates of Approval ■ Certificates of Property Use ■ Commercial Fuel Oil Tanks ■ Compliance and Convictions ■ Drill Hole Database ■ Environmental Activity and Sector Registry ■ Environmental Compliance Approval ■ Emergency Management Historical Event ■ Environmental Registry ■ Fuel Storage Tank ■ Fuel Storage Tank – Historic ■ Inventory of Coal Gasification Plants and Tar Sites ■ Inventory of PCB Storage Sites ■ Landfill Inventory Management Ontario ■ List of TSSA Expired Facilities ■ Environmental Penalty Annual Report ■ Mineral Occurrences ■ Non-Compliance Reports ■ Ontario Oil and Gas Wells ■ Ontario Regulation 347 Waste Generators Summary ■ Ontario Regulation 347 Waste Receivers Summary ■ Ontario Spills ■ Orders ■ Permit to Take Water ■ Pesticide Register ■ Private and Retail Fuel Storage Tanks ■ Record of Site Condition ■ TSSA Historic Incidents ■ TSSA Incidents	■ Anderson's Storage Tanks ■ Anderson's Waste Disposal Sites ■ Automobile Wrecking & Supplies ■ Canadian Mine Locations ■ Canadian Pulp and Paper ■ Chemical Register ■ Compressed Natural Gas Stations ■ ERIS Historical Searches ■ Oil and Gas Wells ■ Retail Fuel Storage Tanks ■ Scott's Manufacturing Directory

Federal	Provincial	Private
	■ TSSA Pipeline Incidents ■ TSSA Variances for Abandonment of Underground Storage Tanks ■ Waste Disposal Sites - MOECC 1991 Historical Approval Inventory ■ Waste Disposal Sites - MOECC CA Inventory ■ Wastewater Discharger Registration Database ■ Water Well Information System	

The complete ERIS report, including a brief description of each of the databases searched for the Phase One ESA, is included in Appendix B.

The following is a summary of the findings as identified within the ERIS report for the Site and for the surrounding properties within the Phase One Study Area:

On-Site

The ERIS Report had a record of one borehole listing and three water wells on the Phase One Property. The borehole was completed in March 1966 to a depth of 13.1 metres below ground surface (mbgs). The subsurface conditions encountered in the borehole was clay over limestone bedrock which was encountered at a depth of 1.5 mbgs. The water wells were completed in March 1966, September 1963 and August 1962 for domestic purposes and were completed to depths ranging between 13.1 and 48.5 mbgs. Although these boreholes and wells were indicated to be on the Site; the description provided for their location is on Lot 17, Concession 5 which includes a much larger portion of land than the Site and the Site has never been developed. Therefore, it is likely that they were completed off-Site.

Surrounding Properties within 250 metres of the Site

Noteworthy records for the Phase One Study Area (excluding the Phase One Property) included the following:

- The List of TSSA Expired Facilities (EXP), Fuel Storage Tank (FST), Fuel Storage Tank – Historic (FSTH), Private and Retail Fuel Storage Tanks (PRT) and/or Retail Storage Tanks (RST) database have records of retail fuel outlets with associated fuel underground storage tanks (USTs) were identified at 4726 Bank Street (approximately 90 m southwest of the Site), at 4727 Bank Street (approximately 110 m south of the Site) and at 4728 Bank Street (155 m southwest of the Site). However, based on the review of the aerial photographs and the Site visit, it is likely that the record for the retail fuel outlet at 4728 Bank Street is actually for that at the property 4726 Bank Street, 90 m to the south. The retail fuel outlet at 4726 was identified as waste generating site in the Ontario Regulations 347 Waste Generators Summary (GEN) database that generated waste oils and lubricants, oil skimmings and sludges, light fuels, aliphatic solvents and residues, waste crankcase oils.

- The Ontario Regulations 347 Waste Generators Summary (GEN) database identified several other generation Site listings within the Phase One Study Area. The only noteworthy waste generators other than the retail fuel outlet at 4726 Bank Street was a cemetery located at 4660 Bank Street (approximately 40 m west of the Site) which generated waste oils and lubricants and a hydro facility located at 4565 Bank Street (175 m north of the Site) which generated aliphatic solvents, waste oils and lubricants, acid waste, alkaline wastes, light fuels, petroleum distillates, other specified inorganics, waste compressed gases, paint/pigment/coating residues, polychlorinated biphenyls (PCBs) and photoprocessing waste. The remaining waste generator records and waste classes are included in the ERIS report in Appendix B.
- The hydro facility at 4565 Bank Street was listed in the National PCB Inventory (NPCB) and Inventory or PCB Storage Sites (OPCB) databases as a PCB storage site with transformer and drums of various materials with high levels of PCBs.
- A nursery located approximately 85 m northwest of the Site at 4590 Bank Street was listed as a vendor or pesticides in the Pesticide Register (PES) database.
- The Ontario Spills (SPL) database has records of five spills occurring within the Phase One Study Area. The details of the spills are provided in the table below.

Spill Occurrences within the Phase One Study Area

Company	Location	Year of Occurrence	Description
Blue Wave Energy Limited Partnership	4695 Bank Street (approximately 25 m south the Site)	2009	454 L of furnace oil spilled to a concrete basement floor from a fuel oil AST. The record indicated that environmental impact due to the spill was not anticipated.
W.O. Stinson & Sons Ltd.	4726 Bank Street (approximately 90 m southwest of the Site)	2003	25 L of fuel oil spilled to the ground from a tanker truck. The record indicated that environmental impact was possible.
Private Residence	4727 Bank Street (approximately 110 m south the Site)	1994	Unknown amount of furnace oil spilled to the ground from a fuel UST. The record indicated that the receiving medium was land and environmental impacted due to the spill was confirmed.
W.O. Stinson & Sons Ltd	4727 Bank Street (approximately 110 m south the Site)	2016	75 L of diesel spilled to the ground.
Hydro Ottawa Limited	4565 Bank Street (approximately 175 m north of the Site)	September 2013	Raw sewage spill to a drainage pit.

- The TSSA Incidents (INC) database has records of TSSA incidents within the Phase One Study Area. Both records were for fuel oil spills that occurred at a private residence at 4695 Bank Street, approximately 25 m south of the Site. One spill occurred in 2009 and the other occurred in 2011. Although no other information was provided, it is likely that the 2009 spill was the 454 L fuel oil spill to basement that was noted in the Ontario Spills database mentioned above and that the 2011 fuel oil spill was also from a fuel AST in the basement.

Based on the review of the ERIS report, the current and/or former presence of retail fuel outlets with associated fuel USTs, the Hydro Ottawa facility with PCB storage, a nursery and a cemetery located within the Phase One Study Area are off-Site PCAs. There have been a couple reported fuel oil spills at 4695 Bank Street; however, given that these spills were to the concrete basement floor from a fuel AST and that they occurred hydraulically down-gradient with respect to the Site, they are not considered to be issues of concern for the Site. The remainder of the spills that were reported to have occurred within the Phase One Study Area were either not significant in size, were located at least 100 m from the Site, located hydraulically cross- or down-gradient with respect to the Site or were spills of substances that are not considered to have the potential to impact the soil and/or groundwater and as such they are not considered to be issues of potential environmental concern for the Site. The ERIS report also identified waste generating sites within the Phase One Study Area. The presence of waste generators alone is not considered an issue of concern on its own as there is no information as to the handling practices at the identified sites; however, it is an indication of the presence of chemical storage.

3.2.2 Ministry of the Environment, Conservation and Parks

A Freedom of Information (FOI) Request was sent to the Ontario Ministry of Environment, Conservation and Parks (MECP) asking the MECP to report any environmental information relating to the Site.

A formal response from the MECP was received by Golder on August 21, 2019. The review of the MECP response indicated that no Active Orders, Certificate of Approvals, or Environmental Compliance Approvals have been issued for the Site.

3.2.3 City of Ottawa

Golder completed a review of the City of Ottawa Historical Land Use Inventory (HLUI) for the Phase One Property and Phase One Study Area. The following summarizes the noteworthy findings of the City of Ottawa HLUI review:

- A nursery was identified approximately 85 m northwest of the Site at 4590 Bank Street.
- Gloucester Hydro was located at 4565 Bank Street, approximately 175 m north of the Site.
- A cemetery was identified at 4660 Bank Street, approximately 40 m west of the Site.
- Retail fuel outlets listed at 4726 Bank Street (approximately 90 m southwest of the Site) and at 4727 Bank Street (approximately 110 m south of the Site).
- An asphalting company was identified at 4603 Bank Street which is located approximately 25 m north of the Site. This property was also identified as an automotive garage; however, based on the other records review and Site visit, the automotive garage is actually located at 4605 Bank Street, approximately 40 m northeast of the Site.

Based on the review of the City of Ottawa HLUI, the former presence of retail fuel outlets, dry cleaning facility, automotive garages, a machine shop and commercial printing shop located within the Phase One Study Area are off-Site PCAs.

3.2.4 Ministry of Natural Resources and Forestry (MNRF)

Based on available resources and information provided by the MNRF Ministry of Natural Resources and Forestry (MNRF), there are no Natural Heritage Features (e.g., Provincially Significant Wetlands, Areas of Natural and Scientific Interest, etc.) located on the Site; however, there is a potential for the several Species at Risk (SAR) to be present on the Site or in proximity to it. It is noted; however, that the potential for SAR presence is provided by geographic townships (Gloucester Township for this Site) which is a much larger area that the Phase One Study Area.

3.2.5 Technical Standards and Safety Authority, Fuel Safety Division Records

The Technical Standards and Safety Authority (TSSA) maintains records related to registered underground storage tanks ("USTs") for petroleum-related products. The TSSA was contacted to establish the status of the Site and to identify outstanding instructions, incident reports, fuel oil spills or contamination records.

The TSSA replied on August 21, 2019 and indicated that the TSSA had records of a retail fuel outlet with four active fuel tank and a former propane refill centre with associated propane tank at 4727 Bank Street and an active propane filling centre with associated propane tank at 4726 Bank Street.

3.3 Physical Setting Sources

3.3.1 Aerial Photographs

Aerial photographs of the Site and neighbouring properties were obtained from Golder's in-house photo records and were dated 1945, 1956 and 1983. In addition, the aerial photographs for 1965, 1976, 1991, 1999, 2005, 2011, 2014 and 2017 from the City of Ottawa geo-map (http://maps.ottawa.ca/geoOttawa/) were reviewed on-line. Golder selected aerial photographs based on availability and date intervals to help develop an understanding of the history of the development of the Phase One Property and Phase One Study Area. The information obtained from the aerial photographs was limited by the quality and scale of the available aerial photographs. The earliest aerial photograph available was from 1945.

Based on the aerial photographs, the Phase One Property has been undeveloped vacant land since at least 1945. A small creek intersected the northeast corner of the Site from sometime between 1856 and 1965 until it was filled in sometime between 2011 and 2014. Over the years there appears to have been a few advertisement signs along the western portion of the Site.

The surrounding properties within the Phase One Study Area were developed with a few residential properties since prior to 1945 but primarily consisted of vacant land until commercial and residential development began in the 1970's and 1980's. The commercial development was primarily to the north and south of the Site and included a retail fuel outlet at 4726 Bank Street between 1983 and 1991, a retail fuel outlet at 4727 Bank Street between 1991 and 1999, a hydro substation at 4601 Bank Street since sometime between 2011 and 2014, and a nursery with multiple greenhouses at 4590 Bank Street between 1983 and 1991. Since the 1980's, several vehicles, machines and equipment appear to have been present to the north and northeast of the Site at 4603 and 4605 Bank Street which, based on other records reviews and the Site visit, have been a former asphalting company and an automotive garage which remains present. A tar or asphalt AST that was observed approximately 40 m northeast of the Site on the corner of the former asphalt company property has been present since sometime between 1999 and 2002. It is noted that the AST and most of the structures that have been located on the former asphalting company appear to have been to the northeast of the Site, upgradient of the adjacent property east of the Site.

Several residential houses were constructed to the east of the Site between 2011 and 2014.

The presence of fill material on the Site used to fill in the creek is considered to be an on-site PCA and the former presence of the retail fuel outlets, hydro yard, garage, asphalting company and nursery located within the Phase One Study Area are off-Site PCAs.

3.3.2 Topography, Hydrology and Geology

The following records were reviewed to identify topographic, geologic and hydrogeological conditions at the Site. A topographic map (Ontario Base Map) showing the Site and the Phase One Study Area and the location of any water bodies is provided in Figure 3. Additional information on Site features, as observed at the time of the Site visit, is provided in Section 6.

Topic	Conditions	Comment / Source
Topography of Site and Surrounding Area	The topography of the Site and surrounding area is uneven with an overall slope to the south.	Site and surrounding area observations and Figure 3 – Topographic Map and Areas of Natural Significance
Overburden Soils	Geological mapping indicates that the overburden soils at the Site consist of till, plain with local relief <5 m. However, based on the geotechnical test pit investigation that was completed for the Site in September 2019 (reported under separate cover), the overburden soils at the Site generally consisted of topsoil over fill material below which was native silt over silty sand glacial till. The fill material consisted of silty clay, clayey silt, silt and silty sand.	Bélanger, J. R. 2008 Urban Geology of the National Capital Area, Geological Survey of Canada, Open File 5311, 1 DVD. Current Geotechnical Investigation
Type of Bedrock	Lindsay Formation (limestone, nodular to black laminated).	Armstrong, D.K. and Dodge, J.E.P. 2007. Paleozoic Geology of Southern Ontario; Ontario Geological Survey, Miscellaneous Release – Data 219
Depth to Bedrock	The geological mapping indicates that the depth to bedrock is expected to be at between 2 and 3 mbgs on the northern portion of the Site and between 3 and 5 mbgs on the central and southern portions of the Site.	2010 Bélanger, J. R., Urban Geology of the National Capital Area, Geological Survey of Canada, Open File D3256, 2001
Inferred Near Surface Groundwater Flow	Local groundwater is anticipated to flow south towards Findlay Creek.	Site and surrounding area observations, Figure 1 – Key Plan and Figure 3 – Topographic Map and Areas of Natural Significance
Site Grade Relative to the Adjoining Properties	The Site is below the grade of the adjacent properties north of the Site, above the grade of the adjacent properties south of the Site at generally at grade with the adjacent properties west and east of the Site.	Site and surrounding area observations and Figure 3 – Topographic Map and Areas of Natural Significance
Depth to Groundwater	Not identified.	N/A

It should be noted that local groundwater flow may be influenced by underground utilities (i.e., service trenches) and building structures. For example, the gravel pack used around utilities, such as a water line, can act as interceptors and redirect groundwater flow along the direction of the pipe. If a more accurate description of geology, groundwater flow and groundwater quality is required, a subsurface investigation would be necessary.

3.3.3 Fill Materials

Topic	Conditions	Comment / Source
Fill Materials	No fill materials were observed or reported the Site at the time of the Site visit. However, fill was encountered in the six test pits completed at part of the current geotechnical investigation at this Site. The fill consisted of silty clay, clayey silt, silt and silty sand which extended to depths between 0.75 and 1.90 mbgs. No evidence of contamination (staining, odours, debris) was observed in the fill with the exception of a piece of concrete which was found in the fill in the test pit on the southwest corner of the Site. It is also noted that based on the review of the aerial photographs, fill material has been placed on the Site to fill in the former creek that intersected the northeast corner of the Site.	Site observations. Aerial Photographs and Current Geotechnical Investigation

3.3.4 Water Bodies and Areas of Natural Significance

Topic	Conditions	Comment / Source
Nearest Open Water Body	The nearest permanent watercourse is Findlay Creek which is located approximately 1,050 m south of the Site.	Site observations and Figure 1– Key Plan
Areas of Natural Significance	No areas of natural and scientific interest (ANSI) are known to be located on the Site or on the Phase One Study Area. Based on available information, the Site is not considered to be an environmentally sensitive area. However, Species at Risk have been identified by the MNRF to be potentially present on the Site or on the nearby lands;	Figure 3 (Topographic Map and Areas of Natural Significance)

3.3.5 Well Records

Topic	Conditions	Comment / Source
Water Wells on Site (location, stratigraphy of the overburden, from ground surface to bedrock, depth to bedrock, depth to water table, drilling date, use)	The ERIS report indicated that two water wells were constructed on the Site for domestic purposes. However, based on the description of their location which included a larger portion of land than the Site, that the Site has never been developed and there is no other evidence of wells on the Site; it is likely that they were completed off-Site.	ERIS Report and Site Observations
Water Wells on the Neighbouring Properties (location, stratigraphy of the overburden, from ground surface to bedrock, depth to bedrock, depth to water table, drilling rate, use)	Based on the ERIS report, there are 18 water wells within the Phase One Study Area. The wells were completed between July 1953 and October 2015 to depths ranging between 3.5 and 121.9 mbgs. The static water levels were not provided. Additional information regarding the water wells is included in the ERIS report in Appendix B.	ERIS Report

3.4 Site Operating Records

At the time of the Site visit, the Phase One Property was an undeveloped property. No operations were being conducted at the Site and therefore no Site operating records were available for review

4.0 INTERVIEWS

At the time of the Site visit, Golder conducted an interview with Peter Halpenny (hereinafter referred to as the "Site Representative") to discuss information about the historical and current activities carried out on the Site. Pursuant to the requirements O.Reg. 153/04, the Site Representative was interviewed as the "current owner" with knowledge of current Site operations.

Relevant information obtained during the interview and Site visit is provided in Section 5.0.

5.0 SITE RECONNAISSANCE

5.1 General Requirements

Alyssa Whiteduck of Golder visited the Site on August 23, 2019. The Site visit consisted of a walk-around the Site along with a cursory inspection of surrounding properties from the Site and publicly accessible areas. The Site was undeveloped vegetated land.

Photographs of relevant features noted during the Site visit are provided in Appendix C.

5.2 Specific Observations at Phase One Property

The specific observations made during the Site visit are presented in the following sections.

Topic	Observations	Source
Structures **Number and Age of Buildings on the Site**	No buildings or structures were present on the Site.	Site observations and Site Representative
General Descriptions of Each Building (including improvements)	Not applicable.	Site observations and Site Representative
Building Areas	Not applicable.	Site observations
Number of Floors (include all levels, whether above or below ground)	Not applicable.	Site observations
Number, Age, and Depth of Levels Below Ground Level	Not applicable.	Site observations

Topic	Observations	Source
Number and Details of all Aboveground Storage Tanks ("ASTs")	No evidence (fill/vent pipes extending through walls or slabs/ground surface, no staining or any obvious odours) was observed during the Site visit to indicate the current or former presence of fuel or chemical ASTs on the Site and the Site Representative indicated that no fuel storage tanks have been present on the Site. There was also evidence at some of the adjacent buildings of piping associated with former or existing fuel oil storage tanks, most likely ASTs.	Site observations and Site Representative
Number and Details of all Underground Storage Tanks ("USTs")	No evidence (fill/vent pipes extending through walls or slabs/ground surface, no staining or any obvious odours) was observed during the Site visit to indicate the current or former presence of fuel or chemical USTs on the Site.	Site observations and Site Representative
Asbestos-Containing Materials (ACMs)	No evidence was observed during the Site visit to indicate the presence of ACMs.	Site observations
Lead-Based Paints (LBPs)	No evidence was observed during the Site visit to indicate the presence of LBPs.	Site observations
Polychlorinated Biphenyls (PCB) Containing Materials and Equipment	No evidence was observed during the Site visit to indicate the current or former presence of PCB-containing material or equipment. However, pole-mounted transformers were noted adjacent to the roads within the Phase One Study Area including one pole-mounted transformer located along Bank Street neat the western Site boundary. No evidence of spills of leaks was noted in the area of the transformers at the time of the Site visit. No labels indicating whether the transformers are PCB-containing or not were noted on any of the transformers.	Site observations
Underground Utilities **Potable and Non-Potable Water Sources**	The Site is not connected to the municipal water supply. However, the adjacent developed lands are connected to the municipal water supply. There were no potable water sources identified at the Site at the time of the Site visit.	Site observations
Utility Lines Present (i.e. Electrical, Natural Gas, other)	Overhead electrical lines were along Bank Street near the western Site boundary.	Site observations and Site Representative
Sanitary/Process Wastewater Receptor	No sanitary or process wastewater is generated on-Site.	Site observations
Sanitary Sewer Connection	The Site is not connected to the municipal sanitary sewer. However, there is sanitary sewer service in the adjacent roadways.	Site observations
Septic Systems	None identified.	Site observations and Site Representative

Topic	Observations	Source
Storm Water Flow	Storm water run-off is through natural soil infiltration.	Site observations
Storm Sewer Connection	The Site is not connected to the municipal storm sewer.	Site observations
Interior of Structures **Entry and Exit Points for Site Buildings**	No buildings or structures were present on the Site.	Site observations and Site Representative
Existing and Former Heating System(s) (include fuel type / source)	As no buildings or structures were present on the Site, there were no existing heating systems observed or reported.	Site observations and Site Representative
Existing and Former Cooling System(s) (include fuel type / source)	As no buildings or structures were present on the Site, there were no existing cooling systems observed or reported.	Site observations
Drains, Pits, and Sumps (include current use, if any, and former use)	None identified.	Site observations
Unidentified Substances	None identified.	Site observations
Floor Stains or Corrosion Located near a Potential Discharge Location	None identified.	Site observations
Miscellaneous Exterior **Location of any Current and Former Wells**	None identified.	Site observations and Site Representative
Ground Cover (i.e., grass, gravel, soil, or pavement, etc.)	The Site was overgrown with vegetation. A few trees were present on the Site.	Site observations and Site Representative
Current or Former Railway Lines or Spurs	None observed or reported.	Site observations.
Presence of Stained Soil, Vegetation, or Pavement	None identified.	Site observations

Topic	Observations	Source
Presence of Stressed Vegetation	None identified.	Site observations
Areas Where Fill and/or Debris Materials Appear to Have Been Placed	No fill materials were observed or reported the Site during the Site visit. However, silty clay and sandy silt fill material was found across the Site during the current geotechnical test pit investigation. The fill extended to depths between 0.75 and 1.90 mbgs. No evidence of contamination (staining, odours, debris) was observed in the fill with the exception of one piece of concrete which was present in the fill in the test pit on the southwest corner of the Site.	Site observations, Site Representative and Current Geotechnical Investigation
Potentially Contaminating Activity	None identified.	Site observations and Site Representative

5.2.1 Enhanced Investigation Property

The Site is vacant parcel of land that has never been developed and has not been used as an automotive garage, a bulk liquid dispensing facility or a dry-cleaning facility. As such, the Site is not considered to be an enhanced investigation property as defined by O. Reg. 153/04.

5.3 Surrounding Land Use

During the Site visit, a visual reconnaissance of the outdoor operations in the Phase One Study Area was carried out from the Site and publicly accessible areas.

The surrounding properties include residential, commercial and community land uses, as illustrated on Figure 2.

North: Rotary Way followed by commercial development including a used car dealership, a hydro station, an automotive garage, a nursery with a few greenhouses and a retail store. The nursery was located approximately 85 m northwest of the Site at 4590 Bank Street and the hydro station was located approximately 85 m northeast of the Site at 4564 and 4601 Bank Street. The automotive garage was located approximately 40 m northeast of the Site at 4605 Bank Street and included an old fuel AST. The fuel AST was located approximately 60 m northeast of the Site and appeared to be out of service and for former vehicle fuelling activities. In addition, a there appeared to be large black tar or asphalt AST and a trailer with pails of tar or asphalt approximately 40 m northeast of the Site on the corner of the former asphalting company property (4603 Bank Street).

East: A hospice followed by residential development.

South: A mix of residential houses and a few commercial properties including two retail fuel outlets. One was located approximately 90 m southwest of the Site at 4726 Bank Street and was noted to have a lubricant storage building. The other approximately 110 m south of the Site at 4727 Bank Street.

West: Bank Street followed by a cemetery. Although the cemetery property is located across Bank Street at 4660 Bank Street, the cemetery/graveyard is actually about 90 m west of the Site.

5.4 Written Description of Investigation

The Site is located at 4639 Bank Street in Ottawa, Ontario and is bounded to the west by Bank Street and to the north by Rotary Way. At the time of the Site visit, conducted on August 23, 2019, the Site consisted of a 1.23-hectare parcel of vacant, undeveloped land that was overgrown with vegetation.

The surrounding properties within the Phase One Study Area included residential, commercial and community (general mixed use) land uses. During the Site visit, several PCAs were observed on the surrounding lands within the Phase One Study Area including a hydro station at 4564 and 4601 Bank Street (approximately 85 m northeast of the Site), a car dealership property with and old fuel AST at 4605 Bank Street (approximately 40 m northeast of the Site), a cemetery located approximately 90 m west of the Site on 4660 Bank Street, a nursey with associated greenhouses at 4590 Bank Street (approximately 85 m northwest of the Site), a retail fuel outlet with associated lubricants storage building at 4726 Bank Street (approximately 90 m southwest of the Site), a retail fuel outlet at 4727 Bank Street (approximately 110 m south of the Site) as well as an old tar or asphalt AST and a trailer with pails of tar or asphalt approximately 40 m northeast of the Site the former asphalting company property (4603 Bank Street.

6.0 REVIEW AND EVALUATION OF INFORMATION

6.1 Current and Past Uses of the Site

The following summarizes the current and past uses of the Phase One Property:

Year(s)	Name of Owner(s)	Description of Property Use	Property Land Use According to Reg.153/04	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
Prior to 1968	Unknown	Undeveloped	Agricultural or other use	Based on the review of the aerial photographs, information provided by the Site Representative and observations during the Site visit, the Site has never been developed.
1968 to Present	Mr. and Mrs. Halpenny	Undeveloped	Agricultural or other use	Based on the review of the aerial photographs, information provided by the Site Representative and observations during the Site visit, the Site has never been developed.

6.2 Potentially Contaminating Activity

Potentially contaminating activities, which if currently or historically carried out at a Site, may contribute to an area of potential environmental concern (APEC). Based on the information obtained as part of this Phase One ESA, the following PCA was identified within the Phase One Study Area:

Location	Potentially Contaminating Activity	Information Source	Rationale for Potential Contribution of the PCA to an APEC
Phase One Property	**30. Importation of Fill Material of Unknown Quality or Origin** – Fill material was found to be present across the Site up to depths of 0.75 and 1.90 mbgs during the current geotechnical investigation at the Site. Fill material was used to fill in the former creek that intersected the northeast corner of the Site.	Aerial Photographs and	Although this PCA is located on the Phase One Property, there was no evidence of contamination (staining, odour or debris) found in the fill with the exception of one piece of concrete found in the fill at one location and therefore, it is not expected to be of poor quality. Additionally, future development of the Site is likely to include the removal of the fill. Therefore, this PCA is not considered to represent an APEC on the Site.
Phase One Study Area	**10. Commercial Autobody Shops and 28. Gasoline and Associated Products Storage in Fixed Tanks –** Current automotive garage and fuel AST at 4605 Bank Street, approximately 40 m northeast of the Site.	City of Ottawa HLUI, aerial photographs and Site observations	Given that his facility is located hydraulically cross-gradient with respect to the Site and is separated from the Site by Rotary Way and its underlying services, it is not considered to be a PCA that will result in an APEC on the Site.
	5. Asphalt and Bitumen Manufacturing – Former asphalting company with associated tar or asphalt AST at 4603 Bank Street. This property is located approximately 25 m north of the Site. However, the AST and most of the former structures on this property have been located northeast of the Site suggesting that the manufacturing, handling and storage of products has occurred northeast of the Site rather than directly upgradient of the Site. The tank is located approximately 40 m northeast of the Site.	City of Ottawa HLUI, aerial photographs and Site observations	Although this facility was located up and up-to cross-gradient with respect to the Site, the manufacturing, handling and storage of products has likely occurred northeast of the Site, upgradient of the adjacent property east of the Site rather than upgradient to the Site. In addition, this property was separated by the Site from Rotary Way and its underlying services. As such, the potential for subsurface impacts on the Site from the former asphalting company is low and it is not considered to be a PCA that will result in an APEC on the Site.

Location	Potentially Contaminating Activity	Information Source	Rationale for Potential Contribution of the PCA to an APEC
Phase One Study Area	**18. Electricity Generation, Transformation and Power Stations; and 55. Transformer Manufacturing, Processing and Use** – Current hydro facility and substation at 4602 and 4061 Bank Street, approximately 85 m northeast of the Site.	ERIs Report, City of Ottawa HLUI, Aerial Photographs and Site observations	Given the distance and amount of infrastructure between the Site and this facility and that is located hydraulically cross-gradient with respect to the Site, it is not considered to be a PCA that will result in an APEC on the Site.
	40. Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications – Current nursery with associated greenhouses at 4590 Bank Street, approximately 85 m northwest of the Site.	ERIS Report, City of Ottawa HLUI, Aerial Photographs, Site Observations	Given the distance and amount of infrastructure between the Site and this facility, it is not considered to be a PCA that will result in an APEC on the Site.
	28. Gasoline and Associated Products Storage in Fixed Tanks – Current retail fuel outlet associated fuel USTs located approximately 110 m south of the Site at 4727 Bank Street.	ERIS Report, City of Ottawa HLUI, Aerial Photographs, Site Observations	Given the distance between the Site and this facility and that this facility was located hydraulically down-gradient with respect to the Site, it is not considered to be a PCA that will result in an APEC on the Site.
	28. Gasoline and Associated Products Storage in Fixed Tanks – Current retail fuel outlet associated fuel USTs and lubricant storage building located approximately 90 m southwest of the Site at 4726 Bank Street.	ERIS Report, City of Ottawa HLUI, Aerial Photographs, Site Observations	Given the distance and amount of infrastructure between the Site and this facility and that this facility was located hydraulically down-gradient with respect to the Site, it is not considered to be a PCA that will result in an APEC on the Site.
	#28. Gasoline and Associated Products Storage in Fixed Tanks – Former and/or current presence of fuel oil storage tanks located at some of the residential buildings within the Phase One Study Area. The ERIS report identified two fuel oil spills at one of the adjacent residential at 4695 Bank Street (approximately 25 m south the Site). One spill was for up to of 454 L of fuel oil and the other of unknown quantity.	ERIS report, Site observations	The storage tanks were likely ASTs located on concrete floors in the basements of the residential buildings. Given that the spills at 4695 Bank Street was from a concrete basement floor and that it was located hydraulically down-gradient with respect to the Site, it is not considered to be an issue of concern. Additionally, as any other former and/or current fuel oil storage tanks were likely ASTs on concrete basement floors of the residential building, they are not considered to represent and APEC on the Site. hydraulically down-gradient with respect to the Site, they are not considered to be issues of concern for the Site

In addition to the aforementioned PCAs, a cemetery is located within the Phase One Study Area at 4660 Bank Street. A cemetery is not listed PCAs under O.Reg. 153/04; however, it is still an activity that could potentially result in an APEC on the Site. Although this property is located directly across Bank Street to the west, the cemetery/graveyard is actually located approximately 90 m west of the Site. Given the distance and amount of infrastructure between the cemetery and the Site and that it is located hydraulically cross-gradient with respect to the Site, it is not considered to result in an APEC on the Site.

6.3 Areas of Potential Environmental Concern

Based on the information obtained as part of this Phase One ESA, none of the PCAs identified on the Site or off-Site were considered to represent an APEC on the Phase One Property. This Phase One ESA has not been completed to support a Record of Site Condition; however, should a Record of Site Condition need to be filed for the Site, the on-Site PCA (presence of fill material on the Site) will be considered to be represent an APEC on the Phase One Property and a Phase Two ESA will be required to support to the submission of the Record of Site Condition. However, outside the RSC process, the additional information from the geotechnical test pits did not suggest the fill was of poor quality and as such this PCA is not considered to have impacted the site.

6.4 Conceptual Site Model

A Conceptual Site Model of the Phase One Study Area (as required by O.Reg. 153/04) is presented in a series of Figures 1 to 8 (Figure 1: Key Plan, Figure 2: Site Plan and Potentially Contaminating Activities, Figure 3: Topographic Map and Areas of Natural Significance, Figure 4: Surficial Geology, Figure 5: Bedrock Geology, Figure 6: Drift Thickness, Figure 7: Soil Survey Complex (Ontario Soils), and Figure 8: Physiography Map).

The combined set of figures shows:

- Existing buildings and structures
- Water bodies and Areas of Natural Significance (if present) located in the Phase One Study Area
- Drinking water wells on the Phase One Property
- Roads (including names) within the Phase One Study Area
- Uses of properties adjacent to the Phase One Property
- Location of identified PCAs in the Phase One Study Area (including any storage tanks)

The following describes the Phase One ESA Conception Site Model (CSM) for the Site based on the information obtained and reviewed as part of this Phase One ESA:

- At the time of the Site visit, conducted on August 23, 2019, the Site consisted of a 1.23-hectare parcel of vacant, undeveloped land that was overgrown with vegetation.
- The ERIS report indicated that two water wells were constructed on the Site for domestic purposes. However, based on the description of their location which included a larger portion of land that the Site, that the Site has never been developed and there is no other evidence of wells on the Site, it is likely that they these wells were off-Site.
- The Site is bounded to the north by Rotary Way and to the west by Bank Street.

- No fill materials were observed or reported the Site at the time of the Site visit. However, fill was encountered in the six test pits completed on the Site as part of the current geotechnical investigation that is being completed for the Site. The fill consists of silty clay, clayey silt, silt and silty sand which extended to depths between 0.75 and 1.90 mbgs. It is noted that fill material has been placed on the Site to infill the former creek which intersected the northeast corner of the Site. No evidence of contamination (staining, odours, debris) was observed in the fill with the exception of concrete which was noted in the fill in the test pit completed on the southwest corner of the Site.
- The nearest permanent watercourse is Findlay Creek which is located approximately 1.05 kilometres south of the Site.
- No areas of natural and scientific interest (ANSI) are known to be located on the Site or on the Phase One Study Area. Based on available information, the Site is not considered to be an environmentally sensitive area. However, Species at Risk have been identified by the MNRF to be potentially present on the Site or on the nearby lands.
- At the time of the Phase One ESA, the surrounding properties within the Phase One Study Area were comprised of commercial, residential and community land uses.
- The following roads were located within the Phase One Study Area at the time of the Site visit:
  - Bank Street, Rotary Way, Kingswell Street, Sunburst Street, Fairweather Street, Fiddlehead Street, Littlerock Street, Shasta Street and Stalwart Crescent.
- The geological mapping indicates that the subsurface conditions at the Site are till, plain with local relief <5 m and that the bedrock at the Site of the Lindsay Formation (limestone, nodular to black laminated). Based on the geotechnical test pit investigation that was completed for the Site in September 2019, the overburden soils at the Site generally consisted of topsoil over fill material below which was native silt over silty sand glacial till.
- Groundwater is anticipated to flow south towards Findlay Creek.
- The PCAs that may have resulted in an APEC on the Site are presented in Section 6.2 in of this report.

6.4.1 Uncertainty and Absence of Information

There were no material deviations to the Phase One ESA requirements set out in O.Reg. 153/04 that would cause uncertainty or absence of information that would affect the validity of the Phase One Conceptual Site Model or the findings of this Phase One ESA.

7.0 CONCLUSIONS

Given that no APECs were identified on the Site during the Phase One ESA, a Phase Two ESA is not recommended to be carried out at the Site at this time.

This Phase One ESA has not been completed to support a Record of Site Condition; however, should a Record of Site Condition need to be filed for the Site, the on-Site PCA associated with fill material on the Site will be considered to be represent APECs on the Phase One Property and a Phase Two ESA will be required to support to the submission of the Record of Site Condition. Outside the formal RSC process, the geotechnical test pits completed have been used to determine that the fill PCA has not resulted in an APEC to the Site.

7.1 Record of Site Condition Based on Phase One Environmental Site Assessment Alone

Given that the Phase One Property has never been developed and is proposed to be developed with residential buildings, there will be no change in the land use from less sensitive to more sensitive. As such, there is no mandatory requirement for a RSC to be filed for the Site.

8.0 REFERENCES

The following documents and/or data were cited in this report:

Source	Date
Ontario Regulation 153/04 as amended	October 31, 2011
Bélanger, J. R. 2008 Urban Geology of the National Capital Area, Geological Survey of Canada, Open File 5311, 1 DVD.	2008
Armstrong, D.K. and Dodge, J.E.P. 2007. Paleozoic Geology of Southern Ontario; Ontario Geological Survey, Miscellaneous Release—Data 219	2007
2010 Bélanger, J. R., Urban Geology of the National Capital Area, Geological Survey of Canada, Open File D3256, 2001	2010
Aerial Photographs – National Air Photo Library (Natural Resources Canada)	1945, 1956 and 1983
Aerial Photograph Images – geoOttawa (http://maps.ottawa.ca/geoOttawa/)	1965, 1976, 1991, 1999, 2005, 2011, 2014 and 2017
ERIS Report	August 14, 2019
Ontario Ministry of the Environment, Conservation and Parks	August 21, 2019
Technical Standards and Safety Authority	August 21, 2019

9.0 LIMITATIONS AND USE OF REPORT

This report (the “Report”) was prepared for the exclusive use Glenview Properties Inc. for the express purpose of providing advice with respect to the environmental condition of the Site. In evaluating the Site, Golder Associates Ltd. (Golder) has relied in good faith on information provided by others as noted in the Report. We have assumed that the information provided is factual and accurate. We accept no responsibility for any deficiency, misstatement or inaccuracy contained in this Report as a result of omissions, misinterpretations or fraudulent acts of persons interviewed or contacted, or incomplete or inaccurate historical information from the various agencies. Any use which a third party makes of this Report, or any reliance on or decisions to be made based on it, is the sole responsibility of such third party. If a third party requires reliance on this Report, prior written authorization from Golder is required. Golder disclaims any responsibility of consequential financial effects on transactions or property values, or requirements for follow-up actions and costs.

The scope and the period of Golder’s assessment are described in this Report, and are subject to restrictions, assumptions and limitations. Except as noted herein, the work was conducted in accordance with the scope of work and terms and conditions of Golder’s proposal. Golder did not perform a complete assessment of all possible conditions or circumstances that may exist at the Site referenced in the Report. Conditions may therefore exist which were not detected given the limited nature of the assessment Golder was retained to undertake with respect to the Site and additional environmental studies and actions may be required. In addition, it is recognized that the passage of time affects the information provided in the Report. Golder’s opinions are based upon information that existed at the time of the writing of the Report. It is understood that the services provided for in the scope of work allowed Golder to form no more than an opinion of the actual conditions at the Site at the time the Site was visited, and cannot be used to assess the effect of any subsequent changes in any laws, regulations, the environmental quality of the Site or its surroundings. Asbestos and mould surveys were not performed. If a service is not expressly indicated, do not assume it has been provided.

The results of an assessment of this nature should in no way be construed as a warranty that the Site is free from any and all contamination from past or current practices.

10.0 STATEMENT OF COMPLETION

The undersigned confirm that this Phase One Environmental Site Assessment was conducted in a manner consistent with the expected standard of care for the consulting industry in Ontario and meets the requirements for Phase One ESAs as set out in O.Reg. 153/04, however this report has not been completed with the intent of filing a Record of Site Condition.

11.0 CLOSURE

We trust that the information presented in this report meets your current requirements. Should you have any questions or concerns, please do not hesitate to contact the undersigned.

Golder Associates Ltd.

Alyssa Whiteduck, P.Eng.
Environmental Engineer

Keith Holmes, M.Sc., P.Geo
Geoscientist/Associate

AW/KPH/sg/hw
https://golderassociates.sharepoint.com/sites/114589/project files/6 deliverables/phase i esa/final report/19128449-r-rev 0-4639 bank phase one esa sept2019.docx



LEGEND

- PHASE ONE SITE
- PHASE ONE STUDY AREA

0 250 500 1,000

1:25,000 METRES

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. PROJECTION: TRANSVERSE MERCATOR DATUM: NAD 83
COORDINATE SYSTEM: MTM ZONE 9 VERTICAL DATUM: CGVD28

CLIENT

GLENVIEW PROPERTIES INC.

PROJECT

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE

KEY PLAN

CONSULTANT

GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	FIGURE
19128449	0001	0	1

Path: N:\Active\Spatial_IM\CityofOttawa\4639_Bank_St\99_PROJ\19128449_Glenview_Enviro\0001_PhaseOne_ESA\19128449-0001-HS-0001.mxd

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: 25mm

LEGEND

ROADWAY
PCA 1
PHASE ONE SITE
PHASE ONE STUDY AREA

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. LAND INFORMATION ONTARIO (LIO) DATA PRODUCED BY GOLDER ASSOCIATES LTD. UNDER LICENCE FROM ONTARIO MINISTRY OF NATURAL RESOURCES, © QUEENS PRINTER 2014
2. PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83, COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

Potentially Contaminating Activities (PCAs)

Location	Detail	PCA #
1	Importation of Fill Material of Unknown Quality or Origin – Fill material was found to be present across the Site up to depths of 0.75 and 1.90 mbgs during the current geotechnical investigation at the Site. Fill material was used to fill in the former creek that interested the northeast corner of the Site. No signs of contaminated were observed in the fill.	30
2	Commercial Autobody Shops and Gasoline and Associated Products Storage in Fixed Tanks – Current automotive garage and fuel AST at 4605 Bank Street, approximately 40 m northeast of the Site.	10, 28
3	Asphalt and Bitumen Manufacturing– Former asphalting company with associated tar or asphalt AST at 4603 Bank Street, approximately 25 m north of the Site. The tank is located approximately 40 m northeast of the Site.	5
4	Electricity Generation, Transformation and Power Stations; and Transformer Manufacturing, Processing and Use – Current hydro facility and substation at 4602 and 4061 Bank Street, approximately 85 m northeast of the Site.	18, 55
5	Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications – Current nursery with associated greenhouses at 4590 Bank Street, approximately 85 m northwest of the Site.	40
6	Gasoline and Associated Products Storage in Fixed Tanks– Current retail fuel outlet associated fuel USTs located approximately 110 m south of the Site at 4727 Bank Street.	28
7	Gasoline and Associated Products Storage in Fixed Tanks– Current retail fuel outlet associated fuel USTs and lubricant storage building located approximately 90 m southwest of the Site at 4726 Bank Street.	28
8	Current ceemtary at 4660 Bank Street. This property is located directly across Bank Street to the west; however, the cemetery/graveyard is actually located approximately 90 m west of the Site	N/A
N/A	Gasoline and Associated Products Storage in Fixed Tanks – Former and/or current presence of fuel oil storage tanks located at some of the residential buildings within the Phase One Study Area. The ERIS report identified two fuel oil spills at one of the adjacent residential at 4695 Bank Street (approximately 25 m south the Site). This PCA is not shown on figure as is is located at various locations within the Phase One Study Area.	28

0 25 50 100
1:2,750 METRES

CLIENT
GLENVIEW PROPERTIES INC.

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE
SITE PLAN

CONSULTANT
GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	FIGURE
19128449	0001	0	**2**

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: 25mm 0

Path: N:\Active\Spatial_IM\City\Ottawa\4639_Bank_St\9_PROJ\19128449_Glenview_Enviro\0001_PhaseOne_ESA\19128449-0001-HS-0002.mxd



LEGEND

PHASE ONE SITE

PHASE ONE STUDY AREA

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. SERVICE LAYER CREDITS: SOURCES: ESRI, HERE, GARMIN, INTERMAP, INCREMENT P CORP., GEBCO, USGS, FAO, NPS, NRCAN, GEOBASE, IGN, KADASTER NL, ORDNANCE SURVEY, ESRI JAPAN, METI, ESRI CHINA (HONG KONG), SWISSTOPO, © OPENSTREETMAP CONTRIBUTORS, AND THE GIS USER COMMUNITY
2. PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83, COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

0 25 50 100

1:2,750 METRES

CLIENT

GLENVIEW PROPERTIES INC.

PROJECT

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE

TOPOGRAPHIC MAP AND AREAS OF NATURAL SIGNIFICANCE

CONSULTANT

GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	FIGURE
19128449	0001	0	3

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: 25mm

Path: N:\Active\Spatial_IM\City of Ottawa\4639_Bank_St\09_PRO\19128449_Glenveiw_Envir\mxd\0001_PhaseOne_ESA\19128449-0001-HS-0003.mxd



LEGEND

- ROADWAY
- PHASE ONE SITE
- PHASE ONE STUDY AREA
- 5b: NEARSHORE SEDIMENTS: FINE TO MEDIUM GRAINED SAND
- 1a. TILL, PLAIN WITH LOCAL RELIEF <5 m

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. BÉLANGER, J. R. 2008 URBAN GEOLOGY OF THE NATIONAL CAPITAL AREA, GEOLOGICAL SURVEY OF CANADA, OPEN FILE 5311, 1 DVD.
2. LAND INFORMATION ONTARIO (LIO) DATA PRODUCED BY GOLDER ASSOCIATES LTD. UNDER LICENCE FROM ONTARIO MINISTRY OF NATURAL RESOURCES, © QUEENS PRINTER 2014
3. PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83, COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

0 25 50 100
1:2,750 METRES

CLIENT
GLENVIEW PROPERTIES INC.

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE
SURFICIAL GEOLOGY

CONSULTANT
GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	FIGURE
19128449	0001	0	4

Path: N:\Active\Spatial_IM\City\Ottawa\4639_Bank_St\99_PRO\19128449_Glenview_Enviro\0001_PhaseOne_ES\A\19128449-0001-4S-0004.mxd

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM:
25mm
0



LEGEND

- ROADWAY
- PHASE ONE SITE
- PHASE ONE STUDY AREA
- 16: QUEENSTON FORMATION - SHALE, SILTSTONE, MINOR LIMESTONE AND SANDSTONE
- 15: CARLSBAD FORMATION - SHALE AND LIMESTONE
- 11: LINDSAY FORMATION - LIMESTONE; NODULAR TO BLACK LAMINATED
- 4: MARCH FORMATION - SANDSTONE, DOLOMITIC SANDSTONE, DOLOSTONE

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. ARMSTRONG, D.K. AND DODGE, J.E.P. 2007. PALEOZOIC GEOLOGY OF SOUTHERN ONTARIO; ONTARIO GEOLOGICAL SURVEY, MISCELLANEOUS RELEASE--DATA 219
2. LAND INFORMATION ONTARIO (LIO) DATA PRODUCED BY GOLDER ASSOCIATES LTD. UNDER LICENCE FROM ONTARIO MINISTRY OF NATURAL RESOURCES, © QUEENS PRINTER 2014
3. PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83,
COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

0 25 50 100
1:2,750 METRES

CLIENT
GLENVIEW PROPERTIES INC.

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE
BEDROCK GEOLOGY

CONSULTANT
GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	FIGURE
19128449	0001	0	5

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: 25mm

Path: N:\Active\Spatial_IM\City\Ottawa\4639_Bank_St\99_PRO\19128449_Glenview_Enviro\0001_PhaseOne_ESA\19128449-0001-HS-0005.mxd



LEGEND

- ROADWAY
- PHASE ONE SITE
- PHASE ONE STUDY AREA

TREND IN DEPTH TO BEDROCK (METRES)

- 1 to 2
- 2 to 3
- 3 to 5
- 5 to 10
- 10 to 15
- 15 to 25

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. 2010 BÉLANGER, J. R., URBAN GEOLOGY OF THE NATIONAL CAPITAL AREA, GEOLOGICAL SURVEY OF CANADA, OPEN FILE D3256, 2001
2. LAND INFORMATION ONTARIO (LIO) DATA PRODUCED BY GOLDER ASSOCIATES LTD. UNDER LICENCE FROM ONTARIO MINISTRY OF NATURAL RESOURCES, © QUEENS PRINTER 2014
3. PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83, COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

0 25 50 100
1:2,750 METRES

CLIENT
GLENVIEW PROPERTIES INC.

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE
DRIFT THICKNESS

CONSULTANT
GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	FIGURE
19128449	0001	0	**6**

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM:
0 25mm

Path: N:\Active\Spatial_IM\Cityof\Ottawa\4639_Bank_St\09_PRO\19128449_Glenview_Env\rev0\0001_PhaseOne_ESA\19128449-0001-HS-006.mxd



LEGEND

- ROADWAY
- PHASE ONE SITE
- PHASE ONE STUDY AREA
- DEEKAYE
- ELLESS
- LEICESTER
- LEITRIM

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. LAND INFORMATION ONTARIO (LIO) DATA PRODUCED BY GOLDER ASSOCIATES LTD. UNDER LICENCE FROM ONTARIO MINISTRY OF NATURAL RESOURCES, © QUEENS PRINTER 2014
2. PROJECT: TRANSVERSE MERCATOR, DATUM: NAD 83, COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

0 25 50 100

1:2,750 METRES

CLIENT

GLENVIEW PROPERTIES INC.

PROJECT

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE

SOIL SURVEY COMPLEX (ONTARIO SOILS)

CONSULTANT

GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	FIGURE
19128449	0001	0	7

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: ANSI B

25mm

0

Path: N:\Active\Spatial_IM\City\Ottawa\4639_Bank_St\09_PRO\19128449_Glenview_Enviro\0001_PhaseOne_ESA\19128449-0001-HS-0007.mxd



LEGEND

- ROADWAY
- PHASE ONE SITE
- PHASE ONE STUDY AREA
- 11: SAND PLAINS

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. CHAPMAN, L.J. AND PUTNAM, D.F. 2007. PHYSIOGRAPHY OF SOUTHERN ONTARIO; ONTARIO GEOLOGICAL SURVEY, MISCELLANEOUS RELEASE-DATA 228
2. LAND INFORMATION ONTARIO (LIO) DATA PRODUCED BY GOLDER ASSOCIATES LTD. UNDER LICENCE FROM ONTARIO MINISTRY OF NATURAL RESOURCES, © QUEENS PRINTER 2014
3. PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83, COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

0 25 50 100
1:2,750 METRES

CLIENT
GLENVIEW PROPERTIES INC.

PROJECT
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE
PHYSIOGRAPHY MAP

CONSULTANT
GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	FIGURE
19128449	0001	0	**8**

Path: N:\Active\Spatial_IM\City of Ottawa\4639_Bank_St\99_PRO\19128449_Glenview_Enviro\0001_PhaseOne_ESA\19128449-0001-41S-0008.mxd

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM:
0 25mm

APPENDIX A

Regulatory Responses

Ministry of the Environment, Conservation and Parks

Ottawa District Office
2430 Don Reid Drive, Suite 103
Ottawa ON K1H 1E1
Tel.: 613-521-3450 or 1-800-860-2195
Fax: 613-521-5437

Ministère de l'Environnement, de la Protection de la nature et des Parcs

Bureau du district d'Ottawa
2430, promenade Don Reid, Unité 103
Ottawa ON K1H 1E1
Tél.: 613-521-3450 ou 1-800-860-2195
Téléc.: 613-521-5437

Ontario

OTT File No: **53**

INDEX REVIEW REPORT
COMMERCIAL/INDUSTRIAL/AGRICULTURAL

Attention:	**Alyssa Whiteduck**	Your File:
	Golder Associates	Date Received: August 21, 2019

Thank you for your inquiry requesting a search of records from the Ministry of the Environment, Conservation and Parks (ministry). The ministry encourages you to use the available on-line resources to access publically-available information which may assist with your inquiry.

PROPERTY OWNER AND LOCATION

Location: Municipality: **Ottawa City**

Address: **4639 Bank Street**
Lot Concession Township

INDEX OF NAMES FOR ORDERS

We have searched the *Ottawa* District Index Record of Active Orders under the Environmental Protection Act (EPA), Ontario Water Resources Act (OWRA) and the Pesticides Act (PA) issued to: **4639 Bank Street** and the following information has been found:

☒ No Active Orders are outstanding

Please Note: *For information related to any ministry Orders issued to the property in question,* ***please request this information from the property owner.*** *If you would like further information regarding a specific Order issued, please contact the Ottawa District Office.*

Date of Search: August 29, 2019

RECORD OF SITE CONDITION

For information on **Records of Site Condition** filed on the Environmental Site Registry since October 1, 2004, please use the following links:
For records of site condition filed between October 1, 2004 and June 30, 2011 https://www.lrcsde.lrc.gov.on.ca/besrWebPublic/generalSearch and for records of site condition filed since July 1, 2011 https://www.ontario.ca/environment-and-energy/records-site-condition

INDEX REVIEW REPORT
COMMERCIAL/INDUSTRIAL/AGRICULTURAL

INDEX OF NAMES FOR APPROVALS ISSUED SINCE 1999

A search of the Index Record of names of all persons to whom approvals have been issued, maintained by the Director, Approvals Branch and the Regional Director, *Eastern Region*, and the District Manager, *Ottawa District*, under Section 19 EPA and Section 13 OWRA and the following information has been provided :

Type	Number	Issued To	Issue Date
Section 9 EPA *(Air)*			
Section 39 EPA *(Waste Management)*			
Section 52 OWRA *(Water)*			
Section 53 OWRA *(Municipal/Private/ Industrial Sewage)*			
Other			

The **ministry's Access Environment** is an on-line, map-based search tool designed to allow the public, quick and easy access to the ministry approvals and registration information from December 1999 onward. Access Environment currently displays Environmental Compliance Approvals (ECA), Renewable Energy Approvals (REA) and registrations on the Environmental Activity and Sector Registry (EASR). ECAs include all Certificates of Approval (CofAs) previously issued under the Environmental Protection Act (EPA) and approvals previously issued under s.53 of the Ontario Water Resources Act (OWRA). You can access this information from the ministry website or at the following link:
www.accessenvironment.ene.gov.on.ca/AEWeb/ae/GoSearch.action?search=basic&lang=en

Copies of **ECAs issued before January 1, 2000** can be obtained by submitting a Request for a Copy of an Environmental Compliance Approval

Please Note:

1) The information provided above is based solely on the address(es) and name(s) of the present and past owners provided by you.
2) The Index Record of Names to whom approvals have been issued, maintained by the Regional Director and District Manager, has been searched back to 1999.
3) A search of our records does **NOT** indicate whether there are:
   - other uses for which an approval may have been required, **nor**
   - other uses on the property or in the vicinity that may affect the suitability of the property, for the use proposed to be made of it.

   If a comprehensive knowledge of the property and the nearby lands and their environmental condition is required, you must examine them and other relevant records yourself, with the aid of a qualified person, if needed.

☒ No Approvals have been issued.

Date of Search: August 29, 2019

INDEX REVIEW REPORT
COMMERCIAL/INDUSTRIAL/AGRICULTURAL

Additional site information related to the **location of landfill sites** in the province can be found at the following link:

http://www.ontario.ca/environment-and-energy/small-landfill-sites

http://www.ontario.ca/environment-and-energy/map-large-landfill-sites

The **ministry's Hazardous Waste Information Network (HWIN)** can also be accessed to search for information on generators, carriers, and receivers of subject waste in the province at the following link: www.hwin.ca

The **ministry's Environmental Compliance Reports** provide information about contaminant discharges to water and emissions to air that exceed limits found in legislation, environmental approvals, orders and/or policies/guidelines and can be accessed at the following link: http://www.ontario.ca/environment-and-energy/environmental-compliance-reports

Information on **Environmental Penalties**, which are monetary penalties that can be imposed by the ministry for some industrial spills, can be assessed at the following link: https://www.ontario.ca/search/search-results?query=environmental%20penalties

Additional ministry information can be accessed through the **Government of Ontario's Open Data Catalogue**: http://www.ontario.ca/government/open-data-ontario

The ministry also encourages you to consider best practices and standards of care used within the legal community and through your associations as a guide to obtaining information related to specific property for any legal purpose.

We trust this information will help meet your requirements quickly and effectively.

Please advise your colleagues that responses to requests for searches always take some time. As a result the Ministry of the Environment and Climate Change may not be able to meet deadlines imposed by other parties on real estate and other transactions.

Thank you for your inquiry.

Signature: Jehanne Hurlbut

Contact Name: Jéhanne Hurlbut
Title: District Administrative Assistant

Address: Ministry of the Environment, Conservation and Parks
2430 Don Reid Drive, Unit 103
Ottawa, ON K1H 1E1

Phone: (613) 521-3450 Ext 221

Date: August 29, 2019

E&OE

Please Note: *If you would like to receive an email with all the environmental links above, please contact me at jehanne.hurlbut@ontario.ca and I will be pleased to send them to you.*

From: Whiteduck, Alyssa
To: "jehanne.hurlbut@ontario.ca"
Subject: Property Information Request for 4639 Bank Street, Ottawa, Ontario
Date: August 21, 2019 11:29:00 AM
Attachments: image001.jpg
image003.jpg

Hi Jéhanne,

Could you please check for approvals and orders for the following property:

- 4639 Bank Street, Ottawa, ON

Please let me know if you have any questions.

Kindest Regards,

Alyssa Whiteduck (P.Eng.)
Environmental Engineer

Golder Associates Ltd.
1931 Robertson Road, Ottawa, Ontario, Canada, K2H 5B7
T: +1 613 592 9600 | **D:** +1 (613) 592-4006 x4299 | **C:** +1 613 290 8736 | **golder.com**
LinkedIn | Instagram | Facebook | Twitter

Work Safe, Home Safe

From: Public Information Services <publicinformationservices@tssa.org>
Sent: August 21, 2019 11:52 AM
To: Whiteduck, Alyssa
Subject: RE: TSSA Search - Bank Street, Ottawa, Ontario

EXTERNAL EMAIL

Records Found

Hello,

Thank you for your request for confirmation of public information.

- We confirm that there are **fuel storage tanks records** in our database at the subject address(es).

Inst Number	Segment1	Address	City	Status
64708544	FS PROPANE FILLING PLT > 5000 USW	4726 BANK ST	OTTAWA	Active
64711525	FS PROPANE TANK	4726 BANK ST	OTTAWA	Active
10175444	FS GASOLINE STATION - FULL SERVE	4727 BANK ST	OTTAWA	Active
11406000	FS PROPANE TANK	4727 BANK ST	OTTAWA	EXPIRED
11476269	FS LIQUID FUEL TANK	4727 BANK ST	OTTAWA	Active
11589682	FS LIQUID FUEL TANK	4727 BANK ST	OTTAWA	Active
11589672	FS LIQUID FUEL TANK	4727 BANK ST	OTTAWA	Active
11589676	FS LIQUID FUEL TANK	4727 BANK ST	OTTAWA	Active
9629204	FS PROPANE REFILL CNTR - CYLR FILL	4727 BANK ST	OTTAWA	EXPIRED

For a further search in our archives please complete our release of public information form found at https://www.tssa.org/en/about-tssa/release-of-public-information.aspx?_mid_=392 and email the completed form to publicinformationservices@tssa.org or through mail along with a fee of $56.50 (including HST) per location. The fee is payable with credit card (Visa or MasterCard) or with a Cheque made payable to TSSA.

Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Kind regards,

Connie Hill | Public Information Agent
Facilities
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1-416-734-3383 | Fax: +1-416-231-6183 | E-Mail: publicinformationservices@tssa.org
www.tssa.org

From: Whiteduck, Alyssa <Alyssa_Whiteduck@golder.com>
Sent: August 21, 2019 11:40 AM

To: Public Information Services <publicinformationservices@tssa.org>
Subject: TSSA Search - Bank Street, Ottawa, Ontario

Hello,

Could you please perform a TSSA database search for any underground storage tanks, registered fuel tanks, outstanding instructions, incident reports, fuel oil spills or contaminations records for the following properties:

- 4639 Bank Street, Ottawa, ON
- 4637 Bank Street, Ottawa, ON
- 4603 Bank Street, Ottawa, ON
- 4593 Bank Street, Ottawa, ON
- 4605 Bank Street, Ottawa, ON
- 4590 Bank Street, Ottawa, ON
- 4726 Bank Street, Ottawa, ON
- 4727 Bank Street, Ottawa, ON
- 4700 Bank Street, Ottawa, ON
- 4565 Bank Street, Ottawa, ON

Please let me know if you have any questions.

Kindest Regards,

Alyssa Whiteduck (P.Eng.)
Environmental Engineer

GOLDER

Golder Associates Ltd.
1931 Robertson Road, Ottawa, Ontario, Canada, K2H 5B7
T: +1 613 592 9600 | **D:** +1 (613) 592-4006 x4299 | **C:** +1 613 290 8736 | **golder.com**
LinkedIn | Instagram | Facebook | Twitter

Work Safe, Home Safe

APPENDIX B

ERIS Report, City Directories

ENVIRONMENTAL RISK INFORMATION SERVICES

DATABASE REPORT

Project Property:	*Bank Street* *4639 Bank Street* *Gloucester ON K1T 3W6*
Project No:	*19128449*
Report Type:	*RSC Report (Rural)*
Order No:	*20190814043*
Requested by:	*Golder Associates Ltd.*
Date Completed:	*August 14, 2019*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....7
Map.....20
Aerial.....21
Topographic Map.....22
Detail Report.....23
Unplottable Summary.....138
Unplottable Report.....140
Appendix: Database Descriptions.....151
Definitions.....160

Executive Summary

Property Information:

Project Property:	*Bank Street* *4639 Bank Street Gloucester ON K1T 3W6*
Project No:	*19128449*

Coordinates:

Latitude:	*45.326771*
Longitude:	*-75.596713*
UTM Northing:	*5,019,424.69*
UTM Easting:	*453,238.00*
UTM Zone:	*UTM Zone 18T*

Elevation:	*334 FT* *101.88 M*

Order Information:

Order No:	*20190814043*
Date Requested:	*August 14, 2019*
Requested by:	*Golder Associates Ltd.*
Report Type:	*RSC Report (Rural)*

Historical/Products:

Topographic Map	*RSC Maps*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Within 0.25 km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	1	5	6
CA	Certificates of Approval	Y	0	7	7
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	2	2
CHEM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
EASR	Environmental Activity and Sector Registry	Y	0	0	0
EBR	Environmental Registry	Y	0	5	5
ECA	Environmental Compliance Approval	Y	0	13	13
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	0	3	3
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of TSSA Expired Facilities	Y	0	37	37
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FST	Fuel Storage Tank	Y	0	9	9
FSTH	Fuel Storage Tank - Historic	Y	0	4	4
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	37	37
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	0	0
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	TSSA Incidents	Y	0	2	2
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0

Database	Name	Searched	Project Property	Within 0.25 km	Total
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	3	3
NPRI	National Pollutant Release Inventory	Y	0	0	0
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	5	5
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	4	4
PINC	TSSA Pipeline Incidents	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	0	4	4
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	0	0
RST	Retail Fuel Storage Tanks	Y	0	3	3
SCT	Scott's Manufacturing Directory	Y	0	0	0
SPL	Ontario Spills	Y	0	5	5
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	TSSA Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	3	18	21
	Total:		4	166	170

Executive Summary: Site Report Summary - Project Property

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
BORE	1		ON	-/0.0	0.00	23
WWIS	1		lot 17 con 5 ON ***Well ID:*** 1502242	-/0.0	0.00	80
WWIS	2		lot 17 con 5 ON ***Well ID:*** 1502240	-/0.0	-0.69	82
WWIS	3		lot 17 con 5 ON ***Well ID:*** 1502239	-/0.0	-0.57	84

Executive Summary: Site Report Summary - Surrounding Properties

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
BORE	10		ON	SE/49.2	0.00	24
BORE	14		ON	SW/86.0	-2.03	25
BORE	20		ON	S/125.0	-2.00	26
BORE	24		ON	NE/168.3	0.54	27
BORE	31		ON	NNE/201.8	2.03	28
CA	4	Claridge Homes (Leitrim) Inc.	4635,4703,4723 Bank Street Ottawa ON	SSW/8.7	-1.00	29
CA	11	The Ottawa Rotary Home	4637 Bank St formerly 4635 Bank Street Ottawa ON	ENE/52.5	1.08	29
CA	11	The Ottawa Rotary Club for Crippled Children	4637 Bank St formerly 4635 Bank Street Ottawa ON	ENE/52.5	1.08	30
CA	11	The Ottawa Rotary Club for Crippled Children	4637 Bank St formerly 4635 Bank Street Ottawa ON	ENE/52.5	1.08	30
CA	22	The Roman Catholic Episcopal Corporation of Ottawa	4660 Bank St Gloucester Ottawa ON	SW/132.6	-2.01	30
CA	36	Hydro Ottawa Limited	4565 Bank St Ottawa ON	NNW/244.8	2.00	31
CA	36	Hydro Ottawa Limited	4565 Bank Street Ottawa ON	NNW/244.8	2.00	31

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
CFOT	21	W.O. Stinson & Son Ltd.	4727 Bank St. GLOUCESTER ON K1T 3W7	SSE/130.9	-1.00	31
CFOT	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	32
EBR	22	The Roman Catholic Episcopal Corporation of Ottawa	4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA ON	SW/132.6	-2.01	32
EBR	22	The Roman Catholic Episcopal Corporation of Ottawa	4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA ON	SW/132.6	-2.01	32
EBR	22	The Roman Catholic Episcopal Corporation of Ottawa	4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA ON	SW/132.6	-2.01	33
EBR	38	Hydro Ottawa Limited/ Hydro Ottawa Limitee	4565 Bank Street Ottawa K1T 3W6 CITY OF OTTAWA ON	NNW/247.5	2.54	33
EBR	38	Hydro Ottawa Limited	4565 Bank Street Ottawa K1T 3W6 CITY OF OTTAWA ON	NNW/247.5	2.54	34
ECA	11	The Ottawa Rotary Club for Crippled Children	4637 Bank St formerly 4635 Bank Street Ottawa ON K1R 3V3	ENE/52.5	1.08	34
ECA	11	The Ottawa Rotary Home	4637 Bank St formerly 4635 Bank Street Ottawa ON K1R 7V3	ENE/52.5	1.08	35
ECA	11	The Ottawa Rotary Club for Crippled Children	4637 Bank St formerly 4635 Bank Street Ottawa ON K1R 7V3	ENE/52.5	1.08	35
ECA	11	The Ottawa Rotary Club for Crippled Children	4637 Bank St formerly 4635 Bank Street Ottawa ON K1R 3V3	ENE/52.5	1.08	35
ECA	22	The Roman Catholic Episcopal Corporation of Ottawa	4660 Bank St Gloucester Ottawa ON K1H 6K9	SW/132.6	-2.01	35

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
ECA	22	The Roman Catholic Episcopal Corporation of Ottawa	4660 Bank St Gloucester Ottawa ON K1H 6K9	SW/132.6	-2.01	36
ECA	22	The Roman Catholic Episcopal Corporation of Ottawa	4660 Bank St Gloucester Ottawa ON K1H 6K9	SW/132.6	-2.01	36
ECA	32	Claridge Homes (Leitrim) Inc.	4635,4703,4723 Bank Street Ottawa ON K2P 0Y6	ESE/203.5	-2.00	36
ECA	32	Claridge Homes (Leitrim) Inc.	4635,4703,4723 Bank Street Ottawa ON K2P 0Y6	ESE/203.5	-2.00	37
ECA	34	W. O. Stinson & Son Limited	4728 Bank St Part of Lot 17, Concession 4 Rideau Front Ottawa ON K1T 3W7	S/212.7	-2.00	37
ECA	38	Hydro Ottawa Limited/ Hydro Ottawa Limitee	4565 Bank St Ottawa ON K1G 3S4	NNW/247.5	2.54	37
ECA	38	Hydro Ottawa Limited	4565 Bank St Ottawa ON K1T 3W6	NNW/247.5	2.54	37
ECA	38	Hydro Ottawa Limited	4565 Bank St Ottawa ON K1G 3S4	NNW/247.5	2.54	38
EHS	15		4603 Bank Street n/a ON K1T 3W6	NNW/87.7	0.85	38
EHS	22		4660 Bank St Ottawa ON K1T3W7	SW/132.6	-2.01	38
EHS	33		4565 Bank St Ottawa ON K1T3W6	N/212.1	3.00	38
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	39
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	39

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	39
EXP	17	W O STINSON & SONS LTD	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	39
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	39
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	40
EXP	17	TILBAR LEASING LIMITED	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	40
EXP	17	W O STINSON SONS LTD. ATTN ERIC STINSON	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	40
EXP	17	TILBAR LEASING LIMITED	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	40
EXP	17	W O STINSON & SONS LTD	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	41
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	41
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	41
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	41
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	42
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON	S/114.7	-1.86	42

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	42
EXP	17	W O STINSON & SON LTD*	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	42
EXP	17	W O STINSON & SONS LTD	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	43
EXP	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON	SSE/130.9	-1.00	43
EXP	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON	SSE/130.9	-1.00	43
EXP	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON	SSE/130.9	-1.00	43
EXP	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON	SSE/130.9	-1.00	44
EXP	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON	SSE/130.9	-1.00	44
EXP	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON	SSE/130.9	-1.00	44
EXP	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON	SSE/130.9	-1.00	44
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	44
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	45
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	45

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	45
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	45
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	46
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	46
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	46
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	46
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	47
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	47
EXP	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	47
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	47
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	48
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	48
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	48

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	48
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST OTTAWA ON K1T 3W7	S/212.7	-2.00	49
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	49
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	49
FST	34	W.O. STINSON & SON LIMITED	4728 BANK ST GLOUCESTER ON K1T 3W7	S/212.7	-2.00	50
FSTH	17	W O STINSON & SONS LTD	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	50
FSTH	17	W.O. STINSON & SONS LTD	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	51
FSTH	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON K1T 3W7	SSE/130.9	-1.00	51
FSTH	21	W O STINSON & SON LTD*	4727 BANK ST GLOUCESTER ON K1T 3W7	SSE/130.9	-1.00	52
GEN	8	BRIAN McGUIRE	4695 BANK ST OTTAWA ON	SSE/40.7	-0.69	53
GEN	8	BRIAN McGUIRE	4695 BANK ST OTTAWA ON	SSE/40.7	-0.69	53
GEN	13	MDG DOOR SERVICE LTD.	4700 HIGHWAY 31 GLOUCESTER ON K1T 3W7	S/77.1	-1.05	53
GEN	13	MDG DOOR SERVICE LTD.	4700 HIGHWAY #31 GLOUCESTER ON K1T 3W7	S/77.1	-1.05	53

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	54
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	54
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	55
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	55
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	55
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	56
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	56
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	56
GEN	17	W.O. STINSON & SONS LTD. 42-540	4726 BANK STREET GLOUCESTER ON K1G 3N4	S/114.7	-1.86	57
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1T 3W7	S/114.7	-1.86	57
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON	S/114.7	-1.86	58
GEN	17	W.O. STINSON & SONS LIMITED	4726 BANK STREET GLOUCESTER ON K1G 3N4	S/114.7	-1.86	58
GEN	22	HOPE CEMETERY	4660 BANK STREET GLOUCESTER ON K1T 3W7	SW/132.6	-2.01	58

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
GEN	22	HOPE CEMETERY	4660 BANK STREET KING'S HWY 31 GLOUCESTER ON K1T 3W7	SW/132.6	-2.01	59
GEN	22	HOPE CEMETERY	4660 BANK STREET GLOUCESTER ON K1T 3W7	SW/132.6	-2.01	59
GEN	22	HOPE CEMETERY	4660 BANK STREET KING'S HWY 31 GLOUCESTER ON K1T 3W7	SW/132.6	-2.01	59
GEN	22	HOPE CEMETERY	4660 BANK STREET GLOUCESTER ON K1T 3W7	SW/132.6	-2.01	59
GEN	22	HOPE CEMETERY	4660 BANK STREET KING'S HWY 31 GLOUCESTER ON K1T 3W7	SW/132.6	-2.01	60
GEN	23	Valley Squire Furniture	4599 Bank St Ottawa ON K1T 3W8	NNW/150.2	0.93	60
GEN	36	GLOUCESTER HYDRO	4565 BANK STREET GLOUCESTER ON K1G 4C1	NNW/244.8	2.00	60
GEN	36	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1G 4C1	NNW/244.8	2.00	61
GEN	36	GLOUCESTER HYDRO 17-066	4565 BANK STREET GLOUCESTER ON K1G 4C1	NNW/244.8	2.00	62
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	62
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	63
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	64
GEN	38	GLOUCESTER HYDRO	P.O. BOX 9800 4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	65

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1G 4C1	NNW/247.5	2.54	65
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	66
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON	NNW/247.5	2.54	66
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1G 4C1	NNW/247.5	2.54	67
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1G 4C1	NNW/247.5	2.54	68
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1G 4C1	NNW/247.5	2.54	69
GEN	38	Hydro Ottawa Ltd.	4565 BANK STREET GLOUCESTER ON K1G 4C1	NNW/247.5	2.54	69
INC	7		4695 BANK STREET, OTTAWA ON	SSE/39.3	-0.69	70
INC	7		4695 Bank Street, Ottawa ON	SSE/39.3	-0.69	71
NPCB	38	GLOUCESTER HYDRO	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	72
NPCB	38	HYDRO OTTAWA	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	72
NPCB	38	GLOUCESTER HYDRO	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	72
OPCB	38	GLOUCESTER HYDRO	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	73

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
OPCB	38	GLOUCESTER HYDRO	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	73
OPCB	38	GLOUCESTER HYDRO	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	73
OPCB	38	GLOUCESTER HYDRO	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	74
OPCB	38	GLOUCESTER HYDRO	4565 BANK STREET GLOUCESTER ON K1T 3W6	NNW/247.5	2.54	74
PES	18	KNIPPEL PETER NURSERY INC.	4590 BANK ST., R.R. #6 GLOUCESTER ON K1T 3W6	NW/122.0	0.00	75
PES	18	KNIPPEL PETER NURSERY INC	4590 BANK ST GLOUCESTER ON K1T3W6	NW/122.0	0.00	75
PES	18	KNIPPEL PETER NURSERY INC	4590 BANK ST GLOUCESTER ON K1T3W6	NW/122.0	0.00	75
PES	18	KNIPPEL PETER NURSERY INC	4590 BANK ST GLOUCESTER ON K1T 3W6	NW/122.0	0.00	76
PRT	21	W O STINSON & SON LTD	4727 BANK ST HWY 31 LEITRIM ON	SSE/130.9	-1.00	76
PRT	21		4727 BANK ST. GLOUCESTER ON	SSE/130.9	-1.00	76
PRT	21	W O STINSON & SON LTD	4727 BANK ST HWY 31 LEITRIM ON K1T 3W7	SSE/130.9	-1.00	76
PRT	21	W O STINSON & SON LTD	4727 BANK ST HWY 31 LEITRIM ON K1T 3W7	SSE/130.9	-1.00	77
RST	17	STINSON W O & SON LTD	4726 BANK ST GLOUCESTER ON K1T 3W7	S/114.7	-1.86	77

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
RST	17	STINSON W O & SON LTD	4726 BANK ST GLOUCESTER ON K1T3W7	S/114.7	-1.86	77
RST	21	W O STINSON & SONS LTD	4727 BANK ST GLOUCESTER ON K1T3W7	SSE/130.9	-1.00	77
SPL	8	Blue Wave Energy Limited Partnership	4695 Bank St. Ottawa ON	SSE/40.7	-0.69	77
SPL	17	Stinson WO & Sons Ltd.<UNOFFICIAL>	4726 Bank Street, Gloucester Ottawa ON	S/114.7	-1.86	78
SPL	21	W. O. Stinson & Son Limited	4727 Bank St Ottawa ON	SSE/130.9	-1.00	78
SPL	21	PRIVATE RESIDENCE	AT RESIDENCE BESIDE 4727 BANK ST. FURNACE OIL TANK GLOUCESTER CITY ON K1T 3W7	SSE/130.9	-1.00	79
SPL	38	Hydro Ottawa Limited	4565 Bank St. Ottawa ON	NNW/247.5	2.54	79
WWIS	5		Ottawa ON ***Well ID:*** 7133780	S/31.7	-1.05	87
WWIS	6		Ottawa ON ***Well ID:*** 7133796	SSE/37.6	-0.46	90
WWIS	9		lot 16 con 5 OTTAWA ON ***Well ID:*** 7170843	NNW/45.2	0.31	92
WWIS	12		Ottawa ON ***Well ID:*** 7133779	SSE/60.8	-1.00	94
WWIS	16		lot 17 con 4 ON ***Well ID:*** 1502171	SSW/94.8	-2.00	96
WWIS	19		lot 16 con 5 ON ***Well ID:*** 1502237	NNW/122.8	1.00	98

DB	Map Key	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
WWIS	20		lot 17 con 4 ON ***Well ID:*** 1502170	S/125.0	-2.00	101
WWIS	24		lot 17 con 5 ON ***Well ID:*** 1502241	NE/168.3	0.54	103
WWIS	25		Ottawa ON ***Well ID:*** 7227708	WSW/175.7	-2.14	105
WWIS	26		lot 16 con 5 ON ***Well ID:*** 1502238	NNW/179.3	1.31	107
WWIS	27		lot 17 con 4 OTTAWA ON ***Well ID:*** 7226518	S/180.4	-2.00	109
WWIS	28		Ottawa ON ***Well ID:*** 7252050	N/190.3	1.92	117
WWIS	29		Ottawa ON ***Well ID:*** 7252048	NNW/190.7	2.00	119
WWIS	30		Ottawa ON ***Well ID:*** 7252049	NNW/195.4	2.03	122
WWIS	31		lot 16 con 5 ON ***Well ID:*** 1502235	NNE/201.8	2.03	125
WWIS	35		OTTAWA ON ***Well ID:*** 7177033	ESE/226.3	-1.92	128
WWIS	37		Ottawa ON ***Well ID:*** 7252051	N/246.8	3.00	130
WWIS	39		lot 16 con 4 ON ***Well ID:*** 1519538	WNW/248.8	-1.31	133



Map : 0.25 Kilometer Radius

Order No: 20190814043

Address: 4639 Bank Street, Gloucester, ON, K1T 3W6

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

75°36'W

45°19'30"N



45°19'30"N

Aerial (2017)

Address: 4639 Bank Street, Gloucester, ON, K1T 3W6

Source: ESRI World Imagery

Order No: 20190814043

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES



Topographic Map

Address: 4639 Bank Street, Gloucester, ON, K1T 3W6

Source: ESRI World Topographic Map

Order No: 20190814043

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

Detail Report

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
BORE	1	1 of 2	-/0.0	101.9 / 0.00	ON

Borehole ID:	614718	**Inclin FLG:**	No
OGF ID:	215515661	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:	MAR-1966	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.327016
Total Depth m:	13.1	**Longitude DD:**	-75.597064
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	453211
Drill Method:		**Northing:**	5019452
Orig Ground Elev m:	103	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	104		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218399125	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Boulders	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	CLAY.		

Geology Stratum ID:	218399126	**Mat Consistency:**	
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	13.1	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Limestone	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	LIMESTONE. 00040Y. SANDSTONE. GREY. 0007000205GREY. 0002500297ROCK. SEISMIC VELOCITY = **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:		**Horizontal:**	NAD27

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Observatio: **Verticalda:** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 07226 NTS_Sheet:
Confiden 1:

Source List

Source Identifier: 1 **Horizontal Datum:** NAD27
Source Type: Data Survey **Vertical Datum:** Mean Average Sea Level
Source Date: 1956-1972 **Projection Name:** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

BORE 10 **1 of 1** **SE/49.2** **101.9 / 0.00** **ON**

Borehole ID: 614715 **Inclin FLG:** No
OGF ID: 215515658 **SP Status:** Initial Entry
Status: **Surv Elev:** No
Type: Borehole **Piezometer:** No
Use: **Primary Name:**
Completion Date: **Municipality:**
Static Water Level: 3.4 **Lot:**
Primary Water Use: **Township:**
Sec. Water Use: **Latitude DD:** 45.325854
Total Depth m: -999 **Longitude DD:** -75.59552
Depth Ref: Ground Surface **UTM Zone:** 18
Depth Elev: **Easting:** 453331
Drill Method: **Northing:** 5019322
Orig Ground Elev m: 100 **Location Accuracy:**
Elev Reliabil Note: **Accuracy:** Not Applicable
DEM Ground Elev m: 103
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218399118 **Mat Consistency:**
Top Depth: 0 **Material Moisture:**
Bottom Depth: 1.5 **Material Texture:**
Material Color: **Non Geo Mat Type:**
Material 1: Till **Geologic Formation:**
Material 2: **Geologic Group:**
Material 3: **Geologic Period:**
Material 4: **Depositional Gen:**
Gsc Material Description:
Stratum Description: TILL.

Geology Stratum ID: 218399119 **Mat Consistency:**
Top Depth: 1.5 **Material Moisture:**
Bottom Depth: **Material Texture:**
Material Color: Grey **Non Geo Mat Type:**
Material 1: Bedrock **Geologic Formation:**
Material 2: Limestone **Geologic Group:**
Material 3: **Geologic Period:**
Material 4: **Depositional Gen:**
Gsc Material Description:
Stratum Description: BEDROCK. CK. WATER STABLE AT 319.0 FEET.STONE. GREY. 0002500297ROCK. SEISMIC VELOCITY =
**Note: Many records provided by the department have a truncated [Stratum Description] field.

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 072230 NTS_Sheet: 31G05A		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

BORE **14** ***1 of 1*** ***SW/86.0*** ***99.8 / -2.03*** ***ON***

Borehole ID:	614714	***Inclin FLG:***	No
OGF ID:	215515657	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:		***Primary Name:***	
Completion Date:		***Municipality:***	
Static Water Level:	4.9	***Lot:***	
Primary Water Use:		***Township:***	
Sec. Water Use:		***Latitude DD:***	45.325752
Total Depth m:	-999	***Longitude DD:***	-75.597816
Depth Ref:	Ground Surface	***UTM Zone:***	18
Depth Elev:		***Easting:***	453151
Drill Method:		***Northing:***	5019312
Orig Ground Elev m:	102	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	102		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218399116	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	4.9	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Stones	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	STONES. LOOSE.		

Geology Stratum ID:	218399117	***Mat Consistency:***	
Top Depth:	4.9	***Material Moisture:***	
Bottom Depth:		***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	

Material 4: **Depositional Gen:**
Gsc Material Description:
Stratum Description: BEDROCK. WATER STABLE AT 319.0 FEET.STONE. GREY. 0002500297ROCK. SEISMIC VELOCITY = 12000.

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 072220 NTS_Sheet: 31G05A
Confiden 1: Reliable information but incomplete.
Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

BORE **20** ***1 of 2*** ***S/125.0*** ***99.9 / -2.00*** ***ON***

Borehole ID: 614710
OGF ID: 215515653
Status:
Type: Borehole
Use:
Completion Date: JUL-1953
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 77.7
Depth Ref: Ground Surface
Depth Elev:
Drill Method:
Orig Ground Elev m: 104
Elev Reliabil Note:
DEM Ground Elev m: 102
Concession:
Location D:
Survey D:
Comments:
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 45.324766
Longitude DD: -75.59704
UTM Zone: 18
Easting: 453211
Northing: 5019202
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218399102
Top Depth: 4.9
Bottom Depth: 77.7
Material Color: Black
Material 1: Shale
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SHALE. BLACK. 001001300. UNSPECIFIED. SEISMIC VELOCITY = 6400. BEDROCK. SEISMIC VELOCITY = **Note: Many records provided by the department have a truncated [Stratum Description] field.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218399101
Mat Consistency:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Soil	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SHALE.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:		**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 07218 NTS_Sheet:		
Confiden 1:			

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

BORE	***24***	***1 of 2***	***NE/168.3***	***102.4 / 0.54***	***ON***

Borehole ID:	614722	**Inclin FLG:**	No
OGF ID:	215515665	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:	AUG-1964	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.328288
Total Depth m:	21.3	**Longitude DD:**	-75.59478
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	453391
Drill Method:		**Northing:**	5019592
Orig Ground Elev m:	103	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	103		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218399139	**Mat Consistency:**	
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	21.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Slate	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Material 4: **Depositional Gen:**
Gsc Material Description:
Stratum Description: SLATE. BROWN. 00070. 00190STONE. GREY. 000570002500297ROCK. SEISMIC VELOCITY = 12000.

Geology Stratum ID: 218399138
Top Depth: 0
Bottom Depth: 2.4
Material Color: Brown
Material 1: Shale
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SHALE. BROWN.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence:
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 07230 NTS_Sheet:
Confiden 1:

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

BORE	31	1 of 2	NNE/201.8	103.9 / 2.03	ON

Borehole ID: 614724
OGF ID: 215515666
Status:
Type: Borehole
Use:
Completion Date: NOV-1953
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 72.8
Depth Ref: Ground Surface
Depth Elev:
Drill Method:
Orig Ground Elev m: 103
Elev Reliabil Note:
DEM Ground Elev m: 104
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 45.329186
Longitude DD: -75.5953
UTM Zone: 18
Easting: 453351
Northing: 5019692
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218399140
Top Depth: 0

Mat Consistency:
Material Moisture:

Bottom Depth:	4.9	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Gravel	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	GRAVEL. BLACK.		

Geology Stratum ID:	218399141	**Mat Consistency:**	
Top Depth:	4.9	**Material Moisture:**	
Bottom Depth:	72.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK. 00160070. 00190STONE. GREY. 000570002500297ROCK. SEISMIC VELOCITY = 12000.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:		**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 07232 NTS_Sheet:		
Confiden 1:			

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

CA | **4** | ***1 of 1*** | ***SSW/8.7*** | ***100.9 / -1.00*** | ***Claridge Homes (Leitrim) Inc. 4635,4703,4723 Bank Street Ottawa ON***

Certificate #:	4237-8J4JV3
Application Year:	2011
Issue Date:	7/8/2011
Approval Type:	Municipal and Private Sewage Works
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

CA | **11** | ***1 of 7*** | ***ENE/52.5*** | ***103.0 / 1.08*** | ***The Ottawa Rotary Home 4637 Bank St formerly 4635 Bank Street Ottawa ON***

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Certificate #: 1750-7GNMAR
Application Year: 2008
Issue Date: 8/14/2008
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
CA	11	***2 of 7***	***ENE/52.5***	***103.0 / 1.08***	***The Ottawa Rotary Club for Crippled Children 4637 Bank St formerly 4635 Bank Street Ottawa ON***

Certificate #: 3707-7GFQTB
Application Year: 2008
Issue Date: 7/14/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
CA	11	***3 of 7***	***ENE/52.5***	***103.0 / 1.08***	***The Ottawa Rotary Club for Crippled Children 4637 Bank St formerly 4635 Bank Street Ottawa ON***

Certificate #: 4390-7HXPK6
Application Year: 2008
Issue Date: 8/28/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
CA	22	***1 of 14***	***SW/132.6***	***99.9 / -2.01***	***The Roman Catholic Episcopal Corporation of Ottawa 4660 Bank St Gloucester Ottawa ON***

Certificate #: 8875-83VNMT

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Application Year: 2010
Issue Date: 4/28/2010
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

CA	***36***	***1 of 5***	***NNW/244.8***	***103.9 / 2.00***	***Hydro Ottawa Limited 4565 Bank St Ottawa ON***

Certificate #: 9836-8B5R3R
Application Year: 2011
Issue Date: 4/5/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

CA	***36***	***2 of 5***	***NNW/244.8***	***103.9 / 2.00***	***Hydro Ottawa Limited 4565 Bank Street Ottawa ON***

Certificate #: 2200-6FSLF7
Application Year: 2005
Issue Date: 9/6/2005
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

CFOT	***21***	***1 of 17***	***SSE/130.9***	***100.9 / -1.00***	***W.O. Stinson & Son Ltd. 4727 Bank St. GLOUCESTER ON K1T 3W7***

Licence No:
Registration No: 200204-2415
Posse File No:
Posse Reg No:
Tank Type:
Instance Number:
Facility Type:
Instance Type:
Letter Sent:
Corrosion Protection:
Province:
Nbr:
Contact Name:
Contact Address: 4726 Bank St
Contact Address2:
Contact Suite:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Status Name:		**Contact City:**	Glouchester
Fuel Type:		**Contact Prov:**	ON
Distributor:	W.O. Stinson & Son Ltd.	**Contact Postal:**	K1T 3W7
Tank Material:	Steel	**Tank Address:**	4727 Bank St.
Tank Age (as of 05/1992):	11 yrs	**Comments:**	
Tank Size:	2200 L		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
CFOT	34	**1 of 23**	**S/212.7**	**99.9 / -2.00**	**W.O. STINSON & SON LIMITED 4728 BANK ST OTTAWA ON K1T 3W7**

Licence No:		**Letter Sent:**	
Registration No:		**Corrosion Protection:**	Sacrificial anode
Posse File No:		**Province:**	ON
Posse Reg No:		**Nbr:**	2259
Tank Type:	Single Wall UST	**Contact Name:**	
Instance Number:	61165468	**Contact Address:**	
Facility Type:	FS Fuel Oil Tank	**Contact Address2:**	
Instance Type:	FS Fuel Oil Tank	**Contact Suite:**	
Status Name:	Active	**Contact City:**	
Fuel Type:	Fuel Oil	**Contact Prov:**	
Distributor:		**Contact Postal:**	
Tank Material:	Steel	**Tank Address:**	4728 BANK ST
Tank Age (as of 05/1992):		**Comments:**	
Tank Size:	2200		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EBR	22	**2 of 14**	**SW/132.6**	**99.9 / -2.01**	**The Roman Catholic Episcopal Corporation of Ottawa 4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA ON**

EBR Registry No:	010-3275	**Year:**	2008
Ministry Ref No:	8693-7CELTN	**Act 1:**	
Notice Type:	Instrument Decision	**Act 2:**	
Notice Stage:		**Comment Period:**	
Notice Date:	November 13, 2014	**Section:**	
Proposal Date:	April 15, 2008	**Site Location Map:**	
Decision Posted:			
Posted By:			
Company Name:	The Roman Catholic Episcopal Corporation of Ottawa		
Off Instrument Name:			
Instrument Type:	(EPA Part II.1-air) - Environmental Compliance Approval (project type: air)		
Proponent Name:			
Proponent Address:	1247 Kilborn Place, Ottawa Ontario, Canada K1H 6K9		
Site Address:			
Location Other:			
URL:			

Site Location Details:

4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EBR	22	**3 of 14**	**SW/132.6**	**99.9 / -2.01**	**The Roman Catholic Episcopal Corporation of Ottawa 4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA ON**

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

EBR Registry No: 010-8374 **Year:** 2009
Ministry Ref No: 3272-7XANPL **Act 1:**
Notice Type: Instrument Decision **Act 2:**
Notice Stage: 803474401 **Comment Period:**
Notice Date: May 03, 2010 **Section:**
Proposal Date: November 16, 2009 **Site Location Map:**
Decision Posted:
Posted By:
Company Name: The Roman Catholic Episcopal Corporation of Ottawa
Off Instrument Name:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Proponent Name:
Proponent Address: 1247 Kilborn place, Ottawa Ontario, Canada K1H 6K9
Site Address:
Location Other:
URL:

Site Location Details:

4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA

EBR	22	4 of 14	SW/132.6	99.9 / -2.01	The Roman Catholic Episcopal Corporation of Ottawa 4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA ON

EBR Registry No: 011-9319 **Year:** 2013
Ministry Ref No: 6702-97QL8Q **Act 1:**
Notice Type: Instrument Decision **Act 2:**
Notice Stage: 808941735 **Comment Period:**
Notice Date: October 14, 2015 **Section:**
Proposal Date: June 05, 2013 **Site Location Map:**
Decision Posted:
Posted By:
Company Name: The Roman Catholic Episcopal Corporation of Ottawa
Off Instrument Name:
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Proponent Name:
Proponent Address: 1247 Kilborn place, Ottawa Ontario, Canada K1H 6K9
Site Address:
Location Other:
URL:

Site Location Details:

4660 Bank Street Ottawa K1T 3W7 CITY OF OTTAWA

EBR	38	1 of 25	NNW/247.5	104.4 / 2.54	Hydro Ottawa Limited/ Hydro Ottawa Limitee 4565 Bank Street Ottawa K1T 3W6 CITY OF OTTAWA ON

EBR Registry No: 012-2093 **Year:** 2014
Ministry Ref No: 6111-9JTJCF **Act 1:**
Notice Type: Instrument Decision **Act 2:**
Notice Stage: 819960499 **Comment Period:**
Notice Date: October 21, 2015 **Section:**
Proposal Date: July 04, 2014 **Site Location Map:**

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Decision Posted:
Posted By:
Company Name: Hydro Ottawa Limited/ Hydro Ottawa Limitée
Off Instrument Name:
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Proponent Name:
Proponent Address: 3025 Albion Road, Ottawa Ontario, Canada K1V 9V9
Site Address:
Location Other:
URL:

Site Location Details:

4565 Bank Street Ottawa K1T 3W6 CITY OF OTTAWA

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EBR	38	***2 of 25***	***NNW/247.5***	***104.4 / 2.54***	***Hydro Ottawa Limited 4565 Bank Street Ottawa K1T 3W6 CITY OF OTTAWA ON***

EBR Registry No: 010-6526
Ministry Ref No: 9498-7RBPG7
Notice Type: Instrument Decision
Notice Stage: 803319922
Notice Date: April 11, 2011
Proposal Date: April 27, 2009
Year: 2009
Act 1:
Act 2:
Comment Period:
Section:
Site Location Map:
Decision Posted:
Posted By:
Company Name: Hydro Ottawa Limited
Off Instrument Name:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Proponent Name:
Proponent Address: 3025 Albion Road North, Ottawa Ontario, Canada K1G 3S4
Site Address:
Location Other:
URL:

Site Location Details:

4565 Bank Street Ottawa K1T 3W6 CITY OF OTTAWA

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	11	***4 of 7***	***ENE/52.5***	***103.0 / 1.08***	***The Ottawa Rotary Club for Crippled Children 4637 Bank St formerly 4635 Bank Street Ottawa ON K1R 3V3***

Approval No: 9117-7GFQLK
Approval Date: 2008-07-14
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Address: 4637 Bank St formerly 4635 Bank Street
Full Address:
Full PDF Link:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	11	5 of 7	ENE/52.5	103.0 / 1.08	The Ottawa Rotary Home 4637 Bank St formerly 4635 Bank Street Ottawa ON K1R 7V3

Approval No:	1750-7GNMAR	**MOE District:**	
Approval Date:	2008-08-14	**City:**	
Status:	Approved	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	
SWP Area Name:		**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Address:	4637 Bank St formerly 4635 Bank Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7600-7FCQ6R-14.pdf		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	11	6 of 7	ENE/52.5	103.0 / 1.08	The Ottawa Rotary Club for Crippled Children 4637 Bank St formerly 4635 Bank Street Ottawa ON K1R 7V3

Approval No:	4390-7HXPK6	**MOE District:**	
Approval Date:	2008-08-28	**City:**	
Status:	Approved	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	
SWP Area Name:		**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	4637 Bank St formerly 4635 Bank Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6917-7GEK8W-14.pdf		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	11	7 of 7	ENE/52.5	103.0 / 1.08	The Ottawa Rotary Club for Crippled Children 4637 Bank St formerly 4635 Bank Street Ottawa ON K1R 3V3

Approval No:	3707-7GFQTB	**MOE District:**	
Approval Date:	2008-07-14	**City:**	
Status:	Approved	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	
SWP Area Name:		**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	4637 Bank St formerly 4635 Bank Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2745-7GEK83-14.pdf		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	22	5 of 14	SW/132.6	99.9 / -2.01	The Roman Catholic Episcopal Corporation of Ottawa 4660 Bank St Gloucester Ottawa ON K1H 6K9

Approval No:	8875-83VNMT	**MOE District:**	Ottawa
Approval Date:	2010-04-28	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-75.59443999999999

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Record Type: ECA | **Latitude:** 45.321445
Link Source: IDS | **Geometry X:**
SWP Area Name: South Nation | **Geometry Y:**
Approval Type: ECA-AIR
Project Type: AIR
Address: 4660 Bank St Gloucester
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3272-7XANPL-14.pdf

---

ECA | 22 | **6 of 14** | **SW/132.6** | **99.9 / -2.01** | **The Roman Catholic Episcopal Corporation of Ottawa**
4660 Bank St Gloucester
Ottawa ON K1H 6K9

Approval No: 6280-9YMK8U | **MOE District:** Ottawa
Approval Date: 2015-10-09 | **City:**
Status: Approved | **Longitude:** -75.59443999999999
Record Type: ECA | **Latitude:** 45.321445
Link Source: IDS | **Geometry X:**
SWP Area Name: South Nation | **Geometry Y:**
Approval Type: ECA-AIR
Project Type: AIR
Address: 4660 Bank St Gloucester
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6702-97QL8Q-14.pdf

---

ECA | 22 | **7 of 14** | **SW/132.6** | **99.9 / -2.01** | **The Roman Catholic Episcopal Corporation of Ottawa**
4660 Bank St Gloucester
Ottawa ON K1H 6K9

Approval No: 8875-83VNMT | **MOE District:** Ottawa
Approval Date: 2012-09-11 | **City:**
Status: Revoked and/or Replaced | **Longitude:** -75.59443999999999
Record Type: ECA | **Latitude:** 45.321445
Link Source: IDS | **Geometry X:**
SWP Area Name: South Nation | **Geometry Y:**
Approval Type: ECA-AIR
Project Type: AIR
Address: 4660 Bank St Gloucester
Full Address:
Full PDF Link:

ECA | 32 | **1 of 2** | **ESE/203.5** | **99.9 / -2.00** | **Claridge Homes (Leitrim) Inc.**
4635,4703,4723 Bank Street
Ottawa ON K2P 0Y6

Approval No: 9736-97PJXS | **MOE District:** Ottawa
Approval Date: 2013-05-21 | **City:**
Status: Approved | **Longitude:** -75.5858
Record Type: ECA | **Latitude:** 45.330200000000005
Link Source: IDS | **Geometry X:**
SWP Area Name: South Nation | **Geometry Y:**
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: 4635,4703,4723 Bank Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9774-968RVE-14.pdf

---

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	32	2 of 2	ESE/203.5	99.9 / -2.00	Claridge Homes (Leitrim) Inc. 4635,4703,4723 Bank Street Ottawa ON K2P 0Y6

Approval No:	4237-8J4JV3	**MOE District:**	Ottawa
Approval Date:	2011-07-08	**City:**	
Status:	Approved	**Longitude:**	-75.5858
Record Type:	ECA	**Latitude:**	45.330200000000005
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	South Nation	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	4635,4703,4723 Bank Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/0186-8HZLY9-14.pdf		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	34	2 of 23	S/212.7	99.9 / -2.00	W. O. Stinson & Son Limited 4728 Bank St Part of Lot 17, Concession 4 Rideau Front Ottawa ON K1T 3W7

Approval No:	0653-9WUQXG	**MOE District:**	Ottawa
Approval Date:	2015-05-27	**City:**	
Status:	Approved	**Longitude:**	-75.5956
Record Type:	ECA	**Latitude:**	45.323764999999995
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	South Nation	**Geometry Y:**	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Address:	4728 Bank St Part of Lot 17, Concession 4 Rideau Front		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/5288-9R7PH3-14.pdf		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	38	3 of 25	NNW/247.5	104.4 / 2.54	Hydro Ottawa Limited/ Hydro Ottawa Limitee 4565 Bank St Ottawa ON K1G 3S4

Approval No:	2634-A34NHV	**MOE District:**	Ottawa
Approval Date:	2015-10-13	**City:**	
Status:	Approved	**Longitude:**	-75.59756999999999
Record Type:	ECA	**Latitude:**	45.32978
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	South Nation	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Address:	4565 Bank St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6111-9JTJCF-14.pdf		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
ECA	38	4 of 25	NNW/247.5	104.4 / 2.54	Hydro Ottawa Limited 4565 Bank St Ottawa ON K1T 3W6

Approval No:	2200-6FSLF7	**MOE District:**	Ottawa
Approval Date:	2005-09-06	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-75.59756999999999
Record Type:	ECA	**Latitude:**	45.32978
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	South Nation	**Geometry Y:**	
Approval Type:	ECA-AIR		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Project Type: AIR
Address: 4565 Bank St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5818-6DTL78-14.pdf

---

ECA | 38 | 5 of 25 | NNW/247.5 | 104.4 / 2.54 | Hydro Ottawa Limited
4565 Bank St
Ottawa ON K1G 3S4

Approval No: 9836-8B5R3R
Approval Date: 2011-04-05
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: South Nation
Approval Type: ECA-AIR
Project Type: AIR
Address: 4565 Bank St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9498-7RBPG7-14.pdf

MOE District: Ottawa
City:
Longitude: -75.59756999999999
Latitude: 45.32978
Geometry X:
Geometry Y:

EHS | 15 | 1 of 1 | NNW/87.7 | 102.7 / 0.85 | 4603 Bank Street
n/a ON K1T 3W6

Order No: 20060404013w
Status: C
Report Type: Online Mapless
Report Date: 4/4/2006
Date Received: 4/4/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X:
Y:

EHS | 22 | 8 of 14 | SW/132.6 | 99.9 / -2.01 | 4660 Bank St
Ottawa ON K1T3W7

Order No: 20160621069
Status: C
Report Type: Custom Report
Report Date: 27-JUN-16
Date Received: 21-JUN-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory

Nearest Intersection:
Municipality: Gloucester
Client Prov/State: ON
Search Radius (km): .25
X: -75.608007
Y: 45.321844

EHS | 33 | 1 of 1 | N/212.1 | 104.9 / 3.00 | 4565 Bank St
Ottawa ON K1T3W6

Order No: 20150902074
Status: C
Report Type: Custom Report
Report Date: 24-SEP-15
Date Received: 02-SEP-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.597178
Y: 45.329568

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	1 of 35	S/114.7	100.0 / -1.86	W O STINSON & SON LTD* 4726 BANK ST GLOUCESTER ON

Instance No: 10475864
Instance ID: 20793
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	2 of 35	S/114.7	100.0 / -1.86	W O STINSON & SON LTD* 4726 BANK ST GLOUCESTER ON K1T 3W7

Instance No: 10024137
Instance ID:
Instance Type: FS Facility
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 5/21/2009

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	3 of 35	S/114.7	100.0 / -1.86	W O STINSON & SON LTD* 4726 BANK ST GLOUCESTER ON K1T 3W7

Instance No: 11185880
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 5/6/2013 16:26

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	4 of 35	S/114.7	100.0 / -1.86	W O STINSON & SONS LTD 4726 BANK ST GLOUCESTER ON

Instance No: 11353742
Instance ID: 79524
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	5 of 35	S/114.7	100.0 / -1.86	W O STINSON & SON LTD* 4726 BANK ST GLOUCESTER ON

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Instance No: 10462638
Instance ID: 18551
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

EXP | **17** | ***6 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W O STINSON & SON LTD****
4726 BANK ST
GLOUCESTER ON

Instance No: 10474656
Instance ID: 21962
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

EXP | **17** | ***7 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***TILBAR LEASING LIMITED***
4726 BANK ST
GLOUCESTER ON

Instance No: 10487701
Instance ID: 22552
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

EXP | **17** | ***8 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W O STINSON SONS LTD. ATTN ERIC STINSON***
4726 BANK ST
GLOUCESTER ON

Instance No: 28356277
Instance ID: 285475
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

EXP | **17** | ***9 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***TILBAR LEASING LIMITED***
4726 BANK ST
GLOUCESTER ON

Instance No: 10487692

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
Instance ID:		23547			
Instance Type:		FS Highway Tank - Gas/Diesel			
Description:		FS HIGHWAY TANK - GASOLINE/DIESEL			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:					

EXP	17	**10 of 35**	**S/114.7**	**100.0 / -1.86**	**W O STINSON & SONS LTD** **4726 BANK ST** **GLOUCESTER ON K1T 3W7**
Instance No:		11353723			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		5/21/2009			

EXP	17	**11 of 35**	**S/114.7**	**100.0 / -1.86**	**W O STINSON & SON LTD*** **4726 BANK ST** **GLOUCESTER ON K1T 3W7**
Instance No:		11185945			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		5/6/2013 16:26			

EXP	17	**12 of 35**	**S/114.7**	**100.0 / -1.86**	**W O STINSON & SON LTD*** **4726 BANK ST** **GLOUCESTER ON K1T 3W7**
Instance No:		11185764			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		5/6/2013 16:26			

EXP	17	**13 of 35**	**S/114.7**	**100.0 / -1.86**	**W O STINSON & SON LTD*** **4726 BANK ST** **GLOUCESTER ON**
Instance No:		10485536			
Instance ID:		22562			
Instance Type:		FS Highway Tank - Gas/Diesel			
Description:		FS HIGHWAY TANK - GASOLINE/DIESEL			

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:					

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	14 of 35	S/114.7	100.0 / -1.86	W O STINSON & SON LTD* 4726 BANK ST GLOUCESTER ON K1T 3W7

Instance No:	11185918
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	5/6/2013 16:26

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	15 of 35	S/114.7	100.0 / -1.86	W O STINSON & SON LTD* 4726 BANK ST GLOUCESTER ON

Instance No:	10475883
Instance ID:	22114
Instance Type:	FS Highway Tank - Gas/Diesel
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	16 of 35	S/114.7	100.0 / -1.86	W O STINSON & SON LTD* 4726 BANK ST GLOUCESTER ON K1T 3W7

Instance No:	11185804
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	5/6/2013 16:26

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	17	17 of 35	S/114.7	100.0 / -1.86	W O STINSON & SON LTD* 4726 BANK ST GLOUCESTER ON K1T 3W7

Instance No:	11185842
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
Facility Type:					
Expired Date:		5/6/2013 16:26			

EXP	17	18 of 35	S/114.7	100.0 / -1.86	W O STINSON & SONS LTD 4726 BANK ST GLOUCESTER ON K1T 3W7

Instance No:	10024107
Instance ID:	
Instance Type:	FS Facility
Description:	
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	5/6/2013 16:26

EXP	21	2 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SON LTD* 4727 BANK ST GLOUCESTER ON

Instance No:	11476206
Instance ID:	86594
Instance Type:	FS Liquid Fuel Tank
Description:	FS Liquid Fuel Tank
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	

EXP	21	3 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SON LTD* 4727 BANK ST GLOUCESTER ON

Instance No:	11476224
Instance ID:	86424
Instance Type:	FS Liquid Fuel Tank
Description:	FS Liquid Fuel Tank
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	

EXP	21	4 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SON LTD* 4727 BANK ST GLOUCESTER ON

Instance No:	11476239
Instance ID:	86650
Instance Type:	FS Liquid Fuel Tank
Description:	FS Liquid Fuel Tank
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	21	5 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SON LTD* 4727 BANK ST GLOUCESTER ON

Instance No: 11476304
Instance ID: 86788
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	21	6 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SON LTD* 4727 BANK ST GLOUCESTER ON

Instance No: 11476257
Instance ID: 86147
Instance Type: FS Liquid Fuel Tank
Description: FS Liquid Fuel Tank
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	21	7 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SON LTD* 4727 BANK ST GLOUCESTER ON

Instance No: 11476186
Instance ID: 86139
Instance Type: FS Liquid Fuel Tank
Description: FS Liquid Fuel Tank
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	21	8 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SON LTD* 4727 BANK ST GLOUCESTER ON

Instance No: 11476286
Instance ID: 86061
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	34	3 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
					4728 BANK ST **OTTAWA ON K1T 3W7**

Instance No: 11353723
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/21/2009

EXP	34	**4 of 23**	**S/212.7**	**99.9 / -2.00**	**W.O. STINSON & SON LIMITED** **4728 BANK ST** **GLOUCESTER ON K1T 3W7**

Instance No: 11476257
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/21/2009

EXP	34	**5 of 23**	**S/212.7**	**99.9 / -2.00**	**W.O. STINSON & SON LIMITED** **4728 BANK ST** **OTTAWA ON K1T 3W7**

Instance No: 11185945
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/6/2013 4:26:24 PM

EXP	34	**6 of 23**	**S/212.7**	**99.9 / -2.00**	**W.O. STINSON & SON LIMITED** **4728 BANK ST** **OTTAWA ON K1T 3W7**

Instance No: 11185764
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/6/2013 4:26:24 PM

EXP	34	**7 of 23**	**S/212.7**	**99.9 / -2.00**	**W.O. STINSON & SON LIMITED** **4728 BANK ST** **OTTAWA ON K1T 3W7**

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Instance No: 11185880
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/6/2013 4:26:24 PM

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	34	8 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST GLOUCESTER ON K1T 3W7

Instance No: 11476186
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/21/2009

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	34	9 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST GLOUCESTER ON K1T 3W7

Instance No: 11476206
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/21/2009

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	34	10 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST OTTAWA ON K1T 3W7

Instance No: 11185842
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/6/2013 4:26:24 PM

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	34	11 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST OTTAWA ON K1T 3W7

Instance No: 11185804
Instance ID:
Instance Type: FS Liquid Fuel Tank

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
Description:		FS Gasoline Station - Self Serve			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:		FS Liquid Fuel Tank			
Expired Date:		5/6/2013 4:26:24 PM			

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	34	12 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST GLOUCESTER ON K1T 3W7

Instance No:	11476224
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	FS Gasoline Station - Full Serve
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	FS Liquid Fuel Tank
Expired Date:	5/21/2009

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	34	13 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST GLOUCESTER ON K1T 3W7

Instance No:	11476239
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	FS Gasoline Station - Full Serve
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	FS Liquid Fuel Tank
Expired Date:	5/21/2009

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
EXP	34	14 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST OTTAWA ON K1T 3W7

Instance No:	11185918
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	FS Gasoline Station - Self Serve
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	FS Liquid Fuel Tank
Expired Date:	5/6/2013 4:26:24 PM

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
FST	34	15 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST OTTAWA ON K1T 3W7

Instance No:	11550641
Cont Name:	
Instance Type:	FS Liquid Fuel Tank
Fuel Type:	Diesel
Status:	Active
Capacity:	50000

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 1998
Parent Facility Type: FS Gasoline Station - Card/Keylock
Facility Type: FS Liquid Fuel Tank

FST | 34 | 16 of 23 | S/212.7 | 99.9 / -2.00 | **W.O. STINSON & SON LIMITED**
4728 BANK ST
OTTAWA ON K1T 3W7

Instance No: 11550600
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Gasoline
Status: Active
Capacity: 25000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 1998
Parent Facility Type: FS Gasoline Station - Card/Keylock
Facility Type: FS Liquid Fuel Tank

FST | 34 | 17 of 23 | S/212.7 | 99.9 / -2.00 | **W.O. STINSON & SON LIMITED**
4728 BANK ST
OTTAWA ON K1T 3W7

Instance No: 11550574
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Gasoline
Status: Active
Capacity: 50000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 1998
Parent Facility Type: FS Gasoline Station - Card/Keylock
Facility Type: FS Liquid Fuel Tank

FST | 34 | 18 of 23 | S/212.7 | 99.9 / -2.00 | **W.O. STINSON & SON LIMITED**
4728 BANK ST
GLOUCESTER ON K1T 3W7

Instance No: 11589672
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Gasoline
Status: Active
Capacity: 25000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 1999
Parent Facility Type: FS Gasoline Station - Full Serve
Facility Type: FS Liquid Fuel Tank

FST | 34 | 19 of 23 | S/212.7 | 99.9 / -2.00 | **W.O. STINSON & SON LIMITED**

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
					4728 BANK ST OTTAWA ON K1T 3W7

Instance No:	11550587
Cont Name:	
Instance Type:	FS Liquid Fuel Tank
Fuel Type:	Gasoline
Status:	Active
Capacity:	25000
Tank Material:	Fiberglass (FRP)
Corrosion Protection:	Fiberglass
Tank Type:	Double Wall UST
Install Year:	1998
Parent Facility Type:	FS Gasoline Station - Card/Keylock
Facility Type:	FS Liquid Fuel Tank

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
FST	34	20 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST OTTAWA ON K1T 3W7

Instance No:	11550661
Cont Name:	
Instance Type:	FS Liquid Fuel Tank
Fuel Type:	Diesel
Status:	Active
Capacity:	25000
Tank Material:	Fiberglass (FRP)
Corrosion Protection:	Fiberglass
Tank Type:	Double Wall UST
Install Year:	1998
Parent Facility Type:	FS Gasoline Station - Card/Keylock
Facility Type:	FS Liquid Fuel Tank

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
FST	34	21 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST GLOUCESTER ON K1T 3W7

Instance No:	11476269
Cont Name:	
Instance Type:	FS Liquid Fuel Tank
Fuel Type:	Other
Status:	Active
Capacity:	4500
Tank Material:	Steel
Corrosion Protection:	Sacrificial anode
Tank Type:	Single Wall UST
Install Year:	1981
Parent Facility Type:	FS Gasoline Station - Full Serve
Facility Type:	FS Liquid Fuel Tank

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
FST	34	22 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST GLOUCESTER ON K1T 3W7

Instance No:	11589682
Cont Name:	
Instance Type:	FS Liquid Fuel Tank
Fuel Type:	Diesel
Status:	Active
Capacity:	25000
Tank Material:	Fiberglass (FRP)

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 1999
Parent Facility Type: FS Gasoline Station - Full Serve
Facility Type: FS Liquid Fuel Tank

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
FST	34	23 of 23	S/212.7	99.9 / -2.00	W.O. STINSON & SON LIMITED 4728 BANK ST GLOUCESTER ON K1T 3W7

Instance No: 11589676
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Gasoline
Status: Active
Capacity: 25000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 1999
Parent Facility Type: FS Gasoline Station - Full Serve
Facility Type: FS Liquid Fuel Tank

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
FSTH	17	19 of 35	S/114.7	100.0 / -1.86	W O STINSON & SONS LTD 4726 BANK ST GLOUCESTER ON K1T 3W7

License Issue Date: 9/27/2002
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Card/Keylock

--Details--
Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 25000

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

FSTH | **17** | ***20 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W.O. STINSON & SONS LTD***
4726 BANK ST
GLOUCESTER ON K1T 3W7

License Issue Date: 9/27/2002
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Card/Keylock

--Details--
Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

Status: Active
Year of Installation: 1998
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

FSTH | **21** | ***9 of 17*** | ***SSE/130.9*** | ***100.9 / -1.00*** | ***W O STINSON & SON LTD****
4727 BANK ST
GLOUCESTER ON K1T 3W7

License Issue Date: 9/3/2002
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Full Serve

--Details--
Status: Active
Year of Installation: 1999
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Year of Installation: 1999
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1999
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

Status: Active
Year of Installation: 1999
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Tank UST and Piping System (Conversion Only) - Diesel

Status: Active
Year of Installation: 1999
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Tank UST and Piping System (Conversion Only) - Gasoline

---

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
FSTH	***21***	***10 of 17***	***SSE/130.9***	***100.9 / -1.00***	***W O STINSON & SON LTD**** ***4727 BANK ST*** ***GLOUCESTER ON K1T 3W7***

License Issue Date: 9/3/2002
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Full Serve

--Details--
Status: Removed
Year of Installation: 1981
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Removed
Year of Installation: 1981
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Removed
Year of Installation: 1981
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Removed
Year of Installation: 1981
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Removed
Year of Installation: 1981
Corrosion Protection:
Capacity: 15000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Status: Removed
Year of Installation: 1981
Corrosion Protection:
Capacity: 4500
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	8	1 of 3	SSE/40.7	101.2 / -0.69	BRIAN McGUIRE 4695 BANK ST OTTAWA ON

Generator No: ON7704220
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 236110
SIC Description: Residential Building Construction

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	8	2 of 3	SSE/40.7	101.2 / -0.69	BRIAN McGUIRE 4695 BANK ST OTTAWA ON

Generator No: ON7704220
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 236110
SIC Description: Residential Building Construction

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	13	1 of 2	S/77.1	100.8 / -1.05	MDG DOOR SERVICE LTD. 4700 HIGHWAY 31 GLOUCESTER ON K1T 3W7

Generator No: ON2094700
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	13	2 of 2	S/77.1	100.8 / -1.05	MDG DOOR SERVICE LTD. 4700 HIGHWAY #31 GLOUCESTER ON K1T 3W7

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Generator No: ON2094700
Status:
Approval Years: 95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **17** | ***21 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W.O. STINSON & SONS LIMITED***
4726 BANK STREET
GLOUCESTER ON K1T 3W7

Generator No: ON1139501
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 412110
SIC Description: PETROLEUM PRODUCT WHOLESALER-DISTRIBUTORS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

GEN | **17** | ***22 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W.O. STINSON & SONS LIMITED***
4726 BANK STREET
GLOUCESTER ON K1T 3W7

Generator No: ON1139501
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 221 I
Waste Class Desc: Light fuels

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	17	23 of 35	S/114.7	100.0 / -1.86	W.O. STINSON & SONS LIMITED 4726 BANK STREET GLOUCESTER ON K1T 3W7

Generator No: ON1139501
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 412110
SIC Description: PETROLEUM PRODUCT WHOLESALER-DISTRIBUTORS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	17	24 of 35	S/114.7	100.0 / -1.86	W.O. STINSON & SONS LIMITED 4726 BANK STREET GLOUCESTER ON K1T 3W7

Generator No: ON1139501
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 412110
SIC Description: PETROLEUM PRODUCT WHOLESALER-DISTRIBUTORS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	17	25 of 35	S/114.7	100.0 / -1.86	W.O. STINSON & SONS LIMITED 4726 BANK STREET GLOUCESTER ON K1T 3W7

Generator No: ON1139501
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 412110
SIC Description: Petroleum Product Wholesaler-Distributors

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

GEN | **17** | ***26 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W.O. STINSON & SONS LIMITED***
4726 BANK STREET
GLOUCESTER ON K1T 3W7

Generator No: ON1139501
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 412110
SIC Description: Petroleum Product Wholesaler-Distributors

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **17** | ***27 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W.O. STINSON & SONS LIMITED***
4726 BANK STREET
GLOUCESTER ON K1T 3W7

Generator No: ON1139501
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 412110
SIC Description: Petroleum Product Wholesaler-Distributors

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **17** | ***28 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W.O. STINSON & SONS LIMITED***
4726 BANK STREET
GLOUCESTER ON K1T 3W7

Generator No: ON1139501
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

MHSW Facility: ***Phone No Admin:***
SIC Code:
SIC Description:

Detail(s)

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 221 I
Waste Class Desc: Light fuels

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

GEN **17** ***29 of 35*** ***S/114.7*** ***100.0 / -1.86*** ***W.O. STINSON & SONS LTD. 42-540***
4726 BANK STREET
GLOUCESTER ON K1G 3N4

Generator No: ON1139501 ***PO Box No:***
Status: ***Country:***
Approval Years: 92,93,94,95,96,97,98 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 4563
SIC Description: BULK LIQ. TRUCKING

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN **17** ***30 of 35*** ***S/114.7*** ***100.0 / -1.86*** ***W.O. STINSON & SONS LIMITED***
4726 BANK STREET
GLOUCESTER ON K1T 3W7

Generator No: ON1139501 ***PO Box No:***
Status: ***Country:***
Approval Years: 2009 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 412110
SIC Description: Petroleum Product Wholesaler-Distributors

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **17** | ***31 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W.O. STINSON & SONS LIMITED***
4726 BANK STREET
GLOUCESTER ON

Generator No: ON1139501
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 412110
SIC Description: PETROLEUM PRODUCT WHOLESALER-DISTRIBUTORS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

GEN | **17** | ***32 of 35*** | ***S/114.7*** | ***100.0 / -1.86*** | ***W.O. STINSON & SONS LIMITED***
4726 BANK STREET
GLOUCESTER ON K1G 3N4

Generator No: ON1139501
Status:
Approval Years: 99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 4563
SIC Description: BULK LIQ. TRUCKING

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **22** | ***9 of 14*** | ***SW/132.6*** | ***99.9 / -2.01*** | ***HOPE CEMETERY***
4660 BANK STREET
GLOUCESTER ON K1T 3W7

Generator No: ON2049100
Status:
Approval Years: 95,96,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4589
SIC Description: OTHER TRANS. IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **22** | ***10 of 14*** | ***SW/132.6*** | ***99.9 / -2.01*** | ***HOPE CEMETERY***
4660 BANK STREET KING'S HWY 31
GLOUCESTER ON K1T 3W7

Generator No: ON2049100
Status:
Approval Years: 02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **22** | ***11 of 14*** | ***SW/132.6*** | ***99.9 / -2.01*** | ***HOPE CEMETERY***
4660 BANK STREET
GLOUCESTER ON K1T 3W7

Generator No: ON2049100
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

GEN | **22** | ***12 of 14*** | ***SW/132.6*** | ***99.9 / -2.01*** | ***HOPE CEMETERY***
4660 BANK STREET KING'S HWY 31
GLOUCESTER ON K1T 3W7

Generator No: ON2049100
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 812220
SIC Description: Cemeteries and Crematoria

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **22** | ***13 of 14*** | ***SW/132.6*** | ***99.9 / -2.01*** | ***HOPE CEMETERY***
4660 BANK STREET
GLOUCESTER ON K1T 3W7

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Generator No: ON2049100
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

GEN | **22** | ***14 of 14*** | ***SW/132.6*** | ***99.9 / -2.01*** | ***HOPE CEMETERY***
4660 BANK STREET KING'S HWY 31
GLOUCESTER ON K1T 3W7

Generator No: ON2049100
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 812220
SIC Description: Cemeteries and Crematoria
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **23** | ***1 of 1*** | ***NNW/150.2*** | ***102.8 / 0.93*** | ***Valley Squire Furniture***
4599 Bank St
Ottawa ON K1T 3W8

Generator No: ON5531328
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 442298
SIC Description: All Other Home Furnishings Stores
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

GEN | **36** | ***3 of 5*** | ***NNW/244.8*** | ***103.9 / 2.00*** | ***GLOUCESTER HYDRO***
4565 BANK STREET
GLOUCESTER ON K1G 4C1

Generator No: ON0483800
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4911
SIC Description: ELECT. POWER SYS.
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	36	4 of 5	NNW/244.8	103.9 / 2.00	Hydro Ottawa Ltd. 4565 BANK STREET GLOUCESTER ON K1G 4C1

Generator No: ON0483800
Status:
Approval Years: 02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

GEN **36** ***5 of 5*** ***NNW/244.8*** ***103.9 / 2.00***

GLOUCESTER HYDRO 17-066
4565 BANK STREET
GLOUCESTER ON K1G 4C1

Generator No: ON0483800
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 4911
SIC Description: ELECT. POWER SYS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

GEN **38** ***6 of 25*** ***NNW/247.5*** ***104.4 / 2.54***

Hydro Ottawa Ltd.
4565 BANK STREET
GLOUCESTER ON K1T 3W6

Generator No: ON0483800
Status:
Approval Years: 2010

PO Box No:
Country:
Choice of Contact:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 221122
SIC Description: Electric Power Distribution

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	**38**	***7 of 25***	***NNW/247.5***	***104.4 / 2.54***	***Hydro Ottawa Ltd.*** ***4565 BANK STREET*** ***GLOUCESTER ON K1T 3W6***

Generator No: ON0483800 ***PO Box No:***
Status: ***Country:***
Approval Years: 2011 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 221122
SIC Description: Electric Power Distribution

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	38	8 of 25	NNW/247.5	104.4 / 2.54	Hydro Ottawa Ltd. 4565 BANK STREET GLOUCESTER ON K1T 3W6

Generator No: ON0483800
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 221122, 232510
SIC Description: Electric Power Distribution

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

GEN | 38 | *9 of 25* | *NNW/247.5* | *104.4 / 2.54* | ***GLOUCESTER HYDRO P.O. BOX 9800 4565 BANK STREET GLOUCESTER ON K1T 3W6***

Generator No: ON0483800
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:
SIC Code: 4911
SIC Description: ELECT. POWER SYS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

GEN | 38 | *10 of 25* | *NNW/247.5* | *104.4 / 2.54* | ***Hydro Ottawa Ltd. 4565 BANK STREET GLOUCESTER ON K1G 4C1***

Generator No: ON0483800
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 221122
SIC Description: ELECTRIC POWER DISTRIBUTION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	38	11 of 25	NNW/247.5	104.4 / 2.54	Hydro Ottawa Ltd. 4565 BANK STREET GLOUCESTER ON K1T 3W6

Generator No: ON0483800
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 221122
SIC Description: Electric Power Distribution

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	38	12 of 25	NNW/247.5	104.4 / 2.54	Hydro Ottawa Ltd.

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
					4565 BANK STREET GLOUCESTER ON

Generator No: ON0483800
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 221122
SIC Description: ELECTRIC POWER DISTRIBUTION

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 243
Waste Class Desc: PCBS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
GEN	38	13 of 25	NNW/247.5	104.4 / 2.54	Hydro Ottawa Ltd. 4565 BANK STREET GLOUCESTER ON K1G 4C1

Generator No: ON0483800
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 221122
SIC Description: ELECTRIC POWER DISTRIBUTION

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Joel Stairs
Phone No Admin: 613-738-5499 Ext.7612

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

GEN | **38** | ***14 of 25*** | ***NNW/247.5*** | ***104.4 / 2.54*** | ***Hydro Ottawa Ltd.***
4565 BANK STREET
GLOUCESTER ON K1G 4C1

Generator No: ON0483800
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 121 C
Waste Class Desc: Alkaline slutions - containing heavy metals

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 212 I
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 221 L

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Waste Class Desc: Light fuels

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

GEN | **38** | ***15 of 25*** | ***NNW/247.5*** | ***104.4 / 2.54*** | ***Hydro Ottawa Ltd.***
4565 BANK STREET
GLOUCESTER ON K1G 4C1

Generator No: ON0483800
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 212 I
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 121 C
Waste Class Desc: Alkaline slutions - containing heavy metals

Waste Class: 221 L
Waste Class Desc: Light fuels

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

GEN | **38** | ***16 of 25*** | ***NNW/247.5*** | ***104.4 / 2.54*** | ***Hydro Ottawa Ltd.***
4565 BANK STREET
GLOUCESTER ON K1G 4C1

Generator No: ON0483800
Status:

PO Box No:
Country: Canada

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 221122
SIC Description: ELECTRIC POWER DISTRIBUTION

Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 243
Waste Class Desc: PCBS

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
INC	7	1 of 2	SSE/39.3	101.2 / -0.69	4695 BANK STREET, OTTAWA ON

Incident No: 188540
Incident ID: 2339474
Attribute Category: FS-Perform L1 Incident Insp
Status Code: Causal Analysis Complete
Incident Location: 4695 BANK STREET, OTTAWA - LEAK
Drainage System: Unknown
Sub Surface Contam.: unknown
Aff. Prop. Use Water: No
Contam. Migrated: Unknown
Contact Natural Env.: Unknown
Near Body of Water: Unknown
Approx. Quant. Rel.: unknown
Equipment Model:
Serial No:
Residential App. Type:
Commercial App. Type:
Industrial App. Type:
Institutional App. Type:
Venting Type:
Vent Connector Mater:
Vent Chimney Mater:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Pipeline Type:
Pipeline Involved:
Pipe Material:
Depth Ground Cover:
Regulator Location:
Regulator Type:
Operation Pressure:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Equipment Type:
Cylinder Capacity:
Cylinder Capac. Units:
Cylinder Material Type:
Tank Capacity:
Fuels Occurence Type: Discovery of a Petroleum Product
Fuel Type Involved: Fuel Oil
Date of Occurence: 2009/09/18 00:00:00
Time of Occurence: NULL
Occur Insp Start Date: 2009/09/21 00:00:00
Any Health Impact: No
Any Environmental Impact: Unknown
Was Service Interrupted: Yes
Was Property Damaged: Yes
Operation Type Involved: Private Dwelling
Enforcement Policy: NULL
Prc Escalation Required: NULL
Task No: 2417419
Notes:
Occurence Narrative: NULL
Tank Material Type:
Tank Storage Type:
Tank Location Type:
Pump Flow Rate Capac:
Liquid Prop Notes:

INC	***7***	***2 of 2***	***SSE/39.3***	***101.2 / -0.69***	***4695 Bank Street, Ottawa ON***

Incident No: 704172
Incident ID: 2861112
Attribute Category: FS-Perform L1 Incident Insp
Status Code: Causal Analysis Complete
Incident Location: 4695 Bank Street, Ottawa - Leak
Drainage System: Unknown
Sub Surface Contam.:
Aff. Prop. Use Water: Unknown
Contam. Migrated: Unknown
Contact Natural Env.: Unknown
Near Body of Water: No
Approx. Quant. Rel.: unknown
Equipment Model:
Serial No:
Residential App. Type:
Commercial App. Type:
Industrial App. Type:
Institutional App. Type:
Venting Type:
Vent Connector Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Depth Ground Cover:
Regulator Location:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Regulator Type:
Operation Pressure:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Equipment Type:
Cylinder Capacity:
Cylinder Capac. Units:
Cylinder Material Type:
Tank Capacity:
Fuels Occurence Type: Leak
Fuel Type Involved: Fuel Oil
Date of Occurence: 2011/12/13 00:00:00
Time of Occurence: NULL
Occur Insp Start Date: 2011/12/13 00:00:00
Any Health Impact: No
Any Environmental Impact: Unknown
Was Service Interrupted: Yes
Was Property Damaged: Yes
Operation Type Involved: Private Dwelling
Enforcement Policy: NULL
Prc Escalation Required: NULL
Task No: 3651378
Notes:
Occurence Narrative: NULL
Tank Material Type:
Tank Storage Type:
Tank Location Type:
Pump Flow Rate Capac:
Liquid Prop Notes:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
NPCB	38	***17 of 25***	***NNW/247.5***	***104.4 / 2.54***	***GLOUCESTER HYDRO 4565 BANK STREET GLOUCESTER ON K1T 3W6***

Company Code: F1482
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
NPCB	38	***18 of 25***	***NNW/247.5***	***104.4 / 2.54***	***HYDRO OTTAWA 4565 BANK STREET GLOUCESTER ON K1T 3W6***

Company Code: O005066
Industry: UTILITY
Site Status:
Transaction Date:
Inspection Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
NPCB	38	***19 of 25***	***NNW/247.5***	***104.4 / 2.54***	***GLOUCESTER HYDRO 4565 BANK STREET GLOUCESTER ON K1T 3W6***

Company Code: F1326
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
OPCB	38	20 of 25	NNW/247.5	104.4 / 2.54	GLOUCESTER HYDRO 4565 BANK STREET GLOUCESTER ON K1T 3W6

Year: 2000
Site Number: 40288A228
Name Owner:
Additional Site Information:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
OPCB	38	21 of 25	NNW/247.5	104.4 / 2.54	GLOUCESTER HYDRO 4565 BANK STREET GLOUCESTER ON K1T 3W6

Year: 2003
Site Number: 40288A228
Name Owner:
Additional Site Information:

--Details--
Quantity: 4.00
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
OPCB	38	22 of 25	NNW/247.5	104.4 / 2.54	GLOUCESTER HYDRO 4565 BANK STREET GLOUCESTER ON K1T 3W6

Year: 1998
Site Number: 40288A228
Name Owner:
Additional Site Information:

--Details--
Quantity: 1000.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 2.00
Address Site:
Description: Number of Capacitors with High Level PCBs (>1000 ppm)

Quantity: 2.00
Address Site:
Description: Number of Drums of Soil with High Level PCBs (>1000 ppm)

Quantity: 800.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Soil with High Level PCBs (>1000 ppm)

Quantity: 6.00
Address Site:
Description: Number of Drums of Other Material with High Level PCBs (>1000 ppm)

Quantity: 900.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Other Material with High Level PCBs (>1000 ppm) kg

Quantity: 59.00
Address Site:

Description: Weight of Liquid in Transformer with High Level PCBs (>1000 ppm) kg

Quantity: 5.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

OPCB | 38 | **23 of 25** | **NNW/247.5** | **104.4 / 2.54** | **GLOUCESTER HYDRO 4565 BANK STREET GLOUCESTER ON K1T 3W6**

Year: 1999
Site Number: 40288A228
Name Owner:
Additional Site Information:

OPCB | 38 | **24 of 25** | **NNW/247.5** | **104.4 / 2.54** | **GLOUCESTER HYDRO 4565 BANK STREET GLOUCESTER ON K1T 3W6**

Year: 1995
Site Number: 40288A228
Name Owner:
Additional Site Information:

--Details--
Quantity: 77.00
Address Site:
Description: Weight of Liquid in Transformer with High Level PCBs (>1000 ppm) kg

Quantity: 5.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 1000.00
Address Site:
Description: Weight of Drums of Ballasts with High Level PCBs (>1000 ppm) kg

Quantity: 2.00
Address Site:
Description: Number of Capacitors with High Level PCBs (>1000 ppm)

Quantity: 2.00
Address Site:
Description: Number of Drums of Soil with High Level PCBs (>1000 ppm)

Quantity: 800.00
Address Site:
Description: Weight of Drums of Soil with High Level PCBs (>1000 ppm) kg

Quantity: 5.00
Address Site:
Description: Number of Drums of Other Material with High Level PCBs (>1000 ppm)

Quantity: 750.00
Address Site:
Description: Weight of Drums of Other Material with High Level PCBs (>1000 ppm) kg

Quantity: 2761.00
Address Site:
Description: Weight of Bulk Liquid with Low Level PCBs (< 1000 ppm) kg

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
PES	18	1 of 4	NW/122.0	101.9 / 0.00	KNIPPEL PETER NURSERY INC. 4590 BANK ST., R.R. #6 GLOUCESTER ON K1T 3W6

Detail Licence No:		Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	Vendor	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF Link:			

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
PES	18	2 of 4	NW/122.0	101.9 / 0.00	KNIPPEL PETER NURSERY INC 4590 BANK ST GLOUCESTER ON K1T3W6

Detail Licence No:		Operator Box:	
Licence No:	08142	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:	Legacy Licenses (Excluding TS)	Oper Area Code:	613
Licence Type:	Limited Vendor	Oper Phone No:	8220383
Licence Type Code:	23	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF Link:			

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
PES	18	3 of 4	NW/122.0	101.9 / 0.00	KNIPPEL PETER NURSERY INC 4590 BANK ST GLOUCESTER ON K1T3W6

Detail Licence No:		Operator Box:	
Licence No:	08142	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:	Legacy Licenses (Excluding TS)	Oper Area Code:	613
Licence Type:	Retail Vendor Class 03	Oper Phone No:	8220383
Licence Type Code:	21	Operator Ext:	
Licence Class:	03	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Concession:
Region:
District:
County:
Trade Name:
PDF Link:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

PES | 18 | 4 of 4 | NW/122.0 | 101.9 / 0.00 | KNIPPEL PETER NURSERY INC
4590 BANK ST
GLOUCESTER ON K1T 3W6

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

PRT | 21 | 11 of 17 | SSE/130.9 | 100.9 / -1.00 | W O STINSON & SON LTD
4727 BANK ST HWY 31
LEITRIM ON

Location ID: 7618
Type: retail
Expiry Date: 1995-07-31
Capacity (L): 2000
Licence #: 0033092001

PRT | 21 | 12 of 17 | SSE/130.9 | 100.9 / -1.00 | 4727 BANK ST.
GLOUCESTER ON

Location ID: 5267
Type: retail
Expiry Date:
Capacity (L):
Licence #:

PRT | 21 | 13 of 17 | SSE/130.9 | 100.9 / -1.00 | W O STINSON & SON LTD
4727 BANK ST HWY 31
LEITRIM ON K1T 3W7

Location ID: 7618
Type: private
Expiry Date:
Capacity (L): 190000.00
Licence #: 0001016854

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
PRT	21	14 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SON LTD 4727 BANK ST HWY 31 LEITRIM ON K1T 3W7

Location ID: 7618
Type: retail
Expiry Date: 1995-07-31
Capacity (L): 0
Licence #: 0050465001

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
RST	17	33 of 35	S/114.7	100.0 / -1.86	STINSON W O & SON LTD 4726 BANK ST GLOUCESTER ON K1T 3W7

Headcode: 01070510
Headcode Desc: PROPANE GAS-SALES & SERVICE
Phone:
List Name:
Description:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
RST	17	34 of 35	S/114.7	100.0 / -1.86	STINSON W O & SON LTD 4726 BANK ST GLOUCESTER ON K1T3W7

Headcode: 00924800
Headcode Desc: FUEL OIL
Phone: 6138227400
List Name:
Description:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
RST	21	15 of 17	SSE/130.9	100.9 / -1.00	W O STINSON & SONS LTD 4727 BANK ST GLOUCESTER ON K1T3W7

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 6138221749
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
SPL	8	3 of 3	SSE/40.7	101.2 / -0.69	Blue Wave Energy Limited Partnership 4695 Bank St. Ottawa ON

Ref No: 6064-7VZTRA
Site No:
Incident Dt:
Year:
Incident Cause: Tank (Above Ground) Leak
Incident Event:
Contaminant Code: 13
Contaminant Name: FURNACE OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:	Referral to others	***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	9/18/2009	***Site Map Datum:***	
Dt Document Closed:	2/9/2010	***SAC Action Class:***	TSSA - Fuel Safety Branch
Incident Reason:	Equipment Failure	***Source Type:***	
Site Name:	Residence<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Blue Wave: ~ 454L furn oil to cement bsmt floor		
Contaminant Qty:	454 L		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
SPL	17	***35 of 35***	***S/114.7***	***100.0 / -1.86***	***Stinson WO & Sons Ltd.<UNOFFICIAL>*** ***4726 Bank Street, Gloucester*** ***Ottawa ON***

Ref No:	4476-5PAN6U	***Discharger Report:***	
Site No:		***Material Group:***	Oil
Incident Dt:	7/9/2003	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Container Leak (Fuel Tank Barrels)	***Sector Type:***	Tank Truck
Incident Event:		***Agency Involved:***	
Contaminant Code:	13	***Nearest Watercourse:***	
Contaminant Name:	FUEL OIL	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Ottawa
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	Eastern
Environment Impact:	Possible	***Site Municipality:***	Ottawa
Nature of Impact:	Soil Contamination	***Site Lot:***	
Receiving Medium:	Land	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	7/9/2003	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Spill to Land
Incident Reason:	Equipment Failure - Malfunction of system components	***Source Type:***	
Site Name:	STINSON FUEL<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TSSA: fuel oil spill from missing cap on tanker		
Contaminant Qty:	25 L		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
SPL	21	***16 of 17***	***SSE/130.9***	***100.9 / -1.00***	***W. O. Stinson & Son Limited*** ***4727 Bank St*** ***Ottawa ON***

Ref No:	8344-ACEJU9	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2016/08/01	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:		***Sector Type:***	Unknown / N/A
Incident Event:	Leak/Break	***Agency Involved:***	
Contaminant Code:	13	***Nearest Watercourse:***	
Contaminant Name:	DIESEL FUEL	***Site Address:***	4727 Bank St
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	Ottawa
Nature of Impact:		***Site Lot:***	

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Receiving Medium:		**Site Conc:**	
Receiving Env:	Land	**Northing:**	5019220
MOE Response:	No	**Easting:**	453319
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2016/08/01	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:	Equipment Failure	**Source Type:**	
Site Name:	W O Stinson<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	W O Stinson: spill diesel, cleaning		
Contaminant Qty:	75 L		

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
SPL	21	17 of 17	SSE/130.9	100.9 / -1.00	PRIVATE RESIDENCE AT RESIDENCE BESIDE 4727 BANK ST. FURNACE OIL TANK GLOUCESTER CITY ON K1T 3W7

Ref No:	98228	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	4/6/1994	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	UNDERGROUND TANK LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	CONFIRMED	**Site Municipality:**	20105
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/6/1994	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	RESIDENCE - UNKNOWN AMOUNT OF FURNACE OIL TO GROUND FROM TANK.		
Contaminant Qty:			

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
SPL	38	25 of 25	NNW/247.5	104.4 / 2.54	Hydro Ottawa Limited 4565 Bank St. Ottawa ON

Ref No:	1552-9BHHZR	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2013/09/06	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Leak/Break	**Sector Type:**	Tank - Underground
Incident Event:		**Agency Involved:**	
Contaminant Code:	44	**Nearest Watercourse:**	
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	**Site Address:**	4565 Bank St.
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Ottawa
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2013/09/13	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:	Equipment Failure	**Source Type:**	
Site Name:	4565 Bank St.<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Hydro Ottawa: Raw swg to drainage pit		
Contaminant Qty:	0 other - see incident description		

WWIS	**1**	***2 of 2***	***-/0.0***	***101.9 / 0.00***	***lot 17 con 5 ON***

Well ID:	1502242	**Data Entry Status:**	
Construction Date:		**Data Src:**	1
Primary Water Use:	Domestic	**Date Received:**	5/17/1966
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Water Supply	**Abandonment Rec:**	
Water Type:		**Contractor:**	3601
Casing Material:		**Form Version:**	1
Audit No:		**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	OTTAWA-CARLETON
Elevation (m):		**Municipality:**	GLOUCESTER TOWNSHIP
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	017
Well Depth:		**Concession:**	05
Overburden/Bedrock:		**Concession Name:**	RF
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	10024285	**Elevation:**	104.107398
DP2BR:	5	**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	r	**East83:**	453210.7
Code OB Desc:	Bedrock	**North83:**	5019452
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	3/15/1966	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930994010
Layer:	1
Color:	
General Color:	
Mat1:	05
Most Common Material:	CLAY
Mat2:	13

Other Materials: BOULDERS
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930994011
Layer: 2
Color:
General Color:
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 5
Formation End Depth: 43
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572855
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041350
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 23
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930041351
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 43
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Results of Well Yield Testing

Pump Test ID:	991502242
Pump Set At:	
Static Level:	4
Final Level After Pumping:	10
Recommended Pump Depth:	26
Pumping Rate:	5
Flowing Rate:	
Recommended Pump Rate:	5
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	N

Water Details

Water ID:	933454995
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	40
Water Found Depth UOM:	ft

WWIS	2	***1 of 1***	***-/0.0***	***101.2 / -0.69***	***lot 17 con 5 ON***

Well ID:	1502240	***Data Entry Status:***	
Construction Date:		***Data Src:***	1
Primary Water Use:	Domestic	***Date Received:***	12/3/1963
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Water Supply	***Abandonment Rec:***	
Water Type:		***Contractor:***	3701
Casing Material:		***Form Version:***	1
Audit No:		***Owner:***	
Tag:		***Street Name:***	
Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	GLOUCESTER TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	017
Well Depth:		***Concession:***	05
Overburden/Bedrock:		***Concession Name:***	RF
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	10024283	***Elevation:***	104.027519
DP2BR:	15	***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:	r	***East83:***	453230.7
Code OB Desc:	Bedrock	***North83:***	5019382
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	9/15/1963	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 930994007
Layer: 2
Color: 6
General Color: BROWN
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 15
Formation End Depth: 130
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930994006
Layer: 1
Color:
General Color:
Mat1: 03
Most Common Material: MUCK
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 15
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572853
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041347
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:

Depth To:	130
Casing Diameter:	6
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930041346
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	20
Casing Diameter:	6
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pump Test ID:	991502240
Pump Set At:	
Static Level:	10
Final Level After Pumping:	90
Recommended Pump Depth:	110
Pumping Rate:	4
Flowing Rate:	
Recommended Pump Rate:	3
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	2
Pumping Duration MIN:	0
Flowing:	N

Water Details

Water ID:	933454993
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	100
Water Found Depth UOM:	ft

WWIS **3** ***1 of 1*** ***-/0.0*** ***101.3 / -0.57*** ***lot 17 con 5 ON***

Well ID:	1502239	***Data Entry Status:***	
Construction Date:		***Data Src:***	1
Primary Water Use:	Domestic	***Date Received:***	12/7/1962
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Water Supply	***Abandonment Rec:***	
Water Type:		***Contractor:***	3701
Casing Material:		***Form Version:***	1
Audit No:		***Owner:***	
Tag:		***Street Name:***	
Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	GLOUCESTER TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	017
Well Depth:		***Concession:***	05
Overburden/Bedrock:		***Concession Name:***	RF

Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	10024282	***Elevation:***	104.00267
DP2BR:	14	***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:	r	***East83:***	453250.7
Code OB Desc:	Bedrock	***North83:***	5019342
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	8/19/1962	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930994005
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	14
Formation End Depth:	150
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930994004
Layer:	1
Color:	
General Color:	
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	14
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	1

Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572852
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041344
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 20
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930041345
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 150
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502239
Pump Set At:
Static Level: 20
Final Level After Pumping: 100
Recommended Pump Depth: 120
Pumping Rate: 4
Flowing Rate:
Recommended Pump Rate: 4
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: N

Water Details

Water ID: 933454992
Layer: 3
Kind Code: 1
Kind: FRESH
Water Found Depth: 150
Water Found Depth UOM: ft

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Water Details

Water ID:	933454991
Layer:	2
Kind Code:	1
Kind:	FRESH
Water Found Depth:	140
Water Found Depth UOM:	ft

Water Details

Water ID:	933454990
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	110
Water Found Depth UOM:	ft

WWIS **5** ***1 of 1*** ***S/31.7*** ***100.8 / -1.05*** ***Ottawa ON***

Well ID:	7133780	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	11/13/2009
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	0	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	7
Audit No:	Z104752	***Owner:***	
Tag:	A081024	***Street Name:***	4695 BANK ST. W.
Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	OTTAWA CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1002815934	***Elevation:***	103.980323
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	453256
Code OB Desc:		***North83:***	5019298
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/29/2009	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID: 1003008146
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Other Materials:
Mat3: 66
Other Materials: DENSE
Formation Top Depth: 15
Formation End Depth: 16
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003008145
Layer: 2
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Other Materials:
Mat3: 66
Other Materials: DENSE
Formation Top Depth: 8
Formation End Depth: 15
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003008144
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 12
Other Materials: STONES
Mat3: 68
Other Materials: DRY
Formation Top Depth: 0
Formation End Depth: 8
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003008148
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003008149
Layer: 2
Plug From: 1

Plug To: 10
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003008150
Layer: 3
Plug From: 10
Plug To: 16
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1003008143
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003008152
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 11
Casing Diameter: 1
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003008153
Layer: 1
Slot: 10
Screen Top Depth: 11
Screen End Depth: 16
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.25

Hole Diameter

Hole ID: 1003008147
Diameter: 2.25
Depth From: 0
Depth To: 16
Hole Depth UOM: ft
Hole Diameter UOM: inch

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
WWIS	6	1 of 1	SSE/37.6	101.4 / -0.46	Ottawa ON

Well ID:	7133796	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	11/13/2009
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z104893	**Owner:**	
Tag:	A090896	**Street Name:**	4635 BANK STREET
Construction Method:		**County:**	OTTAWA-CARLETON
Elevation (m):		**Municipality:**	OTTAWA CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1002816093	**Elevation:**	103.629905
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	453288
Code OB Desc:		**North83:**	5019310
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	9/29/2009	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003008689
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	05
Other Materials:	CLAY
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	4
Formation End Depth:	8
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003008690
Layer:	3

Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3: 66
Other Materials: DENSE
Formation Top Depth: 8
Formation End Depth: 11.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003008688
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Other Materials: GRAVEL
Mat3: 66
Other Materials: DENSE
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003008693
Layer: 2
Plug From: 3
Plug To: 11.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003008692
Layer: 1
Plug From: 0
Plug To: 3
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1003008687
Casing No: 0
Comment:
Alt Name:

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site

Construction Record - Casing

Casing ID:	1003008695
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	4
Casing Diameter:	1.36
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003008696
Layer:	1
Slot:	10
Screen Top Depth:	4
Screen End Depth:	11.5
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.66

Hole Diameter

Hole ID:	1003008691
Diameter:	2.25
Depth From:	0
Depth To:	11.5
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

WWIS	***9***	***1 of 1***	***NNW/45.2***	***102.2 / 0.31***	***lot 16 con 5 OTTAWA ON***

Well ID:	7170843	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Not Used	***Date Received:***	11/1/2011
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	7260
Casing Material:		***Form Version:***	7
Audit No:	Z128687	***Owner:***	
Tag:		***Street Name:***	4629 BANK ST.
Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	GLOUCESTER TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	016
Well Depth:		***Concession:***	05
Overburden/Bedrock:		***Concession Name:***	RF
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003593474	***Elevation:***	104.454582
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	453170

Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 9/28/2011
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
North83: 5019539
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1003997425
Layer: 2
Plug From: 30
Plug To: 98
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003997424
Layer: 1
Plug From: 0
Plug To: 30
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 1003997416
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003997420
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003997421
Layer:
Slot:

Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1003997418
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

WWIS **12** ***1 of 1*** ***SSE/60.8*** ***100.9 / -1.00*** ***Ottawa ON***

Well ID: 7133779
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: Z104724
Tag: A081025
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 11/13/2009
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 4695 BANK ST. WEST
County: OTTAWA-CARLETON
Municipality: OTTAWA CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1002815931
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/29/2009
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 103.942932
Elevrc:
Zone: 18
East83: 453276
North83: 5019276
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1003008090
Layer: 2

Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3:
Other Materials:
Formation Top Depth: 8
Formation End Depth: 15
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003008089
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 26
Other Materials: ROCK
Mat3: 68
Other Materials: DRY
Formation Top Depth: 0
Formation End Depth: 8
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003008092
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003008093
Layer: 2
Plug From: 1
Plug To: 9
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003008094
Layer: 3
Plug From: 9
Plug To: 15
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID:	1003008088
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003008096
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	10
Casing Diameter:	1
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003008097
Layer:	1
Slot:	10
Screen Top Depth:	10
Screen End Depth:	15
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.25

Hole Diameter

Hole ID:	1003008091
Diameter:	2.25
Depth From:	0
Depth To:	15
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

WWIS **16** ***1 of 1*** ***SSW/94.8*** ***99.9 / -2.00*** ***lot 17 con 4 ON***

Well ID:	1502171	***Data Entry Status:***	
Construction Date:		***Data Src:***	1
Primary Water Use:	Domestic	***Date Received:***	1/4/1954
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Water Supply	***Abandonment Rec:***	
Water Type:		***Contractor:***	3113
Casing Material:		***Form Version:***	1
Audit No:		***Owner:***	
Tag:		***Street Name:***	
Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	GLOUCESTER TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	017
Well Depth:		***Concession:***	04
Overburden/Bedrock:		***Concession Name:***	RF
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	10024214	***Elevation:***	102.459541
DP2BR:	0	***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:	h	***East83:***	453190.7
Code OB Desc:	Mixed in a Layer	***North83:***	5019242
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	7/31/1953	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930993823
Layer:	1
Color:	
General Color:	
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	17
Other Materials:	SHALE
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	16
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930993824
Layer:	2
Color:	
General Color:	
Mat1:	26
Most Common Material:	ROCK
Mat2:	17
Other Materials:	SHALE
Mat3:	
Other Materials:	
Formation Top Depth:	16
Formation End Depth:	229
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID: 10572784
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041213
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 229
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930041212
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 16
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502171
Pump Set At:
Static Level: 14
Final Level After Pumping: 220
Recommended Pump Depth:
Pumping Rate: 1
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 10
Flowing: N

Water Details

Water ID: 933454912
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 150
Water Found Depth UOM: ft

WWIS | ***19*** | ***1 of 1*** | ***NNW/122.8*** | ***102.9 / 1.00*** | ***lot 16 con 5 ON***

Well ID: 1502237
Construction Date:
Data Entry Status:
Data Src: 1

Primary Water Use:	Domestic	**Date Received:**	8/15/1961
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Water Supply	**Abandonment Rec:**	
Water Type:		**Contractor:**	3113
Casing Material:		**Form Version:**	1
Audit No:		**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	OTTAWA-CARLETON
Elevation (m):		**Municipality:**	GLOUCESTER TOWNSHIP
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	016
Well Depth:		**Concession:**	05
Overburden/Bedrock:		**Concession Name:**	RF
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	10024280	**Elevation:**	104.87854
DP2BR:	0	**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	r	**East83:**	453140.7
Code OB Desc:	Bedrock	**North83:**	5019612
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	7/3/1961	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930993999
Layer:	1
Color:	
General Color:	
Mat1:	26
Most Common Material:	ROCK
Mat2:	17
Other Materials:	SHALE
Mat3:	05
Other Materials:	CLAY
Formation Top Depth:	0
Formation End Depth:	16
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930994000
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	26
Most Common Material:	ROCK
Mat2:	

Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 16
Formation End Depth: 105
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572850
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041341
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 105
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930041340
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502237
Pump Set At:
Static Level: 3
Final Level After Pumping: 5
Recommended Pump Depth: 40
Pumping Rate: 7
Flowing Rate:
Recommended Pump Rate: 6
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0

Flowing: N

Water Details

Water ID: 933454988
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 105
Water Found Depth UOM: ft

WWIS 20 **2 of 2** **S/125.0** **99.9 / -2.00** **lot 17 con 4 ON**

Well ID: 1502170
Construction Date:
Primary Water Use: Not Used
Sec. Water Use: 0
Final Well Status: Abandoned-Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 4/9/1954
Selected Flag: Yes
Abandonment Rec:
Contractor: 3113
Form Version: 1
Owner:
Street Name:
County: OTTAWA-CARLETON
Municipality: GLOUCESTER TOWNSHIP
Site Info:
Lot: 017
Concession: 04
Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10024213
DP2BR: 0
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 7/24/1953
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 102.807319
Elevrc:
Zone: 18
East83: 453210.7
North83: 5019202
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 930993821
Layer: 1
Color:
General Color:
Mat1: 17
Most Common Material: SHALE
Mat2: 02

Other Materials: TOPSOIL
Mat3: 11
Other Materials: GRAVEL
Formation Top Depth: 0
Formation End Depth: 16
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930993822
Layer: 2
Color: 8
General Color: BLACK
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 16
Formation End Depth: 255
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572783
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041211
Layer: 1
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502170
Pump Set At:
Static Level: 14
Final Level After Pumping: 225
Recommended Pump Depth:
Pumping Rate: 0
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM

Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	24
Pumping Duration MIN:	0
Flowing:	N

Water Details

Water ID:	933454911
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	100
Water Found Depth UOM:	ft

WWIS 24 | **2 of 2** | **NE/168.3** | **102.4 / 0.54** | **lot 17 con 5 ON**

Well ID:	1502241	**Data Entry Status:**	
Construction Date:		**Data Src:**	1
Primary Water Use:	Domestic	**Date Received:**	1/19/1965
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Water Supply	**Abandonment Rec:**	
Water Type:		**Contractor:**	1504
Casing Material:		**Form Version:**	1
Audit No:		**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	OTTAWA-CARLETON
Elevation (m):		**Municipality:**	GLOUCESTER TOWNSHIP
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	017
Well Depth:		**Concession:**	05
Overburden/Bedrock:		**Concession Name:**	RF
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	10024284	**Elevation:**	103.882324
DP2BR:	0	**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	r	**East83:**	453390.7
Code OB Desc:	Bedrock	**North83:**	5019592
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	8/14/1964	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930994009
Layer:	2

Color: 6
General Color: BROWN
Mat1: 19
Most Common Material: SLATE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 8
Formation End Depth: 70
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930994008
Layer: 1
Color: 6
General Color: BROWN
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 8
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572854
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041349
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 70
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930041348
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:

Depth To:	30
Casing Diameter:	5
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pump Test ID:	991502241
Pump Set At:	
Static Level:	4
Final Level After Pumping:	60
Recommended Pump Depth:	60
Pumping Rate:	6
Flowing Rate:	
Recommended Pump Rate:	6
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	2
Pumping Duration MIN:	0
Flowing:	N

Water Details

Water ID:	933454994
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	70
Water Found Depth UOM:	ft

WWIS **25** ***1 of 1*** ***WSW/175.7*** ***99.7 / -2.14*** ***Ottawa ON***

Well ID:	7227708	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	9/19/2014
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	7238
Casing Material:		***Form Version:***	7
Audit No:	Z180973	***Owner:***	
Tag:	A157521	***Street Name:***	4660 BANK ST.
Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	GLOUCESTER TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005128919	***Elevation:***	100.227943
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	453044

Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 7/4/2014
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
North83: 5019342
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005378955
Layer: 1
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Other Materials: SAND
Mat3: 05
Other Materials: CLAY
Formation Top Depth: 0
Formation End Depth: 15
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005378962
Layer: 1
Plug From: 0
Plug To: 4
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: F
Method Construction: H.S.A.
Other Method Construction:

Pipe Information

Pipe ID: 1005378954
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005378958
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 5
Casing Diameter: 2
Casing Diameter UOM: inch

Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005378959
Layer: 1
Slot: 10
Screen Top Depth: 5
Screen End Depth: 10
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Hole Diameter

Hole ID: 1005378956
Diameter: 8
Depth From: 0
Depth To: 15
Hole Depth UOM: ft
Hole Diameter UOM: inch

WWIS **26** ***1 of 1*** ***NNW/179.3*** ***103.2 / 1.31*** ***lot 16 con 5 ON***

Well ID: 1502238
Construction Date:
Primary Water Use: Commerical
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 5/17/1966
Selected Flag: Yes
Abandonment Rec:
Contractor: 1503
Form Version: 1
Owner:
Street Name:
County: OTTAWA-CARLETON
Municipality: GLOUCESTER TOWNSHIP
Site Info:
Lot: 016
Concession: 05
Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10024281
DP2BR: 19
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 2/28/1966
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Elevation: 104.953674
Elevrc:
Zone: 18
East83: 453130.7
North83: 5019672
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 930994001
Layer: 1
Color:
General Color:
Mat1: 23
Most Common Material: PREVIOUSLY DUG
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 11
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930994002
Layer: 2
Color:
General Color:
Mat1: 09
Most Common Material: MEDIUM SAND
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 11
Formation End Depth: 19
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 930994003
Layer: 3
Color:
General Color:
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 19
Formation End Depth: 62
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572851
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041342
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 15
Casing Diameter: 8
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930041343
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 62
Casing Diameter: 8
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502238
Pump Set At:
Static Level: 4
Final Level After Pumping: 25
Recommended Pump Depth: 30
Pumping Rate: 7
Flowing Rate:
Recommended Pump Rate: 6
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 24
Pumping Duration MIN: 0
Flowing: N

Water Details

Water ID: 933454989
Layer: 1
Kind Code: 3
Kind: SULPHUR
Water Found Depth: 60
Water Found Depth UOM: ft

WWIS | ***27*** | ***1 of 1*** | ***S/180.4*** | ***99.9 / -2.00*** | ***lot 17 con 4 OTTAWA ON***

Well ID: 7226518
Construction Date:
Primary Water Use: Domestic
Data Entry Status:
Data Src:
Date Received: 9/2/2014

Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Water Supply	**Abandonment Rec:**	
Water Type:		**Contractor:**	1119
Casing Material:		**Form Version:**	7
Audit No:	Z166959	**Owner:**	
Tag:	A144896	**Street Name:**	4726 BANK STREET
Construction Method:		**County:**	OTTAWA-CARLETON
Elevation (m):		**Municipality:**	GLOUCESTER TOWNSHIP
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	017
Well Depth:		**Concession:**	04
Overburden/Bedrock:		**Concession Name:**	RF
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005109021	**Elevation:**	102.503822
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	453228
Code OB Desc:		**North83:**	5019144
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	7/7/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005243299
Layer:	1
Color:	
General Color:	
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	18
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005243300
Layer:	2
Color:	
General Color:	
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	13
Other Materials:	BOULDERS

Mat3:
Other Materials:
Formation Top Depth: 18
Formation End Depth: 52
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005243303
Layer: 5
Color: 1
General Color: WHITE
Mat1: 18
Most Common Material: SANDSTONE
Mat2: 15
Other Materials: LIMESTONE
Mat3:
Other Materials:
Formation Top Depth: 381
Formation End Depth: 400
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005243301
Layer: 3
Color: 8
General Color: BLACK
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 52
Formation End Depth: 353
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005243302
Layer: 4
Color: 1
General Color: WHITE
Mat1: 18
Most Common Material: SANDSTONE
Mat2: 15
Other Materials: LIMESTONE
Mat3:
Other Materials:
Formation Top Depth: 353
Formation End Depth: 381
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005243338
Layer: 1
Plug From: 60

Plug To: 50
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005243339
Layer: 2
Plug From: 50
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1005243297
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005243308
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From: 60
Depth To: 400
Casing Diameter: 6.125
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 1005243307
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From: 2
Depth To: 60
Casing Diameter: 6.25
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005243309
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Results of Well Yield Testing

Pump Test ID:	1005243298
Pump Set At:	380
Static Level:	50.2
Final Level After Pumping:	109.2
Recommended Pump Depth:	350
Pumping Rate:	15
Flowing Rate:	
Recommended Pump Rate:	15
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	3
Water State After Test:	OTHER
Pumping Test Method:	0
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	N

Draw Down & Recovery

Pump Test Detail ID:	1005243322
Test Type:	Draw Down
Test Duration:	15
Test Level:	92.6
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	1005243332
Test Type:	Draw Down
Test Duration:	50
Test Level:	107.7
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	1005243334
Test Type:	Draw Down
Test Duration:	60
Test Level:	109.2
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	1005243335
Test Type:	Recovery
Test Duration:	60
Test Level:	54.9
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	1005243317
Test Type:	Recovery
Test Duration:	4
Test Level:	86
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID: 1005243321
Test Type: Recovery
Test Duration: 10
Test Level: 69.7
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243330
Test Type: Draw Down
Test Duration: 40
Test Level: 106
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243311
Test Type: Recovery
Test Duration: 1
Test Level: 99.3
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243313
Test Type: Recovery
Test Duration: 2
Test Level: 94.6
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243323
Test Type: Recovery
Test Duration: 15
Test Level: 63.4
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243326
Test Type: Draw Down
Test Duration: 25
Test Level: 100.2
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243327
Test Type: Recovery
Test Duration: 25
Test Level: 58.5
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243318
Test Type: Draw Down
Test Duration: 5
Test Level: 73.8

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243320
Test Type: Draw Down
Test Duration: 10
Test Level: 85.2
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243328
Test Type: Draw Down
Test Duration: 30
Test Level: 103
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243312
Test Type: Draw Down
Test Duration: 2
Test Level: 63.7
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243315
Test Type: Recovery
Test Duration: 3
Test Level: 89.9
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243324
Test Type: Draw Down
Test Duration: 20
Test Level: 97.4
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243329
Test Type: Recovery
Test Duration: 30
Test Level: 58
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243316
Test Type: Draw Down
Test Duration: 4
Test Level: 71.1
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243314
Test Type: Draw Down
Test Duration: 3
Test Level: 67.6
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243319
Test Type: Recovery
Test Duration: 5
Test Level: 82.5
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243331
Test Type: Recovery
Test Duration: 40
Test Level: 56.9
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243333
Test Type: Recovery
Test Duration: 50
Test Level: 55.8
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243310
Test Type: Draw Down
Test Duration: 1
Test Level: 58.7
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005243325
Test Type: Recovery
Test Duration: 20
Test Level: 60.4
Test Level UOM: ft

Water Details

Water ID: 1005243306
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 381
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005243305
Diameter: 6.125
Depth From: 60
Depth To: 400

Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1005243304
Diameter: 9.75
Depth From: 0
Depth To: 60
Hole Depth UOM: ft
Hole Diameter UOM: inch

WWIS **28** ***1 of 1*** ***N/190.3*** ***103.8 / 1.92*** ***Ottawa ON***

Well ID: 7252050
Construction Date:
Primary Water Use: Monitoring and Test Hole
Sec. Water Use: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z215053
Tag: A178570
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 11/16/2015
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 4564 BANK STREET
County: OTTAWA-CARLETON
Municipality: GLOUCESTER TOWNSHIP
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1005798122
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/20/2015
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 105.191711
Elevrc:
Zone: 18
East83: 453223
North83: 5019716
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005817782
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT

Mat2: 81
Other Materials: SANDY
Mat3: 73
Other Materials: HARD
Formation Top Depth: 0.61
Formation End Depth: 2.44
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005817783
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 81
Other Materials: SANDY
Mat3: 73
Other Materials: HARD
Formation Top Depth: 2.44
Formation End Depth: 4.57
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005817781
Layer: 1
Color: 6
General Color: BROWN
Mat1: 11
Most Common Material: GRAVEL
Mat2: 81
Other Materials: SANDY
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 0
Formation End Depth: 0.61
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005817793
Layer: 3
Plug From: 1.22
Plug To: 4.57
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005817791
Layer: 1
Plug From: 0
Plug To: 0.31
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1005817792
Layer:	2
Plug From:	0.31
Plug To:	1.22
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005817780
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005817786
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	1.5
Casing Diameter:	4.03
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005817787
Layer:	1
Slot:	10
Screen Top Depth:	1.5
Screen End Depth:	4.57
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.82

Hole Diameter

Hole ID:	1005817784
Diameter:	8.25
Depth From:	0
Depth To:	4.57
Hole Depth UOM:	m
Hole Diameter UOM:	cm

WWIS **29** ***1 of 1*** ***NNW/190.7*** ***103.9 / 2.00*** ***Ottawa ON***

Well ID:	7252048	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	11/16/2015
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Monitoring and Test Hole	**Abandonment Rec:**	

Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	7
Audit No:	Z215050	***Owner:***	
Tag:	A178572	***Street Name:***	4565 BANK STREET
Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	GLOUCESTER TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005798116	***Elevation:***	105.04972
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	453170
Code OB Desc:		***North83:***	5019705
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/20/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005817752
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	81
Other Materials:	SANDY
Mat3:	85
Other Materials:	SOFT
Formation Top Depth:	0.61
Formation End Depth:	2.13
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005817751
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	77
Other Materials:	LOOSE

Formation Top Depth:	0
Formation End Depth:	0.61
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005817754
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	3.1
Formation End Depth:	4.57
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005817753
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	85
Other Materials:	SOFT
Mat3:	81
Other Materials:	SANDY
Formation Top Depth:	2.13
Formation End Depth:	3.1
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005817763
Layer:	2
Plug From:	0.31
Plug To:	1.22
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005817764
Layer:	3
Plug From:	1.22
Plug To:	4.57
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005817762
Layer:	1
Plug From:	0
Plug To:	0.31

Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1005817750
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005817757
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.5
Casing Diameter: 4.03
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005817758
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 4.57
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.82

Hole Diameter

Hole ID: 1005817755
Diameter: 8.25
Depth From: 0
Depth To: 4.57
Hole Depth UOM: m
Hole Diameter UOM: cm

WWIS **30** ***1 of 1*** ***NNW/195.4*** ***103.9 / 2.03*** ***Ottawa ON***

Well ID:	7252049	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring and Test Hole	***Date Received:***	11/16/2015
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Monitoring and Test Hole	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	7
Audit No:	Z215054	***Owner:***	
Tag:	A178571	***Street Name:***	4565 BANK STREET

Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	GLOUCESTER TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005798119	***Elevation:***	104.943206
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	453153
Code OB Desc:		***North83:***	5019703
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/20/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005817766
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	28
Other Materials:	SAND
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0
Formation End Depth:	0.61
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005817769
Layer:	4
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	3.1
Formation End Depth:	3.96
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID: 1005817768
Layer: 3
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 81
Other Materials: SANDY
Mat3: 73
Other Materials: HARD
Formation Top Depth: 2.13
Formation End Depth: 3.1
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005817767
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 81
Other Materials: SANDY
Mat3: 85
Other Materials: SOFT
Formation Top Depth: 0.61
Formation End Depth: 2.13
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005817778
Layer: 2
Plug From: 0.31
Plug To: 0.91
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005817779
Layer: 3
Plug From: 0.91
Plug To: 3.96
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005817777
Layer: 1
Plug From: 0
Plug To: 0.31
Plug Depth UOM: m

Method of Construction & Well

Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1005817765
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005817772
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 0.91
Casing Diameter: 4.03
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005817773
Layer: 1
Slot: 10
Screen Top Depth: 0.91
Screen End Depth: 3.96
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.82

Hole Diameter

Hole ID: 1005817770
Diameter: 8.25
Depth From: 0
Depth To: 3.96
Hole Depth UOM: m
Hole Diameter UOM: cm

WWIS **31** ***2 of 2*** ***NNE/201.8*** ***103.9 / 2.03*** ***lot 16 con 5 ON***

Well ID: 1502235
Construction Date:
Primary Water Use: Livestock
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:

Data Entry Status:
Data Src: 1
Date Received: 1/4/1954
Selected Flag: Yes
Abandonment Rec:
Contractor: 3113
Form Version: 1
Owner:
Street Name:
County: OTTAWA-CARLETON
Municipality: GLOUCESTER TOWNSHIP
Site Info:
Lot: 016

Well Depth:		***Concession:***	05
Overburden/Bedrock:		***Concession Name:***	RF
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	10024278	***Elevation:***	104.774185
DP2BR:	0	***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:	h	***East83:***	453350.7
Code OB Desc:	Mixed in a Layer	***North83:***	5019692
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	11/4/1953	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	930993996
Layer:	2
Color:	
General Color:	
Mat1:	26
Most Common Material:	ROCK
Mat2:	17
Other Materials:	SHALE
Mat3:	
Other Materials:	
Formation Top Depth:	16
Formation End Depth:	239
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	930993995
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	17
Other Materials:	SHALE
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	16
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10572848
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930041337
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 239
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930041336
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 16
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502235
Pump Set At:
Static Level: 60
Final Level After Pumping: 239
Recommended Pump Depth:
Pumping Rate: 1
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: N

Water Details

Water ID: 933454986
Layer: 1
Kind Code: 3
Kind: SULPHUR
Water Found Depth: 160
Water Found Depth UOM: ft

DB	Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site
WWIS	35	1 of 1	ESE/226.3	100.0 / -1.92	OTTAWA ON

Well ID:	7177033	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Not Used	**Date Received:**	2/22/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	7260
Casing Material:		**Form Version:**	7
Audit No:	Z128676	**Owner:**	
Tag:		**Street Name:**	3077 ANALDOA DR.
Construction Method:		**County:**	OTTAWA-CARLETON
Elevation (m):		**Municipality:**	GLOUCESTER TOWNSHIP
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003694353	**Elevation:**	101.182792
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	453514
Code OB Desc:		**North83:**	5019286
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/23/2011	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004103942
Layer:	2
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	
Formation End Depth:	
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID: 1004103941
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth:
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004103951
Layer: 3
Plug From: 20
Plug To: 24
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004103950
Layer: 2
Plug From: 12
Plug To: 20
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004103949
Layer: 1
Plug From: 0
Plug To: 12
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: A
Method Construction: Digging
Other Method Construction:

Pipe Information

Pipe ID: 1004103940
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004103945
Layer:
Material:
Open Hole or Material:

Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004103946
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004103943
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

WWIS **37** ***1 of 1*** ***N/246.8*** ***104.9 / 3.00*** ***Ottawa ON***

Well ID:	7252051	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring and Test Hole	***Date Received:***	11/16/2015
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Monitoring and Test Hole	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	7
Audit No:	Z215052	***Owner:***	
Tag:	A178569	***Street Name:***	4565 BANK STREET
Construction Method:		***County:***	OTTAWA-CARLETON
Elevation (m):		***Municipality:***	GLOUCESTER TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005798125	***Elevation:***	104.72377
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	453205
Code OB Desc:		***North83:***	5019771
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/20/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1005817798
Layer:	4
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	3.1
Formation End Depth:	5.18
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005817797
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	81
Other Materials:	SANDY
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	1.83
Formation End Depth:	3.1
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005817795
Layer:	1
Color:	2
General Color:	GREY
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	28
Other Materials:	SAND
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0
Formation End Depth:	0.31
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005817796
Layer:	2
Color:	6

General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	0.31
Formation End Depth:	1.83
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005817808
Layer:	3
Plug From:	1.83
Plug To:	5.18
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005817806
Layer:	1
Plug From:	0
Plug To:	0.31
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005817807
Layer:	2
Plug From:	0.31
Plug To:	1.83
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005817794
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005817801
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	2.13
Casing Diameter:	4.03

Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005817802
Layer: 1
Slot: 10
Screen Top Depth: 2.13
Screen End Depth: 5.18
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.82

Hole Diameter

Hole ID: 1005817799
Diameter: 8.25
Depth From: 0
Depth To: 5.18
Hole Depth UOM: m
Hole Diameter UOM: cm

WWIS 39 **1 of 1** **WNW/248.8** **100.6 / -1.31** **lot 16 con 4 ON**

Well ID: 1519538
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 4/16/1985
Selected Flag: Yes
Abandonment Rec:
Contractor: 1558
Form Version: 1
Owner:
Street Name:
County: OTTAWA-CARLETON
Municipality: GLOUCESTER TOWNSHIP
Site Info:
Lot: 016
Concession: 04
Concession Name: RF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10041408
DP2BR: 61
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 3/1/1985
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:

Elevation: 99.908378
Elevrc:
Zone: 18
East83: 452929.7
North83: 5019521
Org CS:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: p4

Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931041985
Layer: 4
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2: 17
Other Materials: SHALE
Mat3: 74
Other Materials: LAYERED
Formation Top Depth: 64
Formation End Depth: 90
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931041986
Layer: 5
Color: 8
General Color: BLACK
Mat1: 17
Most Common Material: SHALE
Mat2: 15
Other Materials: LIMESTONE
Mat3: 74
Other Materials: LAYERED
Formation Top Depth: 90
Formation End Depth: 140
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931041984
Layer: 3
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2: 12
Other Materials: STONES
Mat3: 71
Other Materials: FRACTURED
Formation Top Depth: 61
Formation End Depth: 64
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931041983
Layer: 2
Color: 2
General Color: GREY
Mat1: 28
Most Common Material: SAND

Mat2: 13
Other Materials: BOULDERS
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 30
Formation End Depth: 61
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931041982
Layer: 1
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 28
Other Materials: SAND
Mat3: 12
Other Materials: STONES
Formation Top Depth: 0
Formation End Depth: 30
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10589978
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930072304
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 66
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930072305
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 140
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID:	991519538
Pump Set At:	
Static Level:	4
Final Level After Pumping:	65
Recommended Pump Depth:	70
Pumping Rate:	7
Flowing Rate:	
Recommended Pump Rate:	5
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	2
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	N

Draw Down & Recovery

Pump Test Detail ID:	934109171
Test Type:	Draw Down
Test Duration:	15
Test Level:	60
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934653322
Test Type:	Draw Down
Test Duration:	45
Test Level:	65
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934894084
Test Type:	Draw Down
Test Duration:	60
Test Level:	65
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934383345
Test Type:	Draw Down
Test Duration:	30
Test Level:	65
Test Level UOM:	ft

Water Details

Water ID:	933476569
Layer:	2
Kind Code:	1
Kind:	FRESH
Water Found Depth:	132
Water Found Depth UOM:	ft

Water Details

Water ID:	933476568
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	72
Water Found Depth UOM:	ft

Unplottable Summary

Total: 33 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	CITY	BANK ST.	GLOUCESTER CITY ON	
CA	MACDONALD DEVELOPMENT CORP.	BANK ST.	OTTAWA CITY ON	
CA	THE DOUGLAS MACDONALD DEV. CORP.	COMMERCIAL PLAZA BANK STREET	OTTAWA CITY ON	
CA	W. O. Stinson & Son Limited		Ottawa ON	
CA	MACDONALD DEVELOPMENT CORP.-PLAZA	EASEMENT-BANK STREET	OTTAWA CITY ON	
CA	City of Ottawa	Bank St from Laurier Avenue to Somerest Street	Ottawa ON	
CA	OSSORY CANADA INC.	PRIVATE BLDG. BANK ST.	OTTAWA CITY ON	
CA	THE ROMAN CATHOLIC EPISCOPAL CORP.OTTAWA	HOPE CEMETERY	GLOUCESTER CITY ON	
CA	MINISTRY OF TRANSPORTATION	HIGHWAY #31, LAT. CATCHBASINS	OTTAWA CITY ON	
CONV	Taggart Construction Limited	Bank Street	South Ottawa ON	
EHS		Bank St	Ottawa ON	
EHS		Bank St	Ottawa ON	
EXP	W O STINSON & SON LTD*	HWY 31	OTTAWA ON	
EXP	UPI ENERGY LP*	HWY 31	OTTAWA ON	
GEN	SPIC & SPAN-VALETOR-CASH CLEANERS	BILLINGS BRIDGE PLAZA, BANK STREET C/O 1764 WOODWARD DRIVE	OTTAWA ON	K2C 0P8
GEN	Hydro Ottawa Ltd.	Bank St	Ottawa ON	
HINC		BANK STREET [NORTH OF MITCH OWENS ROAD]	GLOUCESTER ON	
PES	OTTAWA FEED & HARDWARE INC. (V95023-03/2005)	4836 KING'S HWY 31	GOUCESTER ON	K1X1G6

PRT	NAZIMA MEDEWAR	HWY 31	OTTAWA ON	
PRT	W O STINSON & SON LTD	PRT LOT 17 CON 4 RIDEAU FRONT	GLOUCESTER ON	
PTTW	Claridge Homes (Leitrim) Inc.		ON	
RST	DRUMMOND'S GAS	HIGHWAY 31	GLOUCESTER ON	K1B 3B8
RST	DRUMMOND'S GAS	HIGHWAY 31	GLOUCESTER ON	K1B3B8
RST	CAPITAL CITY GAS	HIGHWAY 31	GLOUCESTER ON	K1G3N4
RST	CAPITAL CITY GAS	HIGHWAY 31	GLOUCESTER ON	K1G 3N4
SPL	OC TRANSPO	BANK ST. SOUTH MOTOR VEHICLE (OPERATING FLUID)	OTTAWA CITY ON	
SPL	City of Ottawa	Bank St in front of Bethshalam Cemetary	Ottawa ON	
SPL	ONTARIO HYDRO	BANK ST TRANSFORMER	GLOUCESTER CITY ON	
SPL	PIONEER PETROLEUMS LTD.	BANK STREET SOUTH PIONEER GAS STATION. SERVICE STATION	OTTAWA CITY ON	
SPL	TRANSPORT TRUCK	BANK ST. BRIDGE MOTOR VEHICLE (OPERATING FLUID)	OTTAWA CITY ON	
SPL	PRIVATE OWNER	RIDEAU CANAL BETWEEN BANK ST AND CLEGG ST MOTOR VEHICLE (OPERATING FLUID)	OTTAWA CITY ON	
SPL	UNKNOWN	OSGOODE TOWNSHIP HISTORICAL MUSEUM, HIGHWAAY 31,VERNON	OTTAWA-CARLETON R.M. ON	
SPL	ESSO PETROLEUM CANADA	BANK STREET SERVICE STATION	OTTAWA CITY ON	

Unplottable Report

Database: CA **Site:** CITY
BANK ST. GLOUCESTER CITY ON

Certificate #: 3-0859-85-006
Application Year: 85
Issue Date: 8/1/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Database: CA **Site:** MACDONALD DEVELOPMENT CORP.
BANK ST. OTTAWA CITY ON

Certificate #: 3-1072-88-
Application Year: 88
Issue Date: 9/28/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Database: CA **Site:** THE DOUGLAS MACDONALD DEV. CORP.
COMMERCIAL PLAZA BANK STREET OTTAWA CITY ON

Certificate #: 7-1304-86-
Application Year: 86
Issue Date: 10/28/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Database: CA **Site:** W. O. Stinson & Son Limited

Ottawa ON

Certificate #: 7712-79VSZY
Application Year: 2007
Issue Date: 12/28/2007
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Database: ***CA*** ***Site:*** ***MACDONALD DEVELOPMENT CORP.-PLAZA EASEMENT-BANK STREET OTTAWA CITY ON***

Certificate #: 3-1864-86-
Application Year: 86
Issue Date: 12/19/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Database: ***CA*** ***Site:*** ***City of Ottawa Bank St from Laurier Avenue to Somerest Street Ottawa ON***

Certificate #: 4804-7DGNT6
Application Year: 2008
Issue Date: 4/8/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Database: ***CA*** ***Site:*** ***OSSORY CANADA INC. PRIVATE BLDG. BANK ST. OTTAWA CITY ON***

Certificate #: 3-0515-87-
Application Year: 87
Issue Date: 4/23/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:

Project Description:
Contaminants:
Emission Control:

Database: ***CA*** ***Site:*** ***THE ROMAN CATHOLIC EPISCOPAL CORP.OTTAWA HOPE CEMETERY GLOUCESTER CITY ON***

Certificate #: 8-4015-88-
Application Year: 88
Issue Date: 4/26/1988
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: CREMATOR
Contaminants: Nitrogen Oxides, Suspended Particulate Matter
Emission Control: No Controls

Database: ***CA*** ***Site:*** ***MINISTRY OF TRANSPORTATION HIGHWAY #31, LAT. CATCHBASINS OTTAWA CITY ON***

Certificate #: 3-1342-93-
Application Year: 93
Issue Date: 12/31/1993
Approval Type: Municipal sewage
Status: Preliminary approval
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Database: ***CONV*** ***Site:*** ***Taggart Construction Limited Bank Street South Ottawa ON***

File No: 010503 ***Location:***
Crown Brief No: ***Region:***
Court Location: ***Ministry District:***
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: On December 3, 2009, Taggart Construction Limited pleaded guilty to one violation under the Ontario Water Resources Act for failing to comply with a Provincial Officer Order to submit weekly water taking records showing daily water taking volumes. The company was contracted to install municipal services for the Findlay Creek Subdivision located on Bank Street in South Ottawa. A ministry inspection of the construction site in the fall of 2007 revealed concerns with water taking activities and a Provincial Officer Order was issued. One of the requirements of the Order, related to keeping accurate water taking records and submitting them to the ministry, was not complied with. The company was charged following an investigation by the ministry's Investigations and Enforcement Branch and was fined $5,000 plus victim fine surcharge. The company was given 30 days to pay the fine.
Background:

URL:

Additional Details

Publication Date:
Count: 1
Act: Provincial Officer Order
Regulation:
Section:
Act/Regulation/Section: Provincial Officer Order
Date of Offence:
Date of Conviction:
Date Charged: December 3, 2009
Charge Disposition: fine, victim fine surcharge
Fine: $5,000
Synopsis:

Database: ***EHS*** ***Site:***
Bank St Ottawa ON

Order No: 20060427021
Status: C
Report Type: Custom Report
Report Date: 5/5/2006
Date Received: 4/26/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.670288
Y: 45.364953

Database: ***EHS*** ***Site:***
Bank St Ottawa ON

Order No: 20031121005
Status: C
Report Type: Basic Report
Report Date: 11/25/03
Date Received: 11/21/03
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: See Faxed Map
Municipality:
Client Prov/State: ON
Search Radius (km): 0.50
X: -75.654252
Y: 45.363635

Database: ***EXP*** ***Site:*** ***W O STINSON & SON LTD****
HWY 31 OTTAWA ON

Instance No: 10449391
Instance ID: 18397
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Database: ***EXP*** ***Site:*** ***UPI ENERGY LP****
HWY 31 OTTAWA ON

Instance No: 10454099
Instance ID: 18935
Instance Type: FS Highway Tank - Gas/Diesel

Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Database: ***GEN*** ***Site:*** ***SPIC & SPAN-VALETOR-CASH CLEANERS***
BILLINGS BRIDGE PLAZA, BANK STREET C/O 1764 WOODWARD DRIVE OTTAWA ON K2C 0P8

Generator No: ON0573413
Status:
Approval Years: 86,87,88
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Database: ***GEN*** ***Site:*** ***Hydro Ottawa Ltd.***
Bank St Ottawa ON

Generator No: ON8798860
Status:
Approval Years: 03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Database: ***HINC*** ***Site:***
BANK STREET [NORTH OF MITCH OWENS ROAD] GLOUCESTER ON

External File Num: FS INC 0712-07599
Fuel Occurrence Type: Discovery of a Petroleum Product
Date of Occurrence: 12/16/2007
Fuel Type Involved: Gasoline
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Other-Specify
Service Interruptions: No
Property Damage: No
Fuel Life Cycle Stage: Other-specify
Root Cause: Root Cause: Equipment/Material/Component:No Procedures:No Maintenance:No Design:No Training:No Management:Yes Human Factors:Yes
Reported Details: Report of a nearby retail gasoline site at a construction site where contaminated soil has been disc
Fuel Category: Unknown
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Ottawa
Approx. Quant. Rel: 1
Nearby body of water: No
Enter Drainage Syst.: No
Approx. Quant. Unit: Liters
Environmental Impact: product found at time of matinance on a fire hydrant. Excavation near a decommisioned service station at 5352 BANK ST, GLOUCESTER, ON K1X 1H1 equipment removed.

Database: PES **Site:** OTTAWA FEED & HARDWARE INC. (V95023-03/2005)
4836 KING'S HWY 31 GOUCESTER ON K1X1G6

Detail Licence No:	22-01-03950-0	**Operator Box:**	
Licence No:	03950	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	General Vendor	**Oper Phone No:**	8220760
Licence Type Code:	22	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	4
Longitude:		**Operator District:**	
Lot:		**Operator County:**	15
Concession:		**Op Municipality:**	
Region:	4	**Post Office Box:**	
District:		**MOE District:**	
County:	15	**SWP Area Name:**	
Trade Name:			
PDF Link:			

Database: PRT **Site:** NAZIMA MEDEWAR
HWY 31 OTTAWA ON

Location ID:	11082
Type:	retail
Expiry Date:	1996-03-31
Capacity (L):	36368
Licence #:	0016234001

Database: PRT **Site:** W O STINSON & SON LTD
PRT LOT 17 CON 4 RIDEAU FRONT GLOUCESTER ON

Location ID:	5313
Type:	retail
Expiry Date:	1995-10-31
Capacity (L):	10999
Licence #:	0053755001

Database: PTTW **Site:** Claridge Homes (Leitrim) Inc.
ON

EBR Registry No:	011-1598	**Year:**	2010
Ministry Ref No:	2138-8AUM2F	**Act 1:**	
Notice Type:	Instrument Decision	**Act 2:**	
Notice Stage:		**Comment Period:**	
Notice Date:	December 02, 2014	**Section:**	
Proposal Date:	November 05, 2010	**Site Location Map:**	
Decision Posted:			
Posted By:			
Company Name:	Claridge Homes (Leitrim) Inc.		
Off Instrument Name:			
Instrument Type:	(OWRA s. 34) - Permit to Take Water		
Proponent Name:			
Proponent Address:	2001 210 Gladstone avenue, Ottawa Ontario, Canada K2P 0Y6		
Site Address:			
Location Other:			
URL:			

Site Location Details:

Part of Lot 19 Address: Lot: part of 19, Concession: V, Ottawa, City District Office: Ottawa + + + + Part of Lots 17, 18 and 19 Concession V Address: Lot: Part of 17, 18, 19 & 20, Concession: V, Ottawa, City District Office: Ottawa + + + + Part of Lots 17 and 18, Concession V Address: Lot: Part of Lots 17 and 18, Concession: Concession V, Ottawa, City District Office: Ottawa CITY OF OTTAWA

Database: ***RST*** ***Site:*** ***DRUMMOND'S GAS***
HIGHWAY 31 GLOUCESTER ON K1B 3B8

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

Database: ***RST*** ***Site:*** ***DRUMMOND'S GAS***
HIGHWAY 31 GLOUCESTER ON K1B3B8

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 6138221391
List Name:
Description:

Database: ***RST*** ***Site:*** ***CAPITAL CITY GAS***
HIGHWAY 31 GLOUCESTER ON K1G3N4

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 6138221324
List Name:
Description:

Database: ***RST*** ***Site:*** ***CAPITAL CITY GAS***
HIGHWAY 31 GLOUCESTER ON K1G 3N4

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

Database: ***SPL*** ***Site:*** ***OC TRANSPO***
BANK ST. SOUTH MOTOR VEHICLE (OPERATING FLUID) OTTAWA CITY ON

Ref No:	223917	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/11/2002	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	20107
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	

Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/11/2002	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SPILL OF DIESEL FUEL TO GRND, CLEAN UP CREW ON THE WAY		
Contaminant Qty:			

Database: ***SPL*** ***Site:*** ***City of Ottawa***
Bank St in front of Bethshalam Cemetary Ottawa ON

Ref No:	1101-6BTH2J	***Discharger Report:***	0
Site No:		***Material Group:***	Chemical
Incident Dt:	4/26/2005	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Cooling System Leak	***Sector Type:***	Other Motor Vehicle
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:	ETHYLENE GLYCOL (ANTIFREEZE)	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Ottawa
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Not Anticipated	***Site Municipality:***	Ottawa
Nature of Impact:	Soil Contamination	***Site Lot:***	
Receiving Medium:	Land	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/26/2005	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Spill to Land
Incident Reason:	Equipment Failure	***Source Type:***	
Site Name:	shoulder of road<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Ottawa:OC Transpo- 8 L antifreeze to grnd, clng		
Contaminant Qty:			

Database: ***SPL*** ***Site:*** ***ONTARIO HYDRO***
BANK ST TRANSFORMER GLOUCESTER CITY ON

Ref No:	19785	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	7/9/1988	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	COOLING SYSTEM LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	20105
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	7/11/1988	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	OTHER	***Source Type:***	
Site Name:			

Site County/District:
Site Geo Ref Meth:
Incident Summary: BACKENTRY - ONTARIO HYDROTRANSFORMER OIL (AMT U/K)ON GROUND
Contaminant Qty:

Database: ***SPL*** ***Site:*** ***PIONEER PETROLEUMS LTD.***
BANK STREET SOUTH PIONEER GAS STATION. SERVICE STATION OTTAWA CITY ON

Ref No:	137358	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/20/1997	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	CONTAINER OVERFLOW	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	20101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/20/1997	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: PIONEER PETROLEUMS-4L GASOLINE TO GROUND,UNSAFESPILL RESPONSE BY STAFF.
Contaminant Qty:

Database: ***SPL*** ***Site:*** ***TRANSPORT TRUCK***
BANK ST. BRIDGE MOTOR VEHICLE (OPERATING FLUID) OTTAWA CITY ON

Ref No:	88427	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	7/13/1993	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	20101
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	FIRE DEPT
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	7/13/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	CORROSION	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: HYDRAULIC OIL LEAK FROM UNIDENTIFIED TRANSPORT TRUCK TO BANK ST. BRIDGE
Contaminant Qty:

Database: SPL **Site:** ***PRIVATE OWNER***
RIDEAU CANAL BETWEEN BANK ST AND CLEGG ST MOTOR VEHICLE (OPERATING FLUID) OTTAWA CITY ON

Ref No:	225430	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	5/14/2002	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER TRANSPORTATION ACCIDENT	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	20107
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/14/2002	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	NEGLIGENCE (APPARENT)	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	PRIVATE VEHICLE:UKN QTY GAS AND OIL IN CANAL,DRI-VER DROVE INTO CANAL		
Contaminant Qty:			

Database: SPL **Site:** ***UNKNOWN***
OSGOODE TOWNSHIP HISTORICAL MUSEUM, HIGHWAAY 31,VERNON OTTAWA-CARLETON R.M. ON

Ref No:	3978	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	//	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	UNDERGROUND TANK LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	20000
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/20/1988	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	CORROSION	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	STINSON FUELS-<1111 L FURNACE OIL TO GROUND FROM DESERTED TANK		
Contaminant Qty:			

Database: SPL **Site:** ***ESSO PETROLEUM CANADA***
BANK STREET SERVICE STATION OTTAWA CITY ON

Ref No:	147934	***Discharger Report:***	

Site No:		***Material Group:***	
Incident Dt:	10/16/1997	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	20101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/16/1997	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	DAMAGE BY MOVING EQUIPMENT	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO SERVICE STATION: 40 L GASOLINE TO GROUND		
Contaminant Qty:			

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Natural Resources maintains a database of all active pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Sep 2018

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Oct 2018

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Jan 31, 2019

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2017

Commercial Fuel Oil Tanks: Provincial CFOT

List of commercial underground fuel oil tanks made available by the Fuels Safety Program of the Technical Standards & Safety Authority (TSSA). Ontario Regulation 213/01 of the Technical Standards and Safety Act (2000) requires that all underground tanks be registered with the TSSA. Note: the Fuels Safety Division does not register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of commercial fuel tanks in the province. The TSSA updates information in its system on an ongoing basis; this listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Chemical Register: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2019

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 - Mar 2019

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-May 2019

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994-Jun 30, 2019

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Oct 2018

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Jun 31, 2019

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994-Jun 30, 2019

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Jun 30, 2019

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Apr 30, 2019

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Dec 31, 2016

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2018

List of TSSA Expired Facilities: Provincial EXP

List of facilities and tanks - for which there was once a registration - no longer registered with the Fuels Safety Program of the Technical Standards and Safety Authority (TSSA). Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc. Tanks which have been removed from the ground are included in the expired facilities inventory held by the TSSA. Notes: the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990, or furnace oil tanks prior to May 1, 2002; nor does the Division register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government.

Government Publication Date: Jun 2000-May 2019

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2018

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks made available by the Fuels Safety Program of the Technical Standards & Safety Authority (TSSA). Ontario Regulation 213/01 of the Technical Standards and Safety Act (2000) requires that all underground tanks be registered with the TSSA. Notes: the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990, or furnace oil tanks prior to May 1, 2002; nor does the Division register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of fuel storage tanks/tank facilities in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Jul 31, 2019

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2017

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

TSSA Incidents: Provincial INC

List of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC) and made available by the Technical Standards and Safety Authority (TSSA). Under the Technical Standards & Safety Act (2000), the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors, and equipment or appliances that use fuels. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the ministry compiles new and updated information. The inventory will include small and large landfills. Additionally, each year the ministry will request operators of the larger landfills complete a landfill data collection form that will be used to update LIMO and will include the following information from the previous operating year. This will include additional information such as estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills will include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Feb 28, 2019

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Jan 2019

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2017

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Dec 31, 2018

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-May 31, 2019

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-May 2018

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994-Jun 30, 2019

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: 1988-Mar 2019

TSSA Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills) made available by the Technical Standards and Safety Authority (TSSA). Under the Technical Standards & Safety Act (2000), the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors, and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of pipeline incidents in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994-Jun 30, 2019

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-2016

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-May 2019

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Jan 31, 2019

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Feb 2019

Wastewater Discharger Registration Database: Provincial SRDS

Information under this heading is combination of the following 2 programs. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment maintained a database of all direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation; Mining; Petroleum Refining; Organic Chemicals; Inorganic Chemicals; Pulp & Paper; Metal Casting; Iron & Steel; and Quarries. All sampling information is now collected and stored within the Sample Result Data Store (SRDS).

Government Publication Date: 1990-Dec 31, 2017

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970-Aug 2018

TSSA Variances for Abandonment of Underground Storage Tanks: Provincial VAR

List of variances granted for abandoned tanks. Under the Technical Standards and Safety Authority (TSSA) Liquid Fuels Handling Code and Fuel Oil Code, all underground storage tanks must be removed within two years of disuse. If removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of tank variances in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Jun 31, 2019

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Feb 28, 2019

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX C

Site Photographs

Photo 1: Looking southwest at the Site.

Photo 2: Looking northeast at the Site followed by the church to the east of the Site.

Photo 3: Photo of the nursery located on the surrounding lands northwest of the Site at 4590 Bank Street.

Photo 4: Photo of the tar or asphalt AST on the former asphalting company property north of the Site at 4603 Bank Street.

Photo 5: Looking north at the automotive garage on the surrounding lands north of the Site at 4605 Bank Street.

Photo 6: Residential houses on the adjacent lands east of the Site, looking east.

Photo 7: Photo of the fill and vent pipes observed on a residential house south of the Site at 4695 Bank Street.

Photo 8: View of the cemetery on the surrounding lands west of the Site at 4660 Bank Street, looking northwest.

Photo 9: View of the retail fuel outlet located on the surrounding lands west of the Site at 4727 Bank Street, looking southeast.

Photo 10: Looking southwest at the retail fuel outlet at 4726 Bank Street on the surrounding lands southwest of the Site.

Photo 11: Fuel AST located on the automotive garage property at 4065 Bank Street.

APPENDIX D

Aerial Photographs



LEGEND

PHASE ONE SITE

PHASE ONE STUDY AREA

0 35 70 140

1:3,500 METRES

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. PROJECTION: TRANSVERSE MERCATOR DATUM: NAD 83
COORDINATE SYSTEM: MTM ZONE 9 VERTICAL DATUM: CGVD28

CLIENT

GLENVIEW PROPERTIES INC.

PROJECT

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE

1945 AIR PHOTO

CONSULTANT

GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	APPENDIX
19128449	0001	0	**D1**

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: 25mm 0

Path: N:\Active\Spatial\MXD\vol\Ottawa\4639 Bank St\19 PRO\19128449 Glenview Environ\0001 PhaseOne ESA\19128449-0001-HS-0001.mxd



LEGEND

PHASE ONE SITE

PHASE ONE STUDY AREA

0 35 70 140

1:3,500 METRES

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. PROJECTION: TRANSVERSE MERCATOR DATUM: NAD 83
COORDINATE SYSTEM: MTM ZONE 9 VERTICAL DATUM: CGVD28

CLIENT

GLENVIEW PROPERTIES INC.

PROJECT

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE

1956 AIR PHOTO

CONSULTANT

GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	APPENDIX
19128449	0001	0	**D2**

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: 25mm 0

Path: N:\Active\Spatial\MCity\Ottawa\4639 Bank St\19 PRO\19128449 Glenview Environ\0001 PhaseOne ESA\19128449-0001-HS-002.mxd



LEGEND

PHASE ONE SITE

PHASE ONE STUDY AREA

0 35 70 140

1:3,500 METRES

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

1. PROJECTION: TRANSVERSE MERCATOR DATUM: NAD 83
COORDINATE SYSTEM: MTM ZONE 9 VERTICAL DATUM: CGVD28

CLIENT

GLENVIEW PROPERTIES INC.

PROJECT

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
4639 BANK STREET, OTTAWA, ONTARIO

TITLE

1983 AIR PHOTO

CONSULTANT

GOLDER

YYYY-MM-DD	2019-08-15
DESIGNED	----
PREPARED	JEM
REVIEWED	ADW
APPROVED	KPH

PROJECT NO.	CONTROL	REV.	APPENDIX
19128449	0001	0	**D3**

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM:
25mm
0

Path: N:\Active\Spatial\ IM\City of Ottawa\4639 Bank St\99 PRO\19128449 Glenview Environ\0001 PhaseOne ESA\19128449-0001-HS-0003.mxd

golder.com