PATERSON GROUP

# Phase I Environmental Site Assessment

260 MacLaren Street

Ottawa, Ontario

Prepared for Claridge Homes

**Report: PE7414-1**
**May 29, 2026**

# TABLE OF CONTENTS

EXECUTIVE SUMMARY ..... ii
1.0 INTRODUCTION ..... 1
2.0 PHASE I PROPERTY INFORMATION ..... 2
3.0 SCOPE OF INVESTIGATION ..... 3
4.0 RECORDS REVIEW ..... 4
4.1 General ..... 4
4.2 Environmental Source Information ..... 5
4.3 Physical Setting Sources ..... 9
5.0 INTERVIEWS ..... 11
6.0 SITE RECONNAISSANCE ..... 11
6.1 General Requirements ..... 11
6.2 Site Inspection Observations ..... 11
7.0 REVIEW AND EVALUATION OF INFORMATION ..... 13
7.1 Land Use History ..... 13
7.2 Conceptual Site Model ..... 13
8.0 CONCLUSIONS ..... 15
8.1 Assessment ..... 15
8.2 Recommendations ..... 16
9.0 STATEMENT OF LIMITATIONS ..... 17
10.0 REFERENCES ..... 18

## List of Figures

Figure 1 - Key Plan
Figure 2 - Topographic Map
Drawing PE7414-1 - Site Plan
Drawing PE7414-2 - Surrounding Land Use Plan

## List of Appendices

Appendix 1 Aerial Photographs
Site Photographs

Appendix 2 MECP Freedom of Information
MECP Well Records
TSSA
City of Ottawa HLUI
ERIS Report

Appendix 3 Qualifications of Assessors

# EXECUTIVE SUMMARY

## Assessment

Paterson Group was retained by Claridge Homes to carry out a Phase I Environmental Site Assessment (ESA) for 260 MacLaren Street, in the City of Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the Phase I Property.

According to the historical research, the Phase I Property was initially developed with two residential dwellings circa 1890's which existed until the 1970s after which it has been used as a parking lot. No historical Potentially Contaminating Activities were identified on the Phase I Property.

The presence of fill of unknown quality, associated with previous building structures, is considered to pose a potential environmental concern on the Phase I Property.

The surrounding properties within the Phase I Study Area have been used for residential, commercial or institutional purposes. The historical research of the neighbouring properties did not identify any environmental concerns with the potential to impact the Phase I Property.

Following the historical research, Paterson carried out a site visit and a visual assessment of the properties within the Phase I Study Area. The Phase I Property is currently vacant and used as parking lot. No concerns were identified with the current use of the Phase I Property.

The surrounding lands within the vicinity of the Phase I Property consist of residential or commercial properties. No environmental concerns were identified with respect to the surrounding properties.

## Recommendations

Based on the results of the Phase I ESA, in our opinion, **a Phase II Environmental Site Assessment is required for the Phase I Property**.

# 1.0 INTRODUCTION

At the request of Claridge Homes, Paterson Group (Paterson) carried out a Phase I-Environmental Site Assessment (Phase I-ESA) for 260 MacLaren Street, in the City of Ottawa, Ontario, herein referred to as the Phase I Property. The purpose of this Phase I-ESA was to research the past and current use of the Phase I ESA Property and properties within the Phase I Study Area to identify any potentially contaminating activities (PCAs) that would result in areas of potential environmental concern (APECs) on the Phase I Property.

Paterson was engaged to conduct this Phase I-ESA by Ms. Victoria St. Pierre with Claridge Homes. Ms. Victoria St. Pierre can be reached at info@claridgehomes.com.

This report has been prepared specifically and solely for the above noted project which is described herein. It contains all of our findings and results of the environmental conditions at this site.

This Phase I-ESA report has been prepared under the supervision of a Qualified Person, in general accordance with Ontario Regulation (O.Reg.) 153/04, as amended under the Environmental Protection Act, and CSA Z768-01 (as amended). The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I-ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

# 2.0 PHASE I PROPERTY INFORMATION

| | |
|---|---|
| Address: | 260 MacLaren Street, Ottawa, Ontario. |
| Location: | The Phase I Property is located on the south side of MacLaren Street, approximately 40 m west of the MacLaren Street and Metcalfe Street intersection, in the City of Ottawa, Ontario. Refer to Figure 1 - Key Plan in the Figures section following the text. |
| Latitude and Longitude: | 45° 24' 57.114" N, 75° 41' 32.442" W |

**Site Description:**

| | |
|---|---|
| Configuration: | Rectangular |
| Area: | 1189 $m^3$ (approximately). |
| Zoning: | R5B – Residential Fifth Density Zone. |
| Current Use: | The Phase I ESA Property is currently vacant and utilized as a parking lot. |
| Services: | The Phase I ESA Property is situated in a municipally serviced area. |

# 3.0 SCOPE OF INVESTIGATION

The scope of work for this Phase I – Environmental Site Assessment was as follows:

- ❑ Determine the historical activities on the Phase I Property and study area by conducting a review of readily available records, reports, photographs, plans, mapping, databases, and regulatory agencies;
- ❑ Investigate the existing conditions present at the Phase I ESA Property and study area by conducting site reconnaissance;
- ❑ Conduct interviews with persons knowledgeable of current and historic operations on the Phase I ESA Property, and if warranted, neighbouring properties;
- ❑ Present the results of our findings in a comprehensive report in general accordance with the requirements O.Reg. 153/04 as amended under the Environmental Protection Act and in compliance with the requirements of CSA Z768-01 (reaffirmed 2022);
- ❑ Provide a preliminary environmental site evaluation based on our findings;
- ❑ Provide preliminary remediation recommendations and further investigative work if contamination is suspected or encountered.

# 4.0 RECORDS REVIEW

## 4.1 General

### Phase I-ESA Study Area Determination

A radius of approximately 250 m was determined to be appropriate as a Phase I Study Area for this assignment. Properties outside the 250 m radius are not considered to have impacted the Phase I ESA Property based on their significant separation distance.

### First Developed Use Determination

Based on a review of available historical information, the Phase I Property was first developed with two residential dwellings between 1878 and 1888. The dwellings were removed in the 1970s, after which the Phase I Property was used as a parking lot.

### Fire Insurance Plans

1878

The Phase I and surrounding properties were not listed in the 1878 FIPs.

1888

The Phase I Property is occupied by two residential dwellings. Surrounding properties consisted of residential properties.

1912

No significant changes have been made to the Phase I or surrounding properties since the 1888 FIPs.

1956

No significant changes have been made to the Phase I Property. Surrounding lands now consist of residential, institutional and commercial buildings. A gasoline service station was present at 280 Elgin Street, approximately 200 m northeast of the Phase I Property, this property is considered to be a PCA, but not an APEC due to its separation distance. No potential environmental concerns were noted during the FIPs review for the surrounding properties.

### City of Ottawa Street Directories

City directories were reviewed in approximate ten (10) year intervals from 1900s to 2011. Based on the directories, the Phase I Property was occupied by residential dwellings until the 1970s, after which it has been used as a parking lot. The surrounding properties have been used for residential, commercial retail and institutional throughout the years reviewed. No potentially contaminating activities were identified in the directories for the Phase I or surrounding properties.

### Chain of Title

Paterson did not request a Chain of Title for the Phase I Property as it was determined that sufficient information was gathered from other sources, such as, aerial photographs, city directories and personal interviews.

## 4.2 Environmental Source Information

### National Pollutant Release Inventory

A search of the National Pollutant Release Inventory (NPRI) was carried out as part of this assessment. No records of any pollutant releases were identified for the Phase I or for any properties situated within the Phase I study area.

### PCB Waste Storage Site Inventory

A search of the provincial PCB waste storage site inventory was carried out as part of this assessment. One PCB storage site was identified at 225 Metcalfe Street, approximately 160 m northeast of the Phase I Property. Due to its distance away, this property is not considered to pose a potential environmental concern to the Phase I Property.

### MECP Coal Gasification Plant Inventory

The Ontario Ministry of Environment, Conservation and Parks document entitled, *"Municipal Coal Gasification Plant Site Inventory, 1991"* was reviewed as part of this assessment. This document provides a reference to the locations of former plants with respect to the Phase I Property. A review of this document did not identify any former coal gasification plants located on the Phase I Property or within the Phase I study area.

### MECP Waste Disposal Site Inventory

The Ontario Ministry of Environment, Conservation and Parks document entitled, *"Waste Disposal Site Inventory in Ontario, 1991"* was reviewed as part of this assessment. This document includes all recorded active and closed waste

disposal sites, industrial manufactured gas plants, and coal tar distillation plants situated in the Province of Ontario. Based on the MECP Waste Disposal Site Inventory no such sites were identified within 250 m of the Phase I Property.

**MECP Submissions**

A request was submitted to the MECP Freedom of Information office for information with respect to reports related to environmental conditions for the Phase I Property. The response from the MECP indicated that no records were identified for the Phase I or surrounding properties.

**MECP Instruments**

A request was submitted to the MECP Freedom of Information office for information with respect to certificates of approval, permits to take water, certificates of property use, or any other similar MECP issued instruments for the Phase I Property. The response from the MECP indicated that no records were identified for the Phase I or surrounding properties.

**MECP Incident Reports**

A request was submitted to the MECP Freedom of Information office for information with respect to records concerning environmental incidents, orders, offences, spills, discharges of contaminants, or inspections maintained by the MECP for the Phase I Property or neighbouring properties. The response from the MECP indicated that no records were identified for the Phase I or surrounding properties.

**MECP Waste Management Records**

A request was submitted to the MECP Freedom of Information office for information with respect to waste management records for the Phase I Property. The response from the MECP indicated that no records were identified for the Phase I or surrounding properties.

**MECP Brownfields Environmental Site Registry**

A search of the MECP Brownfields Environmental Site Registry was carried out as part of this assessment. A record of site condition (RSC) was filed for the property located at 330 Gilmour Street (approximately 50 m south of the Phase I Property). A Phase II ESA was not conducted as part of the RSC, therefore, it is not considered to pose a potential environmental concern to the Phase I Property. No Records of Site Condition (RSCs) were identified in the database as having been filed for the Phase I or surrounding properties.

### OMNRF Areas of Natural Significance

A search for areas of natural and scientific interest situated within the Phase I study area was carried out electronically vis the Ontario Ministry of Natural Resources and Forestry (OMNRF) website. The search did not identify any natural features or areas of natural significance within the Phase I study area.

### Technical Standards and Safety Authority (TSSA)

The TSSA, Fuels Safety Branch in Toronto, was contacted to inquire about current and former underground/aboveground storage tanks for the subject and neighbouring properties. The TSSA response indicates that no records were identified for the subject site or neighbouring properties. A copy of the correspondence with the TSSA is included in Appendix 2.

### City of Ottawa Historical Land Use Inventory (HLUI) Database

As part of this assessment, a requisition form was submitted to the City of Ottawa to request information from the City's Historical Land Use Inventory (HLUI) database for any environmental records pertaining to the Phase I Property as well as any properties situated within the Phase I study area.

The response did not indicate any records on the Phase I Property. The HLUI response indicated several potentially contaminating activities within the Phase I Study Area.

The HLUI response identified a paper bag manufacturing facility at 270 MacLaren Street, a former hydraulic oil spill at 283 MacLaren Street, an underground storage tank at 252 Metcalfe Street, a motion picture production facility, and a former coal storage area and underground storage tank leak at 330 Gilmour Street. Due to the nature of these records and/or their cross-gradient orientation relative to the Phase I Property, they are not considered to represent potential environmental concerns for the Phase I Property.

The remaining records pertain to properties located a significant distance from the Phase I Property and, therefore, are not considered to represent potential environmental concerns for the Phase I Property. A copy of the response has been included in Appendix 2.

### City of Ottawa Old Landfill Sites

The City of Ottawa's Former Landfills online map was reviewed as part of this assessment. This map identifies 123 former landfills through the City of Ottawa's Old Landfill Management Strategy (OLMS 2004) and includes location, ownership, periods of operation and waste type for 82 sites identified as previously

owned/operated either fully or in part by former municipalities and townships within the boundaries of the City of Ottawa and is updated periodically.

A review of this map did not identify any landfill sites situated on the Phase I Property or within 250 m of the Phase I Property.

**City of Ottawa Former Industrial Sites**

The document prepared by Intera Technologies Limited entitled, *"Mapping and Assessment of Former Industrial Sites, City of Ottawa"*, was reviewed as part of this assessment. No former industrial sites were identified on the Phase I Property or within the Phase I study area.

**ERIS Database Report**

A database report, prepared by ERIS (Environmental Risk Information Services) Ltd., dated January 28, 2026, was acquired and reviewed as part of this assessment. The complete ERIS report has been included in Appendix 2.

❒ *On-Site Records:*

The ERIS report did not identify any records on the Phase I Property.

❒ *Off-Site Records:*

The ERIS report identified three-hundred and sixty-seven (367) records pertaining to properties located within a 250 m radius of the Phase I Property. The off-site records pertain to boreholes, certificates of approval, ERIS historical searches, environmental compliance approval, pipeline incidents, Ontario spills, national PCB inventory, inventory of PCB storage sites, delisted fuel tanks, waste generators, TSSA historic incidents, historical business activity risk, pipeline incidents, private and retail fuel storage tanks, record of site condition, retail fuel storage tanks, Scott's manufacturing directories, variances for abandonment of underground storage tanks, permit to take water and water wells.

One waste oils and lubricant waste generator record was identified on the property south of the Phase I ESA (addressed 295 Gilmour Street). One light fuels waste generator record was identified on the property southwest of the Phase I ESA (addressed 280 MacLaren Street) and the property addressed 283 MacLaren Street (approximately 25m northwest of the Phase I ESA). Due to their distance away or their cross-gradient orientation to the Phase I Property, they are not considered to pose a potential environmental concern to the Phase I Property.

An Ontario Spill record was identified at 283 MacLaren Street, and it pertains to a hydraulic oil spill resulting from equipment failure. An Ontario spill was recorded for the property approximately 25m northwest of the Phase I Property. Due to their

cross-gradient orientation to the Phase I Property, they are not considered to pose a potential environmental concern to the Phase I Property.

Two national PCB inventory and four inventory of PCB storage sites records were identified on the property addressed 255 Metcalfe Street. Due to its distance away and its down-gradient orientation, this property is not considered to pose a potential environmental concern to the Phase I Property.

Due to the nature of the remaining records, they are not considered to pose a potential environmental concern to the Phase I Property.

## 4.3 Physical Setting Sources

### Aerial Photographs

Historical air photos from the National Air Photo Library and Geo Ottawa were reviewed in approximate ten (10) year intervals. Based on the review, the following observations have been made:

1928 (City of Ottawa website) The Phase I Property is occupied by two residential dwellings at this time. Surrounding properties consist of residential properties.

1958 (City of Ottawa website) The Phase I Property appears to remain unchanged from the previous photograph. Residential apartment buildings have been constructed in the general area of the Phase I Property.

1965 (City of Ottawa website) The Phase I Property appears to remain unchanged from the previous photograph. The properties to the west, southwest and south of the Phase I Property are now vacant. Additional residential apartment buildings have been constructed in the general area of the Phase I Property.

1976 (City of Ottawa website) The Phase I Property is now vacant and used as a parking lot. No significant changes appear to have been made to the surrounding properties.

1991 (City of Ottawa website) The Phase I Property appears to remain unchanged from the previous photograph. A residential apartment building has been constructed southwest of the Phase I Property.

2002 (City of Ottawa website) No significant changes appear to have been made to the Phase I or surrounding properties.

2011 (City of Ottawa website) No significant changes appear to have been made to the Phase I or surrounding properties.

2022 (City of Ottawa website) No significant changes appear to have been made to the Phase I or surrounding properties.

Copies of selected aerial photographs reviewed are included in Appendix 1.

### Water Bodies

No water bodies are present on the Phase I Property. The nearest named water body with respect to the Phase I Property is the Rideau Canal, located approximately 760 m to the east.

### Physiographic Maps

A physiographic map was reviewed from the Natural Resources Canada – The Atlas of Canada website, as a part of this assessment. According to the publication and mapping information, the Phase I Property is situated within the St. Lawrence Lowlands. According to the description provided: *"The lowlands are plain-like areas that were affected by the Pleistocene glaciations and are therefore covered by surficial deposits and other features associated with the ice sheets."* The Phase I Property is specifically located within the Central St. Lawrence Lowland area, which is rarely more than 150 m above sea level.

### Topographic Maps

Topographic maps were obtained from Natural Resources Canada – The Atlas of Canada website and from the City of Ottawa website. The topographic maps indicate that the regional topography in the general area of the site slopes down in an easterly direction towards the Rideau Canal. An illustration of the referenced topographic map is presented on Figure 2 – Topographic Map, appended to this report.

### Geological Maps

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, bedrock in the area consists of shale, of the Billings Formation. The surficial geology in the area of the site consists of Offshore Marine Sediments, with a drift thickness ranging from 15 to 25 m.

### Water Well Records

A search of the MECPs website for all drilled well records within a 250 m radius of the Phase I Property was carried out as part of this assessment. The search identified no wells on the Phase I Property and thirteen (29) well records within the Phase I study area. These records pertain to wells installed between 2007 and 2021 and used for groundwater observation purposes. According to the well records, the overburden stratigraphy in the area of the Phase I Property generally consists of silt and clay. Bedrock was not encountered in any of the boreholes.

A select number of the aforementioned well records have been included in Appendix 2.

# 5.0 INTERVIEWS

### Property Owner Representative

Ms. Victoria St. Pierre, a representative the current property owner, was available to answer questions during the site visit. Ms. St. Pierre was unaware of any potential environmental concerns associated with the subject and neighbouring properties. Ms. St. Pierre indicated that she was not aware of any previous environmental reports prepared for the subject property.

# 6.0 SITE RECONNAISSANCE

## 6.1 General Requirements

The site visit was carried out on February 16, 2026 by Mr. Mohammed Ramadan with Paterson's Environmental Department. In addition to the site, the uses of neighbouring properties within the Phase I Study Area were also assessed at the time of the site visit, from publicly accessible areas.

## 6.2 Site Inspection Observations

### Site Features

The Phase I Property is vacant and is being used as a parking lot. The site and regional topographies slope downward to the east towards the Rideau Canal. The subject site is considered to be mostly elevated with respect to the adjacent roads and the neighbouring properties. No ponded water, stressed vegetation, surficial staining, or any other indications of potential sub-surface contamination were observed on the subject site at the time of the site inspection.

A depiction of the Phase I Property is illustrated on Drawing PE7414-1 – Site Plan, in the Figures section of this report.

**Potential Environmental Concerns**

❒ **Fuels and Chemical Storage**

No chemical storage areas, above ground storage tanks (ASTs), or signs of underground storage tanks (USTs) were observed on the exterior of the Phase I Property at the time of the site inspection.

❒ **Hazardous Materials and Unidentified Substances**

No hazardous materials, unidentified substances, spills, surficial staining, abnormal odours, stressed vegetation, or any other indications of potential sub-surface contamination were observed on the exterior of the Phase I Property at the time of the site inspection.

❒ **Polychlorinated Biphenyls (PCBs) and Transformer Oil**

No potential sources of PCBs were identified on the exterior of the subject property at the time of the site inspection.

❒ **Waste Management**

No waste is currently being generated at the Phase I Property.

**Neighbouring Properties**

An inspection of the neighbouring properties was carried out from publicly accessible roadways at the time of the site inspection. Land use adjacent to the Phase I Property is as follows:

- ❒ North: MacLaren Street, followed by residential properties;
- ❒ South: Residential apartment building, followed by Gilmour Street;
- ❒ East: Residential apartment building, followed by Metcalfe Street;
- ❒ West: Residential dwelling, followed by residential and commercial office properties.

The current use of the immediately adjacent properties is not considered to pose an environmental concern to the Phase I Property. Surrounding land use is shown on Drawing PE7414-2 – Surrounding Land Use Plan.

# 7.0 REVIEW AND EVALUATION OF INFORMATION

## 7.1 Land Use History

Based on a review of available historical information, the Phase I Property was first developed with two residential dwellings between 1878 and 1888. The dwellings were removed in the 1970s, after which the Phase I Property was used as a parking lot.

### Potentially Contaminating Activities (PCAs) and Areas of Potential Environmental Concern (APECs)

One potentially contaminating activity (PCA) that results in an area of environmental potential concern was identified on the Phase I Property and it pertains to the presence of fill of unknown quality. Twenty-two (22) off-site potentially contaminating activities were identified within the study area but were deemed not to pose a potential environmental concern due to their distance away from the Phase I Property. Surrounding land use is presented on Drawing P7414-2 – Surrounding Land Use Plan, in the Figures section of this report.

### Contaminants of Potential Concern

Contaminants of potential concern (CPCs) in the soil and/or groundwater beneath the Phase I-ESA Property include the following:

- ❑ Metals (including arsenic (As), antimony (Sb) and selenium (Se))
- ❑ Polycyclic Aromatic Hydrocarbons (PAHs)
- ❑ Petroleum Hydrobcarbons (PHCs)
- ❑ Benzene, Toluene, Ethylbenzene, and Xylene (BTEX)

In accordance with Section 49.1 of O.Reg.153/04, as amended, electrical conductivity (EC) and sodium adsorption ratio (SAR) are not considered to be CPCs.

## 7.2 Conceptual Site Model

### Geological and Hydrogeological Setting

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, bedrock in the area consists of shale, of the Billings Formation. The surficial geology in the area of the site consists of Offshore Marine Sediments, with a drift thickness ranging from 15 to 25 m.

Groundwater flow is interpreted to be in an easterly direction towards the Rideau Canal.

**Water Bodies and Areas of Natural and Scientific Interest**

No water bodies are present on the Phase I Property. The nearest named water body with respect to the Phase I Property is the Rideau Canal, located approximately 760 m to the east.

No areas of natural significance were identified within the Phase I Study area.

**Existing Buildings and Structures**

No existing buildings or structures are present on the Phase I Property.

**Drinking Water Wells**

Based on the availability of municipal water services, no drinking water wells are expected to be in use within the Phase I study area.

**Neighbouring Land Use**

The neighbouring lands within the Phase I study area consist of residential and commercial. Current land use is shown on Drawing PE7414-2 – Surrounding Land Use Plan, in the Figures section of this report.

**Potentially Contaminating Activities and Areas of Potential Environmental Concern**

As per Section 7.1, one potentially contaminating activity (PCA) resulting in an area of potential environmental concern (APEC) was identified on the Phase I Property. Twenty-two (22) off-site potentially contaminating activities were identified within the study area but were deemed not to pose a potential environmental concern due to their distance away from the Phase I Property.

**Contaminants of Potential Concern**

Contaminants of potential concern (CPCs) in the soil and/or groundwater beneath the Phase I-ESA Property include the following:

- ❑ Metals (including arsenic (As), antimony (Sb) and selenium (Se))
- ❑ Polycyclic Aromatic Hydrocarbons (PAHs)
- ❑ Petroleum Hydrobcarbons (PHCs)
- ❑ Benzene, Toluene, Ethylbenzene, and Xylene (BTEX)

In accordance with Section 49.1 of O.Reg.153/04, as amended, electrical conductivity (EC) and sodium adsorption ratio (SAR) are not considered to be CPCs.

**Assessment of Uncertainty and/or Absence of Information**

The information available for review as part of the preparation of this Phase I ESA is considered to be sufficient to conclude that there is one APEC associated with the Phase I Property. This was confirmed by a variety of independent sources, and as such, the conclusions of this report are not affected by uncertainty which may be present with respect to the individual sources.

# 8.0 CONCLUSIONS

## 8.1 Assessment

Paterson Group was retained by Claridge Homes to carry out a Phase I Environmental Site Assessment (ESA) for 260 MacLaren Street, in the City of Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the Phase I Property.

According to the historical research, the Phase I Property was initially developed with two residential dwellings circa 1890's which existed until the 1970s after which it has been used as a parking lot. No historical Potentially Contaminating Activities were identified on the Phase I Property.

The presence of fill of unknown quality, associated with previous building structures, is considered to pose a potential environmental concern on the Phase I Property.

The surrounding properties within the Phase I Study Area have been used for residential, commercial or institutional purposes. The historical research of the neighbouring properties did not identify any environmental concerns with the potential to impact the Phase I Property.

Following the historical research, Paterson carried out a site visit and a visual assessment of the properties within the Phase I Study Area. The Phase I Property is currently vacant and used as parking lot. No concerns were identified with the current use of the Phase I Property.

The surrounding lands within the vicinity of the Phase I Property consist of residential or commercial properties. No environmental concerns were identified with respect to the surrounding properties.

## 8.2 Recommendations

Based on the results of the Phase I ESA, in our opinion, **a Phase II Environmental Site Assessment is required for the Phase I Property**.

# 9.0 STATEMENT OF LIMITATIONS

This Phase I - Environmental Site Assessment report has been prepared under the supervision of a Qualified Person, in general accordance with O.Reg. 153/04, as amended, and CSA Z768-01 (as amended). The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I - ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

Should any conditions be encountered at the Phase I Property and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Claridge Homes. Permission and notification from the above noted party and Paterson will be required to release this report to any other party.

**Paterson Group Inc.**



Mohammed Ramadan, B.Sc.






Mark D'Arcy, P.Eng, QP$_{ESA}$

**Report Distribution:**

- ❑ Claridge Homes
- ❑ Paterson Group

# 10.0 REFERENCES

**Federal Records**
Air photos at the Energy Mines and Resources Air Photo Library.
National Archives.
Maps and photographs (Geological Survey of Canada surficial and subsurface mapping).
Natural Resources Canada – The Atlas of Canada.
Environment Canada, National Pollutant Release Inventory.
PCB Waste Storage Site Inventory.

**Provincial Records**
MECP Freedom of Information and Privacy Office.
MECP Municipal Coal Gasification Plant Site Inventory, 1991.
MECP document titled “Waste Disposal Site Inventory in Ontario”.
MECP Brownfields Environmental Site Registry.
Office of Technical Standards and Safety Authority, Fuels Safety Branch.
MNR Areas of Natural Significance.
MECP Water Well Record Inventory.
Chapman, L.J., and Putnam, D.F., 1984: ‘The Physiography of Southern Ontario, Third Edition’, Ontario Geological Survey Special Volume 2.

**Municipal Records**
City of Ottawa Document “Old Landfill Management Strategy, Phase I - Identification of Sites.”, prepared by Golder Associates, 2004.
Intera Technologies Limited Report “Mapping and Assessment of Former Industrial Sites, City of Ottawa”, 1988.
geoOttawa: City of Ottawa electronic mapping website.
City of Ottawa Historical Land Use Inventory (HLUI) Database

**Local Information Sources**
Personal Interviews.

**Public Information Sources**
Google Earth.
Google Maps/Street View.

**Private Information Sources**
ERIS Report

# FIGURES

**FIGURE 1 – KEY PLAN**

**FIGURE 2 – TOPOGRAPHIC MAP**

**DRAWING PE7414-1 – SITE PLAN**

**DRAWING PE7414-2 – SURROUNDING LAND USE PLAN**





FIGURE 1

# KEY PLAN

PATERSON GROUP





FIGURE 2

# TOPOGRAPHIC MAP

287 MacLAREN STREET
RESIDENTIAL

283 MacLAREN STREET
RESIDENTIAL

275 MacLAREN STREET
RESIDENTIAL

263 MacLAREN STREET
RESIDENTIAL

252 METCALFE STREET
RESIDENTIAL

MACLAREN STREET

270 MacLAREN STREET
COMMERCIAL OFFICE

264 MacLAREN STREET
RESIDENTIAL

APEC 1

**260 MacLAREN STREET**
**VACANT**

260 METCALFE STREET
RESIDENTIAL

METCALFE STREET

255 METCALFE STREET
RESIDENTIAL

267 O'CONNOR STREET
RESIDENTIAL

307 GILMOUR STREET
COMMERCIAL OFFICE

295 GILMOUR STREET
RESIDENTIAL

280 METCALFE STREET
RESIDENTIAL

233 GILMOUR STREET
RESIDENTIAL

LEGEND:

PHASE I PROPERTY BOUNDARY

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN :

| ID # | PCA ID | DESCRIPTION |
|---|---|---|
| 1 | 30 | FILL MATERIAL OF UNKNOWN QUALITY |

SCALE: 1:400

0 5 10 15 20 25m

PATERSON GROUP
9 AURIGA DRIVE
OTTAWA, ON
K2E 7T9
TEL: (613) 226-7381

| NO. | REVISIONS | DATE | INITIAL |
|---|---|---|---|

**CLARIDGE HOMES**

# PHASE I - ENVIRONMENTAL SITE ASSESSMENT
# 260 MacLAREN STREET

**OTTAWA,** **ONTARIO**

**Title:**

## SITE PLAN

| | |
|---|---|
| **Scale:** 1:400 | **Date:** 02/2026 |
| **Drawn by:** GK | **Report No.:** PE7414-1 |
| **Checked by:** MR | **Dwg. No.:** PE7414-1 |
| **Approved by:** MSD | **Revision No.:** |

p:\autocad drawings\environmental\pe7414xx\pe7414\pe7414-1 site plan.dwg

11x17




POTENTIAL ENVIRONMENTAL CONCERN :

| ID # | PCA ID | DESCRIPTION |
|---|---|---|
| 1 | 30 | FILL MATERIAL OF UNKNOWN QUALITY |
| 2 | 31 | FORMER PORTRAIT STUDIO AND PRINTER |
| 3 | N/A | FORMER COAL STORAGE |
| 4 | 10 | FORMER COMMERCIAL AUTOMOTIVE SERVICE GARAGE |
| 5 | N/A | FORMER PCB STORAGE SITE |
| 6 | N/A | PAPER BAG MANUFACTURER |
| 7 | N/A | FORMER HYDRAULIC OIL SPILL (VOLUME UNKNOWN) |
| 8 | 28 | UNDERGROUND STORAGE TANK LEAK (VOLUME UNKNOWN) |
| 9 | 31 | FORMER PUBLISHER |
| 10 | N/A | FORMER PCB STORAGE SITE |
| 11 | N/A | FORMER PCB STORAGE SITE |
| 12 | 31 | FORMER PUBLISHER |
| 13 | N/A | FORMER 180L FURNACE OIL SPILL |
| 14 | 31 | FORMER PRINTER/PUBLISHER |
| 15 | 28 | FORMER UNDERGROUND STORAGE TANK |
| 16 | 31 | FORMER PRINTING FACILITY |
| 17 | 28 | FORMER ABOVEGROUND STORAGE TANK |
| 18 | 28 | FORMER UNDERGROUND STORAGE TANK |
| 19 | 28 | FORMER UNDERGROUND STORAGE TANK |
| 20 | 28 | FORMER UNDERGROUND STORAGE TANK |
| 21 | 28 | FORMER UNDERGROUND STORAGE TANK |
| 22 | 28 | FORMER UNDERGROUND STORAGE TANK |

PATERSON GROUP
9 AURIGA DRIVE
OTTAWA, ON
K2E 7T9
TEL: (613) 226-7381

| NO. | REVISIONS | DATE | INITIAL |
|---|---|---|---|
| | | | |

CLARIDGE HOMES

**PHASE I - ENVIRONMENTAL SITE ASSESSMENT**
**260 MacLAREN STREET**

OTTAWA, ONTARIO

Title:

# SURROUNDING LAND USE PLAN

| | |
|---|---|
| Scale: 1:2500 | Date: 02/2026 |
| Drawn by: GK | Report No.: PE7414-1 |
| Checked by: MR | Dwg. No.: PE7414-2 |
| Approved by: MSD | Revision No.: |


11x17

p:\autocad drawings\environmental\pe7414x\pe7414\pe7414-2 surrounding land use plan.dwg

# APPENDIX 1


## AERIAL PHOTOGRAPHS

## SITE PHOTOGRAPHS





AERIAL PHOTOGRAPH
1928

PATERSON GROUP




AERIAL PHOTOGRAPH
1958

PATERSON GROUP





AERIAL PHOTOGRAPH
1965

PATERSON GROUP





AERIAL PHOTOGRAPH
1976

PATERSON GROUP




AERIAL PHOTOGRAPH
1991

PATERSON GROUP




AERIAL PHOTOGRAPH
2002

PATERSON GROUP




AERIAL PHOTOGRAPH
2011

PATERSON GROUP




AERIAL PHOTOGRAPH
2022

PATERSON GROUP

# Site Photographs

PE7414 | 260 MacLaren Street, Ottawa ON | February 16, 2025



Photograph 1: View of the Phase I Property, facing south.

# APPENDIX 2

**MECP FREEDOM OF INFORMATION**

**MECP WELL RECORDS**

**TSSA**

**CITY OF OTTAWA HLUI**

**ERIS REPORT**

**Ministry of the Environment, Conservation and Parks**

Corporate Services Branch
40 St. Clair Avenue West
Toronto ON M4V 1M2

**Ministère de l'Environnement, de la Protection de la nature et des Parcs**

Direction des services généraux
40, avenue St. Clair Ouest
Toronto ON M4V 1M2

Ontario

February 17, 2026

Mohammed Ramadan
Paterson Group
9 Auriga Drive
Ottawa, Ontario K2E 7T9
mramadan@patersongroup.ca

Dear Mohammed Ramadan:

RE: **MECP FOI A-2026-00621, Your Reference PE7414 – Decision Letter**

This letter is in response to your request made pursuant to the Freedom of Information and Protection of Privacy Act (the Act) relating to:

260 MacLaren Street, Ottawa

Timeframe: 1850/01/01 to 2026/01/26

After a thorough search through the ministry files, no records were located responsive to your request. The official responsible for making the access decision on your request is the undersigned. This file is now closed.

You may request a review of my decision within 30 days from the date of this letter by contacting the Information and Privacy Commissioner/Ontario at http://www.ipc.on.ca. Please note there may be a fee associated with submitting the appeal.

If you have any questions, please contact Christian Brodersen at christian.brodersen@ontario.ca.

Yours truly,

Christian Brodersen

for
Josephine DeSouza
Manager, Access and Privacy Office

Ontario Ministry of the Environment

Well T... A 061568 ...mber below)

A 061568

# Well Record

*Regulation 903 Ontario Water Resources Act*

page ___ of ___

**Instructions for Completing Form**

- For use in the **Province of Ontario** only. This document is a permanent **legal** document. Please retain for future reference.
- All Sections **must** be completed in full to avoid delays in processing. Further instructions and explanations are available on the back of this form.
- Questions regarding completing this application can be directed to the Water Well Help Desk (Toll Free) at 1-888-396-9355.
- **All metre measurements shall be reported to 1/10th of a metre.**
- Please print clearly in blue or black ink only.

**Ministry Use Only**

MUN | CON | LOT

## Well Owner's Information and Location of Well Information

| First Name | Last Name | Mailing Address (Street Number/Name, RR, Lot, Concession) |
|---|---|---|
| Canadian Federation | of Students | 170 Metcalfe st |

| County/District/Municipality | Township/City/Town/Village | Province | Postal Code | Telephone Number (include area code) |
|---|---|---|---|---|
| CARLETON | Ottawa | Ontario | K2P 1P3 | |

| Address of Well Location (County/District/Municipality) | Township | Lot | Concession |
|---|---|---|---|
| 338 Somerset st. W., CARLETON | | | |

| RR#/Street Number/Name | City/Town/Village | Site/Compartment/Block/Tract etc. |
|---|---|---|
| | Ottawa | |

| GPS Reading | NAD | Zone | Easting | Northing | Unit Make/Model | Mode of Operation | |
|---|---|---|---|---|---|---|---|
| | 83 | 18 | 445602 | 5029369 | Garmin Etrex | ETREX | ☐ Undifferentiated ☑ Averaged ☐ Differentiated, specify |

## Log of Overburden and Bedrock Materials (see instructions)

| General Colour | Most common material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| Brn | Topsoil | | Sandy Gravel, soft | 0 | .91 |
| Brn | silt | Sand / clay | fine sand, dry, soft | .91 | 1.5 |
| Brn Grey | silt | clay | soft, moist | 1.5 | 3.66 |
| Grey | clay | silt | soft, moist | 3.66 | 6.1 |
| Grey | clay | | wet, sticky, soft | 6.1 | 8.23 |

## Hole Diameter

| Depth From | Depth To | Diameter Centimetres |
|---|---|---|
| 0 | 8.23 | 8.89 |

## Water Record

Water found at ___ Metres / Kind of Water

___ m ☐ Fresh ☐ Sulphur ☐ Gas ☐ Salty ☐ Minerals ☐ Other:

___ m ☐ Fresh ☐ Sulphur ☐ Gas ☐ Salty ☐ Minerals ☐ Other:

___ m ☐ Fresh ☐ Sulphur ☐ Gas ☐ Salty ☐ Minerals ☐ Other:

After test of well yield, water was ☐ Clear and sediment free ☐ Other, specify

Chlorinated ☐ Yes ☐ No

## Construction Record

| Inside diam centimetres | Material | Wall thickness centimetres | Depth From | Depth To |
|---|---|---|---|---|
| **Casing** | | | | |
| 3.81 | ☐ Steel ☐ Fibreglass ☑ Plastic ☐ Concrete ☐ Galvanized | ~~3.81~~ 0.25 | 0 | 4.88 |
| | ☐ Steel ☐ Fibreglass ☐ Plastic ☐ Concrete ☐ Galvanized | | | |
| | ☐ Steel ☐ Fibreglass ☐ Plastic ☐ Concrete ☐ Galvanized | | | |
| **Screen** | | | | |
| Outside diam | ☐ Steel ☐ Fibreglass ☑ Plastic ☐ Concrete ☐ Galvanized | Slot No. 10 | 4.88 | 8.23 |
| **No Casing or Screen** | | | | |
| | ☐ Open hole | | | |

## Test of Well Yield

| Pumping test method | Draw Down Time min | Draw Down Water Level Metres | Recovery Time min | Recovery Water Level Metres |
|---|---|---|---|---|
| Pump intake set at - (metres) | Static Level | | | |
| Pumping rate - (litres/min) | 1 | | 1 | |
| Duration of pumping ___hrs +___ min | 2 | | 2 | |
| Final water level end of pumping ___metres | 3 | | 3 | |
| Recommended pump type. ☐ Shallow ☐ Deep | 4 | | 4 | |
| Recommended pump depth. ___metres | 5 | | 5 | |
| Recommended pump rate. (litres/min) | 10 | | 10 | |
| | 15 | | 15 | |
| If flowing give rate - (litres/min) | 20 | | 20 | |
| | 25 | | 25 | |
| If pumping discontinued, give reason. | 30 | | 30 | |
| | 40 | | 40 | |
| | 50 | | 50 | |
| | 60 | | 60 | |

## Plugging and Sealing Record

☑ Annular space ☐ Abandonment

| Depth set at - Metres From | Depth set at - Metres To | Material and type (bentonite slurry, neat cement slurry) etc. | Volume Placed (cubic metres) |
|---|---|---|---|
| 0 | .31 | flushmount / concrete | |
| .31 | | Benseal | |
| | | Sand | |
| | | | |
| | | | |

## Method of Construction

☐ Cable Tool ☐ Rotary (air) ☐ Diamond ☐ Digging
☐ Rotary (conventional) ☐ Air percussion ☐ Jetting ☑ Other Geoprobe
☐ Rotary (reverse) ☐ Boring ☐ Driving

## Water Use


☐ Domestic ☐ Industrial ☐ Public Supply ☑ Other monitoring well
☐ Stock ☐ Commercial ☐ Not used
☐ Irrigation ☐ Municipal ☐ Cooling & air conditioning

## Final Status of Well

☐ Water Supply ☐ Recharge well ☐ Unfinished ☐ Abandoned, (Other)
☑ Observation well ☐ Abandoned, insufficient supply ☐ Dewatering
☑ Test Hole ☐ Abandoned, poor quality ☐ Replacement well

## Location of Well

In diagram below show distances of well from road, lot line, and building. Indicate north by arrow.




Audit No. Z 74024

Date Well Completed YYYY MM DD: 2007 06 22

Was the well owner's information package delivered? ☐ Yes ☑ No

Date Delivered YYYY MM DD

## Well Contractor/Technician Information

| Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| STRATA SOIL SAMPLING | 7241 |

Business Address (street name, number, city etc.): 147 WEST BEAVER CREEK, RICHMOND HILL

| Name of Well Technician (last name, first name) | Well Technician's Licence No. |
|---|---|
| TENELIUS JOHN T-3069 | T-3069 |

Signature of Technician/Contractor: X

Date Submitted YYYY MM DD: 2007 06 27

## Ministry Use Only

| Data Source | Contractor |
|---|---|
| | 7241 |
| Date Received YYYY MM DD: JUL 17 2007 | Date of Inspection YYYY MM DD |
| Remarks | Well Record Number |

0506E (08/2006) Ministry's Copy

Cette formule est disponible en français

Bonitha Brian, 1796

7337489

Ontario — Ministry of the Environment, Conservation and Parks

Measurements recorded in: ☑ Metric ☐ Imperial

**Well Tag No.** *(Place Sticker and/or Print Below)* A265336

# Well Record

***Regulation 903 Ontario Water Resources Act***

5-23385 Page ____ of ____

CARLETON UNIVERSITY

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| Bronson Rd and Raven | | | |
| **County/District/Municipality** | **City/Town/Village** | **Province** | **Postal Code** |
| | Ottawa | Ontario | [illegible] |
| **UTM Coordinates** NAD 83 Zone 18 Easting 445821 Northing 5029518 | **Municipal Plan and Sublot Number** | **Other** | |

**Overburden and Bedrock Materials/Abandonment Sealing Record** *(see instructions on the back of this form)*

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| Brown | Topsoil | Stones | Loose | 0 | 1.5 |
| Brown | Clay | Silt | Hard | 1.5 | 4.88 |

**Annular Space**

| Depth Set at (m/ft) From | To | Type of Sealant Used (Material and Type) | Volume Placed ($m^3$/$ft^3$) |
|---|---|---|---|
| 0 | 0.61 | Monument | |
| 0.61 | 3.1 | Bentonite | |
| 3.1 | 4.88 | Sand | |

**Method of Construction**

☐ Cable Tool ☐ Diamond ☐ Rotary (Conventional) ☐ Jetting ☐ Rotary (Reverse) ☐ Driving ☐ Boring ☐ Digging ☐ Air percussion ☒ Other, *specify* D.P.

**Well Use**

☐ Public ☐ Commercial ☐ Not used ☐ Domestic ☐ Municipal ☐ Dewatering ☐ Livestock ☒ Test Hole ☒ Monitoring ☐ Irrigation ☐ Cooling & Air Conditioning ☐ Industrial ☐ Other, *specify*

**Construction Record - Casing**

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 4.03 | PVC | 0.368 | 0 | 3.35 |

**Construction Record - Screen**

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 4.82 | PVC | 10 | 3.35 | 4.88 |

**Status of Well**

☐ Water Supply ☐ Replacement Well ☐ Test Hole ☐ Recharge Well ☐ Dewatering Well ☒ Observation and/or Monitoring Hole ☐ Alteration (Construction) ☐ Abandoned, Insufficient Supply ☐ Abandoned, Poor Water Quality ☐ Abandoned, other, *specify* ☐ Other, *specify*

**Water Details**

| Water found at Depth (m/ft) | Kind of Water | |
|---|---|---|
| ☐ Gas | ☐ Fresh ☐ Untested | ☐ Other, *specify* |
| ☐ Gas | ☐ Fresh ☐ Untested | ☐ Other, *specify* |
| ☐ Gas | ☐ Fresh ☐ Untested | ☐ Other, *specify* |

**Hole Diameter**

| Depth (m/ft) From | To | Diameter (cm/in) |
|---|---|---|
| 0 | 4.88 | 8.3 |

**Results of Well Yield Testing**

After test of well yield, water was: ☐ Clear and sand free ☐ Other, *specify*

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)


Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

| Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|
| Static Level | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 50 | | 50 | |
| 60 | | 60 | |

**Map of Well Location**

Please provide a map below following instructions on the back.




Comments:

**Well Contractor and Well Technician Information**

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| STRATA Drilling Group | 7141 |
| **Business Address (Street Number/Name)** | **Municipality** |
| 165 Shields Ct | Markham |
| **Province** | **Postal Code** | **Business E-mail Address** |
| ON | L3R8V2 | Records@STRATAGeol.com |
| **Bus. Telephone No. (inc. area code)** | **Name of Well Technician (Last Name, First Name)** |
| 905 940 7949 | Beatty, Brian |
| **Well Technician's Licence No.** | **Signature of Technician and/or Contractor** | **Date Submitted** |
| 3611 | | 2019 04 30 |

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered: Y Y Y Y M M D D

Date Work Completed: 2019 03 27

**Ministry Use Only**

Audit No. Z311181

JUN 14 2019

Received

0506E (2018/12)

Ministry's Copy

© Queen's Printer for Ontario, 2018

Ontario

Ministry of the Environment, Conservation and Parks

Measurements recorded in: ☑ Metric ☐ Imperial

**Well Tag No.** *(Place Sticker and/or Print Below)* A302969

5-26399

# Well Record

***Regulation 903 Ontario Water Resources Act***

Page _____ of _____

## Well Owner's Information

| First Name | Last Name / Organization | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| | Somerset & O'Conner LTD | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. *(inc. area code)* |
|---|---|---|---|---|
| 252 Argyle Ave | Ottawa | ON | K2P1B9 | |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| 311 Somerset st W | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | Ottawa | Ontario | |

| UTM Coordinates | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| NAD | 18 | 445647 | 5029419 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| Dry | Gravel | | hard | 0 | 2 |
| dry/brn | Gravel | Fill | hard | 2 | 5 |
| gry | Silt | Clay | Soft | 5 | 9 |
| gry | Clay | | Soft / wet | 9 | 20 |

## Annular Space

| Depth Set at (m/ft) From | To | Type of Sealant Used *(Material and Type)* | Volume Placed ($m^3$/$ft^3$) |
|---|---|---|---|
| 0 | 1 | Concrete/ flush mount | |
| 1 | 9 | Benseal | |
| 9 | 20 | Sand | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☒ Other, *specify* DP

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☒ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 2.047 | PVC | 0.154 | 0 | 10 |
| | | | | |
| | | | | |
| | | | | |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 2.375 | PVC | 10 | 10 | 20 |
| | | | | |

## Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

## Water Details

| Water found at Depth (m/ft) | ☐ Gas | Kind of Water: ☐ Fresh ☐ Untested ☐ Other, *specify* |
|---|---|---|
| | | |
| | | |
| | | |

## Hole Diameter

| Depth (m/ft) From | To | Diameter (cm/in) |
|---|---|---|
| 0 | 20 | 4.5 |
| | | |
| | | |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping _____ hrs + _____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*

Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

| | Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|---|
| Static Level | | | | |
| 1 | | | 1 | |
| 2 | | | 2 | |
| 3 | | | 3 | |
| 4 | | | 4 | |
| 5 | | | 5 | |
| 10 | | | 10 | |
| 15 | | | 15 | |
| 20 | | | 20 | |
| 25 | | | 25 | |
| 30 | | | 30 | |
| 40 | | | 40 | |
| 50 | | | 50 | |
| 60 | | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.

See map

Comments:

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Strata Drilling Group | 7241 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 129 Ringwood Ave | Stouffville |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| ON | L4A8C1 | Wrecords@Stratagal.com |

| Bus. Telephone No. *(inc. area code)* | Name of Well Technician (Last Name, First Name) |
|---|---|
| 9055940799 | Beatty, Brian |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted |
|---|---|---|
| 3616 | | |

| Well owner's information package delivered | Date Package Delivered | Date Work Completed |
|---|---|---|
| ☐ Yes ☐ No | | 2021/03/19 |

**Ministry Use Only**


Audit No. Z338246

Received MAR 18 2021

0506E (2018/12)

**Ministry's Copy**

© Queen's Printer for Ontario, 2018




N↑

C-XXX/
433246

MAR 18 2021

Ontario — Ministry of the Environment, Conservation and Parks

# Well Record

*Regulation 903 Ontario Water Resources Act*

**Well Tag No.** (Place Sticker and/or Print Below) A302968 5-26399

Measurements recorded in: ☑ Metric ☐ Imperial

Page _____ of _____

## Well Owner's Information

| First Name | Last Name/Organization | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| | Somerset & O'connor LTD | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. (inc. area code) |
|---|---|---|---|---|
| 252 Argyle Ave | Ottawa | ON | K2P 1B9 | |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| 311 Somerset St W | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | Ottawa | Ontario | |

| UTM Coordinates | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| NAD 83 | 18 | 445633 | 5029462 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| Gry | Gravel | | dense | 0 | 2 |
| Gry/brn | Fill | | dense | 2 | 4 |
| Gry | Silt | Clay | Soft | 4 | 10 |
| Gry | Clay | | Soft/wet | 10 | 22.5 |

## Annular Space

| Depth Set at (m/ft) From | To | Type of Sealant Used (Material and Type) | Volume Placed (m³/ft³) |
|---|---|---|---|
| 0 | 1 | Concrete/flush mount | |
| 1 | 11.5 | Bensea1 | |
| 11.5 | 22.5 | Sand | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☒ Other, specify DP

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☒ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 2.047 | PVC | 0.154 | 0 | 22.5 |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 2.37 | PVC | 10 | 12.5 | 22.5 |

## Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

## Water Details

| Water found at Depth (m/ft) | Gas | Kind of Water: Fresh Untested / Other, specify |
|---|---|---|
| | | |
| | | |
| | | |

## Hole Diameter

| Depth (m/ft) From | To | Diameter (cm/in) |
|---|---|---|
| 0 | 22.5 | 4.5 |
| | | |
| | | |

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Strata Drilling Group | 7241 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 129 Ringwood dr | Stouffville |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| ON | L4A8C1 | Wrecords@Stratasoil.com |

| Bus. Telephone No. (inc. area code) | Name of Well Technician (Last Name, First Name) |
|---|---|
| 9059407919 | Beatty, Brian |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted |
|---|---|---|
| 3616 | | |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify _____

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping _____ hrs + _____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min/GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min/GPM)

Well production (l/min/GPM)

Disinfected? ☐ Yes ☐ No

| | Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|---|
| Static Level | | | | |
| 1 | | | 1 | |
| 2 | | | 2 | |
| 3 | | | 3 | |
| 4 | | | 4 | |
| 5 | | | 5 | |
| 10 | | | 10 | |
| 15 | | | 15 | |
| 20 | | | 20 | |
| 25 | | | 25 | |
| 30 | | | 30 | |
| 40 | | | 40 | |
| 50 | | | 50 | |
| 60 | | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.

See map

Comments:

| Well owner's information package delivered | Date Package Delivered | Date Work Completed |
|---|---|---|
| ☐ Yes ☐ No | | 2021/02/09 |


**Ministry Use Only**

Audit No. Z343100

MAR 17 2021 Received

 © Queen's Printer for Ontario, 2020

**Ministry's Copy**




N

MAR 17 2021
C7241
Z343100

5-26872

Ontario — Ministry of the Environment, Conservation and Parks

# Well Record

Regulation 903 Ontario Water Resources Act

Well Tag No. (Place Sticker and/or Print Below): A302972 Tag#:A302972

Measurements recorded in: ☑ Metric ☐ Imperial

Page ____ of ____

## Well Owner's Information

| First Name | Last Name/Organization | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| | Somerset & O'Connor | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. (inc. area code) |
|---|---|---|---|---|
| 252 Argyle Ave | Ottawa | ON | K2P1B9 | |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| 311 Somerset | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | Ottawa | Ontario | |

| UTM Coordinates | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| NAD 83 | 18 | 445653 | 5029431 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| GRY | gravel | sand | loose | 0 | .3 |
| BRN | sand | gravel | soft | .3 | 2.74 |
| BRN | clay | sand | soft | 2.74 | 3.96 |
| GRY | clay | silt | soft, wet | 3.96 | 10.67 |
| GRY | silt | gravel, shale | dense | 10.67 | 13.1 |

## Annular Space

| Depth Set at (m/ft) From | To | Type of Sealant Used (Material and Type) | Volume Placed ($m^3$/$ft^3$) |
|---|---|---|---|
| 0 | .3 | concrete/cement | |
| .3 | 9.75 | bentonite | |
| 9.75 | 13.1 | Filter sand | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☑ Air percussion
☐ Other, specify

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 5.20 | PVC | .340 | 0 | 10.05 |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 6.03 | PVC | 10 | 10.05 | 13.1 |

## Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

## Water Details

| Water found at Depth (m/ft) | Gas | Kind of Water: ☐ Fresh ☐ Untested ☐ Other, specify |
|---|---|---|
| | ☐ | |
| | ☐ | |
| | ☐ | |

## Hole Diameter

| Depth (m/ft) From | Depth (m/ft) To | Diameter (cm/in) |
|---|---|---|
| 0 | 13.1 | 11.43 |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min/GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min/GPM)


Well production (l/min/GPM)

Disinfected? ☐ Yes ☐ No

| | Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|---|
| Static Level | | | | |
| 1 | | | 1 | |
| 2 | | | 2 | |
| 3 | | | 3 | |
| 4 | | | 4 | |
| 5 | | | 5 | |
| 10 | | | 10 | |
| 15 | | | 15 | |
| 20 | | | 20 | |
| 25 | | | 25 | |
| 30 | | | 30 | |
| 40 | | | 40 | |
| 50 | | | 50 | |
| 60 | | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.




Comments:

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Strata Drilling Group | 7241 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 129 Ringwood Dr. | Stouffville |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| ON | L4A8C1 | wrecord@stradasoil.com |

| Bus. Telephone No. (inc. area code) | Name of Well Technician (Last Name, First Name) |
|---|---|
| 9059467919 | Milly, James |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted |
|---|---|---|
| 7107 | | |

| Well owner's information package delivered | Date Package Delivered | Date Work Completed |
|---|---|---|
| ☐ Yes ☐ No | | 2021/05/26 |

**Ministry Use Only**

Addit No. Z364080

Received JUN 29 2021

0506E (2020/06) © Queen's Printer for Ontario, 2020

**Ministry's Copy**

Ontario — Ministry of the Environment, Conservation and Parks

# Well Record

Well Tag No. (Place Sticker and/or Print Below): A302973 Tag#:A302973

...ation 903 Ontario Water Resources Act

Measurements recorded in: ☑ Metric ☐ Imperial

Page _____ of _____

## Well Owner's Information

| First Name | Last Name/Organization | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| | Somerset & O'Conner | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. (inc. area code) |
|---|---|---|---|---|
| 252 Argyle Ave | Ottawa | ON | K2P1B9 | |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| 311 Somerset | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | Ottawa | Ontario | |

| UTM Coordinates | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| NAD 83 | 18 | 445630 | 5029428 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| GRY | gravel | sand | loose | 0 | .31 |
| BRN | sand | gravel | soft | .31 | 2.44 |
| BRN | clay | sand | soft | 2.44 | 3.66 |
| GRY | clay | silt | soft, wet | 3.66 | 11.28 |
| GRY | silt | gravel, shale | dense | 11.28 | 13.1 |

## Annular Space

| Depth Set at (m/ft) From | To | Type of Sealant Used (Material and Type) | Volume Placed (m³/ft³) |
|---|---|---|---|
| 0 | .31 | concrete/Bentonite | |
| .31 | 9.75 | Bentonite | |
| 9.75 | 13.1 | filter sand | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☑ Air percussion
☐ Other, specify _____

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify _____

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 5.20 | PVC | .390 | 0 | 10.05 |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 6.03 | PVC | 10 | 10.05 | 13.1 |

## Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

## Water Details

| Water found at Depth (m/ft) ☐ Gas | Kind of Water: ☐ Fresh ☐ Untested ☐ Other, specify |
|---|---|
| Water found at Depth (m/ft) ☐ Gas | Kind of Water: ☐ Fresh ☐ Untested ☐ Other, specify |
| Water found at Depth (m/ft) ☐ Gas | Kind of Water: ☐ Fresh ☐ Untested ☐ Other, specify |

## Hole Diameter

| Depth (m/ft) From | Depth (m/ft) To | Diameter (cm/in) |
|---|---|---|
| 0 | 13.1 | 11.43 |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify _____

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping _____ hrs + _____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min/GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min/GPM)


Well production (l/min/GPM)

Disinfected? ☐ Yes ☐ No

| | Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|---|
| Static Level | | | | |
| 1 | | | 1 | |
| 2 | | | 2 | |
| 3 | | | 3 | |
| 4 | | | 4 | |
| 5 | | | 5 | |
| 10 | | | 10 | |
| 15 | | | 15 | |
| 20 | | | 20 | |
| 25 | | | 25 | |
| 30 | | | 30 | |
| 40 | | | 40 | |
| 50 | | | 50 | |
| 60 | | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.




Comments:

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Stratas Drilling Group | 7241 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 129 Ringwood Dr. | Stouffville |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| ON | L4A8C1 | awrecord@stratasinl.com |

| Bus. Telephone No. (inc. area code) | Name of Well Technician (Last Name, First Name) |
|---|---|
| 9059487919 | McCoy, James |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted Y Y Y Y M M D D |
|---|---|---|
| 7108 | | |

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered Y Y Y Y M M D D

Date Work Completed 2021 05 26

**Ministry Use Only**

Audit No. Z364081

Received JUN 29 2021

0506E (2020/06) © Queen's Printer for Ontario, 2020

**Ministry's Copy**

Ontario — Ministry of the Environment, Conservation and Parks

# Well Record

...ation 903 Ontario Water Resources Act

Measurements recorded in: ☑ Metric ☐ Imperial

**Well Tag No.** (Place Sticker and/or Print Below) A302951 Tag#:A302951

Page _____ of _____

## Well Owner's Information

| First Name | Last Name/Organization | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| | Somerset & O'Connor | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. (inc. area code) |
|---|---|---|---|---|
| 252 Argyle Ave | Ottawa | ON | K2P1B9 | |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| 311 Somerset | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | Ottawa | Ontario | |

| UTM Coordinates NAD 83 | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| | 18 | 445624 | 5029452 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| BRN | top soil | | soft | 0 | .31 |
| BRN | sand | gravel | soft | .31 | 2.13 |
| BRN | clay | sand | soft | 2.13 | 3.66 |
| GRY | clay | silt | soft, wet | 3.66 | 10.36 |
| GRY | silt | gravel, shale | dense | 10.36 | 14.33 |

## Annular Space

| Depth Set at (m/ft) From | To | Type of Sealant Used (Material and Type) | Volume Placed ($m^3$/$ft^3$) |
|---|---|---|---|
| 0 | .31 | cement/bentonite | |
| .31 | 10.97 | bentonite | |
| 10.97 | 14.33 | filter sand | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, specify _____

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify _____

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | To |
|---|---|---|---|---|
| 10 | PVC | .390 | 0 | 11.28 |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | To |
|---|---|---|---|---|
| 6.03 | PVC | 10 | 11.28 | 14.33 |

## Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

## Water Details

| Water found at Depth (m/ft) | Gas | Kind of Water: ☐ Fresh ☐ Untested ☐ Other, specify |
|---|---|---|
| | | |
| | | |
| | | |

## Hole Diameter

| Depth (m/ft) From | To | Diameter (cm/in) |
|---|---|---|
| 0 | 14.33 | 11.43 |

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Strata Drilling Group | 7214 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 129 Ringwood Dr | Stouffville |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| Ont | L4A8C1 | wlrecord@stratasoil.com |

| Bus. Telephone No. (inc. area code) | Name of Well Technician (Last Name, First Name) |
|---|---|
| 9059407917 | McCoy, James |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted Y Y Y Y M M D D |
|---|---|---|
| 7210 | | |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify _____

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping _____ hrs + _____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min/GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min/GPM)


Well production (l/min/GPM)

Disinfected? ☐ Yes ☐ No

| | Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|---|
| Static Level | | | | |
| 1 | | | 1 | |
| 2 | | | 2 | |
| 3 | | | 3 | |
| 4 | | | 4 | |
| 5 | | | 5 | |
| 10 | | | 10 | |
| 15 | | | 15 | |
| 20 | | | 20 | |
| 25 | | | 25 | |
| 30 | | | 30 | |
| 40 | | | 40 | |
| 50 | | | 50 | |
| 60 | | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.




Comments:

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered Y Y Y Y M M D D

Date Work Completed 2021 05 25

**Ministry Use Only**

Audit No. Z364138

Received JUN 29 2021

0506E (2020/06) © Queen's Printer for Ontario, 2020

**Ministry's Copy**

Ontario — Ministry of the Environment, Conservation and Parks

Measurements recorded in: ☑ Metric ☐ Imperial

Well Tag No. (Place Sticker and/or Print Below): 1302952 | Tag#:A302952

# Well Record

Regulation 903 Ontario Water Resources Act

Page ____ of ____

## Well Owner's Information

| First Name | Last Name/Organization | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| | Somerset & O'Connor | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. (inc. area code) |
|---|---|---|---|---|
| 252 Argyle Ave | Ottawa | ON | K2P1B9 | |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| 311 Somerset | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | Ottawa | Ontario | |

| UTM Coordinates | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| NAD 83 | 18 | 445647 | 5029441 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| GRY | gravel | sand | loose | 0 | .31 |
| BRN | sand | gravel | soft | .31 | 2.74 |
| BRN | clay | sand | soft | 2.74 | 3.35 |
| GRY | clay | silt | soft | 3.35 | 11.28 |
| GRY | silt | gravel, shale | dense | 11.28 | 14.94 |

## Annular Space

| Depth Set at (m/ft) From | Depth Set at (m/ft) To | Type of Sealant Used (Material and Type) | Volume Placed (m³/ft³) |
|---|---|---|---|
| 0 | .31 | concrete/Bushmat | |
| .31 | 11.58 | bentonite | |
| 11.58 | 14.94 | filter sand | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☑ Air percussion
☐ Other, specify ____

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☑ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify ____

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 5.20 | PVC | .390 | 0 | 11.89 |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 6.03 | PVC | 10 | 11.89 | 14.94 |

## Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

## Water Details

| Water found at Depth (m/ft) | Gas | Kind of Water | Other, specify |
|---|---|---|---|
| | ☐ | ☐ Fresh ☐ Untested | |
| | ☐ | ☐ Fresh ☐ Untested | |
| | ☐ | ☐ Fresh ☐ Untested | |

## Hole Diameter

| Depth (m/ft) From | Depth (m/ft) To | Diameter (cm/in) |
|---|---|---|
| 0 | 14.94 | 11.43 |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify ____

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min/GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min/GPM)


Well production (l/min/GPM)

Disinfected? ☐ Yes ☐ No

| Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|
| Static Level | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 50 | | 50 | |
| 60 | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.




Comments:

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Strata Drilling Group | 7241 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 129 Ringwood Dr | Stouffville |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| Ont | L4A8C1 | wrecord@stratasoil.com |

| Bus. Telephone No. (inc. area code) | Name of Well Technician (Last Name, First Name) |
|---|---|
| 9059407917 | McCoy, James |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted |
|---|---|---|
| 7107 | | |

Well owner's information package delivered: ☐ Yes ☐ No

Date Package Delivered: ____

Date Work Completed: 2021/05/25

**Ministry Use Only**

Audit No. Z364139

Received JUN 29 2021

0506E (2020/06) © Queen's Printer for Ontario, 2020

**Ministry's Copy**

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473693
Well Audit Number: *Z398871*
Well Tag Number: *A384758*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | |
|---|---|
| **Address of Well Location** | |
| **Township** | NEPEAN TOWNSHIP |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445801.00<br>Northing: 5029304.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed | |
|---|---|---|---|---|
| | | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use | |
|---|---|---|
| | | |
| | | |
| | | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To | |
|---|---|---|---|---|
| | | | | |
| | | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z398871

**Date Well Completed:** January 18, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473694
Well Audit Number: *Z425449*
Well Tag Number: *A400061*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | | |
|---|---|---|
| **Address of Well Location** | | |
| **Township** | NEPEAN TOWNSHIP | |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445773.00<br>Northing: 5029390.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed | |
|---|---|---|---|---|
| | | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use | |
|---|---|---|
| | | |
| | | |
| | | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To | |
|---|---|---|---|---|
| | | | | |
| | | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z425449

**Date Well Completed:** January 16, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473695
Well Audit Number: *Z425450*
Well Tag Number: *A400062*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | | |
|---|---|---|
| **Address of Well Location** | | |
| **Township** | NEPEAN TOWNSHIP | |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445773.00<br>Northing: 5029394.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed |
|---|---|---|---|
| | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use |
|---|---|
| | |
| | |
| | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z425450

**Date Well Completed:** January 16, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario Ministry of the Environment

A 054894

# The Ontario Water Resources Act
# WATER WELL RECORD

Print only in spaces provided.
Mark correct box with a checkmark, where applicable.

11 (1 2)

Municipality (10 14) Con. (13 22 23 24)

| County or District | Township/Borough/City/Town/Village | Con block tract survey, etc. | Lot (25-27) |
|---|---|---|---|
| CANADA | Ottawa | | |

| Owner's surname (28-47) | First Name | Address | Date completed (48-53) |
|---|---|---|---|
| [redacted] | | 190 & 192 SOMERSET STREET WEST | 27 day 10 month 09 year |

21 (1 2)

UTM Zone (10) 18 Easting (12-17) 445965 Northing (18-24) 5029573 RC (25) Elevation (26-30) RC (30) Basin Code (31-47) I II III IV

## LOG OF OVERBURDEN AND BEDROCK MATERIALS (see instructions)

| General colour | Most common material | Other materials | General description | Depth - feet From | Depth - feet To |
|---|---|---|---|---|---|
| BHMW4 | | | | | |
| | | | | | |
| BLACK | ASPHALT | | | 0 | 0.25 |
| BROWN | Sand and Gravel | | | 0.25 | 3 |
| BROWN | Sand | some silt, trace gravel | | 3 | 5.5 |
| GREY | Clay | trace silt | | 5.5 | 20 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

31 (10 14 15 21) 32 (32 43 54 65 75 80)

## 41 WATER RECORD

| Water found at - feet (10-13) | Kind of water (14) | (60) |
|---|---|---|
| 19.46 | 1 ☒ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 6 ☐ Gas | |
| (15-18) | 1 ☐ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 6 ☐ Gas (19) | |
| (20-23) | 1 ☐ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 6 ☐ Gas (24) | |
| (25-28) | 1 ☐ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 6 ☐ Gas (29) | |
| (30-33) | 1 ☐ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 6 ☐ Gas (34) | |

## 51 CASING & OPEN HOLE RECORD

| Inside diam inches | Material | Wall thickness inches | Depth - feet From | Depth - feet To |
|---|---|---|---|---|
| (10-11) 2 | (12) 1 ☐ Steel 2 ☐ Galvanized 3 ☐ Concrete 4 ☐ Open hole 5 ☒ Plastic | 1/4" | 0 | (13-16) 20.34 |
| (17-18) | (19) 1 ☐ Steel 2 ☐ Galvanized 3 ☐ Concrete 4 ☐ Open hole 5 ☐ Plastic | | | (20-23) |
| (24-25) | (26) 1 ☐ Steel 2 ☐ Galvanized 3 ☐ Concrete 4 ☐ Open hole 5 ☐ Plastic | | | (27-30) |

## SCREEN

| Sizes of opening (Slot No.) (31-33) | Diameter (34-38) | Length (39-40) |
|---|---|---|
| 10 | 2 inches | 10 feet |

| Material and type | Depth at top of screen (41-44) (30) |
|---|---|
| Plastic | 10.34 feet |

## 61 PLUGGING & SEALING RECORD

☒ Annular space ☐ Abandonment

| Depth set at - feet From (13) | To (14-17) | Material and type (Cement grout, bentonite, etc.) |
|---|---|---|
| 0 | 9 | Bentonite |
| 9 (18-21) | 20.34 (22-25) | Sand |
| (26-29) | (30-33) (80) | |

## 71 PUMPING TEST

| Pumping test method (10) 1 ☐ Pump 2 ☐ Bailer | Pumping rate (11-14) GPM | Duration of pumping (15-16) Hours (17-18) Mins |
|---|---|---|

| Static level (19-21) feet | Water level end of pumping (22-24) feet | Water levels during (25) 1 ☐ Pumping 2 ☐ Recovery | |
|---|---|---|---|
| | | 15 minutes (26-28) feet | 30 minutes (29-31) feet |
| | | 45 minutes (32-34) feet | 60 minutes (35-37) feet |

| If flowing give rate (38-41) GPM | Pump intake set at feet | Water at end of test (42) ☐ Clear ☐ Cloudy |
|---|---|---|
| Recommended pump type ☐ Shallow ☐ Deep | Recommended pump setting (43-45) feet | Recommended pump rate (46-49) GPM |

(50-53)

## FINAL STATUS OF WELL (54)

1 ☐ Water supply 2 ☐ Observation well 3 ☒ Test hole 4 ☐ Recharge well 5 ☐ Abandoned, insufficient supply 6 ☐ Abandoned, poor quality 7 ☐ Abandoned (Other) 8 ☐ Dewatering 9 ☐ Unfinished 10 ☐ Replacement well

## WATER USE (55-56)


1 ☐ Domestic 2 ☐ Stock 3 ☐ Irrigation 4 ☐ Industrial 5 ☐ Commercial 6 ☐ Municipal 7 ☐ Public supply 8 ☐ Cooling & air conditioning 9 ☐ Not use 10 ☐ Other

## METHOD OF CONSTRUCTION (57)

1 ☐ Cable tool 2 ☐ Rotary (conventional) 3 ☐ Rotary (reverse) 4 ☐ Rotary (air) 5 ☐ Air percussion 6 ☒ Boring 7 ☐ Diamond 8 ☐ Jetting 9 ☐ Driving 10 ☐ Digging 11 ☐ Other

## LOCATION OF WELL

In diagram below show distances of well from road and lot line.
Indicate north by arrow.




239796

| Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| DST Consulting Engineers Inc | 6838 |
| Address: 605 Hewitson St, Thunder Bay, ON, P7B 5V5 | |
| Name of Well Technician: Nicholas Norton | Well Technician's Licence No.: 2099 |
| Signature of Technician/Contractor | Submission date: 20 day 11 mo 09 yr |

## MINISTRY USE ONLY

| Data source (58) | Contractor (59-62) | Date received (63-68) NOV 27 2009 (80) |
|---|---|---|
| Date of inspection | Inspector | |
| Remarks | | |

0506 (07/00) Front Form 9

2 - MINISTRY OF THE ENVIRONMENT COPY

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473722
Well Audit Number: *Z413372*
Well Tag Number: *A400087*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | | |
|---|---|---|
| **Address of Well Location** | | |
| **Township** | NEPEAN TOWNSHIP | |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445769.00<br>Northing: 5029400.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed |
|---|---|---|---|
| | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use |
|---|---|
| | |
| | |
| | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z413372

**Date Well Completed:** February 21, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473723
Well Audit Number: *Z413371*
Well Tag Number: *A400086*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | | |
|---|---|---|
| **Address of Well Location** | | |
| **Township** | OTTAWA CITY | |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445772.00<br>Northing: 5029388.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed |
|---|---|---|---|
| | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use |
|---|---|
| | |
| | |
| | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z413371

**Date Well Completed:** February 21, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473724
Well Audit Number: *Z412883*
Well Tag Number: *A400085*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | | |
|---|---|---|
| **Address of Well Location** | | |
| **Township** | NEPEAN TOWNSHIP | |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445765.00<br>Northing: 5029390.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed |
|---|---|---|---|
| | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use |
|---|---|
| | |
| | |
| | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z412883

**Date Well Completed:** February 21, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473725
Well Audit Number: *Z412884*
Well Tag Number: *A400084*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | | |
|---|---|---|
| **Address of Well Location** | | |
| **Township** | NEPEAN TOWNSHIP | |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445769.00<br>Northing: 5029395.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed | |
|---|---|---|---|---|
| | | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use | |
|---|---|---|
| | | |
| | | |
| | | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To | |
|---|---|---|---|---|
| | | | | |
| | | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z412884

**Date Well Completed:** February 20, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473726
Well Audit Number: *Z412885*
Well Tag Number: *A400083*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | | |
|---|---|---|
| **Address of Well Location** | | |
| **Township** | NEPEAN TOWNSHIP | |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445784.00<br>Northing: 5029386.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed | |
|---|---|---|---|---|
| | | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use | |
|---|---|---|
| | | |
| | | |
| | | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To | |
|---|---|---|---|---|
| | | | | |
| | | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z412885

**Date Well Completed:** February 20, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473727
Well Audit Number: *Z425489*
Well Tag Number: *A400082*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | | |
|---|---|---|
| **Address of Well Location** | | |
| **Township** | NEPEAN TOWNSHIP | |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445786.00<br>Northing: 5029387.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed | |
|---|---|---|---|---|
| | | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use | |
|---|---|---|
| | | |
| | | |
| | | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To | |
|---|---|---|---|---|
| | | | | |
| | | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z425489

**Date Well Completed:** February 20, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario (https://www.ontario.ca/page/government-ontario)

# Map: Well records

This map allows you to search and view well record information from reported wells in Ontario.

Full dataset is available in the Open Data catalogue (https://data.ontario.ca/dataset/well-records) .

---

Go Back to Map

## Well ID

Well ID Number: 7473728
Well Audit Number: *Z425488*
Well Tag Number: *A400081*
*This table contains information from the original well record and any subsequent updates.*

## Well Location

| | |
|---|---|
| **Address of Well Location** | |
| **Township** | NEPEAN TOWNSHIP |

| | |
|---|---|
| **Lot** | |
| **Concession** | |
| **County/District/Municipality** | OTTAWA-CARLETON |
| **City/Town/Village** | |
| **Province** | ON |
| **Postal Code** | n/a |
| **UTM Coordinates** | NAD83 — Zone 18<br>Easting: 445798.00<br>Northing: 5029381.00 |
| **Municipal Plan and Sublot Number** | |
| **Other** | |

# Overburden and Bedrock Materials Interval

| General Colour | Most Common Material | Other Materials | General Description | Depth From | Depth To |
|---|---|---|---|---|---|
| | | | | | |

# Annular Space/Abandonment Sealing Record

| Depth From | Depth To | Type of Sealant Used (Material and Type) | Volume Placed | |
|---|---|---|---|---|
| | | | | |

# Method of Construction & Well Use

| Method of Construction | Well Use | |
|---|---|---|
| | | |
| | | |
| | | |

# Status of Well

# Construction Record - Casing

| Inside Diameter | Open Hole or material | Depth From | Depth To | |
|---|---|---|---|---|
| | | | | |
| | | | | |

# Construction Record - Screen

| Outside Diameter | Material | Depth From | Depth To |
|---|---|---|---|
| | | | |
| | | | |

# Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

# Results of Well Yield Testing

| | |
|---|---|
| **After test of well yield, water was** | |
| **If pumping discontinued, give reason** | |
| **Pump intake set at** | |
| **Pumping Rate** | |
| **Duration of Pumping** | |
| **Final water level** | |
| **If flowing give rate** | |

| | |
|---|---|
| **Recommended pump depth** | |
| **Recommended pump rate** | |
| **Well Production** | |
| **Disinfected?** | |

### Draw Down & Recovery

| Draw Down Time(min) | Draw Down Water level | Recovery Time(min) | Recovery Water level |
|---|---|---|---|
| SWL | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |

| | | | |
|---|---|---|---|
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 45 | | 45 | |
| 50 | | 50 | |
| 60 | | 60 | |
| | | | |

### Water Details

| Water Found at Depth | Kind |
|---|---|
| | |
| | |
| | |

### Hole Diameter

| Depth From | Depth To | Diameter |
|---|---|---|

| | | |
|---|---|---|
| | | |
| | | |
| | | |

**Audit Number:** Z425488

**Date Well Completed:** February 20, 2024

**Date Well Record Received by MOE:** March 22, 2024

## Related

How to use a Ministry of the Environment map (https://www.ontario.ca/page/how-use-ministry-environment-map#wells)

Technical documentation: Metadata record (https://data.ontario.ca/dataset/well-records/resource/3031344e-e3f2-48d5-888c-c1deadfd2f77)

Updated: January 10, 2024
Published: March 20, 2014

Ontario Ministry of the Environment

# The Ontario Water Resources Act
# WATER WELL RECORD

A 054894

Print only in spaces provided.
Mark correct box with a checkmark, where applicable.

11

Municipality | Con.

| County or District | Township/Borough/City/Town/Village | Con block tract survey, etc. | Lot |
|---|---|---|---|
| CANADA | Ottawa | | |

| Owner's surname | First Name | Address | Date completed |
|---|---|---|---|
| [redacted] | | 190 + 192 SOMERSET ST WEST | 27 day 10 month 09 year |

21 | UTM Zone 18 | Easting 445979 | Northing 5029558 | RC | Elevation | RC | Basin Code | ii | iii | iv

## LOG OF OVERBURDEN AND BEDROCK MATERIALS (see instructions)

| General colour | Most common material | Other materials | General description | Depth - feet From | Depth - feet To |
|---|---|---|---|---|---|
| BHMW3 | | | | | |
| BLACK | Asphalt | | | 0 | 0.21 |
| ~~BROWN~~ | | | | ~~0.21~~ | |
| BROWN | Sand and Gravel | | | 0.21 | ~~4.5~~ |
| GREY | Clay | trace silt and Gravel | | ~~4.5~~ 4.5 | ~~27~~ 27 |

31

32

## 41 WATER RECORD

| Water found at - feet | Kind of water |
|---|---|
| 23.10 | 1 [x] Fresh 2 [ ] Salty 3 [ ] Sulphur 4 [ ] Minerals 6 [ ] Gas |
| | 1 [ ] Fresh 2 [ ] Salty 3 [ ] Sulphur 4 [ ] Minerals 6 [ ] Gas |
| | 1 [ ] Fresh 2 [ ] Salty 3 [ ] Sulphur 4 [ ] Minerals 6 [ ] Gas |
| | 1 [ ] Fresh 2 [ ] Salty 3 [ ] Sulphur 4 [ ] Minerals 6 [ ] Gas |
| | 1 [ ] Fresh 2 [ ] Salty 3 [ ] Sulphur 4 [ ] Minerals 6 [ ] Gas |

## 51 CASING & OPEN HOLE RECORD

| Inside diam inches | Material | Wall thickness inches | Depth - feet From | Depth - feet To |
|---|---|---|---|---|
| 2" | 1 [ ] Steel 2 [ ] Galvanized 3 [ ] Concrete 4 [ ] Open hole 5 [x] Plastic | 1/4" | 0 | 25.26 |
| | 1 [ ] Steel 2 [ ] Galvanized 3 [ ] Concrete 4 [ ] Open hole 5 [ ] Plastic | | | |
| | 1 [ ] Steel 2 [ ] Galvanized 3 [ ] Concrete 4 [ ] Open hole 5 [ ] Plastic | | | |

## SCREEN

| Sizes of opening (Slot No.) | Diameter | Length |
|---|---|---|
| 10 | 2 inches | 10 feet |

Material and type: Plastic

Depth at top of screen: 15 feet

## 61 PLUGGING & SEALING RECORD

[x] Annular space [ ] Abandonment

| Depth set at - feet From | Depth set at - feet To | Material and type (Cement grout, bentonite, etc.) |
|---|---|---|
| 0 | ~~16~~ 15 | BENTONITE |
| ~~16~~ 15 | 25 | SAND |

## 71 PUMPING TEST

Pumping test method: 1 [ ] Pump 2 [ ] Bailer

Pumping rate: GPM

Duration of pumping: Hours Mins

| Static level | Water level end of pumping | Water levels during: 1 [ ] Pumping 2 [ ] Recovery | | | |
|---|---|---|---|---|---|
| feet | feet | 15 minutes feet | 30 minutes feet | 45 minutes feet | 60 minutes feet |

If flowing give rate: GPM

Pump intake set at: feet

Water at end of test: [ ] Clear [ ] Cloudy


Recommended pump type: [ ] Shallow [ ] Deep

Recommended pump setting: feet

Recommended pump rate: GPM

## LOCATION OF WELL

In diagram below show distances of well from road and lot line. Indicate north by arrow.




239794

## FINAL STATUS OF WELL

1 [ ] Water supply
2 [ ] Observation well
3 [x] Test hole
4 [ ] Recharge well
5 [ ] Abandoned, insufficient supply
6 [ ] Abandoned, poor quality
7 [ ] Abandoned (Other)
8 [ ] Dewatering
9 [ ] Unfinished
10 [ ] Replacement well

## WATER USE

1 [ ] Domestic
2 [ ] Stock
3 [ ] Irrigation
4 [ ] Industrial
5 [ ] Commercial
6 [ ] Municipal
7 [ ] Public supply
8 [ ] Cooling & air conditioning
9 [ ] Not use
10 [ ] Other

## METHOD OF CONSTRUCTION

1 [ ] Cable tool
2 [ ] Rotary (conventional)
3 [ ] Rotary (reverse)
4 [ ] Rotary (air)
5 [ ] Air percussion
6 [x] Boring
7 [ ] Diamond
8 [ ] Jetting
9 [ ] Driving
10 [ ] Digging
11 [ ] Other

| Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| DST CONSULTING ENGINEERING INC | 6838 |
| Address: 605 Hewitson Street, Thunder Bay, ON, P7B 5V5 | |
| Name of Well Technician: Nicholas Norton | Well Technician's Licence No.: 2099 |
| Signature of Technician/Contractor | Submission date: 30 day 11 mo 09 yr |

## MINISTRY USE ONLY

| Data source | Contractor | Date received |
|---|---|---|
| | | NOV 27 2009 |

Date of inspection | Inspector

Remarks

0506 (07/00) Front Form 9

2 - MINISTRY OF THE ENVIRONMENT COPY

Ontario Ministry of the Environment

A 054894

# The Ontario Water Resources Act
# WATER WELL RECORD

Print only in spaces provided.
Mark correct box with a checkmark, where applicable.

11

Municipality

Con.

| County or District | Township/Borough/City/Town/Village | Con block tract survey, etc. | Lot |
|---|---|---|---|
| CANADA | Ottawa | | |

| Owner's surname | First Name | Address | Date completed |
|---|---|---|---|
| [redacted] | | 190+192 SOMERSET ST WEST | 27 day 10 month 09 year |

21

UTM Zone 18 | Easting 445973 | Northing 5029510 | RC | Elevation | RC | Basin Code

## LOG OF OVERBURDEN AND BEDROCK MATERIALS (see instructions)

| General colour | Most common material | Other materials | General description | Depth - feet From | Depth - feet To |
|---|---|---|---|---|---|
| BHMW1 | | | | | |
| BLACK | Asphalt | | | 0 | 0.25 |
| BROWN | Sand and Gravel | | | 0.25 | 2.5 |
| BROWN | Sand | some silt | | 2.5 | 5.5 |
| GREY | Clay | trace silt | | 5.5 | 16.5 |

31

32

## 41 WATER RECORD

| Water found at - feet | Kind of water |
|---|---|
| 10.3 | 1 Fresh 2 Salty 3 Sulphur 4 Minerals 6 Gas |
| | 1 Fresh 2 Salty 3 Sulphur 4 Minerals 6 Gas |
| | 1 Fresh 2 Salty 3 Sulphur 4 Minerals 6 Gas |
| | 1 Fresh 2 Salty 3 Sulphur 4 Minerals 6 Gas |

## 51 CASING & OPEN HOLE RECORD

| Inside diam inches | Material | Wall thickness inches | Depth - feet From | Depth - feet To |
|---|---|---|---|---|
| 2 | 5 Plastic | 1/4" | 0 | 16.5 |
| | | | | |
| | | | | |

## SCREEN

| Sizes of opening (Slot No.) | Diameter | Length |
|---|---|---|
| 10 | 2 inches | 5 feet |

Material and type: Plastic

Depth at top of screen: 16.5 feet

## 61 PLUGGING & SEALING RECORD

Annular space ☒ Abandonment ☐

| Depth set at - feet From | Depth set at - feet To | Material and type (Cement grout, bentonite, etc.) |
|---|---|---|
| 0 | 10 | BENTONITE |
| 10 | 16.5 | SAND |
| | | |

## 71 PUMPING TEST

Pumping test method: 1 Pump 2 Bailer

Pumping rate: GPM

Duration of pumping: Hours Mins

| Static level | Water level end of pumping | Water levels during: 1 Pumping 2 Recovery | | | |
|---|---|---|---|---|---|
| feet | feet | 15 minutes feet | 30 minutes feet | 45 minutes feet | 60 minutes feet |

If flowing give rate: GPM

Pump intake set at: feet

Water at end of test: Clear Cloudy


Recommended pump type: Shallow Deep

Recommended pump setting: feet

Recommended pump rate: GPM

## LOCATION OF WELL

In diagram below show distances of well from road and lot line.
Indicate north by arrow.




239793

## FINAL STATUS OF WELL

1 Water supply 2 Observation well 3 ☒ Test hole 4 Recharge well 5 Abandoned, insufficient supply 6 Abandoned, poor quality 7 Abandoned (Other) 8 Dewatering 9 Unfinished 10 Replacement well

## WATER USE

1 Domestic 2 Stock 3 Irrigation 4 Industrial 5 Commercial 6 Municipal 7 Public supply 8 Cooling & air conditioning 9 Not use 10 Other

## METHOD OF CONSTRUCTION

1 Cable tool 2 Rotary (conventional) 3 Rotary (reverse) 4 Rotary (air) 5 Air percussion 6 ☒ Boring 7 Diamond 8 Jetting 9 Driving 10 Digging 11 Other

| Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| DST CONSULTING ENGINEERS INC | 6838 |

Address: 605 Hewitson Street, Thunder Bay, ON, P7B 5V5

| Name of Well Technician | Well Technician's Licence No. |
|---|---|
| Nicholas Norton | 2099 |

Signature of Technician/Contractor

Submission date: 20 11 09 (day mo yr)

## MINISTRY USE ONLY

| Data source | Contractor | Date received |
|---|---|---|
| | | NOV 27 2009 |

Date of inspection | Inspector

Remarks

0506 (07/00) Front Form 9

2 - MINISTRY OF THE ENVIRONMENT COPY

Ontario — Ministry of the Environment

# The Ontario Water Resources Act
# WATER WELL RECORD

A0548944

Print only in spaces provided.
Mark correct box with a checkmark, where applicable.

11

Municipality | Con.

| County or District | Township/Borough/City/Town/Village | Con block tract survey, etc. | Lot |
|---|---|---|---|
| CANADA | Ottawa | | |
| Owner's surname [redacted] First Name | Address 190 & 192 Somerset Street West | Date completed 27 day 10 month 09 year | |

21 | UTM Zone 18 | Easting 445976 | Northing 5029535 | RC | Elevation | RC | Basin Code | ii | iii | iv

## LOG OF OVERBURDEN AND BEDROCK MATERIALS (see instructions)

| General colour | Most common material | Other materials | General description | Depth - feet From | Depth - feet To |
|---|---|---|---|---|---|
| Black | ASPHALT | | | 0 | 0.08 |
| Brown | Sand | Gravel | (Fill) | 0.08 | 2.5 |
| Brown | Sand | Some silt | | 2.5 | 5.5 |
| Grey | Clay | trace silt | | 5.5 | 16.5 |
| BHMW2 | | | | | |
| BLACK | Asphalt | | | 0 | 0.08 |
| Brown | Sand and gravel | | (Fill) | 0.08 | 2.5 |
| Brown | Sand | Some silt | | 2.5 | 6 |
| Grey | Clay | trace silt | | 6 | 20 |

31

32

## 41 WATER RECORD

| Water found at | Kind of water |
|---|---|
| BH/MW1 3.14 | 1 ☒ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 5 ☐ Gas |
| BHMW2 ~~3~~ | 1 ☒ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 5 ☐ Gas |
| BHMW2 10.16ft | 1 ☒ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 5 ☐ Gas |
| | 1 ☐ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 5 ☐ Gas |
| | 1 ☐ Fresh 2 ☐ Salty 3 ☐ Sulphur 4 ☐ Minerals 5 ☐ Gas |

## 51 CASING & OPEN HOLE RECORD

| Inside diam inches | Material | Wall thickness inches | Depth - feet From | Depth - feet To |
|---|---|---|---|---|
| 2 | 1 ☐ Steel 2 ☐ Galvanized 3 ☐ Concrete 4 ☐ Open hole 5 ☐ Plastic | 1/4" | 0 | 20 |
| | 1 ☐ Steel 2 ☐ Galvanized 3 ☐ Concrete 4 ☐ Open hole 5 ☐ Plastic | | | |
| | 1 ☐ Steel 2 ☐ Galvanized 3 ☐ Concrete 4 ☐ Open hole 5 ☐ Plastic | | | |

## SCREEN

| Sizes of opening (Slot No.) | Diameter | Length |
|---|---|---|
| 10 | 2 inches | 10 feet |

Material and type | Depth at top of screen feet

## 61 PLUGGING & SEALING RECORD

☐ Annular space ☐ Abandonment

| Depth set at - feet From | Depth set at - feet To | Material and type (Cement grout, bentonite, etc.) |
|---|---|---|
| 0 | 7 | BENTONITE |
| 7 | 20 | Sand |
| | | |

## 71 PUMPING TEST

Pumping test method: 1 ☐ Pump 2 ☐ Bailer | Pumping rate GPM | Duration of pumping ____ Hours ____ Mins

| Static level feet | Water level end of pumping feet | Water levels during: 1 ☐ Pumping 2 ☐ Recovery | | | |
|---|---|---|---|---|---|
| | | 15 minutes feet | 30 minutes feet | 45 minutes feet | 60 minutes feet |
| | | | | | |

If flowing give rate GPM | Pump intake set at feet | Water at end of test ☐ Clear ☐ Cloudy

Recommended pump type ☐ Shallow ☐ Deep | Recommended pump setting feet | Recommended pump rate GPM

## FINAL STATUS OF WELL

1 ☐ Water supply 2 ☐ Observation well 3 ☒ Test hole 4 ☐ Recharge well 5 ☐ Abandoned, insufficient supply 6 ☐ Abandoned, poor quality 7 ☐ Abandoned (Other) 8 ☐ Dewatering 9 ☐ Unfinished 10 ☐ Replacement well

## WATER USE


1 ☐ Domestic 2 ☐ Stock 3 ☐ Irrigation 4 ☐ Industrial 5 ☐ Commercial 6 ☐ Municipal 7 ☐ Public supply 8 ☐ Cooling & air conditioning 9 ☐ Not use 10 ☐ Other

## METHOD OF CONSTRUCTION

1 ☐ Cable tool 2 ☐ Rotary (conventional) 3 ☐ Rotary (reverse) 4 ☐ Rotary (air) 5 ☐ Air percussion 6 ☒ Boring 7 ☐ Diamond 8 ☐ Jetting 9 ☐ Driving 10 ☐ Digging 11 ☐ Other

## LOCATION OF WELL

In diagram below show distances of well from road and lot line. Indicate north by arrow.




239792

| Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| DST CONSULTING ENGINEERS | 6838 |
| Address: 1605 Hewitson Street, Thunder Bay, ON, P7B 5V5 | |
| Name of Well Technician: Nicholas Norton | Well Technician's Licence No.: 2099 |
| Signature of Technician/Contractor | Submission date: 20 day 11 mo 2009 yr |

## MINISTRY USE ONLY

| Data source | Contractor | Date received |
|---|---|---|
| | | NOV 27 2009 |
| Date of inspection | Inspector | |
| Remarks | | |

0506 (07/00) Front Form 9

2 - MINISTRY OF THE ENVIRONMENT COPY

Ontario Ministry of the Environment

Measurements recorded in: ☐ Metric ☐ Imperial

**Well Tag No.** *(Place Sticker and/or Print Below)* A152341

# Well Record

***Regulation 903 Ontario Water Resources Act***

Page 1 of 1

## Well Owner's Information

| First Name | Last Name / Organization | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| | City of Ottawa | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. *(inc. area code)* |
|---|---|---|---|---|
| 110 Laurier Ave. West | Ottawa | ON. | K1P1J1 | 613 5802424 |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | | Ontario | |

| UTM Coordinates | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| NAD 83 | 18 | 445650 | 5029430 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| BH 105 | Quick Grout + Cement | | | 57m | 0 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

## Annular Space

| Depth Set at (m/ft) From | Depth Set at (m/ft) To | Type of Sealant Used (Material and Type) | Volume Placed ($m^3$/$ft^3$) |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify* _____

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☐ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify* _____

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| | | | | |
| | | | | |

## Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☐ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☒ Abandoned, other, *specify* Removed
☐ Other, *specify*

## Water Details

| Water found at Depth (m/ft) | Kind of Water | Hole Diameter Depth (m/ft) From | Hole Diameter Depth (m/ft) To | Hole Diameter (cm/in) |
|---|---|---|---|---|
| ☐ Gas ☐ Other, *specify* | ☐ Fresh ☐ Untested | | | |
| ☐ Gas ☐ Other, *specify* | ☐ Fresh ☐ Untested | | | |
| ☐ Gas ☐ Other, *specify* | ☐ Fresh ☐ Untested | | | |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping _____ hrs + _____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*


Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

| Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|
| Static Level | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 50 | | 50 | |
| 60 | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.




Comments:

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Marathon Drilling Co. Ltd | 6894 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 6847 Hiram Dr. | OTT |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| ON | K4P1A2 | |

| Bus. Telephone No. *(inc. area code)* | Name of Well Technician (Last Name, First Name) |
|---|---|
| 6139220571 | Wright Terry |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted |
|---|---|---|
| 0715 | | 20130913 |

| Well owner's information package delivered | Date Package Delivered | Date Work Completed |
|---|---|---|
| ☐ Yes ☐ No | Y Y Y Y M M D D | Y Y Y Y M M D D |

**Ministry Use Only**

Audit No. Z096856

NOV 14 2013 Received

0506E (12/2007)

Ministry's Copy

© Queen's Printer for Ontario, 2007

Ontario — Ministry of the Environment

Measurements recorded in: ☐ Metric ☐ Imperial

**Well Tag No.** *(Place Sticker and/or Print Below)* A152336

# Well Record

*Regulation 903 Ontario Water Resources Act*

Page 1 of 1

## Well Owner's Information

| First Name | Last Name / Organization | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| | City of Ottawa | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. *(inc. area code)* |
|---|---|---|---|---|
| 110 Lawrence Ave West | Ottawa | ON | K1P 1J1 | 613 5802474 |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | | Ontario | |

| UTM Coordinates | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| NAD 83 | 18 | 445795 | 5029519 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| BH 103 | Quick Grout | + Cement | | 57m | 0 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

## Annular Space

| Depth Set at (m/ft) From | To | Type of Sealant Used (Material and Type) | Volume Placed ($m^3$/$ft^3$) |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify*

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☐ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | To |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | To |
|---|---|---|---|---|
| | | | | |
| | | | | |

## Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☐ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☒ Abandoned, other, *specify* Removed
☐ Other, *specify*

## Water Details

| Water found at Depth (m/ft) | Kind of Water: ☐ Fresh ☐ Untested ☐ Gas ☐ Other, *specify* |
|---|---|
| | |
| | |
| | |

## Hole Diameter

| Depth (m/ft) From | To | Diameter (cm/in) |
|---|---|---|
| | | |
| | | |
| | | |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify*

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping ____ hrs + ____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*


Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

| Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|
| Static Level | | | |
| 1 | | 1 | |
| 2 | | 2 | |
| 3 | | 3 | |
| 4 | | 4 | |
| 5 | | 5 | |
| 10 | | 10 | |
| 15 | | 15 | |
| 20 | | 20 | |
| 25 | | 25 | |
| 30 | | 30 | |
| 40 | | 40 | |
| 50 | | 50 | |
| 60 | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.




Comments:

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Marathon Drilling Co Ltd | 6894 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 6847 Hwam Dr | OTT |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| ON | K4P 1A2 | |

| Bus. Telephone No. *(inc. area code)* | Name of Well Technician (Last Name, First Name) |
|---|---|
| 6139220571 | Wright Terry |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted |
|---|---|---|
| 0715 | Terry | 20130913 |

| Well owner's information package delivered | Date Package Delivered | Date Work Completed |
|---|---|---|
| ☐ Yes ☐ No | Y Y Y Y M M D D | Y Y Y Y M M D D |

**Ministry Use Only**

Audit No. Z096855

Received NOV 14 2013

0506E (12/2007)

Ministry's Copy

© Queen's Printer for Ontario, 2007

Ontario — Ministry of the Environment

**Well Tag No.** *(Place Sticker and/or Print Below)*: A136699 BH 12-01

# Well Record

*Regulation 903 Ontario Water Resources Act*

Page 1 of 1

Measurements recorded in: ☒ Metric ☐ Imperial

## Well Owner's Information

| First Name | Last Name | E-mail Address | ☐ Well Constructed by Well Owner |
|---|---|---|---|
| AUBUT HOLDINGS, | [redacted] | | |

| Mailing Address (Street Number/Name) | Municipality | Province | Postal Code | Telephone No. *(inc. area code)* |
|---|---|---|---|---|
| [redacted] | | | | |

## Well Location

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| 356 MACLAREN STREET | | | |

| County/District/Municipality | City/Town/Village | Province | Postal Code |
|---|---|---|---|
| | OTTAWA | Ontario | |

| UTM Coordinates | Zone | Easting | Northing | Municipal Plan and Sublot Number | Other |
|---|---|---|---|---|---|
| NAD 83 | 18 | 445678 | 5029243 | | |

## Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| GREY | CONCRETE | | ASPHALTIC CONCRETE | 0 | 0.05 |
| GREY | CRUSHED SAND/GRAVEL | | FILL MATERIAL | 0.95 | 0.53 |
| BROWN | SAND | | FILL MATERIAL | 0.53 | 1.52 |
| GREY BROWN | SILTY CLAY | | WEATHERED CRUST | 1.52 | 3.51 |
| | | | | 3.51 | 5.18 |

## Annular Space

| Depth Set at (m/ft) From | Depth Set at (m/ft) To | Type of Sealant Used (Material and Type) | Volume Placed ($m^3$/$ft^3$) |
|---|---|---|---|
| 0.75 | 1.5 | BENTONITE | |

## Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping _____ hrs + _____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*

Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

| | Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|---|
| Static Level | | | | |
| 1 | | | 1 | |
| 2 | | | 2 | |
| 3 | | | 3 | |
| 4 | | | 4 | |
| 5 | | | 5 | |
| 10 | | | 10 | |
| 15 | | | 15 | |
| 20 | | | 20 | |
| 25 | | | 25 | |
| 30 | | | 30 | |
| 40 | | | 40 | |
| 50 | | | 50 | |
| 60 | | | 60 | |

## Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☒ Other, specify SSA

## Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☐ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 3.18 | PVC | SHED 40 | 0 | 3.05 |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 3.8 | PVC | 10 | 3.05 | 4.57 |

## Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

## Water Details

| Water found at Depth (m/ft) | Kind of Water | Hole Diameter Depth From (m/ft) | Hole Diameter Depth To (m/ft) | Diameter (cm/in) |
|---|---|---|---|---|
| ☐ Gas ☐ Other, specify | ☐ Fresh ☐ Untested | 0 | 5.18 | 16.51 |
| ☐ Gas ☐ Other, specify | ☐ Fresh ☐ Untested | | | |
| ☐ Gas ☐ Other, specify | ☐ Fresh ☐ Untested | | | |

## Map of Well Location

Please provide a map below following instructions on the back.

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| GEORGE DOWNING ESTATE DRILLING | 1844 |

| Business Address (Street Number/Name) | Municipality |
|---|---|
| 410 RUE PRINCIPALE | GRENVILLE-SUR-LA-ROUGE |

| Province | Postal Code | Business E-mail Address |
|---|---|---|
| QC | J0V1B0 | downing@hawk.igs.net |

| Bus. Telephone No. *(inc. area code)* | Name of Well Technician (Last Name, First Name) |
|---|---|
| 8192426469 | DOWNING STEPHEN |

| Well Technician's Licence No. | Signature of Technician and/or Contractor | Date Submitted |
|---|---|---|
| 3326 | | 2013/12/27 |

Comments: SEE ATTACHED

| Well owner's information package delivered | Date Package Delivered | Date Work Completed |
|---|---|---|
| ☐ Yes ☐ No | | 2012/12/03 |


**Ministry Use Only**

Audit No. Z163980

Received APR 03 2014

A136699
Z163980

#352 MACLAREN STREET




APR 03 2014

C-1844
Z163980

LEGEND

BH12-1 APPROXIMATE BOREHOLE LOCATION IN PLAN, CURRENT INVESTIGATION BY HOULE CHEVRIER ENGINEERING LTD.

98.95 GEODETIC ELEVATION AT GROUND SURFACE OF BOREHOLE, MEASURED IN METRES.

| | | | |
|---|---|---|---|
| Client: AUBUT HOLDINGS LTD. | | Location: 356 MACLAREN STREET OTTAWA, ONTARIO. | Revision: 0 |
| Drawn by: M.L. | Approved by: A.C. | Project No.: 12-582 | Scale: 1:125 |
| Houle Chevrier Engineering | | Title: BOREHOLE LOCATION PLAN | |
| | | Date: January 2013 | FIGURE 2 |

7334763

Ontario — Ministry of the Environment and Climate Change

Measurements recorded in: ☐ Metric ☒ Imperial

Well T... Tag#: A257375 ...Below)

A257375

# Well Record

*Regulation 903 Ontario Water Resources Act*

S-22915 Page ____ of ____

[redacted]

| Address of Well Location (Street Number/Name) | Township | Lot | Concession |
|---|---|---|---|
| 331 Cooper St | | | |
| **County/District/Municipality** | **City/Town/Village** | **Province** | **Postal Code** |
| | Ottawa | Ontario | |
| **UTM Coordinates** NAD 83 Zone 18 Easting 445651 Northing 5029536 | **Municipal Plan and Sublot Number** | **Other** | |

## Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

| General Colour | Most Common Material | Other Materials | General Description | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|---|
| GRY | Gravel | Asphalt | hard packed | 0 | 1 |
| BRN | Med Sand | | Soft loose | 1 | 6 |
| GRY | Clay | S. H | Soft | 6 | 18 |

## Annular Space

| Depth Set at (m/ft) From | To | Type of Sealant Used (Material and Type) | Volume Placed (m³/ft³) |
|---|---|---|---|
| 0 | 1 | Concrete / flushmount | |
| 1 | 2 | Bensea | |
| 2 | 18 | Filter Sand | |

## Method of Construction

☐ Cable Tool ☐ Diamond ☐ Rotary (Conventional) ☐ Jetting ☐ Rotary (Reverse) ☐ Driving ☐ Boring ☐ Digging ☐ Air percussion ☒ Other, specify direct push

## Well Use

☐ Public ☐ Commercial ☐ Not used ☐ Domestic ☐ Municipal ☐ Dewatering ☐ Livestock ☒ Test Hole ☒ Monitoring ☐ Irrigation ☐ Cooling & Air Conditioning ☐ Industrial ☐ Other, specify

## Construction Record - Casing

| Inside Diameter (cm/in) | Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel) | Wall Thickness (cm/in) | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 1.38 | pvc | .14 | 0 | 8 |

## Construction Record - Screen

| Outside Diameter (cm/in) | Material (Plastic, Galvanized, Steel) | Slot No. | Depth (m/ft) From | Depth (m/ft) To |
|---|---|---|---|---|
| 1.66 | pvc | 10 | 8 | 18 |

## Status of Well

☐ Water Supply ☐ Replacement Well ☒ Test Hole ☐ Recharge Well ☐ Dewatering Well ☒ Observation and/or Monitoring Hole ☐ Alteration (Construction) ☐ Abandoned, Insufficient Supply ☐ Abandoned, Poor Water Quality ☐ Abandoned, other, specify ☐ Other, specify

## Water Details

| Water found at Depth (m/ft) | Kind of Water | Gas | Other, specify |
|---|---|---|---|
| | ☐ Fresh ☐ Untested | ☐ | |
| | ☐ Fresh ☐ Untested | ☐ | |
| | ☐ Fresh ☐ Untested | ☐ | |

## Hole Diameter

| Depth (m/ft) From | To | Diameter (cm/in) |
|---|---|---|
| 0 | 18 | 2.375 |

## Results of Well Yield Testing

After test of well yield, water was: ☐ Clear and sand free ☐ Other, specify

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)

Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

| | Draw Down Time (min) | Draw Down Water Level (m/ft) | Recovery Time (min) | Recovery Water Level (m/ft) |
|---|---|---|---|---|
| Static Level | | | | |
| 1 | | | 1 | |
| 2 | | | 2 | |
| 3 | | | 3 | |
| 4 | | | 4 | |
| 5 | | | 5 | |
| 10 | | | 10 | |
| 15 | | | 15 | |
| 20 | | | 20 | |
| 25 | | | 25 | |
| 30 | | | 30 | |
| 40 | | | 40 | |
| 50 | | | 50 | |
| 60 | | | 60 | |

## Map of Well Location

Please provide a map below following instructions on the back.

MW1 on MAP

## Well Contractor and Well Technician Information

| Business Name of Well Contractor | Well Contractor's Licence No. |
|---|---|
| Strata Drilling Group | 7241 |
| **Business Address (Street Number/Name)** | **Municipality** |
| 165 Shields Court | Markham |
| **Province** | **Postal Code** |
| ON | L3R 8V2 |
| **Business E-mail Address** | |
| wreports@stratasoil.com | |
| **Bus. Telephone No. (inc. area code)** | **Name of Well Technician (Last Name, First Name)** |
| 9059400719 | Beattie, Brian |
| **Well Technician's Licence No.** | **Signature of Technician and/or Contractor** |
| 3616 | |
| **Date Submitted** | |
| 2019/03/06 | |

Comments: Pinchin General Contractors

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered: ____

Date Work Completed: 2019/03/06

**Ministry Use Only**

Audit No. Z298238


MAR 08 2019 Received

0506E (2014/11) Ministry's Copy

© Queen's Printer for Ontario, 2014

MAR 0 8 2019

G7241 229838




PINCHIN

LEGEND

- SITE BOUNDARY
- SITE BUILDING
- RES RESIDENTIAL
- MTR MULTI-TENANT RESIDENTIAL
- COM COMMERCIAL
- MTC MULTI-TENANT COMMERCIAL
- CMY COMMUNITY
- UST UNDERGROUND STORAGE TANK
- (P) PARKING
- GROUNDWATER MONITORING WELL

| | | | |
|---|---|---|---|
| PROJECT NAME: PHASE I ENVIRONMENTAL SITE ASSESSMENT | | | |
| CLIENT NAME: SERCO COMMERCIAL HOLDINGS INC. | | | |
| PROJECT LOCATION: 309 AND 331 COOPER STREET, OTTAWA, ONTARIO | | | |
| FIGURE NAME: SITE AND SURROUNDING LAND USE PLAN | | | FIGURE NO. 2 |
| APPROXIMATE SCALE: AS SHOWN | PROJECT NO.: 230021 | DATE: OCTOBER 2018 | |

Outlook

**RE: Records Search for PE7414**

**From** Public Information Services <publicinformationservices@tssa.org>
**Date** Mon 1/26/2026 2:49 PM
**To** Mohammed Ramadan <MRamadan@patersongroup.ca>

**External Email:** Do not click on links or open attachments unless you trust the sender.

Hello ,

**NO RECORDS FOUND IN CURRENT DATABASE:**

- We confirm that there are NO **fuels records** in our database at the subject address(es).

This is not a confirmation that there are no records in the archives. For a further search in our archives, please go to the **TSSA Client Portal** to complete an Application for Release of Public Information.

Please refer to Training (tssa.org) for instructions on how to use the portal. Please refer to How to Submit a Public Information Request (tssa.org) for instructions.

The associated fee must be paid via credit card (Visa or MasterCard).

Once all steps have been successfully completed you will receive your payment receipt via email.

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.

If you have any questions or concerns, please do not hesitate to contact our Public Information Release team at publicinformationservices@tssa.org.

Kind regards,

**Slavka Zahrebelny | Public Information & Records Agent**
Public Information
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1 416-734-3585 | Fax: +1 416-734-6242 | E-Mail: szahrebelny@tssa.org
www.tssa.org




***Winner of 2025 5-Star Safety Cultures Award***

**From:** Mohammed Ramadan <MRamadan@patersongroup.ca>

**Sent:** January 26, 2026 1:35 PM
**To:** Public Information Services <publicinformationservices@tssa.org>
**Subject:** Records Search for PE7414

⚠ External Email >

**[⚠ CAUTION]:** THIS EMAIL ORIGINATED OUTSIDE THE ORGANISATION.
DO NOT CLICK LINKS OR OPEN ATTACHMENTS UNLESS YOU KNOW THE SENDER AND ARE EXPECTING THIS EMAIL.
PLEASE REPORT WITH THE PHISH REPORT BUTTON IF SUSPICIONS.

Good Morning,

Could you please complete a search of your records for underground/aboveground storage tanks for the following address in **Ottawa, Ontario**:

MacLaren Street: 260, 263, 264, 275
Metcalfe St: 252, 260, 280
Gilmour Street: 295, 307

Regards,

PATERSON GROUP
SOLUTION ORIENTED ENGINEERING

**MOHAMMED RAMADAN, B.Sc.**
Environmental Scientist
TEL: (613) 226-7381 ext. 345
DIRECT: (613) 909-8069
9 AURIGA DRIVE
OTTAWA ON K2E 7T9
patersongroup.ca

TEMPORARY SHORING DESIGN SERVICES ARE NOW AVAILABLE, PLEASE CONTACT US TO SEE HOW WE CAN HELP!
This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

File Number: D06-03-26-0020

March 12 2026

Mohammed Ramadan
Paterson Group

*Sent via email [*mramadan@patersongroup.ca*]*

Dear Mohammed Ramadan,

**Re: Information Request**
260 MacLaren Street**, Ottawa, Ontario ("Subject Property")**

**Internal Department Circulation:**

The Planning, Infrastructure and Economic Development Department has the following information in response to your request for information regarding the Subject Property:

**Environmental Remediation Unit:** The City's Environmental Remediation Unit (ERU) has copies of the following environmental reports for the property:

- Paterson, 2008. 287 & 293 Lisgar, 260 MacLaren, 89 Nepean - Phase I & II ESA. 2Jul2008

Please contact ERU-UAE@ottawa.ca to request copies of the reports if required

**Sewer Use Program:** No information found pertaining to the subject property.

**Solid Waste Services:** No information found pertaining to the subject property.

**Ottawa Public Health - Environmental Health:** all public inspection results are publicly available on the Ottawa Public Health website: https://www.ottawapublichealth.ca/en/public-health-services/public-health-inspections.aspx

**Documents Provided:**

**HLUI Summary Report and HLUI Map**

The HLUI Summary Report Excel spreadsheet identifies HLUI area, point and line features within 250 metres of the Subject Property, as shown on the provided HLUI Map PDF. Within 500 metres of the Subject Property, landfills and Environmental Risk Management Area (ERMA) are also identified if applicable.

For more information on how to interpret the HLUI data identified in the attached excel sheet ('26-0020 HLUI Summary report.xlsx'), please refer to the Overview and User Guide."

**Additional information may be obtained by contacting:**

**Ontario's Environmental Registry**

The Environmental Registry found at https://ero.ontario.ca/ contains "public notices" about environmental matters being proposed by all government ministries covered by the Environmental Bill of Rights. The public notices may contain information about proposed new laws, regulations, policies and programs or about proposals to change or eliminate existing ones. By using keys words i.e. name of proponent/owner and the address one can ascertain if there is any information on the proponent and address under the following categories: Ministry, keywords, notice types, Notice Status, Acts, Instruments and published date (all years).

**The Ontario Land Registry Office**

Registration of real property is recorded in the Ontario Land Registry Office through the Land Titles Act or the Registry Act. Documents relating to title and other agreements that may affect your property are available to the public for a fee. It is recommended that a property search at the Land Registry Office be included in any investigation as to the historic use of your property. The City of Ottawa cannot comment on any documents to which it is not a party.

Court House
161 Elgin Street 4th Floor
Ottawa ON K2P 2K1
Tel: (613) 239-1230
Fax: (613) 239-1422

**Ottawa Public Health**

Ottawa Public Health inspects many different types of establishments. To view inspection results, please visit the Ottawa Public Health website: Public Health Inspections - Ottawa Public Health

Please note that Ottawa Public Health is not the lead agency on land use contamination in the City of Ottawa – contact the Ministry of Environment Conservation and Parks (MECP) for further information.

**Please note, as per the HLUI Disclaimer, that the information contained in the HLUI database has been compiled from publicly available records and other sources of information. The HLUI may contain erroneous information given that the records used as sources of information may be flawed. For instance, changes in municipal addresses over time may introduce error. Accordingly, all information from the HLUI database is provided on an "as is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in responding to the request.**

**Furthermore, the HLUI database and the results of this search in no way confirm the presence or absence of contamination or pollution of any kind. This information is provided on the assumption that it will not be relied upon by any person for any purpose whatsoever. The City of Ottawa denies all liability to any persons attempting to rely on any information provided from the HLUI database.**

**Please note that in responding to your request, the City of Ottawa does not guarantee or comment on the environmental condition of the Subject Property. You may wish to contact the Ontario Ministry of Environment and Climate Change for additional information.**

If you have any further questions or comments, please contact HLUI@ottawa.ca.


Sincerely,

**Mevanya Kasturiarachchi**
Student Planner | Étudiante en Urbanism
Development Review | Examen des projects d'amenagement
City of Ottawa | Ville d'Ottawa

Enclosures: (2)
1. HLUI Map
2. HLUI Summary Report

cc: File no. D06-03-26-0020

# HISTORIC LAND USE INVENTORY (HLUI) - REPORT REFERENCE MAP



# DATABASE REPORT

| | |
|---|---|
| **Project Property:** | *Phase I ESA*<br>*260 MacLaren Street*<br>*Ottawa ON K2P 1W5* |
| **Project No:** | *P.O. 64971/PE7414* |
| **Report Type:** | *Standard Report* |
| **Order No:** | *26012600426* |
| **Requested by:** | *Paterson Group Inc.* |
| **Date Completed:** | *January 28, 2026* |

**Environmental Risk Information Services**
*A division of Glacier Media Inc.*
1.866.517.5204 | info@erisinfo.com | erisinfo.com

# Table of Contents


Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....37
Map.....72
Aerial.....73
Topographic Map.....74
Detail Report.....75
Unplottable Summary.....314
Unplottable Report.....315
Appendix: Database Descriptions.....319
Definitions.....330



**Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY**

**Reliance on information in Report:** This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

**License for use of information in Report:** No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

**Your Liability for misuse:** Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

**No warranty of Accuracy or Liability for ERIS:** The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

**Trademark and Copyright:** You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

# Executive Summary

***Property Information:***

| | |
|---|---|
| **Project Property:** | *Phase I ESA*<br>*260 MacLaren Street  Ottawa ON K2P 1W5* |
| **Project No:** | *P.O. 64971/PE7414* |

**Coordinates:**

| | |
|---|---|
| **Latitude:** | *45.4159202* |
| **Longitude:** | *-75.6923368* |
| **UTM Northing:** | *5,029,388.66* |
| **UTM Easting:** | *445,829.51* |
| **UTM Zone:** | *18T* |

**Elevation:** *242 FT*
*73.88 M*

***Order Information:***

| | |
|---|---|
| **Order No:** | *26012600426* |
| **Date Requested:** | *January 26, 2026* |
| **Requested by:** | *Paterson Group Inc.* |
| **Report Type:** | *Standard Report* |

***Historical/Products:***

| | |
|---|---|
| **ERIS Xplorer** | *ERIS Xplorer* |

# Executive Summary: Report Summary

| Database | Name | Searched | Project Property | Within 0.25 km | Total |
|---|---|---|---|---|---|
| AAGR | *Abandoned Aggregate Inventory* | Y | 0 | 0 | 0 |
| AGR | *Aggregate Inventory* | Y | 0 | 0 | 0 |
| AMIS | *Abandoned Mine Information System* | Y | 0 | 0 | 0 |
| ANDR | *Anderson's Waste Disposal Sites* | Y | 0 | 0 | 0 |
| AST | *Aboveground Storage Tanks* | Y | 0 | 0 | 0 |
| AUWR | *Automobile Wrecking & Supplies* | Y | 0 | 0 | 0 |
| BORE | *Borehole* | Y | 0 | 8 | 8 |
| CA | *Certificates of Approval* | Y | 0 | 9 | 9 |
| CDRY | *Dry Cleaning Facilities* | Y | 0 | 0 | 0 |
| CFOT | *Commercial Fuel Oil Tanks* | Y | 0 | 0 | 0 |
| CHEM | *Chemical Manufacturers and Distributors* | Y | 0 | 0 | 0 |
| CHM | *Chemical Register* | Y | 0 | 0 | 0 |
| CNG | *Compressed Natural Gas Stations* | Y | 0 | 0 | 0 |
| COAL | *Inventory of Coal Gasification Plants and Coal Tar Sites* | Y | 0 | 0 | 0 |
| CONV | *Compliance and Convictions* | Y | 0 | 0 | 0 |
| CPU | *Certificates of Property Use* | Y | 0 | 0 | 0 |
| DRL | *Drill Hole Database* | Y | 0 | 0 | 0 |
| DTNK | *Delisted Fuel Tanks* | Y | 0 | 1 | 1 |
| EASR | *Environmental Activity and Sector Registry* | Y | 0 | 0 | 0 |
| EBR | *Environmental Registry* | Y | 0 | 0 | 0 |
| ECA | *Environmental Compliance Approval* | Y | 0 | 6 | 6 |
| EEM | *Environmental Effects Monitoring* | Y | 0 | 0 | 0 |
| EHS | *ERIS Historical Searches* | Y | 0 | 74 | 74 |
| EIIS | *Environmental Issues Inventory System* | Y | 0 | 0 | 0 |
| EMHE | *Emergency Management Historical Event* | Y | 0 | 0 | 0 |
| EOR | *Environmental Offenders Registry* | Y | 0 | 0 | 0 |
| EPAR | *Environmental Penalty Annual Report* | Y | 0 | 0 | 0 |
| ESNR | *Excess Soil Registry* | Y | 0 | 0 | 0 |
| EXP | *List of Expired Fuels Safety Facilities* | Y | 0 | 0 | 0 |
| FCON | *Federal Convictions* | Y | 0 | 0 | 0 |
| FCS | *Contaminated Sites on Federal Land* | Y | 0 | 0 | 0 |
| FOFT | *Fisheries & Oceans Fuel Tanks* | Y | 0 | 0 | 0 |
| FRST | *Federal Identification Registry for Storage Tank Systems (FIRSTS)* | Y | 0 | 0 | 0 |
| FST | *Fuel Storage Tank* | Y | 0 | 0 | 0 |
| FSTH | *Fuel Storage Tank - Historic* | Y | 0 | 0 | 0 |
| GEN | *Ontario Regulation 347 Waste Generators Summary* | Y | 0 | 171 | 171 |
| GHG | *Greenhouse Gas Emissions from Large Facilities* | Y | 0 | 0 | 0 |

| Database | Name | Searched | Project Property | Within 0.25 km | Total |
|---|---|---|---|---|---|
| HINC | TSSA Historic Incidents | Y | 0 | 5 | 5 |
| HIST RISK | Historical Business Activity Risk | Y | 0 | 12 | 12 |
| IAFT | Indian & Northern Affairs Fuel Tanks | Y | 0 | 0 | 0 |
| INC | Fuel Oil Spills and Leaks | Y | 0 | 0 | 0 |
| LIMO | Landfill Inventory Management Ontario | Y | 0 | 0 | 0 |
| MINE | Canadian Mine Locations | Y | 0 | 0 | 0 |
| MNR | Mineral Occurrences | Y | 0 | 0 | 0 |
| NATE | National Analysis of Trends in Emergencies System (NATES) | Y | 0 | 0 | 0 |
| NCPL | Non-Compliance Reports | Y | 0 | 0 | 0 |
| NDFT | National Defense & Canadian Forces Fuel Tanks | Y | 0 | 0 | 0 |
| NDSP | National Defense & Canadian Forces Spills | Y | 0 | 0 | 0 |
| NDWD | National Defence & Canadian Forces Waste Disposal Sites | Y | 0 | 0 | 0 |
| NEBI | National Energy Board Pipeline Incidents | Y | 0 | 0 | 0 |
| NEBP | National Energy Board Wells | Y | 0 | 0 | 0 |
| NEES | National Environmental Emergencies System (NEES) | Y | 0 | 0 | 0 |
| NOC | Notice of Contamination List | Y | 0 | 0 | 0 |
| NPCB | National PCB Inventory | Y | 0 | 3 | 3 |
| NPR2 | National Pollutant Release Inventory | Y | 0 | 0 | 0 |
| NPRI | National Pollutant Release Inventory - Historic | Y | 0 | 0 | 0 |
| OGWE | Oil and Gas Wells | Y | 0 | 0 | 0 |
| OOGW | Ontario Oil and Gas Wells | Y | 0 | 0 | 0 |
| OPCB | Inventory of PCB Storage Sites | Y | 0 | 6 | 6 |
| ORD | Orders | Y | 0 | 0 | 0 |
| PAP | Canadian Pulp and Paper | Y | 0 | 0 | 0 |
| PCFT | Parks Canada Fuel Storage Tanks | Y | 0 | 0 | 0 |
| PES | Pesticide Register | Y | 0 | 0 | 0 |
| PFAS | Ontario PFAS Spills | Y | 0 | 0 | 0 |
| PFCH | NPRI Reporters - PFAS Substances | Y | 0 | 0 | 0 |
| PFHA | Potential PFAS Handlers from NPRI | Y | 0 | 0 | 0 |
| PINC | Pipeline Incidents | Y | 0 | 3 | 3 |
| PPHA | Potential PFAS Handlers from EASR | Y | 0 | 0 | 0 |
| PRT | Private and Retail Fuel Storage Tanks | Y | 0 | 1 | 1 |
| PTTW | Permit to Take Water | Y | 0 | 1 | 1 |
| REC | Ontario Regulation 347 Waste Receivers Summary | Y | 0 | 0 | 0 |
| RSC | Record of Site Condition | Y | 0 | 1 | 1 |
| RST | Retail Fuel Storage Tanks | Y | 0 | 1 | 1 |
| SCT | Scott's Manufacturing Directories | Y | 0 | 29 | 29 |
| SPL | Ontario Spills | Y | 0 | 8 | 8 |
| SRDS | Wastewater Discharger Registration Database | Y | 0 | 0 | 0 |
| TANK | Anderson's Storage Tanks | Y | 0 | 0 | 0 |
| TCFT | Transport Canada Fuel Storage Tanks | Y | 0 | 0 | 0 |

| Database | Name | Searched | Project Property | Within 0.25 km | Total |
|---|---|---|---|---|---|
| VAR | ***Variances for Abandonment of Underground Storage Tanks*** | *Y* | *0* | *1* | *1* |
| WDS | ***Waste Disposal Sites - MOE CA Inventory*** | *Y* | *0* | *0* | *0* |
| WDSH | ***Waste Disposal Sites - MOE 1991 Historical Approval Inventory*** | *Y* | *0* | *0* | *0* |
| WMS | ***Waste Management Site*** | *Y* | *0* | *0* | *0* |
| WWIS | ***Water Well Information System*** | *Y* | *0* | *27* | *27* |
| | | ***Total:*** | *0* | *367* | *367* |

# Executive Summary: Site Report Summary - Project Property

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev diff (m) | Page Number |
|---|---|---|---|---|---|---|

No records found in the selected databases for the project property.

# Executive Summary: Site Report Summary - Surrounding Properties

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 1 | SCT | Invenire4 Ltd. | 260 Metcalfe St Unit 2A<br>Ottawa ON K2P 1R6 | E/28.3 | 0.00 | 75 |
| 2 | WWIS | | ON<br>***Well ID:*** 7473728 | W/32.4 | 0.69 | 75 |
| 3 | GEN | Elevation Elevator Inc | 295 Gilmour Street<br>Ottawa ON | SSE/40.9 | -0.03 | 76 |
| 4 | SCT | Innova Envelope | 270 MacLaren St<br>Ottawa ON K2P 0M3 | WSW/43.3 | 1.00 | 77 |
| 4 | SCT | Supremex Inc. | 270 MacLaren St Suite 25<br>Ottawa ON K2P 0M3 | WSW/43.3 | 1.00 | 77 |
| 5 | WWIS | | ON<br>***Well ID:*** 7473727 | W/43.5 | 1.00 | 78 |
| 6 | WWIS | | ON<br>***Well ID:*** 7473726 | W/45.6 | 1.00 | 79 |
| 7 | GEN | Trilex Holdings Ltd (Care of District Reality) | 307 GILMOUR ST<br>OTTAWA ON K2P 0P7 | SSW/53.6 | 0.69 | 79 |
| 8 | EHS | | 283 MacLaren Street<br>Ottawa ON K2P 0M2 | W/56.1 | 1.00 | 80 |
| 8 | GEN | CM3 Environmental Inc. | 283 MacLaren Street<br>Ottawa ON | W/56.1 | 1.00 | 80 |
| 8 | SPL | s.21 | 283 Maclaren, Ottawa<br>Ottawa ON | W/56.1 | 1.00 | 81 |
| 8 | SPL | | OTTAWA ON | W/56.1 | 1.00 | 82 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 9 | WWIS | | ON<br>**Well ID:** 7473694 | W/56.5 | 1.00 | 83 |
| 10 | WWIS | | ON<br>**Well ID:** 7473695 | W/56.8 | 1.00 | 83 |
| 11 | WWIS | | ON<br>**Well ID:** 7473723 | W/57.5 | 1.00 | 84 |
| 12 | EHS | | 252 Metcalfe St.<br>Ottawa ON K2P 1R3 | N/58.5 | -0.03 | 85 |
| 12 | EHS | | 252 Metcalfe Street<br>Ottawa ON K2P 1R3 | N/58.5 | -0.03 | 85 |
| 13 | WWIS | | ON<br>**Well ID:** 7473725 | W/60.8 | 1.00 | 86 |
| 14 | WWIS | | ON<br>**Well ID:** 7473722 | W/61.6 | 1.00 | 86 |
| 15 | WWIS | | ON<br>**Well ID:** 7473724 | W/64.5 | 1.00 | 87 |
| 16 | BORE | | ON | SW/67.4 | 1.00 | 88 |
| 17 | NPCB | TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE/70.2 | 0.00 | 90 |
| 17 | NPCB | TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE/70.2 | 0.00 | 90 |
| 17 | OPCB | TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE/70.2 | 0.00 | 90 |
| 17 | OPCB | TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE/70.2 | 0.00 | 90 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 17 | OPCB | TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE/70.2 | 0.00 | 90 |
| 17 | OPCB | TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE/70.2 | 0.00 | 91 |
| 18 | SPL | OTTAWA BOARD OF EDUCATION | 300 GILMOUR ST.<br>OTTAWA CITY ON | SSE/70.6 | 0.00 | 91 |
| 19 | EHS | | 255 Metcalfe Street<br>Ottawa ON K2P 0N9 | ENE/73.6 | 0.00 | 92 |
| 20 | EHS | | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 92 |
| 20 | EHS | | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 92 |
| 20 | EHS | | 267 O'connor St<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 92 |
| 20 | EHS | | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 93 |
| 20 | GEN | KOPP CLINICAL LABORATORIES | 267 O'CONNOR STREET, SUITE 104<br>OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 93 |
| 20 | GEN | KOPP CLINICAL LABORAT (OUT OF BUSINESS) | 267 O'CONNOR STREET, SUITE 104<br>OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 93 |
| 20 | GEN | KOPP CLINICAL LABORATORIES 23-100 | 267 O'CONNOR STREET, SUITE 104<br>OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 94 |
| 20 | GEN | O'CONNOR PHARMACY | 267 O'CONNER STREET<br>OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 94 |
| 20 | GEN | CML HealthCare Inc. | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 94 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 20 | GEN | CML HealthCare Inc. | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 95 |
| 20 | GEN | CML HealthCare Inc. | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 95 |
| 20 | GEN | Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 95 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 96 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'conner Street Suite 225<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 96 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 225<br>Ottawa ON | SW/78.8 | 1.00 | 96 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 97 |
| 20 | GEN | Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 97 |
| 20 | GEN | CML HealthCare Inc. | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 97 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON | SW/78.8 | 1.00 | 98 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 98 |
| 20 | GEN | Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 99 |
| 20 | GEN | LifeLabs LP | 267 O'Connor Street, Unit B003<br>Ottawa ON | SW/78.8 | 1.00 | 99 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 20 | GEN | LifeLabs LP | 267 O'Connor Street, Unit B003<br>Ottawa ON | SW/78.8 | 1.00 | 99 |
| 20 | GEN | Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON | SW/78.8 | 1.00 | 100 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON | SW/78.8 | 1.00 | 100 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON | SW/78.8 | 1.00 | 100 |
| 20 | GEN | Midtown Family Health | 267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 101 |
| 20 | GEN | Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120<br>OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 101 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 102 |
| 20 | GEN | We Care Home Health Services | 267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 102 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 103 |
| 20 | GEN | We Care Home Health Services | 267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 103 |
| 20 | GEN | LifeLabs LP | 267 O'Connor Street, Unit B003<br>Ottawa ON K1S 1C2 | SW/78.8 | 1.00 | 103 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 104 |
| 20 | GEN | Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P1V3 | SW/78.8 | 1.00 | 104 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 105 |
| 20 | GEN | Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120 OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 105 |
| 20 | GEN | Midtown Family Health | 267 O'Connor ST. Suite 306 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 105 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 106 |
| 20 | GEN | LifeLabs LP | 267 O'Connor Street, Unit B003 Ottawa ON K1S 1C2 | SW/78.8 | 1.00 | 106 |
| 20 | GEN | Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St Ottawa ON K2P1V3 | SW/78.8 | 1.00 | 107 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 107 |
| 20 | GEN | Midtown Family Health | 267 O'Connor ST. Suite 306 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 107 |
| 20 | GEN | Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120 OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 108 |
| 20 | GEN | CBI Home Health formerly We Care Home Health | 267 O'Connor Street Suite 609 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 108 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 109 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 OConnor Street Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 109 |
| 20 | GEN | Midtown Family Health | 267 O'Connor ST. Suite 306 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 109 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 20 | GEN | Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120 OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 110 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 110 |
| 20 | GEN | Midtown Family Health | 267 O'Connor ST. Suite 306 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 111 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 OConnor Street Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 111 |
| 20 | GEN | CBI Home Health formerly We Care Home Health | 267 O'Connor Street Suite 609 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 112 |
| 20 | GEN | Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 OConnor Street Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 112 |
| 20 | GEN | CBI Home Health formerly We Care Home Health | 267 O'Connor Street Suite 609 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 113 |
| 20 | GEN | Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120 OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 113 |
| 20 | GEN | Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 115 |
| 20 | GEN | Midtown Family Health | 267 O'Connor ST. Suite 306 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 118 |
| 20 | GEN | CBI Home Health formerly We Care Home Health | 267 O'Connor Street Suite 609 Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 118 |
| 20 | GEN | Midtown Ottawa FHO | 267 O'Connor ST. Suite 306 Ottawa ON | SW/78.8 | 1.00 | 123 |
| 20 | GEN | CENTRAL OTTAWA FAMILY MEDICINE ASSOCIATES LTD. | Suite 500, 267 O'Connor Street Ottawa ON | SW/78.8 | 1.00 | 126 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 20 | SCT | DENTAL TECHNOLOGY GROUP INC. | 267 O'CONNOR ST SUITE 101<br>OTTAWA ON K2P 1V3 | SW/78.8 | 1.00 | 129 |
| 20 | SCT | E.L. LITTLEJOHN & ASSOCIATES | 267 O'Connor St<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 130 |
| 20 | SCT | The Dental Technology Group | 267 O'Connor St Suite 101<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 130 |
| 20 | SCT | E.L. Littlejohn & Associates Ltd. | 267 O'Connor St<br>Ottawa ON K2P 1V3 | SW/78.8 | 1.00 | 131 |
| 20 | SCT | GALLEY Kitchen + Provisions | 267 O'Connor St<br>Ottawa ON K2P1V3 | SW/78.8 | 1.00 | 131 |
| 21 | SCT | Cdn Council-International Law | 236 Metcalfe St Suite 215<br>Ottawa ON K2P 1R3 | NNW/80.0 | 0.69 | 132 |
| 22 | EHS | | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | WSW/84.6 | 1.00 | 132 |
| 23 | HINC | | 293 McLAREN STREET<br>OTTAWA ON | W/86.7 | 1.00 | 133 |
| 24 | EHS | | 258-260 Somerset Street West<br>Ottawa ON K2P 0J6 | NNW/87.0 | 1.00 | 133 |
| 25 | WWIS | | ON<br>***Well ID:*** 7473693 | SSW/89.3 | 0.69 | 133 |
| 26 | GEN | GLENVIEW CORPORATION | 270 SOMERSET WEST<br>OTTAWA ON K2P 0J7 | NW/100.9 | 1.00 | 134 |
| 27 | BORE | | ON | S/116.8 | -0.03 | 134 |
| 28 | CA | R.M. OF OTTAWA-CARLETON | SOMERSET ST./METCALFE ST.<br>OTTAWA CITY ON | N/120.8 | 0.00 | 136 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 28 | CA | City of Ottawa | Somerset Street and Metcalfe Street<br>Ottawa ON | N/120.8 | 0.00 | 137 |
| 28 | ECA | City of Ottawa | Somerset Street and Metcalfe St<br>Ottawa ON K2G 6J8 | N/120.8 | 0.00 | 137 |
| 28 | ECA | City of Ottawa | Somerset Street and Metcalfe St<br>Ottawa ON K2G 6J8 | N/120.8 | 0.00 | 137 |
| 29 | GEN | PUBLIC SERVICE ALLIANCE OF CANADA | 233 GILMOUR ST.<br>OTTAWA ON K2P 0P1 | E/124.3 | -0.68 | 138 |
| 29 | GEN | PUBLIC SERVICE ALLIANCE OF CANADA 31-381 | 233 GILMOUR ST.<br>OTTAWA ON K2P 0P1 | E/124.3 | -0.68 | 138 |
| 29 | GEN | PSAC Holdings Ltd. | 233 Gilmour Street<br>Ottawa ON K2P 0P2 | E/124.3 | -0.68 | 138 |
| 29 | GEN | PSAC Holdings Ltd. | 233 Gilmour Street<br>Ottawa ON | E/124.3 | -0.68 | 139 |
| 29 | GEN | PSAC Holdings Ltd. | 233 Gilmour Street<br>Ottawa ON | E/124.3 | -0.68 | 139 |
| 29 | GEN | PSAC HOLDINGS LTD. | 233 GILMOUR STREET<br>OTTAWA ON K1S 1V7 | E/124.3 | -0.68 | 140 |
| 29 | GEN | Plomberie Bourget Plumbing | 233 gilmour st ottawa<br>Ottawa ON | E/124.3 | -0.68 | 140 |
| 30 | CA | R.M. OF OTTAWA-CARLETON | LEWIS ST/METCALFE ST.<br>OTTAWA CITY ON | ESE/124.6 | -0.31 | 141 |
| 31 | EHS | | 225 MacLaren Street<br>Ottawa ON K2P 0L4 | NE/127.0 | 0.00 | 141 |
| 32 | EHS | | 296 Metcalfe Street<br>Ottawa ON K2P 1S2 | ESE/128.2 | -1.12 | 141 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 33 | EHS | | 300 Somerset St W<br>Ottawa ON K2P0J6 | W/129.0 | 1.31 | 141 |
| 34 | CA | 1384274 Ontario Inc. | 330 Gilmour St Ward 14<br>Ottawa ON K2P 2P6 | SSW/129.1 | 0.69 | 142 |
| 34 | ECA | 1384274 Ontario Inc. | 330 Gilmour St Ward 14<br>Ottawa ON K2E 1A9 | SSW/129.1 | 0.69 | 142 |
| 34 | GEN | OTTAWA BOARD OF EDUCATION | 330 GILMOUR STREET<br>OTTAWA ON K2P 2P6 | SSW/129.1 | 0.69 | 142 |
| 34 | GEN | OTTAWA BOARD OF EDUCATION 29-129 | 330 GILMOUR STREET<br>OTTAWA ON K2P 2P6 | SSW/129.1 | 0.69 | 142 |
| 34 | GEN | OTTAWA BOARD OF EDUCATION | ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.<br>OTTAWA ON K2P 0P9 | SSW/129.1 | 0.69 | 143 |
| 34 | GEN | OTTAWA (SEE&USE ON1285703) | ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.<br>OTTAWA ON K2P 0P9 | SSW/129.1 | 0.69 | 143 |
| 34 | GEN | OTTAWA (SEE&USE ON1285703) 29-129 | ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.<br>OTTAWA ON K2P 0P9 | SSW/129.1 | 0.69 | 143 |
| 34 | RSC | 1384274 Ontario Incorporated | 330 GILMOUR ST ON<br>OTTAWA ON | SSW/129.1 | 0.69 | 144 |
| 35 | WWIS | | BRONSON RD AND RAVEN<br>Ottawa ON<br>***Well ID:*** 7337489 | N/129.6 | 0.00 | 144 |
| 36 | CA | OTTAWA CITY - BANK STREET | GILMOUR ST./O'CONNOR ST.<br>OTTAWA CITY ON | SW/130.4 | 1.00 | 147 |
| 37 | BORE | | ON | WNW/134.7 | 1.00 | 148 |
| 38 | WWIS | | ON | NNW/134.8 | 1.00 | 149 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| | | | ***Well ID:*** 7211111 | | | |
| 39 | GEN | OCSCC # 1049 | 222 Somerset St. West<br>Ottawa ON K2P 0A7 | NNE/137.8 | 0.00 | 151 |
| 39 | SCT | Air Force Productions Ltd. | 222 Somerset St W<br>Ottawa ON K2P 2G3 | NNE/137.8 | 0.00 | 152 |
| 40 | EHS | | 222 MacLaren Street<br>Ottawa ON K2P 0L8 | ENE/139.3 | -1.06 | 152 |
| 40 | EHS | | 222 Maclaren St<br>Ottawa ON K2P0L8 | ENE/139.3 | -1.06 | 153 |
| 41 | GEN | Timbercreek Communities | 222 Metcalfe St<br>Ottawa ON K2P 1R2 | N/143.1 | -0.08 | 153 |
| 42 | EHS | | 250 O'Connor Street<br>Ottawa ON K2P 1V2 | W/144.2 | 1.85 | 153 |
| 43 | GEN | Carleton Condominium Corporation 251 | 420 Lewis Street<br>Ottawa ON K2P 0S9 | S/146.3 | -0.03 | 153 |
| 44 | GEN | GTA'S Finest Restoration | 236 Somerset<br>Ottawa ON K2P0J4 | NNE/147.6 | 0.00 | 154 |
| 45 | EHS | | 278-280 O'Connor St and 347 Gilmour St<br>Ottawa ON K2P 1V4 | SW/148.0 | 1.00 | 155 |
| 46 | PTTW | 1578051 Ontario Inc. | 237 Somerset Street West<br>Ottawa ON K2P 0J3 | N/148.4 | 0.00 | 155 |
| 47 | GEN | AK Global Management Inc | 280-282 O'Connor Street<br>Ottawa ON K2P 1V4 | SW/150.1 | 1.00 | 156 |
| 48 | GEN | TAGGART CORPORATION | 235 SOMERSET STREET WEST<br>OTTAWA ON K2P 0J3 | N/156.1 | 0.00 | 156 |
| 49 | EHS | | 331 Maclaren St<br>Ottawa ON K2P0M4 | W/156.9 | 2.00 | 157 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 50 | EHS | | 246 Gilmour St<br>Ottawa ON K2P 0P6 | E/158.0 | -1.00 | 157 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S/159.0 | 0.69 | 157 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S/159.0 | 0.69 | 157 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON | S/159.0 | 0.69 | 158 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S/159.0 | 0.69 | 158 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S/159.0 | 0.69 | 158 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S/159.0 | 0.69 | 159 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S/159.0 | 0.69 | 159 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S/159.0 | 0.69 | 159 |
| 51 | GEN | David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S/159.0 | 0.69 | 160 |
| 51 | GEN | David Jordan Medicine Professional Corporation | 301 O'Connor St.<br>Ottawa ON | S/159.0 | 0.69 | 160 |
| 52 | BORE | | ON | W/161.0 | 2.01 | 164 |
| 53 | EHS | | 301 Metcalfe Street<br>Ottawa ON K2P 1R9 | ESE/167.4 | -1.00 | 166 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 54 | EHS | | 301 Metcalfe Street<br>Ottawa ON K2P 1R9 | ESE/168.0 | -1.00 | 166 |
| 55 | EHS | | 301 Metcalfe St<br>Ottawa ON K2P1R9 | ESE/169.7 | -1.00 | 166 |
| 56 | EHS | | 218 maclaren street<br>ottawa ON K2P 0L7 | ENE/171.0 | -1.00 | 166 |
| 56 | EHS | | 218 MacLaren Street<br>Ottawa ON K2P 0L4 | ENE/171.0 | -1.00 | 167 |
| 57 | EHS | | 318 Cooper St<br>Ottawa ON | NW/172.1 | 0.97 | 167 |
| 58 | SCT | Dr George Wehbi Dentist | 229 Metcalfe St<br>Ottawa ON K2P2C2 | N/175.5 | 0.00 | 167 |
| 59 | PINC | PIPELINE HIT 1/2" | 310 COOPER ST,,OTTAWA,ON,K2P 0G7, CA<br>ON | NW/175.6 | 1.00 | 168 |
| 59 | SPL | Enbridge Gas Distribution Inc. | 310 Cooper St.<br>Ottawa ON | NW/175.6 | 1.00 | 168 |
| 60 | EHS | | 320 Cooper Street<br>Ottawa ON K2P 0G7 | WNW/177.4 | 0.97 | 169 |
| 60 | EHS | | 320 Cooper St<br>Ottawa ON K2P0G7 | WNW/177.4 | 0.97 | 170 |
| 60 | EHS | | 320 Cooper Street Ottawa ON<br>Ottawa ON K2P 0G7 | WNW/177.4 | 0.97 | 170 |
| 61 | EHS | | 334 MacLaren Street<br>Ottawa ON K2P 0M6 | WSW/178.2 | 2.00 | 170 |
| 62 | SCT | HICKS MEDIA | 300 Cooper St Suite 30<br>Ottawa ON K2P 0G7 | NW/178.3 | 1.00 | 170 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 62 | SCT | Hicks Media - Div. of Gidney News & Publishing Limited | 300 Cooper St Suite 30<br>Ottawa ON K2P 0G7 | NW/178.3 | 1.00 | 171 |
| 63 | BORE | | ON | ESE/178.3 | -1.00 | 171 |
| 64 | WWIS | | 311 SOMERSET<br>Ottawa ON<br>***Well ID:*** 7391112 | W/181.5 | 2.00 | 172 |
| 65 | EHS | | 223 Somerset St W<br>Ottawa ON K2P0J1 | NNE/182.2 | -0.14 | 176 |
| 66 | BORE | | ON | ESE/182.2 | -1.00 | 176 |
| 67 | GEN | Ottawa-Carleton District School Board | Elgin Street Public School 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 177 |
| 67 | GEN | Ottawa-Carleton District School Board | Elgin Street PS 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 178 |
| 67 | GEN | Ottawa-Carleton District School Board | 310 Elgin St.<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 178 |
| 67 | GEN | Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 178 |
| 67 | GEN | Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 179 |
| 67 | GEN | Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON | E/182.6 | -1.00 | 179 |
| 67 | GEN | Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 180 |
| 67 | GEN | Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 180 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 67 | GEN | Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 181 |
| 67 | GEN | Ottawa-Carleton District School Board Health & Safety | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 182 |
| 67 | GEN | Ottawa-Carleton District School Board Health & Safety | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 183 |
| 67 | GEN | Ottawa-Carleton District School Board Health & Safety | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E/182.6 | -1.00 | 183 |
| 67 | GEN | Ottawa-Carleton District School Board | Elgin Street Public School, 310 Elgin Street<br>Ottawa ON | E/182.6 | -1.00 | 184 |
| 68 | EHS | | 335 MacLaren Street<br>Ottawa ON K2P 0M4 | WSW/182.8 | 2.00 | 187 |
| 69 | HBAR | California Standard Co | 233 Metcalfe<br>Ottawa ON | N/183.3 | 0.00 | 188 |
| 70 | WWIS | | ON<br>***Well ID:*** 7211110 | W/184.2 | 2.00 | 188 |
| 71 | EHS | | 335 Maclaren St<br>Ottawa ON K2P0M5 | WSW/184.3 | 2.00 | 190 |
| 72 | HINC | | 438 LEWIS STREET<br>OTTAWA ON | SSW/184.6 | 1.00 | 190 |
| 73 | WWIS | | 311 Somerset St W<br>Ottawa ON<br>***Well ID:*** 7382782 | W/185.0 | 2.00 | 190 |
| 74 | EHS | | 350 Gilmour Street<br>Ottawa ON K2P 0R3 | SW/185.3 | 1.00 | 194 |
| 75 | PINC | KEN RALPH | 231 O'CONNOR ST,,OTTAWA,ON,K2P 1T8,CA<br>ON | WNW/185.7 | 2.00 | 194 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 76 | SCT | Kun Shoulder Rest Inc. | 200 MacLaren St<br>Ottawa ON K2P0L4 | ENE/188.9 | -1.00 | 195 |
| 77 | EHS | | 318 Cooper Street Ottawa ON<br>Ottawa ON K2P 0G7 | NW/189.5 | 0.97 | 196 |
| 78 | WWIS | | 311 SONERSET<br>Ottawa ON<br>***Well ID:*** 7391115 | W/189.9 | 2.00 | 196 |
| 79 | GEN | ARTEXT (OUT OF BUS) | 225 METCALFE STREET, SUITE 710<br>OTTAWA ON K2P 1P9 | N/190.2 | 0.00 | 200 |
| 79 | GEN | ARTEXT ELECTRONIC PUBLISHING INC. | 225 METCALFE STREET, SUITE 710<br>OTTAWA ON K2P 1P9 | N/190.2 | 0.00 | 200 |
| 79 | GEN | TAGGART CORPORATION | 708-225 Metcalfe Street<br>OTTAWA ON K2P 1P9 | N/190.2 | 0.00 | 201 |
| 79 | GEN | Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 201 |
| 79 | GEN | Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 201 |
| 79 | GEN | Dr. J. Li Dentistry Professional Corporation | 400-225 Metcalfe Street<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 202 |
| 79 | GEN | dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503<br>ottawa ON K2P1P9 | N/190.2 | 0.00 | 202 |
| 79 | GEN | Dr. J. Li Dentistry Professional Corporation | 400-225 Metcalfe Street<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 203 |
| 79 | GEN | Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 203 |
| 79 | GEN | Dr. J. Li Dentistry Professional Corporation | 400-225 Metcalfe Street<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 204 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 79 | GEN | dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503<br>ottawa ON K2P1P9 | N/190.2 | 0.00 | 204 |
| 79 | GEN | Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 204 |
| 79 | GEN | Dr. J. Li Dentistry Professional Corporation | 400-225 Metcalfe Street<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 205 |
| 79 | GEN | Metcalfe Street Dental | 225 Metcalfe Street, Unit 104<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 207 |
| 79 | GEN | dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503<br>ottawa ON K2P1P9 | N/190.2 | 0.00 | 207 |
| 79 | GEN | Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 207 |
| 79 | GEN | Metcalfe Street Dental | 225 Metcalfe Street, Unit 104<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 208 |
| 79 | GEN | Metcalfe Street Dental | 225 Metcalfe Street Unit 104<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 209 |
| 79 | GEN | dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503<br>ottawa ON K2P1P9 | N/190.2 | 0.00 | 209 |
| 79 | GEN | Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 210 |
| 79 | GEN | Metcalfe Street Dental | 225 Metcalfe Street Unit 104<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 210 |
| 79 | GEN | Capital Dentistry Group Ltd. | 225 Metcalfe Street, Unit 104<br>Ottawa ON | N/190.2 | 0.00 | 211 |
| 79 | GEN | Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 213 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 79 | GEN | Metcalfe and Cooper Family Dentistry | 225 Metcalfe St. Unit 507<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 216 |
| 79 | GEN | Dr. Amar Kuruganti Dentistry Professional Corporat Kenson Downtown Dentistry | 225 Metcalfe Street Suite 504<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 217 |
| 79 | GEN | dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503<br>ottawa ON K2P1P9 | N/190.2 | 0.00 | 217 |
| 79 | GEN | Kenson Downtown Dentistry | 225 Metcalfe Street, Suite 504<br>Ottawa ON | N/190.2 | 0.00 | 220 |
| 79 | GEN | DR STANLEY SHIFF | 225 Metcalfe Street<br>Ottawa ON | N/190.2 | 0.00 | 221 |
| 79 | GEN | Capital Dentistry Group Ltd. | 225 Metcalfe Street<br>Ottawa ON | N/190.2 | 0.00 | 222 |
| 79 | GEN | Capital Dentistry Group Ltd. | 225 Metcalfe Street<br>Ottawa ON | N/190.2 | 0.00 | 223 |
| 79 | NPCB | TAGGART CORPORATION | 225 METCALFE STREET SUITE 708<br>OTTAWA ON K2P 1P9 | N/190.2 | 0.00 | 224 |
| 79 | OPCB | TAGGART CORPORATION | 225 METCALFE STREET, SUITE 708<br>OTTAWA ON K2P 1P9 | N/190.2 | 0.00 | 224 |
| 79 | OPCB | TAGGART CORPORATION | 225 METCALFE STREET, SUITE 708<br>OTTAWA ON K2P 1P9 | N/190.2 | 0.00 | 224 |
| 79 | SCT | F K Dental Lab Ltd | 225 Metcalfe St Suite 500<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 225 |
| 79 | SCT | Chromatek Dental Laboratories | 225 Metcalfe St Suite 500<br>Ottawa ON K2P 1P9 | N/190.2 | 0.00 | 225 |
| 79 | SCT | Ottawa Dentistry | 225 Metcalfe St<br>Ottawa ON K2P1P9 | N/190.2 | 0.00 | 225 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 80 | EHS | | 305 Metcalfe St<br>Ottawa ON K2P1S1 | ESE/190.4 | -1.00 | 226 |
| 81 | EHS | | 324 Somerset Street West<br>Ottawa ON K2P 0J9 | W/192.4 | 2.00 | 226 |
| 82 | HINC | | 322 SOMERSET STREET WEST<br>OTTAWA ON | W/192.8 | 2.00 | 227 |
| 83 | EHS | | 234 O'connor St<br>Ottawa ON K2P1T9 | W/193.8 | 2.00 | 227 |
| 84 | EHS | | 311 Somerset Street West<br>Ottawa ON K2P 0J8 | W/194.2 | 2.00 | 227 |
| 85 | EHS | | 350-352 Gilmour Street and 453 Lewis Street Ottawa, Ontario<br>Ottawa ON K2P 0R3 | SW/194.5 | 1.00 | 227 |
| 86 | GEN | CRAIG OFFICE PRODUCTS CORPORATION | 329 WAVERLEY STREET<br>OTTAWA ON K2P 0V9 | S/195.7 | 0.00 | 228 |
| 86 | GEN | CRAIG OFFICE PRODUCTS CORPORATION 11-330 | 329 WAVERLEY STREET<br>OTTAWA ON K2P 0V9 | S/195.7 | 0.00 | 228 |
| 87 | EHS | | 340 MacLaren Street<br>Ottawa ON K2P 0M6 | WSW/196.8 | 2.00 | 228 |
| 88 | EHS | | 320 Cooper Street Ottawa<br>Ottawa ON K2P 0G7 | NW/199.0 | 0.97 | 229 |
| 89 | EHS | | 326 Somerset St W<br>Ottawa ON K2P0J9 | W/200.7 | 2.00 | 229 |
| 89 | GEN | EnviroCentre | 326 Somerset St. West<br>Ottawa ON K2P 0J9 | W/200.7 | 2.00 | 229 |
| 90 | EHS | | 302 Waverley Street<br>Ottawa ON K2P 0W3 | SSE/201.9 | -1.00 | 230 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 91 | WWIS | | 311 SOMERSET<br>Ottawa ON<br>***Well ID:*** 7391113 | W/203.4 | 2.00 | 230 |
| 92 | SCT | Dentacraft Dental Studio | 190 MacLaren St<br>Ottawa ON K2P0L6 | ENE/205.1 | -1.00 | 234 |
| 92 | SCT | Dentacraft Dental Studio Inc. | 190 MacLaren St Suite 205<br>Ottawa ON K2P 0L6 | ENE/205.1 | -1.00 | 235 |
| 92 | SPL | UNKNOWN | 190 MACLAREN ST.<br>OTTAWA CITY ON K2P 0L6 | ENE/205.1 | -1.00 | 236 |
| 93 | WWIS | | ON<br>***Well ID:*** 7134824 | NE/207.1 | -0.97 | 237 |
| 94 | WWIS | | ON<br>***Well ID:*** 7134806 | NE/208.6 | -0.97 | 240 |
| 95 | EHS | | 340 Cooper street Ottawa ON<br>Ottawa ON K2P 0G7 | WNW/208.6 | 2.00 | 243 |
| 96 | SCT | Aromaflex | 340 MacLaren St<br>Ottawa ON K2P0M6 | WSW/209.4 | 2.00 | 243 |
| 97 | WWIS | | 311 Somerset St W<br>Ottawa ON<br>***Well ID:*** 7382859 | WNW/209.8 | 2.00 | 244 |
| 98 | WWIS | | 356 MACLAREN STREET<br>Ottawa ON<br>***Well ID:*** 7218928 | SW/210.2 | 2.00 | 248 |
| 99 | EHS | | 371 Gilmour St<br>Ottawa ON K2P0R2 | WSW/210.3 | 2.00 | 251 |
| 100 | EHS | | 371 Gilmour Street Ottawa ON<br>Ottawa ON K2P 0R3 | WSW/210.8 | 2.00 | 251 |
| 101 | EHS | | 323 Somerset Street West<br>Ottawa ON K2P 0J8 | W/211.3 | 2.00 | 251 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 102 | GEN | Centretown Citizens Ottawa Corporation | 345 Waverley Street<br>Ottawa ON | SSW/211.6 | 1.08 | 251 |
| 103 | EHS | | 322 Waverly Street Ottawa Ontario<br>Ottawa ON K2P 0W3 | SSE/214.8 | 0.06 | 252 |
| 104 | WWIS | | 311 SOMERSET<br>Ottawa ON<br>***Well ID:*** 7391114 | WNW/215.1 | 2.00 | 252 |
| 105 | EHS | | 250-254 Cooper St<br>Ottawa ON K2P 0G4 | N/216.0 | 0.00 | 256 |
| 106 | EHS | | 297 Cooper St<br>Ottawa ON K2P0G5 | NW/217.3 | 1.00 | 256 |
| 107 | EHS | | 322-326 Waverley Street<br>Ottawa ON K2P 0W3 | SSE/218.3 | 0.06 | 256 |
| 108 | EHS | | 292 Elgin St<br>Ottawa ON K2P1M3 | ENE/218.8 | -1.00 | 257 |
| 109 | EHS | | 309 Cooper Street<br>Ottawa ON K2P 0G5 | NW/219.2 | 0.98 | 257 |
| 109 | SCT | DOMUS SOFTWARE LTD | 309 COOPER ST UNIT 500<br>OTTAWA ON K2P 0G5 | NW/219.2 | 0.98 | 257 |
| 109 | SCT | The Canadian Council on Social Development | 309 Cooper St Floor 5<br>Ottawa ON K2P 0G5 | NW/219.2 | 0.98 | 257 |
| 109 | SCT | Cdn Council on Social Dev | 309 Cooper St Floor 5<br>Ottawa ON K2P 0G5 | NW/219.2 | 0.98 | 258 |
| 109 | SCT | The Ottawa XPress | 309 Cooper St Suite 401<br>Ottawa ON K2P 0G5 | NW/219.2 | 0.98 | 258 |
| 109 | VAR | DALE R KENNY | 309 COOPER ST,,OTTAWA,ON,K2P 0G5, CA<br>ON | NW/219.2 | 0.98 | 258 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 110 | GEN | Elevation Elevator Inc. | 215 Somerset Street, West<br>Ottawa ON K2P0J3 | NNE/219.4 | -1.00 | 259 |
| 111 | GEN | AUBUT & NADEAU SERVICES INC. | 342 MCLAREN STREET<br>OTTAWA ON K2P 0M6 | WSW/219.6 | 2.00 | 259 |
| 112 | EHS | | 330 Metcalfe Street<br>Ottawa ON K2P 1S4 | SE/220.7 | -1.00 | 259 |
| 113 | EHS | | 320 Jack Purcell Lane<br>Ottawa ON K2P2J5 | E/220.7 | -1.00 | 260 |
| 113 | GEN | KONE Inc | 320 JACK PURCELL LANE<br>Ottawa ON K2P 2J5 | E/220.7 | -1.00 | 260 |
| 113 | GEN | City of Ottawa | 320 Jack Purcell Lane<br>Ottawa ON K2P 2J5 | E/220.7 | -1.00 | 260 |
| 113 | GEN | City of Ottawa | 320 Jack Purcell Lane<br>Ottawa ON K2P 2J5 | E/220.7 | -1.00 | 261 |
| 113 | GEN | City of Ottawa | 320 Jack Purcell Lane<br>Ottawa ON K2P 2J5 | E/220.7 | -1.00 | 261 |
| 113 | GEN | City of Ottawa Facility Operations Service | 320 Jack Purcell Lane<br>Ottawa ON | E/220.7 | -1.00 | 261 |
| 114 | EHS | | 341 Maclaren St<br>Ottawa ON K2P2E2 | WSW/220.9 | 1.97 | 264 |
| 115 | EHS | | 214 Metcalfe Street<br>Ottawa ON K2P 1P7 | NNW/221.3 | 0.31 | 264 |
| 116 | EHS | | 338 Somerset Street West Ottawa Ontario<br>Ottawa ON K2P 0J9 | W/221.5 | 2.00 | 265 |
| 116 | HINC | | 338 SOMERSET STREET WEST<br>OTTAWA ON | W/221.5 | 2.00 | 265 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 116 | SCT | CDIA Report Newsletter | 338 Somerset St W Unit 4<br>Ottawa ON K2P 0J9 | W/221.5 | 2.00 | 265 |
| 116 | SCT | whatif? Technologies Inc. | 338 Somerset St W Unit 3<br>Ottawa ON K2P 0J9 | W/221.5 | 2.00 | 266 |
| 116 | SPL | Enbridge Gas Distribution Inc. | 338 Sommerset West<br>Ottawa ON | W/221.5 | 2.00 | 266 |
| 117 | HBAR | Elgin Motors | 286 Elgin<br>Ottawa ON | ENE/222.1 | -1.00 | 267 |
| 117 | HBAR | Elliott Alex | 286 Elgin<br>Ottawa ON | ENE/222.1 | -1.00 | 267 |
| 117 | HBAR | Hillary's Fraser Ltd | 286 Elgin<br>Ottawa ON | ENE/222.1 | -1.00 | 267 |
| 117 | HBAR | Hillary's Fraser Ltd | 286 Elgin<br>Ottawa ON | ENE/222.1 | -1.00 | 267 |
| 117 | HBAR | Elgin Motors | 286 Elgin<br>Ottawa ON | ENE/222.1 | -1.00 | 268 |
| 117 | HBAR | Elgin Motors | 286 Elgin<br>Ottawa ON | ENE/222.1 | -1.00 | 268 |
| 117 | HBAR | Quigg Victor | 286 Elgin<br>Ottawa ON | ENE/222.1 | -1.00 | 268 |
| 118 | HBAR | Elgin Motors | 296 Elgin<br>Ottawa ON | ENE/223.3 | -1.00 | 268 |
| 118 | HBAR | Ottawash Laundry | 211 Gilmour<br>Ottawa ON | ENE/223.3 | -1.00 | 268 |
| 119 | EHS | | 341 MacLaren Street<br>Ottawa ON K2P 2E2 | WSW/223.5 | 2.00 | 268 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 120 | EHS | | 325 Cooper Street<br>Ottawa ON K2P 0G5 | NW/224.1 | 1.46 | 268 |
| 121 | EHS | | 375 Gilmour St<br>Ottawa ON | WSW/225.7 | 2.00 | 269 |
| 122 | EHS | | 330 Metcalfe Street<br>Ottawa ON K2P 1S4 | SE/225.8 | -1.00 | 269 |
| 123 | WWIS | | ON<br>***Well ID:*** 7134805 | NE/225.9 | -0.97 | 269 |
| 124 | EHS | | 261 Cooper Street<br>Ottawa ON K2P 0G3 | NNW/226.0 | 0.00 | 272 |
| 124 | GEN | Regency Towers Ltd. | 261 Cooper Street<br>Ottawa ON K2P 0G3 | NNW/226.0 | 0.00 | 272 |
| 125 | EHS | | 330 Metcalfe Street Ottawa Ontario<br>Ottawa ON K2P 1S4 | SE/226.1 | -1.00 | 273 |
| 126 | EHS | | 327 Somerset St W<br>Ottawa ON K2P0J8 | W/226.3 | 2.00 | 273 |
| 127 | HBAR | Blair's Doc B A Station | 280 Elgin<br>Ottawa ON | ENE/227.3 | -1.33 | 273 |
| 128 | CA | ALLAN KWAI | 331 SOMERSET ST. W., SWM<br>OTTAWA CITY ON K2P 0J8 | W/228.1 | 2.00 | 274 |
| 129 | WWIS | | 338 SOMERSET STREET WEST<br>OTTAWA ON<br>***Well ID:*** 7046637 | W/228.4 | 2.00 | 274 |
| 130 | WWIS | | ON<br>***Well ID:*** 7134804 | NE/228.8 | -1.45 | 277 |
| 131 | SCT | Fettuccine's | 280 Elgin St<br>Ottawa ON K2P 1M2 | ENE/229.0 | -1.33 | 281 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 132 | RST | TOPIA ENERGY | 311 O'CONNOR ST<br>OTTAWA ON K2P 2G9 | S/230.2 | 0.00 | 281 |
| 133 | WWIS | | 331 Cooper St<br>Ottawa ON<br>***Well ID:*** 7334763 | WNW/231.5 | 2.00 | 281 |
| 134 | EHS | | 335 Cooper Street<br>Ottawa ON K2P 0G5 | WNW/232.4 | 2.00 | 284 |
| 135 | EHS | | 295 frank st<br>Ottawa ON K2P 0X7 | SE/232.7 | -1.00 | 285 |
| 136 | CA | Tartan Land Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | WNW/233.4 | 2.00 | 285 |
| 136 | CA | Tartan Land Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | WNW/233.4 | 2.00 | 285 |
| 136 | CA | Tartan Land Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | WNW/233.4 | 2.00 | 285 |
| 136 | ECA | South Nepean Development Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON K1R 7Y2 | WNW/233.4 | 2.00 | 286 |
| 136 | ECA | South Nepean Development Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON | WNW/233.4 | 2.00 | 286 |
| 136 | ECA | South Nepean Development Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON | WNW/233.4 | 2.00 | 286 |
| 136 | PINC | PIPELINE HIT 1" | 331 COOPER ST,,OTTAWA,ON,K2P 0G5,<br>CA<br>ON | WNW/233.4 | 2.00 | 287 |
| 136 | SPL | Enbridge Gas Distribution Inc. | 331 Cooper St.<br>Ottawa ON | WNW/233.4 | 2.00 | 287 |
| 137 | EHS | | 264 Elgin St<br>Ottawa ON K2P 1M2 | NE/233.9 | -1.69 | 288 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 137 | GEN | WHITE CROSS DISPENSARY | 264 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE/233.9 | -1.69 | 288 |
| 137 | GEN | White Cross Dispensary Ottawa 2006 Ltd | 264 Elgin Street<br>Ottawa ON K2P 1M2 | NE/233.9 | -1.69 | 289 |
| 137 | GEN | White Cross Dispensary Ottawa 2006 Ltd | 264 Elgin Street<br>Ottawa ON K2P 1M2 | NE/233.9 | -1.69 | 289 |
| 137 | GEN | White Cross Dispensary | 264 Elgin Street<br>Ottawa ON | NE/233.9 | -1.69 | 289 |
| 138 | GEN | CMG | 344 Waverley St.<br>Ottawa ON K2P 0W5 | S/234.7 | 0.00 | 292 |
| 139 | EHS | | 292 Elgin Street Ottawa Ontario<br>Ottawa ON K2P 1M3 | ENE/234.8 | -1.00 | 292 |
| 140 | BORE | | ON | WNW/235.7 | 2.00 | 292 |
| 141 | DTNK | 350807 ONTARIO LTD ELGIN SERVICE CENTRE | 280 ELGIN ST<br>OTTAWA ON | NE/235.9 | -1.33 | 294 |
| 141 | GEN | SUNSHINE BICYCLE BOARD & BLADES | 280 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE/235.9 | -1.33 | 295 |
| 141 | PRT | 350807 ONTARIO LTD ELGIN SERVICE CENTRE | 280 ELGIN ST<br>OTTAWA ON K2P 1M2 | NE/235.9 | -1.33 | 295 |
| 142 | GEN | JUST TYPESETTING | 298 ELGIN ST. ST. 105<br>OTTAWA ON K2P 1M3 | ENE/236.6 | -1.00 | 296 |
| 142 | GEN | JUST TYPESETTING (OUT OF BUSINESS) | 298 ELGIN ST. ST. 105<br>OTTAWA ON K2P 1M3 | ENE/236.6 | -1.00 | 296 |
| 142 | GEN | JUST TYPESETTING 22-281 | 298 ELGIN ST. ST. 105<br>OTTAWA ON K2P 1M3 | ENE/236.6 | -1.00 | 296 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 142 | SCT | Empire Photo and Video Inc. | 298 Elgin St #104<br>Ottawa ON K2P1M3 | ENE/236.6 | -1.00 | 297 |
| 143 | GEN | BROWNS CLEANERS & TAILORS LTD. | 300 ELGIN STREET C/O 6 CHAMPAGNE AVENUE NORTH<br>OTTAWA-CARLTON ON K2P 1M3 | ENE/236.8 | -1.00 | 298 |
| 143 | GEN | BROWNS CLEANERS & TAILORS LTD. 06-342 | 300 ELGIN STREET C/O 6 CHAMPAGNE AVENUE NORTH<br>OTTAWA-CARLTON ON K2P 1M3 | ENE/236.8 | -1.00 | 298 |
| 144 | GEN | ENR Abraham | 284 Elgin<br>Ottawa ON K2P 1M3 | ENE/240.9 | -1.00 | 298 |
| 145 | GEN | Danosh construction | 325 Cooper St<br>ottawa ON K2P 0G5 | NW/241.0 | 0.88 | 299 |
| 145 | GEN | Danosh construction | 325 Cooper St<br>ottawa ON K2P 0G5 | NW/241.0 | 0.88 | 299 |
| 146 | EHS | | 190 Somerset Street West<br>Ottawa ON K2P0J1 | NE/241.4 | -1.69 | 300 |
| 146 | EHS | | 190 Somerset St. W.<br>Ottawa ON | NE/241.4 | -1.69 | 300 |
| 146 | GEN | DST Consulting | 190 somerset west<br>ottawa ON | NE/241.4 | -1.69 | 301 |
| 147 | GEN | AIM Healt Group - Elgin | 270 Elgin Street<br>Ottawa ON K2P 1M2 | NE/242.6 | -2.06 | 301 |
| 147 | GEN | Saralex Medical Inc. | 270 Elgin Street<br>Ottawa ON K2P 1M2 | NE/242.6 | -2.06 | 301 |
| 147 | GEN | Saralex Medical Inc. | 270 Elgin Street<br>Ottawa ON K2P 1M2 | NE/242.6 | -2.06 | 301 |
| 147 | GEN | Saralex Medical Inc. | 270 Elgin Street<br>Ottawa ON K2P 1M2 | NE/242.6 | -2.06 | 302 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 148 | GEN | SKETCHLEY CLEANING SERVICES LTD. | 268 ELGIN ST.<br>OTTAWA ON K2P 1M2 | NE/243.7 | -1.69 | 304 |
| 148 | GEN | SKETCHLEY CLEANING SERVICES LTD. | 268 ELGIN ST.<br>OTTAWA ON K2P 1M2 | NE/243.7 | -1.69 | 304 |
| 148 | GEN | SKETCHLEY CLEANING SERVICES LTD. 35-248 | 268 ELGIN ST.<br>OTTAWA ON K2P 1M2 | NE/243.7 | -1.69 | 304 |
| 148 | GEN | SKETCHLEY CLEANING SERVICES LIMITED | 268 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE/243.7 | -1.69 | 305 |
| 148 | GEN | HILLARY CLEANERS (SEE&USEON0240427- | SKETCH) 268 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE/243.7 | -1.69 | 305 |
| 148 | GEN | HILLARY (SEE & USE ON0240427) 20-099 | 268 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE/243.7 | -1.69 | 306 |
| 149 | GEN | Ottawa Community Housing Corp | 379 Gilmour Street<br>Ottawa ON K2P 2M6 | WSW/245.2 | 2.00 | 306 |
| 150 | WWIS | | ON<br>***Well ID:*** 7471728 | WNW/245.7 | 2.00 | 307 |
| 151 | HINC | | 331 METCALFE STREET<br>OTTAWA ON K2P 1S3 | ESE/246.1 | -0.92 | 307 |
| 152 | EHS | | 346 Waverley St<br>Ottawa ON K2P 0W5 | S/246.4 | 0.00 | 308 |
| 152 | SCT | Paramount Gold & Silver Corp. | 346 Waverley St<br>Ottawa ON K2P 0W5 | S/246.4 | 0.00 | 308 |
| 153 | HBAR | Langley's | 281 Elgin<br>Ottawa ON | ENE/248.0 | -1.24 | 309 |
| 154 | BORE | | ON | SE/248.1 | -1.00 | 309 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 155 | SPL | 285 MacLaren St | OTTAWA ON | WSW/248.6 | 1.91 | 311 |
| 156 | EHS | | 356 MacLaren Street<br>Ottawa ON K2P 0M6 | WSW/248.8 | 1.91 | 312 |
| 156 | EHS | | 356 MacLaren Street<br>Ottawa ON K2P 0M6 | WSW/248.8 | 1.91 | 312 |
| 156 | GEN | AUBUT & NADEAU SERVICES INC. | 356 MCLAREN STREET<br>OTTAWA ON K2P 0M6 | WSW/248.8 | 1.91 | 312 |

# Executive Summary: Summary By Data Source

## BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 8 BORE site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | ON | SW | 67.44 | 16 |
| | ON | WNW | 134.73 | 37 |
| | ON | W | 161.04 | 52 |
| | ON | WNW | 235.67 | 140 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | ON | S | 116.83 | 27 |
| | ON | ESE | 178.34 | 63 |
| | ON | ESE | 182.19 | 66 |
| | ON | SE | 248.12 | 154 |

## CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 9 CA site(s) within approximately 0.25 kilometers of

the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| R.M. OF OTTAWA-CARLETON | SOMERSET ST./METCALFE ST.<br>OTTAWA CITY ON | N | 120.75 | 28 |
| City of Ottawa | Somerset Street and Metcalfe Street<br>Ottawa ON | N | 120.75 | 28 |
| 1384274 Ontario Inc. | 330 Gilmour St Ward 14<br>Ottawa ON K2P 2P6 | SSW | 129.10 | 34 |
| OTTAWA CITY - BANK STREET | GILMOUR ST./O'CONNOR ST.<br>OTTAWA CITY ON | SW | 130.39 | 36 |
| ALLAN KWAI | 331 SOMERSET ST. W., SWM<br>OTTAWA CITY ON K2P 0J8 | W | 228.12 | 128 |
| Tartan Land Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | WNW | 233.44 | 136 |
| Tartan Land Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | WNW | 233.44 | 136 |
| Tartan Land Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | WNW | 233.44 | 136 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| R.M. OF OTTAWA-CARLETON | LEWIS ST/METCALFE ST.<br>OTTAWA CITY ON | ESE | 124.59 | 30 |

### DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 1 DTNK site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|

| | | | | |
|---|---|---|---|---|
| 350807 ONTARIO LTD ELGIN SERVICE CENTRE | 280 ELGIN ST<br>OTTAWA ON | NE | 235.90 | 141 |

## ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011 - Nov 30, 2025 has found that there are 6 ECA site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| City of Ottawa | Somerset Street and Metcalfe St<br>Ottawa ON K2G 6J8 | N | 120.75 | 28 |
| City of Ottawa | Somerset Street and Metcalfe St<br>Ottawa ON K2G 6J8 | N | 120.75 | 28 |
| 1384274 Ontario Inc. | 330 Gilmour St Ward 14<br>Ottawa ON K2E 1A9 | SSW | 129.10 | 34 |
| South Nepean Development Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON | WNW | 233.44 | 136 |
| South Nepean Development Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON | WNW | 233.44 | 136 |
| South Nepean Development Corporation | 331 Cooper Street, Suite 400<br>Ottawa ON K1R 7Y2 | WNW | 233.44 | 136 |

## EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Nov 30, 2025 has found that there are 74 EHS site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 283 MacLaren Street<br>Ottawa ON K2P 0M2 | W | 56.10 | 8 |
| | 255 Metcalfe Street<br>Ottawa ON K2P 0N9 | ENE | 73.59 | 19 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| | 267 O'connor St<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | WSW | 84.64 | 22 |
| | 258-260 Somerset Street West<br>Ottawa ON K2P 0J6 | NNW | 87.04 | 24 |
| | 225 MacLaren Street<br>Ottawa ON K2P 0L4 | NE | 126.98 | 31 |
| | 300 Somerset St W<br>Ottawa ON K2P0J6 | W | 129.00 | 33 |
| | 250 O'Connor Street<br>Ottawa ON K2P 1V2 | W | 144.19 | 42 |
| | 278-280 O'Connor St and 347 Gilmour St<br>Ottawa ON K2P 1V4 | SW | 147.98 | 45 |
| | 331 Maclaren St<br>Ottawa ON K2P0M4 | W | 156.88 | 49 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 318 Cooper St<br>Ottawa ON | NW | 172.05 | 57 |
| | 320 Cooper Street<br>Ottawa ON K2P 0G7 | WNW | 177.38 | 60 |
| | 320 Cooper St<br>Ottawa ON K2P0G7 | WNW | 177.38 | 60 |
| | 320 Cooper Street Ottawa ON<br>Ottawa ON K2P 0G7 | WNW | 177.38 | 60 |
| | 334 MacLaren Street<br>Ottawa ON K2P 0M6 | WSW | 178.24 | 61 |
| | 335 MacLaren Street<br>Ottawa ON K2P 0M4 | WSW | 182.82 | 68 |
| | 335 Maclaren St<br>Ottawa ON K2P0M5 | WSW | 184.30 | 71 |
| | 350 Gilmour Street<br>Ottawa ON K2P 0R3 | SW | 185.29 | 74 |
| | 318 Cooper Street Ottawa ON<br>Ottawa ON K2P 0G7 | NW | 189.49 | 77 |
| | 324 Somerset Street West<br>Ottawa ON K2P 0J9 | W | 192.40 | 81 |
| | 234 O'connor St<br>Ottawa ON K2P1T9 | W | 193.78 | 83 |
| | 311 Somerset Street West<br>Ottawa ON K2P 0J8 | W | 194.22 | 84 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 350-352 Gilmour Street and 453 Lewis Street Ottawa, Ontario<br>Ottawa ON K2P 0R3 | SW | 194.50 | 85 |
| | 340 MacLaren Street<br>Ottawa ON K2P 0M6 | WSW | 196.77 | 87 |
| | 320 Cooper Street Ottawa<br>Ottawa ON K2P 0G7 | NW | 199.05 | 88 |
| | 326 Somerset St W<br>Ottawa ON K2P0J9 | W | 200.74 | 89 |
| | 340 Cooper street Ottawa ON<br>Ottawa ON K2P 0G7 | WNW | 208.64 | 95 |
| | 371 Gilmour St<br>Ottawa ON K2P0R2 | WSW | 210.25 | 99 |
| | 371 Gilmour Street Ottawa ON<br>Ottawa ON K2P 0R3 | WSW | 210.82 | 100 |
| | 323 Somerset Street West<br>Ottawa ON K2P 0J8 | W | 211.31 | 101 |
| | 322 Waverly Street Ottawa Ontario<br>Ottawa ON K2P 0W3 | SSE | 214.77 | 103 |
| | 250-254 Cooper St<br>Ottawa ON K2P 0G4 | N | 216.02 | 105 |
| | 297 Cooper St<br>Ottawa ON K2P0G5 | NW | 217.35 | 106 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 322-326 Waverley Street<br>Ottawa ON K2P 0W3 | SSE | 218.27 | 107 |
| | 309 Cooper Street<br>Ottawa ON K2P 0G5 | NW | 219.25 | 109 |
| | 341 Maclaren St<br>Ottawa ON K2P2E2 | WSW | 220.88 | 114 |
| | 214 Metcalfe Street<br>Ottawa ON K2P 1P7 | NNW | 221.34 | 115 |
| | 338 Somerset Street West Ottawa Ontario<br>Ottawa ON K2P 0J9 | W | 221.48 | 116 |
| | 341 MacLaren Street<br>Ottawa ON K2P 2E2 | WSW | 223.55 | 119 |
| | 325 Cooper Street<br>Ottawa ON K2P 0G5 | NW | 224.08 | 120 |
| | 375 Gilmour St<br>Ottawa ON | WSW | 225.74 | 121 |
| | 261 Cooper Street<br>Ottawa ON K2P 0G3 | NNW | 225.97 | 124 |
| | 327 Somerset St W<br>Ottawa ON K2P0J8 | W | 226.33 | 126 |
| | 335 Cooper Street<br>Ottawa ON K2P 0G5 | WNW | 232.43 | 134 |
| | 346 Waverley St<br>Ottawa ON K2P 0W5 | S | 246.36 | 152 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 356 MacLaren Street<br>Ottawa ON K2P 0M6 | WSW | 248.82 | 156 |
| | 356 MacLaren Street<br>Ottawa ON K2P 0M6 | WSW | 248.82 | 156 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 252 Metcalfe St.<br>Ottawa ON K2P 1R3 | N | 58.47 | 12 |
| | 252 Metcalfe Street<br>Ottawa ON K2P 1R3 | N | 58.47 | 12 |
| | 296 Metcalfe Street<br>Ottawa ON K2P 1S2 | ESE | 128.19 | 32 |
| | 222 MacLaren Street<br>Ottawa ON K2P 0L8 | ENE | 139.28 | 40 |
| | 222 Maclaren St<br>Ottawa ON K2P0L8 | ENE | 139.28 | 40 |
| | 246 Gilmour St<br>Ottawa ON K2P 0P6 | E | 157.95 | 50 |
| | 301 Metcalfe Street<br>Ottawa ON K2P 1R9 | ESE | 167.39 | 53 |
| | 301 Metcalfe Street<br>Ottawa ON K2P 1R9 | ESE | 167.98 | 54 |
| | 301 Metcalfe St<br>Ottawa ON K2P1R9 | ESE | 169.73 | 55 |

| | | | |
|---|---|---|---|
| 218 maclaren street<br>ottawa ON K2P 0L7 | ENE | 170.96 | 56 |
| 218 MacLaren Street<br>Ottawa ON K2P 0L4 | ENE | 170.96 | 56 |
| 223 Somerset St W<br>Ottawa ON K2P0J1 | NNE | 182.17 | 65 |
| 305 Metcalfe St<br>Ottawa ON K2P1S1 | ESE | 190.43 | 80 |
| 302 Waverley Street<br>Ottawa ON K2P 0W3 | SSE | 201.94 | 90 |
| 292 Elgin St<br>Ottawa ON K2P1M3 | ENE | 218.75 | 108 |
| 330 Metcalfe Street<br>Ottawa ON K2P 1S4 | SE | 220.65 | 112 |
| 320 Jack Purcell Lane<br>Ottawa ON K2P2J5 | E | 220.69 | 113 |
| 330 Metcalfe Street<br>Ottawa ON K2P 1S4 | SE | 225.84 | 122 |
| 330 Metcalfe Street Ottawa Ontario<br>Ottawa ON K2P 1S4 | SE | 226.05 | 125 |
| 295 frank st<br>Ottawa ON K2P 0X7 | SE | 232.71 | 135 |
| 264 Elgin St<br>Ottawa ON K2P 1M2 | NE | 233.85 | 137 |

| | | | | |
|---|---|---|---|---|
| | 292 Elgin Street Ottawa Ontario<br>Ottawa ON K2P 1M3 | ENE | 234.81 | 139 |
| | 190 Somerset Street West<br>Ottawa ON K2P0J1 | NE | 241.37 | 146 |
| | 190 Somerset St. W.<br>Ottawa ON | NE | 241.37 | 146 |

## GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Mar 31, 2025 has found that there are 171 GEN site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Trilex Holdings Ltd (Care of District Reality) | 307 GILMOUR ST<br>OTTAWA ON K2P 0P7 | SSW | 53.64 | 7 |
| CM3 Environmental Inc. | 283 MacLaren Street<br>Ottawa ON | W | 56.10 | 8 |
| KOPP CLINICAL LABORATORIES | 267 O'CONNOR STREET, SUITE 104<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |
| KOPP CLINICAL LABORAT (OUT OF BUSINESS) | 267 O'CONNOR STREET, SUITE 104<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |
| KOPP CLINICAL LABORATORIES 23-100 | 267 O'CONNOR STREET, SUITE 104<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |
| O'CONNOR PHARMACY | 267 O'CONNER STREET<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |
| CML HealthCare Inc. | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| CML HealthCare Inc. | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| CML HealthCare Inc. | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'conner Street Suite 225<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 225<br>Ottawa ON | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| CML HealthCare Inc. | 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| LifeLabs LP | 267 O'Connor Street, Unit B003<br>Ottawa ON | SW | 78.85 | 20 |
| LifeLabs LP | 267 O'Connor Street, Unit B003<br>Ottawa ON | SW | 78.85 | 20 |
| Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON | SW | 78.85 | 20 |
| Midtown Family Health | 267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| We Care Home Health Services | 267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| We Care Home Health Services | 267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| LifeLabs LP | 267 O'Connor Street, Unit B003<br>Ottawa ON K1S 1C2 | SW | 78.85 | 20 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P1V3 | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |
| Midtown Family Health | 267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| LifeLabs LP | 267 O'Connor Street, Unit B003<br>Ottawa ON K1S 1C2 | SW | 78.85 | 20 |
| Dr. Donald K. Wilson Medicine Prof. Corp. | 403-267 O'Connor St<br>Ottawa ON K2P1V3 | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Midtown Family Health | 267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| CBI Home Health formerly We Care Home Health | 267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 OConnor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Midtown Family Health | 267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Midtown Family Health | 267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 OConnor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| CBI Home Health formerly We Care Home Health | 267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Central Ottawa Family Medicine Associates Ltd. | Suite 500 267 OConnor Street<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| CBI Home Health formerly We Care Home Health | 267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Sajjad Giby Pharmacies Inc. | 267 O'CONNOR STREET, UNIT 120<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Ottawa Endoscopy & Day Surgery | 267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Midtown Family Health | 267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| CBI Home Health formerly We Care Home Health | 267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| Midtown Ottawa FHO | 267 O'Connor ST. Suite 306<br>Ottawa ON | SW | 78.85 | 20 |
| CENTRAL OTTAWA FAMILY MEDICINE ASSOCIATES LTD. | Suite 500, 267 O'Connor Street<br>Ottawa ON | SW | 78.85 | 20 |
| GLENVIEW CORPORATION | 270 SOMERSET WEST<br>OTTAWA ON K2P 0J7 | NW | 100.85 | 26 |
| OTTAWA BOARD OF EDUCATION | 330 GILMOUR STREET<br>OTTAWA ON K2P 2P6 | SSW | 129.10 | 34 |
| OTTAWA BOARD OF EDUCATION 29-129 | 330 GILMOUR STREET<br>OTTAWA ON K2P 2P6 | SSW | 129.10 | 34 |
| OTTAWA BOARD OF EDUCATION | ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.<br>OTTAWA ON K2P 0P9 | SSW | 129.10 | 34 |
| OTTAWA (SEE&USE ON1285703) | ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.<br>OTTAWA ON K2P 0P9 | SSW | 129.10 | 34 |
| OTTAWA (SEE&USE ON1285703) 29-129 | ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.<br>OTTAWA ON K2P 0P9 | SSW | 129.10 | 34 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| OCSCC # 1049 | 222 Somerset St. West<br>Ottawa ON K2P 0A7 | NNE | 137.78 | 39 |
| GTA'S Finest Restoration | 236 Somerset<br>Ottawa ON K2P0J4 | NNE | 147.59 | 44 |
| AK Global Management Inc | 280-282 O'Connor Street<br>Ottawa ON K2P 1V4 | SW | 150.12 | 47 |
| TAGGART CORPORATION | 235 SOMERSET STREET WEST<br>OTTAWA ON K2P 0J3 | N | 156.10 | 48 |
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S | 159.02 | 51 |
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S | 159.02 | 51 |
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON | S | 159.02 | 51 |
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S | 159.02 | 51 |
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S | 159.02 | 51 |
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S | 159.02 | 51 |
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S | 159.02 | 51 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S | 159.02 | 51 |
| David Jordan Medicne Professional Corporation | 301 O'Connor St.<br>Ottawa ON K2P 1V6 | S | 159.02 | 51 |
| David Jordan Medicine Professional Corporation | 301 O'Connor St.<br>Ottawa ON | S | 159.02 | 51 |
| dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503<br>ottawa ON K2P1P9 | N | 190.21 | 79 |
| Kenson Downtown Dentistry | 225 Metcalfe Street, Suite 504<br>Ottawa ON | N | 190.21 | 79 |
| DR STANLEY SHIFF | 225 Metcalfe Street<br>Ottawa ON | N | 190.21 | 79 |
| Capital Dentistry Group Ltd. | 225 Metcalfe Street<br>Ottawa ON | N | 190.21 | 79 |
| Capital Dentistry Group Ltd. | 225 Metcalfe Street<br>Ottawa ON | N | 190.21 | 79 |
| ARTEXT (OUT OF BUS) | 225 METCALFE STREET, SUITE 710<br>OTTAWA ON K2P 1P9 | N | 190.21 | 79 |
| ARTEXT ELECTRONIC PUBLISHING INC. | 225 METCALFE STREET, SUITE 710<br>OTTAWA ON K2P 1P9 | N | 190.21 | 79 |
| TAGGART CORPORATION | 708-225 Metcalfe Street<br>OTTAWA ON K2P 1P9 | N | 190.21 | 79 |
| Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N | 190.21 | 79 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102 Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Dr. J. Li Dentistry Professional Corporation | 400-225 Metcalfe Street Ottawa ON K2P1P9 | N | 190.21 | 79 |
| dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503 ottawa ON K2P1P9 | N | 190.21 | 79 |
| Dr. J. Li Dentistry Professional Corporation | 400-225 Metcalfe Street Ottawa ON K2P1P9 | N | 190.21 | 79 |
| Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102 Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Dr. J. Li Dentistry Professional Corporation | 400-225 Metcalfe Street Ottawa ON K2P1P9 | N | 190.21 | 79 |
| dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503 ottawa ON K2P1P9 | N | 190.21 | 79 |
| Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102 Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Dr. J. Li Dentistry Professional Corporation | 400-225 Metcalfe Street Ottawa ON K2P1P9 | N | 190.21 | 79 |
| Metcalfe Street Dental | 225 Metcalfe Street, Unit 104 Ottawa ON K2P1P9 | N | 190.21 | 79 |
| dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503 ottawa ON K2P1P9 | N | 190.21 | 79 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Metcalfe Street Dental | 225 Metcalfe Street, Unit 104<br>Ottawa ON K2P1P9 | N | 190.21 | 79 |
| Metcalfe Street Dental | 225 Metcalfe Street Unit 104<br>Ottawa ON K2P1P9 | N | 190.21 | 79 |
| dr stanley shiff/dr dana shiff | 225 metcalfe st suite 503<br>ottawa ON K2P1P9 | N | 190.21 | 79 |
| Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Metcalfe Street Dental | 225 Metcalfe Street Unit 104<br>Ottawa ON K2P1P9 | N | 190.21 | 79 |
| Capital Dentistry Group Ltd. | 225 Metcalfe Street, Unit 104<br>Ottawa ON | N | 190.21 | 79 |
| Drs. John and Micaela Fitzgerald Dentistry Profess | 225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Metcalfe and Cooper Family Dentistry | 225 Metcalfe St. Unit 507<br>Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Dr. Amar Kuruganti Dentistry Professional Corporat Kenson Downtown Dentistry | 225 Metcalfe Street Suite 504<br>Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| CRAIG OFFICE PRODUCTS CORPORATION | 329 WAVERLEY STREET<br>OTTAWA ON K2P 0V9 | S | 195.70 | 86 |
| CRAIG OFFICE PRODUCTS CORPORATION 11-330 | 329 WAVERLEY STREET<br>OTTAWA ON K2P 0V9 | S | 195.70 | 86 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| EnviroCentre | 326 Somerset St. West<br>Ottawa ON K2P 0J9 | W | 200.74 | 89 |
| Centretown Citizens Ottawa Corporation | 345 Waverley Street<br>Ottawa ON | SSW | 211.64 | 102 |
| AUBUT & NADEAU SERVICES INC. | 342 MCLAREN STREET<br>OTTAWA ON K2P 0M6 | WSW | 219.59 | 111 |
| Regency Towers Ltd. | 261 Cooper Street<br>Ottawa ON K2P 0G3 | NNW | 225.97 | 124 |
| CMG | 344 Waverley St.<br>Ottawa ON K2P 0W5 | S | 234.68 | 138 |
| Danosh construction | 325 Cooper St<br>ottawa ON K2P 0G5 | NW | 241.04 | 145 |
| Danosh construction | 325 Cooper St<br>ottawa ON K2P 0G5 | NW | 241.04 | 145 |
| Ottawa Community Housing Corp | 379 Gilmour Street<br>Ottawa ON K2P 2M6 | WSW | 245.16 | 149 |
| AUBUT & NADEAU SERVICES INC. | 356 MCLAREN STREET<br>OTTAWA ON K2P 0M6 | WSW | 248.82 | 156 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Elevation Elevator Inc | 295 Gilmour Street<br>Ottawa ON | SSE | 40.87 | 3 |
| PSAC Holdings Ltd. | 233 Gilmour Street<br>Ottawa ON K2P 0P2 | E | 124.28 | 29 |

| | | | | |
|---|---|---|---|---|
| PSAC Holdings Ltd. | 233 Gilmour Street<br>Ottawa ON | E | 124.28 | 29 |
| PSAC Holdings Ltd. | 233 Gilmour Street<br>Ottawa ON | E | 124.28 | 29 |
| PSAC HOLDINGS LTD. | 233 GILMOUR STREET<br>OTTAWA ON K1S 1V7 | E | 124.28 | 29 |
| Plomberie Bourget Plumbing | 233 gilmour st ottawa<br>Ottawa ON | E | 124.28 | 29 |
| PUBLIC SERVICE ALLIANCE OF CANADA | 233 GILMOUR ST.<br>OTTAWA ON K2P 0P1 | E | 124.28 | 29 |
| PUBLIC SERVICE ALLIANCE OF CANADA 31-381 | 233 GILMOUR ST.<br>OTTAWA ON K2P 0P1 | E | 124.28 | 29 |
| Timbercreek Communities | 222 Metcalfe St<br>Ottawa ON K2P 1R2 | N | 143.11 | 41 |
| Carleton Condominium Corporation 251 | 420 Lewis Street<br>Ottawa ON K2P 0S9 | S | 146.31 | 43 |
| Ottawa-Carleton District School Board | Elgin Street Public School 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board | Elgin Street PS 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board | 310 Elgin St.<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |

| | | | | |
|---|---|---|---|---|
| Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON | E | 182.64 | 67 |
| Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board Health & Safety | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board Health & Safety | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board Health & Safety | 310 Elgin Street<br>Ottawa ON K2P 1M4 | E | 182.64 | 67 |
| Ottawa-Carleton District School Board | Elgin Street Public School, 310 Elgin Street<br>Ottawa ON | E | 182.64 | 67 |
| Elevation Elevator Inc. | 215 Somerset Street, West<br>Ottawa ON K2P0J3 | NNE | 219.44 | 110 |
| KONE Inc | 320 JACK PURCELL LANE<br>Ottawa ON K2P 2J5 | E | 220.69 | 113 |
| City of Ottawa | 320 Jack Purcell Lane<br>Ottawa ON K2P 2J5 | E | 220.69 | 113 |
| City of Ottawa | 320 Jack Purcell Lane<br>Ottawa ON K2P 2J5 | E | 220.69 | 113 |

| | | | | |
|---|---|---|---|---|
| City of Ottawa | 320 Jack Purcell Lane<br>Ottawa ON K2P 2J5 | E | 220.69 | 113 |
| City of Ottawa Facility Operations Service | 320 Jack Purcell Lane<br>Ottawa ON | E | 220.69 | 113 |
| WHITE CROSS DISPENSARY | 264 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE | 233.85 | 137 |
| White Cross Dispensary Ottawa 2006 Ltd | 264 Elgin Street<br>Ottawa ON K2P 1M2 | NE | 233.85 | 137 |
| White Cross Dispensary Ottawa 2006 Ltd | 264 Elgin Street<br>Ottawa ON K2P 1M2 | NE | 233.85 | 137 |
| White Cross Dispensary | 264 Elgin Street<br>Ottawa ON | NE | 233.85 | 137 |
| SUNSHINE BICYCLE BOARD & BLADES | 280 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE | 235.90 | 141 |
| JUST TYPESETTING | 298 ELGIN ST. ST. 105<br>OTTAWA ON K2P 1M3 | ENE | 236.64 | 142 |
| JUST TYPESETTING (OUT OF BUSINESS) | 298 ELGIN ST. ST. 105<br>OTTAWA ON K2P 1M3 | ENE | 236.64 | 142 |
| JUST TYPESETTING 22-281 | 298 ELGIN ST. ST. 105<br>OTTAWA ON K2P 1M3 | ENE | 236.64 | 142 |
| BROWNS CLEANERS & TAILORS LTD. | 300 ELGIN STREET C/O 6 CHAMPAGNE AVENUE NORTH<br>OTTAWA-CARLTON ON K2P 1M3 | ENE | 236.79 | 143 |
| BROWNS CLEANERS & TAILORS LTD. 06-342 | 300 ELGIN STREET C/O 6 CHAMPAGNE AVENUE NORTH<br>OTTAWA-CARLTON ON K2P 1M3 | ENE | 236.79 | 143 |

| | | | | |
|---|---|---|---|---|
| ENR Abraham | 284 Elgin<br>Ottawa ON K2P 1M3 | ENE | 240.91 | 144 |
| DST Consulting | 190 somerset west<br>ottawa ON | NE | 241.37 | 146 |
| AIM Healt Group - Elgin | 270 Elgin Street<br>Ottawa ON K2P 1M2 | NE | 242.55 | 147 |
| Saralex Medical Inc. | 270 Elgin Street<br>Ottawa ON K2P 1M2 | NE | 242.55 | 147 |
| Saralex Medical Inc. | 270 Elgin Street<br>Ottawa ON K2P 1M2 | NE | 242.55 | 147 |
| Saralex Medical Inc. | 270 Elgin Street<br>Ottawa ON K2P 1M2 | NE | 242.55 | 147 |
| SKETCHLEY CLEANING SERVICES LTD. | 268 ELGIN ST.<br>OTTAWA ON K2P 1M2 | NE | 243.69 | 148 |
| SKETCHLEY CLEANING SERVICES LTD. | 268 ELGIN ST.<br>OTTAWA ON K2P 1M2 | NE | 243.69 | 148 |
| SKETCHLEY CLEANING SERVICES LTD. 35-248 | 268 ELGIN ST.<br>OTTAWA ON K2P 1M2 | NE | 243.69 | 148 |
| SKETCHLEY CLEANING SERVICES LIMITED | 268 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE | 243.69 | 148 |
| HILLARY CLEANERS (SEE&USEON0240427- | SKETCH) 268 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE | 243.69 | 148 |
| HILLARY (SEE & USE ON0240427) 20-099 | 268 ELGIN STREET<br>OTTAWA ON K2P 1M2 | NE | 243.69 | 148 |

## HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 5 HINC site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 293 McLAREN STREET<br>OTTAWA ON | W | 86.74 | 23 |
| | 438 LEWIS STREET<br>OTTAWA ON | SSW | 184.58 | 72 |
| | 322 SOMERSET STREET WEST<br>OTTAWA ON | W | 192.78 | 82 |
| | 338 SOMERSET STREET WEST<br>OTTAWA ON | W | 221.48 | 116 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 331 METCALFE STREET<br>OTTAWA ON K2P 1S3 | ESE | 246.05 | 151 |

## HIST RISK - Historical Business Activity Risk

A search of the HIST RISK database, dated 1920s - 1960 has found that there are 12 HIST RISK site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| California Standard Co | 233 Metcalfe<br>Ottawa ON | N | 183.34 | 69 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Hillary's Fraser Ltd | 286 Elgin<br>Ottawa ON | ENE | 222.10 | 117 |
| Quigg Victor | 286 Elgin<br>Ottawa ON | ENE | 222.10 | 117 |

| | | | | |
|---|---|---|---|---|
| Elgin Motors | 286 Elgin<br>Ottawa ON | ENE | 222.10 | 117 |
| Elliott Alex | 286 Elgin<br>Ottawa ON | ENE | 222.10 | 117 |
| Hillary's Fraser Ltd | 286 Elgin<br>Ottawa ON | ENE | 222.10 | 117 |
| Elgin Motors | 286 Elgin<br>Ottawa ON | ENE | 222.10 | 117 |
| Elgin Motors | 286 Elgin<br>Ottawa ON | ENE | 222.10 | 117 |
| Ottawash Laundry | 211 Gilmour<br>Ottawa ON | ENE | 223.33 | 118 |
| Elgin Motors | 296 Elgin<br>Ottawa ON | ENE | 223.33 | 118 |
| Blair's Doc B A Station | 280 Elgin<br>Ottawa ON | ENE | 227.32 | 127 |
| Langley's | 281 Elgin<br>Ottawa ON | ENE | 247.97 | 153 |

## NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 3 NPCB site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE | 70.17 | 17 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE | 70.17 | 17 |
| TAGGART CORPORATION | 225 METCALFE STREET SUITE 708<br>OTTAWA ON K2P 1P9 | N | 190.21 | 79 |

## OPCB - Inventory of PCB Storage Sites

A search of the OPCB database, dated 1987-Oct 2004; 2012-Dec 2013 has found that there are 6 OPCB site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE | 70.17 | 17 |
| TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE | 70.17 | 17 |
| TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE | 70.17 | 17 |
| TAGGART CORPORATION | 255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | ENE | 70.17 | 17 |
| TAGGART CORPORATION | 225 METCALFE STREET, SUITE 708<br>OTTAWA ON K2P 1P9 | N | 190.21 | 79 |
| TAGGART CORPORATION | 225 METCALFE STREET, SUITE 708<br>OTTAWA ON K2P 1P9 | N | 190.21 | 79 |

## PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 3 PINC site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| PIPELINE HIT 1/2" | 310 COOPER ST,,OTTAWA,ON,K2P 0G7,CA<br>ON | NW | 175.64 | 59 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| KEN RALPH | 231 O'CONNOR ST,,OTTAWA,ON, K2P 1T8,CA ON | WNW | 185.66 | 75 |
| PIPELINE HIT 1" | 331 COOPER ST,,OTTAWA,ON,K2P 0G5,CA ON | WNW | 233.44 | 136 |

## PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 1 PRT site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| 350807 ONTARIO LTD ELGIN SERVICE CENTRE | 280 ELGIN ST OTTAWA ON K2P 1M2 | NE | 235.90 | 141 |

## PTTW - Permit to Take Water

A search of the PTTW database, dated 1994 - Nov 30, 2025 has found that there are 1 PTTW site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| 1578051 Ontario Inc. | 237 Somerset Street West Ottawa ON K2P 0J3 | N | 148.44 | 46 |

## RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004 - 31 Dec, 2025 has found that there are 1 RSC site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| 1384274 Ontario Incorporated | 330 GILMOUR ST ON OTTAWA ON | SSW | 129.10 | 34 |

## RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Apr 30, 2025 has found that there are 1 RST site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| TOPIA ENERGY | 311 O'CONNOR ST<br>OTTAWA ON K2P 2G9 | S | 230.16 | 132 |

## SCT - Scott's Manufacturing Directories

A search of the SCT database, dated 1992-Mar 2011; Feb 2025 has found that there are 29 SCT site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Invenire4 Ltd. | 260 Metcalfe St Unit 2A<br>Ottawa ON K2P 1R6 | E | 28.30 | 1 |
| Innova Envelope | 270 MacLaren St<br>Ottawa ON K2P 0M3 | WSW | 43.28 | 4 |
| Supremex Inc. | 270 MacLaren St Suite 25<br>Ottawa ON K2P 0M3 | WSW | 43.28 | 4 |
| DENTAL TECHNOLOGY GROUP INC. | 267 O'CONNOR ST SUITE 101<br>OTTAWA ON K2P 1V3 | SW | 78.85 | 20 |
| E.L. LITTLEJOHN & ASSOCIATES | 267 O'Connor St<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| The Dental Technology Group | 267 O'Connor St Suite 101<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| E.L. Littlejohn & Associates Ltd. | 267 O'Connor St<br>Ottawa ON K2P 1V3 | SW | 78.85 | 20 |
| GALLEY Kitchen + Provisions | 267 O'Connor St<br>Ottawa ON K2P1V3 | SW | 78.85 | 20 |
| Cdn Council-International Law | 236 Metcalfe St Suite 215<br>Ottawa ON K2P 1R3 | NNW | 80.00 | 21 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Air Force Productions Ltd. | 222 Somerset St W<br>Ottawa ON K2P 2G3 | NNE | 137.78 | 39 |
| Dr George Wehbi Dentist | 229 Metcalfe St<br>Ottawa ON K2P2C2 | N | 175.53 | 58 |
| HICKS MEDIA | 300 Cooper St Suite 30<br>Ottawa ON K2P 0G7 | NW | 178.25 | 62 |
| Hicks Media - Div. of Gidney News & Publishing Limited | 300 Cooper St Suite 30<br>Ottawa ON K2P 0G7 | NW | 178.25 | 62 |
| F K Dental Lab Ltd | 225 Metcalfe St Suite 500<br>Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Chromatek Dental Laboratories | 225 Metcalfe St Suite 500<br>Ottawa ON K2P 1P9 | N | 190.21 | 79 |
| Ottawa Dentistry | 225 Metcalfe St<br>Ottawa ON K2P1P9 | N | 190.21 | 79 |
| Aromaflex | 340 MacLaren St<br>Ottawa ON K2P0M6 | WSW | 209.39 | 96 |
| The Canadian Council on Social Development | 309 Cooper St Floor 5<br>Ottawa ON K2P 0G5 | NW | 219.25 | 109 |
| The Ottawa XPress | 309 Cooper St Suite 401<br>Ottawa ON K2P 0G5 | NW | 219.25 | 109 |
| Cdn Council on Social Dev | 309 Cooper St Floor 5<br>Ottawa ON K2P 0G5 | NW | 219.25 | 109 |
| DOMUS SOFTWARE LTD | 309 COOPER ST UNIT 500<br>OTTAWA ON K2P 0G5 | NW | 219.25 | 109 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| whatif? Technologies Inc. | 338 Somerset St W Unit 3<br>Ottawa ON K2P 0J9 | W | 221.48 | 116 |
| CDIA Report Newsletter | 338 Somerset St W Unit 4<br>Ottawa ON K2P 0J9 | W | 221.48 | 116 |
| Paramount Gold & Silver Corp. | 346 Waverley St<br>Ottawa ON K2P 0W5 | S | 246.36 | 152 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Kun Shoulder Rest Inc. | 200 MacLaren St<br>Ottawa ON K2P0L4 | ENE | 188.86 | 76 |
| Dentacraft Dental Studio | 190 MacLaren St<br>Ottawa ON K2P0L6 | ENE | 205.11 | 92 |
| Dentacraft Dental Studio Inc. | 190 MacLaren St Suite 205<br>Ottawa ON K2P 0L6 | ENE | 205.11 | 92 |
| Fettuccine's | 280 Elgin St<br>Ottawa ON K2P 1M2 | ENE | 228.98 | 131 |
| Empire Photo and Video Inc. | 298 Elgin St #104<br>Ottawa ON K2P1M3 | ENE | 236.64 | 142 |

## SPL - Ontario Spills

A search of the SPL database, dated 1988-Oct 2025 has found that there are 8 SPL site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | OTTAWA ON | W | 56.10 | 8 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| s.21 | 283 Maclaren, Ottawa<br>Ottawa ON | W | 56.10 | 8 |
| OTTAWA BOARD OF EDUCATION | 300 GILMOUR ST.<br>OTTAWA CITY ON | SSE | 70.60 | 18 |
| Enbridge Gas Distribution Inc. | 310 Cooper St.<br>Ottawa ON | NW | 175.64 | 59 |
| Enbridge Gas Distribution Inc. | 338 Sommerset West<br>Ottawa ON | W | 221.48 | 116 |
| Enbridge Gas Distribution Inc. | 331 Cooper St.<br>Ottawa ON | WNW | 233.44 | 136 |
| 285 MacLaren St | OTTAWA ON | WSW | 248.56 | 155 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| UNKNOWN | 190 MACLAREN ST.<br>OTTAWA CITY ON K2P 0L6 | ENE | 205.11 | 92 |

## VAR - Variances for Abandonment of Underground Storage Tanks

A search of the VAR database, dated Feb 28, 2022 has found that there are 1 VAR site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| DALE R KENNY | 309 COOPER ST,,OTTAWA,ON,K2P 0G5,CA<br>ON | NW | 219.25 | 109 |


## WWIS - Water Well Information System

A search of the WWIS database, dated Jul 31, 2025 has found that there are 27 WWIS site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | ON<br>***Well ID:*** 7473728 | W | 32.43 | 2 |
| | ON<br>***Well ID:*** 7473727 | W | 43.54 | 5 |
| | ON<br>***Well ID:*** 7473726 | W | 45.59 | 6 |
| | ON<br>***Well ID:*** 7473694 | W | 56.53 | 9 |
| | ON<br>***Well ID:*** 7473695 | W | 56.76 | 10 |
| | ON<br>***Well ID:*** 7473723 | W | 57.51 | 11 |
| | ON<br>***Well ID:*** 7473725 | W | 60.84 | 13 |
| | ON<br>***Well ID:*** 7473722 | W | 61.56 | 14 |
| | ON<br>***Well ID:*** 7473724 | W | 64.52 | 15 |
| | ON<br>***Well ID:*** 7473693 | SSW | 89.33 | 25 |
| | BRONSON RD AND RAVEN<br>Ottawa ON<br>***Well ID:*** 7337489 | N | 129.62 | 35 |
| | ON | NNW | 134.83 | 38 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | ***Well ID:*** 7211111 | | | |
| | 311 SOMERSET<br>Ottawa ON | W | 181.52 | 64 |
| | ***Well ID:*** 7391112 | | | |
| | ON | W | 184.21 | 70 |
| | ***Well ID:*** 7211110 | | | |
| | 311 Somerset St W<br>Ottawa ON | W | 185.01 | 73 |
| | ***Well ID:*** 7382782 | | | |
| | 311 SONERSET<br>Ottawa ON | W | 189.87 | 78 |
| | ***Well ID:*** 7391115 | | | |
| | 311 SOMERSET<br>Ottawa ON | W | 203.35 | 91 |
| | ***Well ID:*** 7391113 | | | |
| | 311 Somerset St W<br>Ottawa ON | WNW | 209.75 | 97 |
| | ***Well ID:*** 7382859 | | | |
| | 356 MACLAREN STREET<br>Ottawa ON | SW | 210.17 | 98 |
| | ***Well ID:*** 7218928 | | | |
| | 311 SOMERSET<br>Ottawa ON | WNW | 215.05 | 104 |
| | ***Well ID:*** 7391114 | | | |
| | 338 SOMERSET STREET WEST<br>OTTAWA ON | W | 228.36 | 129 |
| | ***Well ID:*** 7046637 | | | |
| | 331 Cooper St<br>Ottawa ON | WNW | 231.46 | 133 |
| | ***Well ID:*** 7334763 | | | |
| | ON | WNW | 245.68 | 150 |
| | ***Well ID:*** 7471728 | | | |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | ON<br>***Well ID:*** 7134824 | NE | 207.06 | **93** |
| | ON<br>***Well ID:*** 7134806 | NE | 208.55 | **94** |
| | ON<br>***Well ID:*** 7134805 | NE | 225.89 | **123** |
| | ON<br>***Well ID:*** 7134804 | NE | 228.78 | **130** |




# Map: 0.25 Kilometer Radius


Order Number: 26012600426

Address: 260 MacLaren Street, Ottawa, ON

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

**Source:** © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership




# Aerial **Year: 2025**


**Address: 260 MacLaren Street, Ottawa, ON**

**Source:** ESRI World Imagery

Order Number: 26012600426

ERIS

© ERIS Information Limited Partnership




# Topographic Map

**Address: 260 MacLaren Street, ON**

**Source:** ESRI World Topographic Map

Order Number: 26012600426

ERIS

© ERIS Information Limited Partnership

# Detail Report

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 1 | 1 of 1 | E/28.3 | 73.9 / 0.00 | Invenire4 Ltd.<br>260 Metcalfe St Unit 2A<br>Ottawa ON K2P 1R6 | SCT |

**Scott S ID:** 57739959
**Latitude:**
**Longitude:**

***Historical Details***

**Established:** 01-AUG-01
**Plant Size (ft²):**
**Employment:**

***Historical Details***

**Description:** Administrative Management and General Management Consulting Services
**SIC/NAICS Code:** 541611

***Historical Details***

**Description:** Administrative Management and General Management Consulting Services
**SIC/NAICS Code:** 541611

***Historical Details***

**Description:** Book Publishers
**SIC/NAICS Code:** 511130

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 1 of 1 | W/32.4 | 74.6 / 0.69 | ON | WWIS |

| | | | |
|---|---|---|---|
| **Well ID:** | 7473728 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z425488 | **Contractor:** | 7241 |
| **Tag:** | A400081 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |

**Municipality:** NEPEAN TOWNSHIP
**Site Info:**

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1010281665 | ***Tag No:*** | A400081 |
| ***Depth (m):*** | | ***Contractor:*** | 7241 |
| ***Year Completed:*** | 2024 | ***Latitude:*** | 45.4158488324598 |
| ***Well Completed Dt:*** | 02/20/2024 | ***Longitude:*** | -75.6927386487294 |
| ***Audit No:*** | Z425488 | ***Point Y:*** | 45.41584882513822 |
| ***Path:*** | | ***Point X:*** | -75.69273848717552 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1010281665 | ***Elevation:*** | |
| ***DP2BR:*** | | ***Elevrc:*** | |
| ***Spatial Status:*** | | ***Zone:*** | 18 |
| ***Code OB:*** | | ***East83:*** | 445798.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029381.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 4 |
| ***Date Completed:*** | 02/20/2024 | ***UTMRC Desc:*** | margin of error : 30 m - 100 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 3 | *1 of 1* | *SSE/40.9* | *73.8 / -0.03* | ***Elevation Elevator Inc***<br>***295 Gilmour Street***<br>***Ottawa ON*** | ***GEN*** |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON001064134 |
| ***Generator Company Name:*** | Elevation Elevator Inc |
| ***Street:*** | 295 Gilmour Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P 1R7 |
| ***Waste Class:*** | 252 L |

***Waste Class Decoded:***

252 - WASTE OILS & LUBRICANTS

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | Elevation Elevator Inc |
| ***Generator Site Address:*** | 295 Gilmour Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P 1R7 |
| ***Waste Class:*** | 252 L |

***Waste Class Decoded:***

252 - WASTE OILS & LUBRICANTS

***Waste Characteristic Decoded:***

L - Liquid Industrial Waste

---

**4** ***1 of 2*** ***WSW/43.3*** ***74.9 / 1.00*** ***Innova Envelope*** ***SCT***
***270 MacLaren St***
***Ottawa ON K2P 0M3***

***Scott S ID:*** 19409243
***Latitude:***
***Longitude:***

***Historical Details***

***Established:*** 1960
***Plant Size (ft²):***
***Employment:*** 5

***Historical Details***

***Description:*** Paper Bag and Coated and Treated Paper Manufacturing
***SIC/NAICS Code:*** 322220

***Historical Details***

***Description:*** Stationery Product Manufacturing
***SIC/NAICS Code:*** 322230

***Historical Details***

***Description:*** Manifold Business Forms Printing
***SIC/NAICS Code:*** 323116

***Historical Details***

***Description:*** Plastics Bag Manufacturing
***SIC/NAICS Code:*** 326111

---

**4** ***2 of 2*** ***WSW/43.3*** ***74.9 / 1.00*** ***Supremex Inc.*** ***SCT***
***270 MacLaren St Suite 25***
***Ottawa ON K2P 0M3***

***Scott S ID:*** 19409243
***Latitude:***
***Longitude:***

***Historical Details***

***Established:*** 01-AUG-60
***Plant Size (ft²):***
***Employment:***

***Historical Details***

**Description:** Stationery and Office Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 418210

***Historical Details***

**Description:** Other Paper and Disposable Plastic Product Wholesaler-Distributors
**SIC/NAICS Code:** 418220

***Historical Details***

**Description:** Stationery and Office Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 418210

***Historical Details***

**Description:** Professional Machinery, Equipment and Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 417930

---

**5** | ***1 of 1*** | ***W/43.5*** | ***74.9 / 1.00*** | ***ON*** | ***WWIS***

| | | | |
|---|---|---|---|
| **Well ID:** | 7473727 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z425489 | **Contractor:** | 7241 |
| **Tag:** | A400082 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | NEPEAN TOWNSHIP | | |
| **Site Info:** | | | |

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281662 | **Tag No:** | A400082 |
| **Depth (m):** | | **Contractor:** | 7241 |
| **Year Completed:** | 2024 | **Latitude:** | 45.4159019059016 |
| **Well Completed Dt:** | 02/20/2024 | **Longitude:** | -75.6928926661297 |
| **Audit No:** | Z425489 | **Point Y:** | 45.41590189894945 |
| **Path:** | | **Point X:** | -75.69289250417373 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281662 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445786.00 |
| **Code OB Desc:** | | **North83:** | 5029387.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 02/20/2024 | **UTMRC Desc:** | margin of error : 30 m - 100 m |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

---

**6** | ***1 of 1*** | ***W/45.6*** | ***74.9 / 1.00*** | ***ON*** | ***WWIS***

| | | | |
|---|---|---|---|
| **Well ID:** | 7473726 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z412885 | **Contractor:** | 7241 |
| **Tag:** | A400083 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | NEPEAN TOWNSHIP | | |
| **Site Info:** | | | |

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281659 | **Tag No:** | A400083 |
| **Depth (m):** | | **Contractor:** | 7241 |
| **Year Completed:** | 2024 | **Latitude:** | 45.4158927502358 |
| **Well Completed Dt:** | 02/20/2024 | **Longitude:** | -75.6929181155595 |
| **Audit No:** | Z412885 | **Point Y:** | 45.415892742970804 |
| **Path:** | | **Point X:** | -75.69291795433637 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281659 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445784.00 |
| **Code OB Desc:** | | **North83:** | 5029386.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 02/20/2024 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

---

**7** | ***1 of 1*** | ***SSW/53.6*** | ***74.6 / 0.69*** | ***Trilex Holdings Ltd (Care of District Reality)*** | ***GEN***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| | | | | **307 GILMOUR ST**<br>**OTTAWA ON K2P 0P7** | |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON2922059 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 06 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 531210 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Offices of Real Estate Agents and Brokers | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 221 |
| ***Waste Class Name:*** | LIGHT FUELS |

| | | | | | |
|---|---|---|---|---|---|
| 8 | ***1 of 4*** | ***W/56.1*** | ***74.9 / 1.00*** | ***283 MacLaren Street***<br>***Ottawa ON K2P 0M2*** | ***EHS*** |

| | | | |
|---|---|---|---|
| ***Order No:*** | 24043000266 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 03-MAY-24 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 30-APR-24 | ***X:*** | -75.6930373 |
| ***Previous Site Name:*** | | ***Y:*** | 45.4160277 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos | | |

| | | | | | |
|---|---|---|---|---|---|
| 8 | ***2 of 4*** | ***W/56.1*** | ***74.9 / 1.00*** | ***CM3 Environmental Inc.***<br>***283 MacLaren Street***<br>***Ottawa ON*** | ***GEN*** |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON001063874 |
| ***Generator Company Name:*** | CM3 Environmental Inc. |
| ***Street:*** | 283 MacLaren Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P 0M2 |
| ***Waste Class:*** | 221 L |

***Waste Class Decoded:***

221 - LIGHT FUELS

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | CM3 Environmental Inc. |
| ***Generator Site Address:*** | 283 MacLaren Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |

**Postal Code:** K2P 0M2
**Waste Class:** 221 L

**Waste Class Decoded:**

221 - LIGHT FUELS

**Waste Characteristic Decoded:**

L - Liquid Industrial Waste

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 8 | 3 of 4 | W/56.1 | 74.9 / 1.00 | s.21<br>283 Maclaren, Ottawa<br>Ottawa ON | SPL |

**Ref No:** 2751-A2LSTQ
**Year:**
**Incident Dt:** 9/22/2015
**Dt MOE Arvl on Scn:**
**MOE Reported Dt:** 9/22/2015
**Dt Document Closed:** 10/1/2015
**Site No:** NA
**MOE Response:** No
**Site County/District:**
**Site Geo Ref Meth:**
**Site District Office:**
**Nearest Watercourse:**
**Site Name:** Hydraulic Spill<UNOFFICIAL>
**Site Address:** 283 Maclaren, Ottawa
**Site Region:**
**Site Municipality:** Ottawa
**Site Lot:**
**Site Conc:**
**Site Geo Ref Accu:**
**Site Map Datum:**
**Northing:**
**Easting:**
**Entity Operating Name:**
**Client Name:** s.21
**Client Type:**
**Source Type:**
**Incident Cause:**
**Incident Preceding Spill:**
**Incident Reason:** Equipment Failure
**Incident Summary:** Spill to road, hydraulic oil.
**Environment Impact:**
**Health Env Consequence:**
**Nature of Impact:**
**Contaminant Qty:** 20 other - see incident description
**Contaminant Qty 1:** 20
**Contaminant Unit:** other - see incident description
**Contaminant Code:** 15
**Contaminant Name:** HYDRAULIC OIL
**Contaminant Limit 1:**
**Contam Limit Freq 1:**
**Contaminant UN No 1:**
**Receiving Medium:**
**Activity Preceding Spill:**
**Property 2nd Watershed:**
**Property Tertiary Watershed:**
**Sector Type:** Other
**SAC Action Class:** Land Spills
**Call Report Locatn Geodata:**

**Municipality No:**
**Nature of Damage:**
**Discharger Report:**
**Material Group:**
**Impact to Health:**
**Agency Involved:**

***Time Reported:***
***System Facility Address:***
***Source Sector Type:***
***Conservtn Auth Name:***
***Primary Watershed:***
***Quaternary Watershed:***
***Offsite Impacts Y N:***
***Waterbody Impacted Y N:***

---

**8** | ***4 of 4*** | ***W/56.1*** | ***74.9 / 1.00*** | ***OTTAWA ON*** | ***SPL***

***Ref No:*** 1-4HPLXK
***Year:***
***Incident Dt:*** 12/14/2023 2:00:00 PM
***Dt MOE Arvl on Scn:***
***MOE Reported Dt:*** 12/14/2023 2:29:50 PM
***Dt Document Closed:*** 12/20/2023 7:11:26 AM
***Site No:***
***MOE Response:*** Desktop Response
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:*** Ottawa District Office
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Site Region:***
***Site Municipality:*** OTTAWA
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***
***Entity Operating Name:***
***Client Name:***
***Client Type:***
***Source Type:*** Tank - Underground
***Incident Cause:***
***Incident Preceding Spill:*** Leak/Break
***Incident Reason:*** Equipment failure/malfunction
***Incident Summary:*** Mannion Petroleum: heating oil leaked from old tank underground
***Environment Impact:***
***Health Env Consequence:***
***Nature of Impact:***
***Contaminant Qty:*** 0 other - see notes
***Contaminant Qty 1:***
***Contaminant Unit:***
***Contaminant Code:***
***Contaminant Name:*** HEATING OIL, LIGHT
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** Land
***Activity Preceding Spill:*** Other (specify)
***Property 2nd Watershed:*** 02L | Lower Ottawa River
***Property Tertiary Watershed:*** 02LA | Rideau River
***Sector Type:***
***SAC Action Class:***
***Call Report Locatn Geodata:*** {"integration_ids":["PR00003803184"],"wkts":["POINT (-75.6930373000 45.4160277000)"],"creation_date":"2023-12-14"}
***Time Reported:***
***System Facility Address:***
***Source Sector Type:***

**Conservtn Auth Name:**
**Primary Watershed:**
**Quaternary Watershed:**
**Offsite Impacts Y N:**
**Waterbody Impacted Y N:**

---

**9** **1 of 1** **W/56.5** **74.9 / 1.00** **ON** **WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7473694 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z425449 | **Contractor:** | 7241 |
| **Tag:** | A400061 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | NEPEAN TOWNSHIP | | |
| **Site Info:** | | | |

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281563 | **Tag No:** | A400061 |
| **Depth (m):** | | **Contractor:** | 7241 |
| **Year Completed:** | 2024 | **Latitude:** | 45.4159278997613 |
| **Well Completed Dt:** | 01/16/2024 | **Longitude:** | -75.6930591332696 |
| **Audit No:** | Z425449 | **Point Y:** | 45.4159278932288 |
| **Path:** | | **Point X:** | -75.69305897092163 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281563 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445773.00 |
| **Code OB Desc:** | | **North83:** | 5029390.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 01/16/2024 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

---

**10** **1 of 1** **W/56.8** **74.9 / 1.00** **ON** **WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7473695 | **Flowing (Y/N):** | |

| | | | |
|---|---|---|---|
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z425450 | **Contractor:** | 7241 |
| **Tag:** | A400062 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | NEPEAN TOWNSHIP | | |
| **Site Info:** | | | |

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281566 | **Tag No:** | A400062 |
| **Depth (m):** | | **Contractor:** | 7241 |
| **Year Completed:** | 2024 | **Latitude:** | 45.4159639021978 |
| **Well Completed Dt:** | 01/16/2024 | **Longitude:** | -75.6930595736895 |
| **Audit No:** | Z425450 | **Point Y:** | 45.41596389536769 |
| **Path:** | | **Point X:** | -75.69305941199121 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281566 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445773.00 |
| **Code OB Desc:** | | **North83:** | 5029394.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 01/16/2024 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

---

**11** | ***1 of 1*** | ***W/57.5*** | ***74.9 / 1.00*** | ***ON*** | ***WWIS***

| | | | |
|---|---|---|---|
| **Well ID:** | 7473723 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z413371 | **Contractor:** | 7241 |
| **Tag:** | A400086 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Depth to Bedrock:*** ***Concession:***
***Well Depth:*** ***Concession Name:***
***Overburden/Bedrock:*** ***Easting NAD83:***
***Pump Rate:*** ***Northing NAD83:***
***Static Water Level:*** ***Zone:***
***Clear/Cloudy:*** ***UTM Reliability:***
***Municipality:*** OTTAWA CITY
***Site Info:***

***Additional Detail(s) (Map)***

***Bore Hole ID:*** 1010281650 ***Tag No:*** A400086
***Depth (m):*** ***Contractor:*** 7241
***Year Completed:*** 2024 ***Latitude:*** 45.415909820997
***Well Completed Dt:*** 02/21/2024 ***Longitude:*** -75.6930716928174
***Audit No:*** Z413371 ***Point Y:*** 45.415909813959736
***Path:*** ***Point X:*** -75.6930715311633

***Bore Hole Information***

***Bore Hole ID:*** 1010281650 ***Elevation:***
***DP2BR:*** ***Elevrc:***
***Spatial Status:*** ***Zone:*** 18
***Code OB:*** ***East83:*** 445772.00
***Code OB Desc:*** ***North83:*** 5029388.00
***Open Hole:*** ***Org CS:*** UTM83
***Cluster Kind:*** ***UTMRC:*** 4
***Date Completed:*** 02/21/2024 ***UTMRC Desc:*** margin of error : 30 m - 100 m
***Remarks:*** ***Location Method:*** wwr
***Location Method Desc:*** on Water Well Record
***Elevrc Desc:***
***Location Source Date:***
***Improvement Location Source:***
***Improvement Location Method:***
***Source Revision Comment:***
***Supplier Comment:***

---

| | | | | | |
|---|---|---|---|---|---|
| 12 | *1 of 2* | *N/58.5* | *73.8 / -0.03* | ***252 Metcalfe St.***<br>***Ottawa ON K2P 1R3*** | ***EHS*** |

***Order No:*** 20010322014 ***Nearest Intersection:*** at Somerset st.
***Status:*** C ***Municipality:***
***Report Type:*** Basic Report ***Client Prov/State:*** ON
***Report Date:*** 4/2/01 ***Search Radius (km):*** 0.25
***Date Received:*** 3/23/01 ***X:*** -75.692039
***Previous Site Name:*** ***Y:*** 45.416427
***Lot/Building Size:***
***Additional Info Ordered:***

---

| | | | | | |
|---|---|---|---|---|---|
| 12 | *2 of 2* | *N/58.5* | *73.8 / -0.03* | ***252 Metcalfe Street***<br>***Ottawa ON K2P 1R3*** | ***EHS*** |

***Order No:*** 20181203116 ***Nearest Intersection:***
***Status:*** C ***Municipality:***
***Report Type:*** Site Report ***Client Prov/State:*** ON
***Report Date:*** 04-DEC-18 ***Search Radius (km):*** .001
***Date Received:*** 03-DEC-18 ***X:*** -75.692282
***Previous Site Name:*** ***Y:*** 45.416473
***Lot/Building Size:***
***Additional Info Ordered:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 13 | 1 of 1 | W/60.8 | 74.9 / 1.00 | ON | WWIS |

| | | | |
|---|---|---|---|
| **Well ID:** | 7473725 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z412884 | **Contractor:** | 7241 |
| **Tag:** | A400084 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | NEPEAN TOWNSHIP | | |
| **Site Info:** | | | |

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281656 | **Tag No:** | A400084 |
| **Depth (m):** | | **Contractor:** | 7241 |
| **Year Completed:** | 2024 | **Latitude:** | 45.4159725926136 |
| **Well Completed Dt:** | 02/20/2024 | **Longitude:** | -75.693110802881 |
| **Audit No:** | Z412884 | **Point Y:** | 45.41597258597277 |
| **Path:** | | **Point X:** | -75.6931106410975 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281656 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445769.00 |
| **Code OB Desc:** | | **North83:** | 5029395.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 02/20/2024 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 14 | 1 of 1 | W/61.6 | 74.9 / 1.00 | ON | WWIS |

| | | | |
|---|---|---|---|
| **Well ID:** | 7473722 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |

| | | | |
|---|---|---|---|
| **Audit No:** | Z413372 | **Contractor:** | 7241 |
| **Tag:** | A400087 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | NEPEAN TOWNSHIP | | |
| **Site Info:** | | | |

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281647 | **Tag No:** | A400087 |
| **Depth (m):** | | **Contractor:** | 7241 |
| **Year Completed:** | 2024 | **Latitude:** | 45.4160175956583 |
| **Well Completed Dt:** | 02/21/2024 | **Longitude:** | -75.693111353448 |
| **Audit No:** | Z413372 | **Point Y:** | 45.41601758892248 |
| **Path:** | | **Point X:** | -75.69311119086247 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281647 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445769.00 |
| **Code OB Desc:** | | **North83:** | 5029400.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 02/21/2024 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

---

**15** | ***1 of 1*** | ***W/64.5*** | ***74.9 / 1.00*** | ***ON*** | ***WWIS***

| | | | |
|---|---|---|---|
| **Well ID:** | 7473724 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z412883 | **Contractor:** | 7241 |
| **Tag:** | A400085 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |

**Municipality:** NEPEAN TOWNSHIP
**Site Info:**

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281653 | **Tag No:** | A400085 |
| **Depth (m):** | | **Contractor:** | 7241 |
| **Year Completed:** | 2024 | **Latitude:** | 45.4159272793528 |
| **Well Completed Dt:** | 02/21/2024 | **Longitude:** | -75.6931613713603 |
| **Audit No:** | Z412883 | **Point Y:** | 45.41592727211498 |
| **Path:** | | **Point X:** | -75.69316120904857 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1010281653 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445765.00 |
| **Code OB Desc:** | | **North83:** | 5029390.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 02/21/2024 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

---

**16** | ***1 of 1*** | ***SW/67.4*** | ***74.9 / 1.00*** | ***ON*** | ***BORE***

| | | | |
|---|---|---|---|
| **Borehole ID:** | 613286 | **Inclin FLG:** | No |
| **OGF ID:** | 215514587 | **SP Status:** | Initial Entry |
| **Status:** | | **Surv Elev:** | No |
| **Type:** | Borehole | **Piezometer:** | No |
| **Use:** | | **Primary Name:** | |
| **Completion Date:** | | **Municipality:** | |
| **Static Water Level:** | 15.2 | **Lot:** | |
| **Primary Water Use:** | | **Township:** | |
| **Sec. Water Use:** | | **Latitude DD:** | 45.415498 |
| **Total Depth m:** | -999 | **Longitude DD:** | -75.692956 |
| **Depth Ref:** | Ground Surface | **UTM Zone:** | 18 |
| **Depth Elev:** | | **Easting:** | 445781 |
| **Drill Method:** | | **Northing:** | 5029342 |
| **Orig Ground Elev m:** | 70.1 | **Location Accuracy:** | |
| **Elev Reliabil Note:** | | **Accuracy:** | Not Applicable |
| **DEM Ground Elev m:** | 71.4 | | |
| **Concession:** | | | |
| **Location D:** | | | |
| **Survey D:** | | | |
| **Comments:** | | | |

***Borehole Geology Stratum***

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394504 | **Mat Consistency:** | |
| **Top Depth:** | 12.3 | **Material Moisture:** | |
| **Bottom Depth:** | 12.6 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Sand | **Geologic Formation:** | |

***Material 2:*** Gravel
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** SAND.

***Geology Stratum ID:*** 218394502
***Top Depth:*** 0
***Bottom Depth:*** .8
***Material Color:***
***Material 1:*** Sand
***Material 2:*** Clay
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** SAND.

***Mat Consistency:***
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394507
***Top Depth:*** 17.9
***Bottom Depth:***
***Material Color:***
***Material 1:*** Bedrock
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** BEDROCK. 219.2 FEET.FIED. DENSE. 00000 018 00050 017 00130 038 00200 023 **Note: Many records provided by the department have a truncated [Stratum Description] field.

***Mat Consistency:*** Dense
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394506
***Top Depth:*** 17.7
***Bottom Depth:*** 17.9
***Material Color:***
***Material 1:*** Gravel
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** GRAVEL. WATER STABLE AT 180.0 FEET.

***Mat Consistency:***
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394503
***Top Depth:*** .8
***Bottom Depth:*** 12.3
***Material Color:***
***Material 1:*** Clay
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** CLAY.

***Mat Consistency:***
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394505
***Top Depth:*** 12.6
***Bottom Depth:*** 17.7
***Material Color:***
***Material 1:*** Clay
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** CLAY.

***Mat Consistency:***
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Source***

***Source Type:*** Data Survey
***Source Appl:*** Spatial/Tabular

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Source Orig:** Geological Survey of Canada
**Source Iden:** 1
**Source Date:** 1956-1972
**Scale or Res:** Varies
**Confidence:** H
**Horizontal:** NAD27
**Observatio:**
**Verticalda:** Mean Average Sea Level
**Source Name:** Urban Geology Automated Information System (UGAIS)
**Source Details:** File: OTTAWA2.txt RecordID: 057940 NTS_Sheet: 31G05G
**Confiden 1:** Logged by professional. Exact and complete description of material and properties.

***Source List***

**Source Identifier:** 1
**Horizontal Datum:** NAD27
**Source Type:** Data Survey
**Vertical Datum:** Mean Average Sea Level
**Source Date:** 1956-1972
**Projection Name:** Universal Transverse Mercator
**Scale or Resolution:** Varies
**Source Name:** Urban Geology Automated Information System (UGAIS)
**Source Originators:** Geological Survey of Canada

---

**17** | **1 of 6** | **ENE/70.2** | **73.9 / 0.00** | **TAGGART CORPORATION**
**255 METCALFE STREET**
**OTTAWA ON K2P 1R4** | **NPCB**

**Company Code:** F1444
**Industry:**
**Site Status:**
**Transaction Date:**
**Inspection Date:**

---

**17** | **2 of 6** | **ENE/70.2** | **73.9 / 0.00** | **TAGGART CORPORATION**
**255 METCALFE STREET**
**OTTAWA ON K2P 1R4** | **NPCB**

**Company Code:** F1361
**Industry:** UNDEFINED
**Site Status:**
**Transaction Date:**
**Inspection Date:**

---

**17** | **3 of 6** | **ENE/70.2** | **73.9 / 0.00** | **TAGGART CORPORATION**
**255 METCALFE STREET**
**OTTAWA ON K2P 1R4** | **OPCB**

**Year:** 1995
**Site Number:** 40294A012
**Name Owner:**
**Additional Site Information:**

---

**17** | **4 of 6** | **ENE/70.2** | **73.9 / 0.00** | **TAGGART CORPORATION**
**255 METCALFE STREET**
**OTTAWA ON K2P 1R4** | **OPCB**

**Year:** 1998
**Site Number:** 40294A012
**Name Owner:**
**Additional Site Information:**

---

**17** | **5 of 6** | **ENE/70.2** | **73.9 / 0.00** | **TAGGART CORPORATION**
**255 METCALFE STREET** | **OPCB**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| | | | | OTTAWA ON K2P 1R4 | |

Year: 1999
Site Number: 40294A012
Name Owner:
Additional Site Information:

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 17 | 6 of 6 | ENE/70.2 | 73.9 / 0.00 | TAGGART CORPORATION<br>255 METCALFE STREET<br>OTTAWA ON K2P 1R4 | OPCB |

Year: 2000
Site Number: 40294A012
Name Owner:
Additional Site Information:

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 18 | 1 of 1 | SSE/70.6 | 73.9 / 0.00 | OTTAWA BOARD OF EDUCATION<br>300 GILMOUR ST.<br>OTTAWA CITY ON | SPL |

Ref No: 89979
Year:
Incident Dt: //
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/11/1993
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: UNDERGROUND TANK LEAK
Incident Preceding Spill:
Incident Reason: CORROSION
Incident Summary: BACKENTRY-OTTAWA B.O.E.: FURNACE OIL LEAK FROM UNDERGROUND OIL TANK
Environment Impact: CONFIRMED
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Municipality No: 20101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:***
***SAC Action Class:***
***Call Report Locatn Geodata:***
***Time Reported:***
***System Facility Address:***
***Source Sector Type:***
***Conservtn Auth Name:***
***Primary Watershed:***
***Quaternary Watershed:***
***Offsite Impacts Y N:***
***Waterbody Impacted Y N:***

---

**19** | ***1 of 1*** | ***ENE/73.6*** | ***73.9 / 0.00*** | ***255 Metcalfe Street Ottawa ON K2P 0N9*** | ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20200723047 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 28-JUL-20 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 23-JUL-20 | ***X:*** | -75.6915411 |
| ***Previous Site Name:*** | | ***Y:*** | 45.4162734 |
| ***Lot/Building Size:*** | 0.12 hectares | | |
| ***Additional Info Ordered:*** | | | |

---

**20** | ***1 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***267 O'Connor Street Ottawa ON K2P 1V3*** | ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20061012001 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Custom Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 10/20/2006 | ***Search Radius (km):*** | 0.25 |
| ***Date Received:*** | 10/12/2006 | ***X:*** | -75.693092 |
| ***Previous Site Name:*** | | ***Y:*** | 45.415298 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | Fire Insur. Maps And /or Site Plans | | |

---

**20** | ***2 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***267 O'Connor Street Ottawa ON K2P 1V3*** | ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20090313006 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Custom Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 3/23/2009 | ***Search Radius (km):*** | 0.25 |
| ***Date Received:*** | 3/13/2009 | ***X:*** | -75.693105 |
| ***Previous Site Name:*** | | ***Y:*** | 45.415292 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | | | |

---

**20** | ***3 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***267 O'connor St Ottawa ON K2P 1V3*** | ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20121001003 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | Ottawa |
| ***Report Type:*** | Custom Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 05-OCT-12 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 01-OCT-12 | ***X:*** | -75.693207 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Previous Site Name:***
***Lot/Building Size:***
***Additional Info Ordered:***
***Y:*** 45.415395

---

**20** | ***4 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***267 O'Connor Street Ottawa ON K2P 1V3*** | ***EHS***

***Order No:*** 20200323030
***Status:*** C
***Report Type:*** Standard Report
***Report Date:*** 26-MAR-20
***Date Received:*** 23-MAR-20
***Previous Site Name:***
***Lot/Building Size:***
***Additional Info Ordered:***
***Nearest Intersection:***
***Municipality:***
***Client Prov/State:*** ON
***Search Radius (km):*** .25
***X:*** -75.6930364
***Y:*** 45.4154094

---

**20** | ***5 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***KOPP CLINICAL LABORATORIES 267 O'CONNOR STREET, SUITE 104 OTTAWA ON K2P 1V3*** | ***GEN***

***Generator Info***

***Generator No:*** ON0390100
***Approval Years:*** 86,87,88,89,90
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** MEDICAL LABORATORIES
***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 8681

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**20** | ***6 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***KOPP CLINICAL LABORAT (OUT OF BUSINESS) 267 O'CONNOR STREET, SUITE 104 OTTAWA ON K2P 1V3*** | ***GEN***

***Generator Info***

***Generator No:*** ON0390100
***Approval Years:*** 92,93,96,97,98
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** MEDICAL LABORATORIES
***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 8681

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 7 of 66 | SW/78.8 | 74.9 / 1.00 | KOPP CLINICAL LABORATORIES 23-100<br>267 O'CONNOR STREET, SUITE 104<br>OTTAWA ON K2P 1V3 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0390100 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 94,95 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 8681 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | MEDICAL LABORATORIES | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 8 of 66 | SW/78.8 | 74.9 / 1.00 | O'CONNOR PHARMACY<br>267 O'CONNER STREET<br>OTTAWA ON K2P 1V3 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON8434988 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 02,03,04 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 261 |
| ***Waste Class Name:*** | PHARMACEUTICALS |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 9 of 66 | SW/78.8 | 74.9 / 1.00 | CML HealthCare Inc.<br>267 O'Connor Street<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON2674529 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 04,05,07,08 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 621510 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Medical and Diagnostic Laboratories | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**20** | ***10 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***CML HealthCare Inc.*** ***267 O'Connor Street*** ***Ottawa ON K2P 1V3*** | ***GEN***

***Generator Info***

***Generator No:*** ON2674529
***Approval Years:*** 2009
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** Medical and Diagnostic Laboratories

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 621510

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**20** | ***11 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***CML HealthCare Inc.*** ***267 O'Connor Street*** ***Ottawa ON K2P 1V3*** | ***GEN***

***Generator Info***

***Generator No:*** ON2674529
***Approval Years:*** 2010
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** Medical and Diagnostic Laboratories

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 621510

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**20** | ***12 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Dr. Donald K. Wilson Medicine Prof. Corp.*** ***403-267 O'Connor St*** ***Ottawa ON K2P 1V3*** | ***GEN***

***Generator Info***

***Generator No:*** ON9901254
***Approval Years:*** 2010
***Status:***
***PO Box No:***
***Country:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 621110

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Co Admin:**
**Phone No Admin:**
**SIC Description:** Offices of Physicians

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | 13 of 66 | SW/78.8 | 74.9 / 1.00 | **Central Ottawa Family Medicine Associates Ltd.**<br>**Suite 500 267 O'Connor Street**<br>**Ottawa ON K2P 1V3** | GEN |

***Generator Info***

**Generator No:** ON6644068
**Approval Years:** 2010
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** Offices of Physicians

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 621110

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | 14 of 66 | SW/78.8 | 74.9 / 1.00 | **Ottawa Endoscopy & Day Surgery**<br>**267 O'conner Street Suite 225**<br>**Ottawa ON K2P 1V3** | GEN |

***Generator Info***

**Generator No:** ON7074415
**Approval Years:** 2010
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** Offices of All Other Health Practitioners

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 621390

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | 15 of 66 | SW/78.8 | 74.9 / 1.00 | **Ottawa Endoscopy & Day Surgery**<br>**267 O'connor Street Suite 225**<br>**Ottawa ON** | GEN |

***Generator Info***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Generator No:** ON7074415
**Approval Years:** 2011
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** Offices of All Other Health Practitioners

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 621390

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 16 of 66 | SW/78.8 | 74.9 / 1.00 | Central Ottawa Family Medicine Associates Ltd.<br>Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

**Generator No:** ON6644068
**Approval Years:** 2011
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** Offices of Physicians

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 621110

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 17 of 66 | SW/78.8 | 74.9 / 1.00 | Dr. Donald K. Wilson Medicine Prof. Corp.<br>403-267 O'Connor St<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

**Generator No:** ON9901254
**Approval Years:** 2011
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** Offices of Physicians

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 621110

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 18 of 66 | SW/78.8 | 74.9 / 1.00 | CML HealthCare Inc.<br>267 O'Connor Street<br>Ottawa ON K2P 1V3 | GEN |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON2674529 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2011 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 621510 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Medical and Diagnostic Laboratories | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | ***19 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Ottawa Endoscopy & Day Surgery***<br>***267 O'connor Street Suite 207***<br>***Ottawa ON*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON7074415 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2012 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 621390 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Offices of All Other Health Practitioners | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | ***20 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Central Ottawa Family Medicine Associates Ltd.***<br>***Suite 500 267 O'Connor Street***<br>***Ottawa ON K2P 1V3*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON6644068 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2012 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 621110 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Offices of Physicians | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 21 of 66 | SW/78.8 | 74.9 / 1.00 | Dr. Donald K. Wilson Medicine Prof. Corp.<br>403-267 O'Connor St<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON9901254 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2012 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 621110 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Offices of Physicians | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 22 of 66 | SW/78.8 | 74.9 / 1.00 | LifeLabs LP<br>267 O'Connor Street, Unit B003<br>Ottawa ON | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON2674529 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2012 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 621510 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Medical and Diagnostic Laboratories | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 23 of 66 | SW/78.8 | 74.9 / 1.00 | LifeLabs LP<br>267 O'Connor Street, Unit B003<br>Ottawa ON | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON2674529 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2013 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 621510 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | MEDICAL AND DIAGNOSTIC LABORATORIES | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**20** | ***24 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Dr. Donald K. Wilson Medicine Prof. Corp.***
***403-267 O'Connor St***
***Ottawa ON*** | ***GEN***

***Generator Info***

***Generator No:*** ON9901254
***Approval Years:*** 2013
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** OFFICES OF PHYSICIANS

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 621110

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**20** | ***25 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Central Ottawa Family Medicine Associates Ltd.***
***Suite 500 267 O'Connor Street***
***Ottawa ON*** | ***GEN***

***Generator Info***

***Generator No:*** ON6644068
***Approval Years:*** 2013
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** OFFICES OF PHYSICIANS

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 621110

***Waste Detail(s)***

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**20** | ***26 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Ottawa Endoscopy & Day Surgery***
***267 O'connor Street Suite 207***
***Ottawa ON*** | ***GEN***

***Generator Info***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Generator No:** ON7074415
**Approval Years:** 2013
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** OFFICES OF ALL OTHER HEALTH PRACTITIONERS

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 621390

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

**20** | ***27 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Midtown Family Health***
***267 O'Connor ST. Suite 306***
***Ottawa ON K2P 1V3*** | ***GEN***

***Generator Info***

**Generator No:** ON5935207
**Approval Years:** 2016
**Status:**
**PO Box No:**
**Country:** Canada
**Co Admin:** Helen Rizzo
**Phone No Admin:** 6132336652 Ext.
**SIC Description:** OFFICES OF PHYSICIANS

**Choice of Contact:** CO_OFFICIAL
**Contaminated Fac:** No
**MHSW Facility:** No
**SIC Code:** 621110

***Waste Detail(s)***

**Waste Class:** 261
**Waste Class Name:** PHARMACEUTICALS

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

**20** | ***28 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Sajjad Giby Pharmacies Inc.***
***267 O'CONNOR STREET, UNIT 120***
***OTTAWA ON K2P 1V3*** | ***GEN***

***Generator Info***

**Generator No:** ON3475419
**Approval Years:** 2016
**Status:**
**PO Box No:**
**Country:** Canada
**Co Admin:** NASTRAN NAJAFI-FARD
**Phone No Admin:** 4164931120 Ext.3218
**SIC Description:** 446110

**Choice of Contact:** CO_ADMIN
**Contaminated Fac:** No
**MHSW Facility:** No
**SIC Code:** 446110

***Waste Detail(s)***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

***Waste Detail(s)***

**Waste Class:** 261
**Waste Class Name:** PHARMACEUTICALS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 29 of 66 | SW/78.8 | 74.9 / 1.00 | Central Ottawa Family Medicine Associates Ltd.<br>Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

**Generator No:** ON6644068
**Approval Years:** 2016
**Status:**
**PO Box No:**
**Country:** Canada
**Co Admin:** Jasmine Soule
**Phone No Admin:** 613-730-3701 Ext.
**SIC Description:** OFFICES OF PHYSICIANS
**Choice of Contact:** CO_ADMIN
**Contaminated Fac:** No
**MHSW Facility:** No
**SIC Code:** 621110

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

***Waste Detail(s)***

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 30 of 66 | SW/78.8 | 74.9 / 1.00 | We Care Home Health Services<br>267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

**Generator No:** ON6991797
**Approval Years:** 2016
**Status:**
**PO Box No:**
**Country:** Canada
**Co Admin:** Heather Bozik
**Phone No Admin:** 6137822244 Ext.1811
**SIC Description:** 621610, OFFICES OF ALL OTHER HEALTH PRACTITIONERS
**Choice of Contact:** CO_OFFICIAL
**Contaminated Fac:** No
**MHSW Facility:** No
**SIC Code:** 621610, 621390

***Waste Detail(s)***

**Waste Class:** 261
**Waste Class Name:** PHARMACEUTICALS

***Waste Detail(s)***

**Waste Class:** 312

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Waste Class Name:** PATHOLOGICAL WASTES

---

**20** | **31 of 66** | **SW/78.8** | **74.9 / 1.00** | **Ottawa Endoscopy & Day Surgery**
**267 O'connor Street Suite 207**
**Ottawa ON K2P 1V3** | **GEN**

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON7074415 | **Choice of Contact:** | CO_ADMIN |
| **Approval Years:** | 2016 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621390 |
| **Country:** | Canada | | |
| **Co Admin:** | Grace Wilson | | |
| **Phone No Admin:** | 6135678106 Ext. | | |
| **SIC Description:** | OFFICES OF ALL OTHER HEALTH PRACTITIONERS | | |

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

**20** | **32 of 66** | **SW/78.8** | **74.9 / 1.00** | **We Care Home Health Services**
**267 O'Connor Street Suite 609**
**Ottawa ON K2P 1V3** | **GEN**

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON6991797 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2015 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621610 |
| **Country:** | Canada | | |
| **Co Admin:** | Heather Bozik | | |
| **Phone No Admin:** | 6137822244 Ext.1811 | | |
| **SIC Description:** | 621610 | | |

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

***Waste Detail(s)***

**Waste Class:** 261
**Waste Class Name:** PHARMACEUTICALS

---

**20** | **33 of 66** | **SW/78.8** | **74.9 / 1.00** | **LifeLabs LP**
**267 O'Connor Street, Unit B003**
**Ottawa ON K1S 1C2** | **GEN**

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON2674529 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2015 | **Contaminated Fac:** | No |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Status:** **MHSW Facility:** No
**PO Box No:** **SIC Code:** 621510
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:** MEDICAL AND DIAGNOSTIC LABORATORIES

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 34 of 66 | SW/78.8 | 74.9 / 1.00 | Central Ottawa Family Medicine Associates Ltd.<br>Suite 500 267 O'Connor Street<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

**Generator No:** ON6644068 **Choice of Contact:** CO_ADMIN
**Approval Years:** 2015 **Contaminated Fac:** No
**Status:** **MHSW Facility:** No
**PO Box No:** **SIC Code:** 621110
**Country:** Canada
**Co Admin:** Jasmine Soule
**Phone No Admin:** 613-730-3701 Ext.
**SIC Description:** OFFICES OF PHYSICIANS

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

***Waste Detail(s)***

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 35 of 66 | SW/78.8 | 74.9 / 1.00 | Dr. Donald K. Wilson Medicine Prof. Corp.<br>403-267 O'Connor St<br>Ottawa ON K2P1V3 | GEN |

***Generator Info***

**Generator No:** ON9901254 **Choice of Contact:** CO_OFFICIAL
**Approval Years:** 2015 **Contaminated Fac:** No
**Status:** **MHSW Facility:** No
**PO Box No:** **SIC Code:** 621110
**Country:** Canada
**Co Admin:** Judy Costantini
**Phone No Admin:** 613-567-3904 Ext.
**SIC Description:** OFFICES OF PHYSICIANS

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 36 of 66 | SW/78.8 | 74.9 / 1.00 | Ottawa Endoscopy & Day Surgery<br>267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | GEN |

**Generator Info**

| | | | |
|---|---|---|---|
| **Generator No:** | ON7074415 | **Choice of Contact:** | CO_ADMIN |
| **Approval Years:** | 2015 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621390 |
| **Country:** | Canada | | |
| **Co Admin:** | Grace Wilson | | |
| **Phone No Admin:** | 6135678106 Ext. | | |
| **SIC Description:** | OFFICES OF ALL OTHER HEALTH PRACTITIONERS | | |

**Waste Detail(s)**

| | |
|---|---|
| **Waste Class:** | 312 |
| **Waste Class Name:** | PATHOLOGICAL WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 37 of 66 | SW/78.8 | 74.9 / 1.00 | Sajjad Giby Pharmacies Inc.<br>267 O'CONNOR STREET, UNIT 120<br>OTTAWA ON K2P 1V3 | GEN |

**Generator Info**

| | | | |
|---|---|---|---|
| **Generator No:** | ON3475419 | **Choice of Contact:** | CO_ADMIN |
| **Approval Years:** | 2015 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 446110 |
| **Country:** | Canada | | |
| **Co Admin:** | NASTRAN NAJAFI-FARD | | |
| **Phone No Admin:** | 4164931120 Ext.3218 | | |
| **SIC Description:** | 446110 | | |

**Waste Detail(s)**

| | |
|---|---|
| **Waste Class:** | 312 |
| **Waste Class Name:** | PATHOLOGICAL WASTES |

**Waste Detail(s)**

| | |
|---|---|
| **Waste Class:** | 261 |
| **Waste Class Name:** | PHARMACEUTICALS |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 38 of 66 | SW/78.8 | 74.9 / 1.00 | Midtown Family Health<br>267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | GEN |

**Generator Info**

| | | | |
|---|---|---|---|
| **Generator No:** | ON5935207 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2015 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621110 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Country:*** Canada
***Co Admin:*** Helen Rizzo
***Phone No Admin:*** 6132336652 Ext.
***SIC Description:*** OFFICES OF PHYSICIANS

***Waste Detail(s)***

***Waste Class:*** 261
***Waste Class Name:*** PHARMACEUTICALS

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 39 of 66 | SW/78.8 | 74.9 / 1.00 | ***Central Ottawa Family Medicine Associates Ltd.***<br>***Suite 500 267 O'Connor Street***<br>***Ottawa ON K2P 1V3*** | GEN |

***Generator Info***

***Generator No:*** ON6644068
***Approval Years:*** 2014
***Status:***
***PO Box No:***
***Country:*** Canada
***Co Admin:*** Jasmine Soule
***Phone No Admin:*** 613-730-3701 Ext.
***SIC Description:*** OFFICES OF PHYSICIANS

***Choice of Contact:*** CO_ADMIN
***Contaminated Fac:*** No
***MHSW Facility:*** No
***SIC Code:*** 621110

***Waste Detail(s)***

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 40 of 66 | SW/78.8 | 74.9 / 1.00 | ***LifeLabs LP***<br>***267 O'Connor Street, Unit B003***<br>***Ottawa ON K1S 1C2*** | GEN |

***Generator Info***

***Generator No:*** ON2674529
***Approval Years:*** 2014
***Status:***
***PO Box No:***
***Country:*** Canada
***Co Admin:*** Jacquie Maertz
***Phone No Admin:*** 905 565 0433 Ext.2202
***SIC Description:*** MEDICAL AND DIAGNOSTIC LABORATORIES

***Choice of Contact:*** CO_ADMIN
***Contaminated Fac:*** No
***MHSW Facility:*** No
***SIC Code:*** 621510

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

**20** | **41 of 66** | **SW/78.8** | **74.9 / 1.00** | **Dr. Donald K. Wilson Medicine Prof. Corp.**
**403-267 O'Connor St**
**Ottawa ON K2P1V3** | **GEN**

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON9901254 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2014 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621110 |
| **Country:** | Canada | | |
| **Co Admin:** | Judy Costantini | | |
| **Phone No Admin:** | 613-567-3904 Ext. | | |
| **SIC Description:** | OFFICES OF PHYSICIANS | | |

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

**20** | **42 of 66** | **SW/78.8** | **74.9 / 1.00** | **Ottawa Endoscopy & Day Surgery**
**267 O'connor Street Suite 207**
**Ottawa ON K2P 1V3** | **GEN**

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON7074415 | **Choice of Contact:** | CO_ADMIN |
| **Approval Years:** | 2014 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621390 |
| **Country:** | Canada | | |
| **Co Admin:** | Grace Wilson | | |
| **Phone No Admin:** | 6135678106 Ext. | | |
| **SIC Description:** | OFFICES OF ALL OTHER HEALTH PRACTITIONERS | | |

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

**20** | **43 of 66** | **SW/78.8** | **74.9 / 1.00** | **Midtown Family Health**
**267 O'Connor ST. Suite 306**
**Ottawa ON K2P 1V3** | **GEN**

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON5935207 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2014 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621110 |
| **Country:** | Canada | | |
| **Co Admin:** | Amanda Peskettt | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Phone No Admin:** 6135633332 Ext.
**SIC Description:** OFFICES OF PHYSICIANS

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

***Waste Detail(s)***

**Waste Class:** 261
**Waste Class Name:** PHARMACEUTICALS

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | 44 of 66 | SW/78.8 | 74.9 / 1.00 | **Sajjad Giby Pharmacies Inc.**<br>**267 O'CONNOR STREET, UNIT 120**<br>**OTTAWA ON K2P 1V3** | GEN |

***Generator Info***

**Generator No:** ON3475419
**Approval Years:** As of Dec 2018
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** Pathological wastes

***Waste Detail(s)***

**Waste Class:** 261 A
**Waste Class Name:** Pharmaceuticals

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | 45 of 66 | SW/78.8 | 74.9 / 1.00 | **CBI Home Health formerly We Care Home Health**<br>**267 O'Connor Street Suite 609**<br>**Ottawa ON K2P 1V3** | GEN |

***Generator Info***

**Generator No:** ON6991797
**Approval Years:** As of Dec 2018
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 261 A

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Waste Class Name:** | | Pharmaceuticals | | | |
| **Waste Detail(s)** | | | | | |
| **Waste Class:** | | 312 P | | | |
| **Waste Class Name:** | | Pathological wastes | | | |
| 20 | 46 of 66 | SW/78.8 | 74.9 / 1.00 | Ottawa Endoscopy & Day Surgery<br>267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | GEN |
| **Generator Info** | | | | | |
| **Generator No:** | ON7074415 | | | **Choice of Contact:** | |
| **Approval Years:** | As of Dec 2018 | | | **Contaminated Fac:** | |
| **Status:** | Registered | | | **MHSW Facility:** | |
| **PO Box No:** | | | | **SIC Code:** | |
| **Country:** | Canada | | | | |
| **Co Admin:** | | | | | |
| **Phone No Admin:** | | | | | |
| **SIC Description:** | | | | | |
| **Waste Detail(s)** | | | | | |
| **Waste Class:** | | 312 P | | | |
| **Waste Class Name:** | | Pathological wastes | | | |
| 20 | 47 of 66 | SW/78.8 | 74.9 / 1.00 | Central Ottawa Family Medicine Associates Ltd.<br>Suite 500 267 OConnor Street<br>Ottawa ON K2P 1V3 | GEN |
| **Generator Info** | | | | | |
| **Generator No:** | ON6644068 | | | **Choice of Contact:** | |
| **Approval Years:** | As of Dec 2018 | | | **Contaminated Fac:** | |
| **Status:** | Registered | | | **MHSW Facility:** | |
| **PO Box No:** | | | | **SIC Code:** | |
| **Country:** | Canada | | | | |
| **Co Admin:** | | | | | |
| **Phone No Admin:** | | | | | |
| **SIC Description:** | | | | | |
| **Waste Detail(s)** | | | | | |
| **Waste Class:** | | 148 C | | | |
| **Waste Class Name:** | | Misc. wastes and inorganic chemicals | | | |
| **Waste Detail(s)** | | | | | |
| **Waste Class:** | | 312 P | | | |
| **Waste Class Name:** | | Pathological wastes | | | |
| 20 | 48 of 66 | SW/78.8 | 74.9 / 1.00 | Midtown Family Health<br>267 O'Connor ST. Suite 306<br>Ottawa ON K2P 1V3 | GEN |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON5935207 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Dec 2018 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | Pathological wastes |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 261 A |
| ***Waste Class Name:*** | Pharmaceuticals |

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | ***49 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Sajjad Giby Pharmacies Inc.***<br>***267 O'CONNOR STREET, UNIT 120***<br>***OTTAWA ON K2P 1V3*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3475419 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Jul 2020 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | Pathological wastes |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 261 A |
| ***Waste Class Name:*** | Pharmaceuticals |

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | ***50 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Ottawa Endoscopy & Day Surgery***<br>***267 O'connor Street Suite 207***<br>***Ottawa ON K2P 1V3*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON7074415 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Jul 2020 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |

***PO Box No:*** ***SIC Code:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

**20** ***51 of 66*** ***SW/78.8*** ***74.9 / 1.00*** ***Midtown Family Health***
***267 O'Connor ST. Suite 306***
***Ottawa ON K2P 1V3*** ***GEN***

***Generator Info***

***Generator No:*** ON5935207 ***Choice of Contact:***
***Approval Years:*** As of Jul 2020 ***Contaminated Fac:***
***Status:*** Registered ***MHSW Facility:***
***PO Box No:*** ***SIC Code:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

***Waste Detail(s)***

***Waste Class:*** 261 A
***Waste Class Name:*** Pharmaceuticals

---

**20** ***52 of 66*** ***SW/78.8*** ***74.9 / 1.00*** ***Central Ottawa Family Medicine Associates Ltd.***
***Suite 500 267 OConnor Street***
***Ottawa ON K2P 1V3*** ***GEN***

***Generator Info***

***Generator No:*** ON6644068 ***Choice of Contact:***
***Approval Years:*** As of Jul 2020 ***Contaminated Fac:***
***Status:*** Registered ***MHSW Facility:***
***PO Box No:*** ***SIC Code:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

**20** | ***53 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***CBI Home Health formerly We Care Home Health*** ***267 O'Connor Street Suite 609*** ***Ottawa ON K2P 1V3*** | ***GEN***

***Generator Info***

***Generator No:*** ON6991797
***Approval Years:*** As of Jul 2020
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 261 A
***Waste Class Name:*** Pharmaceuticals

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

**20** | ***54 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Central Ottawa Family Medicine Associates Ltd.*** ***Suite 500 267 OConnor Street*** ***Ottawa ON K2P 1V3*** | ***GEN***

***Generator Info***

***Generator No:*** ON6644068
***Approval Years:*** As of Nov 2021
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 55 of 66 | SW/78.8 | 74.9 / 1.00 | CBI Home Health formerly We Care Home Health<br>267 O'Connor Street Suite 609<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON6991797 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Nov 2021 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 261 A |
| ***Waste Class Name:*** | Pharmaceuticals |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | Pathological wastes |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 56 of 66 | SW/78.8 | 74.9 / 1.00 | Sajjad Giby Pharmacies Inc.<br>267 O'CONNOR STREET, UNIT 120<br>OTTAWA ON K2P 1V3 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3475419 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Jan 2021 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | Pathological wastes |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 261 A |
| ***Waste Class Name:*** | Pharmaceuticals |

***2017 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3475419 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 13973 | ***Phone No Official:*** | 613-238-8552 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 4164931120 Ext.3218 |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 446110 | ***County Out:*** | |

| | | | |
|---|---|---|---|
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Sajjad Giby Pharmacies Inc. | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | SHOPPERS SIMPLY PHARMACY 3003 | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 267 O'CONNOR STREET, UNIT 120 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | OTTAWA | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1V3 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | SAJJAD H GIBY GIBY | | |
| ***Co Admin:*** | NASTRAN NAJAFI-FARD | | |

***2018 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3475419 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 13844 | ***Phone No Official:*** | 613-238-8552 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 4164931120 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 446110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Sajjad Giby Pharmacies Inc. | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | SHOPPERS SIMPLY PHARMACY 3003 | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 267 O'CONNOR STREET, UNIT 120 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | OTTAWA | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1V3 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | SAJJAD H GIBY GIBY | | |
| ***Co Admin:*** | Pharmacy Operations Development | | |

***2019 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3475419 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 13631 | ***Phone No Official:*** | 613-238-8552 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 4164931120 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 446110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Sajjad Giby Pharmacies Inc. | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | SHOPPERS SIMPLY PHARMACY 3003 | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 267 O'CONNOR STREET, UNIT 120 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | OTTAWA | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1V3 | | |

**Site Country:** Canada
**Co Official:** SAJJAD H GIBY GIBY
**Co Admin:** Pharmacy Operations Development

***2020 Generator Info***

**Gen No:** ON3475419
**ID:** 13296
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 446110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Sajjad Giby Pharmacies Inc.
**Gen Div:**
**Gen Op Name:** SHOPPERS SIMPLY PHARMACY 3003
**Gen Op Div:**
**Site Adrs1:** 267 O'CONNOR STREET, UNIT 120
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** OTTAWA
**Province Out:**
**Site Postal Code:** K2P 1V3
**Site Country:** Canada
**Co Official:** SAJJAD H GIBY GIBY
**Co Admin:** Pharmacy Operations Development
**Choice of Contact:** CO_ADMIN
**Phone No Official:** 613-238-8552 Ext.
**Phone No Admin:** 4164931120 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 57 of 66 | SW/78.8 | 74.9 / 1.00 | Ottawa Endoscopy & Day Surgery<br>267 O'connor Street Suite 207<br>Ottawa ON K2P 1V3 | GEN |

***Generator Info***

**Generator No:** ON7074415
**Approval Years:** As of Jan 2021
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**
**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** Pathological wastes

***2017 Generator Info***

**Gen No:** ON7074415
**ID:** 27762
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621390
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Ottawa Endoscopy & Day Surgery
**Gen Div:**
**Gen Op Name:** Ottawa Endoscopy & Day Surgery
**Choice of Contact:** CO_ADMIN
**Phone No Official:** 613-567-4922 Ext.
**Phone No Admin:** 6135678106 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***Gen Op Div:***
***Site Adrs1:*** 267 O'connor Street
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** Suite 207
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3
***Site Country:*** Canada
***Co Official:*** Russell Kronick
***Co Admin:*** Grace Wilson

***2017 Generator Manifest***

***ID:*** 54059
***Generator No:*** ON7074415
***Receiver Type:*** 030
***Waste Char:*** P
***Waste Code:*** 312
***Sum Received Qty:*** 99.5
***Waste Class Name:*** PATHOLOGICAL WASTES
***Count Manifests:*** 2
***District:*** 402

***2018 Generator Info***

***Gen No:*** ON7074415
***ID:*** 28210
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 621390
***NAICS Code2:***
***NAICS Code3:***
***Choice of Contact:*** CO_ADMIN
***Phone No Official:*** 613-567-4922 Ext.
***Phone No Admin:*** 6135678106 Ext.
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402
***Gen Name:*** Ottawa Endoscopy & Day Surgery
***Gen Div:***
***Gen Op Name:*** Ottawa Endoscopy & Day Surgery
***Gen Op Div:***
***Site Adrs1:*** 267 O'connor Street
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** Suite 207
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3
***Site Country:*** Canada
***Co Official:*** Russell Kronick
***Co Admin:*** Grace Wilson

***2018 Generator Manifest***

***ID:*** 54122
***Generator No:*** ON7074415
***Receiver Type:*** 030
***Waste Char:*** P
***Waste Code:*** 312
***Sum Received Qty:*** 140.7
***Waste Class Name:*** PATHOLOGICAL WASTES
***Count Manifests:*** 3
***District:*** 402

***2019 Generator Info***

***Gen No:*** ON7074415
***ID:*** 28490
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 621390
***NAICS Code2:***
***Choice of Contact:*** CO_ADMIN
***Phone No Official:*** 613-567-4922 Ext.1
***Phone No Admin:*** 6135678106 Ext.
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402

***NAICS Code3:***
***Gen Name:*** Ottawa Endoscopy & Day Surgery
***Gen Div:***
***Gen Op Name:*** Ottawa Endoscopy & Day Surgery
***Gen Op Div:***
***Site Adrs1:*** 267 O'connor Street
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** Suite 207
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3
***Site Country:*** Canada
***Co Official:*** Russell Kronick
***Co Admin:*** Grace Wilson

***2019 Generator Manifest***

***ID:*** 54107
***Generator No:*** ON7074415
***Receiver Type:*** 030
***Waste Char:*** P
***Waste Code:*** 312
***Sum Received Qty:*** 147.0
***Waste Class Name:*** PATHOLOGICAL WASTES
***Count Manifests:*** 2
***District:*** 402

***2020 Generator Info***

***Gen No:*** ON7074415
***ID:*** 28184
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 621390
***NAICS Code2:***
***NAICS Code3:***
***Choice of Contact:*** CO_ADMIN
***Phone No Official:*** 613-567-4922 Ext.1
***Phone No Admin:*** 6135678106 Ext.
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402
***Gen Name:*** Ottawa Endoscopy & Day Surgery
***Gen Div:***
***Gen Op Name:*** Ottawa Endoscopy & Day Surgery
***Gen Op Div:***
***Site Adrs1:*** 267 O'connor Street
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** Suite 207
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3
***Site Country:*** Canada
***Co Official:*** Russell Kronick
***Co Admin:*** Grace Wilson

***2020 Generator Manifest***

***ID:*** 50505
***Generator No:*** ON7074415
***Receiver Type:*** 030
***Waste Char:*** P
***Waste Code:*** 312
***Sum Received Qty:*** 89.6
***Waste Class Name:*** PATHOLOGICAL WASTES
***Count Manifests:*** 2
***District:*** 402

***2021 Generator Info***

***Gen No:*** ON7074415
***ID:*** 28710
***Choice of Contact:*** CO_ADMIN
***Phone No Official:*** 613-567-4922 Ext.1

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Contaminated Fac:** | N | **Phone No Admin:** | 6135678106 Ext. |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 621390 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | Ottawa Endoscopy & Day Surgery | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | Ottawa Endoscopy & Day Surgery | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 267 O'connor Street | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | Suite 207 | | |
| **Site City:** | Ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P 1V3 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | Russell Kronick | | |
| **Co Admin:** | Grace Wilson | | |

***2021 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 52535 | **Sum Received Qty:** | 33.8 |
| **Generator No:** | ON7074415 | **Waste Class Name:** | PATHOLOGICAL WASTES |
| **Receiver Type:** | 030 | **Count Manifests:** | 1 |
| **Waste Char:** | P | **District:** | 402 |
| **Waste Code:** | 312 | | |

| | | | | | |
|---|---|---|---|---|---|
| 20 | ***58 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***Midtown Family Health***<br>***267 O'Connor ST. Suite 306***<br>***Ottawa ON K2P 1V3*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON5935207 | **Choice of Contact:** | |
| **Approval Years:** | As of Nov 2021 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 312 P |
| **Waste Class Name:** | Pathological wastes |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 261 A |
| **Waste Class Name:** | Pharmaceuticals |

| | | | | | |
|---|---|---|---|---|---|
| 20 | ***59 of 66*** | ***SW/78.8*** | ***74.9 / 1.00*** | ***CBI Home Health formerly We Care Home Health***<br>***267 O'Connor Street Suite 609***<br>***Ottawa ON K2P 1V3*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON6991797 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Oct 2022 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 261 A |
| ***Waste Class Name:*** | PHARMACEUTICALS |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

***2017 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6991797 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 27457 | ***Phone No Official:*** | 6137822244 Ext.34527 |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 6137822244 Ext.1811 |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621610 | ***County Out:*** | |
| ***NAICS Code2:*** | 621390 | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | CBI Home Health formerly We Care Home Health | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | CBI Home Health formerly We Care Home Health | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 267 O'Connor Street Suite 609 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1V3 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | Melina A Verhaegen | | |
| ***Co Admin:*** | Heather Bozik | | |

***2017 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 53636 | ***Sum Received Qty:*** | 303.82 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PHARMACEUTICALS |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 8 |
| ***Waste Char:*** | A | ***District:*** | 402 |
| ***Waste Code:*** | 261 | | |

***2017 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 53637 | ***Sum Received Qty:*** | 102.94 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 6 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

***2018 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6991797 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 27876 | ***Phone No Official:*** | 6137822244 Ext.34527 |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-782-2244 Ext.34527 |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621610 | ***County Out:*** | |
| ***NAICS Code2:*** | 621390 | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |

***Gen Name:*** CBI Home Health formerly We Care Home Health
***Gen Div:***
***Gen Op Name:*** CBI Home Health formerly We Care Home Health
***Gen Op Div:***
***Site Adrs1:*** 267 O'Connor Street Suite 609
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3
***Site Country:*** Canada
***Co Official:*** Melina A Verhaegen
***Co Admin:*** Ankita Gandhi

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 53627 | ***Sum Received Qty:*** | 145.93 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 9 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 53626 | ***Sum Received Qty:*** | 178.93 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PHARMACEUTICALS |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 12 |
| ***Waste Char:*** | A | ***District:*** | 402 |
| ***Waste Code:*** | 261 | | |

***2019 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6991797 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 28145 | ***Phone No Official:*** | 6137822244 Ext.34527 |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-782-2244 Ext.34527 |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621610 | ***County Out:*** | |
| ***NAICS Code2:*** | 621390 | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |

***Gen Name:*** CBI Home Health formerly We Care Home Health
***Gen Div:***
***Gen Op Name:*** CBI Home Health formerly We Care Home Health
***Gen Op Div:***
***Site Adrs1:*** 267 O'Connor Street Suite 609
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3

**Site Country:** Canada
**Co Official:** Melina A Verhaegen
**Co Admin:** Ankita Gandhi

***2019 Generator Manifest***

**ID:** 53560
**Generator No:** ON6991797
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 261
**Sum Received Qty:** 9.0
**Waste Class Name:** PHARMACEUTICALS
**Count Manifests:** 1
**District:** 402

***2019 Generator Manifest***

**ID:** 53559
**Generator No:** ON6991797
**Receiver Type:** 030
**Waste Char:** A
**Waste Code:** 261
**Sum Received Qty:** 173.0
**Waste Class Name:** PHARMACEUTICALS
**Count Manifests:** 11
**District:** 402

***2019 Generator Manifest***

**ID:** 53561
**Generator No:** ON6991797
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 58.0
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 9
**District:** 402

***2020 Generator Info***

**Gen No:** ON6991797
**ID:** 27851
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621610
**NAICS Code2:** 621390
**NAICS Code3:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 6137822244 Ext.34527
**Phone No Admin:** 613-782-2244 Ext.34527
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402
**Gen Name:** CBI Home Health formerly We Care Home Health
**Gen Div:**
**Gen Op Name:** CBI Home Health formerly We Care Home Health
**Gen Op Div:**
**Site Adrs1:** 267 O'Connor Street Suite 609
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1V3
**Site Country:** Canada
**Co Official:** Melina A Verhaegen
**Co Admin:** Ankita Gandhi

***2020 Generator Manifest***

**ID:** 50015
**Generator No:** ON6991797
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 18.84
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 2
**District:** 402

***2020 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 50012 | ***Sum Received Qty:*** | 41.7 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PHARMACEUTICALS |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 3 |
| ***Waste Char:*** | A | ***District:*** | 305 |
| ***Waste Code:*** | 261 | | |

***2020 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 50013 | ***Sum Received Qty:*** | 19.7 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 2 |
| ***Waste Char:*** | P | ***District:*** | 305 |
| ***Waste Code:*** | 312 | | |

***2020 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 50014 | ***Sum Received Qty:*** | 28.73 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PHARMACEUTICALS |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 3 |
| ***Waste Char:*** | A | ***District:*** | 402 |
| ***Waste Code:*** | 261 | | |

***2021 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6991797 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 28360 | ***Phone No Official:*** | 6137822244 Ext.34527 |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-782-2244 Ext.34527 |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621610 | ***County Out:*** | |
| ***NAICS Code2:*** | 621390 | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | CBI Home Health formerly We Care Home Health | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | CBI Home Health formerly We Care Home Health | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 267 O'Connor Street Suite 609 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1V3 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | Melina A Verhaegen | | |
| ***Co Admin:*** | Ankita Gandhi | | |

***2021 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 51977 | ***Sum Received Qty:*** | 54.82 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 6 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

***2021 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 51976 | ***Sum Received Qty:*** | 64.8 |
| ***Generator No:*** | ON6991797 | ***Waste Class Name:*** | PHARMACEUTICALS |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 10 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Waste Char:** | A | | | **District:** 402 | |
| **Waste Code:** | 261 | | | | |

| | | | | | |
|---|---|---|---|---|---|
| 20 | 60 of 66 | SW/78.8 | 74.9 / 1.00 | **Midtown Ottawa FHO**<br>**267 O'Connor ST. Suite 306**<br>**Ottawa ON** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON5935207 | **Choice of Contact:** | |
| **Approval Years:** | As of Oct 2022 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 312 P |
| **Waste Class Name:** | PATHOLOGICAL WASTES |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 261 A |
| **Waste Class Name:** | PHARMACEUTICALS |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| **Generator No:** | ON5935207 |
| **Generator Company Name:** | Midtown Ottawa FHO |
| **Street:** | 267 O'Connor ST. Suite 306 |
| **City:** | Ottawa |
| **Province State:** | Ontario |
| **Country:** | Canada |
| **Postal Code:** | K2P1V3 |
| **Waste Class:** | 312 P,261 A |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| **Generator Company Name:** | Midtown Ottawa FHO |
| **Generator Site Address:** | 267 O'Connor ST. Suite 306 |
| **City:** | Ottawa |
| **Province State:** | Ontario |
| **Country:** | Canada |
| **Postal Code:** | K2P1V3 |
| **Waste Class:** | 312 P, 261 A |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

***Waste Characteristic Decoded:***

P - Pathological; A - Acutely Hazardous Waste Chem.

***2017 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON5935207 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 23417 | ***Phone No Official:*** | 613-233-6652 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 6132336652 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Midtown Family Health | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | bhavna Valia | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 267 O'Connor ST. Suite 306 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1V3 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | Bhavna Valia | | |
| ***Co Admin:*** | Helen Rizzo | | |

***2017 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 48459 | ***Sum Received Qty:*** | 6.1 |
| ***Generator No:*** | ON5935207 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | P | ***District:*** | 305 |
| ***Waste Code:*** | 312 | | |

***2017 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 48460 | ***Sum Received Qty:*** | 23.9 |
| ***Generator No:*** | ON5935207 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 3 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

***2018 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON5935207 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 23664 | ***Phone No Official:*** | 613-233-6652 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 6132336652 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Midtown Family Health | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | bhavna Valia | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 267 O'Connor ST. Suite 306 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |

**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1V3
**Site Country:** Canada
**Co Official:** Bhavna Valia
**Co Admin:** Helen Rizzo

***2018 Generator Manifest***

**ID:** 48338
**Generator No:** ON5935207
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 23.9
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 3
**District:** 402

***2019 Generator Info***

**Gen No:** ON5935207
**ID:** 23786
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Midtown Family Health
**Gen Div:**
**Gen Op Name:** bhavna Valia
**Gen Op Div:**
**Site Adrs1:** 267 O'Connor ST. Suite 306
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1V3
**Site Country:** Canada
**Co Official:** Bhavna Valia
**Co Admin:** Helen Rizzo
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 613-233-6652 Ext.
**Phone No Admin:** 6132336652 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2019 Generator Manifest***

**ID:** 48097
**Generator No:** ON5935207
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 23.0
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 3
**District:** 402

***2020 Generator Info***

**Gen No:** ON5935207
**ID:** 23501
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Midtown Family Health
**Gen Div:**
**Gen Op Name:** Bhavna Valia
**Gen Op Div:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 613-233-6652 Ext.
**Phone No Admin:** 6132336652 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Site Adrs1:** 267 O'Connor ST. Suite 306
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1V3
**Site Country:** Canada
**Co Official:** Bhavna Valia
**Co Admin:** Helen Rizzo

***2020 Generator Manifest***

**ID:** 44705
**Generator No:** ON5935207
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 13.1
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 2
**District:** 402

***2021 Generator Info***

**Gen No:** ON5935207
**ID:** 23852
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Midtown Family Health
**Gen Div:**
**Gen Op Name:** Darren Whatley
**Gen Op Div:**
**Site Adrs1:** 267 O'Connor ST. Suite 306
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1V3
**Site Country:** Canada
**Co Official:** Whatley Darren
**Co Admin:** Helen Rizzo
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 613-233-6652 Ext.
**Phone No Admin:** 6132336652 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2021 Generator Manifest***

**ID:** 46433
**Generator No:** ON5935207
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 24.05
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 3
**District:** 402

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 61 of 66 | SW/78.8 | 74.9 / 1.00 | CENTRAL OTTAWA FAMILY MEDICINE ASSOCIATES LTD.<br>Suite 500, 267 O'Connor Street<br>Ottawa ON | GEN |

***Generator Info***

**Generator No:** ON6644068
**Choice of Contact:**

| | | | |
|---|---|---|---|
| ***Approval Years:*** | As of Oct 2022 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 148 C |
| ***Waste Class Name:*** | INORGANIC LABORATORY CHEMICALS |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON6644068 |
| ***Generator Company Name:*** | CENTRAL OTTAWA FAMILY MEDICINE ASSOCIATES LTD. |
| ***Street:*** | Suite 500, 267 O'Connor Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1V3 |
| ***Waste Class:*** | 312 P,148 C |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 148 - INORGANIC LABORATORY CHEMICALS

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | CENTRAL OTTAWA FAMILY MEDICINE ASSOCIATES LTD. |
| ***Generator Site Address:*** | Suite 500, 267 O'Connor Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1V3 |
| ***Waste Class:*** | 312 P, 148 C |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 148 - INORGANIC LABORATORY CHEMICALS

***Waste Characteristic Decoded:***

P - Pathological; C - Corrosive

***2017 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6644068 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 26121 | ***Phone No Official:*** | 613-760-3701 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-730-3701 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |

***NAICS Code3:***
***Gen Name:*** Central Ottawa Family Medicine Associates Ltd.
***Gen Div:***
***Gen Op Name:*** Central Ottawa Family Medicine Associates
***Gen Op Div:***
***Site Adrs1:*** Suite 500
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** 267 O'Connor Street
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3
***Site Country:*** Canada
***Co Official:*** Jasmine Soule
***Co Admin:*** Jasmine Soule

***2018 Generator Info***

***Gen No:*** ON6644068
***ID:*** 26462
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 621110
***NAICS Code2:***
***NAICS Code3:***
***Choice of Contact:*** CO_ADMIN
***Phone No Official:*** 613-760-3701 Ext.
***Phone No Admin:*** 613-730-3701 Ext.
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402
***Gen Name:*** Central Ottawa Family Medicine Associates Ltd.
***Gen Div:***
***Gen Op Name:*** Central Ottawa Family Medicine Associates
***Gen Op Div:***
***Site Adrs1:*** Suite 500
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** 267 O'Connor Street
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3
***Site Country:*** Canada
***Co Official:*** Jasmine Soule
***Co Admin:*** Jasmine Soule

***2019 Generator Info***

***Gen No:*** ON6644068
***ID:*** 26699
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 621110
***NAICS Code2:***
***NAICS Code3:***
***Choice of Contact:*** CO_ADMIN
***Phone No Official:*** 613-760-3701 Ext.
***Phone No Admin:*** 613-730-3701 Ext.
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402
***Gen Name:*** Central Ottawa Family Medicine Associates Ltd.
***Gen Div:***
***Gen Op Name:*** Central Ottawa Family Medicine Associates
***Gen Op Div:***
***Site Adrs1:*** Suite 500
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** 267 O'Connor Street
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V3
***Site Country:*** Canada

**Co Official:** Jasmine Soule
**Co Admin:** Jasmine Soule

***2020 Generator Info***

**Gen No:** ON6644068
**ID:** 26434
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Central Ottawa Family Medicine Associates Ltd.
**Gen Div:**
**Gen Op Name:** Central Ottawa Family Medicine Associates
**Gen Op Div:**
**Site Adrs1:** Suite 500
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:** 267 O'Connor Street
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1V3
**Site Country:** Canada
**Co Official:** Jasmine Soule
**Co Admin:** Jasmine Soule
**Choice of Contact:** CO_ADMIN
**Phone No Official:** 613-760-3701 Ext.
**Phone No Admin:** 613-730-3701 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2021 Generator Info***

**Gen No:** ON6644068
**ID:** 26892
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Central Ottawa Family Medicine Associates Ltd.
**Gen Div:**
**Gen Op Name:** Central Ottawa Family Medicine Associates
**Gen Op Div:**
**Site Adrs1:** Suite 500
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:** 267 O'Connor Street
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1V3
**Site Country:** Canada
**Co Official:** Jasmine Soule
**Co Admin:** Jasmine Soule
**Choice of Contact:** CO_ADMIN
**Phone No Official:** 613-760-3701 Ext.
**Phone No Admin:** 613-730-3701 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 62 of 66 | SW/78.8 | 74.9 / 1.00 | DENTAL TECHNOLOGY GROUP INC.<br>267 O'CONNOR ST SUITE 101<br>OTTAWA ON K2P 1V3 | SCT |

**Scott S ID:** 18939431
**Latitude:**
**Longitude:**

***Historical Details***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Established:** 1989
**Plant Size (ft²):** 0
**Employment:** 14

***Historical Details***

**Description:** Medical Equipment and Supplies Manufacturing
**SIC/NAICS Code:** 339110

***Historical Details***

**Description:** DENTAL EQUIPMENT AND SUPPLIES
**SIC/NAICS Code:** 3843

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | 63 of 66 | SW/78.8 | 74.9 / 1.00 | **E.L. LITTLEJOHN & ASSOCIATES**<br>**267 O'Connor St**<br>**Ottawa ON K2P 1V3** | SCT |

**Scott S ID:** 18522054
**Latitude:**
**Longitude:**

***Historical Details***

**Established:** 1972
**Plant Size (ft²):** 1200
**Employment:** 2

***Historical Details***

**Description:** Other Printing
**SIC/NAICS Code:** 323119

***Historical Details***

**Description:** Periodical Publishers
**SIC/NAICS Code:** 511120

***Historical Details***

**Description:** Database and Directory Publishers
**SIC/NAICS Code:** 511140

---

| | | | | | |
|---|---|---|---|---|---|
| 20 | 64 of 66 | SW/78.8 | 74.9 / 1.00 | **The Dental Technology Group**<br>**267 O'Connor St Suite 101**<br>**Ottawa ON K2P 1V3** | SCT |

**Scott S ID:** 32905202
**Latitude:**
**Longitude:**

***Historical Details***

**Established:**
**Plant Size (ft²):**
**Employment:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 65 of 66 | SW/78.8 | 74.9 / 1.00 | E.L. Littlejohn & Associates Ltd.<br>267 O'Connor St<br>Ottawa ON K2P 1V3 | SCT |

**Scott S ID:** 18522054
**Latitude:**
**Longitude:**

***Historical Details***

**Established:** 1972
**Plant Size (ft²):** 1200
**Employment:** 2

***Historical Details***

**Description:** Other Printing
**SIC/NAICS Code:** 323119

***Historical Details***

**Description:** Periodical Publishers
**SIC/NAICS Code:** 511120

***Historical Details***

**Description:** Directory and Mailing List Publishers
**SIC/NAICS Code:** 511140

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 66 of 66 | SW/78.8 | 74.9 / 1.00 | GALLEY Kitchen + Provisions<br>267 O'Connor St<br>Ottawa ON K2P1V3 | SCT |

**Scott S ID:** 301371828
**Latitude:** 45.4155
**Longitude:** -75.6933

***Details***

**Bus Type 1:** Accommodation and Food Services
**Bus Type 2:** Manufacturer
**Bus Type 3:**
**Product Cat 1:** Food producer
**Product Cat 2:** Restaurant
**Product Cat 3:**
**Product Cat 4:**
**Product Cat 5:**
**Product Cat 6:**
**Product Cat 7:**
**Product Cat 8:**
**Company Name:** GALLEY Kitchen + Provisions
**Address Line 1:** 267 O'Connor St
**Address Line 2:**
**City:** Ottawa
**Province:** ON
**Postal Code:** K2P1V3
**Census Division:** Ottawa; ON
**Metro Area:** Ottawa/Hull
**Year Established:**
**Head Office Indicator:**

**Employee Count:** 5
**Square Footage:** 0
**Estimated Sales:** Under $1 Million
**Export Indicator:**
**Export Country 1:**
**Export Country 2:**
**Export Country 3:**
**Export Country 4:**
**Export Country 5:**
**Export Country 6:**
**Geocoded by:** Address

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | |
|---|---|
| **Parent Company Nm:** | |
| **Parent Cmpny Addr 1:** | |
| **Parent Cmpny Addr 2:** | |
| **Parent Cmpny City:** | |
| **Parent Cmpny Prov:** | |
| **Parent Cmpy PC:** | |
| **Parent Cmpy Cntry:** | |
| **Head Office Nm:** | |
| **H Office Addr Line 1:** | |
| **H Office Addr Line 2:** | |
| **Head Office City:** | |
| **Head Office Province:** | |
| **Head Office PC:** | |
| **Head Office Cntry:** | |
| **Telephone:** | 613-447-1060 |
| **Fax:** | -- |
| **Website:** | https://www.galleykp.com/contact-1 |
| **Pri NAICS Desc:** | 722410-Drinking Places (Alcoholic Beverages) |
| **NAICS Code 1:** | 311990-All Other Food Manufacturing |
| **NAICS Code 2:** | 722511-Full-Service Restaurants |
| **NAICS Code 3:** | |
| **NAICS Code 4:** | |
| **NAICS Code 5:** | |

---

**21** | **1 of 1** | **NNW/80.0** | **74.6 / 0.69** | **Cdn Council-International Law**
**236 Metcalfe St Suite 215**
**Ottawa ON K2P 1R3** | **SCT**

| | |
|---|---|
| **Scott S ID:** | 35850470 |
| **Latitude:** | |
| **Longitude:** | |

***Historical Details***

| | |
|---|---|
| **Established:** | 1972 |
| **Plant Size (ft²):** | |
| **Employment:** | |

***Historical Details***

| | |
|---|---|
| **Description:** | Periodical Publishers |
| **SIC/NAICS Code:** | 511120 |

***Historical Details***

| | |
|---|---|
| **Description:** | Professional Organizations |
| **SIC/NAICS Code:** | 813920 |

---

**22** | **1 of 1** | **WSW/84.6** | **74.9 / 1.00** | **267 O'Connor Street**
**Ottawa ON K2P 1V3** | **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 23083000586 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 05-SEP-23 | **Search Radius (km):** | .25 |
| **Date Received:** | 30-AUG-23 | **X:** | -75.6931679 |
| **Previous Site Name:** | | **Y:** | 45.4154325 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 1 of 1 | W/86.7 | 74.9 / 1.00 | 293 McLAREN STREET<br>OTTAWA ON | HINC |

| | |
|---|---|
| **External File Num:** | FS INC 0711-07045 |
| **Fuel Occurrence Type:** | |
| **Date of Occurrence:** | |
| **Fuel Type Involved:** | |
| **Status Desc:** | Completed - No Action Required |
| **Job Type Desc:** | Incident/Near-Miss Occurrence (FS) |
| **Oper. Type Involved:** | |
| **Service Interruptions:** | |
| **Property Damage:** | |
| **Fuel Life Cycle Stage:** | |
| **Root Cause:** | |
| **Reported Details:** | |
| **Fuel Category:** | Liquid Fuel |
| **Occurrence Type:** | Near-miss |
| **Affiliation:** | Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.) |
| **County Name:** | Ottawa |
| **Approx. Quant. Rel:** | |
| **Nearby body of water:** | |
| **Enter Drainage Syst.:** | |
| **Approx. Quant. Unit:** | |
| **Environmental Impact:** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 24 | 1 of 1 | NNW/87.0 | 74.9 / 1.00 | 258-260 Somerset Street West<br>Ottawa ON K2P 0J6 | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 20050919026 | **Nearest Intersection:** | Metcalfe St and Somerset St W |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 9/28/2005 | **Search Radius (km):** | 0.25 |
| **Date Received:** | 9/19/2005 | **X:** | -75.692633 |
| **Previous Site Name:** | | **Y:** | 45.416775 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 25 | 1 of 1 | SSW/89.3 | 74.6 / 0.69 | ON | WWIS |

| | | | |
|---|---|---|---|
| **Well ID:** | 7473693 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 03/22/2024 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z398871 | **Contractor:** | 7241 |
| **Tag:** | A384758 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | NEPEAN TOWNSHIP | | |
| **Site Info:** | | | |

***Additional Detail(s) (Map)***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Bore Hole ID:** 1010281560
**Depth (m):**
**Year Completed:** 2024
**Well Completed Dt:** 01/18/2024
**Audit No:** Z398871
**Path:**

**Tag No:** A384758
**Contractor:** 7241
**Latitude:** 45.4151560179716
**Longitude:** -75.6926918359856
**Point Y:** 45.41515601088936
**Point X:** -75.69269167424378

***Bore Hole Information***

**Bore Hole ID:** 1010281560
**DP2BR:**
**Spatial Status:**
**Code OB:**
**Code OB Desc:**
**Open Hole:**
**Cluster Kind:**
**Date Completed:** 01/18/2024
**Remarks:**
**Location Method Desc:** on Water Well Record
**Elevrc Desc:**
**Location Source Date:**
**Improvement Location Source:**
**Improvement Location Method:**
**Source Revision Comment:**
**Supplier Comment:**

**Elevation:**
**Elevrc:**
**Zone:** 18
**East83:** 445801.00
**North83:** 5029304.00
**Org CS:** UTM83
**UTMRC:** 4
**UTMRC Desc:** margin of error : 30 m - 100 m
**Location Method:** wwr

---

**26** | **1 of 1** | **NW/100.9** | **74.9 / 1.00** | **GLENVIEW CORPORATION**
**270 SOMERSET WEST**
**OTTAWA ON K2P 0J7** | **GEN**

***Generator Info***

**Generator No:** ON6707052
**Approval Years:** 02,03,04
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 145
**Waste Class Name:** PAINT/PIGMENT/COATING RESIDUES

***Waste Detail(s)***

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

---

**27** | **1 of 1** | **S/116.8** | **73.8 / -0.03** | **ON** | **BORE**

**Borehole ID:** 613270
**OGF ID:** 215514571
**Status:**
**Type:** Borehole
**Use:**

**Inclin FLG:** No
**SP Status:** Initial Entry
**Surv Elev:** No
**Piezometer:** No
**Primary Name:**

| | | | |
|---|---|---|---|
| **Completion Date:** | | **Municipality:** | |
| **Static Water Level:** | 15.2 | **Lot:** | |
| **Primary Water Use:** | | **Township:** | |
| **Sec. Water Use:** | | **Latitude DD:** | 45.414871 |
| **Total Depth m:** | -999 | **Longitude DD:** | -75.692437 |
| **Depth Ref:** | Ground Surface | **UTM Zone:** | 18 |
| **Depth Elev:** | | **Easting:** | 445821 |
| **Drill Method:** | | **Northing:** | 5029272 |
| **Orig Ground Elev m:** | 70.1 | **Location Accuracy:** | |
| **Elev Reliabil Note:** | | **Accuracy:** | Not Applicable |
| **DEM Ground Elev m:** | 70.3 | | |
| **Concession:** | | | |
| **Location D:** | | | |
| **Survey D:** | | | |
| **Comments:** | | | |

***Borehole Geology Stratum***

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394440 | **Mat Consistency:** | Firm |
| **Top Depth:** | 2.4 | **Material Moisture:** | |
| **Bottom Depth:** | 12.5 | **Material Texture:** | |
| **Material Color:** | Blue | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | CLAY. BLUE,FIRM. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394438 | **Mat Consistency:** | Loose |
| **Top Depth:** | 0 | **Material Moisture:** | |
| **Bottom Depth:** | .6 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Sand | **Geologic Formation:** | |
| **Material 2:** | Gravel | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | SAND. LOOSE. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394439 | **Mat Consistency:** | Compact |
| **Top Depth:** | .6 | **Material Moisture:** | |
| **Bottom Depth:** | 2.4 | **Material Texture:** | |
| **Material Color:** | Blue | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | Sand | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | CLAY. BLUE,COMPACT. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394441 | **Mat Consistency:** | Firm |
| **Top Depth:** | 12.5 | **Material Moisture:** | |
| **Bottom Depth:** | 14.9 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | Sand | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | CLAY. FIRM. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394442 | **Mat Consistency:** | |
| **Top Depth:** | 14.9 | **Material Moisture:** | |
| **Bottom Depth:** | 19.5 | **Material Texture:** | |

***Material Color:*** ***Non Geo Mat Type:***
***Material 1:*** Sand ***Geologic Formation:***
***Material 2:*** Clay ***Geologic Group:***
***Material 3:*** ***Geologic Period:***
***Material 4:*** ***Depositional Gen:***
***Gsc Material Description:***
***Stratum Description:*** SAND,CLAY.

***Geology Stratum ID:*** 218394444 ***Mat Consistency:***
***Top Depth:*** 19.8 ***Material Moisture:***
***Bottom Depth:*** ***Material Texture:***
***Material Color:*** ***Non Geo Mat Type:***
***Material 1:*** Bedrock ***Geologic Formation:***
***Material 2:*** ***Geologic Group:***
***Material 3:*** ***Geologic Period:***
***Material 4:*** ***Depositional Gen:***
***Gsc Material Description:***
***Stratum Description:*** BEDROCK. BEDROCK. 00000 018 00055 053 00100 035 00150 025 00175 028 00190 **Note: Many records provided by the department have a truncated [Stratum Description] field.

***Geology Stratum ID:*** 218394443 ***Mat Consistency:*** Compact
***Top Depth:*** 19.5 ***Material Moisture:***
***Bottom Depth:*** 19.8 ***Material Texture:***
***Material Color:*** ***Non Geo Mat Type:***
***Material 1:*** Sand ***Geologic Formation:***
***Material 2:*** Gravel ***Geologic Group:***
***Material 3:*** ***Geologic Period:***
***Material 4:*** ***Depositional Gen:***
***Gsc Material Description:***
***Stratum Description:*** SAND. COMPACT, WATER STABLE AT 180.0 FEET.

***Source***

***Source Type:*** Data Survey ***Source Appl:*** Spatial/Tabular
***Source Orig:*** Geological Survey of Canada ***Source Iden:*** 1
***Source Date:*** 1956-1972 ***Scale or Res:*** Varies
***Confidence:*** H ***Horizontal:*** NAD27
***Observatio:*** ***Verticalda:*** Mean Average Sea Level
***Source Name:*** Urban Geology Automated Information System (UGAIS)
***Source Details:*** File: OTTAWA2.txt RecordID: 057780 NTS_Sheet: 31G05G
***Confiden 1:*** Logged by professional. Exact and complete description of material and properties.

***Source List***

***Source Identifier:*** 1 ***Horizontal Datum:*** NAD27
***Source Type:*** Data Survey ***Vertical Datum:*** Mean Average Sea Level
***Source Date:*** 1956-1972 ***Projection Name:*** Universal Transverse Mercator
***Scale or Resolution:*** Varies
***Source Name:*** Urban Geology Automated Information System (UGAIS)
***Source Originators:*** Geological Survey of Canada

---

**28** ***1 of 4*** ***N/120.8*** ***73.9 / 0.00*** ***R.M. OF OTTAWA-CARLETON SOMERSET ST./METCALFE ST. OTTAWA CITY ON*** ***CA***

***Certificate #:*** 7-0343-99-
***Application Year:*** 99
***Issue Date:*** 5/21/1999
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

**28** | ***2 of 4*** | ***N/120.8*** | ***73.9 / 0.00*** | ***City of Ottawa*** ***Somerset Street and Metcalfe Street*** ***Ottawa ON*** | ***CA***

***Certificate #:*** 6578-6H3J45
***Application Year:*** 2005
***Issue Date:*** 10/11/2005
***Approval Type:*** Municipal and Private Sewage Works
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

**28** | ***3 of 4*** | ***N/120.8*** | ***73.9 / 0.00*** | ***City of Ottawa*** ***Somerset Street and Metcalfe St*** ***Ottawa ON K2G 6J8*** | ***ECA***

***Approval No:*** 6578-6H3J45
***Approval Date:*** 2005-10-11
***Status:*** Approved
***Record Type:*** ECA
***Link Source:*** IDS
***SWP Area Name:***
***Approval Type:*** ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
***Project Type:*** MUNICIPAL AND PRIVATE SEWAGE WORKS
***Business Name:*** City of Ottawa
***Address:*** Somerset Street and Metcalfe St
***Full Address:***
***Full PDF Link:*** https://www.accessenvironment.ene.gov.on.ca/instruments/9286-6GTRNN-14.pdf
***PDF Site Location:***
***MOE District:***
***City:***
***Longitude:***
***Latitude:***
***Geometry X:***
***Geometry Y:***

---

**28** | ***4 of 4*** | ***N/120.8*** | ***73.9 / 0.00*** | ***City of Ottawa*** ***Somerset Street and Metcalfe St*** ***Ottawa ON K2G 6J8*** | ***ECA***

***Approval No:*** 7047-6H3HYB
***Approval Date:*** 2005-10-11
***Status:*** Approved
***Record Type:*** ECA
***Link Source:*** IDS
***SWP Area Name:***
***Approval Type:*** ECA-Municipal Drinking Water Systems
***Project Type:*** Municipal Drinking Water Systems
***Business Name:*** City of Ottawa
***Address:*** Somerset Street and Metcalfe St
***Full Address:***
***Full PDF Link:***
***PDF Site Location:***
***MOE District:***
***City:***
***Longitude:***
***Latitude:***
***Geometry X:***
***Geometry Y:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 1 of 7 | E/124.3 | 73.2 / -0.68 | PUBLIC SERVICE ALLIANCE OF CANADA<br>233 GILMOUR ST.<br>OTTAWA ON K2P 0P1 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0939900 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 86,87,88,89,90 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 8159 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | OTHER GEN. ADMIN. | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 264 |
| ***Waste Class Name:*** | PHOTOPROCESSING WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 2 of 7 | E/124.3 | 73.2 / -0.68 | PUBLIC SERVICE ALLIANCE OF CANADA 31-381<br>233 GILMOUR ST.<br>OTTAWA ON K2P 0P1 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0939900 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 92,93,94,95,96,97,98 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 8159 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | OTHER GEN. ADMIN. | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 264 |
| ***Waste Class Name:*** | PHOTOPROCESSING WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 3 of 7 | E/124.3 | 73.2 / -0.68 | PSAC Holdings Ltd.<br>233 Gilmour Street<br>Ottawa ON K2P 0P2 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3358750 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 06 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 531310 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Real Estate Property Managers | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Detail(s)***

***Waste Class:*** 243
***Waste Class Name:*** PCB'S

---

**29** ***4 of 7*** ***E/124.3*** ***73.2 / -0.68*** ***PSAC Holdings Ltd.*** ***GEN***
***233 Gilmour Street***
***Ottawa ON***

***Generator Info***

***Generator No:*** ON3358750
***Approval Years:*** 2009
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** Real Estate Property Managers

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 531310

***Waste Detail(s)***

***Waste Class:*** 243
***Waste Class Name:*** PCBS

***Waste Detail(s)***

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

**29** ***5 of 7*** ***E/124.3*** ***73.2 / -0.68*** ***PSAC Holdings Ltd.*** ***GEN***
***233 Gilmour Street***
***Ottawa ON***

***Generator Info***

***Generator No:*** ON3358750
***Approval Years:*** 2010
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** Real Estate Property Managers

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 531310

***Waste Detail(s)***

***Waste Class:*** 243
***Waste Class Name:*** PCBS

***Waste Detail(s)***

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 6 of 7 | E/124.3 | 73.2 / -0.68 | PSAC HOLDINGS LTD.<br>233 GILMOUR STREET<br>OTTAWA ON K1S 1V7 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3357645 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Dec 2017 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 251 L |
| ***Waste Class Name:*** | Waste oils/sludges (petroleum based) |

***2017 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3357645 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 13538 | ***Phone No Official:*** | 613-225-9533 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 531310 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | PSAC HOLDINGS LTD. | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | PSAC HOLDINGS LTD. | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 233 GILMOUR STREET | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | OTTAWA | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K1S 1V7 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | Krissy Van Alstein | | |
| ***Co Admin:*** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 7 of 7 | E/124.3 | 73.2 / -0.68 | Plomberie Bourget Plumbing<br>233 gilmour st ottawa<br>Ottawa ON | GEN |

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | Plomberie Bourget Plumbing |
| ***Generator Site Address:*** | 233 gilmour st ottawa |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P 0P2 |
| ***Waste Class:*** | 122 L |

***Waste Class Decoded:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

122 - ALKALINE WASTES - OTHER METALS

***Waste Characteristic Decoded:***

L - Liquid Industrial Waste

---

**30** | ***1 of 1*** | ***ESE/124.6*** | ***73.6 / -0.31*** | ***R.M. OF OTTAWA-CARLETON LEWIS ST/METCALFE ST. OTTAWA CITY ON*** | ***CA***

| | |
|---|---|
| ***Certificate #:*** | 7-0642-95- |
| ***Application Year:*** | 95 |
| ***Issue Date:*** | 7/17/1995 |
| ***Approval Type:*** | Municipal water |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

---

**31** | ***1 of 1*** | ***NE/127.0*** | ***73.9 / 0.00*** | ***225 MacLaren Street Ottawa ON K2P 0L4*** | ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20191128026 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Site Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 29-NOV-19 | ***Search Radius (km):*** | .001 |
| ***Date Received:*** | 28-NOV-19 | ***X:*** | -75.691284 |
| ***Previous Site Name:*** | | ***Y:*** | 45.41679 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | | | |

---

**32** | ***1 of 1*** | ***ESE/128.2*** | ***72.8 / -1.12*** | ***296 Metcalfe Street Ottawa ON K2P 1S2*** | ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 23111000466 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 15-NOV-23 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 10-NOV-23 | ***X:*** | -75.6910996 |
| ***Previous Site Name:*** | | ***Y:*** | 45.4151639 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos | | |

---

**33** | ***1 of 1*** | ***W/129.0*** | ***75.2 / 1.31*** | ***300 Somerset St W Ottawa ON K2P0J6*** | ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20130710005 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Custom Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 16-JUL-13 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 10-JUL-13 | ***X:*** | -75.693958 |
| ***Previous Site Name:*** | | ***Y:*** | 45.416131 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Lot/Building Size:** | | | | | |
| **Additional Info Ordered:** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| 34 | 1 of 8 | SSW/129.1 | 74.6 / 0.69 | **1384274 Ontario Inc.**<br>**330 Gilmour St Ward 14**<br>**Ottawa ON K2P 2P6** | CA |

**Certificate #:** 9606-88TP5T
**Application Year:** 2010
**Issue Date:** 8/31/2010
**Approval Type:** Municipal and Private Sewage Works
**Status:** Approved
**Application Type:**
**Client Name:**
**Client Address:**
**Client City:**
**Client Postal Code:**
**Project Description:**
**Contaminants:**
**Emission Control:**

| | | | | | |
|---|---|---|---|---|---|
| 34 | 2 of 8 | SSW/129.1 | 74.6 / 0.69 | **1384274 Ontario Inc.**<br>**330 Gilmour St Ward 14**<br>**Ottawa ON K2E 1A9** | ECA |

**Approval No:** 9606-88TP5T
**Approval Date:** 2010-08-31
**Status:** Approved
**Record Type:** ECA
**Link Source:** IDS
**SWP Area Name:** Rideau Valley
**MOE District:** Ottawa
**City:**
**Longitude:** -75.69231
**Latitude:** 45.415024
**Geometry X:**
**Geometry Y:**
**Approval Type:** ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
**Project Type:** MUNICIPAL AND PRIVATE SEWAGE WORKS
**Business Name:** 1384274 Ontario Inc.
**Address:** 330 Gilmour St Ward 14
**Full Address:**
**Full PDF Link:** https://www.accessenvironment.ene.gov.on.ca/instruments/2911-843PWJ-14.pdf
**PDF Site Location:**

| | | | | | |
|---|---|---|---|---|---|
| 34 | 3 of 8 | SSW/129.1 | 74.6 / 0.69 | **OTTAWA BOARD OF EDUCATION**<br>**330 GILMOUR STREET**<br>**OTTAWA ON K2P 2P6** | GEN |

***Generator Info***

**Generator No:** ON0375206
**Approval Years:** 86,87,88,89,90
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** EXEMPT
**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 0008

| | | | | | |
|---|---|---|---|---|---|
| 34 | 4 of 8 | SSW/129.1 | 74.6 / 0.69 | **OTTAWA BOARD OF EDUCATION 29-129**<br>**330 GILMOUR STREET**<br>**OTTAWA ON K2P 2P6** | GEN |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0375206 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 92,93,94 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 0008 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | EXEMPT | | |

---

**34** ***5 of 8*** ***SSW/129.1*** ***74.6 / 0.69*** ***OTTAWA BOARD OF EDUCATION*** ***GEN***
***ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.***
***OTTAWA ON K2P 0P9***

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0375222 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 86,87,88,89 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 8511 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | ELEMT./SECON. EDUC. | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 263 |
| ***Waste Class Name:*** | ORGANIC LABORATORY CHEMICALS |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 148 |
| ***Waste Class Name:*** | INORGANIC LABORATORY CHEMICALS |

---

**34** ***6 of 8*** ***SSW/129.1*** ***74.6 / 0.69*** ***OTTAWA (SEE&USE ON1285703)*** ***GEN***
***ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.***
***OTTAWA ON K2P 0P9***

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0375222 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 90 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 8511 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | ELEMT./SECON. EDUC. | | |

---

**34** ***7 of 8*** ***SSW/129.1*** ***74.6 / 0.69*** ***OTTAWA (SEE&USE ON1285703) 29-129*** ***GEN***
***ECOLE S. CHARLEBOIS, 2525, PROM. ALTA VISTA, C/O 330 GILMOUR ST.***

***OTTAWA ON K2P 0P9***

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0375222 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 92,93,94,95,96,97 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 8511 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | ELEMT./SECON. EDUC. | | |

**34** ***8 of 8*** ***SSW/129.1*** ***74.6 / 0.69*** ***1384274 Ontario Incorporated*** ***RSC***
***330 GILMOUR ST ON***
***OTTAWA ON***

| | | | |
|---|---|---|---|
| ***RSC No:*** | 59510 | ***X:*** | -75.69221701209165 |
| ***RA No:*** | | ***Y:*** | 45.41499687236812 |
| ***Status:*** | FILED | ***Latitude:*** | 45.41499687 |
| ***Filing Date:*** | | ***Longitude:*** | -75.69221701 |
| ***Date Ack:*** | | ***UTM Coordinates:*** | |
| ***Date Returned:*** | | ***Latitude Longitude:*** | |
| ***Approval Date:*** | September 3, 2009 | ***Accuracy Estimate:*** | |
| ***Cert Date:*** | | ***Measurement Method:*** | |
| ***Cert Prop Use No:*** | | ***Mailing Address:*** | |
| ***Curr Property Use:*** | | ***Telephone:*** | |
| ***Intended Prop Use:*** | | ***Fax:*** | |
| ***Restoration Type:*** | | ***Email:*** | |
| ***Soil Type:*** | | ***Postal Code:*** | K2P 2P6 |
| ***Criteria:*** | | ***Ministry District:*** | |
| ***Stratified (Y/N):*** | | ***MOE District:*** | Ottawa |
| ***Audit (Y/N):*** | | ***SWP Area Name:*** | Rideau Valley |
| ***Entire Leg Prop. (Y/N):*** | | ***Qual Person Name:*** | Mark S D'Arcy |
| ***CPU Issu Sect 1686:*** | | ***Consultant:*** | |
| ***Business Name:*** | 1384274 Ontario Incorporated | | |
| ***Address:*** | 330 GILMOUR ST ON | | |
| ***Legal Desc:*** | | | |
| ***Site Pin:*** | 04118-0064 LT | | |
| ***Asmt Roll No:*** | | | |
| ***Project Type:*** | PRE2011 | | |
| ***Approval Type:*** | RSC based on Phase One ESA | | |
| ***Applicable Standards:*** | | | |
| ***PDF Link:*** | https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=59510 | | |

**35** ***1 of 1*** ***N/129.6*** ***73.9 / 0.00*** ***BRONSON RD AND RAVEN*** ***WWIS***
***Ottawa ON***

| | | | |
|---|---|---|---|
| ***Well ID:*** | 7337489 | ***Flowing (Y/N):*** | |
| ***Construction Date:*** | | ***Flow Rate:*** | |
| ***Use 1st:*** | Test Hole | ***Data Entry Status:*** | |
| ***Use 2nd:*** | Monitoring | ***Data Src:*** | |
| ***Final Well Status:*** | Observation Wells | ***Date Received:*** | 06/14/2019 |
| ***Water Type:*** | | ***Selected Flag:*** | TRUE |
| ***Casing Material:*** | | ***Abandonment Rec:*** | |
| ***Audit No:*** | Z311181 | ***Contractor:*** | 7241 |
| ***Tag:*** | A265336 | ***Form Version:*** | 7 |
| ***Constructn Method:*** | | ***Owner:*** | |
| ***Elevation (m):*** | | ***County:*** | OTTAWA-CARLETON |
| ***Elevatn Reliabilty:*** | | ***Lot:*** | |
| ***Depth to Bedrock:*** | | ***Concession:*** | |

| | | | |
|---|---|---|---|
| ***Well Depth:*** | | ***Concession Name:*** | |
| ***Overburden/Bedrock:*** | | ***Easting NAD83:*** | |
| ***Pump Rate:*** | | ***Northing NAD83:*** | |
| ***Static Water Level:*** | | ***Zone:*** | |
| ***Clear/Cloudy:*** | | ***UTM Reliability:*** | |
| ***Municipality:*** | OTTAWA CITY | | |
| ***Site Info:*** | | | |

***PDF URL (Map):*** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7337489.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| ***Well Completed Date:*** | 03/27/2019 |
| ***Year Completed:*** | 2019 |
| ***Depth (m):*** | 4.88 |
| ***Latitude:*** | 45.417083698293 |
| ***Longitude:*** | -75.6924597860351 |
| ***Point X:*** | -75.6924596240478 |
| ***Point Y:*** | 45.4170836913987 |
| ***Path:*** | 733\7337489.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1007526053 | ***Elevation:*** | |
| ***DP2BR:*** | | ***Elevrc:*** | |
| ***Spatial Status:*** | | ***Zone:*** | 18 |
| ***Code OB:*** | | ***East83:*** | 445821.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029518.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 4 |
| ***Date Completed:*** | 03/27/2019 | ***UTMRC Desc:*** | margin of error : 30 m - 100 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1008015434 |
| ***Layer:*** | 2 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 05 |
| ***Material 1 Desc:*** | CLAY |
| ***Material 2:*** | 06 |
| ***Material 2 Desc:*** | SILT |
| ***Material 3:*** | 73 |
| ***Material 3 Desc:*** | HARD |
| ***Formation Top Depth:*** | 1.5 |
| ***Formation End Depth:*** | 4.880000114440918 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1008015433 |
| ***Layer:*** | 1 |

| | |
|---|---|
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 02 |
| ***Material 1 Desc:*** | TOPSOIL |
| ***Material 2:*** | 12 |
| ***Material 2 Desc:*** | STONES |
| ***Material 3:*** | 77 |
| ***Material 3 Desc:*** | LOOSE |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 1.5 |
| ***Formation End Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1008016368 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 0.6100000143051147 |
| ***Plug Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1008016369 |
| ***Layer:*** | 2 |
| ***Plug From:*** | 0.6100000143051147 |
| ***Plug To:*** | 3.0999999046325684 |
| ***Plug Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1008016370 |
| ***Layer:*** | 3 |
| ***Plug From:*** | 3.0999999046325684 |
| ***Plug To:*** | 4.880000114440918 |
| ***Plug Depth UOM:*** | m |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1008017310 |
| ***Method Construction Code:*** | B |
| ***Method Construction:*** | Other Method |
| ***Other Method Construction:*** | D.P. |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1008014126 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 1008017861 |
| ***Layer:*** | 1 |
| ***Material:*** | 5 |
| ***Open Hole or Material:*** | PLASTIC |
| ***Depth From:*** | 0.0 |

| | |
|---|---|
| ***Depth To:*** | 3.3499999046325684 |
| ***Casing Diameter:*** | 4.03000020980835 |
| ***Casing Diameter UOM:*** | cm |
| ***Casing Depth UOM:*** | m |

***Construction Record - Screen***

| | |
|---|---|
| ***Screen ID:*** | 1008018198 |
| ***Layer:*** | 1 |
| ***Slot:*** | 10 |
| ***Screen Top Depth:*** | 3.3499999046325684 |
| ***Screen End Depth:*** | 4.880000114440918 |
| ***Screen Material:*** | 5 |
| ***Screen Depth UOM:*** | m |
| ***Screen Diameter UOM:*** | cm |
| ***Screen Diameter:*** | 4.820000171661377 |

***Results of Well Yield Testing***

| | |
|---|---|
| ***Pumping Test Method Desc:*** | |
| ***Pump Test ID:*** | 1008018797 |
| ***Pump Set At:*** | |
| ***Static Level:*** | |
| ***Final Level After Pumping:*** | |
| ***Recommended Pump Depth:*** | |
| ***Pumping Rate:*** | |
| ***Flowing Rate:*** | |
| ***Recommended Pump Rate:*** | |
| ***Levels UOM:*** | m |
| ***Rate UOM:*** | LPM |
| ***Water State After Test Code:*** | |
| ***Water State After Test:*** | |
| ***Pumping Test Method:*** | 0 |
| ***Pumping Duration HR:*** | |
| ***Pumping Duration MIN:*** | |
| ***Flowing:*** | No |

***Hole Diameter***

| | |
|---|---|
| ***Hole ID:*** | 1008017007 |
| ***Diameter:*** | 8.300000190734863 |
| ***Depth From:*** | 0.0 |
| ***Depth To:*** | 4.880000114440918 |
| ***Hole Depth UOM:*** | m |
| ***Hole Diameter UOM:*** | cm |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 36 | *1 of 1* | *SW/130.4* | *74.9 / 1.00* | ***OTTAWA CITY - BANK STREET GILMOUR ST./O'CONNOR ST. OTTAWA CITY ON*** | *CA* |

| | |
|---|---|
| ***Certificate #:*** | 3-0369-91- |
| ***Application Year:*** | 91 |
| ***Issue Date:*** | 4/16/1991 |
| ***Approval Type:*** | Municipal sewage |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |

**Emission Control:**

---

**37** **1 of 1** **WNW/134.7** **74.9 / 1.00** **ON** **BORE**

| | | | |
|---|---|---|---|
| **Borehole ID:** | 613299 | **Inclin FLG:** | No |
| **OGF ID:** | 215514600 | **SP Status:** | Initial Entry |
| **Status:** | | **Surv Elev:** | No |
| **Type:** | Borehole | **Piezometer:** | No |
| **Use:** | | **Primary Name:** | |
| **Completion Date:** | SEP-1933 | **Municipality:** | |
| **Static Water Level:** | 10.3 | **Lot:** | |
| **Primary Water Use:** | | **Township:** | |
| **Sec. Water Use:** | | **Latitude DD:** | 45.416483 |
| **Total Depth m:** | -999 | **Longitude DD:** | -75.693862 |
| **Depth Ref:** | Ground Surface | **UTM Zone:** | 18 |
| **Depth Elev:** | | **Easting:** | 445711 |
| **Drill Method:** | | **Northing:** | 5029452 |
| **Orig Ground Elev m:** | 71.3 | **Location Accuracy:** | |
| **Elev Reliabil Note:** | | **Accuracy:** | Not Applicable |
| **DEM Ground Elev m:** | 72.1 | | |
| **Concession:** | | | |
| **Location D:** | | | |
| **Survey D:** | | | |
| **Comments:** | | | |

***Borehole Geology Stratum***

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394567 | **Mat Consistency:** | Compact |
| **Top Depth:** | 3.4 | **Material Moisture:** | |
| **Bottom Depth:** | | **Material Texture:** | |
| **Material Color:** | Grey | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |

**Stratum Description:** CLAY. SOFT. SOFT. CLAY. GREY,FIRM. CLAY. GREY,FIRM. TILL. COMPACT. BEDROCK. FOSSILIFER
**Note: Many records provided by the department have a truncated [Stratum Description] field.

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394565 | **Mat Consistency:** | |
| **Top Depth:** | 0 | **Material Moisture:** | |
| **Bottom Depth:** | 1.5 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Sand | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |

**Stratum Description:** SAND.

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394566 | **Mat Consistency:** | Firm |
| **Top Depth:** | 1.5 | **Material Moisture:** | |
| **Bottom Depth:** | 3.4 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |

**Stratum Description:** CLAY. FIRM.

***Source***

| | | | |
|---|---|---|---|
| ***Source Type:*** | Data Survey | ***Source Appl:*** | Spatial/Tabular |
| ***Source Orig:*** | Geological Survey of Canada | ***Source Iden:*** | 1 |
| ***Source Date:*** | 1956-1972 | ***Scale or Res:*** | Varies |
| ***Confidence:*** | H | ***Horizontal:*** | NAD27 |
| ***Observatio:*** | | ***Verticalda:*** | Mean Average Sea Level |

***Source Name:*** Urban Geology Automated Information System (UGAIS)
***Source Details:*** File: OTTAWA2.txt RecordID: 058070 NTS_Sheet: 31G05G
***Confiden 1:*** Logged by professional. Exact and complete description of material and properties.

***Source List***

| | | | |
|---|---|---|---|
| ***Source Identifier:*** | 1 | ***Horizontal Datum:*** | NAD27 |
| ***Source Type:*** | Data Survey | ***Vertical Datum:*** | Mean Average Sea Level |
| ***Source Date:*** | 1956-1972 | ***Projection Name:*** | Universal Transverse Mercator |
| ***Scale or Resolution:*** | Varies | | |

***Source Name:*** Urban Geology Automated Information System (UGAIS)
***Source Originators:*** Geological Survey of Canada

---

**38** ***1 of 1*** ***NNW/134.8*** ***74.9 / 1.00*** ***ON*** ***WWIS***

| | | | |
|---|---|---|---|
| ***Well ID:*** | 7211111 | ***Flowing (Y/N):*** | |
| ***Construction Date:*** | | ***Flow Rate:*** | |
| ***Use 1st:*** | Monitoring | ***Data Entry Status:*** | |
| ***Use 2nd:*** | | ***Data Src:*** | |
| ***Final Well Status:*** | Abandoned-Other | ***Date Received:*** | 11/14/2013 |
| ***Water Type:*** | | ***Selected Flag:*** | TRUE |
| ***Casing Material:*** | | ***Abandonment Rec:*** | Yes |
| ***Audit No:*** | Z096855 | ***Contractor:*** | 6894 |
| ***Tag:*** | A152336 | ***Form Version:*** | 7 |
| ***Constructn Method:*** | | ***Owner:*** | |
| ***Elevation (m):*** | | ***County:*** | OTTAWA-CARLETON |
| ***Elevatn Reliabilty:*** | | ***Lot:*** | |
| ***Depth to Bedrock:*** | | ***Concession:*** | |
| ***Well Depth:*** | | ***Concession Name:*** | |
| ***Overburden/Bedrock:*** | | ***Easting NAD83:*** | |
| ***Pump Rate:*** | | ***Northing NAD83:*** | |
| ***Static Water Level:*** | | ***Zone:*** | |
| ***Clear/Cloudy:*** | | ***UTM Reliability:*** | |

***Municipality:*** OTTAWA CITY
***Site Info:***

***PDF URL (Map):*** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7211111.pdf

***Additional Detail(s) (Map)***

***Well Completed Date:***
***Year Completed:***
***Depth (m):***
***Latitude:*** 45.4170906839424
***Longitude:*** -75.6927921767053
***Point X:*** -75.69279201496512
***Point Y:*** 45.41709067742938
***Path:*** 721\7211111.pdf

***Bore Hole Information***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1004633147 | ***Elevation:*** | |
| ***DP2BR:*** | | ***Elevrc:*** | |
| ***Spatial Status:*** | | ***Zone:*** | 18 |

| | | | |
|---|---|---|---|
| ***Code OB:*** | | ***East83:*** | 445795.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029519.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 3 |
| ***Date Completed:*** | | ***UTMRC Desc:*** | margin of error : 10 - 30 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1004895728 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 57.0 |
| ***Plug To:*** | 0.0 |
| ***Plug Depth UOM:*** | ft |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1004895727 |
| ***Method Construction Code:*** | |
| ***Method Construction:*** | |
| ***Other Method Construction:*** | |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1004895720 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 1004895724 |
| ***Layer:*** | |
| ***Material:*** | |
| ***Open Hole or Material:*** | |
| ***Depth From:*** | |
| ***Depth To:*** | |
| ***Casing Diameter:*** | |
| ***Casing Diameter UOM:*** | inch |
| ***Casing Depth UOM:*** | ft |

***Construction Record - Screen***

| | |
|---|---|
| ***Screen ID:*** | 1004895725 |
| ***Layer:*** | |
| ***Slot:*** | |
| ***Screen Top Depth:*** | |
| ***Screen End Depth:*** | |
| ***Screen Material:*** | |
| ***Screen Depth UOM:*** | ft |
| ***Screen Diameter UOM:*** | inch |
| ***Screen Diameter:*** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Water Details***

| | |
|---|---|
| ***Water ID:*** | 1004895723 |
| ***Layer:*** | |
| ***Kind Code:*** | |
| ***Kind:*** | |
| ***Water Found Depth:*** | |
| ***Water Found Depth UOM:*** | ft |

***Hole Diameter***

| | |
|---|---|
| ***Hole ID:*** | 1004895722 |
| ***Diameter:*** | |
| ***Depth From:*** | |
| ***Depth To:*** | |
| ***Hole Depth UOM:*** | ft |
| ***Hole Diameter UOM:*** | inch |

---

| | | | | | |
|---|---|---|---|---|---|
| **39** | ***1 of 2*** | ***NNE/137.8*** | ***73.9 / 0.00*** | ***OCSCC # 1049***<br>***222 Somerset St. West***<br>***Ottawa ON K2P 0A7*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON5718475 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Nov 2021 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 331 I |
| ***Waste Class Name:*** | Waste compressed gases including cylinders |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 145 B |
| ***Waste Class Name:*** | Wastes from the use of pigments, coatings and paints |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 145 L |
| ***Waste Class Name:*** | Wastes from the use of pigments, coatings and paints |

***2021 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON5718475 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 22898 | ***Phone No Official:*** | 613-410-3760 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-237-2425 Ext.202 |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 531310 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | OCSCC # 1049 | | |

**Gen Div:** The Properties Group
**Gen Op Name:** OCSCC #1049
**Gen Op Div:**
**Site Adrs1:** 222 Somerset St. West
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 0A7
**Site Country:** Canada
**Co Official:** Alexander J Robichaud
**Co Admin:** David Romano

***2021 Generator Manifest***

**ID:** 45273
**Generator No:** ON5718475
**Receiver Type:** 030
**Waste Char:** L
**Waste Code:** 145
**Sum Received Qty:** 615.0
**Waste Class Name:** PAINT/PIGMENT/COATING RESIDUES
**Count Manifests:** 1
**District:** 402

***2021 Generator Manifest***

**ID:** 45274
**Generator No:** ON5718475
**Receiver Type:** 030
**Waste Char:** I
**Waste Code:** 331
**Sum Received Qty:** 205.0
**Waste Class Name:** WASTE COMPRESSED GASES
**Count Manifests:** 1
**District:** 402

---

**39** | **2 of 2** | **NNE/137.8** | **73.9 / 0.00** | **Air Force Productions Ltd.**
**222 Somerset St W**
**Ottawa ON K2P 2G3** | **SCT**

**Scott S ID:** 35772880
**Latitude:**
**Longitude:**

***Historical Details***

**Established:**
**Plant Size (ft²):**
**Employment:**

***Historical Details***

**Description:** Social Advocacy Organizations
**SIC/NAICS Code:** 813310

---

**40** | **1 of 2** | **ENE/139.3** | **72.8 / -1.06** | **222 MacLaren Street**
**Ottawa ON K2P 0L8** | **EHS**

**Order No:** 20070326023
**Status:** C
**Report Type:** CAN - Custom Report
**Report Date:** 4/4/2007
**Date Received:** 3/26/2007
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps And /or Site Plans
**Nearest Intersection:**
**Municipality:**
**Client Prov/State:**
**Search Radius (km):** 0.25
**X:** -75.690804
**Y:** 45.416485

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 40 | 2 of 2 | ENE/139.3 | 72.8 / -1.06 | 222 Maclaren St<br>Ottawa ON K2P0L8 | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 20150130070 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 05-FEB-15 | **Search Radius (km):** | .25 |
| **Date Received:** | 30-JAN-15 | **X:** | -75.690861 |
| **Previous Site Name:** | | **Y:** | 45.416534 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 41 | 1 of 1 | N/143.1 | 73.8 / -0.08 | Timbercreek Communities<br>222 Metcalfe St<br>Ottawa ON K2P 1R2 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON9300860 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2016 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 531111 |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS (EXCEPT SOCIAL HOUSING PROJECTS) | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 221 |
| **Waste Class Name:** | LIGHT FUELS |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 42 | 1 of 1 | W/144.2 | 75.7 / 1.85 | 250 O'Connor Street<br>Ottawa ON K2P 1V2 | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 25052700582 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 30-MAY-25 | **Search Radius (km):** | .25 |
| **Date Received:** | 27-MAY-25 | **X:** | -75.6941431 |
| **Previous Site Name:** | | **Y:** | 45.4156631 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans; City Directory | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 43 | 1 of 1 | S/146.3 | 73.8 / -0.03 | Carleton Condominium Corporation 251<br>420 Lewis Street<br>Ottawa ON K2P 0S9 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON4976215 | **Choice of Contact:** | |
| **Approval Years:** | As of Dec 2018 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |

**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

***Waste Detail(s)***

**Waste Class:** 252 I
**Waste Class Name:** Waste crankcase oils and lubricants

***2018 Generator Info***

**Gen No:** ON4976215
**ID:** 19834
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 531310
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Carleton Condominium Corporation 251
**Gen Div:**
**Gen Op Name:** CCC251
**Gen Op Div:**
**Site Adrs1:** 420 Lewis Street
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 0S9
**Site Country:** Canada
**Co Official:** Eileen Boles
**Co Admin:** Tammy Zollinger
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 6132379519 Ext.313
**Phone No Admin:** 613.237.9519 Ext.370
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2018 Generator Manifest***

**ID:** 43630
**Generator No:** ON4976215
**Receiver Type:** 035
**Waste Char:** L
**Waste Code:** 251
**Sum Received Qty:** 5500.0
**Waste Class Name:** OIL SKIMMINGS & SLUDGES
**Count Manifests:** 2
**District:** 402

---

**44** | ***1 of 1*** | ***NNE/147.6*** | ***73.9 / 0.00*** | ***GTA'S Finest Restoration*** ***236 Somerset*** ***Ottawa ON K2P0J4*** | ***GEN***

***Generator Info***

**Generator No:** ON4278311
**Approval Years:** As of Dec 2018
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**
**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** Pathological wastes

***2018 Generator Info***

**Gen No:** ON4278311
**ID:** 17061
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 562910
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** GTA'S Finest Restoration
**Gen Div:**
**Gen Op Name:** GTA'S Finest Restoration
**Gen Op Div:**
**Site Adrs1:** 236 Somerset
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P0J4
**Site Country:** Canada
**Co Official:** Benoit Rochon
**Co Admin:** Veronique Benson

**Choice of Contact:** CO_ADMIN
**Phone No Official:** 6132946351 Ext.
**Phone No Admin:** 6132989215 Ext.
**County Ont:** PRESCOTT & RUSSELL
**County Out:**
**District:** 403

---

**45** | ***1 of 1*** | ***SW/148.0*** | ***74.9 / 1.00*** | ***278-280 O'Connor St and 347 Gilmour St Ottawa ON K2P 1V4*** | ***EHS***

**Order No:** 20191112287
**Status:** C
**Report Type:** Standard Report
**Report Date:** 15-NOV-19
**Date Received:** 12-NOV-19
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.693682
**Y:** 45.414984

---

**46** | ***1 of 1*** | ***N/148.4*** | ***73.9 / 0.00*** | ***1578051 Ontario Inc.<br>237 Somerset Street West<br>Ottawa ON K2P 0J3*** | ***PTTW***

**EBR Registry No:** 011-6245
**Ministry Ref No:** 8482-8TEKE3
**Notice Type:** Instrument Proposal
**Section:**
**Notice Stage:**
**Act 1:**
**Act 2:**
**Site Location Map:**
**Instrument Type:** (OWRA s. 34) - Permit to take water
**Off Instrument Name:**
**Posted By:**
**Company Name:**
**Site Address:**
**Location Other:**
**Proponent Name:**
**Proponent Address:** 237 Somerset Street West Ottawa Ontario Canada K2P 0J3
**Comment Period:**
**URL:**

**Decision Posted:**
**Exception Posted:**
**Bulletin Posted:**
**Appeal Posted:**
**Notice Date:**
**Proposal Date:** May 01, 2012
**Year:** 2012

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Summary:***

***Site Location Details:***

237 Somerset Street West, Ottawa, Ontario CITY OF OTTAWA

---

**47** | ***1 of 1*** | ***SW/150.1*** | ***74.9 / 1.00*** | ***AK Global Management Inc***
***280-282 O'Connor Street***
***Ottawa ON K2P 1V4*** | ***GEN***

***2019 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6234416 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 25011 | ***Phone No Official:*** | 613-983-2290 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 561799 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | AK Global Management Inc | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | AK Global Management Inc | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 280-282 O'Connor Street | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1V4 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | Tony Kazarian | | |
| ***Co Admin:*** | | | |

***2019 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 49632 | ***Sum Received Qty:*** | 650.0 |
| ***Generator No:*** | ON6234416 | ***Waste Class Name:*** | LIGHT FUELS |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | I | ***District:*** | 402 |
| ***Waste Code:*** | 221 | | |

---

**48** | ***1 of 1*** | ***N/156.1*** | ***73.9 / 0.00*** | ***TAGGART CORPORATION***
***235 SOMERSET STREET WEST***
***OTTAWA ON K2P 0J3*** | ***GEN***

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON2565000 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 00,01,02,03,04 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 9959 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | OTHER SERV. TO BLDG. | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Detail(s)***

***Waste Class:*** 243
***Waste Class Name:*** PCB'S

---

**49** | ***1 of 1*** | ***W/156.9*** | ***75.9 / 2.00*** | ***331 Maclaren St Ottawa ON K2P0M4*** | ***EHS***

***Order No:*** 20171030040
***Status:*** C
***Report Type:*** Standard Report
***Report Date:*** 02-NOV-17
***Date Received:*** 30-OCT-17
***Previous Site Name:***
***Lot/Building Size:*** 0.32 acres
***Additional Info Ordered:***

***Nearest Intersection:***
***Municipality:*** Ottawa
***Client Prov/State:*** ON
***Search Radius (km):*** .25
***X:*** -75.694272
***Y:*** 45.415551

---

**50** | ***1 of 1*** | ***E/158.0*** | ***72.9 / -1.00*** | ***246 Gilmour St Ottawa ON K2P 0P6*** | ***EHS***

***Order No:*** 20200206181
***Status:*** C
***Report Type:*** Standard Report
***Report Date:*** 11-FEB-20
***Date Received:*** 06-FEB-20
***Previous Site Name:***
***Lot/Building Size:*** 4291 Ft2
***Additional Info Ordered:***

***Nearest Intersection:***
***Municipality:*** Ottawa
***Client Prov/State:*** ON
***Search Radius (km):*** .25
***X:*** -75.6903236
***Y:*** 45.4158159

---

**51** | ***1 of 10*** | ***S/159.0*** | ***74.6 / 0.69*** | ***David Jordan Medicne Professional Corporation 301 O'Connor St. Ottawa ON K2P 1V6*** | ***GEN***

***Generator Info***

***Generator No:*** ON8141730
***Approval Years:*** 2011
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 621110

---

**51** | ***2 of 10*** | ***S/159.0*** | ***74.6 / 0.69*** | ***David Jordan Medicne Professional Corporation 301 O'Connor St. Ottawa ON K2P 1V6*** | ***GEN***

***Generator Info***

***Generator No:*** ON8141730
***Approval Years:*** 2012
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 621110

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Phone No Admin:** | | | | | |
| **SIC Description:** | | Offices of Physicians | | | |

| | | | | | |
|---|---|---|---|---|---|
| 51 | 3 of 10 | S/159.0 | 74.6 / 0.69 | **David Jordan Medicne Professional Corporation**<br>**301 O'Connor St.**<br>**Ottawa ON** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON8141730 | **Choice of Contact:** | |
| **Approval Years:** | 2013 | **Contaminated Fac:** | |
| **Status:** | | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | 621110 |
| **Country:** | | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | OFFICES OF PHYSICIANS | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 312 |
| **Waste Class Name:** | PATHOLOGICAL WASTES |

| | | | | | |
|---|---|---|---|---|---|
| 51 | 4 of 10 | S/159.0 | 74.6 / 0.69 | **David Jordan Medicne Professional Corporation**<br>**301 O'Connor St.**<br>**Ottawa ON K2P 1V6** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON8141730 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2016 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621110 |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | OFFICES OF PHYSICIANS | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 312 |
| **Waste Class Name:** | PATHOLOGICAL WASTES |

| | | | | | |
|---|---|---|---|---|---|
| 51 | 5 of 10 | S/159.0 | 74.6 / 0.69 | **David Jordan Medicne Professional Corporation**<br>**301 O'Connor St.**<br>**Ottawa ON K2P 1V6** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON8141730 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2015 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621110 |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **SIC Description:** | | OFFICES OF PHYSICIANS | | | |

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| | | | | | |
|---|---|---|---|---|---|
| 51 | 6 of 10 | S/159.0 | 74.6 / 0.69 | **David Jordan Medicne Professional Corporation**<br>**301 O'Connor St.**<br>**Ottawa ON K2P 1V6** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON8141730 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2014 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 621110 |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | OFFICES OF PHYSICIANS | | |

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| | | | | | |
|---|---|---|---|---|---|
| 51 | 7 of 10 | S/159.0 | 74.6 / 0.69 | **David Jordan Medicne Professional Corporation**<br>**301 O'Connor St.**<br>**Ottawa ON K2P 1V6** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON8141730 | **Choice of Contact:** | |
| **Approval Years:** | As of Dec 2018 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | | | |

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** Pathological wastes

---

| | | | | | |
|---|---|---|---|---|---|
| 51 | 8 of 10 | S/159.0 | 74.6 / 0.69 | **David Jordan Medicne Professional Corporation**<br>**301 O'Connor St.**<br>**Ottawa ON K2P 1V6** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON8141730 | **Choice of Contact:** | |
| **Approval Years:** | As of Jul 2020 | **Contaminated Fac:** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 51 | 9 of 10 | S/159.0 | 74.6 / 0.69 | David Jordan Medicne Professional Corporation<br>301 O'Connor St.<br>Ottawa ON K2P 1V6 | GEN |

***Generator Info***

***Generator No:*** ON8141730
***Approval Years:*** As of Nov 2021
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***
***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 51 | 10 of 10 | S/159.0 | 74.6 / 0.69 | David Jordan Medicine Professional Corporation<br>301 O'Connor St.<br>Ottawa ON | GEN |

***Generator Info***

***Generator No:*** ON8141730
***Approval Years:*** As of Oct 2022
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***
***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** PATHOLOGICAL WASTES

***Generator Info (as of Dec 2024)***

***Generator No:*** ON8141730
***Generator Company Name:*** David Jordan Medicine Professional Corporation
***Street:*** 301 O'Connor St.

***City:*** Ottawa
***Province State:*** Ontario
***Country:*** Canada
***Postal Code:*** K2P1V6
***Waste Class:*** 312 P

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES

***Generator Info (as of Apr 2025)***

***Generator Company Name:*** David Jordan Medicine Professional Corporation
***Generator Site Address:*** 301 O'Connor St.
***City:*** Ottawa
***Province State:*** Ontario
***Country:*** Canada
***Postal Code:*** K2P1V6
***Waste Class:*** 312 P

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES

***Waste Characteristic Decoded:***

P - Pathological

***2017 Generator Info***

***Gen No:*** ON8141730
***ID:*** 31842
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 621110
***NAICS Code2:***
***NAICS Code3:***
***Gen Name:*** David Jordan Medicne Professional Corporation
***Gen Div:***
***Gen Op Name:*** David Jordan Medicne Professional Corporation
***Gen Op Div:***
***Site Adrs1:*** 301 O'Connor St.
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1V6
***Site Country:*** Canada
***Co Official:*** David R Jordan
***Co Admin:***
***Choice of Contact:*** CO_OFFICIAL
***Phone No Official:*** 613 563 3800 Ext.
***Phone No Admin:***
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402

***2017 Generator Manifest***

***ID:*** 59287
***Generator No:*** ON8141730
***Receiver Type:*** 030
***Waste Char:*** P
***Waste Code:*** 312
***Sum Received Qty:*** 53.6
***Waste Class Name:*** PATHOLOGICAL WASTES
***Count Manifests:*** 13
***District:*** 402

***2018 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON8141730 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 32445 | ***Phone No Official:*** | 613 563 3800 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |

| | |
|---|---|
| ***Gen Name:*** | David Jordan Medicne Professional Corporation |
| ***Gen Div:*** | |
| ***Gen Op Name:*** | David Jordan Medicne Professional Corporation |
| ***Gen Op Div:*** | |
| ***Site Adrs1:*** | 301 O'Connor St. |
| ***Site Bldg:*** | |
| ***Site Pobox:*** | |
| ***Province In:*** | ONTARIO |
| ***Site Adrs2:*** | |
| ***Site City:*** | Ottawa |
| ***Province Out:*** | |
| ***Site Postal Code:*** | K2P 1V6 |
| ***Site Country:*** | Canada |
| ***Co Official:*** | David R Jordan |
| ***Co Admin:*** | |

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 59534 | ***Sum Received Qty:*** | 51.3 |
| ***Generator No:*** | ON8141730 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 12 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 59533 | ***Sum Received Qty:*** | 6.4 |
| ***Generator No:*** | ON8141730 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | P | ***District:*** | 305 |
| ***Waste Code:*** | 312 | | |

***2019 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON8141730 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 32822 | ***Phone No Official:*** | 613 563 3800 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |

| | |
|---|---|
| ***Gen Name:*** | David Jordan Medicne Professional Corporation |
| ***Gen Div:*** | |
| ***Gen Op Name:*** | David Jordan Medicne Professional Corporation |
| ***Gen Op Div:*** | |
| ***Site Adrs1:*** | 301 O'Connor St. |
| ***Site Bldg:*** | |
| ***Site Pobox:*** | |
| ***Province In:*** | ONTARIO |
| ***Site Adrs2:*** | |
| ***Site City:*** | Ottawa |
| ***Province Out:*** | |

**Site Postal Code:** K2P 1V6
**Site Country:** Canada
**Co Official:** David R Jordan
**Co Admin:**

***2019 Generator Manifest***

**ID:** 59520
**Generator No:** ON8141730
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 52.0
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 13
**District:** 402

***2020 Generator Info***

**Gen No:** ON8141730
**ID:** 32540
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** David Jordan Medicne Professional Corporation
**Gen Div:**
**Gen Op Name:** David Jordan Medicne Professional Corporation
**Gen Op Div:**
**Site Adrs1:** 301 O'Connor St.
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1V6
**Site Country:** Canada
**Co Official:** David R Jordan
**Co Admin:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 613 563 3800 Ext.
**Phone No Admin:**
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2020 Generator Manifest***

**ID:** 55801
**Generator No:** ON8141730
**Receiver Type:** 035
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 9.6
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 1
**District:** 305

***2020 Generator Manifest***

**ID:** 55802
**Generator No:** ON8141730
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 43.96
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 11
**District:** 402

***2021 Generator Info***

**Gen No:** ON8141730
**ID:** 33300
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621110
**NAICS Code2:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 613 563 3800 Ext.
**Phone No Admin:**
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

| | |
|---|---|
| **NAICS Code3:** | |
| **Gen Name:** | David Jordan Medicne Professional Corporation |
| **Gen Div:** | |
| **Gen Op Name:** | David Jordan Medicne Professional Corporation |
| **Gen Op Div:** | |
| **Site Adrs1:** | 301 O'Connor St. |
| **Site Bldg:** | |
| **Site Pobox:** | |
| **Province In:** | ONTARIO |
| **Site Adrs2:** | |
| **Site City:** | Ottawa |
| **Province Out:** | |
| **Site Postal Code:** | K2P 1V6 |
| **Site Country:** | Canada |
| **Co Official:** | David R Jordan |
| **Co Admin:** | |

***2021 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 58094 | **Sum Received Qty:** | 53.8 |
| **Generator No:** | ON8141730 | **Waste Class Name:** | PATHOLOGICAL WASTES |
| **Receiver Type:** | 030 | **Count Manifests:** | 13 |
| **Waste Char:** | P | **District:** | 402 |
| **Waste Code:** | 312 | | |

---

**52** ***1 of 1*** ***W/161.0*** ***75.9 / 2.01*** ***ON*** ***BORE***

| | | | |
|---|---|---|---|
| **Borehole ID:** | 613289 | **Inclin FLG:** | No |
| **OGF ID:** | 215514590 | **SP Status:** | Initial Entry |
| **Status:** | | **Surv Elev:** | No |
| **Type:** | Borehole | **Piezometer:** | No |
| **Use:** | | **Primary Name:** | |
| **Completion Date:** | JAN-1973 | **Municipality:** | |
| **Static Water Level:** | | **Lot:** | |
| **Primary Water Use:** | | **Township:** | |
| **Sec. Water Use:** | | **Latitude DD:** | 45.41567 |
| **Total Depth m:** | 15.5 | **Longitude DD:** | -75.694364 |
| **Depth Ref:** | Ground Surface | **UTM Zone:** | 18 |
| **Depth Elev:** | | **Easting:** | 445671 |
| **Drill Method:** | | **Northing:** | 5029362 |
| **Orig Ground Elev m:** | 71.9 | **Location Accuracy:** | |
| **Elev Reliabil Note:** | | **Accuracy:** | Not Applicable |
| **DEM Ground Elev m:** | 72 | | |
| **Concession:** | | | |
| **Location D:** | | | |
| **Survey D:** | | | |
| **Comments:** | | | |

***Borehole Geology Stratum***

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394521 | **Mat Consistency:** | Soft |
| **Top Depth:** | 3.5 | **Material Moisture:** | |
| **Bottom Depth:** | 5.8 | **Material Texture:** | |
| **Material Color:** | Red | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | Silt | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | CLAY. SOFT TO STIFF,FISSURED. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394524 | **Mat Consistency:** | Dense |

**Top Depth:** 14.6
**Bottom Depth:** 15.5
**Material Color:**
**Material 1:** Unknown
**Material 2:**
**Material 3:**
**Material 4:**
**Gsc Material Description:**
**Stratum Description:** UNSPECIFIED. 00050 043 00080 058 00115 062 0000006200050024002 26DENSE. BEDROCK.

**Material Moisture:**
**Material Texture:**
**Non Geo Mat Type:**
**Geologic Formation:**
**Geologic Group:**
**Geologic Period:**
**Depositional Gen:**

**Geology Stratum ID:** 218394522
**Top Depth:** 5.8
**Bottom Depth:** 13.1
**Material Color:**
**Material 1:** Unknown
**Material 2:**
**Material 3:**
**Material 4:**
**Gsc Material Description:**
**Stratum Description:** UNSPECIFIED.

**Mat Consistency:**
**Material Moisture:**
**Material Texture:**
**Non Geo Mat Type:**
**Geologic Formation:**
**Geologic Group:**
**Geologic Period:**
**Depositional Gen:**

**Geology Stratum ID:** 218394519
**Top Depth:** 1.5
**Bottom Depth:** 2.4
**Material Color:** Brown
**Material 1:** Clay
**Material 2:**
**Material 3:**
**Material 4:**
**Gsc Material Description:**
**Stratum Description:** CLAY. BROWN,GREY,HARD.

**Mat Consistency:** Hard
**Material Moisture:**
**Material Texture:**
**Non Geo Mat Type:**
**Geologic Formation:**
**Geologic Group:**
**Geologic Period:**
**Depositional Gen:**

**Geology Stratum ID:** 218394520
**Top Depth:** 2.4
**Bottom Depth:** 3.5
**Material Color:** Brown
**Material 1:** Clay
**Material 2:**
**Material 3:**
**Material 4:**
**Gsc Material Description:**
**Stratum Description:** CLAY. BROWN,GREY, STIFF TO VERY STIFF.

**Mat Consistency:** Stiff
**Material Moisture:**
**Material Texture:**
**Non Geo Mat Type:**
**Geologic Formation:**
**Geologic Group:**
**Geologic Period:**
**Depositional Gen:**

**Geology Stratum ID:** 218394518
**Top Depth:** 0
**Bottom Depth:** 1.5
**Material Color:**
**Material 1:**
**Material 2:** Brick fragments
**Material 3:** Bedrock
**Material 4:** Wood Fragments
**Gsc Material Description:**
**Stratum Description:** ARTIFICIAL.

**Mat Consistency:**
**Material Moisture:**
**Material Texture:**
**Non Geo Mat Type:**
**Geologic Formation:**
**Geologic Group:**
**Geologic Period:**
**Depositional Gen:**

**Geology Stratum ID:** 218394523
**Top Depth:** 13.1
**Bottom Depth:** 14.6
**Material Color:**
**Material 1:** Unknown
**Material 2:**
**Material 3:**
**Material 4:**
**Gsc Material Description:**
**Stratum Description:** UNSPECIFIED.

**Mat Consistency:**
**Material Moisture:**
**Material Texture:**
**Non Geo Mat Type:**
**Geologic Formation:**
**Geologic Group:**
**Geologic Period:**
**Depositional Gen:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Source***

| | | | |
|---|---|---|---|
| ***Source Type:*** | Data Survey | ***Source Appl:*** | Spatial/Tabular |
| ***Source Orig:*** | Geological Survey of Canada | ***Source Iden:*** | 1 |
| ***Source Date:*** | 1956-1972 | ***Scale or Res:*** | Varies |
| ***Confidence:*** | H | ***Horizontal:*** | NAD27 |
| ***Observatio:*** | | ***Verticalda:*** | Mean Average Sea Level |
| ***Source Name:*** | Urban Geology Automated Information System (UGAIS) | | |
| ***Source Details:*** | File: OTTAWA2.txt RecordID: 057970 NTS_Sheet: 31G05G | | |
| ***Confiden 1:*** | Logged by professional. Exact and complete description of material and properties. | | |

***Source List***

| | | | |
|---|---|---|---|
| ***Source Identifier:*** | 1 | ***Horizontal Datum:*** | NAD27 |
| ***Source Type:*** | Data Survey | ***Vertical Datum:*** | Mean Average Sea Level |
| ***Source Date:*** | 1956-1972 | ***Projection Name:*** | Universal Transverse Mercator |
| ***Scale or Resolution:*** | Varies | | |
| ***Source Name:*** | Urban Geology Automated Information System (UGAIS) | | |
| ***Source Originators:*** | Geological Survey of Canada | | |

---

**53** ***1 of 1*** ***ESE/167.4*** ***72.9 / -1.00*** ***301 Metcalfe Street Ottawa ON K2P 1R9*** ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20090218027 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 2/27/2009 | ***Search Radius (km):*** | 0.25 |
| ***Date Received:*** | 2/18/2009 | ***X:*** | -75.690546 |
| ***Previous Site Name:*** | | ***Y:*** | 45.415096 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | Fire Insur. Maps and/or Site Plans | | |

---

**54** ***1 of 1*** ***ESE/168.0*** ***72.9 / -1.00*** ***301 Metcalfe Street Ottawa ON K2P 1R9*** ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 24112100949 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 26-NOV-24 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 21-NOV-24 | ***X:*** | -75.6904453 |
| ***Previous Site Name:*** | | ***Y:*** | 45.415205 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | Fire Insur. Maps and/or Site Plans | | |

---

**55** ***1 of 1*** ***ESE/169.7*** ***72.9 / -1.00*** ***301 Metcalfe St Ottawa ON K2P1R9*** ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20160513018 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 19-MAY-16 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 13-MAY-16 | ***X:*** | -75.690417 |
| ***Previous Site Name:*** | | ***Y:*** | 45.415209 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | | | |

---

**56** ***1 of 2*** ***ENE/171.0*** ***72.9 / -1.00*** ***218 maclaren street ottawa ON K2P 0L7*** ***EHS***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Order No:** | 20060323017 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 3/28/2006 | **Search Radius (km):** | 0.25 |
| **Date Received:** | 3/23/2006 | **X:** | -75.690514 |
| **Previous Site Name:** | | **Y:** | 45.416716 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | |

---

| | | | | | |
|---|---|---|---|---|---|
| 56 | 2 of 2 | ENE/171.0 | 72.9 / -1.00 | 218 MacLaren Street<br>Ottawa ON K2P 0L4 | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 20191128025 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Site Report | **Client Prov/State:** | ON |
| **Report Date:** | 29-NOV-19 | **Search Radius (km):** | .001 |
| **Date Received:** | 28-NOV-19 | **X:** | -75.690421 |
| **Previous Site Name:** | | **Y:** | 45.41666 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

| | | | | | |
|---|---|---|---|---|---|
| 57 | 1 of 1 | NW/172.1 | 74.8 / 0.97 | 318 Cooper St<br>Ottawa ON | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 20130502013 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 09-MAY-13 | **Search Radius (km):** | .25 |
| **Date Received:** | 02-MAY-13 | **X:** | 0 |
| **Previous Site Name:** | | **Y:** | 0 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

| | | | | | |
|---|---|---|---|---|---|
| 58 | 1 of 1 | N/175.5 | 73.9 / 0.00 | Dr George Wehbi Dentist<br>229 Metcalfe St<br>Ottawa ON K2P2C2 | SCT |

| | |
|---|---|
| **Scott S ID:** | 304120429 |
| **Latitude:** | 45.4174604 |
| **Longitude:** | -75.6925301 |

***Details***

| | | | |
|---|---|---|---|
| **Bus Type 1:** | Educational Services | **Employee Count:** | 5 |
| **Bus Type 2:** | Health Services | **Square Footage:** | 0 |
| **Bus Type 3:** | Manufacturer | **Estimated Sales:** | Under $1 Million |
| **Product Cat 1:** | Dentist | **Export Indicator:** | |
| **Product Cat 2:** | | **Export Country 1:** | |
| **Product Cat 3:** | | **Export Country 2:** | |
| **Product Cat 4:** | | **Export Country 3:** | |
| **Product Cat 5:** | | **Export Country 4:** | |
| **Product Cat 6:** | | **Export Country 5:** | |
| **Product Cat 7:** | | **Export Country 6:** | |
| **Product Cat 8:** | | **Geocoded by:** | Address |
| **Company Name:** | Dr George Wehbi Dentist | | |
| **Address Line 1:** | 229 Metcalfe St | | |
| **Address Line 2:** | | | |
| **City:** | Ottawa | | |
| **Province:** | ON | | |
| **Postal Code:** | K2P2C2 | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | |
|---|---|
| **Census Division:** | Ottawa; ON |
| **Metro Area:** | Ottawa/Hull |
| **Year Established:** | |
| **Head Office Indicator:** | |
| **Parent Company Nm:** | |
| **Parent Cmpny Addr 1:** | |
| **Parent Cmpny Addr 2:** | |
| **Parent Cmpny City:** | |
| **Parent Cmpny Prov:** | |
| **Parent Cmpy PC:** | |
| **Parent Cmpy Cntry:** | |
| **Head Office Nm:** | |
| **H Office Addr Line 1:** | |
| **H Office Addr Line 2:** | |
| **Head Office City:** | |
| **Head Office Province:** | |
| **Head Office PC:** | |
| **Head Office Cntry:** | |
| **Telephone:** | 613-232-7880 |
| **Fax:** | |
| **Website:** | http://www.drwehbi.com/ |
| **Pri NAICS Desc:** | 339110-Medical Equipment and Supplies Manufacturing |
| **NAICS Code 1:** | 339110-Medical Equipment and Supplies Manufacturin |
| **NAICS Code 2:** | 611310-Universities |
| **NAICS Code 3:** | 621210-Offices of Dentists |
| **NAICS Code 4:** | 621390-Offices of All Other Health Practitioners |
| **NAICS Code 5:** | |

---

| | | | | | |
|---|---|---|---|---|---|
| 59 | 1 of 2 | NW/175.6 | 74.9 / 1.00 | **PIPELINE HIT 1/2"**<br>**310 COOPER ST,,OTTAWA,ON,K2P 0G7,CA**<br>**ON** | PINC |

| | | | |
|---|---|---|---|
| **Incident Id:** | | **Pipe Material:** | |
| **Incident No:** | 2390424 | **Fuel Category:** | |
| **Incident Reported Dt:** | 9/5/2018 | **Health Impact:** | |
| **Type:** | FS-Pipeline Incident | **Environment Impact:** | |
| **Status Code:** | | **Property Damage:** | |
| **Tank Status:** | Pipeline Damage Reason Est | **Service Interrupt:** | |
| **Task No:** | | **Enforce Policy:** | |
| **Spills Action Centre:** | | **Public Relation:** | |
| **Fuel Type:** | | **Pipeline System:** | |
| **Fuel Occurrence Tp:** | | **PSIG:** | |
| **Date of Occurrence:** | | **Attribute Category:** | |
| **Occurrence Start Dt:** | | **Regulator Location:** | |
| **Depth:** | | **Method Details:** | |
| **Customer Acct Name:** | PIPELINE HIT 1/2" | | |
| **Incident Address:** | 310 COOPER ST,,OTTAWA,ON,K2P 0G7,CA | | |
| **Operation Type:** | | | |
| **Pipeline Type:** | | | |
| **Regulator Type:** | | | |
| **Summary:** | | | |
| **Reported By:** | | | |
| **Affiliation:** | | | |
| **Occurrence Desc:** | | | |
| **Damage Reason:** | | | |
| **Notes:** | | | |

---

| | | | | | |
|---|---|---|---|---|---|
| 59 | 2 of 2 | NW/175.6 | 74.9 / 1.00 | **Enbridge Gas Distribution Inc.**<br>**310 Cooper St.**<br>**Ottawa ON** | SPL |

| | | | |
|---|---|---|---|
| **Ref No:** | 4103-B4AJEM | **Municipality No:** | |
| **Year:** | | **Nature of Damage:** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Incident Dt:** | 2018/09/04 | **Discharger Report:** | |
| **Dt MOE Arvl on Scn:** | | **Material Group:** | |
| **MOE Reported Dt:** | 2018/09/04 | **Impact to Health:** | 0 - No Impact |
| **Dt Document Closed:** | | **Agency Involved:** | |
| **Site No:** | NA | | |
| **MOE Response:** | No | | |
| **Site County/District:** | | | |
| **Site Geo Ref Meth:** | | | |
| **Site District Office:** | Ottawa | | |
| **Nearest Watercourse:** | | | |
| **Site Name:** | Linestrike location<UNOFFICIAL> | | |
| **Site Address:** | 310 Cooper St. | | |
| **Site Region:** | Eastern | | |
| **Site Municipality:** | Ottawa | | |
| **Site Lot:** | | | |
| **Site Conc:** | | | |
| **Site Geo Ref Accu:** | | | |
| **Site Map Datum:** | | | |
| **Northing:** | 5029557.71 | | |
| **Easting:** | 445744.6 | | |
| **Entity Operating Name:** | | | |
| **Client Name:** | Enbridge Gas Distribution Inc. | | |
| **Client Type:** | Corporation | | |
| **Source Type:** | Pipeline/Components | | |
| **Incident Cause:** | | | |
| **Incident Preceding Spill:** | Leak/Break | | |
| **Incident Reason:** | Operator/Human Error | | |
| **Incident Summary:** | TSSA FSB: 1/2" pl IP gas main dmged - made safe | | |
| **Environment Impact:** | | | |
| **Health Env Consequence:** | | | |
| **Nature of Impact:** | | | |
| **Contaminant Qty:** | 0 other - see incident description | | |
| **Contaminant Qty 1:** | 0 | | |
| **Contaminant Unit:** | other - see incident description | | |
| **Contaminant Code:** | 35 | | |
| **Contaminant Name:** | NATURAL GAS (METHANE) | | |
| **Contaminant Limit 1:** | | | |
| **Contam Limit Freq 1:** | | | |
| **Contaminant UN No 1:** | 1075 | | |
| **Receiving Medium:** | Air | | |
| **Activity Preceding Spill:** | | | |
| **Property 2nd Watershed:** | | | |
| **Property Tertiary Watershed:** | | | |
| **Sector Type:** | Miscellaneous Industrial | | |
| **SAC Action Class:** | TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill | | |
| **Call Report Locatn Geodata:** | | | |
| **Time Reported:** | | | |
| **System Facility Address:** | | | |
| **Source Sector Type:** | | | |
| **Conservtn Auth Name:** | | | |
| **Primary Watershed:** | | | |
| **Quaternary Watershed:** | | | |
| **Offsite Impacts Y N:** | | | |
| **Waterbody Impacted Y N:** | | | |

---

**60** | ***1 of 3*** | ***WNW/177.4*** | ***74.8 / 0.97*** | ***320 Cooper Street Ottawa ON K2P 0G7*** | ***EHS***

| | | | |
|---|---|---|---|
| **Order No:** | 20070316023 | **Nearest Intersection:** | Cooper Street and Metcalf Street |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | CAN - Complete Report | **Client Prov/State:** | |
| **Report Date:** | 3/27/2007 | **Search Radius (km):** | 0.25 |
| **Date Received:** | 3/16/2007 | **X:** | -75.693881 |
| **Previous Site Name:** | | **Y:** | 45.417111 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Lot/Building Size:** | | | | | |
| **Additional Info Ordered:** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| 60 | 2 of 3 | WNW/177.4 | 74.8 / 0.97 | **320 Cooper St**<br>**Ottawa ON K2P0G7** | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 20140224059 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 28-FEB-14 | **Search Radius (km):** | .25 |
| **Date Received:** | 24-FEB-14 | **X:** | -75.694021 |
| **Previous Site Name:** | | **Y:** | 45.416972 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| | | | | | |
|---|---|---|---|---|---|
| 60 | 3 of 3 | WNW/177.4 | 74.8 / 0.97 | **320 Cooper Street Ottawa ON**<br>**Ottawa ON K2P 0G7** | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 23061300287 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 16-JUN-23 | **Search Radius (km):** | .25 |
| **Date Received:** | 13-JUN-23 | **X:** | -75.6940461 |
| **Previous Site Name:** | | **Y:** | 45.416969 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| | | | | | |
|---|---|---|---|---|---|
| 61 | 1 of 1 | WSW/178.2 | 75.9 / 2.00 | **334 MacLaren Street**<br>**Ottawa ON K2P 0M6** | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 20100517016 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 5/21/2010 | **Search Radius (km):** | 0.25 |
| **Date Received:** | 5/17/2010 | **X:** | -75.694368 |
| **Previous Site Name:** | | **Y:** | 45.415194 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| | | | | | |
|---|---|---|---|---|---|
| 62 | 1 of 2 | NW/178.3 | 74.9 / 1.00 | **HICKS MEDIA**<br>**300 Cooper St Suite 30**<br>**Ottawa ON K2P 0G7** | SCT |

| | |
|---|---|
| **Scott S ID:** | 18735954 |
| **Latitude:** | |
| **Longitude:** | |

***Historical Details***

| | |
|---|---|
| **Established:** | 1985 |
| **Plant Size (ft²):** | 0 |
| **Employment:** | 5 |

***Historical Details***

| | |
|---|---|
| **Description:** | Other Publishers |
| **SIC/NAICS Code:** | 511190 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 62 | 2 of 2 | NW/178.3 | 74.9 / 1.00 | Hicks Media - Div. of Gidney News & Publishing Limited<br>300 Cooper St Suite 30<br>Ottawa ON K2P 0G7 | SCT |

**Scott S ID:** 18735954
**Latitude:**
**Longitude:**

***Historical Details***

**Established:** 1985
**Plant Size (ft²):**
**Employment:** 5

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 63 | 1 of 1 | ESE/178.3 | 72.9 / -1.00 | ON | BORE |

**Borehole ID:** 613276
**OGF ID:** 215514577
**Status:**
**Type:** Borehole
**Use:**
**Completion Date:**
**Static Water Level:**
**Primary Water Use:**
**Sec. Water Use:**
**Total Depth m:** -999
**Depth Ref:** Ground Surface
**Depth Elev:**
**Drill Method:**
**Orig Ground Elev m:** 70.1
**Elev Reliabil Note:**
**DEM Ground Elev m:** 70
**Concession:**
**Location D:**
**Survey D:**
**Comments:**

**Inclin FLG:** No
**SP Status:** Initial Entry
**Surv Elev:** No
**Piezometer:** No
**Primary Name:**
**Municipality:**
**Lot:**
**Township:**
**Latitude DD:** 45.415245
**Longitude DD:** -75.690269
**UTM Zone:** 18
**Easting:** 445991
**Northing:** 5029312
**Location Accuracy:**
**Accuracy:** Not Applicable

***Borehole Geology Stratum***

**Geology Stratum ID:** 218394459
**Top Depth:** 0
**Bottom Depth:** 1.5
**Material Color:** Brown
**Material 1:** Sand
**Material 2:**
**Material 3:**
**Material 4:**
**Gsc Material Description:**
**Stratum Description:** SAND. BROWN.

**Mat Consistency:**
**Material Moisture:**
**Material Texture:**
**Non Geo Mat Type:**
**Geologic Formation:**
**Geologic Group:**
**Geologic Period:**
**Depositional Gen:**

**Geology Stratum ID:** 218394460
**Top Depth:** 1.5
**Bottom Depth:** 3.7
**Material Color:** Brown
**Material 1:** Clay
**Material 2:**
**Material 3:**
**Material 4:**
**Gsc Material Description:**
**Stratum Description:** CLAY. BROWN,FRACTURED.

**Mat Consistency:**
**Material Moisture:**
**Material Texture:**
**Non Geo Mat Type:**
**Geologic Formation:**
**Geologic Group:**
**Geologic Period:**
**Depositional Gen:**

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394461 | **Mat Consistency:** | Stiff |
| **Top Depth:** | 3.7 | **Material Moisture:** | |
| **Bottom Depth:** | | **Material Texture:** | |
| **Material Color:** | Dark | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |

**Stratum Description:** CLAY. GREY,FRACTURED. STIFF. SILT. GREY. BEDROCK. DARK,GREY,SOUND,STRATIFIED. 00000010000
**Note: Many records provided by the department have a truncated [Stratum Description] field.

***Source***

| | | | |
|---|---|---|---|
| **Source Type:** | Data Survey | **Source Appl:** | Spatial/Tabular |
| **Source Orig:** | Geological Survey of Canada | **Source Iden:** | 1 |
| **Source Date:** | 1956-1972 | **Scale or Res:** | Varies |
| **Confidence:** | M | **Horizontal:** | NAD27 |
| **Observatio:** | | **Verticalda:** | Mean Average Sea Level |
| **Source Name:** | Urban Geology Automated Information System (UGAIS) | | |
| **Source Details:** | File: OTTAWA2.txt RecordID: 057840 NTS_Sheet: 31G05G | | |
| **Confiden 1:** | Reliable information but incomplete. | | |

***Source List***

| | | | |
|---|---|---|---|
| **Source Identifier:** | 1 | **Horizontal Datum:** | NAD27 |
| **Source Type:** | Data Survey | **Vertical Datum:** | Mean Average Sea Level |
| **Source Date:** | 1956-1972 | **Projection Name:** | Universal Transverse Mercator |
| **Scale or Resolution:** | Varies | | |
| **Source Name:** | Urban Geology Automated Information System (UGAIS) | | |
| **Source Originators:** | Geological Survey of Canada | | |

---

**64** **1 of 1** **W/181.5** **75.9 / 2.00** **311 SOMERSET**
**Ottawa ON**

**WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7391112 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | Monitoring and Test Hole | **Data Entry Status:** | |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | Monitoring and Test Hole | **Date Received:** | 06/29/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z364080 | **Contractor:** | 7241 |
| **Tag:** | A302972 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | OTTAWA CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7391112.pdf

***Additional Detail(s) (Map)***

**Well Completed Date:** 05/26/2021

***Year Completed:*** 2021
***Depth (m):*** 13.1
***Latitude:*** 45.4162876088694
***Longitude:*** -75.6945972286121
***Point X:*** -75.69459706670887
***Point Y:*** 45.41628760214662
***Path:*** 739\7391112.pdf

***Bore Hole Information***

***Bore Hole ID:*** 1008704346
***DP2BR:***
***Spatial Status:***
***Code OB:***
***Code OB Desc:***
***Open Hole:***
***Cluster Kind:***
***Date Completed:*** 05/26/2021
***Remarks:***
***Location Method Desc:*** on Water Well Record
***Elevrc Desc:***
***Location Source Date:***
***Improvement Location Source:***
***Improvement Location Method:***
***Source Revision Comment:***
***Supplier Comment:***

***Elevation:***
***Elevrc:***
***Zone:*** 18
***East83:*** 445653.00
***North83:*** 5029431.00
***Org CS:*** UTM83
***UTMRC:*** 4
***UTMRC Desc:*** margin of error : 30 m - 100 m
***Location Method:*** wwr

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009852393
***Layer:*** 3
***Color:*** 6
***General Color:*** BROWN
***Material 1:*** 05
***Material 1 Desc:*** CLAY
***Material 2:*** 28
***Material 2 Desc:*** SAND
***Material 3:*** 85
***Material 3 Desc:*** SOFT
***Formation Top Depth:*** 2.740000009536743
***Formation End Depth:*** 3.9600000381469727
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009852392
***Layer:*** 2
***Color:*** 6
***General Color:*** BROWN
***Material 1:*** 28
***Material 1 Desc:*** SAND
***Material 2:*** 11
***Material 2 Desc:*** GRAVEL
***Material 3:*** 85
***Material 3 Desc:*** SOFT
***Formation Top Depth:*** 0.3100000023841858
***Formation End Depth:*** 2.740000009536743
***Formation End Depth UOM:*** m

***Overburden and Bedrock***

***Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009852394 |
| ***Layer:*** | 4 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 05 |
| ***Material 1 Desc:*** | CLAY |
| ***Material 2:*** | 06 |
| ***Material 2 Desc:*** | SILT |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 3.9600000381469727 |
| ***Formation End Depth:*** | 10.670000076293945 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009852395 |
| ***Layer:*** | 5 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 06 |
| ***Material 1 Desc:*** | SILT |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | 66 |
| ***Material 3 Desc:*** | DENSE |
| ***Formation Top Depth:*** | 10.670000076293945 |
| ***Formation End Depth:*** | 13.100000381469727 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009852391 |
| ***Layer:*** | 1 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 11 |
| ***Material 1 Desc:*** | GRAVEL |
| ***Material 2:*** | 28 |
| ***Material 2 Desc:*** | SAND |
| ***Material 3:*** | 77 |
| ***Material 3 Desc:*** | LOOSE |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 0.3100000023841858 |
| ***Formation End Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1009853455 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 0.3100000023841858 |
| ***Plug Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009853456
***Layer:*** 2
***Plug From:*** 0.3100000023841858
***Plug To:*** 9.75
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009853457
***Layer:*** 3
***Plug From:*** 9.75
***Plug To:*** 13.100000381469727
***Plug Depth UOM:*** m

***Method of Construction & Well Use***

***Method Construction ID:*** 1009854837
***Method Construction Code:*** 5
***Method Construction:*** Air Percussion
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 1009764982
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1009855215
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 10.050000190734863
***Casing Diameter:*** 5.199999809265137
***Casing Diameter UOM:*** cm
***Casing Depth UOM:*** m

***Construction Record - Screen***

***Screen ID:*** 1009855611
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 10.050000190734863
***Screen End Depth:*** 13.100000381469727
***Screen Material:*** 5
***Screen Depth UOM:*** m
***Screen Diameter UOM:*** cm
***Screen Diameter:*** 6.03000020980835

***Results of Well Yield Testing***

***Pumping Test Method Desc:***
***Pump Test ID:*** 1009856075
***Pump Set At:***
***Static Level:***
***Final Level After Pumping:***

***Recommended Pump Depth:***
***Pumping Rate:***
***Flowing Rate:***
***Recommended Pump Rate:***
***Levels UOM:*** m
***Rate UOM:*** LPM
***Water State After Test Code:***
***Water State After Test:***
***Pumping Test Method:*** 0
***Pumping Duration HR:***
***Pumping Duration MIN:***
***Flowing:*** No

***Hole Diameter***

***Hole ID:*** 1009854396
***Diameter:*** 11.430000305175781
***Depth From:*** 0.0
***Depth To:*** 13.100000381469727
***Hole Depth UOM:*** m
***Hole Diameter UOM:*** cm

---

**65** ***1 of 1*** ***NNE/182.2*** ***73.7 / -0.14*** ***223 Somerset St W Ottawa ON K2P0J1*** ***EHS***

***Order No:*** 20161117139
***Status:*** C
***Report Type:*** Standard Report
***Report Date:*** 23-NOV-16
***Date Received:*** 17-NOV-16
***Previous Site Name:***
***Lot/Building Size:***
***Additional Info Ordered:***

***Nearest Intersection:***
***Municipality:***
***Client Prov/State:*** ON
***Search Radius (km):*** .25
***X:*** -75.691814
***Y:*** 45.417518

---

**66** ***1 of 1*** ***ESE/182.2*** ***72.9 / -1.00*** ***ON*** ***BORE***

***Borehole ID:*** 613263
***OGF ID:*** 215514565
***Status:***
***Type:*** Borehole
***Use:***
***Completion Date:***
***Static Water Level:*** 13.7
***Primary Water Use:***
***Sec. Water Use:***
***Total Depth m:*** -999
***Depth Ref:*** Ground Surface
***Depth Elev:***
***Drill Method:***
***Orig Ground Elev m:*** 69.2
***Elev Reliabil Note:***
***DEM Ground Elev m:*** 69.3
***Concession:***
***Location D:***
***Survey D:***
***Comments:***

***Inclin FLG:*** No
***SP Status:*** Initial Entry
***Surv Elev:*** No
***Piezometer:*** No
***Primary Name:***
***Municipality:***
***Lot:***
***Township:***
***Latitude DD:*** 45.414792
***Longitude DD:*** -75.690647
***UTM Zone:*** 18
***Easting:*** 445961
***Northing:*** 5029262
***Location Accuracy:***
***Accuracy:*** Not Applicable

***Borehole Geology Stratum***

***Geology Stratum ID:*** 218394404
***Top Depth:*** 0

***Mat Consistency:***
***Material Moisture:***

| | | | |
|---|---|---|---|
| **Bottom Depth:** | .9 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Sand | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | SAND. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394406 | **Mat Consistency:** | Compact |
| **Top Depth:** | 21 | **Material Moisture:** | |
| **Bottom Depth:** | | **Material Texture:** | |
| **Material Color:** | Brown | **Non Geo Mat Type:** | |
| **Material 1:** | Silt | **Geologic Formation:** | |
| **Material 2:** | Gravel | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | SILT. WATER STABLE AT 182.0 FEET.. BROWN. CLAY. BROWN,GREY,STIFF. SILT. GREY,COMPACT. SAN<br>**Note: Many records provided by the department have a truncated [Stratum Description] field. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394405 | **Mat Consistency:** | Soft |
| **Top Depth:** | .9 | **Material Moisture:** | |
| **Bottom Depth:** | 21 | **Material Texture:** | |
| **Material Color:** | Grey | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | CLAY. GREY,SOFT. | | |

***Source***

| | | | |
|---|---|---|---|
| **Source Type:** | Data Survey | **Source Appl:** | Spatial/Tabular |
| **Source Orig:** | Geological Survey of Canada | **Source Iden:** | 1 |
| **Source Date:** | 1956-1972 | **Scale or Res:** | Varies |
| **Confidence:** | H | **Horizontal:** | NAD27 |
| **Observatio:** | | **Verticalda:** | Mean Average Sea Level |
| **Source Name:** | Urban Geology Automated Information System (UGAIS) | | |
| **Source Details:** | File: OTTAWA2.txt RecordID: 057710 NTS_Sheet: 31G05G | | |
| **Confiden 1:** | Logged by professional. Exact and complete description of material and properties. | | |

***Source List***

| | | | |
|---|---|---|---|
| **Source Identifier:** | 1 | **Horizontal Datum:** | NAD27 |
| **Source Type:** | Data Survey | **Vertical Datum:** | Mean Average Sea Level |
| **Source Date:** | 1956-1972 | **Projection Name:** | Universal Transverse Mercator |
| **Scale or Resolution:** | Varies | | |
| **Source Name:** | Urban Geology Automated Information System (UGAIS) | | |
| **Source Originators:** | Geological Survey of Canada | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 67 | 1 of 13 | E/182.6 | 72.9 / -1.00 | Ottawa-Carleton District School Board<br>Elgin Street Public School 310 Elgin Street<br>Ottawa ON K2P 1M4 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON5437731 | **Choice of Contact:** | |
| **Approval Years:** | 02,03,04 | **Contaminated Fac:** | |
| **Status:** | | **MHSW Facility:** | |

***PO Box No:*** ***SIC Code:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 243
***Waste Class Name:*** PCB'S

---

**67** ***2 of 13*** ***E/182.6*** ***72.9 / -1.00*** ***Ottawa-Carleton District School Board*** ***GEN***
***Elgin Street PS 310 Elgin Street***
***Ottawa ON K2P 1M4***

***Generator Info***

***Generator No:*** ON7714391 ***Choice of Contact:***
***Approval Years:*** 05 ***Contaminated Fac:***
***Status:*** ***MHSW Facility:***
***PO Box No:*** ***SIC Code:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 243
***Waste Class Name:*** PCB'S

---

**67** ***3 of 13*** ***E/182.6*** ***72.9 / -1.00*** ***Ottawa-Carleton District School Board*** ***GEN***
***310 Elgin St.***
***Ottawa ON K2P 1M4***

***Generator Info***

***Generator No:*** ON6048676 ***Choice of Contact:***
***Approval Years:*** 06 ***Contaminated Fac:***
***Status:*** ***MHSW Facility:***
***PO Box No:*** ***SIC Code:*** 611110
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** Elementary and Secondary Schools

***Waste Detail(s)***

***Waste Class:*** 221
***Waste Class Name:*** LIGHT FUELS

---

**67** ***4 of 13*** ***E/182.6*** ***72.9 / -1.00*** ***Ottawa-Carleton District School Board*** ***GEN***
***310 Elgin Street***
***Ottawa ON K2P 1M4***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3676940 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2011 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 611110 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 67 | 5 of 13 | E/182.6 | 72.9 / -1.00 | ***Ottawa-Carleton District School Board***<br>***310 Elgin Street***<br>***Ottawa ON K2P 1M4*** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3676940 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2012 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 611110 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Elementary and Secondary Schools | | |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 67 | 6 of 13 | E/182.6 | 72.9 / -1.00 | ***Ottawa-Carleton District School Board***<br>***310 Elgin Street***<br>***Ottawa ON*** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3676940 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2013 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 611110 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | ELEMENTARY AND SECONDARY SCHOOLS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 145 |
| ***Waste Class Name:*** | PAINT/PIGMENT/COATING RESIDUES |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 213 |
| ***Waste Class Name:*** | PETROLEUM DISTILLATES |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 146 |
| ***Waste Class Name:*** | OTHER SPECIFIED INORGANICS |

***Waste Detail(s)***

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

**Waste Class:** 263
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

---

**67** | ***7 of 13*** | ***E/182.6*** | ***72.9 / -1.00*** | ***Ottawa-Carleton District School Board*** | ***GEN***
***310 Elgin Street***
***Ottawa ON K2P 1M4***

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON3676940 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2016 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 611110 |
| **Country:** | Canada | | |
| **Co Admin:** | Greg Benson | | |
| **Phone No Admin:** | 613-596-8211 Ext.8549 | | |
| **SIC Description:** | ELEMENTARY AND SECONDARY SCHOOLS | | |

***Waste Detail(s)***

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

**Waste Class:** 213
**Waste Class Name:** PETROLEUM DISTILLATES

***Waste Detail(s)***

**Waste Class:** 145
**Waste Class Name:** PAINT/PIGMENT/COATING RESIDUES

***Waste Detail(s)***

**Waste Class:** 263
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

**Waste Class:** 146
**Waste Class Name:** OTHER SPECIFIED INORGANICS

---

**67** | ***8 of 13*** | ***E/182.6*** | ***72.9 / -1.00*** | ***Ottawa-Carleton District School Board*** | ***GEN***
***310 Elgin Street***
***Ottawa ON K2P 1M4***

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON3676940 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2015 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 611110 |
| **Country:** | Canada | | |
| **Co Admin:** | Greg Benson | | |
| **Phone No Admin:** | 613-596-8211 Ext.8549 | | |
| **SIC Description:** | ELEMENTARY AND SECONDARY SCHOOLS | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 263 |
| **Waste Class Name:** | ORGANIC LABORATORY CHEMICALS |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 145 |
| **Waste Class Name:** | PAINT/PIGMENT/COATING RESIDUES |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 146 |
| **Waste Class Name:** | OTHER SPECIFIED INORGANICS |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 213 |
| **Waste Class Name:** | PETROLEUM DISTILLATES |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 148 |
| **Waste Class Name:** | INORGANIC LABORATORY CHEMICALS |

---

**67** | ***9 of 13*** | ***E/182.6*** | ***72.9 / -1.00*** | ***Ottawa-Carleton District School Board***
***310 Elgin Street***
***Ottawa ON K2P 1M4*** | ***GEN***

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON3676940 | **Choice of Contact:** | CO_OFFICIAL |
| **Approval Years:** | 2014 | **Contaminated Fac:** | No |
| **Status:** | | **MHSW Facility:** | No |
| **PO Box No:** | | **SIC Code:** | 611110 |
| **Country:** | Canada | | |
| **Co Admin:** | Greg Benson | | |
| **Phone No Admin:** | 613-596-8211 Ext.8549 | | |
| **SIC Description:** | ELEMENTARY AND SECONDARY SCHOOLS | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 148 |
| **Waste Class Name:** | INORGANIC LABORATORY CHEMICALS |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 213 |

**Waste Class Name:** PETROLEUM DISTILLATES

***Waste Detail(s)***

**Waste Class:** 145
**Waste Class Name:** PAINT/PIGMENT/COATING RESIDUES

***Waste Detail(s)***

**Waste Class:** 146
**Waste Class Name:** OTHER SPECIFIED INORGANICS

***Waste Detail(s)***

**Waste Class:** 263
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

---

**67** | ***10 of 13*** | ***E/182.6*** | ***72.9 / -1.00*** | ***Ottawa-Carleton District School Board Health & Safety***
***310 Elgin Street***
***Ottawa ON K2P 1M4*** | ***GEN***

***Generator Info***

**Generator No:** ON3676940
**Approval Years:** As of Dec 2018
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 146 T
**Waste Class Name:** Other specified inorganic sludges, slurries or solids

***Waste Detail(s)***

**Waste Class:** 148 C
**Waste Class Name:** Misc. wastes and inorganic chemicals

***Waste Detail(s)***

**Waste Class:** 213 I
**Waste Class Name:** Petroleum distillates

***Waste Detail(s)***

**Waste Class:** 263 I
**Waste Class Name:** Misc. waste organic chemicals

***Waste Detail(s)***

**Waste Class:** 145 I

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Waste Class Name:** | | Wastes from the use of pigments, coatings and paints | | | |

| | | | | | |
|---|---|---|---|---|---|
| 67 | 11 of 13 | E/182.6 | 72.9 / -1.00 | **Ottawa-Carleton District School Board Health & Safety**<br>**310 Elgin Street**<br>**Ottawa ON K2P 1M4** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON3676940 | **Choice of Contact:** | |
| **Approval Years:** | As of Jul 2020 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 145 I |
| **Waste Class Name:** | Wastes from the use of pigments, coatings and paints |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 146 T |
| **Waste Class Name:** | Other specified inorganic sludges, slurries or solids |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 213 I |
| **Waste Class Name:** | Petroleum distillates |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 148 C |
| **Waste Class Name:** | Misc. wastes and inorganic chemicals |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 263 I |
| **Waste Class Name:** | Misc. waste organic chemicals |

| | | | | | |
|---|---|---|---|---|---|
| 67 | 12 of 13 | E/182.6 | 72.9 / -1.00 | **Ottawa-Carleton District School Board Health & Safety**<br>**310 Elgin Street**<br>**Ottawa ON K2P 1M4** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON3676940 | **Choice of Contact:** | |
| **Approval Years:** | As of Nov 2021 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |
| **Country:** | Canada | | |
| **Co Admin:** | | | |

***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 213 I
***Waste Class Name:*** Petroleum distillates

***Waste Detail(s)***

***Waste Class:*** 145 I
***Waste Class Name:*** Wastes from the use of pigments, coatings and paints

***Waste Detail(s)***

***Waste Class:*** 263 I
***Waste Class Name:*** Misc. waste organic chemicals

***Waste Detail(s)***

***Waste Class:*** 146 T
***Waste Class Name:*** Other specified inorganic sludges, slurries or solids

***Waste Detail(s)***

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

---

**67** | ***13 of 13*** | ***E/182.6*** | ***72.9 / -1.00*** | ***Ottawa-Carleton District School Board***
***Elgin Street Public School, 310 Elgin Street***
***Ottawa ON*** | ***GEN***

***Generator Info***

***Generator No:*** ON3676940
***Approval Years:*** As of Oct 2022
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 146 T
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Detail(s)***

***Waste Class:*** 213 I
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Detail(s)***

***Waste Class:*** 145 I

**Waste Class Name:** PAINT/PIGMENT/COATING RESIDUES

***Waste Detail(s)***

**Waste Class:** 263 I
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

**Waste Class:** 148 C
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

***Generator Info (as of Dec 2024)***

**Generator No:** ON3676940
**Generator Company Name:** Ottawa-Carleton District School Board
**Street:** Elgin Street Public School, 310 Elgin Street
**City:** Ottawa
**Province State:** Ontario
**Country:** Canada
**Postal Code:** K2P1M4
**Waste Class:** 145 I,251 L,148 C,213 I,263 I,146 T,263 B,331 I

**Waste Class Decoded:**

145 - PAINT/PIGMENT/COATING RESIDUES; 251 - OIL SKIMMINGS & SLUDGES; 148 - INORGANIC LABORATORY CHEMICALS; 213 - PETROLEUM DISTILLATES; 263 - ORGANIC LABORATORY CHEMICALS; 146 - OTHER SPECIFIED INORGANICS; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES

***Generator Info (as of Apr 2025)***

**Generator Company Name:** Ottawa-Carleton District School Board
**Generator Site Address:** Elgin Street Public School, 310 Elgin Street
**City:** Ottawa
**Province State:** Ontario
**Country:** Canada
**Postal Code:** K2P1M4
**Waste Class:** 251 L, 145 I, 148 C, 213 I, 263 I, 146 T, 263 B, 331 I

**Waste Class Decoded:**

251 - OIL SKIMMINGS & SLUDGES; 145 - PAINT/PIGMENT/COATING RESIDUES; 148 - INORGANIC LABORATORY CHEMICALS; 213 - PETROLEUM DISTILLATES; 263 - ORGANIC LABORATORY CHEMICALS; 146 - OTHER SPECIFIED INORGANICS; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES

**Waste Characteristic Decoded:**

L - Liquid Industrial Waste; I - Ignitable; C - Corrosive; I - Ignitable; I - Ignitable; T - Leachate Toxic; B - Hazardous Waste Chemical; I - Ignitable

***2017 Generator Info***

**Gen No:** ON3676940
**ID:** 14753
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 611110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Ottawa-Carleton District School Board

**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 613-596-8211 Ext.8495
**Phone No Admin:** 613-596-8211 Ext.8549
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

| | |
|---|---|
| **Gen Div:** | Health & Safety |
| **Gen Op Name:** | Ottawa-Carleton District School Board |
| **Gen Op Div:** | Health & Safety |
| **Site Adrs1:** | 310 Elgin Street |
| **Site Bldg:** | Elgin Street Public School |
| **Site Pobox:** | |
| **Province In:** | ONTARIO |
| **Site Adrs2:** | |
| **Site City:** | Ottawa |
| **Province Out:** | |
| **Site Postal Code:** | K2P 1M4 |
| **Site Country:** | Canada |
| **Co Official:** | Clint Vester |
| **Co Admin:** | Greg Benson |

***2018 Generator Info***

| | | | |
|---|---|---|---|
| **Gen No:** | ON3676940 | **Choice of Contact:** | CO_OFFICIAL |
| **ID:** | 14666 | **Phone No Official:** | 613-596-8211 Ext.8495 |
| **Contaminated Fac:** | N | **Phone No Admin:** | 613-596-8211 Ext.8549 |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 611110 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |

| | |
|---|---|
| **Gen Name:** | Ottawa-Carleton District School Board |
| **Gen Div:** | Health & Safety |
| **Gen Op Name:** | Ottawa-Carleton District School Board |
| **Gen Op Div:** | Health & Safety |
| **Site Adrs1:** | 310 Elgin Street |
| **Site Bldg:** | Elgin Street Public School |
| **Site Pobox:** | |
| **Province In:** | ONTARIO |
| **Site Adrs2:** | |
| **Site City:** | Ottawa |
| **Province Out:** | |
| **Site Postal Code:** | K2P 1M4 |
| **Site Country:** | Canada |
| **Co Official:** | Clint Vester |
| **Co Admin:** | Greg Benson |

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 37325 | **Sum Received Qty:** | 64.0 |
| **Generator No:** | ON3676940 | **Waste Class Name:** | ORGANIC LABORATORY CHEMICALS |
| **Receiver Type:** | 035 | **Count Manifests:** | 1 |
| **Waste Char:** | I | **District:** | 201 |
| **Waste Code:** | 263 | | |

***2019 Generator Info***

| | | | |
|---|---|---|---|
| **Gen No:** | ON3676940 | **Choice of Contact:** | CO_OFFICIAL |
| **ID:** | 14485 | **Phone No Official:** | 613-596-8211 Ext.8495 |
| **Contaminated Fac:** | N | **Phone No Admin:** | 613-596-8211 Ext.8549 |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 611110 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |

| | |
|---|---|
| **Gen Name:** | Ottawa-Carleton District School Board |
| **Gen Div:** | Health & Safety |
| **Gen Op Name:** | Ottawa-Carleton District School Board |
| **Gen Op Div:** | Health & Safety |
| **Site Adrs1:** | 310 Elgin Street |
| **Site Bldg:** | Elgin Street Public School |

***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1M4
***Site Country:*** Canada
***Co Official:*** Clint Vester
***Co Admin:*** Greg Benson

***2020 Generator Info***

***Gen No:*** ON3676940
***ID:*** 14142
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 611110
***NAICS Code2:***
***NAICS Code3:***
***Choice of Contact:*** CO_OFFICIAL
***Phone No Official:*** 613-596-8211 Ext.8495
***Phone No Admin:*** 613-596-8211 Ext.8549
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402
***Gen Name:*** Ottawa-Carleton District School Board
***Gen Div:*** Health & Safety
***Gen Op Name:*** Ottawa-Carleton District School Board
***Gen Op Div:*** Health & Safety
***Site Adrs1:*** 310 Elgin Street
***Site Bldg:*** Elgin Street Public School
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1M4
***Site Country:*** Canada
***Co Official:*** Clint Vester
***Co Admin:*** Greg Benson

***2021 Generator Info***

***Gen No:*** ON3676940
***ID:*** 14039
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 611110
***NAICS Code2:***
***NAICS Code3:***
***Choice of Contact:*** CO_OFFICIAL
***Phone No Official:*** 613-596-8211 Ext.8495
***Phone No Admin:*** 613-596-8211 Ext.8549
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402
***Gen Name:*** Ottawa-Carleton District School Board
***Gen Div:*** Health & Safety
***Gen Op Name:*** Ottawa-Carleton District School Board
***Gen Op Div:*** Health & Safety
***Site Adrs1:*** 310 Elgin Street
***Site Bldg:*** Elgin Street Public School
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1M4
***Site Country:*** Canada
***Co Official:*** Clint Vester
***Co Admin:*** Greg Benson

| | | | | | |
|---|---|---|---|---|---|
| **68** | ***1 of 1*** | ***WSW/182.8*** | ***75.9 / 2.00*** | ***335 MacLaren Street Ottawa ON K2P 0M4*** | ***EHS*** |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Order No:** | 25031700359 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 20-MAR-25 | **Search Radius (km):** | .25 |
| **Date Received:** | 17-MAR-25 | **X:** | -75.6945375 |
| **Previous Site Name:** | | **Y:** | 45.4153673 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

| | | | | | |
|---|---|---|---|---|---|
| 69 | 1 of 1 | N/183.3 | 73.9 / 0.00 | California Standard Co<br>233 Metcalfe<br>Ottawa ON | HBAR |

| | |
|---|---|
| **Province:** | ON |
| **Year:** | 1960 |
| **Source:** | Mights |

---

| | | | | | |
|---|---|---|---|---|---|
| 70 | 1 of 1 | W/184.2 | 75.9 / 2.00 | ON | WWIS |

| | | | |
|---|---|---|---|
| **Well ID:** | 7211110 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | Monitoring | **Data Entry Status:** | |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | Abandoned-Other | **Date Received:** | 11/14/2013 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | Yes |
| **Audit No:** | Z096856 | **Contractor:** | 6894 |
| **Tag:** | A152341 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | OTTAWA CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7211110.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | |
| **Year Completed:** | |
| **Depth (m):** | |
| **Latitude:** | 45.4162783751036 |
| **Longitude:** | -75.6946354577708 |
| **Point X:** | -75.69463529630052 |
| **Point Y:** | 45.416278368040004 |
| **Path:** | 721\7211110.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1004633069 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445650.00 |
| **Code OB Desc:** | | **North83:** | 5029430.00 |

| | | | |
|---|---|---|---|
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 3 |
| ***Date Completed:*** | | ***UTMRC Desc:*** | margin of error : 10 - 30 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1004895719 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 57.0 |
| ***Plug To:*** | 0.0 |
| ***Plug Depth UOM:*** | ft |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1004895718 |
| ***Method Construction Code:*** | |
| ***Method Construction:*** | |
| ***Other Method Construction:*** | |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1004895711 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 1004895715 |
| ***Layer:*** | |
| ***Material:*** | |
| ***Open Hole or Material:*** | |
| ***Depth From:*** | |
| ***Depth To:*** | |
| ***Casing Diameter:*** | |
| ***Casing Diameter UOM:*** | inch |
| ***Casing Depth UOM:*** | ft |

***Construction Record - Screen***

| | |
|---|---|
| ***Screen ID:*** | 1004895716 |
| ***Layer:*** | |
| ***Slot:*** | |
| ***Screen Top Depth:*** | |
| ***Screen End Depth:*** | |
| ***Screen Material:*** | |
| ***Screen Depth UOM:*** | ft |
| ***Screen Diameter UOM:*** | inch |
| ***Screen Diameter:*** | |

***Water Details***

**Water ID:** 1004895714
**Layer:**
**Kind Code:**
**Kind:**
**Water Found Depth:**
**Water Found Depth UOM:** ft

***Hole Diameter***

**Hole ID:** 1004895713
**Diameter:**
**Depth From:**
**Depth To:**
**Hole Depth UOM:** ft
**Hole Diameter UOM:** inch

---

**71** | **1 of 1** | **WSW/184.3** | **75.9 / 2.00** | **335 Maclaren St Ottawa ON K2P0M5** | **EHS**

**Order No:** 20160112021
**Status:** C
**Report Type:** Custom Report
**Report Date:** 15-JAN-16
**Date Received:** 12-JAN-16
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.694571
**Y:** 45.415395

---

**72** | **1 of 1** | **SSW/184.6** | **74.9 / 1.00** | **438 LEWIS STREET OTTAWA ON** | **HINC**

**External File Num:** FS INC 0707-03424
**Fuel Occurrence Type:** Pipeline Strike
**Date of Occurrence:** 6/28/2007
**Fuel Type Involved:** Natural Gas
**Status Desc:** Completed - No Action Required
**Job Type Desc:** Incident/Near-Miss Occurrence (FS)
**Oper. Type Involved:** Private Dwelling
**Service Interruptions:** Yes
**Property Damage:** No
**Fuel Life Cycle Stage:** Utilization
**Root Cause:**
**Reported Details:**
**Fuel Category:** Gaseous Fuel
**Occurrence Type:** Incident
**Affiliation:** Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
**County Name:** Ottawa
**Approx. Quant. Rel:**
**Nearby body of water:**
**Enter Drainage Syst.:**
**Approx. Quant. Unit:**
**Environmental Impact:**

---

**73** | **1 of 1** | **W/185.0** | **75.9 / 2.00** | **311 Somerset St W Ottawa ON** | **WWIS**

**Well ID:** 7382782
**Construction Date:**
**Use 1st:** Monitoring and Test Hole
**Use 2nd:**

**Flowing (Y/N):**
**Flow Rate:**
**Data Entry Status:**
**Data Src:**

| | | | |
|---|---|---|---|
| **Final Well Status:** | Observation Wells | **Date Received:** | 03/18/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z338246 | **Contractor:** | 7241 |
| **Tag:** | A302969 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | OTTAWA CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/738\7382782.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | 02/19/2021 |
| **Year Completed:** | 2021 |
| **Depth (m):** | 20 |
| **Latitude:** | 45.416179135269 |
| **Longitude:** | -75.6946725832926 |
| **Point X:** | -75.6946724209724 |
| **Point Y:** | 45.41617912839754 |
| **Path:** | 738\7382782.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008639334 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445647.00 |
| **Code OB Desc:** | | **North83:** | 5029419.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 02/19/2021 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| **Formation ID:** | 1009823458 |
| **Layer:** | 1 |
| **Color:** | 2 |
| **General Color:** | GREY |
| **Material 1:** | 11 |
| **Material 1 Desc:** | GRAVEL |
| **Material 2:** | |
| **Material 2 Desc:** | |
| **Material 3:** | 73 |
| **Material 3 Desc:** | HARD |
| **Formation Top Depth:** | 0.0 |

***Formation End Depth:*** 2.0
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009823460
***Layer:*** 3
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 06
***Material 1 Desc:*** SILT
***Material 2:*** 05
***Material 2 Desc:*** CLAY
***Material 3:*** 85
***Material 3 Desc:*** SOFT
***Formation Top Depth:*** 5.0
***Formation End Depth:*** 9.0
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009823461
***Layer:*** 4
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 05
***Material 1 Desc:*** CLAY
***Material 2:***
***Material 2 Desc:***
***Material 3:*** 85
***Material 3 Desc:*** SOFT
***Formation Top Depth:*** 9.0
***Formation End Depth:*** 20.0
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009823459
***Layer:*** 2
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 11
***Material 1 Desc:*** GRAVEL
***Material 2:*** 01
***Material 2 Desc:*** FILL
***Material 3:*** 73
***Material 3 Desc:*** HARD
***Formation Top Depth:*** 2.0
***Formation End Depth:*** 5.0
***Formation End Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009824634
***Layer:*** 3
***Plug From:*** 9.0
***Plug To:*** 20.0
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1009824633 |
| ***Layer:*** | 2 |
| ***Plug From:*** | 1.0 |
| ***Plug To:*** | 9.0 |
| ***Plug Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1009824632 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 1.0 |
| ***Plug Depth UOM:*** | m |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1009826068 |
| ***Method Construction Code:*** | D |
| ***Method Construction:*** | Direct Push |
| ***Other Method Construction:*** | |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1009718364 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 1009826494 |
| ***Layer:*** | 1 |
| ***Material:*** | 5 |
| ***Open Hole or Material:*** | PLASTIC |
| ***Depth From:*** | 0.0 |
| ***Depth To:*** | 10.0 |
| ***Casing Diameter:*** | 2.046999931335449 |
| ***Casing Diameter UOM:*** | cm |
| ***Casing Depth UOM:*** | m |

***Construction Record - Screen***

| | |
|---|---|
| ***Screen ID:*** | 1009826907 |
| ***Layer:*** | 1 |
| ***Slot:*** | 10 |
| ***Screen Top Depth:*** | 10.0 |
| ***Screen End Depth:*** | 20.0 |
| ***Screen Material:*** | 5 |
| ***Screen Depth UOM:*** | m |
| ***Screen Diameter UOM:*** | cm |
| ***Screen Diameter:*** | 2.375 |

***Results of Well Yield Testing***

***Pumping Test Method Desc:***
***Pump Test ID:*** 1009827322
***Pump Set At:***
***Static Level:***
***Final Level After Pumping:***
***Recommended Pump Depth:***
***Pumping Rate:***
***Flowing Rate:***
***Recommended Pump Rate:***
***Levels UOM:*** m
***Rate UOM:*** LPM
***Water State After Test Code:***
***Water State After Test:***
***Pumping Test Method:*** 0
***Pumping Duration HR:***
***Pumping Duration MIN:***
***Flowing:***

***Hole Diameter***

***Hole ID:*** 1009825630
***Diameter:*** 4.5
***Depth From:*** 0.0
***Depth To:*** 20.0
***Hole Depth UOM:*** m
***Hole Diameter UOM:*** cm

---

**74** | ***1 of 1*** | ***SW/185.3*** | ***74.9 / 1.00*** | ***350 Gilmour Street Ottawa ON K2P 0R3*** | ***EHS***

***Order No:*** 25071100531
***Status:*** C
***Report Type:*** Standard Report
***Report Date:*** 14-JUL-25
***Date Received:*** 11-JUL-25
***Previous Site Name:***
***Lot/Building Size:***
***Additional Info Ordered:*** City Directory
***Nearest Intersection:***
***Municipality:***
***Client Prov/State:*** ON
***Search Radius (km):*** .2
***X:*** -75.6937196
***Y:*** 45.4145663

---

**75** | ***1 of 1*** | ***WNW/185.7*** | ***75.9 / 2.00*** | ***KEN RALPH 231 O'CONNOR ST,,OTTAWA,ON,K2P 1T8,CA ON*** | ***PINC***

***Incident Id:***
***Incident No:*** 1602812
***Incident Reported Dt:*** 3/24/2015
***Type:*** FS-Pipeline Incident
***Status Code:***
***Tank Status:*** Pipeline Damage Reason Est
***Task No:***
***Spills Action Centre:***
***Fuel Type:***
***Fuel Occurrence Tp:***
***Date of Occurrence:***
***Occurrence Start Dt:***
***Depth:***
***Customer Acct Name:*** KEN RALPH
***Incident Address:*** 231 O'CONNOR ST,,OTTAWA,ON,K2P 1T8,CA
***Operation Type:***
***Pipeline Type:***
***Regulator Type:***
***Summary:***
***Pipe Material:***
***Fuel Category:***
***Health Impact:***
***Environment Impact:***
***Property Damage:***
***Service Interrupt:***
***Enforce Policy:***
***Public Relation:***
***Pipeline System:***
***PSIG:***
***Attribute Category:***
***Regulator Location:***
***Method Details:***

***Reported By:***
***Affiliation:***
***Occurrence Desc:***
***Damage Reason:***
***Notes:***

---

**76** | ***1 of 1*** | ***ENE/188.9*** | ***72.9 / -1.00*** | ***Kun Shoulder Rest Inc.***
***200 MacLaren St***
***Ottawa ON K2P0L4*** | ***SCT***

***Scott S ID:*** 57063118
***Latitude:*** 45.4167446
***Longitude:*** -75.6902104

***Details***

| | | | |
|---|---|---|---|
| ***Bus Type 1:*** | Manufacturer | ***Employee Count:*** | 7 |
| ***Bus Type 2:*** | | ***Square Footage:*** | 0 |
| ***Bus Type 3:*** | | ***Estimated Sales:*** | $1-5 Million |
| ***Product Cat 1:*** | Music store | ***Export Indicator:*** | Y |
| ***Product Cat 2:*** | Musical instruments | ***Export Country 1:*** | Worldwide |
| ***Product Cat 3:*** | Musical instruments: supplies; accessories | ***Export Country 2:*** | |
| ***Product Cat 4:*** | | ***Export Country 3:*** | |
| ***Product Cat 5:*** | | ***Export Country 4:*** | |
| ***Product Cat 6:*** | | ***Export Country 5:*** | |
| ***Product Cat 7:*** | | ***Export Country 6:*** | |
| ***Product Cat 8:*** | | ***Geocoded by:*** | Address |

***Company Name:*** Kun Shoulder Rest Inc.
***Address Line 1:*** 200 MacLaren St
***Address Line 2:***
***City:*** Ottawa
***Province:*** ON
***Postal Code:*** K2P0L4
***Census Division:*** Ottawa; ON
***Metro Area:*** Ottawa/Hull
***Year Established:*** 1971
***Head Office Indicator:*** N
***Parent Company Nm:***
***Parent Cmpny Addr 1:***
***Parent Cmpny Addr 2:***
***Parent Cmpny City:***
***Parent Cmpny Prov:***
***Parent Cmpy PC:***
***Parent Cmpy Cntry:***
***Head Office Nm:***
***H Office Addr Line 1:***
***H Office Addr Line 2:***
***Head Office City:***
***Head Office Province:***
***Head Office PC:***
***Head Office Cntry:***
***Telephone:*** 613-232-1861
***Fax:*** 613-232-9771
***Website:*** http://www.kunrest.com/
***Pri NAICS Desc:*** 339990-All Other Miscellaneous Manufacturing
***NAICS Code 1:*** 339990-All Other Miscellaneous Manufacturing
***NAICS Code 2:***
***NAICS Code 3:***
***NAICS Code 4:***
***NAICS Code 5:***

***Historical Details***

**Established:** 01-AUG-75
**Plant Size (ft²):**
**Employment:**

***Historical Details***

**Description:** All Other Miscellaneous Manufacturing
**SIC/NAICS Code:** 339990

***Historical Details***

**Description:** All Other Miscellaneous Manufacturing
**SIC/NAICS Code:** 339990

---

**77** | **1 of 1** | **NW/189.5** | **74.8 / 0.97** | **318 Cooper Street Ottawa ON Ottawa ON K2P 0G7** | **EHS**

**Order No:** 21121400024
**Status:** C
**Report Type:** Standard Report
**Report Date:** 17-DEC-21
**Date Received:** 14-DEC-21
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.6940315
**Y:** 45.4171386

---

**78** | **1 of 1** | **W/189.9** | **75.9 / 2.00** | **311 SONERSET Ottawa ON** | **WWIS**

**Well ID:** 7391115
**Construction Date:**
**Use 1st:** Monitoring and Test Hole
**Use 2nd:**
**Final Well Status:** Monitoring and Test Hole
**Water Type:**
**Casing Material:**
**Audit No:** Z364139
**Tag:** A302952
**Constructn Method:**
**Elevation (m):**
**Elevatn Reliabilty:**
**Depth to Bedrock:**
**Well Depth:**
**Overburden/Bedrock:**
**Pump Rate:**
**Static Water Level:**
**Clear/Cloudy:**
**Municipality:** OTTAWA CITY
**Site Info:**

**Flowing (Y/N):**
**Flow Rate:**
**Data Entry Status:**
**Data Src:**
**Date Received:** 06/29/2021
**Selected Flag:** TRUE
**Abandonment Rec:**
**Contractor:** 7241
**Form Version:** 7
**Owner:**
**County:** OTTAWA-CARLETON
**Lot:**
**Concession:**
**Concession Name:**
**Easting NAD83:**
**Northing NAD83:**
**Zone:**
**UTM Reliability:**

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7391115.pdf

***Additional Detail(s) (Map)***

**Well Completed Date:** 05/25/2021
**Year Completed:** 2021
**Depth (m):** 14.94
**Latitude:** 45.4163771485905
**Longitude:** -75.6946750112729
**Point X:** -75.69467484910098

**Point Y:** 45.41637714214935
**Path:** 739\7391115.pdf

***Bore Hole Information***

**Bore Hole ID:** 1008704355
**DP2BR:**
**Spatial Status:**
**Code OB:**
**Code OB Desc:**
**Open Hole:**
**Cluster Kind:**
**Date Completed:** 05/25/2021
**Remarks:**
**Location Method Desc:** on Water Well Record
**Elevrc Desc:**
**Location Source Date:**
**Improvement Location Source:**
**Improvement Location Method:**
**Source Revision Comment:**
**Supplier Comment:**

**Elevation:**
**Elevrc:**
**Zone:** 18
**East83:** 445647.00
**North83:** 5029441.00
**Org CS:** UTM83
**UTMRC:** 4
**UTMRC Desc:** margin of error : 30 m - 100 m
**Location Method:** wwr

***Overburden and Bedrock Materials Interval***

**Formation ID:** 1009852408
**Layer:** 3
**Color:** 6
**General Color:** BROWN
**Material 1:** 05
**Material 1 Desc:** CLAY
**Material 2:** 28
**Material 2 Desc:** SAND
**Material 3:** 85
**Material 3 Desc:** SOFT
**Formation Top Depth:** 2.740000009536743
**Formation End Depth:** 3.3499999046325684
**Formation End Depth UOM:** m

***Overburden and Bedrock Materials Interval***

**Formation ID:** 1009852409
**Layer:** 4
**Color:** 2
**General Color:** GREY
**Material 1:** 05
**Material 1 Desc:** CLAY
**Material 2:** 06
**Material 2 Desc:** SILT
**Material 3:** 85
**Material 3 Desc:** SOFT
**Formation Top Depth:** 3.3499999046325684
**Formation End Depth:** 11.279999732971191
**Formation End Depth UOM:** m

***Overburden and Bedrock Materials Interval***

**Formation ID:** 1009852406
**Layer:** 1
**Color:** 2

| | |
|---|---|
| ***General Color:*** | GREY |
| ***Material 1:*** | 11 |
| ***Material 1 Desc:*** | GRAVEL |
| ***Material 2:*** | 28 |
| ***Material 2 Desc:*** | SAND |
| ***Material 3:*** | 77 |
| ***Material 3 Desc:*** | LOOSE |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 0.3100000023841858 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009852407 |
| ***Layer:*** | 2 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 28 |
| ***Material 1 Desc:*** | SAND |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 0.3100000023841858 |
| ***Formation End Depth:*** | 2.740000009536743 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009852410 |
| ***Layer:*** | 5 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 06 |
| ***Material 1 Desc:*** | SILT |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | 66 |
| ***Material 3 Desc:*** | DENSE |
| ***Formation Top Depth:*** | 11.279999732971191 |
| ***Formation End Depth:*** | 14.9399995803833 |
| ***Formation End Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1009853465 |
| ***Layer:*** | 2 |
| ***Plug From:*** | 0.3100000023841858 |
| ***Plug To:*** | 11.579999923706055 |
| ***Plug Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1009853466 |
| ***Layer:*** | 3 |
| ***Plug From:*** | 11.579999923706055 |
| ***Plug To:*** | 14.9399995803833 |
| ***Plug Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1009853464 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 0.3100000023841858 |
| ***Plug Depth UOM:*** | m |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1009854840 |
| ***Method Construction Code:*** | 5 |
| ***Method Construction:*** | Air Percussion |
| ***Other Method Construction:*** | |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1009764985 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 1009855218 |
| ***Layer:*** | 1 |
| ***Material:*** | 5 |
| ***Open Hole or Material:*** | PLASTIC |
| ***Depth From:*** | 0.0 |
| ***Depth To:*** | 11.890000343322754 |
| ***Casing Diameter:*** | 5.199999809265137 |
| ***Casing Diameter UOM:*** | cm |
| ***Casing Depth UOM:*** | m |

***Construction Record - Screen***

| | |
|---|---|
| ***Screen ID:*** | 1009855614 |
| ***Layer:*** | 1 |
| ***Slot:*** | 10 |
| ***Screen Top Depth:*** | 11.890000343322754 |
| ***Screen End Depth:*** | 14.9399995803833 |
| ***Screen Material:*** | 5 |
| ***Screen Depth UOM:*** | m |
| ***Screen Diameter UOM:*** | cm |
| ***Screen Diameter:*** | 6.03000020980835 |

***Results of Well Yield Testing***

| | |
|---|---|
| ***Pumping Test Method Desc:*** | |
| ***Pump Test ID:*** | 1009856078 |
| ***Pump Set At:*** | |
| ***Static Level:*** | |
| ***Final Level After Pumping:*** | |
| ***Recommended Pump Depth:*** | |
| ***Pumping Rate:*** | |
| ***Flowing Rate:*** | |
| ***Recommended Pump Rate:*** | |
| ***Levels UOM:*** | m |

***Rate UOM:*** LPM
***Water State After Test Code:***
***Water State After Test:***
***Pumping Test Method:*** 0
***Pumping Duration HR:***
***Pumping Duration MIN:***
***Flowing:*** No

***Hole Diameter***

***Hole ID:*** 1009854399
***Diameter:*** 11.430000305175781
***Depth From:*** 0.0
***Depth To:*** 14.9399995803833
***Hole Depth UOM:*** m
***Hole Diameter UOM:*** cm

---

**79** | ***1 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***ARTEXT (OUT OF BUS)***
***225 METCALFE STREET, SUITE 710***
***OTTAWA ON K2P 1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON0940702
***Approval Years:*** 93,96,97,98
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** PLATEMAKING, ETC.

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 2821

***Waste Detail(s)***

***Waste Class:*** 264
***Waste Class Name:*** PHOTOPROCESSING WASTES

---

**79** | ***2 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***ARTEXT ELECTRONIC PUBLISHING INC.***
***225 METCALFE STREET, SUITE 710***
***OTTAWA ON K2P 1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON0940702
***Approval Years:*** 94,95
***Status:***
***PO Box No:***
***Country:***
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** PLATEMAKING, ETC.

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:*** 2821

***Waste Detail(s)***

***Waste Class:*** 264
***Waste Class Name:*** PHOTOPROCESSING WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 3 of 36 | N/190.2 | 73.9 / 0.00 | TAGGART CORPORATION<br>708-225 Metcalfe Street<br>OTTAWA ON K2P 1P9 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON2565000 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 07,08 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 531310 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Real Estate Property Managers | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 243 |
| ***Waste Class Name:*** | PCB'S |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 4 of 36 | N/190.2 | 73.9 / 0.00 | Drs. John and Micaela Fitzgerald Dentistry Profess<br>225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON9590766 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***Approval Years:*** | 2016 | ***Contaminated Fac:*** | No |
| ***Status:*** | | ***MHSW Facility:*** | No |
| ***PO Box No:*** | | ***SIC Code:*** | 621210 |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | Tracy Hayball | | |
| ***Phone No Admin:*** | 613-235-9832 Ext. | | |
| ***SIC Description:*** | OFFICES OF DENTISTS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 148 |
| ***Waste Class Name:*** | INORGANIC LABORATORY CHEMICALS |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 5 of 36 | N/190.2 | 73.9 / 0.00 | Drs. John and Micaela Fitzgerald Dentistry Profess<br>225 Metcalfe Street Suite 102<br>Ottawa ON K2P 1P9 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON9590766 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***Approval Years:*** | 2015 | ***Contaminated Fac:*** | No |
| ***Status:*** | | ***MHSW Facility:*** | No |

**PO Box No:** **SIC Code:** 621210
**Country:** Canada
**Co Admin:** Tracy Hayball
**Phone No Admin:** 613-235-9832 Ext.
**SIC Description:** OFFICES OF DENTISTS

***Waste Detail(s)***

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 6 of 36 | N/190.2 | 73.9 / 0.00 | **Dr. J. Li Dentistry Professional Corporation**<br>**400-225 Metcalfe Street**<br>**Ottawa ON K2P1P9** | GEN |

***Generator Info***

**Generator No:** ON6802303 **Choice of Contact:** CO_OFFICIAL
**Approval Years:** 2016 **Contaminated Fac:** No
**Status:** **MHSW Facility:** No
**PO Box No:** **SIC Code:** 621390
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:** OFFICES OF ALL OTHER HEALTH PRACTITIONERS

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

***Waste Detail(s)***

**Waste Class:** 261
**Waste Class Name:** PHARMACEUTICALS

***Waste Detail(s)***

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

**Waste Class:** 264
**Waste Class Name:** PHOTOPROCESSING WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 7 of 36 | N/190.2 | 73.9 / 0.00 | **dr stanley shiff/dr dana shiff**<br>**225 metcalfe st suite 503**<br>**ottawa ON K2P1P9** | GEN |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3303382 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***Approval Years:*** | 2016 | ***Contaminated Fac:*** | No |
| ***Status:*** | | ***MHSW Facility:*** | No |
| ***PO Box No:*** | | ***SIC Code:*** | 621210 |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | dana shiff | | |
| ***Phone No Admin:*** | 613 232-4436 Ext. | | |
| ***SIC Description:*** | OFFICES OF DENTISTS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 8 of 36 | N/190.2 | 73.9 / 0.00 | ***Dr. J. Li Dentistry Professional Corporation***<br>***400-225 Metcalfe Street***<br>***Ottawa ON K2P1P9*** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON6802303 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***Approval Years:*** | 2015 | ***Contaminated Fac:*** | No |
| ***Status:*** | | ***MHSW Facility:*** | No |
| ***PO Box No:*** | | ***SIC Code:*** | 621390 |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | OFFICES OF ALL OTHER HEALTH PRACTITIONERS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 9 of 36 | N/190.2 | 73.9 / 0.00 | ***Drs. John and Micaela Fitzgerald Dentistry Profess***<br>***225 Metcalfe Street Suite 102***<br>***Ottawa ON K2P 1P9*** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON9590766 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***Approval Years:*** | 2014 | ***Contaminated Fac:*** | No |
| ***Status:*** | | ***MHSW Facility:*** | No |
| ***PO Box No:*** | | ***SIC Code:*** | 621210 |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | Tracy Hayball | | |
| ***Phone No Admin:*** | 613-235-9832 Ext. | | |
| ***SIC Description:*** | OFFICES OF DENTISTS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Detail(s)***

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

---

**79** | ***10 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***Dr. J. Li Dentistry Professional Corporation*** ***400-225 Metcalfe Street*** ***Ottawa ON K2P1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON6802303
***Approval Years:*** 2014
***Status:***
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:*** OFFICES OF ALL OTHER HEALTH PRACTITIONERS

***Choice of Contact:*** CO_OFFICIAL
***Contaminated Fac:*** No
***MHSW Facility:*** No
***SIC Code:*** 621390

***Waste Detail(s)***

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**79** | ***11 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***dr stanley shiff/dr dana shiff*** ***225 metcalfe st suite 503*** ***ottawa ON K2P1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON3303382
***Approval Years:*** As of Dec 2018
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

**79** | ***12 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***Drs. John and Micaela Fitzgerald Dentistry Profess*** ***225 Metcalfe Street Suite 102*** ***Ottawa ON K2P 1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON9590766
***Approval Years:*** As of Dec 2018
***Status:*** Registered
***PO Box No:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

***Waste Detail(s)***

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

---

**79** | ***13 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***Dr. J. Li Dentistry Professional Corporation*** ***400-225 Metcalfe Street*** ***Ottawa ON K2P1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON6802303
***Approval Years:*** As of Dec 2018
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 264 L
***Waste Class Name:*** Photoprocessing wastes

***Waste Detail(s)***

***Waste Class:*** 148 B
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Detail(s)***

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Detail(s)***

***Waste Class:*** 261 A
***Waste Class Name:*** Pharmaceuticals

***Waste Detail(s)***

***Waste Class:*** 264 T
***Waste Class Name:*** Photoprocessing wastes

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** Pathological wastes

***2017 Generator Info***

**Gen No:** ON6802303
**ID:** 26756
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621390
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Dr. J. Li Dentistry Professional Corporation
**Gen Div:**
**Gen Op Name:** Dr. J. Li Dentistry Professional Corporation
**Gen Op Div:**
**Site Adrs1:** 400-225 Metcalfe Street
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P1P9
**Site Country:** Canada
**Co Official:** Jingjing Li
**Co Admin:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 6132328090 Ext.
**Phone No Admin:**
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2017 Generator Manifest***

**ID:** 52702
**Generator No:** ON6802303
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 4.1
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 1
**District:** 402

***2018 Generator Info***

**Gen No:** ON6802303
**ID:** 27124
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621390
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Dr. J. Li Dentistry Professional Corporation
**Gen Div:**
**Gen Op Name:** Dr. J. Li Dentistry Professional Corporation
**Gen Op Div:**
**Site Adrs1:** 400-225 Metcalfe Street
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P1P9
**Site Country:** Canada
**Co Official:** Jingjing Li
**Co Admin:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 6132328090 Ext.
**Phone No Admin:**
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 52664 | ***Sum Received Qty:*** | 7.4 |
| ***Generator No:*** | ON6802303 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | *14 of 36* | *N/190.2* | *73.9 / 0.00* | ***Metcalfe Street Dental***<br>***225 Metcalfe Street, Unit 104***<br>***Ottawa ON K2P1P9*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON6860508 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Dec 2018 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | Pathological wastes |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | *15 of 36* | *N/190.2* | *73.9 / 0.00* | ***dr stanley shiff/dr dana shiff***<br>***225 metcalfe st suite 503***<br>***ottawa ON K2P1P9*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3303382 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Jul 2020 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | Pathological wastes |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | *16 of 36* | *N/190.2* | *73.9 / 0.00* | ***Drs. John and Micaela Fitzgerald Dentistry Profess***<br>***225 Metcalfe Street Suite 102***<br>***Ottawa ON K2P 1P9*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON9590766 | ***Choice of Contact:*** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Approval Years:*** As of Jul 2020
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

***Waste Detail(s)***

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

---

**79** | ***17 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***Metcalfe Street Dental***
***225 Metcalfe Street, Unit 104***
***Ottawa ON K2P1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON6860508
***Approval Years:*** As of Oct 2019
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***
***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

***2018 Generator Info***

***Gen No:*** ON6860508
***ID:*** 27346
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 621210
***NAICS Code2:***
***NAICS Code3:***
***Gen Name:*** Metcalfe Street Dental
***Gen Div:***
***Gen Op Name:*** Metcalfe Street Dental
***Gen Op Div:***
***Site Adrs1:*** 225 Metcalfe Street, Unit 104
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P1P9
***Site Country:*** Canada
***Choice of Contact:*** CO_OFFICIAL
***Phone No Official:*** 6132377177 Ext.
***Phone No Admin:*** 6132377177 Ext.
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402

***Co Official:*** Harris Prehogan
***Co Admin:*** Maisoun Al-Syoti

***2019 Generator Info***

***Gen No:*** ON6860508
***ID:*** 27582
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 621210
***NAICS Code2:***
***NAICS Code3:***
***Gen Name:*** Metcalfe Street Dental
***Gen Div:***
***Gen Op Name:*** Metcalfe Street Dental
***Gen Op Div:***
***Site Adrs1:*** 225 Metcalfe Street, Unit 104
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P1P9
***Site Country:*** Canada
***Co Official:*** Harris Prehogan
***Co Admin:*** Maisoun Al-Syoti

***Choice of Contact:*** CO_OFFICIAL
***Phone No Official:*** 6132377177 Ext.
***Phone No Admin:*** 6132377177 Ext.
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402

---

| | | | | | |
|---|---|---|---|---|---|
| 79 | ***18 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***Metcalfe Street Dental***<br>***225 Metcalfe Street Unit 104***<br>***Ottawa ON K2P1P9*** | ***GEN*** |

***Generator Info***

***Generator No:*** ON3471838
***Approval Years:*** As of Jul 2020
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

| | | | | | |
|---|---|---|---|---|---|
| 79 | ***19 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***dr stanley shiff/dr dana shiff***<br>***225 metcalfe st suite 503***<br>***ottawa ON K2P1P9*** | ***GEN*** |

***Generator Info***

***Generator No:*** ON3303382
***Approval Years:*** As of Nov 2021
***Status:*** Registered
***PO Box No:***
***Country:*** Canada

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

**79** | ***20 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***Drs. John and Micaela Fitzgerald Dentistry Profess***
***225 Metcalfe Street Suite 102***
***Ottawa ON K2P 1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON9590766
***Approval Years:*** As of Nov 2021
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

**79** | ***21 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***Metcalfe Street Dental***
***225 Metcalfe Street Unit 104***
***Ottawa ON K2P1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON3471838
***Approval Years:*** As of Nov 2021
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** Pathological wastes

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 22 of 36 | N/190.2 | 73.9 / 0.00 | Capital Dentistry Group Ltd.<br>225 Metcalfe Street, Unit 104<br>Ottawa ON | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON3471838 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Oct 2022 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON3471838 |
| ***Generator Company Name:*** | Capital Dentistry Group Ltd. |
| ***Street:*** | 225 Metcalfe Street, Unit 104 |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1P9 |
| ***Waste Class:*** | 312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | Capital Dentistry Group Ltd. |
| ***Generator Site Address:*** | 225 Metcalfe Street, Unit 104 |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1P9 |
| ***Waste Class:*** | 312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES

***Waste Characteristic Decoded:***

P - Pathological

***2019 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3471838 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 13616 | ***Phone No Official:*** | 613-237-7177 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-237-7177 Ext. |

| | | | |
|---|---|---|---|
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621210 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Metcalfe Street Dental | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | Metcalfe Street Dental | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 225 Metcalfe Street | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | Unit 104 | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P1P9 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | Reem Haidar | | |
| ***Co Admin:*** | Maisoun Al-Syoti | | |

***2019 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 35508 | ***Sum Received Qty:*** | 17.0 |
| ***Generator No:*** | ON3471838 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 2 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

***2020 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3471838 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 13282 | ***Phone No Official:*** | 613-237-7177 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-237-7177 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621210 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Metcalfe Street Dental | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | Metcalfe Street Dental | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 225 Metcalfe Street | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | Unit 104 | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P1P9 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | Karen L | | |
| ***Co Admin:*** | Maisoun Al-Syoti | | |

***2020 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 32696 | ***Sum Received Qty:*** | 3.2 |
| ***Generator No:*** | ON3471838 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

***2021 Generator Info***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Gen No:** ON3471838
**ID:** 13142
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621210
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Metcalfe Street Dental
**Gen Div:**
**Gen Op Name:** Metcalfe Street Dental
**Gen Op Div:**
**Site Adrs1:** 225 Metcalfe Street
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:** Unit 104
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P1P9
**Site Country:** Canada
**Co Official:** Karen L
**Co Admin:** Maisoun Al-Syoti
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 613-237-7177 Ext.
**Phone No Admin:** 613-237-7177 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2021 Generator Manifest***

**ID:** 33209
**Generator No:** ON3471838
**Receiver Type:** 030
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 6.1
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 1
**District:** 402

---

| | | | | | |
|---|---|---|---|---|---|
| 79 | 23 of 36 | N/190.2 | 73.9 / 0.00 | ***Drs. John and Micaela Fitzgerald Dentistry Profess***<br>***225 Metcalfe Street Suite 102***<br>***Ottawa ON K2P 1P9*** | GEN |

***Generator Info***

**Generator No:** ON9590766
**Approval Years:** As of Oct 2022
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**
**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 148 C
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** PATHOLOGICAL WASTES

***2017 Generator Info***

| | | | |
|---|---|---|---|
| **Gen No:** | ON9590766 | **Choice of Contact:** | CO_OFFICIAL |
| **ID:** | 37463 | **Phone No Official:** | 613-235-9832 Ext. |
| **Contaminated Fac:** | N | **Phone No Admin:** | 613-235-9832 Ext. |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 621210 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | Drs. John and Micaela Fitzgerald Dentistry Profess | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | Drs. John and Micaela Fitzgerald Dentistry Profess | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 225 Metcalfe Street | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | Suite 102 | | |
| **Site City:** | Ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P 1P9 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | Micaela Fitzgerald | | |
| **Co Admin:** | Tracy Hayball | | |

***2017 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 66247 | **Sum Received Qty:** | 13.8 |
| **Generator No:** | ON9590766 | **Waste Class Name:** | PATHOLOGICAL WASTES |
| **Receiver Type:** | 030 | **Count Manifests:** | 2 |
| **Waste Char:** | P | **District:** | 402 |
| **Waste Code:** | 312 | | |

***2018 Generator Info***

| | | | |
|---|---|---|---|
| **Gen No:** | ON9590766 | **Choice of Contact:** | CO_OFFICIAL |
| **ID:** | 38202 | **Phone No Official:** | 613-235-9832 Ext. |
| **Contaminated Fac:** | N | **Phone No Admin:** | 613-235-9832 Ext. |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 621210 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | Drs. John and Micaela Fitzgerald Dentistry Profess | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | Drs. John and Micaela Fitzgerald Dentistry Profess | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 225 Metcalfe Street | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | Suite 102 | | |
| **Site City:** | Ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P 1P9 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | Micaela Fitzgerald | | |
| **Co Admin:** | Tracy Hayball | | |

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 66804 | **Sum Received Qty:** | 5.8 |
| **Generator No:** | ON9590766 | **Waste Class Name:** | PATHOLOGICAL WASTES |
| **Receiver Type:** | 030 | **Count Manifests:** | 1 |
| **Waste Char:** | P | **District:** | 402 |
| **Waste Code:** | 312 | | |

***2019 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON9590766 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 38767 | ***Phone No Official:*** | 613-235-9832 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-235-9832 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621210 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |

***Gen Name:*** Drs. John and Micaela Fitzgerald Dentistry Profess
***Gen Div:***
***Gen Op Name:*** Drs. John and Micaela Fitzgerald Dentistry Profess
***Gen Op Div:***
***Site Adrs1:*** 225 Metcalfe Street
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** Suite 102
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 1P9
***Site Country:*** Canada
***Co Official:*** Micaela Fitzgerald
***Co Admin:*** Micaela Fitzgerald

***2019 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 66857 | ***Sum Received Qty:*** | 9.0 |
| ***Generator No:*** | ON9590766 | ***Waste Class Name:*** | INORGANIC LABORATORY CHEMICALS |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | C | ***District:*** | 402 |
| ***Waste Code:*** | 148 | | |

***2019 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 66856 | ***Sum Received Qty:*** | 11.0 |
| ***Generator No:*** | ON9590766 | ***Waste Class Name:*** | INORGANIC LABORATORY CHEMICALS |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | C | ***District:*** | 305 |
| ***Waste Code:*** | 148 | | |

***2020 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON9590766 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 38521 | ***Phone No Official:*** | 613-235-9832 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-235-9832 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621210 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |

***Gen Name:*** Drs. John and Micaela Fitzgerald Dentistry Profess
***Gen Div:***
***Gen Op Name:*** Drs. John and Micaela Fitzgerald Dentistry Profess
***Gen Op Div:***
***Site Adrs1:*** 225 Metcalfe Street
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:*** Suite 102
***Site City:*** Ottawa
***Province Out:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Site Postal Code:** K2P 1P9
**Site Country:** Canada
**Co Official:** Micaela Fitzgerald
**Co Admin:** Micaela Fitzgerald

***2021 Generator Info***

**Gen No:** ON9590766
**ID:** 39566
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621210
**NAICS Code2:**
**NAICS Code3:**
**Choice of Contact:** CO_ADMIN
**Phone No Official:** 613-235-9832 Ext.
**Phone No Admin:** 613-235-9832 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402
**Gen Name:** Drs. John and Micaela Fitzgerald Dentistry Profess
**Gen Div:**
**Gen Op Name:** Drs. John and Micaela Fitzgerald Dentistry Profess
**Gen Op Div:**
**Site Adrs1:** 225 Metcalfe Street
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:** Suite 102
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1P9
**Site Country:** Canada
**Co Official:** Micaela Fitzgerald
**Co Admin:** Micaela Fitzgerald

---

| | | | | | |
|---|---|---|---|---|---|
| 79 | 24 of 36 | N/190.2 | 73.9 / 0.00 | **Metcalfe and Cooper Family Dentistry**<br>**225 Metcalfe St. Unit 507**<br>**Ottawa ON K2P 1P9** | GEN |

***Generator Info***

**Generator No:** ON6216513
**Approval Years:** As of Oct 2022
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**
**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 263 I
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

***Waste Detail(s)***

**Waste Class:** 261 A
**Waste Class Name:** PHARMACEUTICALS

***Waste Detail(s)***

**Waste Class:** 148 C
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Detail(s)***

***Waste Class:*** 331 I
***Waste Class Name:*** WASTE COMPRESSED GASES

***Waste Detail(s)***

***Waste Class:*** 263 L
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

---

**79** | ***25 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***Dr. Amar Kuruganti Dentistry Professional Corporat Kenson Downtown Dentistry 225 Metcalfe Street Suite 504 Ottawa ON K2P 1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON8020192
***Approval Years:*** As of Oct 2022
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** PATHOLOGICAL WASTES

---

**79** | ***26 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***dr stanley shiff/dr dana shiff 225 metcalfe st suite 503 ottawa ON K2P1P9*** | ***GEN***

***Generator Info***

***Generator No:*** ON3303382
***Approval Years:*** As of Oct 2022
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 312 P
***Waste Class Name:*** PATHOLOGICAL WASTES

***2017 Generator Info***

***Gen No:*** ON3303382
***ID:*** 13342
***Contaminated Fac:*** N

***Choice of Contact:*** CO_OFFICIAL
***Phone No Official:*** 613 232-4436 Ext.
***Phone No Admin:*** 613 232-4436 Ext.

| | | | |
|---|---|---|---|
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 621210 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | dr stanley shiff/dr dana shiff | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | dr stanley shiff/ drdana shiff | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 225 metcalfe st suite 503 | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | | | |
| **Site City:** | ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P1P9 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | stanley S shiff | | |
| **Co Admin:** | dana shiff | | |

***2017 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 35594 | **Sum Received Qty:** | 4.0 |
| **Generator No:** | ON3303382 | **Waste Class Name:** | PATHOLOGICAL WASTES |
| **Receiver Type:** | 035 | **Count Manifests:** | 1 |
| **Waste Char:** | P | **District:** | 306 |
| **Waste Code:** | 312 | | |

***2018 Generator Info***

| | | | |
|---|---|---|---|
| **Gen No:** | ON3303382 | **Choice of Contact:** | CO_OFFICIAL |
| **ID:** | 13185 | **Phone No Official:** | 613 232-4436 Ext. |
| **Contaminated Fac:** | N | **Phone No Admin:** | 613 232-4436 Ext. |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 621210 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | dr stanley shiff/dr dana shiff | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | dr stanley shiff/ drdana shiff | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 225 metcalfe st suite 503 | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | | | |
| **Site City:** | ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P1P9 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | stanley S shiff | | |
| **Co Admin:** | dana shiff | | |

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 35449 | **Sum Received Qty:** | 7.0 |
| **Generator No:** | ON3303382 | **Waste Class Name:** | PATHOLOGICAL WASTES |
| **Receiver Type:** | 035 | **Count Manifests:** | 1 |
| **Waste Char:** | P | **District:** | 306 |
| **Waste Code:** | 312 | | |

***2019 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3303382 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 12953 | ***Phone No Official:*** | 613 232-4436 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613 232-4436 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621210 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | dr stanley shiff/dr dana shiff | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | dr stanley shiff/ drdana shiff | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 225 metcalfe st suite 503 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P1P9 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | stanley S shiff | | |
| ***Co Admin:*** | dana M shiff | | |

***2019 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 34704 | ***Sum Received Qty:*** | 6.0 |
| ***Generator No:*** | ON3303382 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | P | ***District:*** | 306 |
| ***Waste Code:*** | 312 | | |

***2020 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3303382 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 12614 | ***Phone No Official:*** | 613 232-4436 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613 232-4436 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621210 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | dr stanley shiff/dr dana shiff | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | dr stanley shiff/ drdana shiff | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 225 metcalfe st suite 503 | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P1P9 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | stanley S shiff | | |
| ***Co Admin:*** | dana M shiff | | |

***2020 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 31930 | ***Sum Received Qty:*** | 7.0 |
| ***Generator No:*** | ON3303382 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | P | ***District:*** | 306 |

***Waste Code:*** 312

***2021 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON3303382 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 12450 | ***Phone No Official:*** | 613 232-4436 Ext. |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613 232-4436 Ext. |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621210 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |

| | |
|---|---|
| ***Gen Name:*** | dr stanley shiff/dr dana shiff |
| ***Gen Div:*** | |
| ***Gen Op Name:*** | dr stanley shiff/ drdana shiff |
| ***Gen Op Div:*** | |
| ***Site Adrs1:*** | 225 metcalfe st suite 503 |
| ***Site Bldg:*** | |
| ***Site Pobox:*** | |
| ***Province In:*** | ONTARIO |
| ***Site Adrs2:*** | |
| ***Site City:*** | ottawa |
| ***Province Out:*** | |
| ***Site Postal Code:*** | K2P1P9 |
| ***Site Country:*** | Canada |
| ***Co Official:*** | stanley S shiff |
| ***Co Admin:*** | dana M shiff |

***2021 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 32357 | ***Sum Received Qty:*** | 14.0 |
| ***Generator No:*** | ON3303382 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 2 |
| ***Waste Char:*** | P | ***District:*** | 306 |
| ***Waste Code:*** | 312 | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 27 of 36 | N/190.2 | 73.9 / 0.00 | ***Kenson Downtown Dentistry***<br>***225 Metcalfe Street, Suite 504***<br>***Ottawa ON*** | ***GEN*** |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON8020192 |
| ***Generator Company Name:*** | Kenson Downtown Dentistry |
| ***Street:*** | 225 Metcalfe Street, Suite 504 |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1P9 |
| ***Waste Class:*** | 312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | Kenson Downtown Dentistry |
| ***Generator Site Address:*** | 225 Metcalfe Street, Suite 504 |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |

***Country:*** Canada
***Postal Code:*** K2P1P9
***Waste Class:*** 312 P

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES

***Waste Characteristic Decoded:***

P - Pathological

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 28 of 36 | N/190.2 | 73.9 / 0.00 | DR STANLEY SHIFF<br>225 Metcalfe Street<br>Ottawa ON | GEN |

***Generator Info (as of Dec 2024)***

***Generator No:*** ON001061512
***Generator Company Name:*** DR STANLEY SHIFF
***Street:*** 225 Metcalfe Street
***City:*** Ottawa
***Province State:*** Ontario
***Country:*** Canada
***Postal Code:*** K2P 1P9
***Waste Class:*** 312 P, 148 B, 312 P, 312 P, 263 L, 331 I, 148 C, 263 I, 261 A, 312 P

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 148 - INORGANIC LABORATORY CHEMICALS; 312 - PATHOLOGICAL WASTES; 312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Generator Info (as of Dec 2024)***

***Generator No:*** ON001061512
***Generator Company Name:*** DR STANLEY SHIFF
***Street:*** 225 Metcalfe Street
***City:*** Ottawa
***Province State:*** Ontario
***Country:*** Canada
***Postal Code:*** K2P 1P9
***Waste Class:*** 148 B,312 P,312 P

***Waste Class Decoded:***

148 - INORGANIC LABORATORY CHEMICALS; 312 - PATHOLOGICAL WASTES; 312 - PATHOLOGICAL WASTES

***Generator Info (as of Apr 2025)***

***Generator Company Name:*** DR STANLEY SHIFF
***Generator Site Address:*** 225 Metcalfe Street
***City:*** Ottawa
***Province State:*** Ontario
***Country:*** Canada
***Postal Code:*** K2P 1P9
***Waste Class:*** 148 B, 312 P

***Waste Class Decoded:***

148 - INORGANIC LABORATORY CHEMICALS; 312 - PATHOLOGICAL WASTES

***Waste Characteristic Decoded:***

B - Hazardous Waste Chemical; P - Pathological

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 29 of 36 | N/190.2 | 73.9 / 0.00 | **Capital Dentistry Group Ltd.**<br>**225 Metcalfe Street**<br>**Ottawa ON** | GEN |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON6216513 |
| ***Generator Company Name:*** | Capital Dentistry Group Ltd. |
| ***Street:*** | 225 Metcalfe Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P 1P9 |
| ***Waste Class:*** | 312 P, 148 B, 312 P, 312 P, 263 L, 331 I, 148 C, 263 I, 261 A, 312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 148 - INORGANIC LABORATORY CHEMICALS; 312 - PATHOLOGICAL WASTES; 312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON6216513 |
| ***Generator Company Name:*** | Capital Dentistry Group Ltd. |
| ***Street:*** | 225 Metcalfe Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P 1P9 |
| ***Waste Class:*** | 312 P,263 L,331 I,148 C,263 I,261 A,312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | Capital Dentistry Group Ltd. |
| ***Generator Site Address:*** | 225 Metcalfe Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P 1P9 |
| ***Waste Class:*** | 312 P, 263 L, 331 I, 148 C, 263 I, 261 A, 312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC

LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Waste Characteristic Decoded:***

P - Pathological; L - Liquid Industrial Waste; I - Ignitable; C - Corrosive; I - Ignitable; A - Acutely Hazardous Waste Chem.; P - Pathological

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 79 | 30 of 36 | N/190.2 | 73.9 / 0.00 | ***Capital Dentistry Group Ltd.***<br>***225 Metcalfe Street***<br>***Ottawa ON*** | GEN |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON001055229 |
| ***Generator Company Name:*** | Capital Dentistry Group Ltd. |
| ***Street:*** | 225 Metcalfe Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1P9 |
| ***Waste Class:*** | 312 P, 148 B, 312 P, 312 P, 263 L, 331 I, 148 C, 263 I, 261 A, 312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 148 - INORGANIC LABORATORY CHEMICALS; 312 - PATHOLOGICAL WASTES; 312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON001055229 |
| ***Generator Company Name:*** | Capital Dentistry Group Ltd. |
| ***Street:*** | 225 Metcalfe Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1P9 |
| ***Waste Class:*** | 312 P,263 L,331 I,148 C,263 I,261 A,312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | Capital Dentistry Group Ltd. |
| ***Generator Site Address:*** | 225 Metcalfe Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1P9 |
| ***Waste Class:*** | 312 P, 263 L, 331 I, 148 C, 263 I, 261 A, 312 P |

***Waste Class Decoded:***

312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Waste Characteristic Decoded:***

P - Pathological; L - Liquid Industrial Waste; I - Ignitable; C - Corrosive; I - Ignitable; A - Acutely Hazardous Waste Chem.; P - Pathological

---

**79** | ***31 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***TAGGART CORPORATION***
***225 METCALFE STREET SUITE 708***
***OTTAWA ON K2P 1P9*** | ***NPCB***

***Company Code:*** F1361
***Industry:*** Undefined
***Site Status:*** Stored for Disposal
***Transaction Date:*** 12/30/1995
***Inspection Date:***

***--Details--***
***Label:***
***Serial No.:***
***PCB Type/Code:*** Askarel/Askarel
***Location:***
***Item/State:***
***No. of Items:***
***Manufacturer:***
***Status:*** Stored for disposal
***Contents:***

---

**79** | ***32 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***TAGGART CORPORATION***
***225 METCALFE STREET, SUITE 708***
***OTTAWA ON K2P 1P9*** | ***OPCB***

***Year:*** 2003
***Site Number:*** 40294A012
***Name Owner:***
***Additional Site Information:***

***--Details--***
***Quantity:*** 1.00
***Address Site:***
***Description:*** Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

***Quantity:*** 800.00
***Address Site:***
***Description:*** Weight of Drums of Ballasts with High Level PCBs (>1000 ppm) kg

---

**79** | ***33 of 36*** | ***N/190.2*** | ***73.9 / 0.00*** | ***TAGGART CORPORATION***
***225 METCALFE STREET, SUITE 708***
***OTTAWA ON K2P 1P9*** | ***OPCB***

***Year:*** 2004
***Site Number:*** 40294A012
***Name Owner:***
***Additional Site Information:***

***--Details--***
***Quantity:*** 1
***Address Site:***
***Description:*** Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Quantity:** | | 800 | | | |
| **Address Site:** | | | | | |
| **Description:** | | Weight of Drums of Ballasts with High Level PCBs (>1000 ppm) kg | | | |

| | | | | | |
|---|---|---|---|---|---|
| 79 | 34 of 36 | N/190.2 | 73.9 / 0.00 | **F K Dental Lab Ltd**<br>**225 Metcalfe St Suite 500**<br>**Ottawa ON K2P 1P9** | SCT |

**Scott S ID:** 32901185
**Latitude:**
**Longitude:**

***Historical Details***

**Established:**
**Plant Size (ft²):**
**Employment:**

***Historical Details***

**Description:** Medical Equipment and Supplies Manufacturing
**SIC/NAICS Code:** 339110

| | | | | | |
|---|---|---|---|---|---|
| 79 | 35 of 36 | N/190.2 | 73.9 / 0.00 | **Chromatek Dental Laboratories**<br>**225 Metcalfe St Suite 500**<br>**Ottawa ON K2P 1P9** | SCT |

**Scott S ID:** 32901185
**Latitude:**
**Longitude:**

***Historical Details***

**Established:** 01-AUG-79
**Plant Size (ft²):**
**Employment:**

***Historical Details***

**Description:** Medical Equipment and Supplies Manufacturing
**SIC/NAICS Code:** 339110

***Historical Details***

**Description:** Medical Equipment and Supplies Manufacturing
**SIC/NAICS Code:** 339110

| | | | | | |
|---|---|---|---|---|---|
| 79 | 36 of 36 | N/190.2 | 73.9 / 0.00 | **Ottawa Dentistry**<br>**225 Metcalfe St**<br>**Ottawa ON K2P1P9** | SCT |

**Scott S ID:** 302479392
**Latitude:** 45.4176
**Longitude:** -75.6925

***Details***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Bus Type 1:** | Health Services | **Employee Count:** | 8 |
| **Bus Type 2:** | Manufacturer | **Square Footage:** | 0 |
| **Bus Type 3:** | | **Estimated Sales:** | Under $1 Million |
| **Product Cat 1:** | Cosmetic dentist | **Export Indicator:** | |
| **Product Cat 2:** | Dental clinic | **Export Country 1:** | |
| **Product Cat 3:** | Dental hygienist | **Export Country 2:** | |
| **Product Cat 4:** | Dental implants provider | **Export Country 3:** | |
| **Product Cat 5:** | Dentist | **Export Country 4:** | |
| **Product Cat 6:** | Denture care center | **Export Country 5:** | |
| **Product Cat 7:** | Emergency dental service | **Export Country 6:** | |
| **Product Cat 8:** | Oral surgeon | **Geocoded by:** | Address |
| **Company Name:** | Ottawa Dentistry | | |
| **Address Line 1:** | 225 Metcalfe St | | |
| **Address Line 2:** | | | |
| **City:** | Ottawa | | |
| **Province:** | ON | | |
| **Postal Code:** | K2P1P9 | | |
| **Census Division:** | Ottawa; ON | | |
| **Metro Area:** | Ottawa/Hull | | |
| **Year Established:** | 1991 | | |
| **Head Office Indicator:** | | | |
| **Parent Company Nm:** | | | |
| **Parent Cmpny Addr 1:** | | | |
| **Parent Cmpny Addr 2:** | | | |
| **Parent Cmpny City:** | | | |
| **Parent Cmpny Prov:** | | | |
| **Parent Cmpy PC:** | | | |
| **Parent Cmpy Cntry:** | | | |
| **Head Office Nm:** | | | |
| **H Office Addr Line 1:** | | | |
| **H Office Addr Line 2:** | | | |
| **Head Office City:** | | | |
| **Head Office Province:** | | | |
| **Head Office PC:** | | | |
| **Head Office Cntry:** | | | |
| **Telephone:** | 613-234-1595 | | |
| **Fax:** | | | |
| **Website:** | https://www.ottawadentistry.ca/site/home?utm_source=G | | |
| **Pri NAICS Desc:** | 621210-Offices of Dentists | | |
| **NAICS Code 1:** | 339110-Medical Equipment and Supplies Manufacturin | | |
| **NAICS Code 2:** | 621210-Offices of Dentists | | |
| **NAICS Code 3:** | | | |
| **NAICS Code 4:** | | | |
| **NAICS Code 5:** | | | |

**80** | ***1 of 1*** | ***ESE/190.4*** | ***72.9 / -1.00*** | ***305 Metcalfe St Ottawa ON K2P1S1*** | ***EHS***

| | | | |
|---|---|---|---|
| **Order No:** | 20140918058 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 24-SEP-14 | **Search Radius (km):** | .25 |
| **Date Received:** | 18-SEP-14 | **X:** | -75.690162 |
| **Previous Site Name:** | | **Y:** | 45.415061 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

**81** | ***1 of 1*** | ***W/192.4*** | ***75.9 / 2.00*** | ***324 Somerset Street West Ottawa ON K2P 0J9*** | ***EHS***

| | | | |
|---|---|---|---|
| **Order No:** | 20041214013 | **Nearest Intersection:** | Somerset Street West |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Report Date:** | 12/16/04 | **Search Radius (km):** | 0.25 |
| **Date Received:** | 12/14/04 | **X:** | -75.694783 |
| **Previous Site Name:** | | **Y:** | 45.415917 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

**82** | **1 of 1** | **W/192.8** | **75.9 / 2.00** | **322 SOMERSET STREET WEST OTTAWA ON** | **HINC**

| | |
|---|---|
| **External File Num:** | FS INC 0611-04091 |
| **Fuel Occurrence Type:** | Pipeline Strike |
| **Date of Occurrence:** | 11/27/2006 |
| **Fuel Type Involved:** | Natural Gas |
| **Status Desc:** | Completed - Causal Analysis(End) |
| **Job Type Desc:** | Incident/Near-Miss Occurrence (FS) |
| **Oper. Type Involved:** | Commercial (e.g. restaurant, business unit, etc) |
| **Service Interruptions:** | No |
| **Property Damage:** | No |
| **Fuel Life Cycle Stage:** | Utilization |
| **Root Cause:** | Root Cause: Equipment/Material/Component:No Procedures:Yes Maintenance:No Design:No Training: Yes Management:No Human Factors:No |
| **Reported Details:** | |
| **Fuel Category:** | Gaseous Fuel |
| **Occurrence Type:** | Incident |
| **Affiliation:** | Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.) |
| **County Name:** | Ottawa |
| **Approx. Quant. Rel:** | |
| **Nearby body of water:** | |
| **Enter Drainage Syst.:** | |
| **Approx. Quant. Unit:** | |
| **Environmental Impact:** | |

---

**83** | **1 of 1** | **W/193.8** | **75.9 / 2.00** | **234 O'connor St Ottawa ON K2P1T9** | **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 20150626030 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 06-JUL-15 | **Search Radius (km):** | .25 |
| **Date Received:** | 26-JUN-15 | **X:** | -75.694742 |
| **Previous Site Name:** | | **Y:** | 45.416336 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

**84** | **1 of 1** | **W/194.2** | **75.9 / 2.00** | **311 Somerset Street West Ottawa ON K2P 0J8** | **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 21011400150 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 22-JAN-21 | **Search Radius (km):** | .25 |
| **Date Received:** | 14-JAN-21 | **X:** | -75.6947834 |
| **Previous Site Name:** | | **Y:** | 45.4162153 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | |

---

**85** | **1 of 1** | **SW/194.5** | **74.9 / 1.00** | **350-352 Gilmour Street and 453 Lewis Street Ottawa, Ontario Ottawa ON K2P 0R3** | **EHS**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Order No:** 25040900839
**Status:** C
**Report Type:** Standard Report
**Report Date:** 11-APR-25
**Date Received:** 09-APR-25
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans; City Directory

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** AB
**Search Radius (km):** .25
**X:** -75.6937338
**Y:** 45.4144722

---

**86** *1 of 2* *S/195.7* *73.9 / 0.00*

***CRAIG OFFICE PRODUCTS CORPORATION***
***329 WAVERLEY STREET***
***OTTAWA ON K2P 0V9***

***GEN***

***Generator Info***

**Generator No:** ON0961400
**Approval Years:** 86,87,88,89,90
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** *** NOT DEFINED ***

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 0000

***Waste Detail(s)***

**Waste Class:** 213
**Waste Class Name:** PETROLEUM DISTILLATES

---

**86** *2 of 2* *S/195.7* *73.9 / 0.00*

***CRAIG OFFICE PRODUCTS CORPORATION 11-330***
***329 WAVERLEY STREET***
***OTTAWA ON K2P 0V9***

***GEN***

***Generator Info***

**Generator No:** ON0961400
**Approval Years:** 92,93,94,95,96,97,98
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** ELECT. OFFICE, ETC.

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 3362

***Waste Detail(s)***

**Waste Class:** 213
**Waste Class Name:** PETROLEUM DISTILLATES

---

**87** *1 of 1* *WSW/196.8* *75.9 / 2.00*

***340 MacLaren Street***
***Ottawa ON K2P 0M6***

***EHS***

**Order No:** 20110825005
**Status:** C
**Report Type:** Custom Report

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Report Date:** | 8/31/2011 | **Search Radius (km):** | 0.25 |
| **Date Received:** | 8/25/2011 9:59:37 AM | **X:** | -75.69457 |
| **Previous Site Name:** | | **Y:** | 45.415106 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

**88** | **1 of 1** | **NW/199.0** | **74.8 / 0.97** | **320 Cooper Street Ottawa**
**Ottawa ON K2P 0G7** | **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 20321400026 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 17-DEC-20 | **Search Radius (km):** | .25 |
| **Date Received:** | 14-DEC-20 | **X:** | -75.6941526 |
| **Previous Site Name:** | | **Y:** | 45.417175 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

**89** | **1 of 2** | **W/200.7** | **75.9 / 2.00** | **326 Somerset St W**
**Ottawa ON K2P0J9** | **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 20170203024 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 08-FEB-17 | **Search Radius (km):** | .25 |
| **Date Received:** | 03-FEB-17 | **X:** | -75.69486 |
| **Previous Site Name:** | | **Y:** | 45.415713 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

**89** | **2 of 2** | **W/200.7** | **75.9 / 2.00** | **EnviroCentre**
**326 Somerset St. West**
**Ottawa ON K2P 0J9** | **GEN**

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON4708690 | **Choice of Contact:** | |
| **Approval Years:** | As of Nov 2021 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 263 I |
| **Waste Class Name:** | Misc. waste organic chemicals |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 263 L |
| **Waste Class Name:** | Misc. waste organic chemicals |

***Waste Detail(s)***

**Waste Class:** 331 I
**Waste Class Name:** Waste compressed gases including cylinders

***Waste Detail(s)***

**Waste Class:** 148 C
**Waste Class Name:** Misc. wastes and inorganic chemicals

***2021 Generator Info***

**Gen No:** ON4708690
**ID:** 18572
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 541620
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** EnviroCentre
**Gen Div:**
**Gen Op Name:** EnviroCentre
**Gen Op Div:**
**Site Adrs1:** 326 Somerset St. West
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 0J9
**Site Country:** Canada
**Co Official:** Melanie Johnston
**Co Admin:**

**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 613-894-4121 Ext.
**Phone No Admin:**
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2021 Generator Manifest***

**ID:** 39879
**Generator No:** ON4708690
**Receiver Type:** 035
**Waste Char:** I
**Waste Code:** 263

**Sum Received Qty:** 240.0
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS
**Count Manifests:** 1
**District:** 402

---

**90** | ***1 of 1*** | ***SSE/201.9*** | ***72.9 / -1.00*** | ***302 Waverley Street Ottawa ON K2P 0W3*** | ***EHS***

**Order No:** 20180807167
**Status:** C
**Report Type:** Standard Express Report
**Report Date:** 07-AUG-18
**Date Received:** 07-AUG-18
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans; City Directory

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.691258
**Y:** 45.414269

---

**91** | ***1 of 1*** | ***W/203.4*** | ***75.9 / 2.00*** | ***311 SOMERSET Ottawa ON*** | ***WWIS***

**Well ID:** 7391113
**Construction Date:**
**Use 1st:** Monitoring and Test Hole
**Use 2nd:**

**Flowing (Y/N):**
**Flow Rate:**
**Data Entry Status:**
**Data Src:**

| | | | |
|---|---|---|---|
| **Final Well Status:** | Monitoring and Test Hole | **Date Received:** | 06/29/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z364081 | **Contractor:** | 7241 |
| **Tag:** | A302973 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | OTTAWA CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7391113.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | 05/26/2021 |
| **Year Completed:** | 2021 |
| **Depth (m):** | 13.1 |
| **Latitude:** | 45.4162588191639 |
| **Longitude:** | -75.6948908336928 |
| **Point X:** | -75.69489067198141 |
| **Point Y:** | 45.416258812091236 |
| **Path:** | 739\7391113.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008704349 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445630.00 |
| **Code OB Desc:** | | **North83:** | 5029428.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 05/26/2021 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| **Formation ID:** | 1009852396 |
| **Layer:** | 1 |
| **Color:** | 2 |
| **General Color:** | GREY |
| **Material 1:** | 11 |
| **Material 1 Desc:** | GRAVEL |
| **Material 2:** | 28 |
| **Material 2 Desc:** | SAND |
| **Material 3:** | 77 |
| **Material 3 Desc:** | LOOSE |
| **Formation Top Depth:** | 0.0 |

***Formation End Depth:*** 0.3100000023841858
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009852397
***Layer:*** 2
***Color:*** 6
***General Color:*** BROWN
***Material 1:*** 28
***Material 1 Desc:*** SAND
***Material 2:*** 11
***Material 2 Desc:*** GRAVEL
***Material 3:*** 85
***Material 3 Desc:*** SOFT
***Formation Top Depth:*** 0.3100000023841858
***Formation End Depth:*** 2.440000057220459
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009852398
***Layer:*** 3
***Color:*** 6
***General Color:*** BROWN
***Material 1:*** 05
***Material 1 Desc:*** CLAY
***Material 2:*** 28
***Material 2 Desc:*** SAND
***Material 3:*** 85
***Material 3 Desc:*** SOFT
***Formation Top Depth:*** 2.440000057220459
***Formation End Depth:*** 3.6600000858306885
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009852399
***Layer:*** 4
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 05
***Material 1 Desc:*** CLAY
***Material 2:*** 06
***Material 2 Desc:*** SILT
***Material 3:*** 85
***Material 3 Desc:*** SOFT
***Formation Top Depth:*** 3.6600000858306885
***Formation End Depth:*** 11.279999732971191
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009852400
***Layer:*** 5
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 06

***Material 1 Desc:*** SILT
***Material 2:*** 11
***Material 2 Desc:*** GRAVEL
***Material 3:*** 66
***Material 3 Desc:*** DENSE
***Formation Top Depth:*** 11.279999732971191
***Formation End Depth:*** 13.100000381469727
***Formation End Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009853458
***Layer:*** 1
***Plug From:*** 0.0
***Plug To:*** 0.3100000023841858
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009853459
***Layer:*** 2
***Plug From:*** 0.3100000023841858
***Plug To:*** 9.75
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009853460
***Layer:*** 3
***Plug From:*** 9.75
***Plug To:*** 13.100000381469727
***Plug Depth UOM:*** m

***Method of Construction & Well Use***

***Method Construction ID:*** 1009854838
***Method Construction Code:*** 5
***Method Construction:*** Air Percussion
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 1009764983
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1009855216
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 10.050000190734863
***Casing Diameter:*** 5.199999809265137
***Casing Diameter UOM:*** cm

***Casing Depth UOM:*** m

***Construction Record - Screen***

***Screen ID:*** 1009855612
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 10.050000190734863
***Screen End Depth:*** 13.100000381469727
***Screen Material:*** 5
***Screen Depth UOM:*** m
***Screen Diameter UOM:*** cm
***Screen Diameter:*** 6.03000020980835

***Results of Well Yield Testing***

***Pumping Test Method Desc:***
***Pump Test ID:*** 1009856076
***Pump Set At:***
***Static Level:***
***Final Level After Pumping:***
***Recommended Pump Depth:***
***Pumping Rate:***
***Flowing Rate:***
***Recommended Pump Rate:***
***Levels UOM:*** m
***Rate UOM:*** LPM
***Water State After Test Code:***
***Water State After Test:***
***Pumping Test Method:*** 0
***Pumping Duration HR:***
***Pumping Duration MIN:***
***Flowing:*** No

***Hole Diameter***

***Hole ID:*** 1009854397
***Diameter:*** 11.430000305175781
***Depth From:*** 0.0
***Depth To:*** 13.100000381469727
***Hole Depth UOM:*** m
***Hole Diameter UOM:*** cm

---

**92** | ***1 of 3*** | ***ENE/205.1*** | ***72.9 / -1.00*** | ***Dentacraft Dental Studio***
***190 MacLaren St***
***Ottawa ON K2P0L6*** | ***SCT***

***Scott S ID:*** 33903247
***Latitude:*** 45.4169385
***Longitude:*** -75.689774

***Details***

***Bus Type 1:*** Manufacturer
***Bus Type 2:***
***Bus Type 3:***
***Product Cat 1:*** Bridges: dental
***Product Cat 2:*** Crowns: dental
***Product Cat 3:*** Dental laboratory
***Product Cat 4:*** Dentist
***Product Cat 5:*** Professional services
***Product Cat 6:***

***Employee Count:*** 5
***Square Footage:*** 0
***Estimated Sales:*** Under $1 Million
***Export Indicator:*** N
***Export Country 1:***
***Export Country 2:***
***Export Country 3:***
***Export Country 4:***
***Export Country 5:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| ***Product Cat 7:*** | | ***Export Country 6:*** | |
| ***Product Cat 8:*** | | ***Geocoded by:*** | Address |
| ***Company Name:*** | Dentacraft Dental Studio | | |
| ***Address Line 1:*** | 190 MacLaren St | | |
| ***Address Line 2:*** | | | |
| ***City:*** | Ottawa | | |
| ***Province:*** | ON | | |
| ***Postal Code:*** | K2P0L6 | | |
| ***Census Division:*** | Ottawa; ON | | |
| ***Metro Area:*** | Ottawa/Hull | | |
| ***Year Established:*** | 1986 | | |
| ***Head Office Indicator:*** | N | | |
| ***Parent Company Nm:*** | | | |
| ***Parent Cmpny Addr 1:*** | | | |
| ***Parent Cmpny Addr 2:*** | | | |
| ***Parent Cmpny City:*** | | | |
| ***Parent Cmpny Prov:*** | | | |
| ***Parent Cmpy PC:*** | | | |
| ***Parent Cmpy Cntry:*** | | | |
| ***Head Office Nm:*** | | | |
| ***H Office Addr Line 1:*** | | | |
| ***H Office Addr Line 2:*** | | | |
| ***Head Office City:*** | | | |
| ***Head Office Province:*** | | | |
| ***Head Office PC:*** | | | |
| ***Head Office Cntry:*** | | | |
| ***Telephone:*** | 613-233-1551 | | |
| ***Fax:*** | 613-233-1932 | | |
| ***Website:*** | | | |
| ***Pri NAICS Desc:*** | 339110-Medical Equipment and Supplies Manufacturing | | |
| ***NAICS Code 1:*** | 339110-Medical Equipment and Supplies Manufacturin | | |
| ***NAICS Code 2:*** | | | |
| ***NAICS Code 3:*** | | | |
| ***NAICS Code 4:*** | | | |
| ***NAICS Code 5:*** | | | |

***Historical Details***

| | |
|---|---|
| ***Established:*** | |
| ***Plant Size (ft²):*** | |
| ***Employment:*** | |

***Historical Details***

| | |
|---|---|
| ***Description:*** | Medical Equipment and Supplies Manufacturing |
| ***SIC/NAICS Code:*** | 339110 |

| | | | | | |
|---|---|---|---|---|---|
| 92 | *2 of 3* | ***ENE/205.1*** | ***72.9 / -1.00*** | ***Dentacraft Dental Studio Inc.***<br>***190 MacLaren St Suite 205***<br>***Ottawa ON K2P 0L6*** | ***SCT*** |

| | |
|---|---|
| ***Scott S ID:*** | 33903247 |
| ***Latitude:*** | |
| ***Longitude:*** | |

***Historical Details***

| | |
|---|---|
| ***Established:*** | |
| ***Plant Size (ft²):*** | |
| ***Employment:*** | |

***Historical Details***

***Description:*** Medical Equipment and Supplies Manufacturing
***SIC/NAICS Code:*** 339110

***Historical Details***

***Description:*** Medical Equipment and Supplies Manufacturing
***SIC/NAICS Code:*** 339110

---

**92** ***3 of 3*** ***ENE/205.1*** ***72.9 / -1.00*** ***UNKNOWN***
***190 MACLAREN ST.***
***OTTAWA CITY ON K2P 0L6*** ***SPL***

| | | | |
|---|---|---|---|
| ***Ref No:*** | 28347 | ***Municipality No:*** | 20101 |
| ***Year:*** | | ***Nature of Damage:*** | |
| ***Incident Dt:*** | 11/29/1989 | ***Discharger Report:*** | |
| ***Dt MOE Arvl on Scn:*** | | ***Material Group:*** | |
| ***MOE Reported Dt:*** | 11/29/1989 | ***Impact to Health:*** | |
| ***Dt Document Closed:*** | | ***Agency Involved:*** | PUC |

***Site No:***
***MOE Response:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Site Region:***
***Site Municipality:*** OTTAWA CITY
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***
***Entity Operating Name:***
***Client Name:***
***Client Type:***
***Source Type:***
***Incident Cause:*** UNKNOWN
***Incident Preceding Spill:***
***Incident Reason:*** UNKNOWN
***Incident Summary:*** UNKNOWN QTY GASOLINE SEEPING UP THROUGH WEEPING TILES.
***Environment Impact:*** POSSIBLE
***Health Env Consequence:***
***Nature of Impact:*** Soil contamination
***Contaminant Qty:***
***Contaminant Qty 1:***
***Contaminant Unit:***
***Contaminant Code:***
***Contaminant Name:***
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** LAND
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:***
***SAC Action Class:***
***Call Report Locatn Geodata:***
***Time Reported:***
***System Facility Address:***
***Source Sector Type:***

**Conservtn Auth Name:**
**Primary Watershed:**
**Quaternary Watershed:**
**Offsite Impacts Y N:**
**Waterbody Impacted Y N:**

---

**93** **1 of 1** **NE/207.1** **72.9 / -0.97** **ON** **WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7134824 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | Test Hole | **Date Received:** | 11/27/2009 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | 239792 | **Contractor:** | 6838 |
| **Tag:** | A054894 | **Form Version:** | 2 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | OTTAWA CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/713\7134824.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | 10/27/2009 |
| **Year Completed:** | 2009 |
| **Depth (m):** | 6.096 |
| **Latitude:** | 45.4172487008947 |
| **Longitude:** | -75.6904807466076 |
| **Point X:** | -75.69048058491511 |
| **Point Y:** | 45.41724869450499 |
| **Path:** | 713\7134824.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1002851290 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445976.00 |
| **Code OB Desc:** | | **North83:** | 5029535.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 10/27/2009 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1003349960
***Layer:*** 1
***Color:*** 8
***General Color:*** BLACK
***Material 1:*** 27
***Material 1 Desc:*** OTHER
***Material 2:***
***Material 2 Desc:***
***Material 3:***
***Material 3 Desc:***
***Formation Top Depth:*** 0.0
***Formation End Depth:*** 0.07999999821186066
***Formation End Depth UOM:*** ft

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1003349961
***Layer:*** 2
***Color:*** 6
***General Color:*** BROWN
***Material 1:*** 28
***Material 1 Desc:*** SAND
***Material 2:*** 11
***Material 2 Desc:*** GRAVEL
***Material 3:***
***Material 3 Desc:***
***Formation Top Depth:*** 0.07999999821186066
***Formation End Depth:*** 2.5
***Formation End Depth UOM:*** ft

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1003349962
***Layer:*** 3
***Color:*** 6
***General Color:*** BROWN
***Material 1:*** 28
***Material 1 Desc:*** SAND
***Material 2:*** 06
***Material 2 Desc:*** SILT
***Material 3:***
***Material 3 Desc:***
***Formation Top Depth:*** 2.5
***Formation End Depth:*** 6.0
***Formation End Depth UOM:*** ft

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1003349963
***Layer:*** 4
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 05
***Material 1 Desc:*** CLAY
***Material 2:*** 06
***Material 2 Desc:*** SILT

***Material 3:***
***Material 3 Desc:***
***Formation Top Depth:*** 6.0
***Formation End Depth:*** 20.0
***Formation End Depth UOM:*** ft

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1003349965
***Layer:*** 1
***Plug From:*** 0.0
***Plug To:*** 7.0
***Plug Depth UOM:*** ft

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1003349966
***Layer:*** 2
***Plug From:*** 7.0
***Plug To:*** 20.0
***Plug Depth UOM:*** ft

***Method of Construction & Well Use***

***Method Construction ID:*** 1003349970
***Method Construction Code:*** 6
***Method Construction:*** Boring
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 1003349959
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1003349968
***Layer:*** 1
***Material:***
***Open Hole or Material:***
***Depth From:*** 0.0
***Depth To:*** 20.0
***Casing Diameter:*** 2.0
***Casing Diameter UOM:*** inch
***Casing Depth UOM:*** ft

***Construction Record - Screen***

***Screen ID:*** 1003349969
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:***
***Screen End Depth:***
***Screen Material:***
***Screen Depth UOM:*** ft
***Screen Diameter UOM:*** inch

***Screen Diameter:*** 2.0

***Water Details***

***Water ID:*** 1003349967
***Layer:*** 1
***Kind Code:*** 1
***Kind:*** FRESH
***Water Found Depth:*** 10.600000381469727
***Water Found Depth UOM:*** ft

***Hole Diameter***

***Hole ID:*** 1003349964
***Diameter:***
***Depth From:***
***Depth To:***
***Hole Depth UOM:*** ft
***Hole Diameter UOM:*** inch

---

**94** | ***1 of 1*** | ***NE/208.6*** | ***72.9 / -0.97*** | ***ON*** | ***WWIS***

***Well ID:*** 7134806
***Construction Date:***
***Use 1st:***
***Use 2nd:***
***Final Well Status:*** Test Hole
***Water Type:***
***Casing Material:***
***Audit No:*** 239793
***Tag:*** A054894
***Constructn Method:***
***Elevation (m):***
***Elevatn Reliabilty:***
***Depth to Bedrock:***
***Well Depth:***
***Overburden/Bedrock:***
***Pump Rate:***
***Static Water Level:***
***Clear/Cloudy:***
***Municipality:*** OTTAWA CITY
***Site Info:***

***Flowing (Y/N):***
***Flow Rate:***
***Data Entry Status:***
***Data Src:***
***Date Received:*** 11/27/2009
***Selected Flag:*** TRUE
***Abandonment Rec:***
***Contractor:*** 6838
***Form Version:*** 2
***Owner:***
***County:*** OTTAWA-CARLETON
***Lot:***
***Concession:***
***Concession Name:***
***Easting NAD83:***
***Northing NAD83:***
***Zone:***
***UTM Reliability:***

***PDF URL (Map):*** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/713\7134806.pdf

***Additional Detail(s) (Map)***

***Well Completed Date:*** 10/27/2009
***Year Completed:*** 2009
***Depth (m):*** 5.0292
***Latitude:*** 45.4172934721717
***Longitude:*** -75.6905196353395
***Point X:*** -75.69051947296707
***Point Y:*** 45.41729346502327
***Path:*** 713\7134806.pdf

***Bore Hole Information***

***Bore Hole ID:*** 1002851147
***DP2BR:***
***Spatial Status:***

***Elevation:***
***Elevrc:***
***Zone:*** 18

| | | | |
|---|---|---|---|
| ***Code OB:*** | | ***East83:*** | 445973.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029540.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 4 |
| ***Date Completed:*** | 10/27/2009 | ***UTMRC Desc:*** | margin of error : 30 m - 100 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349947 |
| ***Layer:*** | 1 |
| ***Color:*** | 8 |
| ***General Color:*** | BLACK |
| ***Material 1:*** | 27 |
| ***Material 1 Desc:*** | OTHER |
| ***Material 2:*** | |
| ***Material 2 Desc:*** | |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 0.25 |
| ***Formation End Depth UOM:*** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349949 |
| ***Layer:*** | 3 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 28 |
| ***Material 1 Desc:*** | SAND |
| ***Material 2:*** | 06 |
| ***Material 2 Desc:*** | SILT |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 2.5 |
| ***Formation End Depth:*** | 5.5 |
| ***Formation End Depth UOM:*** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349948 |
| ***Layer:*** | 2 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 28 |
| ***Material 1 Desc:*** | SAND |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 0.25 |
| ***Formation End Depth:*** | 2.5 |

***Formation End Depth UOM:*** ft

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1003349950
***Layer:*** 4
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 05
***Material 1 Desc:*** CLAY
***Material 2:*** 06
***Material 2 Desc:*** SILT
***Material 3:***
***Material 3 Desc:***
***Formation Top Depth:*** 5.5
***Formation End Depth:*** 16.5
***Formation End Depth UOM:*** ft

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1003349953
***Layer:*** 2
***Plug From:*** 10.0
***Plug To:*** 16.5
***Plug Depth UOM:*** ft

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1003349952
***Layer:*** 1
***Plug From:*** 0.0
***Plug To:*** 10.0
***Plug Depth UOM:*** ft

***Method of Construction & Well Use***

***Method Construction ID:*** 1003349957
***Method Construction Code:*** 6
***Method Construction:*** Boring
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 1003349946
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1003349955
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 16.5
***Casing Diameter:*** 2.0

**Casing Diameter UOM:** inch
**Casing Depth UOM:** ft

***Construction Record - Screen***

**Screen ID:** 1003349956
**Layer:** 1
**Slot:** 10
**Screen Top Depth:** 11.5
**Screen End Depth:** 16.5
**Screen Material:** 5
**Screen Depth UOM:** ft
**Screen Diameter UOM:** inch
**Screen Diameter:** 2.0

***Water Details***

**Water ID:** 1003349954
**Layer:** 1
**Kind Code:** 1
**Kind:** FRESH
**Water Found Depth:** 10.300000190734863
**Water Found Depth UOM:** ft

***Hole Diameter***

**Hole ID:** 1003349951
**Diameter:**
**Depth From:**
**Depth To:**
**Hole Depth UOM:** ft
**Hole Diameter UOM:** inch

---

**95** | **1 of 1** | **WNW/208.6** | **75.9 / 2.00** | **340 Cooper street Ottawa ON**
**Ottawa ON K2P 0G7** | **EHS**

**Order No:** 24050100428
**Status:** C
**Report Type:** Standard Report
**Report Date:** 06-MAY-24
**Date Received:** 01-MAY-24
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.6946303
**Y:** 45.4168781

---

**96** | **1 of 1** | **WSW/209.4** | **75.9 / 2.00** | **Aromaflex**
**340 MacLaren St**
**Ottawa ON K2P0M6** | **SCT**

**Scott S ID:** 301027927
**Latitude:** 45.4149846
**Longitude:** -75.6946186

***Details***

**Bus Type 1:** Contract Manufacturing
**Bus Type 2:** Manufacturer
**Bus Type 3:** Professional; Scientific & Technical Services
**Product Cat 1:** Holistic medicine practitioner
**Product Cat 2:**

**Employee Count:** 2
**Square Footage:** 0
**Estimated Sales:** Under $1 Million
**Export Indicator:**
**Export Country 1:**

| | | | |
|---|---|---|---|
| **Product Cat 3:** | | **Export Country 2:** | |
| **Product Cat 4:** | | **Export Country 3:** | |
| **Product Cat 5:** | | **Export Country 4:** | |
| **Product Cat 6:** | | **Export Country 5:** | |
| **Product Cat 7:** | | **Export Country 6:** | |
| **Product Cat 8:** | | **Geocoded by:** | Address |
| **Company Name:** | Aromaflex | | |
| **Address Line 1:** | 340 MacLaren St | | |
| **Address Line 2:** | | | |
| **City:** | Ottawa | | |
| **Province:** | ON | | |
| **Postal Code:** | K2P0M6 | | |
| **Census Division:** | Ottawa; ON | | |
| **Metro Area:** | Ottawa/Hull | | |
| **Year Established:** | 1994 | | |
| **Head Office Indicator:** | | | |
| **Parent Company Nm:** | | | |
| **Parent Cmpny Addr 1:** | | | |
| **Parent Cmpny Addr 2:** | | | |
| **Parent Cmpny City:** | | | |
| **Parent Cmpny Prov:** | | | |
| **Parent Cmpy PC:** | | | |
| **Parent Cmpy Cntry:** | | | |
| **Head Office Nm:** | | | |
| **H Office Addr Line 1:** | | | |
| **H Office Addr Line 2:** | | | |
| **Head Office City:** | | | |
| **Head Office Province:** | | | |
| **Head Office PC:** | | | |
| **Head Office Cntry:** | | | |
| **Telephone:** | 613-355-0686 | | |
| **Fax:** | 613-274-7752 | | |
| **Website:** | http://www.aromaflex.com | | |
| **Pri NAICS Desc:** | 323119-Other Printing | | |
| **NAICS Code 1:** | 621390-Offices of All Other Health Practitioners | | |
| **NAICS Code 2:** | | | |
| **NAICS Code 3:** | | | |
| **NAICS Code 4:** | | | |
| **NAICS Code 5:** | | | |

| | | | | | |
|---|---|---|---|---|---|
| 97 | ***1 of 1*** | ***WNW/209.8*** | ***75.9 / 2.00*** | ***311 Somerset St W Ottawa ON*** | ***WWIS*** |

| | | | |
|---|---|---|---|
| **Well ID:** | 7382859 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | Monitoring and Test Hole | **Data Entry Status:** | |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | Observation Wells | **Date Received:** | 03/17/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z343100 | **Contractor:** | 7241 |
| **Tag:** | A302968 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | OTTAWA CITY | | |
| **Site Info:** | | | |

***PDF URL (Map):*** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/738\7382859.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| ***Well Completed Date:*** | 02/19/2021 |
| ***Year Completed:*** | 2021 |
| ***Depth (m):*** | 22.5 |
| ***Latitude:*** | 45.4165650729785 |
| ***Longitude:*** | -75.6948562475249 |
| ***Point X:*** | -75.69485608593011 |
| ***Point Y:*** | 45.41656506610067 |
| ***Path:*** | 738\7382859.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1008639565 | ***Elevation:*** | |
| ***DP2BR:*** | | ***Elevrc:*** | |
| ***Spatial Status:*** | | ***Zone:*** | 18 |
| ***Code OB:*** | | ***East83:*** | 445633.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029462.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 4 |
| ***Date Completed:*** | 02/19/2021 | ***UTMRC Desc:*** | margin of error : 30 m - 100 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009823648 |
| ***Layer:*** | 4 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 05 |
| ***Material 1 Desc:*** | CLAY |
| ***Material 2:*** | |
| ***Material 2 Desc:*** | |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 10.0 |
| ***Formation End Depth:*** | 22.5 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009823645 |
| ***Layer:*** | 1 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 11 |
| ***Material 1 Desc:*** | GRAVEL |
| ***Material 2:*** | |
| ***Material 2 Desc:*** | |
| ***Material 3:*** | 66 |
| ***Material 3 Desc:*** | DENSE |
| ***Formation Top Depth:*** | 0.0 |

***Formation End Depth:*** 2.0
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009823646
***Layer:*** 2
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 01
***Material 1 Desc:*** FILL
***Material 2:***
***Material 2 Desc:***
***Material 3:*** 66
***Material 3 Desc:*** DENSE
***Formation Top Depth:*** 2.0
***Formation End Depth:*** 4.0
***Formation End Depth UOM:*** m

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1009823647
***Layer:*** 3
***Color:*** 2
***General Color:*** GREY
***Material 1:*** 06
***Material 1 Desc:*** SILT
***Material 2:*** 05
***Material 2 Desc:*** CLAY
***Material 3:*** 85
***Material 3 Desc:*** SOFT
***Formation Top Depth:*** 4.0
***Formation End Depth:*** 10.0
***Formation End Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009824853
***Layer:*** 3
***Plug From:*** 11.5
***Plug To:*** 22.5
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009824852
***Layer:*** 2
***Plug From:*** 1.0
***Plug To:*** 11.5
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009824851
***Layer:*** 1
***Plug From:*** 0.0
***Plug To:*** 1.0

***Plug Depth UOM:*** m

***Method of Construction & Well Use***

***Method Construction ID:*** 1009826151
***Method Construction Code:*** D
***Method Construction:*** Direct Push
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 1009718441
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1009826572
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 12.5
***Casing Diameter:*** 2.046999931335449
***Casing Diameter UOM:*** cm
***Casing Depth UOM:*** m

***Construction Record - Screen***

***Screen ID:*** 1009826983
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 12.5
***Screen End Depth:*** 22.5
***Screen Material:*** 5
***Screen Depth UOM:*** m
***Screen Diameter UOM:*** cm
***Screen Diameter:*** 2.369999885559082

***Results of Well Yield Testing***

***Pumping Test Method Desc:***
***Pump Test ID:*** 1009827398
***Pump Set At:***
***Static Level:***
***Final Level After Pumping:***
***Recommended Pump Depth:***
***Pumping Rate:***
***Flowing Rate:***
***Recommended Pump Rate:***
***Levels UOM:*** m
***Rate UOM:*** LPM
***Water State After Test Code:***
***Water State After Test:***
***Pumping Test Method:*** 0
***Pumping Duration HR:***
***Pumping Duration MIN:***
***Flowing:***

***Hole Diameter***

| | |
|---|---|
| ***Hole ID:*** | 1009825711 |
| ***Diameter:*** | 4.5 |
| ***Depth From:*** | 0.0 |
| ***Depth To:*** | 22.5 |
| ***Hole Depth UOM:*** | m |
| ***Hole Diameter UOM:*** | cm |

---

**98** | ***1 of 1*** | ***SW/210.2*** | ***75.9 / 2.00*** | ***356 MACLAREN STREET Ottawa ON*** | ***WWIS***

| | | | |
|---|---|---|---|
| ***Well ID:*** | 7218928 | ***Flowing (Y/N):*** | |
| ***Construction Date:*** | | ***Flow Rate:*** | |
| ***Use 1st:*** | Monitoring | ***Data Entry Status:*** | |
| ***Use 2nd:*** | | ***Data Src:*** | |
| ***Final Well Status:*** | Observation Wells | ***Date Received:*** | 04/03/2014 |
| ***Water Type:*** | | ***Selected Flag:*** | TRUE |
| ***Casing Material:*** | | ***Abandonment Rec:*** | |
| ***Audit No:*** | Z163980 | ***Contractor:*** | 1844 |
| ***Tag:*** | A136699 | ***Form Version:*** | 7 |
| ***Constructn Method:*** | | ***Owner:*** | |
| ***Elevation (m):*** | | ***County:*** | OTTAWA-CARLETON |
| ***Elevatn Reliabilty:*** | | ***Lot:*** | |
| ***Depth to Bedrock:*** | | ***Concession:*** | |
| ***Well Depth:*** | | ***Concession Name:*** | |
| ***Overburden/Bedrock:*** | | ***Easting NAD83:*** | |
| ***Pump Rate:*** | | ***Northing NAD83:*** | |
| ***Static Water Level:*** | | ***Zone:*** | |
| ***Clear/Cloudy:*** | | ***UTM Reliability:*** | |
| ***Municipality:*** | NEPEAN TOWNSHIP | | |
| ***Site Info:*** | | | |

***PDF URL (Map):*** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7218928.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| ***Well Completed Date:*** | 12/30/2012 |
| ***Year Completed:*** | 2012 |
| ***Depth (m):*** | 3.51 |
| ***Latitude:*** | 45.4145974371379 |
| ***Longitude:*** | -75.694256997179 |
| ***Point X:*** | -75.69425683544122 |
| ***Point Y:*** | 45.414597429975764 |
| ***Path:*** | 721\7218928.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1004729714 | ***Elevation:*** | |
| ***DP2BR:*** | | ***Elevrc:*** | |
| ***Spatial Status:*** | | ***Zone:*** | 18 |
| ***Code OB:*** | | ***East83:*** | 445678.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029243.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 4 |
| ***Date Completed:*** | 12/30/2012 | ***UTMRC Desc:*** | margin of error : 30 m - 100 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |

***Supplier Comment:***

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1005133997 |
| ***Layer:*** | 2 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 28 |
| ***Material 1 Desc:*** | SAND |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | 01 |
| ***Material 3 Desc:*** | FILL |
| ***Formation Top Depth:*** | 0.05000000074505806 |
| ***Formation End Depth:*** | 0.5299999713897705 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1005133999 |
| ***Layer:*** | 4 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 06 |
| ***Material 1 Desc:*** | SILT |
| ***Material 2:*** | 05 |
| ***Material 2 Desc:*** | CLAY |
| ***Material 3:*** | 92 |
| ***Material 3 Desc:*** | WEATHERED |
| ***Formation Top Depth:*** | 1.5199999809265137 |
| ***Formation End Depth:*** | 3.509999990463257 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1005133996 |
| ***Layer:*** | 1 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | |
| ***Material 1 Desc:*** | |
| ***Material 2:*** | |
| ***Material 2 Desc:*** | |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 0.05000000074505806 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1005133998 |
| ***Layer:*** | 3 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 28 |
| ***Material 1 Desc:*** | SAND |

***Material 2:***
***Material 2 Desc:***
***Material 3:*** 01
***Material 3 Desc:*** FILL
***Formation Top Depth:*** 0.5299999713897705
***Formation End Depth:*** 1.5199999809265137
***Formation End Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1005134006
***Layer:*** 1
***Plug From:*** 0.75
***Plug To:*** 1.5
***Plug Depth UOM:*** m

***Method of Construction & Well Use***

***Method Construction ID:*** 1005134005
***Method Construction Code:*** B
***Method Construction:*** Other Method
***Other Method Construction:*** SSA

***Pipe Information***

***Pipe ID:*** 1005133995
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1005134002
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 3.049999952316284
***Casing Diameter:*** 3.180000066757202
***Casing Diameter UOM:*** cm
***Casing Depth UOM:*** m

***Construction Record - Screen***

***Screen ID:*** 1005134003
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 3.049999952316284
***Screen End Depth:***
***Screen Material:*** 5
***Screen Depth UOM:*** m
***Screen Diameter UOM:*** cm
***Screen Diameter:*** 3.799999952316284

***Water Details***

***Water ID:*** 1005134001
***Layer:***
***Kind Code:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Kind:**
**Water Found Depth:**
**Water Found Depth UOM:** m

***Hole Diameter***

**Hole ID:** 1005134000
**Diameter:** 16.510000228881836
**Depth From:** 0.0
**Depth To:**
**Hole Depth UOM:** m
**Hole Diameter UOM:** cm

---

**99** | **1 of 1** | **WSW/210.3** | **75.9 / 2.00** | **371 Gilmour St**
**Ottawa ON K2P0R2** | **EHS**

**Order No:** 20170404157
**Status:** C
**Report Type:** Standard Report
**Report Date:** 10-APR-17
**Date Received:** 04-APR-17
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.694364
**Y:** 45.414678

---

**100** | **1 of 1** | **WSW/210.8** | **75.9 / 2.00** | **371 Gilmour Street Ottawa ON**
**Ottawa ON K2P 0R3** | **EHS**

**Order No:** 23051000074
**Status:** C
**Report Type:** Standard Report
**Report Date:** 15-MAY-23
**Date Received:** 10-MAY-23
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.6943224
**Y:** 45.4146376

---

**101** | **1 of 1** | **W/211.3** | **75.9 / 2.00** | **323 Somerset Street West**
**Ottawa ON K2P 0J8** | **EHS**

**Order No:** 25072800159
**Status:** C
**Report Type:** Standard Report
**Report Date:** 31-JUL-25
**Date Received:** 28-JUL-25
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.6950277
**Y:** 45.4160816

---

**102** | **1 of 1** | **SSW/211.6** | **75.0 / 1.08** | **Centretown Citizens Ottawa Corporation**
**345 Waverley Street**
**Ottawa ON** | **GEN**

***Generator Info (as of Dec 2024)***

**Generator No:** ON001054556
**Generator Company Name:** Centretown Citizens Ottawa Corporation

**Street:** 345 Waverley Street
**City:** Ottawa
**Province State:** Ontario
**Country:** Canada
**Postal Code:** K2P 0W4
**Waste Class:** 251 L

**Waste Class Decoded:**

251 - OIL SKIMMINGS & SLUDGES

***Generator Info (as of Apr 2025)***

**Generator Company Name:** Centretown Citizens Ottawa Corporation
**Generator Site Address:** 345 Waverley Street
**City:** Ottawa
**Province State:** Ontario
**Country:** Canada
**Postal Code:** K2P 0W4
**Waste Class:** 251 L

**Waste Class Decoded:**

251 - OIL SKIMMINGS & SLUDGES

**Waste Characteristic Decoded:**

L - Liquid Industrial Waste

---

**103** | **1 of 1** | **SSE/214.8** | **73.9 / 0.06** | **322 Waverly Street Ottawa Ontario Ottawa ON K2P 0W3** | **EHS**

**Order No:** 20190510179
**Status:** C
**Report Type:** Standard Report
**Report Date:** 16-MAY-19
**Date Received:** 10-MAY-19
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.69184
**Y:** 45.414019

---

**104** | **1 of 1** | **WNW/215.1** | **75.9 / 2.00** | **311 SOMERSET Ottawa ON** | **WWIS**

**Well ID:** 7391114
**Construction Date:**
**Use 1st:** Monitoring and Test Hole
**Use 2nd:**
**Final Well Status:** Monitoring and Test Hole
**Water Type:**
**Casing Material:**
**Audit No:** Z364138
**Tag:** A302951
**Constructn Method:**
**Elevation (m):**
**Elevatn Reliabilty:**
**Depth to Bedrock:**
**Well Depth:**
**Overburden/Bedrock:**
**Pump Rate:**

**Flowing (Y/N):**
**Flow Rate:**
**Data Entry Status:**
**Data Src:**
**Date Received:** 06/29/2021
**Selected Flag:** TRUE
**Abandonment Rec:**
**Contractor:** 7241
**Form Version:** 7
**Owner:**
**County:** OTTAWA-CARLETON
**Lot:**
**Concession:**
**Concession Name:**
**Easting NAD83:**
**Northing NAD83:**

**Static Water Level:**
**Clear/Cloudy:**
**Municipality:** OTTAWA CITY
**Site Info:**
**Zone:**
**UTM Reliability:**

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7391114.pdf

***Additional Detail(s) (Map)***

**Well Completed Date:** 05/25/2021
**Year Completed:** 2021
**Depth (m):** 14.33
**Latitude:** 45.4164743671495
**Longitude:** -75.6949701625181
**Point X:** -75.69497000126127
**Point Y:** 45.41647436047882
**Path:** 739\7391114.pdf

***Bore Hole Information***

**Bore Hole ID:** 1008704352
**DP2BR:**
**Spatial Status:**
**Code OB:**
**Code OB Desc:**
**Open Hole:**
**Cluster Kind:**
**Date Completed:** 05/25/2021
**Remarks:**
**Location Method Desc:** on Water Well Record
**Elevrc Desc:**
**Location Source Date:**
**Improvement Location Source:**
**Improvement Location Method:**
**Source Revision Comment:**
**Supplier Comment:**

**Elevation:**
**Elevrc:**
**Zone:** 18
**East83:** 445624.00
**North83:** 5029452.00
**Org CS:** UTM83
**UTMRC:** 4
**UTMRC Desc:** margin of error : 30 m - 100 m
**Location Method:** wwr

***Overburden and Bedrock Materials Interval***

**Formation ID:** 1009852404
**Layer:** 4
**Color:** 2
**General Color:** GREY
**Material 1:** 05
**Material 1 Desc:** CLAY
**Material 2:** 06
**Material 2 Desc:** SILT
**Material 3:** 85
**Material 3 Desc:** SOFT
**Formation Top Depth:** 3.6600000858306885
**Formation End Depth:** 10.359999656677246
**Formation End Depth UOM:** m

***Overburden and Bedrock Materials Interval***

**Formation ID:** 1009852401
**Layer:** 1
**Color:** 6
**General Color:** BROWN
**Material 1:** 02

| | |
|---|---|
| ***Material 1 Desc:*** | TOPSOIL |
| ***Material 2:*** | |
| ***Material 2 Desc:*** | |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 0.3100000023841858 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009852402 |
| ***Layer:*** | 2 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 28 |
| ***Material 1 Desc:*** | SAND |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 0.3100000023841858 |
| ***Formation End Depth:*** | 2.130000114440918 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009852405 |
| ***Layer:*** | 5 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 06 |
| ***Material 1 Desc:*** | SILT |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | 66 |
| ***Material 3 Desc:*** | DENSE |
| ***Formation Top Depth:*** | 10.359999656677246 |
| ***Formation End Depth:*** | 14.329999923706055 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1009852403 |
| ***Layer:*** | 3 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 05 |
| ***Material 1 Desc:*** | CLAY |
| ***Material 2:*** | 28 |
| ***Material 2 Desc:*** | SAND |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 2.130000114440918 |
| ***Formation End Depth:*** | 3.6600000858306885 |
| ***Formation End Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009853461
***Layer:*** 1
***Plug From:*** 0.0
***Plug To:*** 0.3100000023841858
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009853462
***Layer:*** 2
***Plug From:*** 0.3100000023841858
***Plug To:*** 10.970000267028809
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1009853463
***Layer:*** 3
***Plug From:*** 10.970000267028809
***Plug To:*** 14.329999923706055
***Plug Depth UOM:*** m

***Method of Construction & Well Use***

***Method Construction ID:*** 1009854839
***Method Construction Code:*** 5
***Method Construction:*** Air Percussion
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 1009764984
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1009855217
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 11.279999732971191
***Casing Diameter:***
***Casing Diameter UOM:***
***Casing Depth UOM:*** m

***Construction Record - Screen***

***Screen ID:*** 1009855613
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 11.279999732971191
***Screen End Depth:*** 14.329999923706055
***Screen Material:*** 5
***Screen Depth UOM:*** m

**Screen Diameter UOM:** cm
**Screen Diameter:** 6.03000020980835

***Results of Well Yield Testing***

**Pumping Test Method Desc:**
**Pump Test ID:** 1009856077
**Pump Set At:**
**Static Level:**
**Final Level After Pumping:**
**Recommended Pump Depth:**
**Pumping Rate:**
**Flowing Rate:**
**Recommended Pump Rate:**
**Levels UOM:** m
**Rate UOM:** LPM
**Water State After Test Code:**
**Water State After Test:**
**Pumping Test Method:** 0
**Pumping Duration HR:**
**Pumping Duration MIN:**
**Flowing:** No

***Hole Diameter***

**Hole ID:** 1009854398
**Diameter:** 11.430000305175781
**Depth From:** 0.0
**Depth To:** 2.130000114440918
**Hole Depth UOM:** m
**Hole Diameter UOM:** cm

---

**105** | **1 of 1** | **N/216.0** | **73.9 / 0.00** | **250-254 Cooper St Ottawa ON K2P 0G4** | **EHS**

**Order No:** 20060929003
**Status:** C
**Report Type:** Custom Report
**Report Date:** 10/6/2006
**Date Received:** 9/29/2006
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps And /or Site Plans

**Nearest Intersection:** Cooper St & Metcalfe St
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** 0.25
**X:** -75.691981
**Y:** 45.417851

---

**106** | **1 of 1** | **NW/217.3** | **74.9 / 1.00** | **297 Cooper St Ottawa ON K2P0G5** | **EHS**

**Order No:** 20160311134
**Status:** C
**Report Type:** Standard Report
**Report Date:** 18-MAR-16
**Date Received:** 11-MAR-16
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** City Directory

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.693739
**Y:** 45.417609

---

**107** | **1 of 1** | **SSE/218.3** | **73.9 / 0.06** | **322-326 Waverley Street Ottawa ON K2P 0W3** | **EHS**

**Order No:** 21032600288

**Nearest Intersection:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 31-MAR-21 | **Search Radius (km):** | .25 |
| **Date Received:** | 26-MAR-21 | **X:** | -75.6919417 |
| **Previous Site Name:** | | **Y:** | 45.4139754 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans; Topographic Maps | | |

---

**108** | **1 of 1** | **ENE/218.8** | **72.9 / -1.00** | **292 Elgin St**
**Ottawa ON K2P1M3** | **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 20150119005 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 22-JAN-15 | **Search Radius (km):** | .25 |
| **Date Received:** | 19-JAN-15 | **X:** | -75.68975 |
| **Previous Site Name:** | | **Y:** | 45.416667 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

**109** | **1 of 6** | **NW/219.2** | **74.9 / 0.98** | **309 Cooper Street**
**Ottawa ON K2P 0G5** | **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 20180920045 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 25-SEP-18 | **Search Radius (km):** | .25 |
| **Date Received:** | 20-SEP-18 | **X:** | -75.693999 |
| **Previous Site Name:** | | **Y:** | 45.417449 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | |

---

**109** | **2 of 6** | **NW/219.2** | **74.9 / 0.98** | **DOMUS SOFTWARE LTD**
**309 COOPER ST UNIT 500**
**OTTAWA ON K2P 0G5** | **SCT**

| | |
|---|---|
| **Scott S ID:** | 18523432 |
| **Latitude:** | |
| **Longitude:** | |

***Historical Details***

| | |
|---|---|
| **Established:** | 1983 |
| **Plant Size (ft²):** | 7000 |
| **Employment:** | 100 |

***Historical Details***

| | |
|---|---|
| **Description:** | MAGNETIC AND OPTICAL RECORDING MEDIA |
| **SIC/NAICS Code:** | 3695 |

---

**109** | **3 of 6** | **NW/219.2** | **74.9 / 0.98** | **The Canadian Council on Social Development**
**309 Cooper St Floor 5**
**Ottawa ON K2P 0G5** | **SCT**

| | |
|---|---|
| **Scott S ID:** | 34333097 |
| **Latitude:** | |
| **Longitude:** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Historical Details***

***Established:***
***Plant Size (ft²):***
***Employment:***

***Historical Details***

***Description:*** Book Publishers
***SIC/NAICS Code:*** 511130

---

**109** | ***4 of 6*** | ***NW/219.2*** | ***74.9 / 0.98*** | ***Cdn Council on Social Dev***
***309 Cooper St Floor 5***
***Ottawa ON K2P 0G5*** | ***SCT***

***Scott S ID:*** 35912006
***Latitude:***
***Longitude:***

***Historical Details***

***Established:*** 1920
***Plant Size (ft²):***
***Employment:*** 25

***Historical Details***

***Description:*** Periodical Publishers
***SIC/NAICS Code:*** 511120

***Historical Details***

***Description:*** Business Associations
***SIC/NAICS Code:*** 813910

---

**109** | ***5 of 6*** | ***NW/219.2*** | ***74.9 / 0.98*** | ***The Ottawa XPress***
***309 Cooper St Suite 401***
***Ottawa ON K2P 0G5*** | ***SCT***

***Scott S ID:*** 19409649
***Latitude:***
***Longitude:***

***Historical Details***

***Established:*** 01-AUG-92
***Plant Size (ft²):***
***Employment:***

***Historical Details***

***Description:*** Newspaper Publishers
***SIC/NAICS Code:*** 511110

---

**109** | ***6 of 6*** | ***NW/219.2*** | ***74.9 / 0.98*** | ***DALE R KENNY***
***309 COOPER ST,,OTTAWA,ON,K2P 0G5,CA*** | ***VAR***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| | | | | ON | |

**Incident No:** 009535852-001
**Status:** Variance Approved
**Incident Reported Dt:** 4/1/1996
**Incident Created On:** 7/7/2009
**Item Instance:** NULL
**Incident Type:** FS-Variance
**Aband USTs:** Abandon UST

---

**110** | **1 of 1** | **NNE/219.4** | **72.9 / -1.00** | **Elevation Elevator Inc.**
**215 Somerset Street, West**
**Ottawa ON K2P0J3** | **GEN**

***Generator Info***

**Generator No:** ON5007280
**Approval Years:** 2016
**Status:**
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:** ELEVATOR AND ESCALATOR INSTALLATION CONTRACTORS
**Choice of Contact:** CO_OFFICIAL
**Contaminated Fac:** No
**MHSW Facility:** No
**SIC Code:** 238291

***Waste Detail(s)***

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

---

**111** | **1 of 1** | **WSW/219.6** | **75.9 / 2.00** | **AUBUT & NADEAU SERVICES INC.**
**342 MCLAREN STREET**
**OTTAWA ON K2P 0M6** | **GEN**

***Generator Info***

**Generator No:** ON1785700
**Approval Years:** 94
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** CAMERA/PHOTO. SUPPLY
**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 6571

***Waste Detail(s)***

**Waste Class:** 264
**Waste Class Name:** PHOTOPROCESSING WASTES

---

**112** | **1 of 1** | **SE/220.7** | **72.9 / -1.00** | **330 Metcalfe Street**
**Ottawa ON K2P 1S4** | **EHS**

**Order No:** 20081006004
**Status:** C
**Report Type:** Custom Report
**Report Date:** 10/15/2008
**Date Received:** 10/6/2008
**Previous Site Name:**
**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** 0.25
**X:** -75.690344
**Y:** 45.414515

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Lot/Building Size:** | | | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | | | |

| | | | | | |
|---|---|---|---|---|---|
| 113 | 1 of 6 | E/220.7 | 72.9 / -1.00 | **320 Jack Purcell Lane**<br>**Ottawa ON K2P2J5** | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 20150824006 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | Ottawa |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 28-AUG-15 | **Search Radius (km):** | .25 |
| **Date Received:** | 24-AUG-15 | **X:** | -75.68934 |
| **Previous Site Name:** | | **Y:** | 45.415331 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| | | | | | |
|---|---|---|---|---|---|
| 113 | 2 of 6 | E/220.7 | 72.9 / -1.00 | **KONE Inc**<br>**320 JACK PURCELL LANE**<br>**Ottawa ON K2P 2J5** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON8096604 | **Choice of Contact:** | |
| **Approval Years:** | 2010 | **Contaminated Fac:** | |
| **Status:** | | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | 238291 |
| **Country:** | | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | Elevator and Escalator Installation Contractors | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 252 |
| **Waste Class Name:** | WASTE OILS & LUBRICANTS |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 251 |
| **Waste Class Name:** | OIL SKIMMINGS & SLUDGES |

| | | | | | |
|---|---|---|---|---|---|
| 113 | 3 of 6 | E/220.7 | 72.9 / -1.00 | **City of Ottawa**<br>**320 Jack Purcell Lane**<br>**Ottawa ON K2P 2J5** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON3594040 | **Choice of Contact:** | |
| **Approval Years:** | As of Dec 2018 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |
| **Country:** | Canada | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Detail(s)***

***Waste Class:*** 251 L
***Waste Class Name:*** Waste oils/sludges (petroleum based)

---

**113** | ***4 of 6*** | ***E/220.7*** | ***72.9 / -1.00*** | ***City of Ottawa***
***320 Jack Purcell Lane***
***Ottawa ON K2P 2J5*** | ***GEN***

***Generator Info***

***Generator No:*** ON3594040
***Approval Years:*** As of Jul 2020
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 251 L
***Waste Class Name:*** Waste oils/sludges (petroleum based)

---

**113** | ***5 of 6*** | ***E/220.7*** | ***72.9 / -1.00*** | ***City of Ottawa***
***320 Jack Purcell Lane***
***Ottawa ON K2P 2J5*** | ***GEN***

***Generator Info***

***Generator No:*** ON3594040
***Approval Years:*** As of Nov 2021
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 251 L
***Waste Class Name:*** Waste oils/sludges (petroleum based)

---

**113** | ***6 of 6*** | ***E/220.7*** | ***72.9 / -1.00*** | ***City of Ottawa Facility Operations Service***
***320 Jack Purcell Lane***
***Ottawa ON*** | ***GEN***

***Generator Info***

***Generator No:*** ON3594040
***Approval Years:*** As of Oct 2022
***Status:*** Registered
***PO Box No:***
***Country:*** Canada

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 251 L
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Generator Info (as of Dec 2024)***

***Generator No:*** ON3594040
***Generator Company Name:*** City of Ottawa Facility Operations Service
***Street:*** 320 Jack Purcell Lane
***City:*** Ottawa
***Province State:*** Ontario
***Country:*** Canada
***Postal Code:*** K2P 1M4
***Waste Class:*** 251 L

***Waste Class Decoded:***

251 - OIL SKIMMINGS & SLUDGES

***Generator Info (as of Apr 2025)***

***Generator Company Name:*** City of Ottawa Facility Operations Service
***Generator Site Address:*** 320 Jack Purcell Lane
***City:*** Ottawa
***Province State:*** Ontario
***Country:*** Canada
***Postal Code:*** K2P 1M4
***Waste Class:*** 251 L

***Waste Class Decoded:***

251 - OIL SKIMMINGS & SLUDGES

***Waste Characteristic Decoded:***

L - Liquid Industrial Waste

***2017 Generator Info***

***Gen No:*** ON3594040
***ID:*** 14439
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 913910
***NAICS Code2:***
***NAICS Code3:***
***Gen Name:*** City of Ottawa
***Gen Div:***
***Gen Op Name:*** City of Ottawa
***Gen Op Div:***
***Site Adrs1:*** 320 Jack Purcell Lane
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***

***Choice of Contact:*** CO_OFFICIAL
***Phone No Official:*** 6135802424 Ext.12085
***Phone No Admin:***
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402

**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 2J5
**Site Country:** Canada
**Co Official:** Randy Villeneuve
**Co Admin:**

***2018 Generator Info***

**Gen No:** ON3594040
**ID:** 14330
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 913910
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** City of Ottawa
**Gen Div:**
**Gen Op Name:** City of Ottawa
**Gen Op Div:**
**Site Adrs1:** 320 Jack Purcell Lane
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 2J5
**Site Country:** Canada
**Co Official:** Randy Villeneuve
**Co Admin:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 6135802424 Ext.12085
**Phone No Admin:**
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2019 Generator Info***

**Gen No:** ON3594040
**ID:** 14144
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 913910
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** City of Ottawa
**Gen Div:**
**Gen Op Name:** City of Ottawa
**Gen Op Div:**
**Site Adrs1:** 320 Jack Purcell Lane
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 2J5
**Site Country:** Canada
**Co Official:** Randy Villeneuve
**Co Admin:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 6135802424 Ext.12085
**Phone No Admin:**
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2020 Generator Info***

**Gen No:** ON3594040
**ID:** 13795
**Contaminated Fac:** N
**MHSW Facility:** N
**Choice of Contact:** CO_OFFICIAL
**Phone No Official:** 6135802424 Ext.12085
**Phone No Admin:**
**County Ont:** OTTAWA CARLTON (RM)

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **NAICS Code1:** | 913910 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | City of Ottawa | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | City of Ottawa | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 320 Jack Purcell Lane | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | | | |
| **Site City:** | Ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P 2J5 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | Randy Villeneuve | | |
| **Co Admin:** | | | |

***2021 Generator Info***

| | | | |
|---|---|---|---|
| **Gen No:** | ON3594040 | **Choice of Contact:** | CO_OFFICIAL |
| **ID:** | 13676 | **Phone No Official:** | 6135802424 Ext.12085 |
| **Contaminated Fac:** | N | **Phone No Admin:** | |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 913910 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | City of Ottawa | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | City of Ottawa | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 320 Jack Purcell Lane | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | | | |
| **Site City:** | Ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P 2J5 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | Daniel Alves | | |
| **Co Admin:** | | | |

---

| | | | | | |
|---|---|---|---|---|---|
| **114** | ***1 of 1*** | ***WSW/220.9*** | ***75.9 / 1.97*** | ***341 Maclaren St<br>Ottawa ON K2P2E2*** | ***EHS*** |

| | | | |
|---|---|---|---|
| **Order No:** | 20170203026 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 08-FEB-17 | **Search Radius (km):** | .25 |
| **Date Received:** | 03-FEB-17 | **X:** | -75.695005 |
| **Previous Site Name:** | | **Y:** | 45.415271 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

| | | | | | |
|---|---|---|---|---|---|
| **115** | ***1 of 1*** | ***NNW/221.3*** | ***74.2 / 0.31*** | ***214 Metcalfe Street<br>Ottawa ON K2P 1P7*** | ***EHS*** |

| | | | |
|---|---|---|---|
| **Order No:** | 20191128024 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Site Report | **Client Prov/State:** | ON |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Report Date:** | 29-NOV-19 | **Search Radius (km):** | .001 |
| **Date Received:** | 28-NOV-19 | **X:** | -75.693274 |
| **Previous Site Name:** | | **Y:** | 45.4178 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

**116** **1 of 5** **W/221.5** **75.9 / 2.00** **338 Somerset Street West Ottawa Ontario**
**Ottawa ON K2P 0J9** **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 20191203166 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 06-DEC-19 | **Search Radius (km):** | .25 |
| **Date Received:** | 03-DEC-19 | **X:** | -75.695144 |
| **Previous Site Name:** | | **Y:** | 45.415602 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | |

---

**116** **2 of 5** **W/221.5** **75.9 / 2.00** **338 SOMERSET STREET WEST**
**OTTAWA ON** **HINC**

| | |
|---|---|
| **External File Num:** | FS INC 0903-01589 |
| **Fuel Occurrence Type:** | Vapour Release |
| **Date of Occurrence:** | 3/27/2009 |
| **Fuel Type Involved:** | Natural Gas |
| **Status Desc:** | Completed - No Action Required |
| **Job Type Desc:** | Incident/Near-Miss Occurrence (FS) |
| **Oper. Type Involved:** | Commercial (e.g. restaurant, business unit, etc) |
| **Service Interruptions:** | No |
| **Property Damage:** | No |
| **Fuel Life Cycle Stage:** | Utilization |
| **Root Cause:** | |
| **Reported Details:** | Service riser damage due to mechanical impact. |
| **Fuel Category:** | Gaseous Fuel |
| **Occurrence Type:** | Incident |
| **Affiliation:** | Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.) |
| **County Name:** | Ottawa |
| **Approx. Quant. Rel:** | |
| **Nearby body of water:** | |
| **Enter Drainage Syst.:** | |
| **Approx. Quant. Unit:** | |
| **Environmental Impact:** | |

---

**116** **3 of 5** **W/221.5** **75.9 / 2.00** **CDIA Report Newsletter**
**338 Somerset St W Unit 4**
**Ottawa ON K2P 0J9** **SCT**

| | |
|---|---|
| **Scott S ID:** | 35657298 |
| **Latitude:** | |
| **Longitude:** | |

***Historical Details***

| | |
|---|---|
| **Established:** | |
| **Plant Size (ft²):** | |
| **Employment:** | 3 |

***Historical Details***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Description:** | | Periodical Publishers | | | |
| **SIC/NAICS Code:** | | 511120 | | | |

| | | | | | |
|---|---|---|---|---|---|
| 116 | 4 of 5 | W/221.5 | 75.9 / 2.00 | whatif? Technologies Inc.<br>338 Somerset St W Unit 3<br>Ottawa ON K2P 0J9 | SCT |

**Scott S ID:** 57143655
**Latitude:**
**Longitude:**

***Historical Details***

**Established:** 01-AUG-89
**Plant Size (ft²):** 1500
**Employment:**

***Historical Details***

**Description:** Computer Systems Design and Related Services
**SIC/NAICS Code:** 541510

***Historical Details***

**Description:** Software Publishers
**SIC/NAICS Code:** 511210

| | | | | | |
|---|---|---|---|---|---|
| 116 | 5 of 5 | W/221.5 | 75.9 / 2.00 | Enbridge Gas Distribution Inc.<br>338 Sommerset West<br>Ottawa ON | SPL |

**Ref No:** 5203-7QJJV4
**Year:**
**Incident Dt:**
**Dt MOE Arvl on Scn:**
**MOE Reported Dt:** 3/27/2009
**Dt Document Closed:**
**Site No:**
**MOE Response:**
**Site County/District:**
**Site Geo Ref Meth:**
**Site District Office:**
**Nearest Watercourse:**
**Site Name:** Vespa<UNOFFICIAL>
**Site Address:**
**Site Region:**
**Site Municipality:** Ottawa
**Site Lot:**
**Site Conc:**
**Site Geo Ref Accu:**
**Site Map Datum:**
**Northing:**
**Easting:**
**Entity Operating Name:**
**Client Name:** Enbridge Gas Distribution Inc.
**Client Type:**
**Source Type:**
**Incident Cause:** Other Transport Accident
**Incident Preceding Spill:**
**Incident Reason:** Error- Operator error
**Incident Summary:** Enbridge, Regulator strike, Evac, rd closed, safe
**Environment Impact:** Confirmed
**Municipality No:**
**Nature of Damage:**
**Discharger Report:**
**Material Group:**
**Impact to Health:**
**Agency Involved:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Health Env Consequence:** | | | | | |
| **Nature of Impact:** | Air Pollution; Human Health/Safety | | | | |
| **Contaminant Qty:** | | | | | |
| **Contaminant Qty 1:** | | | | | |
| **Contaminant Unit:** | other - see incident description | | | | |
| **Contaminant Code:** | | | | | |
| **Contaminant Name:** | NATURAL GAS (METHANE) | | | | |
| **Contaminant Limit 1:** | | | | | |
| **Contam Limit Freq 1:** | | | | | |
| **Contaminant UN No 1:** | | | | | |
| **Receiving Medium:** | | | | | |
| **Activity Preceding Spill:** | | | | | |
| **Property 2nd Watershed:** | | | | | |
| **Property Tertiary Watershed:** | | | | | |
| **Sector Type:** | Pipeline | | | | |
| **SAC Action Class:** | Air Spills - Gases and Vapours | | | | |
| **Call Report Locatn Geodata:** | | | | | |
| **Time Reported:** | | | | | |
| **System Facility Address:** | | | | | |
| **Source Sector Type:** | | | | | |
| **Conservtn Auth Name:** | | | | | |
| **Primary Watershed:** | | | | | |
| **Quaternary Watershed:** | | | | | |
| **Offsite Impacts Y N:** | | | | | |
| **Waterbody Impacted Y N:** | | | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 117 | 1 of 7 | ENE/222.1 | 72.9 / -1.00 | Elgin Motors<br>286 Elgin<br>Ottawa ON | HBAR |
| **Province:** | ON | | | | |
| **Year:** | 1941 | | | | |
| **Source:** | Mights | | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 117 | 2 of 7 | ENE/222.1 | 72.9 / -1.00 | Elliott Alex<br>286 Elgin<br>Ottawa ON | HBAR |
| **Province:** | ON | | | | |
| **Year:** | 1927 | | | | |
| **Source:** | Mights | | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 117 | 3 of 7 | ENE/222.1 | 72.9 / -1.00 | Hillary's Fraser Ltd<br>286 Elgin<br>Ottawa ON | HBAR |
| **Province:** | ON | | | | |
| **Year:** | 1960 | | | | |
| **Source:** | Mights | | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 117 | 4 of 7 | ENE/222.1 | 72.9 / -1.00 | Hillary's Fraser Ltd<br>286 Elgin<br>Ottawa ON | HBAR |
| **Province:** | ON | | | | |
| **Year:** | 1955 | | | | |
| **Source:** | Mights | | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 117 | 5 of 7 | ENE/222.1 | 72.9 / -1.00 | Elgin Motors<br>286 Elgin<br>Ottawa ON | HBAR |

**Province:** ON
**Year:** 1936
**Source:** Mights

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 117 | 6 of 7 | ENE/222.1 | 72.9 / -1.00 | Elgin Motors<br>286 Elgin<br>Ottawa ON | HBAR |

**Province:** ON
**Year:** 1945
**Source:** Mights

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 117 | 7 of 7 | ENE/222.1 | 72.9 / -1.00 | Quigg Victor<br>286 Elgin<br>Ottawa ON | HBAR |

**Province:** ON
**Year:** 1924
**Source:** Mights

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 118 | 1 of 2 | ENE/223.3 | 72.9 / -1.00 | Elgin Motors<br>296 Elgin<br>Ottawa ON | HBAR |

**Province:** ON
**Year:** 1950
**Source:** Mights

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 118 | 2 of 2 | ENE/223.3 | 72.9 / -1.00 | Ottawash Laundry<br>211 Gilmour<br>Ottawa ON | HBAR |

**Province:** ON
**Year:** 1960
**Source:** Mights

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 119 | 1 of 1 | WSW/223.5 | 75.9 / 2.00 | 341 MacLaren Street<br>Ottawa ON K2P 2E2 | EHS |

**Order No:** 20061030005
**Status:** C
**Report Type:** Custom Report
**Report Date:** 11/7/2006
**Date Received:** 10/30/2006
**Previous Site Name:**
**Lot/Building Size:** ~ O.30 acre lot
**Additional Info Ordered:** Fire Insur. Maps And /or Site Plans

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** 0.25
**X:** -75.695027
**Y:** 45.415178

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 120 | 1 of 1 | NW/224.1 | 75.3 / 1.46 | 325 Cooper Street<br>Ottawa ON K2P 0G5 | EHS |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Order No:** 20200213021
**Status:** C
**Report Type:** Standard Report
**Report Date:** 19-FEB-20
**Date Received:** 13-FEB-20
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.6944063
**Y:** 45.4173144

---

**121** | **1 of 1** | **WSW/225.7** | **75.9 / 2.00** | **375 Gilmour St Ottawa ON** | **EHS**

**Order No:** 20130124026
**Status:** C
**Report Type:** Standard Report
**Report Date:** 04-FEB-13
**Date Received:** 24-JAN-13
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.694729
**Y:** 45.414533

---

**122** | **1 of 1** | **SE/225.8** | **72.9 / -1.00** | **330 Metcalfe Street Ottawa ON K2P 1S4** | **EHS**

**Order No:** 23072400745
**Status:** C
**Report Type:** Standard Report
**Report Date:** 27-JUL-23
**Date Received:** 24-JUL-23
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.6903877
**Y:** 45.414421

---

**123** | **1 of 1** | **NE/225.9** | **72.9 / -0.97** | **ON** | **WWIS**

**Well ID:** 7134805
**Construction Date:**
**Use 1st:**
**Use 2nd:**
**Final Well Status:** Test Hole
**Water Type:**
**Casing Material:**
**Audit No:** 239794
**Tag:** A054894
**Constructn Method:**
**Elevation (m):**
**Elevatn Reliabilty:**
**Depth to Bedrock:**
**Well Depth:**
**Overburden/Bedrock:**
**Pump Rate:**
**Static Water Level:**
**Clear/Cloudy:**
**Municipality:** OTTAWA CITY
**Site Info:**

**Flowing (Y/N):**
**Flow Rate:**
**Data Entry Status:**
**Data Src:**
**Date Received:** 11/27/2009
**Selected Flag:** TRUE
**Abandonment Rec:**
**Contractor:** 6838
**Form Version:** 2
**Owner:**
**County:** OTTAWA-CARLETON
**Lot:**
**Concession:**
**Concession Name:**
**Easting NAD83:**
**Northing NAD83:**
**Zone:**
**UTM Reliability:**

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/713\7134805.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| ***Well Completed Date:*** | 10/27/2009 |
| ***Year Completed:*** | 2009 |
| ***Depth (m):*** | 8.2296 |
| ***Latitude:*** | 45.417455946737 |
| ***Longitude:*** | -75.6904449293894 |
| ***Point X:*** | -75.69044476728239 |
| ***Point Y:*** | 45.41745594031351 |
| ***Path:*** | 713\7134805.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1002851144 | ***Elevation:*** | |
| ***DP2BR:*** | | ***Elevrc:*** | |
| ***Spatial Status:*** | | ***Zone:*** | 18 |
| ***Code OB:*** | | ***East83:*** | 445979.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029558.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 4 |
| ***Date Completed:*** | 10/27/2009 | ***UTMRC Desc:*** | margin of error : 30 m - 100 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349935 |
| ***Layer:*** | 1 |
| ***Color:*** | 8 |
| ***General Color:*** | BLACK |
| ***Material 1:*** | 27 |
| ***Material 1 Desc:*** | OTHER |
| ***Material 2:*** | |
| ***Material 2 Desc:*** | |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 0.20999999344348907 |
| ***Formation End Depth UOM:*** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349937 |
| ***Layer:*** | 3 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 05 |
| ***Material 1 Desc:*** | CLAY |
| ***Material 2:*** | 06 |
| ***Material 2 Desc:*** | SILT |
| ***Material 3:*** | 11 |
| ***Material 3 Desc:*** | GRAVEL |
| ***Formation Top Depth:*** | 4.5 |
| ***Formation End Depth:*** | 27.0 |
| ***Formation End Depth UOM:*** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349936 |
| ***Layer:*** | 2 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 28 |
| ***Material 1 Desc:*** | SAND |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 0.20999999344348907 |
| ***Formation End Depth:*** | 4.5 |
| ***Formation End Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1003349940 |
| ***Layer:*** | 2 |
| ***Plug From:*** | 16.0 |
| ***Plug To:*** | 25.0 |
| ***Plug Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1003349939 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 16.0 |
| ***Plug Depth UOM:*** | ft |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1003349944 |
| ***Method Construction Code:*** | 6 |
| ***Method Construction:*** | Boring |
| ***Other Method Construction:*** | |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1003349934 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 1003349942 |
| ***Layer:*** | 1 |
| ***Material:*** | 5 |
| ***Open Hole or Material:*** | PLASTIC |
| ***Depth From:*** | 0.0 |
| ***Depth To:*** | 25.260000228881836 |
| ***Casing Diameter:*** | 2.0 |
| ***Casing Diameter UOM:*** | inch |

***Casing Depth UOM:*** ft

***Construction Record - Screen***

***Screen ID:*** 1003349943
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 15.0
***Screen End Depth:*** 25.0
***Screen Material:***
***Screen Depth UOM:*** ft
***Screen Diameter UOM:*** inch
***Screen Diameter:*** 2.0

***Water Details***

***Water ID:*** 1003349941
***Layer:*** 1
***Kind Code:*** 1
***Kind:*** FRESH
***Water Found Depth:*** 23.100000381469727
***Water Found Depth UOM:*** ft

***Hole Diameter***

***Hole ID:*** 1003349938
***Diameter:***
***Depth From:***
***Depth To:***
***Hole Depth UOM:*** ft
***Hole Diameter UOM:*** inch

---

**124** ***1 of 2*** ***NNW/226.0*** ***73.9 / 0.00*** ***261 Cooper Street Ottawa ON K2P 0G3*** ***EHS***

***Order No:*** 25012301142
***Status:*** C
***Report Type:*** Standard Report
***Report Date:*** 28-JAN-25
***Date Received:*** 23-JAN-25
***Previous Site Name:***
***Lot/Building Size:***
***Additional Info Ordered:*** Fire Insur. Maps and/or Site Plans

***Nearest Intersection:***
***Municipality:***
***Client Prov/State:*** ON
***Search Radius (km):*** .25
***X:*** -75.6928088
***Y:*** 45.4179268

---

**124** ***2 of 2*** ***NNW/226.0*** ***73.9 / 0.00*** ***Regency Towers Ltd. 261 Cooper Street Ottawa ON K2P 0G3*** ***GEN***

***Generator Info***

***Generator No:*** ON4137516
***Approval Years:*** As of Nov 2021
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 251 L
***Waste Class Name:*** Waste oils/sludges (petroleum based)

***2021 Generator Info***

***Gen No:*** ON4137516
***ID:*** 16056
***Contaminated Fac:*** N
***MHSW Facility:*** N
***NAICS Code1:*** 531310
***NAICS Code2:***
***NAICS Code3:***
***Gen Name:*** Regency Towers Ltd.
***Gen Div:***
***Gen Op Name:*** Taggart Realty Management
***Gen Op Div:***
***Site Adrs1:*** 261 Cooper Street
***Site Bldg:***
***Site Pobox:***
***Province In:*** ONTARIO
***Site Adrs2:***
***Site City:*** Ottawa
***Province Out:***
***Site Postal Code:*** K2P 0G3
***Site Country:*** Canada
***Co Official:*** Jesse Allan
***Co Admin:***

***Choice of Contact:*** CO_OFFICIAL
***Phone No Official:*** (613) 234-7000 Ext.
***Phone No Admin:***
***County Ont:*** OTTAWA CARLTON (RM)
***County Out:***
***District:*** 402

---

**125** | ***1 of 1*** | ***SE/226.1*** | ***72.9 / -1.00*** | ***330 Metcalfe Street Ottawa Ontario Ottawa ON K2P 1S4*** | ***EHS***

***Order No:*** 20190717034
***Status:*** C
***Report Type:*** Standard Report
***Report Date:*** 22-JUL-19
***Date Received:*** 17-JUL-19
***Previous Site Name:***
***Lot/Building Size:***
***Additional Info Ordered:***

***Nearest Intersection:***
***Municipality:***
***Client Prov/State:*** ON
***Search Radius (km):*** .25
***X:*** -75.690449
***Y:*** 45.41438

---

**126** | ***1 of 1*** | ***W/226.3*** | ***75.9 / 2.00*** | ***327 Somerset St W Ottawa ON K2P0J8*** | ***EHS***

***Order No:*** 20151130011
***Status:*** C
***Report Type:*** Custom Report
***Report Date:*** 03-DEC-15
***Date Received:*** 30-NOV-15
***Previous Site Name:***
***Lot/Building Size:***
***Additional Info Ordered:***

***Nearest Intersection:***
***Municipality:***
***Client Prov/State:*** ON
***Search Radius (km):*** .25
***X:*** -75.695217
***Y:*** 45.416108

---

**127** | ***1 of 1*** | ***ENE/227.3*** | ***72.5 / -1.33*** | ***Blair's Doc B A Station 280 Elgin Ottawa ON*** | ***HBAR***

***Province:*** ON
***Year:*** 1960

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Source:** | | Mights | | | |

| | | | | | |
|---|---|---|---|---|---|
| 128 | 1 of 1 | W/228.1 | 75.9 / 2.00 | ALLAN KWAI<br>331 SOMERSET ST. W., SWM<br>OTTAWA CITY ON K2P 0J8 | CA |

| | |
|---|---|
| **Certificate #:** | 3-1581-97- |
| **Application Year:** | 97 |
| **Issue Date:** | 10/28/1997 |
| **Approval Type:** | Municipal sewage |
| **Status:** | Approved |
| **Application Type:** | |
| **Client Name:** | |
| **Client Address:** | |
| **Client City:** | |
| **Client Postal Code:** | |
| **Project Description:** | |
| **Contaminants:** | |
| **Emission Control:** | |

| | | | | | |
|---|---|---|---|---|---|
| 129 | 1 of 1 | W/228.4 | 75.9 / 2.00 | 338 SOMERSET STREET WEST<br>OTTAWA ON | WWIS |

| | | | |
|---|---|---|---|
| **Well ID:** | 7046637 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | Observation Wells | **Date Received:** | 07/17/2007 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z74024 | **Contractor:** | 7241 |
| **Tag:** | A061568 | **Form Version:** | 3 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | OTTAWA CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7046637.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | 06/22/2007 |
| **Year Completed:** | 2007 |
| **Depth (m):** | 8.23 |
| **Latitude:** | 45.4157256058949 |
| **Longitude:** | -75.6952421522528 |
| **Point X:** | -75.69524199044142 |
| **Point Y:** | 45.41572559951513 |
| **Path:** | 704\7046637.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 23046637 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |

| | | | |
|---|---|---|---|
| ***Spatial Status:*** | | ***Zone:*** | 18 |
| ***Code OB:*** | | ***East83:*** | 445602.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029369.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 3 |
| ***Date Completed:*** | 06/22/2007 | ***UTMRC Desc:*** | margin of error : 10 - 30 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 30146637 |
| ***Layer:*** | 1 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 02 |
| ***Material 1 Desc:*** | TOPSOIL |
| ***Material 2:*** | 81 |
| ***Material 2 Desc:*** | SANDY |
| ***Material 3:*** | 11 |
| ***Material 3 Desc:*** | GRAVEL |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 0.9100000262260437 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 30346637 |
| ***Layer:*** | 3 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 06 |
| ***Material 1 Desc:*** | SILT |
| ***Material 2:*** | 05 |
| ***Material 2 Desc:*** | CLAY |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 1.5 |
| ***Formation End Depth:*** | 3.6600000858306885 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 30546637 |
| ***Layer:*** | 5 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 05 |
| ***Material 1 Desc:*** | CLAY |
| ***Material 2:*** | 91 |
| ***Material 2 Desc:*** | WATER-BEARING |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 6.099999904632568 |

| | |
|---|---|
| ***Formation End Depth:*** | 8.229999542236328 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 30246637 |
| ***Layer:*** | 2 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 06 |
| ***Material 1 Desc:*** | SILT |
| ***Material 2:*** | 28 |
| ***Material 2 Desc:*** | SAND |
| ***Material 3:*** | 05 |
| ***Material 3 Desc:*** | CLAY |
| ***Formation Top Depth:*** | 0.9100000262260437 |
| ***Formation End Depth:*** | 1.5 |
| ***Formation End Depth UOM:*** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 30446637 |
| ***Layer:*** | 4 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 05 |
| ***Material 1 Desc:*** | CLAY |
| ***Material 2:*** | 06 |
| ***Material 2 Desc:*** | SILT |
| ***Material 3:*** | 85 |
| ***Material 3 Desc:*** | SOFT |
| ***Formation Top Depth:*** | 3.6600000858306885 |
| ***Formation End Depth:*** | 6.099999904632568 |
| ***Formation End Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 44001303 |
| ***Layer:*** | 3 |
| ***Plug From:*** | |
| ***Plug To:*** | |
| ***Plug Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 44001302 |
| ***Layer:*** | 2 |
| ***Plug From:*** | 0.3100000023841858 |
| ***Plug To:*** | |
| ***Plug Depth UOM:*** | m |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 44001304 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 0.3100000023841858 |

***Plug Depth UOM:*** m

***Method of Construction & Well Use***

***Method Construction ID:*** 25946637
***Method Construction Code:*** B
***Method Construction:*** Other Method
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 29046637
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 42146637
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 4.880000114440918
***Casing Diameter:*** 3.809999942779541
***Casing Diameter UOM:*** cm
***Casing Depth UOM:*** m

***Construction Record - Screen***

***Screen ID:*** 43146637
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 4.880000114440918
***Screen End Depth:*** 8.229999542236328
***Screen Material:*** 5
***Screen Depth UOM:*** m
***Screen Diameter UOM:*** cm
***Screen Diameter:***

***Hole Diameter***

***Hole ID:*** 46000804
***Diameter:*** 8.890000343322754
***Depth From:*** 0.0
***Depth To:*** 8.229999542236328
***Hole Depth UOM:*** m
***Hole Diameter UOM:*** cm

---

**130** ***1 of 1*** ***NE/228.8*** ***72.4 / -1.45*** ***ON*** ***WWIS***

| | | | |
|---|---|---|---|
| ***Well ID:*** | 7134804 | ***Flowing (Y/N):*** | |
| ***Construction Date:*** | | ***Flow Rate:*** | |
| ***Use 1st:*** | | ***Data Entry Status:*** | |
| ***Use 2nd:*** | | ***Data Src:*** | |
| ***Final Well Status:*** | Test Hole | ***Date Received:*** | 11/27/2009 |
| ***Water Type:*** | | ***Selected Flag:*** | TRUE |
| ***Casing Material:*** | | ***Abandonment Rec:*** | |
| ***Audit No:*** | 239796 | ***Contractor:*** | 6838 |

| | | | |
|---|---|---|---|
| **Tag:** | A054894 | **Form Version:** | 2 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | OTTAWA CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/713\7134804.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | 10/27/2009 |
| **Year Completed:** | 2009 |
| **Depth (m):** | 6.7056 |
| **Latitude:** | 45.4175898741975 |
| **Longitude:** | -75.690625496834 |
| **Point X:** | -75.69062533487147 |
| **Point Y:** | 45.41758986726159 |
| **Path:** | 713\7134804.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1002851141 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445965.00 |
| **Code OB Desc:** | | **North83:** | 5029573.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 10/27/2009 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| **Formation ID:** | 1003349924 |
| **Layer:** | 3 |
| **Color:** | 6 |
| **General Color:** | BROWN |
| **Material 1:** | 28 |
| **Material 1 Desc:** | SAND |
| **Material 2:** | 06 |
| **Material 2 Desc:** | SILT |
| **Material 3:** | 11 |
| **Material 3 Desc:** | GRAVEL |
| **Formation Top Depth:** | 3.0 |
| **Formation End Depth:** | 5.5 |
| **Formation End Depth UOM:** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349922 |
| ***Layer:*** | 1 |
| ***Color:*** | 8 |
| ***General Color:*** | BLACK |
| ***Material 1:*** | 27 |
| ***Material 1 Desc:*** | OTHER |
| ***Material 2:*** | |
| ***Material 2 Desc:*** | |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 0.25 |
| ***Formation End Depth UOM:*** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349923 |
| ***Layer:*** | 2 |
| ***Color:*** | 6 |
| ***General Color:*** | BROWN |
| ***Material 1:*** | 28 |
| ***Material 1 Desc:*** | SAND |
| ***Material 2:*** | 11 |
| ***Material 2 Desc:*** | GRAVEL |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 0.25 |
| ***Formation End Depth:*** | 3.0 |
| ***Formation End Depth UOM:*** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1003349925 |
| ***Layer:*** | 4 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 05 |
| ***Material 1 Desc:*** | CLAY |
| ***Material 2:*** | 06 |
| ***Material 2 Desc:*** | SILT |
| ***Material 3:*** | |
| ***Material 3 Desc:*** | |
| ***Formation Top Depth:*** | 5.5 |
| ***Formation End Depth:*** | 22.0 |
| ***Formation End Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1003349927 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 9.0 |
| ***Plug Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1003349928
***Layer:*** 2
***Plug From:*** 9.0
***Plug To:*** 20.34000015258789
***Plug Depth UOM:*** ft

***Method of Construction & Well Use***

***Method Construction ID:*** 1003349932
***Method Construction Code:*** 6
***Method Construction:*** Boring
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 1003349921
***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1003349930
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 20.34000015258789
***Casing Diameter:*** 2.0
***Casing Diameter UOM:*** inch
***Casing Depth UOM:*** ft

***Construction Record - Screen***

***Screen ID:*** 1003349931
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 10.34000015258789
***Screen End Depth:*** 20.34000015258789
***Screen Material:***
***Screen Depth UOM:*** ft
***Screen Diameter UOM:*** inch
***Screen Diameter:*** 2.0

***Water Details***

***Water ID:*** 1003349929
***Layer:*** 1
***Kind Code:*** 1
***Kind:*** FRESH
***Water Found Depth:*** 19.459999084472656
***Water Found Depth UOM:*** ft

***Hole Diameter***

***Hole ID:*** 1003349926
***Diameter:***
***Depth From:***
***Depth To:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Hole Depth UOM:** ft
**Hole Diameter UOM:** inch

---

**131** | **1 of 1** | **ENE/229.0** | **72.5 / -1.33** | **Fettuccine's**
**280 Elgin St**
**Ottawa ON K2P 1M2** | **SCT**

**Scott S ID:** 52783026
**Latitude:**
**Longitude:**

***Historical Details***

**Established:** 01-AUG-80
**Plant Size (ft²):** 1200
**Employment:**

***Historical Details***

**Description:** All Other Food Manufacturing
**SIC/NAICS Code:** 311990

---

**132** | **1 of 1** | **S/230.2** | **73.9 / 0.00** | **TOPIA ENERGY**
**311 O'CONNOR ST**
**OTTAWA ON K2P 2G9** | **RST**

**Headcode:** 924800
**Headcode Desc:** Oils-Fuel
**Phone:** 6135944777
**List Name:**
**Description:** Petroleum Products, Wholesale

---

**133** | **1 of 1** | **WNW/231.5** | **75.9 / 2.00** | **331 Cooper St**
**Ottawa ON** | **WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7334763 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | Monitoring and Test Hole | **Data Entry Status:** | |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | Monitoring and Test Hole | **Date Received:** | 03/08/2019 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z298238 | **Contractor:** | 7241 |
| **Tag:** | A257375 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | OTTAWA-CARLETON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |

**Municipality:** NEPEAN TOWNSHIP
**Site Info:**

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7334763.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | 11/14/2018 |
| **Year Completed:** | 2018 |
| **Depth (m):** | 5.4864 |
| **Latitude:** | 45.4172325169397 |
| **Longitude:** | -75.6946343758173 |
| **Point X:** | -75.69463421374994 |
| **Point Y:** | 45.41723251004211 |
| **Path:** | 733\7334763.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1007475861 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 18 |
| **Code OB:** | | **East83:** | 445651.00 |
| **Code OB Desc:** | | **North83:** | 5029536.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 11/14/2018 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Location Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| **Formation ID:** | 1007824505 |
| **Layer:** | 2 |
| **Color:** | 6 |
| **General Color:** | BROWN |
| **Material 1:** | 28 |
| **Material 1 Desc:** | SAND |
| **Material 2:** | 85 |
| **Material 2 Desc:** | SOFT |
| **Material 3:** | 77 |
| **Material 3 Desc:** | LOOSE |
| **Formation Top Depth:** | 1.0 |
| **Formation End Depth:** | 6.0 |
| **Formation End Depth UOM:** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| **Formation ID:** | 1007824506 |
| **Layer:** | 3 |
| **Color:** | 2 |
| **General Color:** | GREY |
| **Material 1:** | 05 |
| **Material 1 Desc:** | CLAY |
| **Material 2:** | 06 |
| **Material 2 Desc:** | SILT |
| **Material 3:** | 85 |
| **Material 3 Desc:** | SOFT |
| **Formation Top Depth:** | 6.0 |
| **Formation End Depth:** | 18.0 |
| **Formation End Depth UOM:** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 1007824504 |
| ***Layer:*** | 1 |
| ***Color:*** | 2 |
| ***General Color:*** | GREY |
| ***Material 1:*** | 11 |
| ***Material 1 Desc:*** | GRAVEL |
| ***Material 2:*** | 27 |
| ***Material 2 Desc:*** | OTHER |
| ***Material 3:*** | 79 |
| ***Material 3 Desc:*** | PACKED |
| ***Formation Top Depth:*** | 0.0 |
| ***Formation End Depth:*** | 1.0 |
| ***Formation End Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1007826024 |
| ***Layer:*** | 3 |
| ***Plug From:*** | 7.0 |
| ***Plug To:*** | 18.0 |
| ***Plug Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1007826022 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 1.0 |
| ***Plug Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1007826023 |
| ***Layer:*** | 2 |
| ***Plug From:*** | 1.0 |
| ***Plug To:*** | 7.0 |
| ***Plug Depth UOM:*** | ft |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1007827610 |
| ***Method Construction Code:*** | B |
| ***Method Construction:*** | Other Method |
| ***Other Method Construction:*** | Direct Push |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1007822322 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| **Casing ID:** | 1007828288 |
| **Layer:** | 1 |
| **Material:** | 5 |
| **Open Hole or Material:** | PLASTIC |
| **Depth From:** | 0.0 |
| **Depth To:** | 8.0 |
| **Casing Diameter:** | 1.3799999952316284 |
| **Casing Diameter UOM:** | Inch |
| **Casing Depth UOM:** | ft |

***Construction Record - Screen***

| | |
|---|---|
| **Screen ID:** | 1007828989 |
| **Layer:** | 1 |
| **Slot:** | 10 |
| **Screen Top Depth:** | 8.0 |
| **Screen End Depth:** | 18.0 |
| **Screen Material:** | 5 |
| **Screen Depth UOM:** | ft |
| **Screen Diameter UOM:** | inch |
| **Screen Diameter:** | 1.659999966621399 |

***Results of Well Yield Testing***

| | |
|---|---|
| **Pumping Test Method Desc:** | |
| **Pump Test ID:** | 1007829783 |
| **Pump Set At:** | |
| **Static Level:** | |
| **Final Level After Pumping:** | |
| **Recommended Pump Depth:** | |
| **Pumping Rate:** | |
| **Flowing Rate:** | |
| **Recommended Pump Rate:** | |
| **Levels UOM:** | ft |
| **Rate UOM:** | GPM |
| **Water State After Test Code:** | |
| **Water State After Test:** | |
| **Pumping Test Method:** | 0 |
| **Pumping Duration HR:** | |
| **Pumping Duration MIN:** | |
| **Flowing:** | |

***Hole Diameter***

| | |
|---|---|
| **Hole ID:** | 1007827265 |
| **Diameter:** | 2.375 |
| **Depth From:** | 0.0 |
| **Depth To:** | 18.0 |
| **Hole Depth UOM:** | ft |
| **Hole Diameter UOM:** | Inch |

---

**134** | ***1 of 1*** | ***WNW/232.4*** | ***75.9 / 2.00*** | ***335 Cooper Street Ottawa ON K2P 0G5*** | ***EHS***

| | | | |
|---|---|---|---|
| **Order No:** | 21041400015 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 19-APR-21 | **Search Radius (km):** | .25 |
| **Date Received:** | 14-APR-21 | **X:** | -75.6947608 |
| **Previous Site Name:** | | **Y:** | 45.4171295 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 135 | 1 of 1 | SE/232.7 | 72.9 / -1.00 | 295 frank st<br>Ottawa ON K2P 0X7 | EHS |

**Order No:** 21122000838
**Status:** C
**Report Type:** Standard Report
**Report Date:** 23-DEC-21
**Date Received:** 20-DEC-21
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.6906445
**Y:** 45.4141978

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 136 | 1 of 8 | WNW/233.4 | 75.9 / 2.00 | Tartan Land Corporation<br>331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | CA |

**Certificate #:** 7703-4KFM9J
**Application Year:** 00
**Issue Date:** 5/19/00
**Approval Type:** Municipal & Private sewage
**Status:** Approved
**Application Type:** New Certificate of Approval
**Client Name:** South Nepean Development Corporation
**Client Address:** 427 Laurier Ave. W., Unit 300
**Client City:** Ottawa
**Client Postal Code:**
**Project Description:** Storm and Sanitary Sewers to be constructed in the City of Nepean.
**Contaminants:**
**Emission Control:**

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 136 | 2 of 8 | WNW/233.4 | 75.9 / 2.00 | Tartan Land Corporation<br>331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | CA |

**Certificate #:** 3476-4KFMVT
**Application Year:** 00
**Issue Date:** 7/13/00
**Approval Type:** Municipal & Private water
**Status:** Revoked and/or Replaced
**Application Type:** New Certificate of Approval
**Client Name:** South Nepean Development Corporation
**Client Address:** 427 Laurier Ave. W., Unit 300
**Client City:** Ottawa
**Client Postal Code:**
**Project Description:** Watermains to be constructed in the City of Nepean
**Contaminants:**
**Emission Control:**

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 136 | 3 of 8 | WNW/233.4 | 75.9 / 2.00 | Tartan Land Corporation<br>331 Cooper Street, Suite 400<br>Ottawa ON K2P 0G5 | CA |

**Certificate #:** 3735-4M5HET
**Application Year:** 00
**Issue Date:** 7/13/00
**Approval Type:** Municipal & Private water
**Status:** Approved
**Application Type:** Amended CofA

**Client Name:** South Nepean Development Corporation
**Client Address:** 427 Laurier Ave. W., Unit 300
**Client City:** Ottawa
**Client Postal Code:** K1R 7Y2
**Project Description:** Amend C/A to correct description of works
**Contaminants:**
**Emission Control:**

---

**136** **4 of 8** **WNW/233.4** **75.9 / 2.00** **South Nepean Development Corporation**
**331 Cooper Street, Suite 400**
**Ottawa ON K1R 7Y2** **ECA**

**Approval No:** 3735-4M5HET
**Approval Date:** 2000-07-13
**Status:** Approved
**Record Type:** ECA
**Link Source:** IDS
**SWP Area Name:** Rideau Valley
**Approval Type:** ECA-Municipal and Private Water Works
**Project Type:** Municipal and Private Water Works
**Business Name:** South Nepean Development Corporation
**Address:** 331 Cooper Street, Suite 400
**Full Address:**
**Full PDF Link:**
**PDF Site Location:**
**MOE District:** Ottawa
**City:**
**Longitude:** -75.69465
**Latitude:** 45.417255
**Geometry X:**
**Geometry Y:**

---

**136** **5 of 8** **WNW/233.4** **75.9 / 2.00** **South Nepean Development Corporation**
**331 Cooper Street, Suite 400**
**Ottawa ON** **ECA**

**Approval No:** 7703-4KFM9J
**Approval Date:** 2000-05-19
**Status:** Approved
**Record Type:** ECA
**Link Source:** IDS
**SWP Area Name:** Rideau Valley
**Approval Type:** ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
**Project Type:** MUNICIPAL AND PRIVATE SEWAGE WORKS
**Business Name:** South Nepean Development Corporation
**Address:** 331 Cooper Street, Suite 400
**Full Address:**
**Full PDF Link:** https://www.accessenvironment.ene.gov.on.ca/instruments/3341-4K9RJV-14.pdf
**PDF Site Location:**
**MOE District:** Ottawa
**City:**
**Longitude:** -75.69465
**Latitude:** 45.417255
**Geometry X:**
**Geometry Y:**

---

**136** **6 of 8** **WNW/233.4** **75.9 / 2.00** **South Nepean Development Corporation**
**331 Cooper Street, Suite 400**
**Ottawa ON** **ECA**

**Approval No:** 3476-4KFMVT
**Approval Date:** 2000-07-13
**Status:** Revoked and/or Replaced
**Record Type:** ECA
**Link Source:** IDS
**SWP Area Name:** Rideau Valley
**Approval Type:** ECA-Municipal and Private Water Works
**Project Type:** Municipal and Private Water Works
**Business Name:** South Nepean Development Corporation
**Address:** 331 Cooper Street, Suite 400
**Full Address:**
**Full PDF Link:**
**MOE District:** Ottawa
**City:**
**Longitude:** -75.69465
**Latitude:** 45.417255
**Geometry X:**
**Geometry Y:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**PDF Site Location:**

---

**136** **7 of 8** **WNW/233.4** **75.9 / 2.00** **PIPELINE HIT 1"** **PINC**
**331 COOPER ST,,OTTAWA,ON,K2P 0G5,CA**
**ON**

**Incident Id:**
**Incident No:** 2409866
**Incident Reported Dt:** 10/1/2018
**Type:** FS-Pipeline Incident
**Status Code:**
**Tank Status:** Pipeline Damage Reason Est
**Task No:**
**Spills Action Centre:**
**Fuel Type:**
**Fuel Occurrence Tp:**
**Date of Occurrence:**
**Occurrence Start Dt:**
**Depth:**
**Customer Acct Name:** PIPELINE HIT 1"
**Incident Address:** 331 COOPER ST,,OTTAWA,ON,K2P 0G5,CA
**Operation Type:**
**Pipeline Type:**
**Regulator Type:**
**Summary:**
**Reported By:**
**Affiliation:**
**Occurrence Desc:**
**Damage Reason:**
**Notes:**

**Pipe Material:**
**Fuel Category:**
**Health Impact:**
**Environment Impact:**
**Property Damage:**
**Service Interrupt:**
**Enforce Policy:**
**Public Relation:**
**Pipeline System:**
**PSIG:**
**Attribute Category:**
**Regulator Location:**
**Method Details:**

---

**136** **8 of 8** **WNW/233.4** **75.9 / 2.00** **Enbridge Gas Distribution Inc.** **SPL**
**331 Cooper St.**
**Ottawa ON**

**Ref No:** 2853-B52NE2
**Year:**
**Incident Dt:** 2018/09/28
**Dt MOE Arvl on Scn:**
**MOE Reported Dt:** 2018/09/28
**Dt Document Closed:**
**Site No:** NA
**MOE Response:** No
**Site County/District:**
**Site Geo Ref Meth:**
**Site District Office:** Ottawa
**Nearest Watercourse:**
**Site Name:** 1 Inch IP Plastic Service Damage <UNOFFICIAL>
**Site Address:** 331 Cooper St.
**Site Region:** Eastern
**Site Municipality:** Ottawa
**Site Lot:**
**Site Conc:**
**Site Geo Ref Accu:**
**Site Map Datum:**
**Northing:**
**Easting:**
**Entity Operating Name:**
**Client Name:** Enbridge Gas Distribution Inc.
**Client Type:** Corporation
**Source Type:** Valve/Fitting/Piping
**Incident Cause:**

**Municipality No:**
**Nature of Damage:**
**Discharger Report:**
**Material Group:**
**Impact to Health:** 0 - No Impact
**Agency Involved:**

| | |
|---|---|
| ***Incident Preceding Spill:*** | Leak/Break |
| ***Incident Reason:*** | Operator/Human Error |
| ***Incident Summary:*** | TSSA/FSB: 1" IP Plastic Line Strike - Made Safe |
| ***Environment Impact:*** | |
| ***Health Env Consequence:*** | |
| ***Nature of Impact:*** | |
| ***Contaminant Qty:*** | 0 other - see incident description |
| ***Contaminant Qty 1:*** | 0 |
| ***Contaminant Unit:*** | other - see incident description |
| ***Contaminant Code:*** | 35 |
| ***Contaminant Name:*** | NATURAL GAS (METHANE) |
| ***Contaminant Limit 1:*** | |
| ***Contam Limit Freq 1:*** | |
| ***Contaminant UN No 1:*** | 1075 |
| ***Receiving Medium:*** | Air |
| ***Activity Preceding Spill:*** | |
| ***Property 2nd Watershed:*** | |
| ***Property Tertiary Watershed:*** | |
| ***Sector Type:*** | Miscellaneous Industrial |
| ***SAC Action Class:*** | TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill |
| ***Call Report Locatn Geodata:*** | |
| ***Time Reported:*** | |
| ***System Facility Address:*** | |
| ***Source Sector Type:*** | |
| ***Conservtn Auth Name:*** | |
| ***Primary Watershed:*** | |
| ***Quaternary Watershed:*** | |
| ***Offsite Impacts Y N:*** | |
| ***Waterbody Impacted Y N:*** | |

| | | | | | |
|---|---|---|---|---|---|
| **137** | ***1 of 5*** | ***NE/233.9*** | ***72.2 / -1.69*** | ***264 Elgin St***<br>***Ottawa ON K2P 1M2*** | ***EHS*** |

| | | | |
|---|---|---|---|
| ***Order No:*** | 20091002002 | ***Nearest Intersection:*** | Somerset St. W @ Elgin St. |
| ***Status:*** | C | ***Municipality:*** | Ottawa |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 10/13/2009 | ***Search Radius (km):*** | 0.25 |
| ***Date Received:*** | 10/2/2009 | ***X:*** | -75.690535 |
| ***Previous Site Name:*** | | ***Y:*** | 45.417555 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | Fire Insur. Maps and/or Sire Plans; Title Searches; City Directory | | |

| | | | | | |
|---|---|---|---|---|---|
| **137** | ***2 of 5*** | ***NE/233.9*** | ***72.2 / -1.69*** | ***WHITE CROSS DISPENSARY***<br>***264 ELGIN STREET***<br>***OTTAWA ON K2P 1M2*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON2571000 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 00,01 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 6031 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | PHARMACIES | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 261 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Waste Class Name:** PHARMACEUTICALS

***Waste Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

**137** | ***3 of 5*** | ***NE/233.9*** | ***72.2 / -1.69*** | ***White Cross Dispensary Ottawa 2006 Ltd***
***264 Elgin Street***
***Ottawa ON K2P 1M2*** | ***GEN***

***Generator Info***

**Generator No:** ON9398334
**Approval Years:** As of Jul 2020
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 261 A
**Waste Class Name:** Pharmaceuticals

---

**137** | ***4 of 5*** | ***NE/233.9*** | ***72.2 / -1.69*** | ***White Cross Dispensary Ottawa 2006 Ltd***
***264 Elgin Street***
***Ottawa ON K2P 1M2*** | ***GEN***

***Generator Info***

**Generator No:** ON9398334
**Approval Years:** As of Nov 2021
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** Pathological wastes

***Waste Detail(s)***

**Waste Class:** 261 A
**Waste Class Name:** Pharmaceuticals

---

**137** | ***5 of 5*** | ***NE/233.9*** | ***72.2 / -1.69*** | ***White Cross Dispensary***
***264 Elgin Street***
***Ottawa ON*** | ***GEN***

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON9398334 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Oct 2022 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 261 A |
| ***Waste Class Name:*** | PHARMACEUTICALS |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 P |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

***Generator Info (as of Dec 2024)***

| | |
|---|---|
| ***Generator No:*** | ON9398334 |
| ***Generator Company Name:*** | White Cross Dispensary |
| ***Street:*** | 264 Elgin Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1M2 |
| ***Waste Class:*** | 261 A,312 P |

***Waste Class Decoded:***

261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Generator Info (as of Apr 2025)***

| | |
|---|---|
| ***Generator Company Name:*** | White Cross Dispensary |
| ***Generator Site Address:*** | 264 Elgin Street |
| ***City:*** | Ottawa |
| ***Province State:*** | Ontario |
| ***Country:*** | Canada |
| ***Postal Code:*** | K2P1M2 |
| ***Waste Class:*** | 261 A, 312 P |

***Waste Class Decoded:***

261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

***Waste Characteristic Decoded:***

A - Acutely Hazardous Waste Chem.; P - Pathological

***2020 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON9398334 | ***Choice of Contact:*** | CO_OFFICIAL |

| | | | |
|---|---|---|---|
| **ID:** | 37737 | **Phone No Official:** | 6132334029 Ext.34029 |
| **Contaminated Fac:** | N | **Phone No Admin:** | 6133271056 Ext. |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 446110 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | White Cross Dispensary Ottawa 2006 Ltd | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | White Cross Dispensary | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 264 Elgin Street | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | | | |
| **Site City:** | Ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P 1M2 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | Chantal or James Dumont | | |
| **Co Admin:** | James James Dumont | | |

***2020 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 61908 | **Sum Received Qty:** | 19.5 |
| **Generator No:** | ON9398334 | **Waste Class Name:** | PHARMACEUTICALS |
| **Receiver Type:** | 030 | **Count Manifests:** | 2 |
| **Waste Char:** | A | **District:** | 402 |
| **Waste Code:** | 261 | | |

***2021 Generator Info***

| | | | |
|---|---|---|---|
| **Gen No:** | ON9398334 | **Choice of Contact:** | CO_OFFICIAL |
| **ID:** | 38722 | **Phone No Official:** | 6132334029 Ext.34029 |
| **Contaminated Fac:** | N | **Phone No Admin:** | 6133271056 Ext. |
| **MHSW Facility:** | N | **County Ont:** | OTTAWA CARLTON (RM) |
| **NAICS Code1:** | 446110 | **County Out:** | |
| **NAICS Code2:** | | **District:** | 402 |
| **NAICS Code3:** | | | |
| **Gen Name:** | White Cross Dispensary Ottawa 2006 Ltd | | |
| **Gen Div:** | | | |
| **Gen Op Name:** | White Cross Dispensary | | |
| **Gen Op Div:** | | | |
| **Site Adrs1:** | 264 Elgin Street | | |
| **Site Bldg:** | | | |
| **Site Pobox:** | | | |
| **Province In:** | ONTARIO | | |
| **Site Adrs2:** | | | |
| **Site City:** | Ottawa | | |
| **Province Out:** | | | |
| **Site Postal Code:** | K2P 1M2 | | |
| **Site Country:** | Canada | | |
| **Co Official:** | Chantal or James Dumont | | |
| **Co Admin:** | James James Dumont | | |

***2021 Generator Manifest***

| | | | |
|---|---|---|---|
| **ID:** | 64729 | **Sum Received Qty:** | 30.74 |
| **Generator No:** | ON9398334 | **Waste Class Name:** | PHARMACEUTICALS |
| **Receiver Type:** | 030 | **Count Manifests:** | 1 |
| **Waste Char:** | A | **District:** | 402 |
| **Waste Code:** | 261 | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***2021 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 64730 | ***Sum Received Qty:*** | 8.2 |
| ***Generator No:*** | ON9398334 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 030 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | P | ***District:*** | 402 |
| ***Waste Code:*** | 312 | | |

---

**138** ***1 of 1*** ***S/234.7*** ***73.9 / 0.00*** ***CMG*** ***GEN***
***344 Waverley St.***
***Ottawa ON K2P 0W5***

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON5378833 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2010 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 531310 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | Real Estate Property Managers | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 251 |
| ***Waste Class Name:*** | OIL SKIMMINGS & SLUDGES |

---

**139** ***1 of 1*** ***ENE/234.8*** ***72.9 / -1.00*** ***292 Elgin Street Ottawa Ontario*** ***EHS***
***Ottawa ON K2P 1M3***

| | | | |
|---|---|---|---|
| ***Order No:*** | 22042501257 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 28-APR-22 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 25-APR-22 | ***X:*** | -75.6896014 |
| ***Previous Site Name:*** | | ***Y:*** | 45.4167895 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | | | |

---

**140** ***1 of 1*** ***WNW/235.7*** ***75.9 / 2.00*** ***BORE***
***ON***

| | | | |
|---|---|---|---|
| ***Borehole ID:*** | 613315 | ***Inclin FLG:*** | No |
| ***OGF ID:*** | 215514614 | ***SP Status:*** | Initial Entry |
| ***Status:*** | | ***Surv Elev:*** | No |
| ***Type:*** | Borehole | ***Piezometer:*** | No |
| ***Use:*** | | ***Primary Name:*** | |
| ***Completion Date:*** | | ***Municipality:*** | |
| ***Static Water Level:*** | | ***Lot:*** | |
| ***Primary Water Use:*** | | ***Township:*** | |
| ***Sec. Water Use:*** | | ***Latitude DD:*** | 45.417288 |
| ***Total Depth m:*** | -999 | ***Longitude DD:*** | -75.694639 |
| ***Depth Ref:*** | Ground Surface | ***UTM Zone:*** | 18 |
| ***Depth Elev:*** | | ***Easting:*** | 445651 |
| ***Drill Method:*** | | ***Northing:*** | 5029542 |
| ***Orig Ground Elev m:*** | 71.2 | ***Location Accuracy:*** | |
| ***Elev Reliabil Note:*** | | ***Accuracy:*** | Not Applicable |
| ***DEM Ground Elev m:*** | 71.7 | | |

***Concession:***
***Location D:***
***Survey D:***
***Comments:***

***Borehole Geology Stratum***

***Geology Stratum ID:*** 218394619
***Top Depth:*** 12.3
***Bottom Depth:***
***Material Color:***
***Material 1:*** Bedrock
***Material 2:*** Shale
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** BEDROCK. 0050 043 00080 058 00115 062 00000062000500240022 6DENSE. BEDROCK.
***Mat Consistency:*** Dense
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394613
***Top Depth:*** 1.7
***Bottom Depth:*** 3
***Material Color:*** Grey
***Material 1:*** Clay
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** CLAY. GREY,HARD.
***Mat Consistency:*** Hard
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394618
***Top Depth:*** 10.1
***Bottom Depth:*** 12.3
***Material Color:***
***Material 1:*** Till
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** TILL. COMPACT.
***Mat Consistency:*** Compact
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394615
***Top Depth:*** 6.1
***Bottom Depth:*** 7.6
***Material Color:*** Grey
***Material 1:*** Clay
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** CLAY. GREY,FIRM.
***Mat Consistency:*** Firm
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394611
***Top Depth:*** 0
***Bottom Depth:*** 1.5
***Material Color:***
***Material 1:*** Sand
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** SAND. LOOSE.
***Mat Consistency:*** Loose
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394612
***Top Depth:*** 1.5
***Bottom Depth:*** 1.7
***Mat Consistency:*** Loose
***Material Moisture:***
***Material Texture:***

| | | | |
|---|---|---|---|
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Sand | **Geologic Formation:** | |
| **Material 2:** | Pebbles | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | SAND,PEBBLES. LOOSE. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394614 | **Mat Consistency:** | Soft |
| **Top Depth:** | 3 | **Material Moisture:** | |
| **Bottom Depth:** | 6.1 | **Material Texture:** | |
| **Material Color:** | Grey | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | Shells | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | CLAY. GREY,SOFT. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394617 | **Mat Consistency:** | Firm |
| **Top Depth:** | 9.1 | **Material Moisture:** | |
| **Bottom Depth:** | 10.1 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Till | **Geologic Formation:** | |
| **Material 2:** | Sand | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | TILL. FIRM. | | |

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394616 | **Mat Consistency:** | Loose |
| **Top Depth:** | 7.6 | **Material Moisture:** | |
| **Bottom Depth:** | 9.1 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Till | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |
| **Gsc Material Description:** | | | |
| **Stratum Description:** | TILL. LOOSE. | | |

***Source***

| | | | |
|---|---|---|---|
| **Source Type:** | Data Survey | **Source Appl:** | Spatial/Tabular |
| **Source Orig:** | Geological Survey of Canada | **Source Iden:** | 1 |
| **Source Date:** | 1956-1972 | **Scale or Res:** | Varies |
| **Confidence:** | H | **Horizontal:** | NAD27 |
| **Observatio:** | | **Verticalda:** | Mean Average Sea Level |
| **Source Name:** | Urban Geology Automated Information System (UGAIS) | | |
| **Source Details:** | File: OTTAWA2.txt RecordID: 058230 NTS_Sheet: 31G05G | | |
| **Confiden 1:** | Logged by professional. Exact and complete description of material and properties. | | |

***Source List***

| | | | |
|---|---|---|---|
| **Source Identifier:** | 1 | **Horizontal Datum:** | NAD27 |
| **Source Type:** | Data Survey | **Vertical Datum:** | Mean Average Sea Level |
| **Source Date:** | 1956-1972 | **Projection Name:** | Universal Transverse Mercator |
| **Scale or Resolution:** | Varies | | |
| **Source Name:** | Urban Geology Automated Information System (UGAIS) | | |
| **Source Originators:** | Geological Survey of Canada | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 141 | 1 of 3 | NE/235.9 | 72.5 / -1.33 | 350807 ONTARIO LTD ELGIN SERVICE CENTRE<br>280 ELGIN ST | DTNK |

OTTAWA ON

***Delisted Expired Fuel Safety Facilities***

| | | | |
|---|---|---|---|
| ***Instance No:*** | 9826748 | ***Expired Date:*** | |
| ***Status:*** | EXPIRED | ***Max Hazard Rank:*** | |
| ***Instance ID:*** | 394383 | ***Facility Location:*** | |
| ***Instance Type:*** | FS Facility | ***Facility Type:*** | |
| ***Instance Creation Dt:*** | | ***Fuel Type 2:*** | |
| ***Instance Install Dt:*** | | ***Fuel Type 3:*** | |
| ***Item Description:*** | | ***Panam Related:*** | |
| ***Manufacturer:*** | | ***Panam Venue Nm:*** | |
| ***Model:*** | | ***External Identifier:*** | |
| ***Serial No:*** | | ***Item:*** | |
| ***ULC Standard:*** | | ***Piping Steel:*** | |
| ***Quantity:*** | | ***Piping Galvanized:*** | |
| ***Unit of Measure:*** | | ***Tank Single Wall St:*** | |
| ***Overfill Prot Type:*** | | ***Piping Underground:*** | |
| ***Creation Date:*** | | ***Tank Underground:*** | |
| ***Next Periodic Str DT:*** | | ***Source:*** | |
| ***TSSA Base Sched Cycle 2:*** | | | |
| ***TSSAMax Hazard Rank 1:*** | | | |
| ***TSSA Risk Based Periodic Yn:*** | | | |
| ***TSSA Volume of Directives:*** | | | |
| ***TSSA Periodic Exempt:*** | | | |
| ***TSSA Statutory Interval:*** | | | |
| ***TSSA Recd Insp Interva:*** | | | |
| ***TSSA Recd Tolerance:*** | | | |
| ***TSSA Program Area:*** | | | |
| ***TSSA Program Area 2:*** | | | |
| ***Description:*** | FS Gasoline Station - Full Serve | | |
| ***Original Source:*** | EXP | | |
| ***Record Date:*** | Up to Mar 2012 | | |

| | | | | | |
|---|---|---|---|---|---|
| 141 | ***2 of 3*** | ***NE/235.9*** | ***72.5 / -1.33*** | ***SUNSHINE BICYCLE BOARD & BLADES***<br>***280 ELGIN STREET***<br>***OTTAWA ON K2P 1M2*** | ***GEN*** |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON1740001 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 94,95,96,97,98,99,00,01 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 6542 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | BICYCLE SHOPS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 213 |
| ***Waste Class Name:*** | PETROLEUM DISTILLATES |

| | | | | | |
|---|---|---|---|---|---|
| 141 | ***3 of 3*** | ***NE/235.9*** | ***72.5 / -1.33*** | ***350807 ONTARIO LTD ELGIN SERVICE CENTRE***<br>***280 ELGIN ST***<br>***OTTAWA ON K2P 1M2*** | ***PRT*** |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Location ID:** 10935
**Type:** retail
**Expiry Date:** 1994-06-30
**Capacity (L):** 8000
**Licence #:** 0056039001

---

142 **1 of 4** **ENE/236.6** **72.9 / -1.00** **JUST TYPESETTING**
**298 ELGIN ST. ST. 105**
**OTTAWA ON K2P 1M3**
**GEN**

***Generator Info***

**Generator No:** ON1014300
**Approval Years:** 88,89,90
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** PLATEMAKING, ETC.

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 2821

***Waste Detail(s)***

**Waste Class:** 264
**Waste Class Name:** PHOTOPROCESSING WASTES

---

142 **2 of 4** **ENE/236.6** **72.9 / -1.00** **JUST TYPESETTING (OUT OF BUSINESS)**
**298 ELGIN ST. ST. 105**
**OTTAWA ON K2P 1M3**
**GEN**

***Generator Info***

**Generator No:** ON1014300
**Approval Years:** 92,93,96,97,98
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** PLATEMAKING, ETC.

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 2821

***Waste Detail(s)***

**Waste Class:** 264
**Waste Class Name:** PHOTOPROCESSING WASTES

---

142 **3 of 4** **ENE/236.6** **72.9 / -1.00** **JUST TYPESETTING 22-281**
**298 ELGIN ST. ST. 105**
**OTTAWA ON K2P 1M3**
**GEN**

***Generator Info***

**Generator No:** ON1014300
**Approval Years:** 94,95
**Status:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** PLATEMAKING, ETC.

**SIC Code:** 2821

***Waste Detail(s)***

**Waste Class:** 264
**Waste Class Name:** PHOTOPROCESSING WASTES

---

**142** **4 of 4** **ENE/236.6** **72.9 / -1.00**

***Empire Photo and Video Inc.***
***298 Elgin St #104***
***Ottawa ON K2P1M3***

**SCT**

**Scott S ID:** 73117832
**Latitude:** 45.4165993
**Longitude:** -75.6894703

***Details***

**Bus Type 1:** Information and Cultural Industries
**Bus Type 2:** Manufacturer
**Bus Type 3:** Professional; Scientific & Technical Services
**Product Cat 1:** Digital imaging services
**Product Cat 2:** Photographer
**Product Cat 3:** Photographic services
**Product Cat 4:** Photography Service
**Product Cat 5:** Printing: commercial
**Product Cat 6:** Video editing service
**Product Cat 7:** Video production service
**Product Cat 8:** Video production: corporate
**Company Name:** Empire Photo and Video Inc.
**Address Line 1:** 298 Elgin St #104
**Address Line 2:**
**City:** Ottawa
**Province:** ON
**Postal Code:** K2P1M3
**Census Division:** Ottawa; ON
**Metro Area:** Ottawa/Hull
**Year Established:** 2009
**Head Office Indicator:** N
**Parent Company Nm:**
**Parent Cmpny Addr 1:**
**Parent Cmpny Addr 2:**
**Parent Cmpny City:**
**Parent Cmpny Prov:**
**Parent Cmpy PC:**
**Parent Cmpy Cntry:**
**Head Office Nm:**
**H Office Addr Line 1:**
**H Office Addr Line 2:**
**Head Office City:**
**Head Office Province:**
**Head Office PC:**
**Head Office Cntry:**
**Telephone:** 800-280-5980
**Fax:**
**Website:** http://www.empirephotoandvideo.com/
**Pri NAICS Desc:** 518210-Data Processing; Hosting; and Related Services
**NAICS Code 1:** 323114-Quick Printing
**NAICS Code 2:** 323115-Digital Printing
**NAICS Code 3:** 323119-Other Printing

**Employee Count:** 5
**Square Footage:** 1500
**Estimated Sales:** Under $1 Million
**Export Indicator:** N
**Export Country 1:**
**Export Country 2:**
**Export Country 3:**
**Export Country 4:**
**Export Country 5:**
**Export Country 6:**
**Geocoded by:** Address

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **NAICS Code 4:** | | 512110-Motion Picture and Video Production | | | |
| **NAICS Code 5:** | | 518210-Data Processing; Hosting; and Related Servi | | | |

| | | | | | |
|---|---|---|---|---|---|
| 143 | 1 of 2 | ENE/236.8 | 72.9 / -1.00 | **BROWNS CLEANERS & TAILORS LTD.**<br>**300 ELGIN STREET C/O 6 CHAMPAGNE AVENUE NORTH**<br>**OTTAWA-CARLTON ON K2P 1M3** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON0443203 | **Choice of Contact:** | |
| **Approval Years:** | 88,89,90 | **Contaminated Fac:** | |
| **Status:** | | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | 9721 |
| **Country:** | | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | POWER LAUND./CLEANER | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 241 |
| **Waste Class Name:** | HALOGENATED SOLVENTS |

| | | | | | |
|---|---|---|---|---|---|
| 143 | 2 of 2 | ENE/236.8 | 72.9 / -1.00 | **BROWNS CLEANERS & TAILORS LTD. 06-342**<br>**300 ELGIN STREET C/O 6 CHAMPAGNE AVENUE NORTH**<br>**OTTAWA-CARLTON ON K2P 1M3** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON0443203 | **Choice of Contact:** | |
| **Approval Years:** | 92,93,94,95,96,97,98 | **Contaminated Fac:** | |
| **Status:** | | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | 9721 |
| **Country:** | | | |
| **Co Admin:** | | | |
| **Phone No Admin:** | | | |
| **SIC Description:** | POWER LAUND./CLEANER | | |

***Waste Detail(s)***

| | |
|---|---|
| **Waste Class:** | 241 |
| **Waste Class Name:** | HALOGENATED SOLVENTS |

| | | | | | |
|---|---|---|---|---|---|
| 144 | 1 of 1 | ENE/240.9 | 72.9 / -1.00 | **ENR Abraham**<br>**284 Elgin**<br>**Ottawa ON K2P 1M3** | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| **Generator No:** | ON7298698 | **Choice of Contact:** | |
| **Approval Years:** | As of Oct 2022 | **Contaminated Fac:** | |
| **Status:** | Registered | **MHSW Facility:** | |
| **PO Box No:** | | **SIC Code:** | |
| **Country:** | Canada | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Waste Detail(s)***

***Waste Class:*** 251 L
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 145 | 1 of 2 | NW/241.0 | 74.8 / 0.88 | Danosh construction<br>325 Cooper St<br>ottawa ON K2P 0G5 | GEN |

***Generator Info***

***Generator No:*** ON4032240
***Approval Years:*** As of Jul 2020
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 221 L
***Waste Class Name:*** Light fuels

***Waste Detail(s)***

***Waste Class:*** 221 I
***Waste Class Name:*** Light fuels

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 145 | 2 of 2 | NW/241.0 | 74.8 / 0.88 | Danosh construction<br>325 Cooper St<br>ottawa ON K2P 0G5 | GEN |

***Generator Info***

***Generator No:*** ON4032240
***Approval Years:*** As of Jan 2021
***Status:*** Registered
***PO Box No:***
***Country:*** Canada
***Co Admin:***
***Phone No Admin:***
***SIC Description:***

***Choice of Contact:***
***Contaminated Fac:***
***MHSW Facility:***
***SIC Code:***

***Waste Detail(s)***

***Waste Class:*** 221 I
***Waste Class Name:*** Light fuels

***Waste Detail(s)***

**Waste Class:** 221 L
**Waste Class Name:** Light fuels

***2020 Generator Info***

**Gen No:** ON4032240
**ID:** 15601
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 814110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Danosh construction
**Gen Div:**
**Gen Op Name:** danosh construction
**Gen Op Div:**
**Site Adrs1:** 325 Cooper St
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** ottawa
**Province Out:**
**Site Postal Code:** K2P 0G5
**Site Country:** Canada
**Co Official:** frank kelly
**Co Admin:** Kyla Kroon
**Choice of Contact:** CO_ADMIN
**Phone No Official:** 9054736883 Ext.
**Phone No Admin:** 9054736883 Ext.
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2020 Generator Manifest***

**ID:** 35377
**Generator No:** ON4032240
**Receiver Type:** 035
**Waste Char:** I
**Waste Code:** 221
**Sum Received Qty:** 660.0
**Waste Class Name:** LIGHT FUELS
**Count Manifests:** 1
**District:** 306

---

**146** | ***1 of 3*** | ***NE/241.4*** | ***72.2 / -1.69*** | ***190 Somerset Street West Ottawa ON K2P0J1*** | ***EHS***

**Order No:** 20111216007
**Status:** C
**Report Type:** Standard Report
**Report Date:** 12/29/2011 10:25:44 AM
**Date Received:** 12/16/2011 10:25:44 AM
**Previous Site Name:**
**Lot/Building Size:** 9390.9800 ft²
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans; City Directory
**Nearest Intersection:**
**Municipality:** Ottawa
**Client Prov/State:** ON
**Search Radius (km):** 0.25
**X:** -75.690496
**Y:** 45.417633

---

**146** | ***2 of 3*** | ***NE/241.4*** | ***72.2 / -1.69*** | ***190 Somerset St. W. Ottawa ON*** | ***EHS***

**Order No:** 20120530036
**Status:** C
**Report Type:** Standard Report
**Report Date:** 08-JUN-12
**Date Received:** 30-MAY-12
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Title Searches
**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.690504
**Y:** 45.417617

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 146 | 3 of 3 | NE/241.4 | 72.2 / -1.69 | DST Consulting<br>190 somerset west<br>ottawa ON | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON8660664 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2011 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 236210 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 147 | 1 of 4 | NE/242.6 | 71.8 / -2.06 | AIM Healt Group - Elgin<br>270 Elgin Street<br>Ottawa ON K2P 1M2 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON5048940 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 2011 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 621110 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 147 | 2 of 4 | NE/242.6 | 71.8 / -2.06 | Saralex Medical Inc.<br>270 Elgin Street<br>Ottawa ON K2P 1M2 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON6000631 | ***Choice of Contact:*** | CO_ADMIN |
| ***Approval Years:*** | 2016 | ***Contaminated Fac:*** | No |
| ***Status:*** | | ***MHSW Facility:*** | No |
| ***PO Box No:*** | | ***SIC Code:*** | 621110 |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | Frederika Dana | | |
| ***Phone No Admin:*** | 613-230-8885 Ext.264 | | |
| ***SIC Description:*** | OFFICES OF PHYSICIANS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 312 |
| ***Waste Class Name:*** | PATHOLOGICAL WASTES |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 147 | 3 of 4 | NE/242.6 | 71.8 / -2.06 | Saralex Medical Inc.<br>270 Elgin Street<br>Ottawa ON K2P 1M2 | GEN |

***Generator Info***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Generator No:** ON6000631
**Approval Years:** As of Dec 2018
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** Pathological wastes

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 147 | 4 of 4 | NE/242.6 | 71.8 / -2.06 | **Saralex Medical Inc.**<br>**270 Elgin Street**<br>**Ottawa ON K2P 1M2** | GEN |

***Generator Info***

**Generator No:** ON6000631
**Approval Years:** As of Oct 2019
**Status:** Registered
**PO Box No:**
**Country:** Canada
**Co Admin:**
**Phone No Admin:**
**SIC Description:**

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:**

***Waste Detail(s)***

**Waste Class:** 312 P
**Waste Class Name:** Pathological wastes

***2017 Generator Info***

**Gen No:** ON6000631
**ID:** 23634
**Contaminated Fac:** N
**MHSW Facility:** N
**NAICS Code1:** 621110
**NAICS Code2:**
**NAICS Code3:**
**Gen Name:** Saralex Medical Inc.
**Gen Div:**
**Gen Op Name:** Heart of Ottawa Health Centre
**Gen Op Div:**
**Site Adrs1:** 270 Elgin Street
**Site Bldg:**
**Site Pobox:**
**Province In:** ONTARIO
**Site Adrs2:**
**Site City:** Ottawa
**Province Out:**
**Site Postal Code:** K2P 1M2
**Site Country:** Canada
**Co Official:** James Dumont
**Co Admin:** Frederika Dana

**Choice of Contact:** CO_ADMIN
**Phone No Official:** 613-230-8885 Ext.232
**Phone No Admin:** 613-230-8885 Ext.264
**County Ont:** OTTAWA CARLTON (RM)
**County Out:**
**District:** 402

***2017 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 48798 | ***Sum Received Qty:*** | 78.5 |
| ***Generator No:*** | ON6000631 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 3 |
| ***Waste Char:*** | P | ***District:*** | 305 |
| ***Waste Code:*** | 312 | | |

***2018 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6000631 | ***Choice of Contact:*** | CO_ADMIN |
| ***ID:*** | 23890 | ***Phone No Official:*** | 613-230-8885 Ext.232 |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-230-8885 Ext.264 |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Saralex Medical Inc. | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | Heart of Ottawa Health Centre | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 270 Elgin Street | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1M2 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | James Dumont | | |
| ***Co Admin:*** | Frederika Hess | | |

***2018 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 48669 | ***Sum Received Qty:*** | 26.0 |
| ***Generator No:*** | ON6000631 | ***Waste Class Name:*** | PATHOLOGICAL WASTES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | P | ***District:*** | 305 |
| ***Waste Code:*** | 312 | | |

***2019 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6000631 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 24041 | ***Phone No Official:*** | 613-230-8885 Ext.232 |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | 613-230-8885 Ext.264 |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 621110 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Saralex Medical Inc. | | |
| ***Gen Div:*** | | | |
| ***Gen Op Name:*** | Heart of Ottawa Health Centre | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 270 Elgin Street | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 1M2 | | |
| ***Site Country:*** | Canada | | |

**Co Official:** James Dumont
**Co Admin:** Frederika Hess

***2019 Generator Manifest***

**ID:** 48479
**Generator No:** ON6000631
**Receiver Type:** 035
**Waste Char:** P
**Waste Code:** 312
**Sum Received Qty:** 61.0
**Waste Class Name:** PATHOLOGICAL WASTES
**Count Manifests:** 2
**District:** 305

---

**148** | ***1 of 6*** | ***NE/243.7*** | ***72.2 / -1.69*** | ***SKETCHLEY CLEANING SERVICES LTD.***
***268 ELGIN ST.***
***OTTAWA ON K2P 1M2*** | ***GEN***

***Generator Info***

**Generator No:** ON0240427
**Approval Years:** 86,87,88,89
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** POWER LAUND./CLEANERS
**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 9721

***Waste Detail(s)***

**Waste Class:** 241
**Waste Class Name:** HALOGENATED SOLVENTS

---

**148** | ***2 of 6*** | ***NE/243.7*** | ***72.2 / -1.69*** | ***SKETCHLEY CLEANING SERVICES LTD.***
***268 ELGIN ST.***
***OTTAWA ON K2P 1M2*** | ***GEN***

***Generator Info***

**Generator No:** ON0240427
**Approval Years:** 90
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** POWER LAUND./CLEANER
**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 9721

***Waste Detail(s)***

**Waste Class:** 241
**Waste Class Name:** HALOGENATED SOLVENTS

---

**148** | ***3 of 6*** | ***NE/243.7*** | ***72.2 / -1.69*** | ***SKETCHLEY CLEANING SERVICES LTD. 35-248***
***268 ELGIN ST.***
***OTTAWA ON K2P 1M2*** | ***GEN***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0240427 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 92,93,94,95,96,97 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 9721 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | POWER LAUND./CLEANER | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 241 |
| ***Waste Class Name:*** | HALOGENATED SOLVENTS |

---

**148** ***4 of 6*** ***NE/243.7*** ***72.2 / -1.69*** ***SKETCHLEY CLEANING SERVICES LIMITED 268 ELGIN STREET OTTAWA ON K2P 1M2*** ***GEN***

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0240427 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 98 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 9721 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | POWER LAUND./CLEANERS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 241 |
| ***Waste Class Name:*** | HALOGENATED SOLVENTS |

---

**148** ***5 of 6*** ***NE/243.7*** ***72.2 / -1.69*** ***HILLARY CLEANERS(SEE&USEON0240427-SKETCH) 268 ELGIN STREET OTTAWA ON K2P 1M2*** ***GEN***

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0491104 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 86,87,88,89 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 9721 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | POWER LAUND./CLEANERS | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 241 |
| ***Waste Class Name:*** | HALOGENATED SOLVENTS |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 148 | 6 of 6 | NE/243.7 | 72.2 / -1.69 | HILLARY (SEE & USE ON0240427) 20-099<br>268 ELGIN STREET<br>OTTAWA ON K2P 1M2 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON0491104 | ***Choice of Contact:*** | |
| ***Approval Years:*** | 92,93,94,95,96,97,98 | ***Contaminated Fac:*** | |
| ***Status:*** | | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | 9721 |
| ***Country:*** | | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | POWER LAUND./CLEANER | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 149 | 1 of 1 | WSW/245.2 | 75.9 / 2.00 | Ottawa Community Housing Corp<br>379 Gilmour Street<br>Ottawa ON K2P 2M6 | GEN |

***Generator Info***

| | | | |
|---|---|---|---|
| ***Generator No:*** | ON6125452 | ***Choice of Contact:*** | |
| ***Approval Years:*** | As of Jan 2021 | ***Contaminated Fac:*** | |
| ***Status:*** | Registered | ***MHSW Facility:*** | |
| ***PO Box No:*** | | ***SIC Code:*** | |
| ***Country:*** | Canada | | |
| ***Co Admin:*** | | | |
| ***Phone No Admin:*** | | | |
| ***SIC Description:*** | | | |

***Waste Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 251 L |
| ***Waste Class Name:*** | Waste oils/sludges (petroleum based) |

***2020 Generator Info***

| | | | |
|---|---|---|---|
| ***Gen No:*** | ON6125452 | ***Choice of Contact:*** | CO_OFFICIAL |
| ***ID:*** | 24288 | ***Phone No Official:*** | 613-731-1182 Ext.3231 |
| ***Contaminated Fac:*** | N | ***Phone No Admin:*** | |
| ***MHSW Facility:*** | N | ***County Ont:*** | OTTAWA CARLTON (RM) |
| ***NAICS Code1:*** | 531310 | ***County Out:*** | |
| ***NAICS Code2:*** | | ***District:*** | 402 |
| ***NAICS Code3:*** | | | |
| ***Gen Name:*** | Ottawa Community Housing Corp | | |
| ***Gen Div:*** | Ottawa Community Housing Corp | | |
| ***Gen Op Name:*** | Ottawa Community Housing Corp | | |
| ***Gen Op Div:*** | | | |
| ***Site Adrs1:*** | 379 Gilmour Street | | |
| ***Site Bldg:*** | | | |
| ***Site Pobox:*** | | | |
| ***Province In:*** | ONTARIO | | |
| ***Site Adrs2:*** | | | |
| ***Site City:*** | Ottawa | | |
| ***Province Out:*** | | | |
| ***Site Postal Code:*** | K2P 2M6 | | |
| ***Site Country:*** | Canada | | |
| ***Co Official:*** | Tom Kasouf | | |
| ***Co Admin:*** | | | |

***2020 Generator Manifest***

| | | | |
|---|---|---|---|
| ***ID:*** | 45648 | ***Sum Received Qty:*** | 2300.0 |
| ***Generator No:*** | ON6125452 | ***Waste Class Name:*** | OIL SKIMMINGS & SLUDGES |
| ***Receiver Type:*** | 035 | ***Count Manifests:*** | 1 |
| ***Waste Char:*** | L | ***District:*** | 402 |
| ***Waste Code:*** | 251 | | |

**150** ***1 of 1*** ***WNW/245.7*** ***75.9 / 2.00*** ***ON*** ***WWIS***

| | | | |
|---|---|---|---|
| ***Well ID:*** | 7471728 | ***Flowing (Y/N):*** | |
| ***Construction Date:*** | | ***Flow Rate:*** | |
| ***Use 1st:*** | | ***Data Entry Status:*** | Yes |
| ***Use 2nd:*** | | ***Data Src:*** | |
| ***Final Well Status:*** | | ***Date Received:*** | 02/20/2024 |
| ***Water Type:*** | | ***Selected Flag:*** | TRUE |
| ***Casing Material:*** | | ***Abandonment Rec:*** | |
| ***Audit No:*** | Z399974 | ***Contractor:*** | 6964 |
| ***Tag:*** | A373405 | ***Form Version:*** | 7 |
| ***Constructn Method:*** | | ***Owner:*** | |
| ***Elevation (m):*** | | ***County:*** | OTTAWA-CARLETON |
| ***Elevatn Reliabilty:*** | | ***Lot:*** | |
| ***Depth to Bedrock:*** | | ***Concession:*** | |
| ***Well Depth:*** | | ***Concession Name:*** | |
| ***Overburden/Bedrock:*** | | ***Easting NAD83:*** | |
| ***Pump Rate:*** | | ***Northing NAD83:*** | |
| ***Static Water Level:*** | | ***Zone:*** | |
| ***Clear/Cloudy:*** | | ***UTM Reliability:*** | |
| ***Municipality:*** | OTTAWA CITY | | |
| ***Site Info:*** | | | |

***Additional Detail(s) (Map)***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1010247113 | ***Tag No:*** | A373405 |
| ***Depth (m):*** | | ***Contractor:*** | 6964 |
| ***Year Completed:*** | 2024 | ***Latitude:*** | 45.4168963067575 |
| ***Well Completed Dt:*** | 02/12/2024 | ***Longitude:*** | -75.6951542715185 |
| ***Audit No:*** | Z399974 | ***Point Y:*** | 45.416896300230974 |
| ***Path:*** | | ***Point X:*** | -75.69515410998352 |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1010247113 | ***Elevation:*** | |
| ***DP2BR:*** | | ***Elevrc:*** | |
| ***Spatial Status:*** | | ***Zone:*** | 18 |
| ***Code OB:*** | | ***East83:*** | 445610.00 |
| ***Code OB Desc:*** | | ***North83:*** | 5029499.00 |
| ***Open Hole:*** | | ***Org CS:*** | UTM83 |
| ***Cluster Kind:*** | | ***UTMRC:*** | 4 |
| ***Date Completed:*** | 02/12/2024 | ***UTMRC Desc:*** | margin of error : 30 m - 100 m |
| ***Remarks:*** | | ***Location Method:*** | wwr |
| ***Location Method Desc:*** | on Water Well Record | | |
| ***Elevrc Desc:*** | | | |
| ***Location Source Date:*** | | | |
| ***Improvement Location Source:*** | | | |
| ***Improvement Location Method:*** | | | |
| ***Source Revision Comment:*** | | | |
| ***Supplier Comment:*** | | | |

**151** ***1 of 1*** ***ESE/246.1*** ***73.0 / -0.92*** ***331 METCALFE STREET OTTAWA ON K2P 1S3*** ***HINC***

| | |
|---|---|
| **External File Num:** | FS INC 0805-02460 |
| **Fuel Occurrence Type:** | Pipeline Strike |
| **Date of Occurrence:** | 5/28/2008 |
| **Fuel Type Involved:** | Natural Gas |
| **Status Desc:** | Completed - No Action Required |
| **Job Type Desc:** | Incident/Near-Miss Occurrence (FS) |
| **Oper. Type Involved:** | Private Dwelling |
| **Service Interruptions:** | No |
| **Property Damage:** | No |
| **Fuel Life Cycle Stage:** | Utilization |
| **Root Cause:** | |
| **Reported Details:** | |
| **Fuel Category:** | Gaseous Fuel |
| **Occurrence Type:** | Incident |
| **Affiliation:** | Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.) |
| **County Name:** | Ottawa |
| **Approx. Quant. Rel:** | |
| **Nearby body of water:** | |
| **Enter Drainage Syst.:** | |
| **Approx. Quant. Unit:** | |
| **Environmental Impact:** | |

---

**152** | ***1 of 2*** | ***S/246.4*** | ***73.9 / 0.00*** | ***346 Waverley St***
***Ottawa ON K2P 0W5*** | ***EHS***

| | | | |
|---|---|---|---|
| **Order No:** | 20121212020 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 18-DEC-12 | **Search Radius (km):** | .25 |
| **Date Received:** | 12-DEC-12 | **X:** | -75.692729 |
| **Previous Site Name:** | | **Y:** | 45.413604 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

---

**152** | ***2 of 2*** | ***S/246.4*** | ***73.9 / 0.00*** | ***Paramount Gold & Silver Corp.***
***346 Waverley St***
***Ottawa ON K2P 0W5*** | ***SCT***

| | |
|---|---|
| **Scott S ID:** | 73517404 |
| **Latitude:** | |
| **Longitude:** | |

***Historical Details***

| | |
|---|---|
| **Established:** | 01-SEP-06 |
| **Plant Size (ft²):** | |
| **Employment:** | |

***Historical Details***

| | |
|---|---|
| **Description:** | Other Support Activities for Mining |
| **SIC/NAICS Code:** | 213119 |

***Historical Details***

| | |
|---|---|
| **Description:** | Gold and Silver Ore Mining |
| **SIC/NAICS Code:** | 212220 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Historical Details***

***Description:*** All Other Metal Ore Mining
***SIC/NAICS Code:*** 212299

---

**153** | ***1 of 1*** | ***ENE/248.0*** | ***72.6 / -1.24*** | ***Langley's 281 Elgin Ottawa ON*** | ***HBAR***

***Province:*** ON
***Year:*** 1927
***Source:*** Mights

---

**154** | ***1 of 1*** | ***SE/248.1*** | ***72.9 / -1.00*** | ***ON*** | ***BORE***

***Borehole ID:*** 613254
***OGF ID:*** 215514556
***Status:***
***Type:*** Borehole
***Use:***
***Completion Date:***
***Static Water Level:*** 15.8
***Primary Water Use:***
***Sec. Water Use:***
***Total Depth m:*** -999
***Depth Ref:*** Ground Surface
***Depth Elev:***
***Drill Method:***
***Orig Ground Elev m:*** 69.5
***Elev Reliabil Note:***
***DEM Ground Elev m:*** 69.5
***Concession:***
***Location D:***
***Survey D:***
***Comments:***

***Inclin FLG:*** No
***SP Status:*** Initial Entry
***Surv Elev:*** No
***Piezometer:*** No
***Primary Name:***
***Municipality:***
***Lot:***
***Township:***
***Latitude DD:*** 45.413981
***Longitude DD:*** -75.690764
***UTM Zone:*** 18
***Easting:*** 445951
***Northing:*** 5029172
***Location Accuracy:***
***Accuracy:*** Not Applicable

***Borehole Geology Stratum***

***Geology Stratum ID:*** 218394357
***Top Depth:*** 9.1
***Bottom Depth:*** 22.1
***Material Color:*** Grey
***Material 1:*** Clay
***Material 2:*** Silt
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** CLAY. GREY,SOFT.

***Mat Consistency:*** Soft
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394354
***Top Depth:*** 0
***Bottom Depth:*** 1.5
***Material Color:***
***Material 1:*** Sand
***Material 2:***
***Material 3:***
***Material 4:***
***Gsc Material Description:***
***Stratum Description:*** SAND.

***Mat Consistency:***
***Material Moisture:***
***Material Texture:***
***Non Geo Mat Type:***
***Geologic Formation:***
***Geologic Group:***
***Geologic Period:***
***Depositional Gen:***

***Geology Stratum ID:*** 218394358

***Mat Consistency:*** Firm

| | | | |
|---|---|---|---|
| **Top Depth:** | 22.1 | **Material Moisture:** | |
| **Bottom Depth:** | 27.4 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Till | **Geologic Formation:** | |
| **Material 2:** | Clay | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |

**Gsc Material Description:**
**Stratum Description:** TILL. FIRM, WATER STABLE AT 176.0 FEET.

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394359 | **Mat Consistency:** | |
| **Top Depth:** | 27.4 | **Material Moisture:** | |
| **Bottom Depth:** | 29 | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Till | **Geologic Formation:** | |
| **Material 2:** | Boulders | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |

**Gsc Material Description:**
**Stratum Description:** TILL.

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394360 | **Mat Consistency:** | |
| **Top Depth:** | 29 | **Material Moisture:** | |
| **Bottom Depth:** | | **Material Texture:** | |
| **Material Color:** | | **Non Geo Mat Type:** | |
| **Material 1:** | Bedrock | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |

**Gsc Material Description:**
**Stratum Description:** BEDROCK. BEDROCK. 00010 038 00025 022 00075 060 00320 040 00420 042 0070 **Note: Many records provided by the department have a truncated [Stratum Description] field.

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394355 | **Mat Consistency:** | |
| **Top Depth:** | 1.5 | **Material Moisture:** | |
| **Bottom Depth:** | 2.7 | **Material Texture:** | |
| **Material Color:** | Grey | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |

**Gsc Material Description:**
**Stratum Description:** CLAY. GREY.

| | | | |
|---|---|---|---|
| **Geology Stratum ID:** | 218394356 | **Mat Consistency:** | Soft |
| **Top Depth:** | 2.7 | **Material Moisture:** | |
| **Bottom Depth:** | 9.1 | **Material Texture:** | |
| **Material Color:** | Grey | **Non Geo Mat Type:** | |
| **Material 1:** | Clay | **Geologic Formation:** | |
| **Material 2:** | | **Geologic Group:** | |
| **Material 3:** | | **Geologic Period:** | |
| **Material 4:** | | **Depositional Gen:** | |

**Gsc Material Description:**
**Stratum Description:** CLAY. GREY,SOFT,LAYERED.

***Source***

| | | | |
|---|---|---|---|
| **Source Type:** | Data Survey | **Source Appl:** | Spatial/Tabular |
| **Source Orig:** | Geological Survey of Canada | **Source Iden:** | 1 |
| **Source Date:** | 1956-1972 | **Scale or Res:** | Varies |
| **Confidence:** | H | **Horizontal:** | NAD27 |
| **Observatio:** | | **Verticalda:** | Mean Average Sea Level |

**Source Name:** Urban Geology Automated Information System (UGAIS)
**Source Details:** File: OTTAWA2.txt RecordID: 057620 NTS_Sheet: 31G05G
**Confiden 1:** Logged by professional. Exact and complete description of material and properties.

***Source List***

| | | | |
|---|---|---|---|
| ***Source Identifier:*** | 1 | ***Horizontal Datum:*** | NAD27 |
| ***Source Type:*** | Data Survey | ***Vertical Datum:*** | Mean Average Sea Level |
| ***Source Date:*** | 1956-1972 | ***Projection Name:*** | Universal Transverse Mercator |
| ***Scale or Resolution:*** | Varies | | |
| ***Source Name:*** | Urban Geology Automated Information System (UGAIS) | | |
| ***Source Originators:*** | Geological Survey of Canada | | |

**155** ***1 of 1*** ***WSW/248.6*** ***75.8 / 1.91*** ***285 MacLaren St*** ***SPL***

***OTTAWA ON***

| | | | |
|---|---|---|---|
| ***Ref No:*** | 1-6IGGCB | ***Municipality No:*** | |
| ***Year:*** | | ***Nature of Damage:*** | |
| ***Incident Dt:*** | Dec 14,2023 12:00:00 AM | ***Discharger Report:*** | |
| ***Dt MOE Arvl on Scn:*** | | ***Material Group:*** | |
| ***MOE Reported Dt:*** | May 06,2024 09:35:30 AM | ***Impact to Health:*** | |
| ***Dt Document Closed:*** | May 07,2024 09:44:40 AM | ***Agency Involved:*** | |
| ***Site No:*** | | | |
| ***MOE Response:*** | Desktop Response | | |
| ***Site County/District:*** | | | |
| ***Site Geo Ref Meth:*** | | | |
| ***Site District Office:*** | Ottawa District Office | | |
| ***Nearest Watercourse:*** | | | |
| ***Site Name:*** | 285 MacLaren St | | |
| ***Site Address:*** | | | |
| ***Site Region:*** | | | |
| ***Site Municipality:*** | OTTAWA | | |
| ***Site Lot:*** | | | |
| ***Site Conc:*** | | | |
| ***Site Geo Ref Accu:*** | | | |
| ***Site Map Datum:*** | | | |
| ***Northing:*** | | | |
| ***Easting:*** | | | |
| ***Entity Operating Name:*** | | | |
| ***Client Name:*** | | | |
| ***Client Type:*** | Private Residence | | |
| ***Source Type:*** | Container/Drum/Tote | | |
| ***Incident Cause:*** | | | |
| ***Incident Preceding Spill:*** | Leak/Break | | |
| ***Incident Reason:*** | Improper operation | | |
| ***Incident Summary:*** | TSSA FSB UGST minor leak during removal at private property, clnd | | |
| ***Environment Impact:*** | | | |
| ***Health Env Consequence:*** | Low | | |
| ***Nature of Impact:*** | | | |
| ***Contaminant Qty:*** | 0 other - see notes | | |
| ***Contaminant Qty 1:*** | | | |
| ***Contaminant Unit:*** | | | |
| ***Contaminant Code:*** | | | |
| ***Contaminant Name:*** | FURNACE OIL | | |
| ***Contaminant Limit 1:*** | | | |
| ***Contam Limit Freq 1:*** | | | |
| ***Contaminant UN No 1:*** | | | |
| ***Receiving Medium:*** | Land | | |
| ***Activity Preceding Spill:*** | Other (specify) | | |
| ***Property 2nd Watershed:*** | Lower Ottawa | | |
| ***Property Tertiary Watershed:*** | 02LA-Rideau | | |
| ***Sector Type:*** | PRIVATE HOUSEHOLDS | | |
| ***SAC Action Class:*** | | | |
| ***Call Report Locatn Geodata:*** | {"integration_ids":["PR00004338490"],"wkts":["POINT (-75.6952204000 45.4149817000)"],"creation_date":"2024-05-06"} | | |
| ***Time Reported:*** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**System Facility Address:** 285 MACLAREN ST, OTTAWA, ON K2P 0L9
**Source Sector Type:**
**Conservtn Auth Name:**
**Primary Watershed:**
**Quaternary Watershed:**
**Offsite Impacts Y N:**
**Waterbody Impacted Y N:**

---

**156** *1 of 3* *WSW/248.8* *75.8 / 1.91* ***356 MacLaren Street Ottawa ON K2P 0M6*** ***EHS***

**Order No:** 20070412026
**Status:** C
**Report Type:** CAN - Complete Report
**Report Date:** 4/20/2007
**Date Received:** 4/12/2007
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:** Bank Street
**Municipality:**
**Client Prov/State:**
**Search Radius (km):** 0.25
**X:** -75.694978
**Y:** 45.414769

---

**156** *2 of 3* *WSW/248.8* *75.8 / 1.91* ***356 MacLaren Street Ottawa ON K2P 0M6*** ***EHS***

**Order No:** 21070700009
**Status:** C
**Report Type:** Standard Report
**Report Date:** 12-JUL-21
**Date Received:** 07-JUL-21
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -75.6950971
**Y:** 45.4148082

---

**156** *3 of 3* *WSW/248.8* *75.8 / 1.91* ***AUBUT & NADEAU SERVICES INC. 356 MCLAREN STREET OTTAWA ON K2P 0M6*** ***GEN***

***Generator Info***

**Generator No:** ON1785700
**Approval Years:** 93,95,96,97,98,99,00,01
**Status:**
**PO Box No:**
**Country:**
**Co Admin:**
**Phone No Admin:**
**SIC Description:** CAMERA/PHOTO. SUPPLY

**Choice of Contact:**
**Contaminated Fac:**
**MHSW Facility:**
**SIC Code:** 6571

***Waste Detail(s)***

**Waste Class:** 264
**Waste Class Name:** PHOTOPROCESSING WASTES

# Unplottable Summary

**Total: 13 Unplottable sites**

| DB | Company Name/Site Name | Address | City | Postal |
|---|---|---|---|---|
| CA | OTTAWA CITY | COOPER ST. | OTTAWA CITY ON | |
| CA | City of Ottawa | Somerset St W | Ottawa ON | |
| CA | City of Ottawa | Somerset St W | Ottawa ON | |
| CA | R.M. OF OTTAWA-CARLETON | SOMERSET STREET | OTTAWA CITY ON | |
| CA | City of Ottawa | Gilmour Street (O'Connor to Metcalfe Streets) | Ottawa ON | |
| CA | | Waverley Street | Ottawa ON | |
| CA | | Waverley Street | Ottawa ON | |
| CA | | Waverley Street | Ottawa ON | |
| CA | R.M. OF OTTAWA-CARLETON | GILMOUR STREET | OTTAWA CITY ON | |
| CA | CANLANDS DEVELOPMENT CORP. | METCALFE STREET | OTTAWA CITY ON | |
| ECA | 1578051 Ontario Inc., Operating as Tartan Homes | | Ottawa ON | |
| ECA | City of Ottawa | Somerset St W | Ottawa ON | K1P 1J1 |
| ECA | City of Ottawa | Elgin St | Ottawa ON | K2G 6J8 |

# Unplottable Report

**Site:** ***OTTAWA CITY***
***COOPER ST. OTTAWA CITY ON***

**Database:** ***CA***

***Certificate #:*** 3-1897-88-
***Application Year:*** 88
***Issue Date:*** 10/14/1988
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

**Site:** ***City of Ottawa***
***Somerset St W Ottawa ON***

**Database:** ***CA***

***Certificate #:*** 0195-8HMLH2
***Application Year:*** 2011
***Issue Date:*** 6/15/2011
***Approval Type:*** Municipal and Private Sewage Works
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

**Site:** ***City of Ottawa***
***Somerset St W Ottawa ON***

**Database:** ***CA***

***Certificate #:*** 6180-8JKNNV
***Application Year:*** 2011
***Issue Date:*** 7/22/2011
***Approval Type:*** Municipal and Private Sewage Works
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

**Site:** ***R.M. OF OTTAWA-CARLETON***
***SOMERSET STREET OTTAWA CITY ON***

**Database:** ***CA***

***Certificate #:*** 7-0096-88-
***Application Year:*** 88

***Issue Date:*** 2/10/1988
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***City of Ottawa***
***Gilmour Street (O'Connor to Metcalfe Streets) Ottawa ON***

***Database:*** ***CA***

***Certificate #:*** 6597-5PZN2S
***Application Year:*** 2003
***Issue Date:*** 8/8/2003
***Approval Type:*** Municipal and Private Sewage Works
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:***
***Waverley Street Ottawa ON***

***Database:*** ***CA***

***Certificate #:*** 0020-4J3R8L
***Application Year:*** 00
***Issue Date:*** 4/6/00
***Approval Type:*** Municipal & Private water
***Status:*** Approved
***Application Type:*** New Certificate of Approval
***Client Name:*** Corporation of the Regional Municipality of Ottawa-Carleton
***Client Address:*** 111 Lisgar Street
***Client City:*** Ottawa
***Client Postal Code:*** K2P 2L7
***Project Description:*** Watermains
***Contaminants:***
***Emission Control:***

---

***Site:***
***Waverley Street Ottawa ON***

***Database:*** ***CA***

***Certificate #:*** 5545-57HJZ7
***Application Year:*** 02
***Issue Date:*** 2/19/02
***Approval Type:*** Municipal & Private sewage
***Status:*** Approved
***Application Type:*** New Certificate of Approval
***Client Name:*** City of Ottawa
***Client Address:*** 110 Laurier Avenue West
***Client City:*** City of Ottawa
***Client Postal Code:*** K1P 1J1
***Project Description:*** This application is for the replacement of combined sewers on Waverley Street from Robert Street to Queen Elizabeth Driveway, in the City of Ottawa.
***Contaminants:***
***Emission Control:***

***Site:***
***Waverley Street Ottawa ON***

***Database:*** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 2252-4L5L5A |
| ***Application Year:*** | 00 |
| ***Issue Date:*** | 6/14/00 |
| ***Approval Type:*** | Municipal & Private sewage |
| ***Status:*** | Approved |
| ***Application Type:*** | New Certificate of Approval |
| ***Client Name:*** | Corporation of the City of Ottawa |
| ***Client Address:*** | 111 Sussex Drive, 7th Floor |
| ***Client City:*** | Ottawa |
| ***Client Postal Code:*** | K1N 5A1 |
| ***Project Description:*** | Combined Sewers |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

***Site:*** ***R.M. OF OTTAWA-CARLETON***
***GILMOUR STREET OTTAWA CITY ON***

***Database:*** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 7-0854-87- |
| ***Application Year:*** | 87 |
| ***Issue Date:*** | 6/19/1987 |
| ***Approval Type:*** | Municipal water |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

***Site:*** ***CANLANDS DEVELOPMENT CORP.***
***METCALFE STREET OTTAWA CITY ON***

***Database:*** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 7-0765-89- |
| ***Application Year:*** | 89 |
| ***Issue Date:*** | 5/12/1989 |
| ***Approval Type:*** | Municipal water |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

***Site:*** ***1578051 Ontario Inc., Operating as Tartan Homes***
***Ottawa ON***

***Database:*** ***ECA***

| | | | |
|---|---|---|---|
| ***Approval No:*** | 1573-98LNFS | ***MOE District:*** | |
| ***Approval Date:*** | 2013-06-24 | ***City:*** | |
| ***Status:*** | Approved | ***Longitude:*** | |
| ***Record Type:*** | ECA | ***Latitude:*** | |
| ***Link Source:*** | IDS | ***Geometry X:*** | |
| ***SWP Area Name:*** | | ***Geometry Y:*** | |
| ***Approval Type:*** | ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS | | |
| ***Project Type:*** | MUNICIPAL AND PRIVATE SEWAGE WORKS | | |
| ***Business Name:*** | 1578051 Ontario Inc., Operating as Tartan Homes | | |
| ***Address:*** | | | |

***Full Address:***
***Full PDF Link:*** https://www.accessenvironment.ene.gov.on.ca/instruments/9856-97AR27-14.pdf
***PDF Site Location:***

---

***Site:*** ***City of Ottawa***
***Somerset St W Ottawa ON K1P 1J1***

***Database:*** ***ECA***

***Approval No:*** 0195-8HMLH2
***Approval Date:*** 2011-06-15
***Status:*** Approved
***Record Type:*** ECA
***Link Source:*** IDS
***SWP Area Name:***
***MOE District:***
***City:***
***Longitude:***
***Latitude:***
***Geometry X:***
***Geometry Y:***
***Approval Type:*** ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
***Project Type:*** MUNICIPAL AND PRIVATE SEWAGE WORKS
***Business Name:*** City of Ottawa
***Address:*** Somerset St W
***Full Address:***
***Full PDF Link:*** https://www.accessenvironment.ene.gov.on.ca/instruments/3106-8HFGKN-14.pdf
***PDF Site Location:***

---

***Site:*** ***City of Ottawa***
***Elgin St Ottawa ON K2G 6J8***

***Database:*** ***ECA***

***Approval No:*** 3479-B58MN9
***Approval Date:*** 2018-10-05
***Status:*** Approved
***Record Type:*** ECA
***Link Source:*** IDS
***SWP Area Name:***
***MOE District:***
***City:***
***Longitude:***
***Latitude:***
***Geometry X:***
***Geometry Y:***
***Approval Type:*** ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
***Project Type:*** MUNICIPAL AND PRIVATE SEWAGE WORKS
***Business Name:*** City of Ottawa
***Address:*** Elgin St
***Full Address:***
***Full PDF Link:*** https://www.accessenvironment.ene.gov.on.ca/instruments/9153-B4ZNVU-14.pdf
***PDF Site Location:***

# Appendix: Database Descriptions

*Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update.* ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

***Abandoned Aggregate Inventory:*** Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

***Government Publication Date: Sept 2002****

***Aggregate Inventory:*** Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

***Government Publication Date: Up to Oct 2025***

***Abandoned Mine Information System:*** Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

***Government Publication Date: 1800-May 2025***

***Anderson's Waste Disposal Sites:*** Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

***Government Publication Date: 1860s-Present***

***Aboveground Storage Tanks:*** Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

***Government Publication Date: May 31, 2014***

***Automobile Wrecking & Supplies:*** Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

***Government Publication Date: 1999-Apr 30, 2025***

***Borehole:*** Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

***Government Publication Date: 1875-Jul 2018***

***Certificates of Approval:*** Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

***Government Publication Date: 1985-Oct 30, 2011****

***Dry Cleaning Facilities:*** Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

***Government Publication Date: Jan 2004-Dec 2023***

***Commercial Fuel Oil Tanks:*** Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

***Government Publication Date: Oct 2023***

***Chemical Manufacturers and Distributors:*** Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

***Government Publication Date: 1999-Jan 31, 2020***

***Chemical Register:*** Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

***Government Publication Date: 1999-Apr 30, 2025***

***Compressed Natural Gas Stations:*** Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

***Government Publication Date: Dec 2012 -Nov 2025***

***Inventory of Coal Gasification Plants and Coal Tar Sites:*** Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

***Government Publication Date: Apr 1987 and Nov 1988****

***Compliance and Convictions:*** Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

***Government Publication Date: 1989-Aug 2025***

***Certificates of Property Use:*** Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

***Government Publication Date: 1994 - Nov 30, 2025***

***Drill Hole Database:*** Provincial DRL

The Ontario Drill Hole Database (ODHD) is offered by the Province of Ontario's Ministry of Mines. The dataset contains information for over 164,000 percussion, overburden, sonic and diamond-drill holes. The presence of assay results with cutoff values for gold, silver, copper, zinc, lead, nickel and platinum group elements is noted. Drill hole data are compiled from assessment files that have been submitted to the ministry in accordance with the Ontario Mining Act (OMA). Source assessment file numbers are captured for cross reference with the Ontario Assessment File Database (OAFD). Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

***Government Publication Date: 1886 - Jul 2025***

***Delisted Fuel Tanks:*** Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

***Government Publication Date: Oct 2023***

***Environmental Activity and Sector Registry:*** Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

***Government Publication Date: Oct 2011 - Nov 30, 2025***

***Environmental Registry:*** Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

***Government Publication Date: 1994 - Nov 30, 2025***

***Environmental Compliance Approval:*** Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

***Government Publication Date: Oct 2011 - Nov 30, 2025***

***Environmental Effects Monitoring:*** Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

***Government Publication Date: 1992-2007****

***ERIS Historical Searches:*** Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

***Government Publication Date: 1999-Nov 30, 2025***

***Environmental Issues Inventory System:*** Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

***Government Publication Date: 1992-2001****

***Emergency Management Historical Event:*** Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

***Government Publication Date: Apr 30, 2022***

***Environmental Offenders Registry:*** Federal EOR

The Environmental Offenders Registry, enforced by Environment and Climate Change Canada and Parks Canada, tracks corporations convicted under specific federal environmental laws. The registry includes corporate convictions resulting from court proceedings. Court prosecutions are one of several enforcement measures used when violations or potential violations are detected. Other measures like tickets, warning letters, or compliance orders may also be employed to restore compliance. Although not affected by the Environmental Enforcement Act, convictions obtained by Environment and Climate Change Canada under the Species at Risk Act and the Pollution Prevention Provisions of the Fisheries Act are also included.

***Government Publication Date: Oct 31, 2025***

***Environmental Penalty Annual Report:*** Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment, Conservation and Parks (MECP). These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

***Government Publication Date: Jan 1, 2011 - Dec 31, 2024***

***Excess Soil Registry:*** Provincial ESNR

The Excess Soil Registry is made available by the Resource Productivity and Recovery Authority (RPRA). Excess soil is soil dug up mainly during construction and excavation activities that must be removed from the development site because it cannot or will not be reused. The Minister of the Environment, Conservation and Parks directed the RPRA to establish and maintain the Excess Soil Registry, enabling regulated parties to comply with registration and filing notice requirements, the ministry to access data, and the public to view information from those filings. From January 1, 2023, construction and development project leaders, as well as operators and owners of soil Reuse Sites, and Residential Development Soil Depot sites, must file notices detailing how excess soil is reused and disposed of in compliance with Ontario's Excess Soil Regulation.

***Government Publication Date: Aug 31, 2025***

***List of Expired Fuels Safety Facilities:*** Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

***Government Publication Date: Oct 2023***

***Federal Convictions:*** Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

***Government Publication Date: 1988-Jun 2007****

***Contaminated Sites on Federal Land:*** Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

***Government Publication Date: Jun 2000-Oct 2025***

***Fisheries & Oceans Fuel Tanks:*** Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

***Government Publication Date: 1964-Sep 2019***

***Federal Identification Registry for Storage Tank Systems (FIRSTS):*** Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

***Government Publication Date: Oct 31, 2021***

***Fuel Storage Tank:*** Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

***Government Publication Date: Oct 2023***

***Fuel Storage Tank - Historic:*** Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

***Government Publication Date: Pre-Jan 2010****

***Ontario Regulation 347 Waste Generators Summary:*** Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. As of January 1, 2023, businesses and institutions subject to the amended Reg. 347: General – Waste Management are required to report their activities and pay fees through Resource Productivity & Recovery Authority (RPRA) online Hazardous Waste Program Registry (HWPR) rather than the Hazardous Waste Information Network (HWIN) system previously operated by the Ministry of the Environment, Conservation and Parks (MECP). Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

***Government Publication Date: 1986-Mar 31, 2025***

***Greenhouse Gas Emissions from Large Facilities:*** Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

***Government Publication Date: 2013-Feb 2025***

***TSSA Historic Incidents:*** Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

***Government Publication Date: 2006-June 2009****

***Historical Business Activity Risk:*** Federal HIST RISK

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this list does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including BC Directories, Hendersons, Mights, Sun Directories, Vernons, and Wrights; spanning roughly 1920s through 1960 depending on information available by city.

This list is currently limited to sites as reported in the following provinces: Alberta, British Columbia, Saskatchewan, Manitoba, New Brunswick, Nova Scotia, Ontario, and Quebec.

***Government Publication Date: 1920s - 1960***

***Indian & Northern Affairs Fuel Tanks:*** Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

***Government Publication Date: 1950-Aug 2003****

***Fuel Oil Spills and Leaks:*** Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

***Government Publication Date: Oct 2023***

***Landfill Inventory Management Ontario:*** Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

***Government Publication Date: Mar 31, 2022***

***Canadian Mine Locations:*** Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

***Government Publication Date: 1998-2009****

***Mineral Occurrences:*** Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

***Government Publication Date: 1846-Feb 2025***

***National Analysis of Trends in Emergencies System (NATES):*** Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

***Government Publication Date: 1974-1994****

***Non-Compliance Reports:*** Provincial NCPL

The Ministry of the Environment Conservation and Parks (MECP) provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act. MECP publicly releases the Environmental Compliance Report (ECR) on the Ontario Data Catalogue. In Ontario, all facilities with regulated wastewater discharges or air emissions under the Ontario Water Resources Act and the Environmental Protection Act must monitor and report any cases where approved operating limits have been exceeded.

***Government Publication Date: Dec 31, 2023***

***National Defense & Canadian Forces Fuel Tanks:*** Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

***Government Publication Date: Up to May 2001****

***National Defense & Canadian Forces Spills:*** Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

***Government Publication Date: Mar 1999-Nov 2023***

***National Defence & Canadian Forces Waste Disposal Sites:*** Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

***Government Publication Date: 2001-Apr 2007****

***National Energy Board Pipeline Incidents:*** Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

***Government Publication Date: 2008-Nov 30, 2025***

***National Energy Board Wells:*** Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

***Government Publication Date: 1920-Feb 2003****

***National Environmental Emergencies System (NEES):*** Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

***Government Publication Date: 1974-2003****

***Notice of Contamination List:*** Federal NOC

This dataset contains Notice of Contamination (NOC) submissions reported to the Canada Energy Regulator (CER), including the most recent annual update information where applicable. Regulated companies are required to submit an NOC when contamination is identified or encountered during any phase of a facility's lifecycle and confirmed through analytical sampling, or when contamination resulting from an incident cannot be remediated within 12 weeks of being reported to the CER. Blank values in the Annual Update Year and annual update fields indicate that the site has achieved remediation closure, has been identified as third-party contamination, or was reported recently and does not yet require an annual update.

***Government Publication Date: Nov, 2025***

***National PCB Inventory:*** Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

***Government Publication Date: 1988-2008****

***National Pollutant Release Inventory:*** Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

***Government Publication Date: Feb 2024***

***National Pollutant Release Inventory - Historic:*** Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

***Government Publication Date: 1993-May 2017***

***Oil and Gas Wells:*** Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

***Government Publication Date: 1988-Oct 31, 2025***

***Ontario Oil and Gas Wells:*** Provincial OOGW

In 1998, the Ministry of Natural Resources (MNR) handed over to the Ontario Oil, Gas and Salt Resources (OGSR) Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database includes well owner/operator, location, permit issue date, and well cap date, license number, status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provided for each well record.

***Government Publication Date: 1800-May 2025***

***Inventory of PCB Storage Sites:*** Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

***Government Publication Date: 1987-Oct 2004; 2012-Dec 2013***

***Orders:*** Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

***Government Publication Date: 1994 - Nov 30, 2025***

***Canadian Pulp and Paper:*** Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

***Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014***

***Parks Canada Fuel Storage Tanks:*** Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

***Government Publication Date: 1920-Jan 2005****

***Pesticide Register:*** Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

***Government Publication Date: Oct 2011 - Nov 30, 2025***

***Ontario PFAS Spills:*** Provincial PFAS

This specific list of spills includes those incidents where one or more of the listed contaminants are identified in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA), is originally sourced from the Ministry of the Environment, Conservation and Parks spills related data. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

***Government Publication Date: 1988-Jun 2024; Aug 2024; Oct-Nov 2024***

***NPRI Reporters - PFAS Substances:*** Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

***Government Publication Date: Feb 2024***

***Potential PFAS Handlers from NPRI:*** Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

***Government Publication Date: Feb 2024***

***Pipeline Incidents:*** Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

***Government Publication Date: Feb 28, 2021***

***Potential PFAS Handlers from EASR:*** Provincial PPHA

The Ontario Environmental Activity and Sector Registry (EASR), described in Ontario Regulation 245/11, allows businesses with less complex operations - and hence not requiring an Environmental Compliance Approval - to register their activities with the Ontario Ministry of the Environment, Conservation and Parks (MECP). This list of potential PFAS handlers includes those EASR facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used.

***Government Publication Date: Jun 30, 2024***

***Private and Retail Fuel Storage Tanks:*** Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

***Government Publication Date: 1989-1996****

***Permit to Take Water:*** Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

***Government Publication Date: 1994 - Nov 30, 2025***

***Ontario Regulation 347 Waste Receivers Summary:*** Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

***Government Publication Date: 1986-1990, 1992-2021***

***Record of Site Condition:*** Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

***Government Publication Date: 1997-Sept 2001, Oct 2004 - 31 Dec, 2025***

***Retail Fuel Storage Tanks:*** Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

***Government Publication Date: 1999-Apr 30, 2025***

***Scott's Manufacturing Directories:*** Private SCT

Scott's Directories is a data bank containing information on various manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, applicable NAICS Codes, and product categories are included in this database.

***Government Publication Date: 1992-Mar 2011; Feb 2025***

***Ontario Spills:*** Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

***Government Publication Date: 1988-Oct 2025***

***Wastewater Discharger Registration Database:*** Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

***Government Publication Date: 1990-Dec 31, 2023***

***Anderson's Storage Tanks:*** Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

***Government Publication Date: 1915-1953****

***Transport Canada Fuel Storage Tanks:*** Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

***Government Publication Date: 1970 - Apr 2024***

***Variances for Abandonment of Underground Storage Tanks:*** Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

***Government Publication Date: Feb 28, 2022***

***Waste Disposal Sites - MOE CA Inventory:*** Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

***Government Publication Date: Oct 2011 - Nov 30, 2025***

***Waste Disposal Sites - MOE 1991 Historical Approval Inventory:*** Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

***Government Publication Date: Up to Oct 1990****

***Waste Management Site:*** Provincial WMS

This data contains Waste Disposal Site types collected by the Ministry of Natural Resource (MNR). The new data class brings over data from the Waste Management Information System (WMIS), which is an MS Access based database used by MNR to track Waste Management Sites. This was married with the spatial data from Waste Disposal Sites where possible. Different Waste Disposal Site types collected by the Ministry of Natural Resources include: compost disposal, hazardous waste disposal, household waste disposal, industrial waste disposal, septic drying bed, septic field, sewage disposal, tile bed, and transfer station. The data is currently under development, meaning the data is currently in the process of being created by the MNR.

***Government Publication Date: April 30, 2025***

***Water Well Information System:*** Provincial WWIS

This database consists of information submitted by well contractors detailing locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table. The database is provided by the Ontario Ministry of Environment, Conservation and Parks.

***Government Publication Date: Jul 31, 2025***

# Definitions

***Database Descriptions:*** This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

***Detail Report***: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

***Distance:*** The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

***Direction:*** The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

***Elevation:*** The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

***Executive Summary:*** This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

***Map Key:*** The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

***Unplottables:*** These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

# APPENDIX 3

## QUALIFICATIONS OF ASSESSORS

)

PATERSON GROUP

solution oriented engineering



## Mark S. D'Arcy, P.Eng., QP$_{ESA}$
## Director – Environmental Division

After receiving his Bachelors of Applied Science from Queen's University in 1991 in Geological Engineering, Mark joined Paterson Group Inc. During the first 10 years of Mark's career, he was heavily involved in all aspects of field work, including drilling boreholes, excavating test pits, conducting phase I site inspections, environmental sampling and analysis and inspection of environmental remediations. During Mark's field experience, he gained invaluable field and office experience, which would prepare Mark to become the Environmental Division Manager. Mark's field experience ranges from Phase I Environmental Site Assessments (ESAs) to on-site soil and groundwater remediations, as well as, environmental/geotechnical borehole investigations. Mark's field experience has provided extensive knowledge of subsurface conditions, contractor relations and project management. These skills would provide Mark with the ability to understand a variety of situations, which has lead Paterson to an extremely successful Environmental Department. Mark became the Environmental Manager in 2001 and has been an integral part in growing the Environmental Division. Mark is the Senior Project Manager for a wide variety of environmental projects within the Eastern Ontario area including Phase I ESAs, Phase II ESAs, remediations for filing Records of Site Condition in the Ontario Ministry of the Environment, Conservation and Parks (MECP) Environmental Site Registry, Brownfield Applications and Landfill Monitoring Programs. As the Senior Project Manager, Mark is responsible for directing project personnel, final report review and overall project success. Mark has proven leadership and ability to manage small to large scale projects within the allotted time and budget.

### EDUCATION
B.A.Sc. 1991, Geological Engineering, Queen's University, Kingston, ON

### LICENCE/PROFESSIONAL AFFILIATIONS
Professional Engineers of Ontario

ESA Qualified Person with MECP

Ontario Society of Professional Engineers

Consulting Engineers of Ontario

Ontario Environment Industry Association

### YEARS OF EXPERIENCE
With Paterson: 35

### HEAD OFFICE LOCATION
9 Auriga Drive, Ottawa, Ontario, K2E 7T9

### SELECT LIST OF PROJECTS

- 3342 Navan Road, Ottawa, Ontario; (Senior Project Manager: Phase I ESA, Phase II ESA, Landfill Impact Assessment)
- 900 Carling Avenue – New Ottawa Hospital, Ottawa, Ontario; (Senior Project Manager: Phase I ESA, Phase II ESA, Remediation)
- 3-33 Selkirk Street, Ottawa, Ontario; (Senior Project Manager: Phase I ESA, Phase II ESA, Remediation, Oversee CSM and CPU for Risk Assessment)
- Riverview Development – Kingston, Ontario, (Senior Project Manager: Phase I ESA, Phase II ESA, Oversee RA and RSC process)
- Wellington Street West at Huron Avenue, Ottawa, Ontario; (Senior Project Manager: Soil Vapour Intrusion Assessment, Implementation of Vapour Intrusion Mitigation Measures)
- Art's Court Redevelopment, Ottawa, Ontario (Senior Project Manager for Phase I ESA, Phase II ESA, Phase III ESA, Environmental Remediation)
- Visitor Welcome Centre, Phase II and Phase III, Parliament Hill, Ottawa, Ontario (Senior Project Manager for Environmental Remediation)
- Rideau Centre Expansion, Ottawa, Ontario (Senior Project Manager for Phase I & II ESA, Remediation)

## PROFESSIONAL EXPERIENCE

### 2001 to present, Manager of Environmental Division, Paterson Group Inc., Ottawa, Ontario

- Manage all aspects of the environmental division (management of personnel, budgeting, invoicing, scheduling, business development, reporting, marketing, and fieldwork).
- Review day to day operations within the environmental division.
- Design, perform, and lead Phase I, II and Phase III ESAs, Remediation's, Brownfield Applications and Record of Site conditions, fieldwork surveys, excavation, monitoring, laboratory analysis, and interpretation.
- Write, present, and publish reports with methodology and laboratory analysis results, along with recommendations for environmental findings.
- Responsible for ensuring projects meet Ministry of Environment and Climate Change Standards and Guidelines.
- Building and fostering relationships with clients, stakeholders, and Ministry officials.
- Supervise and continuous training of staff in environmental methods (environmental sampling techniques, technical expertise and guidance).
- Applied due diligence in ensuring the health and safety of staff and the public in field locations.

### 1991 to 2001, Geotechnical and Environmental Engineer, Paterson Group Inc., Ottawa, Ontario

- Provide on-site geotechnical and environmental expertise to various clients.
- Oversee geotechnical and environmental investigations for drilling and test pitting on numerous proposed utility installations, residential and commercial developments.
- Problem solving to help advance or maintain project schedules.
- Complete environmental reports with recommendations to meet environmental standards set by MOE and CCME standards.
- Conduct site inspections, bearing medium evaluations, bearing surface inspections, concrete testing and field density testing.
- Liaising with contractors, consultants and government officials.
- Provide cost estimates for geotechnical and environmental field programs and construction costs.
- Review RFI's, submittals, monthly progress reports and other various construction related work.

PATERSON GROUP
solution oriented engineering

## Mohammed Ramadan, B.Sc
## Environmental Scientist

Mohammed joined Paterson Group in 2021 as part of the Environmental Department. Mohammed received his Bachelor of Science in Environmental Science from Carleton University in 2017. Since joining Paterson group in 2021, Mohammed has worked on numerous residential and commercial development projects, predominantly within the National Capital Region as well as various locations within Southeastern Ontario. His scope of work consists of conducting Phase I & II Environmental Site Assessments, field inspections, contaminated soil and groundwater field sampling and supervising the remediation of contaminated sites.

### EDUCATION
Bachelor of Science in Environmental Science
2017
Carleton University

### YEARS OF EXPERIENCE
With Paterson: 7

### OFFICE LOCATION
9 Auriga Drive, Ottawa, Ontario, K2E 7T9

### SELECT LIST OF PROJECTS

- RESIDENTIAL DEVELOPMENT: 200 BARIBEAU STREET, OTTAWA, ON (SITE REMEDIATION COORDINATOR & SUPERVISOR).
- RESIDENTIAL DEVELOPMENT: 93-105 NORMAN STREET, OTTAWA, ON (SITE REMEDIATION COORDINATOR & SUPERVISOR)
- COMMERCIAL DEVELOPMENT: TOLLGATE ROAD W, CORNWALL, ON (PHASE I & II ENVIRONMENTAL SITE ASSESSMENT)
- COMMERCIAL DEVELOPMENT: 930 WELLINGTON STREET W, OTTAWA, ON (PHASE I & II ENVIRONMENTAL SITE ASSESSMENT)
- COMMERCIAL DEVELOPMENT: 1405 WELLINGTON STREET W, OTTAWA, ON (PHASE I & II ENVIRONMENTAL SITE ASSESSMENT)
- RESIDENTIAL DEVELOPMENT:1124 – 1130 BANK STREET, OTTAWA, ON (PHASE I & II ENVIRONMENTAL SITE ASSESSMENT)
- COMMERCIAL DEVELOPMENT: 1802 – 1804 ST. LAURENT BLVD, OTTAWA, ON (PHASE I ENVIRONMENTAL SITE ASSESSMENT)

## PROFESSIONAL EXPERIENCE

2021 to present, **Environmental Scientist, Paterson Group**, Ottawa, Ontario

- Conducting Phase I and Phase II Environmental Site Assessments in accordance with CSA standards and O.Reg. 153/04.
- Responsible for the application of environmental, hydrogeological, and/or geotechnical principles and practices in the identification and delineation of soil and groundwater contamination plumes while ensuring compliance with federal, provincial, and/or municipal legal and regulatory requirements.
- Presenting analytical test results, interpretations, assessments, recommendations and/or conclusions in a final technical report.
- Field experience in the supervision of drilling and excavation contractors, inspection of aboveground and underground fuel storage tanks, soil and rock classification, soil and groundwater field sampling, as well as the collection of hazardous building materials and designated substances.
- Coordination and on-site supervision of soil and groundwater remediation activities for contaminated sites.
- Liaising with clients, contractors, consultants, and government officials.
- Coordination of contractors and field staff while directly reporting to senior management and client to ensure completion of project on schedule and within budget;
- Manage excavation contractors to ensure soil quality control; daily reporting to project manager;
- Present analytical test results, interpretations, assessments, recommendation and/or conclusions in a final technical report as well as verbal and written communication with clients.