Tree Conservation Report
for 6259, 6267, 6271 and 6273 Renaud Road, Ottawa

October 29, 2026

Updated Final Report

Submitted To:

RICHCRAFT

May Pham
Richcraft Homes
2280 St. Laurent Blvd, Suite 201
Ottawa, ON
K1G 4K1

KILGOUR & ASSOCIATES LTD.
www.kilgourassociates.com

Project Number: RICH 1637.4

TABLE OF CONTENTS

1.0 INTRODUCTION 3

2.0 PROPERTY INFORMATION 3
2.1 PROPERTY OWNER AND APPLICANT CONTACT INFORMATION 3
2.2 ARBORIST CONTACT INFORMATION AND QUALIFICATIONS 5
2.3 ADDITIONAL APPLICATIONS 5

3.0 EXISTING CONDITIONS 6
3.1 TREE INVENTORY 6
3.2 ECOLOGICAL SIGNIFICANCE OF TREES ON SITE 6
3.3 OTHER NATURAL ENVIRONMENT ELEMENTS 8
3.3.1 Surface Water Features 8
3.3.2 Steep Slopes 8
3.3.3 Valued Woodlots 8
3.3.4 Significant Woodlands 8
3.3.5 Greenspace Linkages 8
3.3.6 Distinctive Trees 9
3.3.7 Unique Ecological Features 9
3.3.8 Species at Risk 9

4.0 PROPOSED DEVELOPMENT 9

5.0 MITIGATION MEASURES 11
5.1 SITE PREPARATION AND CONSTRUCTION 11

6.0 CLOSURE 12

LITERATURE CITED 13

List of Figures

Figure 1 Site Context 4
Figure 2 Site Trees 7
Figure 3 Proposed Development 10

List of Tables

Table 1 Organization, role, contact person, phone number, and email address for property owner and applicant 3
Table 2 Organization, role, contact person, phone number, and email address for arborists 5

List of Appendices

Appendix A Tree Data

List of Acronyms and Abbreviations

CRZ – critical root zone
DBH – diameter at breast height
DR – Development Reserve
I1 – Minor Institutional
KAL – Kilgour & Associates Ltd.
MECP – Ministry of the Environment, Conservation and Parks
OWES – Ontario Wetland Evaluation System
SAR – species at risk
SARA – *Species at Risk Act*
SCA – *Species Conservation Act*
TCR – Tree Conservation Report
UNAEES – Urban Natural Areas Environmental Evaluation Study

1.0 INTRODUCTION

This Tree Conservation Report (TCR) has been prepared following guidelines set forth by the City of Ottawa ("the City", 2020) on behalf of Richcraft Homes Ltd. in support of zoning and site plan applications for the properties located at 6259, 6267, 6271, and 6273 Renaud Road in Ottawa, Ontario (the "Site").

A TCR is required for all Plans of Subdivision, Site Plan Control Applications, Common Elements Condominium Applications, and Vacant Land Condominium Applications where there is a tree of 10 cm in diameter at breast height (DBH) or greater on a site and/or if there is a tree on an adjacent site that has a critical root zone (CRZ) extending onto a development site. All trees of any size on City of Ottawa municipal lands are subject to the City of Ottawa Tree Protection By-law (No. 2020-340). A "tree" is defined as any species of woody perennial plant, including its root system, which has reached or can reach a minimum height of at least 450 cm at physiological maturity. The CRZ is calculated as DBH x 10 cm.

The removal of trees on the Site cannot occur until written approval has been granted through a tree permit as per the City's Tree Protection By-law (City of Ottawa, 2020), the application for which will be supported by this TCR. The tree permit will come in the form of a letter from the General Manager[1] with conditions specific to the Site, tree retention (if applicable), and associated tree protection and tree removal. The approved TCR itself is a requirement for the approval of the development applications listed above. A copy of the report must be available on the Site during tree removal, grading, construction, or any other site alteration activities, and for the duration of construction on the Site.

2.0 PROPERTY INFORMATION


The Site includes four adjacent properties on the north side of Renaud Road in the City of Ottawa, comprised of municipal addresses 6259, 6267, 6271, and 6273 Renaud Road. The three westernmost parcels support residential properties, while the easternmost parcel is a predominantly undeveloped storage yard. The Site is approximately 1.3 ha in size. The three westernmost properties are currently zoned as Development Reserve (DR), while the easternmost property is zoned Minor Institutional (I1).

2.1 Property Owner and Applicant Contact Information

Table 1 Organization, role, contact person, phone number, and email address for property owner and applicant

Organization	Role	Contact Person	Phone Number	Email Address
Richcraft Homes Ltd.	Senior Land Development Manager; Applicant	May Pham	613.739.7111 ext. 113	mpham@richcraft.com

[1] General Manager of the Public Works & Environmental Services Department or the General Manager of the Planning, Infrastructure and Economic Development Department of the City of Ottawa, or their designate.



Legend

Site Boundary




Figure 1. Site context

0 37.5 75 150 m

N W E S

Spatial Reference:
PCS: WGS 1984 UTM Zone 18N
Map Units: Meter

Project: RICH 1637
Map File Name: RICH 1637
Date Exported: 3/27/2025 12:31 PM

KILGOUR & Associates

2.2 Arborist Contact Information and Qualifications

Table 2 Organization, role, contact person, phone number, and email address for arborists

Organization	Role	Contact Person	Phone Number	Email Address
KAL	Senior Biologist	Maren Nielsen	613-367-5562	mnielsen@kilgourassociates.com
KAL	Senior Biologist	Kesia Miyashita	613-367-5546	kmiyashita@kilgourassociates.com

Maren Nielsen (BES, EMA) is a Senior Biologist and Project Manager with professional experience and expertise in terrestrial and aquatic ecology, natural heritage policy, and impact assessment. She has worked extensively in the environmental sector with government agencies and private industry, guiding land development, ecological restoration, Species at Risk, and fisheries permitting and approvals processes, delivering adaptive solutions and ensuring compliance with key environmental regulations. She carries out field programs for the collection, analysis, and monitoring of water, fish, benthos, sediment, and soils as well as a variety of vegetation, wetland, Species at Risk, and wildlife surveys, and construction monitoring.

Since joining Kilgour & Associates Ltd. in 2023, Maren has supported the delivery of high-quality assessments, including environmental impact studies, federal and municipal environmental assessments, Species at Risk assessments, headwater drainage feature assessments, community design plans and environmental constraints analyses. Maren is a certified wetland evaluator under the Ontario Wetland Evaluation System (OWES).

Kesia Miyashita (MSc., P.Biol.) is a biologist with 16 years of experience, including 10 years of experience in environmental consulting and extensive field experience in ecosystems in Ontario, Alberta, and British Columbia. During her career in environmental consulting, Kesia has completed environmental assessments for a variety of major infrastructure projects and urban developments. Her expertise is in vascular and non-vascular plant ecology, with experience in both terrestrial and wetland ecosystems; she has performed vegetation community inventories, tree surveys, rare plant surveys and invasive weed surveys in a variety of natural environments, including native forest, urban nature preserves, grasslands, and wetlands. She has undertaken surveys in industrial and construction sites and contributed to revegetation plans for site reclamation. Prior to joining Kilgour & Associates Ltd. in May 2021, Kesia was employed with the Canadian Wildlife Service, where she contributed to policies and guidance documents related to the interface between the *Species at Risk Act* and the *Impact Assessment Act* and developed a strong understanding of key pieces of federal legislation. Kesia is a Professional Biologist with the Alberta Society of Professional Biologists and a Qualified Wetland Science Practitioner in the province of Alberta.

2.3 Additional Applications

Not applicable.

3.0 EXISTING CONDITIONS

3.1 Tree Inventory

An initial inventory of trees for the properties at 6267 and 6271 Renaud Road was performed on March 14, 2024. Subsequently, a tree survey for 6259 Renaud Road was performed on June 17, 2024. A third tree survey for 6273 Renaud Road was performed on March 6, 2025. For each survey, all trees on and adjacent to the Site were identified, and trees with DBH ≥10 cm were mapped and further characterized (e.g., species, size distribution, general health conditions). On June 25, 2025, a Black Ash Health Assessment was completed for the single Black Ash found on the Site in accordance with the *Black Ash Assessment Guidelines: Assessment of Black Ash (Fraxinus nigra) for the purpose of the Endangered Species Act, 2007* (MECP, 2024). City-owned trees offsite <10 DBH were added to this TCR as an addendum.

In general, the majority of the three western parcels comprise manicured areas, with open, grassy lawns. Trees occur as scattered individuals or small clusters. The easternmost parcel comprises a central, cleared gravel pad supporting parking areas, storage containers and an office building, with tree cover concentrated around the property perimeter. Across the whole Site, tree cover increases towards the north (i.e., rear portion of the properties), abutting a public greenspace and multi-use trail situated off-site and parallel to the property line.

Based on aerial imagery from geoOttawa (City of Ottawa, 2025) dating back to 1965, the Site was historically forested. The north edge of the Site has remained in a predominantly treed state, while the south edge of the properties was cleared to accommodate residential development beginning between 1976 and 1991. Aerial imagery indicates that the cleared areas expanded, and the treed area became sparser and more manicured over time. At present, the northern, treed edge of the Site is characterized as individual trees and small clusters of two or three trees interspersed with cleared lawn areas.

In total, 204 trees were identified, situated onsite or immediately adjacent to site boundaries. Existing trees on the Site range in size from 9 cm to 91 cm DBH and represent 24 different species. The majority of trees (166) assessed are situated entirely within Site boundaries and owned by Richcraft. Seven (7) trees are situated along the Site boundaries and reflect shared ownership between Richcraft and adjacent landowners. Thirty-one (31) trees are City-owned trees on adjacent public lands. Two cedar hedgerows and nine trees requested to be included by the City of Ottawa are present on the Site that do not meet tree size requirements (Figure 2).

3.2 Ecological Significance of Trees on Site

The Site does not contain any Butternut trees (*Juglans cinerea*), listed as Endangered under the *Species Conservation Act* (SCA; Government of Ontario, 2025) and *Species at Risk Act* (SARA; Government of Canada, 2002). One Black Ash tree (*Fraxinus nigra*; Endangered under the SCA) was observed onsite, situated adjacent to the north property boundary (T51; Figure 2). A Black Ash Health Assessment was completed on June 25, 2025, in accordance with the *Black Ash Assessment Guidelines: Assessment of Black Ash (Fraxinus nigra) for the purpose of the Endangered Species Act, 2007* (MECP, 2024). The tree measured 9 cm DBH and was assessed as unhealthy. Therefore, species and habitat protections under the SCA do not apply.



Legend

- Site Boundary
- Tree
- Hedgerow



Figure 2. Site Trees

0 10 20 40 m

N W E S

Spatial Reference:
PCS: NAD 1983 MTM 9
Map Units: Meter

Project: RICH 1637
Map File Name: RICH 1637
Date Exported: 3/20/2026 10:07 AM

KILGOUR & Associates

Off-site areas adjacent to the Site boundaries were also searched for Black Ash and Butternut individuals, due to the potential for the root protection zones associated with off-site individuals to extend onto the Site. No additional Black Ash or Butternut trees were observed offsite, adjacent to the property boundary.

The Site does not contain any other tree species considered regionally significant (rare) in the Ottawa area per Muncaster Environmental Planning Inc. and Brunton Consulting Services (2005). The north edge of the Site abuts a public greenspace, with a treed slope down from the north property line down to a multi-use path and a drainage feature. The Site and adjacent lands provide habitat for common bird and mammal species in the Ottawa area.

3.3 Other Natural Environment Elements

3.3.1 Surface Water Features

A minor drainage feature was observed between 6271 and 6273 Renaud Road. It is characterized as a wide depression that collects water and conveys it north off the Site. It did not have defined banks or sides.

The Site does not contain any watercourses or surface water features.

3.3.2 Steep Slopes

The Site does not contain any steep slopes or large banks.

3.3.3 Valued Woodlots

The Site does not contain any woodlots designated as Urban Natural Features or Natural Environment Areas, areas evaluated in the *City of Ottawa Urban Natural Areas Environmental Evaluation Study* (UNAEES; Muncaster Environmental Planning Inc. & Brunton Consulting Services, 2005), or other areas that meet the criteria used in the UNAEES.

3.3.4 Significant Woodlands

The Site represents a relatively small portion of a larger contiguous woodland to the north. Altogether, this woodland area is over 60 years old and approximately 0.26 ha in area. As such, it meets the age criteria under the City's Urban Significant Woodlands Policy but does not satisfy the area requirement of 0.8 ha (City of Ottawa, 2022). Therefore, the woodland on the Site is not considered to be significant.

3.3.5 Greenspace Linkages

The Site represents a relatively small portion of a larger contiguous woodland to the north, which is identified in the Greenspace Master Plan as a supporting greenspace. This includes natural lands and watercourses that strengthen the features and functions of primary natural features by buffering or linking them; additionally, these supporting areas support overall landscape biodiversity (City of Ottawa, 2023).

3.3.6 Distinctive Trees

Beyond the single Black Ash discussed above, the Site contains eight distinctive trees (i.e., with DBH > 50 cm; Appendix A). These trees ranged in DBH from 51 cm to 91 cm and consisted of Trembling Aspen (*Populus tremuloides*; 2 distinctive trees), Balsam Poplar (*Populus balsamifera*; 1 distinctive tree), Sugar Maple (*Acer saccharum*; 1 distinctive tree), American Beech (*Fagus grandifolia*; 1 distinctive tree), and Red Maple (3 distinctive trees).

3.3.7 Unique Ecological Features

The development area does not contain any riparian woodlots, rare communities, or other unique ecological features.

3.3.8 Species at Risk

While a species at risk screening was not undertaken for the Site, potential habitat for SAR was considered during the tree survey. Several trees exhibited peeling bark and cavities, which may be suitable roosting habitat for SAR bats, such as the Eastern Small-footed Myotis (*Myotis leibii*), Little Brown Myotis (*Myotis lucifugus*), Northern Myotis/Northern Long-eared Bat (*Myotis septentrionalis*), and the Tri-colored Bat/Eastern Pipistrelle (*Perimyotis subflavus*).

For listed bat species in areas subject to tree removal, especially when extent of the tree removal is relatively small compared to remaining available treed areas nearby, mitigation measures to protect bat species should focus on the avoidance of harm to individuals. If a proposed activity will avoid impairing or eliminating the function of habitat for supporting bat life processes (e.g. remove, stub, etc. a small number of potential maternity or day roost trees in treed habitats) but the timing of tree removal will avoid the bat active season (April 1 – November 30), then there is no need to conduct species at risk bat surveys of treed habitats.

SAR birds may utilize the forested area immediately north of the Site; however, it is not expected that those species to be dependent on the trees on site as habitat. Any tree clearing will take place outside of the bird nesting period of April 15 to August 15 to protect the nests and young of migratory birds, including SAR birds.

SAR trees are discussed in Section 3.2 above.

4.0 PROPOSED DEVELOPMENT

The proposed Zoning Bylaw Amendment would rezone the Site as R3Z to accommodate future residential development. The proposed development plan for the Site comprises seven back-to-back townhome blocks, for a total of 76 townhome units. Roadway access will extend through the Site with two points of access along Renaud Road. Additional components include an amenity area, paved surface parking, a landscape feature, naturalized areas with a walkway along the north edge of the Site and tying into the multi-use path off-site. Of the 204 trees assessed on and adjacent to the Site, a total of 51 will be retained, and 153 will be removed to accommodate development. Thirty-one City-owned trees were identified adjacent to the Site; of these, 27 will be retained, and four will be removed. Additional tree plantings are proposed throughout the Site.



Legend

- Site Boundary
- Tree Protection Fence

Tree

- Retained
- Removed




Figure 3. Proposed Development

0 10 20 40 m

Spatial Reference:
PCS: NAD 1983 MTM 9
Map Units: Meter

Project: RICH 1637
Map File Name: RICH 1637
Date Exported: 10/29/2026 4:32 PM

KILGOUR & Associates

5.0 MITIGATION MEASURES

5.1 Site Preparation and Construction

The following mitigation measures should be applied during Site preparation and construction:

- Tree and vegetation clearing should not take place during sensitive times of the year for wildlife (breeding season; early spring throughout summer) unless mitigation measures are implemented and/or the habitat has been inspected by a qualified biologist.
    - The *Migratory Birds Convention Act* protects the nests and young of migratory breeding birds in Canada. No clearing of vegetation shall occur during the breeding bird window (between April 15 and August 15; City of Ottawa, 2015) to prevent impacts to birds. Combining the breeding bird window with the bat roosting season (April to November), no clearing of vegetation shall occur between April 1 and November 30 inclusive to prevent impacts to both birds and bats.

One Black Ash tree (9 cm DBH) was documented adjacent to the northern Site boundary during the March 6, 2025, tree inventory. A formal Black Ash Assessment completed on June 25, 2025, determined that the tree is unhealthy. As such, Black Ash species and habitat protections do not apply to this tree or its root protection zone.

It is expected that all trees within the development footprint, except for those retained existing trees within the naturalized and landscaped areas (Figure 3; Appendix A), will need to be cleared to accommodate development. Vegetation removal on the Site should be limited to that which is necessary to accommodate construction. All retainable trees on the Site outside of the development footprint, including those off-site but adjacent to the property boundary and development footprint, should follow the general protection measures recommended during site preparation and construction (City of Ottawa, 2015):

- Erect a fence beyond the critical root zone (CRZ; i.e., 10x the diameter at breast height) of trees to be retained. The fence should be highly visible (orange construction fence) and paired with erosion control fencing. Pruning of branches is recommended in areas of potential conflict with construction equipment;
- Do not place any material or equipment within the CRZ of trees.
- Do not attach any signs, notices, or posters to any trees.
- Do not raise or lower the existing grade within the CRZ of trees without approval.
- Tunnel or bore when digging within the CRZ of a tree.
- Do not damage the root system, trunk, or branches of any remaining trees.
- Ensure that exhaust fumes from all equipment are not directed toward any tree's canopy.
- Do not extend any hard surface or significantly change landscaping within the CRZ of trees.

6.0 CLOSURE

This report was prepared for exclusive use by Richcraft Homes Ltd. and may be distributed only by Richcraft Homes Ltd. Questions relating to the data and interpretation can be addressed to the undersigned.

Respectfully submitted,

KILGOUR & ASSOCIATES LTD.

Veronique Laudriault, MSc
Biologist
E-mail: kmiyashita@kilgourassociates.com
16-2285 St. Laurent Blvd, Ottawa, ON, K1G 4Z6
Office: 613-260-5555
Cell: 613-367-5546

Maren Nielsen, BES, EMA
Senior Biologist and Project Manager
E-mail: mnielsen@kilgourassociates.com
16-2285 St. Laurent Blvd, Ottawa, ON, K1G 4Z6
Office: 613-260-5555
Cell: 613-367-5562

LITERATURE CITED

City of Ottawa. (2015, October). *Environmental Impact Statement Guidelines*.

City of Ottawa. (2020). *Tree Protection (By-law No. 2020-340)*. https://ottawa.ca/en/living-ottawa/laws-licences-and-permits/laws/laws-z/tree-protection-law-no-2020-340

City of Ottawa. (2022). *Significant Woodlands: Guidelines for Identification, Evaluation, and Impact Assessment*. https://documents.ottawa.ca/sites/documents/files/significant_woodlands_en.pdf

City of Ottawa. (2023). *Greenspace Master Plan*. https://ottawa.ca/en/planning-development-and-construction/official-plan-and-master-plans/greenspace-master-plan

City of Ottawa. (2025). *geoOttawa*. https://maps.ottawa.ca/geoottawa/

Government of Canada. (2002). Species at Risk Act. *2002. S.C. 2002, c. 29*. https://laws.justice.gc.ca/eng/acts/S-15.3/

Government of Ontario. (2025). *Species Conservation Act*. https://www.ontario.ca/laws/statute/25s04b

MECP. (2024). *Black Ash Assessment Guidelines: Assessment of Black Ash (Fraxinus nigra) for the purposes of the* Endangered Species Act*, 2007*. https://www.ontario.ca/files/2024-06/mecp-black-ash-assessment-guidelines-en-2024-06-20.pdf

Muncaster Environmental Planning Inc. & Brunton Consulting Services. (2005). *City of Ottawa Urban Natural Areas Environmental Evaluation Study* (Final Report). https://app06.ottawa.ca/calendar/ottawa/citycouncil/pdc/2005/05-24/Final%20Report_UNAEES.htm

Appendix A Tree Data

Tree Number	Date/Time	Species Name	Number of Stems	DBH (cm)	Trunk Health	Canopy Health	Decay Class	Evidence of Pileated Woodpecker	Evidence of EAB	Location	Ownership	Fate
1	45722	Siberian Elm	1	11	Good: tree displays less than 15% deficiency	Fair: tree displays 15-40% deficiency	1: Healthy Live tree	No	No	45.43293017°, -75.50979989°	City-owned	Removed
2	45722	Trembling Aspen	3	21	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43295017°, -75.51014897°	Richcraft	Removed
3	45722	Trembling Aspen	1	11	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43297558°, -75.51016440°	Richcraft	Removed
4	45722	Trembling Aspen	2	24	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43299368°, -75.51018898°	Richcraft	Removed
5	45722	Trembling Aspen	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43301777°, -75.51017495°	Richcraft	Removed
6	45722	Trembling Aspen	1	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43302719°, -75.51017247°	Richcraft	Removed
7	45722	Trembling Aspen	1	15	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43300699°, -75.51018762°	Richcraft	Removed
8	45722	Trembling Aspen	1	16	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43303388°, -75.51016461°	Richcraft	Removed
9	45722	Trembling Aspen	2	44	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43305244°, -75.51020848°	Richcraft	Removed
10	45722	Trembling Aspen	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43304040°, -75.51019698°	Richcraft	Removed
11	45722	Trembling Aspen	1	51	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43303697°, -75.51021425°	Richcraft	Removed
12	45722	Trembling Aspen	1	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43307502°, -75.51023107°	Richcraft	Removed
13	45722	Trembling Aspen	1	16	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43310078°, -75.51021292°	Richcraft	Removed
14	45722	Trembling Aspen	1	31	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43306746°, -75.51022564°	Richcraft	Removed
15	45722	Trembling Aspen	1	25	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43309626°, -75.51023120°	Richcraft	Removed
16	45722	Trembling Aspen	2	24	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43311784°, -75.51024020°	Richcraft	Removed
17	45722	Trembling Aspen	1	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43312842°, -75.51023769°	Richcraft	Removed
18	45722	Trembling Aspen	1	26	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43312364°, -75.51027960°	Richcraft	Removed
19	45722	Trembling Aspen	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43316685°, -75.51026031°	Richcraft	Removed
20	45722	American Elm	1	18	Good: tree displays less than 15% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43319724°, -75.51027927°	Richcraft	Removed
21	45722	American Elm	1	15	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43318444°, -75.51019411°	Richcraft	Removed
22	45722	Trembling Aspen	1	31	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43316208°, -75.51030561°	Richcraft	Removed
23	45722	Trembling Aspen	1	16	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43323487°, -75.51029748°	Richcraft	Removed
24	45722	Trembling Aspen	1	34	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43321195°, -75.51029166°	Richcraft	Removed
25	45722	Trembling Aspen	2	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43324940°, -75.51022588°	Richcraft	Removed
26	45722	Trembling Aspen	1	11	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43324315°, -75.51030744°	Richcraft	Removed
27	45722	Trembling Aspen	2	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43330566°, -75.51027746°	Richcraft	Removed
28	45722	Trembling Aspen	1	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43333363°, -75.51028982°	Richcraft	Removed
29	45722	Trembling Aspen	3	51	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43327027°, -75.51037480°	Richcraft	Removed
30	45722	Trembling Aspen	2	42	Poor: tree displays greater than 40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43329417°, -75.51038536°	Richcraft	Removed
31	45722	Trembling Aspen	2	38	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43333392°, -75.51039950°	Richcraft	Removed
32	45722	Trembling Aspen	2	21	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43334772°, -75.51039678°	Richcraft	Removed
33	45722	Trembling Aspen	4	19	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	1: Healthy Live tree	No	No	45.43343621°, -75.51043902°	Richcraft	Retained
34	45722	Trembling Aspen	2	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43340665°, -75.51032561°	Richcraft	Removed
35	45722	Trembling Aspen	1	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43340575°, -75.51032388°	Richcraft	Removed
36	45722	Balsam Poplar	2	24	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43344274°, -75.51030996°	City-owned	Retained
37	45722	Balsam Poplar	2	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43344800°, -75.51031155°	City-owned	Retained
38	45722	Trembling Aspen	1	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43341845°, -75.51027777°	Richcraft	Removed
39	45722	Balsam Poplar	11	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43340632°, -75.51025724°	Richcraft	Removed
40	45722	Trembling Aspen	1	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43339353°, -75.51022371°	Richcraft	Removed
41	45722	Trembling Aspen	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43342900°, -75.51024039°	Richcraft	Removed
42	45722	Balsam Poplar	3	52	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43344044°, -75.51018843°	Richcraft	Removed

Tree Number	Date/Time	Species Name	Number of Stems	DBH (cm)	Trunk Health	Canopy Health	Decay Class	Evidence of Pileated Woodpecker	Evidence of EAB	Location	Ownership	Fate
43	45722	Trembling Aspen	3	16	Good: tree displays less than 15% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43344274°, -75.51012488°	Richcraft	Removed
44	45722	American Elm	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43342965°, -75.51005122°	Richcraft	Removed
45	45722	Trembling Aspen	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43345947°, -75.51008336°	Richcraft	Retained
46	45722	Trembling Aspen	3	25	Poor: tree displays greater than 40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43346685°, -75.51010835°	City-owned	Removed
47	45722	Trembling Aspen	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43345842°, -75.51014005°	Richcraft	Retained
48	45722	American Elm	1	11	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43342647°, -75.51003418°	Richcraft	Removed
49	45722	Trembling Aspen	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43342723°, -75.51003463°	Richcraft	Removed
50	45722	White Birch	5	24	Poor: tree displays greater than 40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43344917°, -75.51002415°	Richcraft	Removed
51	45722	Black Ash	2	NA	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43344849°, -75.51007427°	Richcraft	Removed
52	45722	Trembling Aspen	1	25	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43346227°, -75.50998902°	Richcraft	Removed
53	45722	Green Ash	3	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43344746°, -75.50993272°	Richcraft	Removed
54	45722	Trembling Aspen	1	21	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43352585°, -75.50984289°	Richcraft	Removed
55	45722	Trembling Aspen	1	14	Poor: tree displays greater than 40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43355196°, -75.50972991°	Richcraft	Removed
56	45722	Trembling Aspen	1	12	Poor: tree displays greater than 40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43354749°, -75.50970342°	Richcraft	Removed
57	45722	Trembling Aspen	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43356679°, -75.50968733°	Richcraft	Removed
58	45722	Trembling Aspen	2	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43357643°, -75.50968364°	Richcraft	Removed
59	45722	Trembling Aspen	1	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43355443°, -75.50966042°	Richcraft	Removed
60	45722	Trembling Aspen	1	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43357609°, -75.50959986°	Richcraft	Removed
61	45722	Trembling Aspen	1	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43359947°, -75.50955880°	Richcraft	Removed
62	45722	Trembling Aspen	2	14	Fair: tree displays 15-40% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43356707°, -75.50951515°	Richcraft	Removed
63	45722	Trembling Aspen	1	16	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43361972°, -75.50953880°	Richcraft	Removed
64	45722	Eastern Cottonwood	2	11	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43360166°, -75.50949766°	Richcraft	Removed
65	45722	Trembling Aspen	5	15	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43360627°, -75.50946569°	Richcraft	Removed
66	45722	Eastern Cottonwood	1	20	Fair: tree displays 15-40% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43360668°, -75.50945274°	Richcraft	Removed
67	45722	Trembling Aspen	1	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43366984°, -75.50948717°	Richcraft	Removed
68	45722	Eastern Cottonwood	1	25	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43368298°, -75.50943791°	Richcraft	Removed
69	45722	Trembling Aspen	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43368177°, -75.50947160°	City-owned	Retained
70	45722	Trembling Aspen	3	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43369184°, -75.50948471°	City-owned	Retained
71	45722	Trembling Aspen	1	15	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43373436°, -75.50942962°	City-owned	Retained
72	45722	Trembling Aspen	1	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43374395°, -75.50948717°	City-owned	Retained
73	45722	Trembling Aspen	3	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43373359°, -75.50944616°	City-owned	Retained
74	45722	Trembling Aspen	2	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43378099°, -75.50940995°	City-owned	Retained
75	45722	Balsam Poplar	1	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43376424°, -75.50939591°	City-owned	Retained
76	45722	Trembling Aspen	1	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43377243°, -75.50939338°	City-owned	Retained
77	45722	Trembling Aspen	1	15	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43379086°, -75.50941258°	City-owned	Retained
78	45722	Trembling Aspen	3	40	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43380659°, -75.50942299°	City-owned	Retained
79	45722	Trembling Aspen	2	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43379907°, -75.50943968°	City-owned	Retained
80	45722	Trembling Aspen	3	21	Poor: tree displays greater than 40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43382957°, -75.50942446°	City-owned	Retained
81	45722	Trembling Aspen	1	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43383701°, -75.50944620°	City-owned	Retained
82	45365	Sugar Maple	1	27	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43287867°, -75.51067167°	Richcraft	Removed
83	45365	Red Oak	1	25	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43305717°, -75.51074967°	Richcraft	Removed
84	45365	Eastern White Pine	14	47	Good: tree displays less than 15% deficiency	Fair: tree displays 15-40% deficiency	1: Healthy Live tree	No	No	45.43309100°, -75.51078917°	Richcraft	Removed

Tree Number	Date/Time	Species Name	Number of Stems	DBH (cm)	Trunk Health	Canopy Health	Decay Class	Evidence of Pileated Woodpecker	Evidence of EAB	Location	Ownership	Fate
85	45365	Sugar Maple	3	89	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43308667°, -75.51091450°	Richcraft	Removed
86	45365	Sugar Maple	2	43	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43313567°, -75.51088783°	Richcraft	Removed
87	45365	Eastern White Cedar	1	20	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43315850°, -75.51082383°	Richcraft	Removed
88	45365	White Spruce	11	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43318000°, -75.51081700°	Richcraft	Removed
89	45365	American Beech	1	11	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43319550°, -75.51081983°	Richcraft	Removed
90	45365	American Beech	1	16	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43322567°, -75.51085533°	Richcraft	Removed
91	45365	Red Maple	1	29	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43326100°, -75.51092967°	Richcraft	Removed
92	45365	Red Maple	2	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43330350°, -75.51092250°	Richcraft	Removed
93	45365	Black Cherry	12	28	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43333950°, -75.51092233°	Richcraft	Removed
94	45365	American Beech	1	25	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43337800°, -75.51096367°	Richcraft	Removed
95	45365	White Birch	3	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43335750°, -75.5109525°	Richcraft	Retained
96	45365	Douglas Fir	11	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43339383°, -75.51099683°	Richcraft	Retained
97	45365	American Beech	1	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43342483°, -75.51103400°	Richcraft	Removed
98	45365	Red Maple	3	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43338383°, -75.51104750°	Richcraft	Retained
99	45365	Red Maple	1	38	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43342817°, -75.51108800°	Richcraft	Retained
100	45365	Red Maple	4	17	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43339817°, -75.51108167°	Richcraft	Removed
101	45365	Red Maple	2	26	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43335517°, -75.51106550°	Richcraft	Retained
102	45365	Red Oak	1	20	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43335300°, -75.51103467°	Richcraft	Removed
103	45365	Red Maple	3	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43334167°, -75.51103083°	Richcraft	Retained
104	45365	Red Maple	3	23	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43334300°, -75.51097317°	Richcraft	Removed
105	45365	Red Maple	2	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43331283°, -75.51102583°	Richcraft	Removed
106	45365	Eastern White Pine	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43335817°, -75.51115900°	Richcraft	Retained
107	45365	Red Maple	1	28	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43338883°, -75.51116833°	Richcraft	Retained
108	45365	Black Cherry	1	39	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43340650°, -75.51118483°	Richcraft	Retained
109	45365	Red Maple	1	43	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43342650°, -75.51118100°	Richcraft	Retained
110	45365	White Spruce	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43340850°, -75.51121450°	Richcraft	Retained
111	45365	Red Maple	1	28	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43338817°, -75.5120667°	Richcraft	Retained
112	45365	White Spruce	1	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43338100°, -75.51128450°	Richcraft	Retained
113	45365	Red Maple	1	33	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43338750°, -75.51131200°	Richcraft	Retained
114	45365	Red Oak	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43336217°, -75.51127533°	Richcraft	Removed
115	45365	Red Oak	3	32	Fair: tree displays 15-40% deficiency	Good: tree displays less than 15% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43335383°, -75.51125933°	Richcraft	Removed
116	45365	Red Pine	1	11	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43328200°, -75.51123367°	Richcraft	Removed
117	45365	Red Pine	1	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43327117°, -75.51118750°	Richcraft	Removed
118	45365	Eastern White Pine	1	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43330700°, -75.51118033°	Richcraft	Retained
119	45365	Red Maple	2	30	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43328950°, -75.51106233°	Richcraft	Removed
120	45365	Red Maple	1	27	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43327467°, -75.51107717°	Richcraft	Removed
121	45365	Red Maple	1	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43325150°, -75.51112950°	Richcraft	Removed
122	45365	Red Maple	1	23	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43326600°, -75.51108317°	Richcraft	Removed
123	45365	Red Maple	1	45	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43322600°, -75.51110783°	Richcraft	Removed
124	45365	White Spruce	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43323700°, -75.51101783°	Richcraft	Removed
125	45365	Red Maple	1	34	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43319267°, -75.51105417°	Richcraft	Removed
126	45365	Red Maple	1	27	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43317600°, -75.51108733°	Richcraft	Removed

Tree Number	Date/Time	Species Name	Number of Stems	DBH (cm)	Trunk Health	Canopy Health	Decay Class	Evidence of Pileated Woodpecker	Evidence of EAB	Location	Ownership	Fate
127	45365	White Spruce	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43315133°, -75.51103633°	Richcraft	Removed
128	45365	Red Maple	1	26	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43316100°, -75.51102783°	Richcraft	Removed
129	45365	Red Maple	1	29	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43315167°, -75.51100250°	Richcraft	Removed
130	45365	Red Maple	2	34	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43310733°, -75.51100017°	Richcraft	Removed
131	45365	Red Oak	1	33	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43309283°, -75.51103550°	Richcraft	Removed
132	45365	Red Maple	2	47	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43310200°, -75.51099517°	Richcraft	Removed
133	45365	Red Maple	1	24	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43305950°, -75.51104167°	Richcraft	Removed
134	45365	Red Maple	2	47	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43302683°, -75.51104400°	Richcraft	Removed
135	45365	Red Maple	1	42	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43302650°, -75.51100483°	Richcraft	Removed
136	45365	Douglas Fir	1	30	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43293200°, -75.51094783°	Richcraft	Removed
137	45365	American Beech	1	91	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43282217°, -75.51083567°	Richcraft	Removed
138	45365	White Birch	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43313933°, -75.51070617°	Richcraft	Removed
139	45365	Red Oak	1	21	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43318400°, -75.51066200°	Richcraft	Removed
140	45365	Red Maple	5	36	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43327050°, -75.51065100°	Richcraft	Removed
141	45365	Red Maple	1	28	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43332933°, -75.51069983°	Richcraft	Removed
142	45365	Red Maple	1	23	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43332967°, -75.51068900°	Richcraft	Removed
143	45365	Red Maple	1	37	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43330383°, -75.51071467°	Richcraft	Removed
144	45365	Red Maple	2	26	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43329600°, -75.51077717°	Richcraft	Removed
145	45365	Red Maple	2	30	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43334850°, -75.51083283°	Richcraft	Removed
146	45365	White Birch	1	24	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43338367°, -75.51088067°	Richcraft	Retained
147	45365	White Birch	1	42	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43340783°, -75.51084133°	Richcraft	Retained
148	45365	Red Maple	2	20	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43341217°, -75.51081800°	Richcraft	Retained
149	45365	American Beech	1	11	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43340717°, -75.51077417°	Richcraft	Removed
150	45365	American Beech	1	11	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43341900°, -75.51076317°	Richcraft	Removed
151	45365	White Birch	2	36	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43340700°, -75.51076167°	Richcraft	Retained
152	45365	Red Maple	1	28	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43338383°, -75.51075583°	Richcraft	Removed
153	45365	Red Maple	1	22	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43335883°, -75.51075867°	Richcraft	Removed
154	45365	Red Maple	1	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43336500°, -75.51072600°	Richcraft	Removed
155	45365	Red Maple	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43333567°, -75.51070350°	Richcraft	Removed
156	45365	Red Maple	1	16	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43333617°, -75.51073367°	Richcraft	Removed
157	45365	Red Maple	1	38	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43334617°, -75.51068333°	Richcraft	Removed
158	45365	White Birch	1	32	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43333900°, -75.51063733°	Richcraft	Removed
159	45365	Red Maple	12	44	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43339133°, -75.51064800°	Richcraft	Retained
160	45365	Red Maple	2	67	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43337683°, -75.51062850°	Richcraft	Retained
161	45365	Eastern White Pine	1	29	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43325100°, -75.51046300°	Richcraft	Removed
162	45365	White Birch	5	21	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43283667°, -75.51038350°	Richcraft	Removed
163	45365	prunus	1	21	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43284133°, -75.51033100°	Richcraft	Removed
164	45365	Red Maple	1	74	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43283083°, -75.51017600°	Richcraft	Removed
165	45365	Trembling Aspen	1	29	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43286200°, -75.51016717°	Richcraft	Removed
166	45365	Red Maple	1	20	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43291217°, -75.51018367°	Richcraft	Removed
167	45365	Red Maple	1	33	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43292850°, -75.51017783°	Richcraft	Removed
168	45365	Red Maple	1	32	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43264967°, -75.51054283°	Richcraft	Removed

Tree Number	Date/Time	Species Name	Number of Stems	DBH (cm)	Trunk Health	Canopy Health	Decay Class	Evidence of Pileated Woodpecker	Evidence of EAB	Location	Ownership	Fate
169	45365	Blue Spruce	1	45	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43260167°, -75.51069200°	Richcraft	Removed
170	45460	Blue Spruce	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43255823°, -75.51084905°	Richcraft	Removed
171	45460	Red Maple	5	51	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43285652°, -75.51110063°	Richcraft	Removed
172	45460	Manitoba Maple	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43279187°, -75.51113405°	Richcraft	Removed
173	45460	Green Ash	2	10	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43278458°, -75.51114758°	Richcraft	Removed
174	45460	Manitoba Maple	1	19	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43277677°, -75.51116252°	Richcraft	Removed
175	45460	Manitoba Maple	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43278693°, -75.51116522°	Richcraft	Removed
176	45460	Manitoba Maple	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43279442°, -75.51119162°	Richcraft	Removed
177	45460	Green Ash	2	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43272798°, -75.51126072°	Richcraft	Removed
178	45460	Manitoba Maple	2	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43273180°, -75.51128047°	Richcraft	Removed
179	45460	Green Ash	6	10	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43273852°, -75.51131948°	Richcraft	Removed
180	45460	Green Ash	2	10	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43274350°, -75.51133227°	City-owned	Removed
181	45460	Green Ash	2	17	Fair: tree displays 15-40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43268073°, -75.51128768°	Richcraft	Removed
182	45460	Black Cherry	1	12	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43265583°, -75.51127143°	Richcraft	Removed
183	45460	Manitoba Maple	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43267975°, -75.51125133°	Richcraft	Removed
184	45460	Manitoba Maple	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43261387°, -75.51121195°	Richcraft	Removed
185	45460	Trembling Aspen	1	14	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43260077°, -75.51125618°	City-owned	Retained
186	45460	Trembling Aspen	1	15	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43260467°, -75.51125443°	City-owned	Retained
187	45460	Apple	2	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43243403°, -75.51111488°	Richcraft	Removed
188	45460	prunus	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43261213°, -75.51125922°	City-owned	Retained
189	45460	Manitoba Maple	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43241337°, -75.51110402°	City-owned	Retained
190	45460	Manitoba Maple	1	16	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43241552°, -75.51116012°	City-owned	Retained
191	45460	Manitoba Maple	2	18	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43240502°, -75.51110423°	City-owned	Retained
192	45460	Manitoba Maple	2	19	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43245425°, -75.51117933°	City-owned	Retained
193	45460	White Willow	5	16	Poor: tree displays greater than 40% deficiency	Fair: tree displays 15-40% deficiency	2: Declining live tree, part of canopy lost	No	No	45.43237313°, -75.51108193°	City-owned	Retained
194	45460	Trembling Aspen	1	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43247642°, -75.51117193°	City-owned	Retained
195	45460	serviceberry	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43250087°, -75.51121973°	City-owned	Retained
196	45460	Manitoba Maple	1	13	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43250737°, -75.51122207°	City-owned	Retained
197	45722	Siberian Elm	2	17	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.43293294°, -75.50974181°	City-owned	Removed
198	45460	Unknown	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.432992°, -75.509673°	Richcraft	Removed
199	45460	Unknown	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.433005°, -75.509612°	Richcraft	Removed
200	45460	Unknown	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.433293°, -75.508998°	Richcraft	Removed
201	45460	Unknown	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.433312°, -75.509016°	Richcraft	Removed
202	45460	Unknown	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.433366°, -75.508977°	Richcraft	Removed
203	45460	Unknown	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.433364°, -75.509004°	Richcraft	Removed
204	45460	Unknown	1	10	Good: tree displays less than 15% deficiency	Good: tree displays less than 15% deficiency	1: Healthy Live tree	No	No	45.433580°, -75.509039°	City-owned	Retained