



CONSULTANTS

RLA ARCHITECTURE RODERICK LAHEY ARCHITECT INC., 56 BEECH STREET, OTTAWA, ONTARIO K1S 3J6 Tel: (613) 724-9932

SURVEYORS:

ANNIS, O'SULLIVAN, VOLLEBEKK LTD.
14 Concourse Gate, Suite 500 Nepean, Ont. K2E 7S6
Phone: (613) 727-0850 / Fax: (613) 727-1079

CIVIL ENGINEERS:

Ontario Land Surveyors



400 - 333 Preston Street Ottawa ON K1S 5N4 Canada tel 613 225 1311 fax 613 225 9868 ibigroup.com

LEGEND



GROUP OF EXISTING TREES TO REMAIN




GROUP OF EXISTING TREES TO BE REMOVED



EXISTING TREE TO BE REMOVED

TREE PROTECTION FENCE (REFER TO DETAIL 2/TCR THIS SHEET)



2 TREE PROTECTION FENCE TCR N.T.S

EXISTING TREE LIST QTY. KEY										
KEY	QTY.	BOTANICAL NAME	COMMON NAME	SIZE	CONDITION	REMARKS	OWNERSHIP			
AL	*	Alnus incana	Speckled Alder	100mm DBH	GOOD	To be removed	4624 Spratt			
AN	2	Acer negundo	Manitoba Maple	150-200mm DBH	GOOD	To be removed	4624 Spratt			
AR	1	Acer rubrum	Red Maple	6x200mm DBH	GOOD	To be removed	4624 Spratt			
FR	*	Fraxinus spp.	Ash	100-300mm DBH	DEAD	To be removed	4624 Spratt			
FX	*	Fraxinus spp.	Ash	100-250mm DBH	DEAD	To remain	City of Ottawa			
PL	*	Populus spp.	Poplar	100-200mm DBH	GOOD	To remain	City of Ottawa			
PO	*	Populus spp.	Poplar	100-300mm DBH	GOOD	To be removed	4624 Spratt			
UA	*	Ulmus americana	American Elm	100-300mm DBH	DEAD-FAIR	To be removed	City of Ottawa			
UL	*	Ulmus americana	American Elm	100-200mm DBH	DEAD-FAIR	To remain	City of Ottawa			

GENERAL NOTES:

- . IT IS THE RESPONSIBILITY OF THE APPROPRIATE CONTRACTOR OR OFFICIAL TO REPORT ANY ERRORS, OMISSIONS OR DISCREPANCIES ON THIS PLAN WITH ACTUAL SITE CONDITIONS TO THE LANDSCAPE ARCHITECT BEFORE PROCEEDING WITH
- THE CONTRACTOR IS TO NOTIFY ALL UTILITY COMPANIES AND AUTHORITIES PRIOR TO ANY EXCAVATION AND ASCERTAIN LOCATIONS OF UNDERGROUND SERVICES.
- THE CONTRACTOR IS TO REINSTATE ALL AREAS AND ITEMS DAMAGED AS A RESULT OF CONSTRUCTION ACTIVITY.
- 4. THE CONTRACTOR IS TO COMPLY WITH ALL PERTINENT CODES AND BY-LAWS.
- 5. THE CONTRACTOR IS TO MAINTAIN A POSITIVE SURFACE RUN-OFF THROUGHOUT THE ENTIRE CONSTRUCTION PERIOD. 6 THE LANDSCAPE ARCHITECT IS NOT RESPONSIBLE FOR SUBSLIBEACE CONDITIONS

7. THE CONTRACTOR IS TO IDENTIFY ALL EXISTING TREES TO REMAIN ON SITE WITH THE LANDSCAPE ARCHITECT PRIOR CONSTRUCTION.	О.	THE LANDSCAPE ARCHITECT IS NOT RESPONSIBLE FOR SUBSURFACE CONDITIONS.
	7.	THE CONTRACTOR IS TO IDENTIFY ALL EXISTING TREES TO REMAIN ON SITE WITH THE LANDSCAPE ARCHITECT PRIOR TO CONSTRUCTION.

1	ISSUED FOR DISCUSSION AND REVIEW	01/06/2022	М
No.	Issue	Date MM/DD/YY	D

JAMES B. LENNOX & ASSOCIATES INC. LANDSCAPE 3332 CARLING AVE. OTTAWA, ONTARIO K2H 5A8 Tel. (613) 722-5168 Fax. 1(866) 343-3942

SPRATT ROAD ZENS

4624 SPRATT ROAD, OTTAWA ON

PROJECT

TREE CONSERVATION REPORT




AS SHOWN START DATE

DECEMBER 2021 PROJECT NO.

PROJECT NORTH

DRAWING NO.



PLOT SIZE ARCH-D