




## **KEY PLAN N.T.S.**



TCR SCALE: NTS

## **GENERAL NOTES:**

- 1. It is the responsibility of the appropriate contractor or official to report any errors, omissions or discrepancies on this plan with actual site conditions to the Landscape Architect before proceeding with construction.
- 2. The contractor is to notify all utility companies and authorities prior to any excavation and ascertain locations of underground services.
- 3. The contractor is to reinstate all areas and items damaged as a result of construction activity. 4. The contractor is to comply with all pertinent codes and by-laws.
- 5. The contractor is to maintain a positive surface run-off throughout the entire construction period.
- 6. The Landscape Architect is not responsible for subsurface conditions. 7. The contractor is to identify all existing trees to remain on site with the Landscape Architect prior to construction.

KEY	QTY.	BOTANICAL NAME	COMMON NAME	SIZE	CONDITION	REMARKS	OWNERSHIP	COMMENT
1	1	Acer rubrum	Red Maple	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TB
2	1	Acer rubrum	Red Maple	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TB
3	1	Acer saccharum	Sugar Maple	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TB
4	1	Acer saccharum	Sugar Maple	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TE
5	1	Acer saccharum	Sugar Maple	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TE
6	1	Acer saccharum	Sugar Maple	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TE
7	1	Acer saccharum	Sugar Maple	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TE
8	1	Quercus rubra	Red Oak	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TE
9	1	Quercus rubra	Red Oak	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % TE
10	1	Quercus rubra	Red Oak	70mm DBH	GOOD	To be removed	City of Ottawa	Canopy % Ti
11	52	Populus deltoides	Eastern Cottonwood	100-300mm DBH	FAIR-GOOD	To be removed	120 Lusk Street	Canopy % TI
12	1	Acer negundo	Manitoba Maple	200mm DBH	GOOD	To be removed	120 Lusk Street	Canopy % Ti
13	1	Acer negundo	Manitoba Maple	100mm DBH	GOOD	To be removed	120 Lusk Street	Canopy % TI
14	1	Acer negundo	Manitoba Maple	160mm DBH	GOOD	To be removed	120 Lusk Street	Canopy % TI
15	1	Populus deltoides	Eastern Cottonwood	2x150mm DBH	GOOD	To be removed		Canopy % Ti
16	1	Populus deltoides	Eastern Cottonwood	200mm DBH	GOOD	To be removed	120 Lusk Street	Canopy % Ti
17	1	Populus deltoides	Eastern Cottonwood	300mm DBH	GOOD	To be removed	120 Lusk Street	Canopy % Ti
18	1	Acer negundo	Manitoba Maple	200mm DBH	GOOD	To remain	100 Lusk Street	Canopy % TI
19	1	Acer negundo	Manitoba Maple	200mm DBH	GOOD	To remain	100 Lusk Street	Canopy % Ti
20	1	Populus deltoides	Eastern Cottonwood	2x350mm DB	GOOD	To be removed	120 Lusk Street	Canopy % Ti
21	12	Ulmus americana	American Elm	15-200mm DBH	GOOD	See plan	120 Lusk Street / City	Canopy % Ti
22	1	Acer negundo	Manitoba Maple	200mm DBH	GOOD	See plan	120 Lusk Street / City	Canopy % TI
23	1	Acer negundo	Manitoba Maple	200mm DBH	GOOD	To remain	City of Ottawa	Canopy % TI
24	1	Acer negundo	Manitoba Maple	250mm DBH	GOOD	To remain	City of Ottawa	Canopy % TI
25	1	Populus deltoides	Eastern Cottonwood	500mm DBH	GOOD	To remain	City of Ottawa	Canopy % TI
26	1	Populus deltoides	Eastern Cottonwood	200mm DBH	GOOD	To remain	City of Ottawa	Canopy % TE
27	1	Populus deltoides	Eastern Cottonwood	200mm DBH	GOOD	To remain	City of Ottawa	Canopy % Ti
28	1	Populus deltoides	Eastern Cottonwood	200mm DBH	GOOD	To remain	City of Ottawa	Canopy % TE
29	1	Populus deltoides	Eastern Cottonwood	450mm DBH	GOOD	To be removed	120 Lusk Street	Canopy % TE
30	1	Ulmus americana	American Elm	150mm DBH	GOOD	To be removed		Canopy % TE
31	1	Populus deltoides	Eastern Cottonwood	400mm DBH	GOOD	To be removed	120 Lusk Street	Canopy % TE
32	1	Populus deltoides	Eastern Cottonwood	400mm DBH	GOOD	To be removed	120 Lusk Street	Canopy % Ti
33	1	Populus deltoides	Eastern Cottonwood	400mm DBH	GOOD	To be removed		Canopy % TE
34	1	Populus deltoides	Eastern Cottonwood	150mm DBH	GOOD	To be removed		Canopy % TE
35	1	Populus deltoides	Eastern Cottonwood	150mm DBH	GOOD	To be removed		Canopy % Ti

## Dr. Sandra Iroakazi

CONSULTANTS

ARCHITECTS:

MATAJ ARCHITECTS INC.

96 Forsythe Street, Oakville Ontario Tel: (905) 281-4444

333 PRESTON STREET SUITE 500 OTTAWA, ON K1S 5N4 Tel : (613) 721-0555

**ARCADIS OTTAWA** 

SURVEYORS:

ANNIS, O'SULLIVAN, **VOLLEBEKK INC.** 

14 CONCOURSE GATE SUITE 500 OTTAWA, ON K2E 7S6 Tel : (613) 727-0850

**LEGEND** 

EXISTING TREE TO REMAIN

GROUP OF EXISTING TREES TO

EXISTING TREE TO BE REMOVED

GROUP OF EXISTING TREES TO BE REMOVED

TREE PROTECTION FENCE


1						ı
		4	REVISED PER NEW CIVIL DRAWING	09/18/2025	ML	
	3	REVISED PER CITY COMMENTS	08/15/2025	ML		
	2	REVISED PER CITY COMMENTS	08/01/2025	ML	Ī	
		1	ISSUED FOR FORESTRY REVIEW	01/16/2025	ML	
		No.	Issue	Date MM/DD/YY	DR	

JAMES B. LENNOX & ASSOCIATES INC. LANDSCAPE **ARCHITECTS** 3332 CARLING AVE. Tel. (613) 722-5168 Fax. 1(866) 343-3942

LUSK MEDICAL BUILDING

120 LUSK STREET, OTTAWA ON

TREE CONSERVATION REPORT



CALE AS SHOWN TART DATE MAY 2024

PROJECT NORTH

24MIS2428 RAWING NO.

ROJECT NO.

