

TOPOGRAPHIC INFORMATION PROVIDED BY STANTEC GEOMATICS LTD PROJ. NO. 161613668-111 DATED APRIL 30, 2019 SITE PLAN INFORMATION SITE PLAN PROVIDED BY RLA ARCHITECTUR DATED REV. OCTOBER 24, 2019 **GEOTECHNICAL STUDY** 

GEOTECHNICAL RECOMMENDATIONS PROVIDED BY GOLDER ASSOCIATES LTD DATED NOVEMBER 2018

TOPOGRAPHIC INFORMATION

SITE SERVICING AND STORMWATER MANAGEMENT STUDY SERVICING AND STORMWATER MANAGEMENT RECOMMENDATIONS PROVIDED BY DSFI DATED NOVEMBER 2019


## **BENCH MARK**

**RioCAN** 

1: 750 | DATE:

BENCHMARK 1: FIRE HYDRANT TOP OF SPINDLE LOCATED ON CARLING AVE SOUTH-EAST CORNER OF SUBJECT SITE ACROSS CONNAUGHT AVENUE. ELEV=74.37m

BENCHMARK 2: FIRE HYDRANT TOP OF SPINDLE LOCATED ON CARLING AVE SOUTH—EAST CORNER OF SUBJECT SITE ACROSS WATERLOO AVENUE. ELEV=74.37m





**GRADING PLAN** LINCOLN FIELDS

> RioCan Yonge Eglinton Centre 2300 Yonge Street, Suite 500 Toronto, Ontario, M4P 1E4

> > 2 of 4

120 Iber Road Unit 103 Stittsville, Ontario, K2S 1E9 Tel. (613) 836-0856 Fax. (613) 836-7183 www.DSEL.ca B.N.C. | CHECKED BY: R.D.F. DRAWING NO. RAWN BY: SHEET NO. B.N.C. CHECKED BY: DESIGNED BY:

© DSEL