


13. Ensure that mulch is pulled back a min. distance of 75mm from base of tree trunk.

NAASCAR INC. & AD **INVESTMENTS**



T.L. Mak Engineering Consultants Ltd. 1455 Youville Drive, Suite 218 Ottawa, ON. K1C 6Z7

LEGEND




- SOIL VOLUME AREA PROPOSED DECIDUOUS TREE



PROPOSED SHRUBS / ORNAMENTAL GRASSES



PROPOSED WOOD MULCH



PROPOSED CONCRETE



PROPOSED BOULDER



EXISTING TREE TO REMAIN

TREE PROTECTION FENCE

__o___o__ 2.4m Ht. NOISE BARRIER FENCE PROPOSED 2.1m Ht. WOOD

SCREEN FENCE

	9				
	8				
	7				
	6				
	5	REVISED PER CITY COMMENTS	03/17/2025	ML	JL
	4	REVISED PER CITY COMMENTS	02/27/2025	ML	JL
	3	ISSUED FOR DISCUSSION AND REVIEW	01/13/2025	WF	JL
	2	REVISED PER CITY COMMENTS	11/20/2024	ML	JL
	1	ISSUED FOR DISCUSSION AND REVIEW	04/26/2024	ML	JL
l	No.	Issue	Date	DR	СК

JAMES B. LENNOX & ASSOCIATES INC. LANDSCAPE **ARCHITECTS** 3332 CARLING AVE. OTTAWA, ONTARIO K2H 5A8 Fax. 1(866) 343-3942

PROPOSED LOW-RISE APARTMENTS 609, 611, 613, 615 PARKVIEW ROAD, OTTAWA ON

TREE CONSERVATION REPORT &



SCALE AS SHOWN TART DATE

24MIS2408

RAWING NO.

FEBRUARY 2024 ROJECT NO.

