

SUN & SHADOW STUDY


JUNE 21



SEPTEMBER 21  
MARCH 21



DECEMBER 21



It is the responsibility of the appropriate contractor to check and verify all dimensions on site and report all errors and/or omissions to the engineer.  
All contractors must comply with all  
Do not scale drawings.  
This drawing may not be used for construction until signed.  
Copyright reserved.