


Appendix B

Photographs



View of Site from Sheffield Road.



View of standing water and storage trailer on-site.



View of western portion of the Site. Debris and dumped wastes visible.



View of vegetated southern portion of the Site and adjacent vacant property, looking south towards Walkley Road.





View of waste storage, trailer, two of four dumpsters, empty pails of fire resistive paint, standing water and parked vehicles on-site.



View of empty 20 L pails of fire resistive paint located on-site.



View of the two transformers and the remaining two dumpsters located on-site.



View of couches, mattress, tires, and other domestic wastes dumped on the western portion of the Site.



Abandoned aboveground storage tank (AST) located north of the Site at 2900 Sheffield Road.



AST with visible dents and rust located north of the Site at 2900 Sheffield Road.



Tires dumped between the transformers located on-site.



Electrical substation located southeast of the Site.