

P.O. BOX 13593, STN. KANATA, OTTAWA, ON K2K 1X6

TELEPHONE: (613) 838-5717

WEBSITE: WWW.IFSASSOCIATES.CA URBAN FORESTRY & FOREST MANAGEMENT CONSULTING

April 13, 2023

Neil Chadha 417 Auto Sales 2026 Carp Road Ottawa, ON K0A 1T0

RE: TREE CONSERVATION REPORT FOR 2026 CARP ROAD, OTTAWA

This Tree Conservation Report (TCR) was prepared by IFS Associates Inc. (IFS) on behalf of 417 Auto Sales in support of the proposed addition of surface car parking and display areas surrounding the existing dwelling at 2026 Carp Road in Ottawa. The need for this report is related to trees protected under the City of Ottawa's Tree Protection By-law (By-law No. 2020-340). The By-law reflects Section 4.8.2. of the City of Ottawa's Official Plan which calls for the retention of the City's urban forestry canopy and, in particular, the protection of "mature, healthy trees on private and public property, including the provision of adequate volumes of high-quality soil".

Under the Tree Protection By-law, a TCR is required for all plans of subdivision, site plan control applications, common elements condominium applications, and vacant land condominium applications where there is a tree of 10 cm in diameter at breast height (DBH) or greater on a site and/or if there is a tree on an adjacent site that has a critical root zone (CRZ) extending onto a development site. Trees of any size on adjacent City lands must also be documented in a TCR. A "tree" is defined in the By-law as any species of woody perennial plant, including its root system, which has reached or can reach a minimum height of at least 450 cm at physiological maturity. The CRZ is calculated as DBH x 10 cm.

The approval of this tree conservation report by the city and the issuing of a permit authorizes the removal of approved trees. Importantly, although this report may be used to support the application for a tree removal permit, it does not by itself constitute permission to remove trees or begin site clearing activities. No such work should occur before a tree removal permit is issued authorizing the injury or destruction of a tree in accordance with the Bylaw. Further, the removal of any trees shared with or fully on neighbouring properties will require written permission of the adjacent landowner.

The inventory in this report details the assessment of all individual trees on the subject and adjacent private property, including City of Ottawa lands. Field work for this report was completed in October 2021 and January 2023.

Table 1 on pages 2 and 3 identifies which trees are recommended for removal and preservation. Importantly, two trees on private neighbouring property to the southeast are proposed for removal. This is a result of significant increases in grade necessary for the proposed parking areas. Permission from the adjacent landowner is included on page 10 of this report.

TREE SPECIES, CONDITION, SIZE AND STATUS

Table 1 below details the species, condition, size (diameter) and status of the individual and groups of trees on the subject and adjacent private property. Each of these trees is referenced by the numbers plotted on the tree conservation plan on page 5 of this report.

Table 1. Species, condition, size (diameter) and status of trees at 2026 Carp Road

Table 1	. Species, condition	,	nameter)	and status of trees at 2026 Carp Road		
Tree	Tree Species	DBH ¹	Owner	Condition, Age Class, Tree Condition Notes,		
No.		(cm)	-ship ²	Species Origin & Status (to be removed or		
				preserved and protected)		
1	Manitoba maple	38	Shared	Poor; mature; tri-stemmed from grade - divergent,		
	(Acer negundo)	avg.	with	broad crown; north stem bifurcates at 1.5m; north		
			City	and south stems pruned back by Hydro; nesting		
			lands	cavities and decay in old pruning wounds; heavy salt		
				spray damage to lower and mid-crown; naturalized		
				species; to be preserved and protected		
2	Manitoba maple	37 (at	Private	Poor; mature; tri-stemmed at 1.5-1.75m – divergent		
	(Acer negundo)	1m)		and asymmetric towards north and east due to		
				influence of tree #1 and clearance pruning from		
				Hydro lines; heavy salt spray damage to lower and		
				mid-crown; naturalized species; to be preserved		
				and protected		
3	Manitoba maple	+/-15	Shared	Fair; immature; double-stemmed at grade – both		
	(Acer negundo)		with	divergent towards south/southeast; naturalized		
			neigh-	species; to be preserved and protected		
			bour			
4	White cedar	+/-25	Shared	Fair; mature; divergent towards southeast; fair		
	(Thuja		with	crown density, growth increment and needle colour;		
	occidentalis)		neigh-	native species; to be preserved and protected		
			bour			
5	Manitoba maple	+/-50	Neigh-	Fair; mature; double stemmed from grade; third		
	(Acer negundo)		bour	stem previously removed; strongly divergent		
				towards southeast; naturalized species; to be		
				preserved and protected		
6	White cedar	+/-40	Neigh-	Fair; mature; upright form; crown asymmetric		
	(Thuja		bour	east/northeast due to influence of tree #8; living		
	occidentalis)			crown held in upper half; fair crown density, growth		
				increment and needle colour; native species; to be		
				removed (CRZ conflicts with proposed retaining		
				wall)		



Table 1. Con't

Tree	Tree species	DBH ¹	Owner	Condition, Age Class, Tree Condition Notes,	
No.		(cm)	-ship ²	Species Origin & Status (to be removed or	
				preserved and protected)	
7	White cedar	+/-50	Neigh-	Fair; mature; form mildly divergent towards	
	(Thuja		bour	southeast; crown asymmetric south/southwest due to	
	occidentalis)			influence of tree #7; living crown held to within 3m	
				of grade; fair crown density, growth increment and	
				needle colour; native species; to be removed (CRZ	
				conflicts with proposed retaining wall)	
8	Bur oak	23	Shared	Good; mature; upright form; basal cavity; wound on	
	(Quercus		with	bole at 1.5m on north is healing; native species; to	
	macrocarpa)		neigh-	be preserved and protected (will survive even	
			bour	though CRZ conflicts with increased grade)	
9	Manitoba maple	10-24	Private	Fair-good; immature to maturing; cluster of	
	(Acer negundo)	coppicing stumps and maturi		coppicing stumps and maturing trees; all originated	
				from seed; naturalized species; to be removed	
				(conflicts with construction)	
10 Manitoba map		19 &	Private	Poor; mature; two remaining stump sprouts (four	
	(Acer negundo)	19		others previously removed); both pruned back by	
				Hydro; naturalized species; to be removed (poor	
				condition & conflicts with proposed parking)	

¹ diameter at breast height, or 1.4m from grade (unless otherwise indicated); average diameters indicate multistemmed trees; ²As determined from locations plotted on topographic survey

Pictures 1 through 4 on pages 7, 8 and 9 of this report show selected trees on and adjacent to the subject property.

FEDERAL AND PROVINCIAL REGULATIONS

Federal and provincial regulations can be applicable to trees on private and public property. In particular, the following regulation has been considered for this property:

- 1) Endangered Species Act (2007): No butternuts (*Juglans cinerea*) were identified on the subject or adjacent properties. This species of tree is listed as threatened under the Province of Ontario's Endangered Species Act (2007) and so is protected from harm.
- 2) <u>Migratory Bird Convention Act (1994)</u>: In the period between April and August of each year nest surveys are required to be performed by a suitably trained person no more than five (5) days before trees or other similar nesting habitat are to be removed.

TREE PRESERVATION MEASURES

As excavation occurs within close proximity to a number of trees, the following measures will be taken:

- 1. Hydro excavation along the edge of excavation in proximity to the trees so as to carefully expose roots. Exposed roots will then be cleanly cut and sealed before being reburied. Excavation can then resume using traditional mechanical means. Sealing the cleanly cut root ends with a beeswax product will help prevent the loss of moisture and facilitate healing.
- 2. If the excavation is to be left open for any time a covering of at least three layers of moistened burlap is to be draped over the exposed face of excavation closet to the tree. This will help reduce the loss of soil moisture (as soil dries the roots contained within die).

TREE PROTECTION MEASURES

Preservation and protection measures intended to mitigate damage during construction will be applied for the trees to be retained on and adjacent to the subject property. The following measures are the minimum required by the City of Ottawa to ensure tree survival during and following construction:

- 1. As per the City of Ottawa's tree protection barrier specification (included on page 6), erect a fence as close as possible to the CRZ of the trees.
- 2. Do not place any material or equipment within the CRZ of the tree(s).
- 3. Do not attach any signs, notices or posters to any tree.
- 4. Do not raise or lower the existing grade within the CRZ without approval.
- 5. Tunnel or bore instead of trenching within the CRZ of any tree.
- 6. Do not damage the root system, trunk or branches of any tree.
- 7. Ensure that exhaust fumes from all equipment are NOT directed towards any tree's canopy.
 - ¹ critical root zone (CRZ) is established as being 10 centimetres from the trunk of a tree for every centimetre of DBH. The CRZ is calculated as DBH x 10 cm.

This report is subject to the attached Limitations of Tree Assessments and Liability to which the reader's attention is directed.

Please do not hesitate to contact me with any questions concerning this report.


Yours,


Andrew K. Boyd, B.Sc.F, R.P.F. (#1828)

Certified Arborist #ON-0496A and TRAQualified

Consulting Urban Forester







TREE PROTECTION REQUIREMENTS:

- PRIOR TO ANY WORK ACTIVITY WITHIN THE CRITICAL ROOT ZONE (CRZ = 10 X DIAMETER) OF A TREE, TREE PROTECTION FENCING MUST BE INSTALLED SURROUNDING THE CRITICAL ROOT ZONE, AND REMAIN IN PLACE UNTIL THE WORK IS COMPLETE.
- 2. UNLESS PLANS ARE APPROVED BY CITY FORESTRY STAFF, FOR WORK WITHIN THE CRZ:
 - DO NOT PLACE ANY MATERIAL OR EQUIPMENT INCLUDING OUTHOUSES;
 - DO NOT ATTACH ANY SIGNS, NOTICES OR POSTERS TO ANY TREE;
 - DO NOT RAISE OR LOWER THE EXISTING GRADE;
 - TUNNEL OR BORE WHEN DIGGING;
 - DO NOT DAMAGE THE ROOT SYSTEM, TRUNK, OR BRANCHES OR ANY TREE:
 - ENSURE THAT EXHAUST FUMES FROM ALL EQUIPMENT ARE NOT DIRECTED TOWARD ANY TREE CANOPY.
 - DO NOT EXTEND HARD SURFACE OR SIGNIFICANTLY CHANGE LANDSCAPING
- 3. TREE PROTECTION FENCING MUST BE AT LEAST 1.2M IN HEIGHT, AND CONSTRUCTED OF RIGID OR FRAMED MATERIALS (E.G. MODULOC STEEL, PLYWOOD HOARDING, OR SNOW FENCE ON A 2"X4" WOOD FRAME) WITH POSTS 2.4M APART, SUCH THAT THE FENCE LOCATION CANNOT BE ALTERED. ALL SUPPORTS AND BRACING MUST BE PLACED OUTSIDE OF THE CRZ, AND INSTALLATION MUST MINIMISE DAMAGE TO EXISTING ROOTS. (SEE DETAIL)
- 4. THE LOCATION OF THE TREE PROTECTION FENCING MUST BE DETERMINED BY AN ARBORIST AND DETAILED ON ANY ASSOCIATED PLANS FOR THE SITE (E.G. TREE CONSERVATION REPORT, TREE INFORMATION REPORT, ETC). THE PLAN AND CONSTRUCTED FENCING MUST BE APPROVED BY CITY FORESTRY STAFF PRIOR TO THE COMMENCEMENT OF WORK.
- 5. IF THE FENCED TREE PROTECTION AREA MUST BE REDUCED TO FACILITATE CONSTRUCTION, MITIGATION MEASURES MUST BE PRESCRIBED BY AN ARBORIST AND APPROVED BY CITY FORESTRY STAFF. THESE MAY INCLUDE THE PLACEMENT OF PLYWOOD, WOOD CHIPS, OR STEEL PLATING OVER THE ROOTS FOR PROTECTION OR THE PROPER PRUNING AND CARE OF ROOTS WHERE ENCOUNTERED.

THE CITY'S TREE PROTECTION BY-LAW, 2020-340 PROTECTS BOTH CITY-OWNED TREES, CITY-WIDE, AND PRIVATELY-OWNED TREES WITHIN THE URBAN AREA. PLEASE REFER TO WWW.OTTAWA.CA/TREEBYLAW FOR MORE INFORMATION ON HOW THE TREE BY-LAW APPLIES.

ACCESSIBLE FORMATS AND COMMUNICATION SUPPORTS ARE AVAILABLE, UPON REQUEST



TREE PROTECTION SPECIFICATION

TO BE IMPLEMENTED FOR RETAINED TREES, BOTH ON SITE AND ON ADJACENT SITES, PRIOR TO ANY TREE REMOVAL OR SITE WORKS AND MAINTAINED FOR THE DURATION OF WORK ACTIVITIES ON SITE.

SCALE: NTS

DATE: MARCH 2021

DRAWING NO.: 1 of 1



Picture 1. Trees #1 and 2 (left to right) at 2026 Carp Road



Picture 2. Tree grouping #9 at 2026 Carp Road



Picture 3. Trees #6 and 7 white cedars (centre) and 8 bur oak (right) at 2026 Carp Road





Picture 4. Tree #10 at 2026 Carp Road





Declaration of Boundary Tree Co-owner

Declaration		
1_ PARMINDER DHILLON	_, the property owner (s) / authorized	
representative(s) of the proprety owner(s) at 2022 CARP		hereby acknowledge
that an Application for Tree Permit is being submitted to the City of Ottaw	a pursuant to the Tre	e Protection By-law No. 2020-
340 by the owner(s) of 2026 CARPROAD, OTTAWA	(the "Applicant")	
I declare that I am the co-owner of the TREE # 7 8 8 CET	DARS	tree of
size 40 50 cm DBH (the "Boundary Tree"). I have read and understand	nd the required proc	edures and provisions under the
City of Ottawa's Tree Protection By-law and I consent to the intention	ns respecting the p	roposed work for which this
Application for Tree Removal Permit is being made and that the statement	nts made in this app	lication are, to the best of my
knowledge, true and complete.		
Certify that I am the legal owner(s) / authorized representative(s) of the Tree listed above is located.	he legal owner(s) of	the property where the Boundary
I am the co-owner of the Boundary Tree that is the subject of the appl and I have read and agreed to the terms of this application.		
Personal information on this form is collected under the authority of sand will be used for the administration and enforcement of Tree Protesthis collection should be directed to 311.		
The City is subject to the Municipal Freedom of Information and Prote ("MFIPPA") with respect to, and protection of, information under its cuprovided to the City by the Applicant pursuant to this application, including unless the Party submitting the information requests that it be MFIPPA and may be subject to release under MFIPPA, notwithstanding confidential.	ustody and control. luding this Declarat treated as confiden	Accordingly, all documents ion, may be available to the tial. All information is subject to
I understand and acknowledge that a permit may be issued Protection By-law No. 2020-340, as amended, to allow for the further understand and agree that the removal of a tree unapplication is done at the owner's risk, and that the City of Cremoval and/or any residual effects of the removal.	nder any permit	issued pursuant to this
gnature of Boundary Tree Co-owner		
dress: 2022 CARP RD		

LIMITATIONS OF TREE ASSESSMENTS & LIABILITY

GENERAL

It is the policy of *IFS Associates Inc.* to attach the following clause regarding limitations. We do this to ensure that our clients are clearly aware of what is technically and professionally realistic in assessing trees for retention.

This report was carried out by *IFS Associates Inc.* at the request of the client. The information, interpretation and analysis expressed in this report are for the sole benefit and exclusive use of the client. Possession of this report or a copy thereof does not imply right of publication or use for any purpose by any other than the client to whom it is addressed. Unless otherwise required by law, neither all or any part of the contents of this report, nor copy thereof, shall be conveyed by anyone, including the client, to the public through public relations, news or other media, without the prior expressly written consent of the author, and especially as to value conclusions, identity of the author, or any reference to any professional society or institute or to any initialed designation conferred upon the author as stated in his qualifications.

This report and any values expressed herein represent the opinion of the author; his fee is in no way contingent upon the reporting of a specified value, a stipulated result, nor upon any finding to be reported. Details obtained from photographs, sketches, *etc.*, are intended as visual aids and are not to scale. They should not be construed as engineering reports or surveys. Although every effort has been made to ensure that this assessment is reasonably accurate, the tree(s) should be reassessed at least annually. The assessment presented in this report is valid at the time of the inspection only. The loss or alteration of any part of this report invalidates the entire report.

LIMITATIONS

The information contained in this report covers only the tree(s) in question and no others. It reflects the condition of the assessed tree(s) at the time of inspection and was limited to a visual examination of the accessible portions only. *IFS Associates Inc.* has prepared this report in a manner consistent with that level of care and skill ordinarily exercised by members of the forestry and arboricultural professions, subject to the time limits and physical constraints applicable to this report. The assessment of the tree(s) presented in this report has been made using accepted arboricultural techniques. These include a visual examination of the above-ground portions of each tree for structural defects, scars, cracks, cavities, external indications of decay such as fungal fruiting bodies, evidence of insect infestations, discoloured foliage, the condition of any visible root structures, the degree and direction of lean (if any), the general condition of the tree(s) and the surrounding site, and the proximity of people and property. Except where specifically noted in the report, the tree(s) examined were not dissected, cored, probed or climbed to gain further evidence of their structural condition. Also, unless otherwise noted, no detailed root collar examinations involving excavation were undertaken.

While reasonable efforts have been made to ensure that the tree(s) proposed for retention are healthy, no warranty or guarantee, expressed or implied, are offered that these trees, or any parts of them, will remain standing. This includes other trees on or off the property not

examined as part of this assignment. It is both professionally and practically impossible to predict with absolute certainty the behaviour of any single tree or groups of trees or their component parts in all circumstances, especially when within construction zones. Inevitably, a standing tree will always pose some risk. Most trees have the potential for failure in the event of root loss due to excavation and other construction-related impacts. This risk can only be eliminated through full tree removal.

Notwithstanding the recommendations and conclusions made in this report, it must be realized that trees are living organisms, and their health and vigour constantly change over time. They are not immune to changes in site conditions, or seasonal variations in the weather. It is a condition of this report that *IFS Associates Inc.* be notified of any changes in tree condition and be provided an opportunity to review or revise the recommendations within this report. Recognition of changes to a tree's condition requires expertise and extensive experience. It is recommended that *IFS Associates Inc.* be employed to re-inspect the tree(s) with sufficient frequency to detect if conditions have changed significantly.

ASSUMPTIONS

Statements made to *IFS Associates Inc*. in regards to the condition, history and location of the tree(s) are assumed to be correct. Unless indicated otherwise, all trees under investigation in this report are assumed to be on the client's property. A recent survey prepared by a Licensed Ontario Land Surveyor showing all relevant trees, both on and adjacent to the subject property, will be provided prior to the start of field work. The final version of the grading plan for the project will be provided prior to completion of the report. Any further changes to this plan invalidate the report on which it is based. *IFS Associates Inc*. must be provided the opportunity to revise the report in relation to any significant changes to the grading plan. The procurement of said survey and grading plan, and the costs associated with them both, are the responsibility of the client, not *IFS Associates Inc*.

LIABILITY

Without limiting the foregoing, no liability is assumed by *IFS Associates Inc*. for: 1) any legal description provided with respect to the property; 2) issues of title and/or ownership with respect to the property; 3) the accuracy of the property line locations or boundaries with respect to the property; 4) the accuracy of any other information provided by the client or third parties; 5) any consequential loss, injury or damages suffered by the client or any third parties, including but not limited to replacement costs, loss of use, earnings and business interruption; and, 6) the unauthorized distribution of the report.

INDEMNIFICATION

An applicant for a permit or other approval based on this report shall agree to indemnify and save harmless *IFS Associates Inc.* from any and all claims, demands, causes of action, losses, costs or damages that affected private landowners and/or the City of Ottawa may suffer, incur or be liable for resulting from the issuance of a permit or approval based on this report or from the performance or non-performance of the applicant, whether with or without negligence on the part of the applicant, or the applicant's employees, directors, contractors and agents.

Further, under no circumstances may any claims be initiated or commenced by the applicant against *IFS Associates Inc.* or any of its directors, officers, employees, contractors, agents or assessors, in contract or in tort, more than 12 months after the date of this report.

ONGOING SERVICES

IFS Associates Inc. accepts no responsibility for the implementation of any or all parts of the report, unless specifically requested to supervise the implementation or examine the results of activates recommended herein. In the event that examination or supervision is requested, that request shall be made in writing and the details, including fees, agreed to in advance.

12