

No.	Botanical Name	Common Name	DBH (cm)	CRZ (m)	Condition	Remarks	Recomm.
1	Thuja occidentalis (hedge)	Hedge of Eastern White Cedar	Avg 14	-	G	On property line.	Remove
2	Prunus ssp	Cherry species	16.0	1.60	G	On adjacent property.	PROTECT
3	Fraxinus ssp	Ash species	14.0	1.40	VP	Dead or nearly dead. On adjacent property/property line.	Remove
4	Fraxinus ssp	Ash species	10.0	1.00	Р	On adjacent property/property line.	Remove
5	Acer negundo	Manitoba Maple	10.0	1.00	G	On adjacent property/property line.	Remove
6	Ulmus ssp	Elm species	13.0	1.30	G	On adjacent property/property line.	Remove
7	Robinia pseudoacacia	Black Locust	12.0	1.20	G	Considered invasive species. On adjacent property/property line.	Remove
8	Robinia pseudoacacia	Black Locust	14.0	1.40	Р	Considered invasive species. On adjacent property/property line. Growing into/around chain link fence.	Remove
9	Acer platanoides	Norway Maple	22.0	2.20	G	On adjacent property.	PROTECT
10	Acer platanoides	Norway Maple	14.0	1.40	G	On adjacent property.	PROTECT
11	Thuja occidentalis	Eastern White Cedar	14.0	1.40	G	On adjacent property.	PROTECT
12	Ulmus ssp	Elm species	38.0	3.80	Р	On adjacent property.	PROTECT
13	Acer platanoides	Norway Maple	48.0	4.80	G	On adjacent property.	PROTECT
Lege							
F	Fair	Remove	Remove du	e to tree he	ealth, invasi	ve status or conflict with construction.	
Ρ	Poor	PROTECT	Protect as	per detail [01 and relat	ed notes.	
VP	Very Poor						

F	Fair	Remove	Remove due to tree health, invasive status or conflict with construction.				
Ρ	Poor	PROTECT	Protect as per detail D1 and related notes.				
VP	Very Poor						