



June 6, 2023

Ref. No.: 23-215-1

SINA
3030 Boul Le Carrefour, Suite 1200
Laval, Quebec
H7T 2P5

Attn: Mohamed El-Koury, ing.

RE: Geotechnical Report Reliance Letter – 788 March Road, Ottawa, Ontario

Dear Mr. El-Koury:

As discussed, SINA can rely on the Geotechnical Investigation report prepared by Geofirma Engineering Ltd. for 10731854 Canada Inc. on the property at 788 March Road, Ottawa, Ontario. The report in question is entitled: "Geotechnical Investigation Report, 788 March Road, Kanata (Ottawa), Ontario, Revision: 4" and is dated October 29, 2020.

The report can be relied upon concerning geotechnical conditions at the site at the time of the investigations. Ground surface conditions have been altered since the geotechnical investigation with the initiation of construction activities, namely site preparation and excavation of the building footprint. The geotechnical properties of undisturbed areas of the site remain unchanged. The limitations of liability described in the report are extended to SINA.

If you have any questions regarding the information presented in the report, please do not hesitate to contact the undersigned.

Sincerely,

Glen Briscoe, P. Eng.
Principal

