

Surveyed by Annis, O'Sullivan, Vollebek Ltd.

Surveyor's Certificate

I CERTIFY THAT:

1. This survey and plan are correct and in accordance with the Surveyors Act and the Surveyors Act and the regulations made under them.
2. The survey was completed on the 31st day of May, 2021.

Notes & Legend

—○— Decade

Survey Monument (Pierced)
 Standard (10' Round)
 Standard (10' Bar)
 Short Standard (10' Bar)
 Iron Bar
 Pin
 Whitties
 (Wt.)
 Applied
 (ACQ) Piece of Survey dated September 17

Deciduous Tree
 Coniferous Tree
 Shrub
 Fire Hydrant
 Water Valve
 Manhole
 Maintenance Hole (Storm Sewer)
 Maintenance Hole (Sanitary)
 Maintenance Hole (Underground)
 Overhead Wire (Watermain)
 Overhead Wire (Sewer)
 Catch Basin
 Manhole
 Monitoring Pipe
 Vent Pipe
 Gas Meter
 Hydro-Meter
 Handhole
 Underdrain
 Ballast
 Hydraulic Terminal Box
 Ballast
 Hydro Transformer
 Lowest Wire
 Concrete Block Retaining Wall
 Edge of Asphalt
 Edge of Asphalt
 Top of Grade
 Top of Pipe
 Foundation
 Deciduous Hedge
 Plastic Fences
 Chain Link Fence
 Board Fence
 Gate
 Wood Pole
 Utility Pole
 Anchor
 Light Standard
 Mail Box
 Air Conditioner
 Diameter
 Location of Elevation
 Top of Wall Elevation
 Contour

For comparison purposes, bearings on plans P3 and P7 have been

ELEVATION NOTES

© Annis, O'Sullivan, Vollebæk Ltd. 2021. THIS PLAN IS PROTECTED BY COPYRIGHT.

