



## NOTES


- 1. OBSTACLES SUCH AS TREES, HYDRO POLES, AND THE IMPACTS/PROVISIONS TO POTENTIAL GAS SERVICES AND OTHER EXISTING UTITLITIES ARE TO BE CIRCULATED TO STANTEC FOR REVIEW AND RESOLUTION.
- 2. 8NO. ROOF DRAINAGE PIPES PROTRUDING FROM BUILDING 3C ON SOUTH SIDE OF ALLEY TO BE RE-ROUTED AWAY FROM ALLEY AND SIDEWALK.
- 3. THE SURFACE BETWEEN BUILDINGS NO. 3A AND 3B AND THE ROADWAY IN THE NORTH AND SURFACE BETWEEN BUILDING NO. 3C AND SIDEWALK IN THE SOUTH TO BE DETERMINED BY THE LANDSCAPING PLANNER.
- THERE ARE THREE (3) TREES IN FRONT OF 2750 SHEFFIELD ROAD THAT WOULD REMAIN, HOWEVER, DURING THE SUMMER MONTHS, THE FOLIAGE ON THESE TREES COULD OBSCURE THE 150M LONG SIGHT LINE OF A HEAVY VEHICLE LEAVING THE ALLEY ACCESS LOOKING TO THE NORTH AND ATTEMPTING TO TURN ONTO SHEFFIELD ROAD. IF THIS IS THE CASE, THE REMAINING TREES SHOULD BE TRIMMED TO ASSURE NO OBSTRUCTION OF THE SIGHT LINE.








## <u>NOTES</u>


- 1. OBSTACLES SUCH AS TREES, HYDRO POLES, AND THE IMPACTS/PROVISIONS TO POTENTIAL GAS SERVICES AND OTHER EXISTING UTITLITIES ARE TO BE CIRCULATED TO STANTEC FOR REVIEW AND RESOLUTION.
- 2. 8NO. ROOF DRAINAGE PIPES PROTRUDING FROM BUILDING 3C ON SOUTH SIDE OF ALLEY TO BE RE-ROUTED AWAY FROM ALLEY AND SIDEWALK.
- 3. THE SURFACE BETWEEN BUILDINGS NO. 3A AND 3B AND THE ROADWAY IN THE NORTH AND SURFACE BETWEEN BUILDING NO. 3C AND SIDEWALK IN THE SOUTH TO BE DETERMINED BY THE LANDSCAPING PLANNER.











## **NOTES**

