

PART OF LOT 307

Surveyed by Annis, O'Sullivan, Vollebekk Ltd.



ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 05-11-2010 BY 60322 UCBAW/DK/STP

1. This Summary and plan are correct and in accordance with the Summary

1. This survey and part of the context are in accordance with the Surveyors Act, the Surveyors Act and the regulations made under them.
2. The survey was completed on the 14th day of May, 2025.

Date 1-1-68 E. H. Herweyer

Denotes

	Survey Monument Pin
	Survey Monument Found
	Standard Iron Bar
	Short Standard Iron Bar
	Iron Bar
	Wireless
	Wired
	Arctic Ordnance, Volskoye, Ltd.
	Registered Plan, 372212
	Plan, 55-5078
	Plan, 55-6695
	Plan, 45-9155
	(467) Plan, December 30, 1880
	(ACG) Plan, February 20, 1889
	(ACG) Plan, February 20, 1889 Plan, 45-24794
	Chow - Carlton Standard Condominium Plan No. 657
	(ACG) Plan, Notes July 6, 1984 (Ref. 372216-12)
	Maintenance Hole (S&B Sewer)
	Maintenance Hole (S&B Sewer)
	Maintenance Hole (Water)
	Water Chamber (Waterman)
	Fire Hydrant
	Water Valve
	Lulley Pole
	Anchor
	Light Standard
	Catch Basin
	Top of Crate
	Gas Meter
	Hydro Meter
	Bell Terminal Box
	Cable Terminal Box
	Sewer
	Chain Link Fence
	Concrete Retaining Wall
	Stone Retaining Wall
	Diameter
	Location of Elevations
	Top of Cut/ Wall Elevation
	C/L
	Elevation
	Elev.
	Deciduous Tree
	Coniferous Tree
	Shrub

1. Elevations shown are geodetic, derived from Ottawa LRT Control Monument

2. It is the responsibility of the user of this information to verify that the job benchmark has not been altered or disrupted and that its relative elevation and description agrees with the information shown on this drawing.

1. This drawing cannot

2. Only visible surface utilities were located;
3. A field location of underground plant by the pertinent utility authority is mandatory before any work involving breaking around or trench excavating etc.

PLAN SUBMISSION FORM

THIS PLAN IS NOT VALID IN INDIA

Regulation 1020, Section 29 (c).

500
5