patersongroup

Consulting Engineers

154 Colonnade Road South Ottawa, Ontario Canada, K2E 7J5 Tel: (613) 226-7381 Fax: (613) 226-6344

> Geotechnical Engineering Environmental Engineering Hydrogeology Geological Engineering Materials Testing Building Science Archaeological Studies

www.patersongroup.ca

November 20, 2018 File: PE4490-LET.01

Richcraft Group of Companies 210-2280 St. Laurent Boulevard Ottawa, Ontario, K1G 4K1

Attention: Mr. Kevin Yemm

Subject: Phase I - Environmental Site Assessment Update 3194 Jockvale Road Ottawa, Ontario

Dear Sir,

Further to your request, Paterson Group (Paterson) conducted a Phase I - Environmental Site Assessment (ESA) Update for the aforementioned property. This report updates the Phase I ESA report entitled: "Phase I-Environmental Site Assessment, Proposed Commercial Development, 3194 Jockvale Road, Ottawa, Ontario," prepared by Paterson in March 2012.

This report is intended to meet the requirements for an updated Phase I ESA, as per the MECP O.Reg 153/04, as amended. This report is to be read in conjunction with the 2012 report.

Background

The Phase I Property is located in a Mixed-Use Centre and Development Reserve zone, located on the west side of Greenbank Road, northwest of the Greenbank Road and Jockvale Road intersection, in the City of Ottawa, Ontario. The subject site was occupied by a farmstead prior to 1954, which was then demolished in 2008/2009. The site has remained vacant.

The original Phase I-ESA for the subject site had identified three (3) minor potential concerns on the Phase I property, which included imported fill material, impact from possible pesticide use, possible leakage of a former domestic aboveground storage tank (AST) and an occurrence report provided by the MECP indicating an onsite spill in 1997

Mr. Kevin Yemm Page 2 File: PE4490-LET.01

that was reported to have been remediated at that time. A geotechnical investigation and limited sampling program were concurrently conducted onsite. Based on the findings of the subsurface investigations, no evidence of impacted fill or contamination as a result of the noted potential concerns was identified. No further investigative work (i.e. Phase II-ESA) was recommended at that time.

Site Conditions

A site visit was conducted on November 16, 2018. No changes were noted since the 2012 Phase I-ESA. The subject site is currently vacant with some trees on the northeast section of the property. Fill material was observed on the northeastern portion of the property, which is most likely from previous grading activities reported in the original Phase I-ESA report. No environmental concerns were identified during the site visit.

Site drainage consists primarily of infiltration. No discoloured snow/vegetation was observed on the property. No private sewage systems or wells were observed on the subject property. No evidence of current or former railway or spur lines on the subject property was observed at the time of the site inspection.

The site is below the grade of Jockvale Road and slopes downwards towards the south. The regional topography also slopes downwards towards the south in the direction of the Jock River, approximately 610 m south from the subject site. No changes to the land use of the surrounding properties were observed during the site visit. The configuration of the subject site is shown on Drawing PE4490-1– Site Plan, which is appended to this report.

Updated Records Review

A request was submitted on November 16, 2018 to the MECP Freedom of Information (FOI) office for information with respect to certificates of approval, permits to take water, certificates of property use or any other similar MECP issued instruments for the site. A response from the MECP had not been received at the time this report was issued. Any pertinent information will be forwarded to the client upon receipt. A copy of the request form has been appended to this report.

A requisition form was sent to the City of Ottawa to request information from the City's Historical Land Use Inventory (HLUI 2005) database as part of the 2012 Phase I-ESA for the subject property. The City's HLUI 2005 database has not been updated since issuing the original Phase I-ESA report; therefore, an additional HLUI request was not submitted for this Phase I-ESA Update. The HLUI search results from the 2005 database have been appended to this report.

Mr. Kevin Yemm Page 3 File: PE4490-LET.01

The TSSA, Fuels Safety Branch in Toronto was contacted electronically on November 16, 2018 to inquire about current and former underground storage tanks, spills and incidents for the site and neighbouring properties. No records of an underground storage tank, spills or incidents were listed in the TSSA registry for the subject site or the adjacent properties. A copy of the TSSA correspondence has been appended to this report.

The latest aerial photograph reviewed at the time of the 2012 Phase I ESA was dated 2008 (GeoOttawa website). A review of an aerial photograph for 2017 shows the site as vacant Inad. No significant changes were noted with regard to the surrounding properties within the Phase I study area since the 2008 aerial photograph, with the exception of some additional commercial development north / northwest of the subject site, what appears to be a retail fuel outlet (RFO) and a commercial/retail building.

The adjacent properties to the north and east of the subject site were occupied by commercial retail stores and a retail fuel outlet (RFO), and Greenbank Road, followed by more commercial retail stores. Adjacent properties to the south and east were vacant lands. Based on relatively recent development, approximately in 2009, the RFO located at 3775 Standherd Drive (approximately 160 m north) is not considered to pose a risk to the subject site.

No other PCAs were identified with regard to the current use of the neighbouring lands.

Update Conceptual Site Model

Based on the above noted records and the site visit, no significant changes were apparent on the subject site or surrounding lands. The surrounding lands to the south and southeast are comprised of agricultural fields and/or vacant lands, lands to the west are a Municipal Stormwater Facility, and the lands to the north and east are comprised of commercial retail businesses along Strandherd Drive. No other PCAs were identified in the study area that are considered to represent APECs for this Phase I-ESA property. Based on our findings, a Phase II-ESA is not required for the subject site.

Statement of Limitations

This Phase I - Environmental Site Assessment Update report has been prepared in general accordance with Ontario Regulation 153/04, as amended under the Environmental Protection Act. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I - ESA Update are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment.

Mr. Kevin Yemm Page 4 File: PE4490-LET.01

Should any conditions be encountered at the subject site and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Richcraft Group of Companies. Permission and notification from the above noted party and Paterson will be required to release this report to any other party.

We trust that this submission satisfies your current requirements. Should you have any questions please contact the undersigned.

Paterson Group Inc.

Mandy Witteman, M.A.Sc.

12

Mark D'Arcy, P.Eng.

Report Distribution:

- Richcraft Group of Companies
- Paterson Group

Appendix:

- MECP FOI Request
- TSSA Correspondence
- City of Ottawa HLUI Report
- □ Figure 1 Key Plan
- Drawing PE4490-1– Site Plan





Ministry of Environment and Energy

Freedom of Information Request

This form is for requesting documents which are in the Ministry's files on environmental concerns related to properties. Please refer to the guide on completion and use of this form. Our fax no. is (416) 314-4285.

Requester Data			For Ministry Use Only			
Name, Company Name, Mailing Address and	Email Address of Requester		FOI Request No.	Date Request Received		
Mandy Witteman Paterson Group Inc.			T OF REQUEST NO.			
154 Colonnade Road			Fee Paid			
Ottawa, ON K2E 7J5				UISA/MC 🗆 CASH		
Email address: mwitteman@	patersongroup.ca	Marina				
Telephone/Fax Nos.	Your Project/Reference No.					
Tel. 613-226-7381 Fax 613-226-6344	PE4490	Mandy Witteman				
		Request Parameters				
Municipal Address / Lot, Concession, Geog	raphic Township (Municipal	address essential for cities, towns or regio		5. 5.11W		
3294 Jockvale Road, Ottawa O	ntario					
Present Property Owner(s) and Date(s) of Own	nership					
Richcraft Group of		1000 pt - 4 d - 8 - 4 - 10 - 10 - 10 - 10 - 10 - 10 - 10				
Previous Property Owner(s) and Date(s) of Ow	mership					
Unknown Present/Previous Tenant(s).(if applicable)						
Unknown						
		rch Parameters				
Files older than 2 years may require	Files older than 2 years may require \$60.00 retrieval cost. There is no guarantee that records responsive to your request will be located.					
Environmental concerns (General correspondence, occurrence reports, abatement) all						
Orders all						
Spills				ail		
Investigations/prosecutions	► Owner AND tena	nt information must be provided	1 - 1 - M - 10	ali		
Waste Generator number/cla	all					
	Certificates	s of Approval > Proponent infor	mation must be provided			
1985 and prior records are sear Certificates of Approval number	ched manually. Search		incurred, depending on the typ	es and years to be searched. Specify		
oonnodes of tippiotal hands	(o) (a monity. It suppo	nung uocumenta are also required,				
			SD	Specify Year(s) Requested		
air - emissions				1986-present		
water - mains, treatment, ground I	level, standpipes & elevate	d storage, pumping stations (local & boos	er)	1986-present		
sewage - sanitary, storm, treatme	1986-present					
waste water - industrial discharg	1986-present					
waste sites - disposal, landfill site	es, transfer stations, proce	ssing sites, incineratosites		1986-present		
waste systems - PCB destruction	on, mobile waste processi	ng units, haulers: sewage, non-hazardou:	s & hazardous waste	1986-present		
pesticides - licenses \$5.00 non-refundable application fee, payable to the Minister of Finance, is mandatory. The cost of locating on-site and/or preparing any						

A \$5.00 non-refundable application fee, payable to the Minister of Finance, is mandatory. The cost of locating on-site and/or preparing any record is \$30.00/hour and 20 cents/page for photocopying and you will be contacted for approval for fees in excess of \$30.00.

Mandy Witteman

From:	Public Information Services <publicinformationservices@tssa.org></publicinformationservices@tssa.org>
Sent:	November-16-18 12:33 PM
To:	Mandy Witteman
Subject:	RE: Search records request (PE4490) - Record Fuels
Follow Up Flag:	Follow up
Flag Status:	Flagged

Hello,

I have searched the below noted address (addresses) and I have located the following record:

Inst Number	Context	Attribute 1	Attribute 2	Address	City	Province	Postal Code	Inventory Item Id SUM	Inststatus
33459198	FS Facility	-	-	3777 STRANDHERD RD	NEPEAN	ON	K2J 4B1	6872	Active
35434142	FS Facility	-	-	3779 STRANDHERD DR	BARRHAVEN	ON	K2J 5M4	6872	Active

Inst Number	Context	Attribute 1	Attribute 2	Address	City	Province	Postal Code	Inventory Item Id SUM	Inststatusname
48371046	FS Facility	-	-	3201 GREENBANK RD	OTTAWA	ON	K2J 4H9	6872	Active

Effective November 1, 2017 TSSA requires that any requests for the release of public information, must complete the release for public information form. The release for public information form can be found at https://www.tssa.org/en/about-tssa/release-of-public-information.aspx?_mid_=392. Please complete the form (1 address per form) and email the completed form to publicinformationservices@tssa.org or through mail along with a fee of \$56.50 (including HST) per location. The fee is payable with credit card (Visa or MasterCard) or with a Cheque made payable to TSSA.

Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Thank you,

Roxana



Roxana Mashtaler | Public Information Agent

Facilities 345 Carlingview Drive Toronto, Ontario M9W 6N9 Tel: +1-416-734-3472 | Fax: +1-416-231-6183 | E-Mail: <u>rmashtaler@tssa.org</u> www.tssa.org

From: Mandy Witteman <MWitteman@Patersongroup.ca>
Sent: November 16, 2018 9:49 AM
To: Public Information Services <publicinformationservices@tssa.org>
Subject: Search records request (PE4490)

Good Morning

Could you please complete a search of your records for **underground/aboveground storage tanks**, **historical spills or other incidents/infractions** for the following addresses in Ottawa, ON:

Strandherd Drive: 3777, 3779, Greenbank Rd: 3161, 3201, 3181 Jockvale Rd: 3194, 3232 Marketplace Ave: 51

Thank you!

Best Regards,

Mandy Witteman

patersongroup solution oriented engineering

154 Colonnade Road South Ottawa, Ontario, K2E 7J5 Tel: (613) 226-7381 Ext. 339 Fax: (613) 226-6344 Email: <u>mwitteman@patersongroup.ca</u>

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.



File Number: C10-01-12-0019

January 30, 2012

Karyn Munch Paterson Group Inc. 28 Concourse Gate, Unit 1 Nepean, ON K2E 7T7

Dear Ms. Munch,

Re: Information Request – File No.: PE2533 3194 Jockvale Road, Ottawa, Ontario ("Subject Property")

Internal Department Circulation

The Infrastructure Services and Community Sustainability Department has the following information in response to your request for information regarding the Subject Property:

- The Waste Diversion Branch notes that the Subject Property is within 5 km of 3 waste management facilities located at 4309 Trail Road, 4475 Trail Road, and 42960 Barnsdale Road.
- Legal Services notes that the Subject Property has a Site Plan Agreement between City of Ottawa and Barrhaven Town Centre Inc., Barrhaven Developments Inc., Mary N. Clarke and Gerald F. Clarke, dated January 29, 2004 and registered March 26, 2004 as Instrument No. OC312642. Reference is made to a Traffic Impact Study, dated February 10, 2003, prepared by Delcan Corporation. There are no environmental requirements in this Agreement.

Search of Historical Land Use Inventory

This acknowledges receipt of the signed Disclaimer regarding your request for information from the City's Historical Land Use Inventory (HLUI 2005) database for the Subject Property.

A search of the HLUI database revealed the following information:

• There are no activities associated with the Subject Property.

Shaping our future together Ensemble, formons notre avenir City of Ottawa Infrastructure Services and Community Sustainability Department Planning and Growth Management Branch

110 Lauriel Avenue West, 4th Floor Ottawa, ON K1P 1J1 Tel: (613) 580-2424 ext. 14743 Fax: (613) 560-6006 www.ottawa.ca Ville d'Ottawa Services d'infrastructure et Viabilité des collectivités Direction de l'approbation des demandes d'aménagement et d'infrastructure

110, avenue Laurier Ouest, 4e étage Ottawa (Ontario) K1P 1J1 Tél.: (613) 580-2424 ext. 14743 Téléc: (613) 560-5006 www.oitawa.ca The HLUI database was also searched for activity associated with properties located within 50m of the Subject Property. The following information was revealed:

• There are 6 activities associated with properties located within 50m of the Subject Property: Activity Number 11965, 13190, 13827, 8147, 9547 & 8737.

A site map has been included to show the location of the Subject Property as well as the location of all the activities noted above.

Please note, as per the HLUI Disclaimer, that the information contained in the HLUI database has been compiled from publicly available records and other sources of information. The HLUI may contain erroneous information given that the records used as sources of information may be flawed. For instance, changes in municipal addresses over time may introduce error. Accordingly, all information from the HLUI database is provided on an "as is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in responding to the request.

Furthermore, the HLUI database and the results of this search in no way confirm the presence or absence of contamination or pollution of any kind. This information is provided on the assumption that it will not be relied upon by any person for any purpose whatsoever. The City of Ottawa denies all liability to any persons attempting to rely on any information provided from the HLUI database.

Please note that in responding to your request, the City of Ottawa does not guarantee or comment on the environmental condition of the Subject Property. You may wish to contact the Ontario Ministry of Environment for additional information.

If you have any further questions or comments, please contact Dilys Huang at 613-580-2424 ext. 14743 or HLUI@ottawa.ca.

Sincerely,


HBunghteen

Michael J. Boughton, MCIP, RPP Acting Program Manager Development Review (Suburban Services) - West Infrastructure Services and Community Sustainability

MB/DH

Attach: 7

cc: File no. C10-01-12-0019





Run On:

Report:

RPTC_OT_DEV0122

27 Jan 2012 at: 10:09:24

Study Year 2005	PIN 0459	95005 6	Multi-NAIC N	Multiple Activities N
Activity ID:	8737	Multiple PINS:	N	
PIN Certainty:	1	Previous Activity	ID(s) :	
Related PINS:	045950056			
Name: Address:		ES HOME SERVICES E ROAD, JOCKVALE		
Facility Type: Comments 1: Comments 2:		ling and Development		
Generator Numbe	r:			
Storage Tanks: HL References 1: HL References 2: HL References 3:	2001 Employment	Survey		
NAICS S	SIC			
236110 0)			
Company Name	9		Year of Operat	tion
MASTERTRADES HOME SERVICES		c. 2001		



Report:

Run On:

RPTC_OT_DEV0122

27 Jan 2012 at: 10:08:45

Study Year 2005	PIN 0459	950052	Multi-NAIC Y	Multiple Activities
Activity ID:	11965	Multiple PINS:	Ν	
PIN Certainty:	1	Previous Activity	ID(s) :	
Related PINS:	045950052			
Name: Address:	RADIO SHACK 3777 STRANDH	ERD DRIVE, NEPEAN		
Facility Type: Comments 1: Comments 2:		vision, Radio and Stereo S	lores	
Generator Number Storage Tanks:				
HL References 1: HL References 2:				
HL References 3:	2001 Employment	Survey		
NAICS S	IC			
443110 0	I			
Company Name			Year of Opera	tion
RADIO SHACK			c. 2001	



Run On:

Report:

RPTC_OT_DEV0122

27 Jan 2012 at: 10:08:45

Study Year	PIN	Multi-NAIC	Multiple Activities
2005	045950052	Y	Y
	· · · · · · · · · · · · · · · · · · ·		

Activity ID:	13190	Multiple PINS:	N
PIN Certainty:	1	Previous Activity ID(s)	:
Related PINS:	045950052		
Name: Address: Facility Type: Comments 1: Comments 2: Generator Number Storage Tanks: HL References 1: HL References 3: HL References 3:	:	D DRIVE, NEPEAN ners	
NAICS	SIC		
812320	0		
Company Nam	e		Year of Operation
STAR FASHION CI	LEANERS		c. 2001



Study Year	PIN	Multi-NAIC	Multiple Activities
2005	045950052	Y	Y

Activity ID:	13827	Multiple PINS:	Ν
PIN Certainty:	1	Previous Activity ID(s) :	
Related PINS:	045950052		
Name: Address: Facility Type: Comments 1: Comments 2: Generator Number Storage Tanks: HL References 1:		DRIVE, NEPEAN	
HL References 2: HL References 3:	_	à	
	SIC 0		
Company Nam	e		Year of Operation
WESTEINIDE CON			c. 2001

RPTC_OT_DEV0122

27 Jan 2012 at: 10:08:45

Report: Run On:



Report:

Run On:

RPTC_OT_DEV0122 27 Jan 2012 at: 10:08:45


Study Year	PIN	Multi-NAIC	Multiple Activities
	045950052	Y	Y

Activity ID:	8147	Multiple PINS:	Ν
PIN Certainty:	1	Previous Activity ID	(s) :
Related PINS:	045950052		
Name: Address: Facility Type: Comments 1:	KAYLEN COMPUTE 3777 STRANDHERI Electrical and Electr	D DRIVE, NEPEAN	ent and Supplies, Wholesale
Comments 2: Generator Numb	per:		
Storage Tanks: HL References 1 HL References 2	-	<i>x</i> .	
HL References 3	: 2001 Employment Sur	vey	
NAICS	SIC		
443120	0		
Company Nam	ıe		Year of Operation
KAYLEN COMPUT	TERS INC.		c. 2001



FIGURE 1 KEY PLAN

patersongroup



	Scale:		Date:
		1:2500	11/2018
	Drawn by:		Report No.:
		MPG	PE4490-LET.01
ONTARIO	Checked by:		Dwg. No.:
		MW	PE4490-1
	Approved by:		F E 4430•1
		MSD	Revision No.: 0