



NOTES

1. TREES SURVEYED RANGE FROM GOOD TO DEAD. SEE SHEET TCR-3 FOR FULL TREE INVENTORY LIST.

770
SOMERSET ST W
TREE INVENTORY LIST

TREE INVENTORY						NOTES
TREE NUMBER	BOTANICAL NAME	COMMON NAME	DBH	HEALTH	ACTION	COMMENTS
1	<i>Acer negundo</i>	Manitoba Maple	3	Fair	Remove	broken branches
2	<i>Acer negundo</i>	Manitoba Maple	5	Fair	Remove	broken limb
3	<i>Euonymus</i>	Spindle tree	3	good	Remove	
4	<i>Populus tremuloides</i>	Trembling Aspen	9	poor	Remove	rotten root
5	<i>Acer negundo</i>	Manitoba Maple	8	poor	Remove	dead yellow leaves
6	<i>Acer negundo</i>	Manitoba Maple	6	poor	Remove	dead yellow leaves
7	<i>Acer negundo</i>	Manitoba Maple	3	Fair	Remove	broken branch
8	<i>Acer negundo</i>	Manitoba Maple	6	poor	Remove	dead
9	<i>Acer negundo</i>	Manitoba Maple	10	Fair	Remove	
10	<i>Acer negundo</i>	Manitoba Maple	3	Poor	Remove	chopped trunk
11	<i>Euonymus alatus</i>	Burning Bush	3	Fair	Remove	crooked leader
12	<i>Acer negundo</i>	Manitoba Maple	6	Good	Remove	
13	<i>Euonymus alatus</i>	Burning Bush	3	Good	Remove	



1	For Client Review	2017.09.19	KZ
No.	REVISION	DATE	BY

CLIENT
KATASA DEVELOPMENT

FOTENN
Planning + Design

223 McLeod Street, Ottawa ON K2P 0Z8
613.730.5709 www.fotenn.com

DESIGNED	KZ
REVIEWED	MS
DATE	2017.09.19

P3