PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



Project No.: CCO-21-0244

Prepared for:

Chris McCluskey 6 Edgewater Street Kanata, ON K2L 1V8

Prepared by:

McIntosh Perry Consulting Engineers Ltd. 115 Walgreen Road, RR3 Carp, ON K0A 1L0

Date: October 5, 2021

McIntosh Perry Consulting Engineers Ltd. (McIntosh Perry) was retained by Chris McCluskey of McCluskey Group to conduct a Phase One Environmental Site Assessment (ESA) updated for 16 Edgewater Street, Kanata, Ontario. The Site is bounded to the northwest by a commercial building 20 Edgewater Street, to the northeast by residential dwellings along Foulis Crescent and a multi-unit commercial building, to the southwest by Edgewater Street followed by Toromont CAT maintenance garage and storage yard and southeast by 6 Edgewater street, a commercial building containing a Tim Hortons and Wendy's followed by Hazelden Road. The property is currently a vacant lot covered in grass ("the Site"). The report is an update to McIntosh Perry's original Phase One ESA in December 2018. At that time, the property was a single property combined with 6 Edgewater Street. McIntosh Perry's original Phase One ESA was only for the vacant portion, now addressed as 16 Edgewater Street.

It is understood that this Phase One ESA is being completed as a component to redevelop the site with affordable housing. The last known uses of the property was commercial and the intended future use is residential housing. This represents a change to a more sensitive land use, and it is our understating that a Record of Site Condition (RSC) will be required prior to development of the residential housing.

The Phase One ESA has been prepared in general accordance with the requirements of Ontario Regulation (O.Reg.) 153/04 as amended. The report is also in general compliance with "Phase I Environmental Site Assessment", Canadian Standards Association (CSA) standard CSA Z768-01, reaffirmed 2016.

The Site is currently vacant. Based on a review of aerial photographs and historical information, the Site appears to have been agricultural land from 1932-1976. Between 1976 and 1983 the site was developed into a materials storage yard (Cashway Building Center). After 1996 the Site has been vacant.

Two PCAs were identified at, on, or under the Site (source).

- Former above ground fuel storage tanks (Previous Phase I and II ESA report)
- Cashway Building Center material storage yard (Ariel Photos and Interviews)

Three off-site PCAs were identified in the Phase One ESA Study Area (source).

- 5 Edgewater Street
 - Heavy equipment garage and storage yard (Site visit)
 - Former private fuel outlet with fuel storage tanks (ERIS report)
 - o Former trichloroethane leak/spill from tank (former Phase I and II ESA report)
- 501 Hazeldean Road
 - Former retail fuel outlet (aerial photos and ERIS Eco Log)
- 21 Young Road
 - Spill of heating oil (ERIS Eco Log)

The above noted on-site PCAs are considered to result in an APEC for the Site. Due to the limited information available for type of materials and operational procedures of the Cashway Building Centers stock yard, it is possible that the operations have had impacts to the soil and groundwater in the vicinity of the materials storage yard.

The above noted Off-site PCA are areas of environmental concern that have the possibility of impacting on-site soil and groundwater conditions. Based on the presence of on-site PCAs resulting in APECs, a Phase Two ESA is recommended at this time to assess whether the historical presence of the materials storage yard and off-site PCAs have impacted soil and groundwater quality at the Site.

McIntosh Perry completed a Phase Two ESA based on the above findings, which are the same as original Phase One ESA conclusions. The Phase Two ESA addressed the PCAs above. McIntosh Perry recommends resampling the wells to confirm the current groundwater conditions.

TABLE OF CONTENTS

1.0	INTRO	DUCTION	1
1.1	Pha	se One Property Information	1
1	1.1.1	Property Identification	1
1	1.1.2	Property Ownership and Contact Details	1
1	1.1.3	Current and Proposed Future Uses	1
1.2	Surr	ounding Land Use	2
2.0	SCOPI	OF INVESTIGATION	3
3.0	RECOI	RDS REVIEW	4
3.1	Gen	eral	4
3	3.1.1	Phase One Study Area Determination	4
3	3.1.2	First Developed Use Determination	4
3	3.1.3	Fire Insurance Plans	4
3	3.1.4	Chain of Title	4
3	3.1.5	Reports by Others	4
3	3.1.6	City Directories	5
3.2	Envi	ronmental Source Information	5
3	3.2.1	Databases Searched	5
3	3.2.2	Database Findings Relevant to the Phase One ESA	7
3	3.2.3	MECP Freedom of Information and Index Review Requests	15
3	3.2.4	TSSA Information Request	15
3	3.2.5	Historic Land Use Inventory (HLUI) Request	15
3	3.2.6	MECP Instruments (PTTW)	16
3	3.2.7	MECP Incident Reports	16
3	3.2.8	MECP Brownfields Environmental Site Registry	16
3	3.2.9	City of Ottawa Landfill Sites	16
3	3.2.10	Former City of Ottawa Industrial Sites	16
4.0	PHYSI	CAL SETTING	17
4.1	Aeri	al Photographs and Satellite Images	17

4.2	Top	oography	18
4.3	Нус	drology	18
4.4	Geo	ology	18
4.	4.1	Surficial Geology	18
4.	4.2	Bedrock Geology	18
4.5	Нус	drogeology	18
4.6	Fill	Materials	18
4.7	Wa	ater Bodies and Areas of Natural Significance	18
4.8	We	ell Records	19
5.0	INTE	RVIEWS	20
6.0	SITE	RECONNAISSANCE UPDATE	22
6.1	Ger	neral Requirements	22
6.	1.1	Qualifications of the Assessors	22
6.	1.2	Weather Conditions at Time of Inspection	22
6.	1.3	Property Occupancy/Use Status at Time of Inspection	22
6.	1.4	Site Photographs	22
6.2	Des	scription of Investigations	23
6	2.1	Phase One Property	23
6	2.2	Phase One Study Area	23
6.3	Spe	ecific Observations at the Phase One Property	23
6.	3.1	Structures and Other Improvements	23
6.	3.2	Below Ground Structures	23
6.	3.3	Storage Tanks	23
6.	3.4	Hazardous Materials	23
6.	3.5	Potable and Non-Potable Water Sources	23
6.	3.6	Underground Service Trenches	24
6.	3.7	Exit and Entry Points	24
6.	3.8	Existing and Former Heating Systems	24
6.	3.9	Cooling Systems	24
6.	3.10	Drains, Pits, and Sumps	24

6	5.3.11	Unidentified Substances	24				
6	5.3.12	2 Stains and/or Corrosion Near Drains, Pits, and Sumps					
6	6.3.13 Well Details						
6	6.3.14 Details of Sewage Works						
6	5.3.15	Ground Surface Details	24				
6	5.3.16	Current and Former Railway Lines	25				
6	5.3.17	Staining to Soil, Vegetation, or Pavement	25				
6	5.3.18	Stressed Vegetation	25				
6	5.3.19	Fill and Debris	25				
6	5.3.20	Mould	25				
6	5.3.21	Potentially Contaminating Activities (PCAs) and Areas of Potential Environmental Concern (APECs)	25				
6.4	Surr	ounding Properties	25				
7.0	REVIE	W AND EVALUATION OF INFORMATION	26				
7.1	Curr	ent and Past Uses of Phase One Property	26				
7.2	Pote	entially Contaminating Activities	27				
7.3	Area	as of Potential Environmental Concern (APEC)	28				
7.4	Pha	se One Conceptual Site Model	28				
7	7.4.1	Areas Where Potentially Contaminating Activities Have Occurred	29				
7	7.4.2	Contaminants of Potential Concern	29				
7	7.4.3	Potential for Underground Utilities to Affect Contaminant Distribution and Transport	29				
7	7.4.4	Geological and Hydrogeological Information	30				
7	7.4.5	Uncertainty or Absence of Information	30				
8.0	CONC	LUSIONS	31				
8.1	Is a	Phase Two ESA Required?	31				
9.0	LIMIT	ATIONS	32				
10.0	REFER	RENCES	34				
TABLI	ES						
Table	1: Boreł	nole Records	8				

Table 2: Ontario Regulation 347 Waste Generators Summary Records	11
Table 3: Scott's Manufacturing Directory Records	13
Table 4: Ontario Spill Records	14
Table 5: Water Well Information System Records	14
Table 6: Current and Historical Land Use from Aerial Photographs and Satellite Images	17
Table 7: Current and Past Uses of the Phase One ESA Property	26
Table 8: Potentially Contaminating Activities	27

FIGURES

Figure 1 Site Location Figure 2 Study Area Figure 3 Surrounding I

Figure 3 Surrounding Land Use
Figure 4 Drainage and Topography

Figure 5 Potentially Contaminating Activities

APPENDICES

Appendix A Chain of Title
Appendix B City Directories
Appendix C ERIS Report
Appendix D Correspondence
Appendix E Aerial Photographs
Appendix F Interview Records
Appendix G Site Photographs

1.0 INTRODUCTION

McIntosh Perry Consulting Engineers Ltd. (McIntosh Perry) was retained by Chris McCluskey of McCluskey Group to conduct a Phase One Environmental Site Assessment (ESA) updated for 16 Edgewater Street, Kanata, Ontario. The Site is bounded to the northwest by a commercial building 20 Edgewater Street, to the northeast by residential dwellings along Foulis Crescent and a multi-unit commercial building, to the southwest by Edgewater Street followed by Toromont CAT maintenance garage and storage yard and southeast by 6 Edgewater street, a commercial building containing a Tim Hortons and Wendy's followed by Hazelden Road. The property is currently a vacant lot covered in grass ("the Site"). The report is an update to McIntosh Perry's original Phase One ESA in December 2018. At that time, the property was a single property combined with 6 Edgewater Street. McIntosh Perry's original Phase One ESA was only for the vacant portion, now addressed as 16 Edgewater Street.

It is understood that this Phase One ESA is being completed as a component to redevelop the site with affordable housing. The last known uses of the property was commercial and the intended future use is residential housing. This represents a change to a more sensitive land use, and it is our understating that a Record of Site Condition (RSC) will be required prior to development of the residential housing.

The Site location is shown on Figure 1 (Site Location). The Site layout and features, including on-site land use, are shown on Figure 2 (Site Layout).

1.1 Phase One Property Information

The property is addressed as 16 Edgewater Street and is currently vacant. Previously, the Site was combined with 6 Edgewater Street but has since been severed (approximately 2019).

Site zoning is IG2 (General Industrial Zone, Subzone 2) as described under section 199-200 of the City of Ottawa Zoning by-laws, which currently does not allow for residential housing.

The total area of the Site is approximately 0.62 hectares (ha).

1.1.1 Property Identification

The legal description of the entire property is as follows;

Part Lot 30 Concession 12 Part 1 4R31503 City of Ottawa; (PIN 044980170)

1.1.2 Property Ownership and Contact Details

McIntosh Perry was retained to complete this Phase One ESA by Chris McCluskey of McCluskey Group. Mr. McCluskey can be contacted at (613) 627-0611. The property is currently owned by 11143921 Canada Inc.

1.1.3 Current and Proposed Future Uses

The Site is currently vacant. The intended future use of the Site will be residential housing.

1.2 Surrounding Land Use

Land use in the vicinity of the Site is a combination of residential, commercial and light industrial.

2.0 SCOPE OF INVESTIGATION

A Phase One ESA is a preliminary environmental screening tool designed to provide a qualitative assessment of the environmental condition of a site, based on a desktop review of available documentation pertaining to the site and observations made during a site visit. Sampling and chemical analysis of soils, groundwater, and/or other materials/substances are beyond the scope of work for a Phase One ESA.

The Phase One ESA has been prepared in general accordance with the requirements of the following legislation:

• Ontario Regulation (O.Reg.) 153/04 - Records of Site Condition (as amended).

The report is also in general compliance with:

 "Phase One Environmental Site Assessment", Canadian Standards Association (CSA) standard CSA Z768-01, Reaffirmed 2016.

A designated substances survey was not completed as part of the current investigation.

The subject property is not an 'Enhanced Investigation Property' as defined in O.Reg. 153/04 (as amended).

3.0 RECORDS REVIEW

3.1 General

3.1.1 Phase One Study Area Determination

The Phase One Study Area includes the following properties:

- The Site
- All properties within approximately 250m of the Site boundary (Phase One ESA Study Area)

The Phase One ESA Study Area, including surrounding land uses, is shown on Figure 2 (Study Area) and Figure 3 (Surrounding Land Use).

3.1.2 First Developed Use Determination

The Site is currently vacant. Based on a review of aerial photographs and historical information, the Site appears to have been agricultural land from 1932-1976. Between 1976 and 1983 the site was developed into a materials storage yard (Cashway Building Center). After 1996 the Site has been vacant.

3.1.3 Fire Insurance Plans

The Catalogue of Canadian Fire Insurance Plans (FIPs) was searched as part of this Phase One ESA. However, no Fire Insurance Plans were available for the area of the Site.

3.1.4 Chain of Title

A Chain of Title was obtained for the Site by Read Titles of Ottawa, Ontario. The Chain of Title indicated that the Site was owned by a series of individuals from the original crown patent 1828 until 1968, at which time it was acquired by a series of holding companies but apparently not developed. In 1974, the Site was acquired by Gilbert and Mary Henderson and leased to the Larkin Lumber Company, at which time it was developed with a hardware store/building materials supplier. The Site was acquired by The TDL Group Inc. in 1995, at which time a portion of the Site was developed with the present-day Tim Horton's. As of 2019, the Site was transferred to the current registered owner, 11143921 Canada Inc.

The Chain of Title is included as Appendix A of this report.

3.1.5 Reports by Others

A Phase I and II ESA report was completed by Jacques Whitford Environmental Ltd. in June 1995. The repot was completed for the entirety of 6 Edgewater Street, which includes the Site and the southeastern portion of the property. The Phase I ESA identified multiple PCAs that were considered to result in APECs for the Site. These include;

- Two underground fuel storage tanks to the east of the Site;
- Two above ground fuel storage tanks on-site;

- Fill of unknown quality;
- Possible groundwater contamination from trichloroethane leak at 5 Edgewater street and
- Multiple designated substances associated with the building on the subject property.

A Phase II ESA was done to address the above PCAs for potential contamination on the property. The field investigation included thirteen boreholes placed to address the noted PCAs. A total of four soil samples were submitted for laboratory analysis of Benzene, Toluene, Ethyl Benzene, Xylenes (BTEX), Total Petroleum Hydrocarbons (TPH) (oil and gas) and TPH (heavy oils). One sample was taken as a representative fill sample and tested for the above parameters and general chemistry. A single water sample was collected from the tap of the Cashway Building Centre and was submitted for analysis of BTEX and trichloroethane.

All samples submitted for laboratory analysis were non-detectable or below site condition standards of that time, Ministry of the Environment and Energy (MOEE) Level II (for soil hydrocarbons and water) and MOEE Decommissioning Guidelines for fine textured soil (for soil general chemistry). It should be noted that current O.Reg 153 Site Condition Standards (SCS) are typically more stringent than the SCS used in 1995. It is further noted that the TPH concentrations analyzed at the time are not directly comparable to the current SCS for petroleum hydrocarbons, fractions 1 through 4 (PHC F1-F4).

3.1.6 City Directories

A City Directory search was completed as part of this Phase One ESA, for the years 1992-2011. The directory lists 6 Edgewater Street as "Tim Hortons" between 2001 and 2011 and "Cashway Building Centers" in 1996/1997. The address was not listed in 1992.

A city directory update was not able to be completed at this time as municipal offices are closed due to the COVID-19 Pandemic. However, the original Phase One ESA city directory included the Site up to 2011 and the property has been vacant since the late 1990s. Therefore, a new directory search is deemed unwarranted.

Based on review of the City Directories, the Cashway Building Centers is considered to represent a PCA for the Site. The City Directory search results are included in this report as Appendix B.

3.2 Environmental Source Information

McIntosh Perry completed a records review to obtain information about the Site pertaining to items of actual and/or potential environmental concern.

3.2.1 Databases Searched

McIntosh Perry obtained information contained in the databases listed below from ERIS of Toronto, Ontario. Details about the sources of information and the years included for each database, as well as the pertinent information obtained from these databases are included in the ERIS report, provided as Appendix C.

Federal Government Databases:

Environmental Effects Monitoring

- Environmental Issues Inventory System
- Federal Convictions
- Contaminated Sites on Federal Land
- Fisheries and Oceans Fuel Tanks
- Indian and Northern Affairs Fuel Tanks
- National Analysis of Trends in Emergencies System (NATES)
- National Defence and Canadian Forces Fuel Tanks
- National Defence and Canadian Forces Spills
- National Defence and Canadian Forces Waste Disposal Sites
- National Environmental Emergencies System (NEES)
- National PCB Inventory
- National Pollutant Release Inventory
- Parks Canada Fuel Storage Tanks
- Transport Canada Fuel Storage Tanks

Provincial Government Databases:

- Abandoned Aggregate Inventory
- Aggregate Inventory
- Abandoned Mines Information System
- Certificates of Approval
- Coal Gasification Plants
- Compliance and Convictions
- Drill Holes
- Environmental Registry
- Ontario Regulation 347 Waste Generators Summary
- Mineral Occurrences
- Non-Compliance Reports
- Ontario Oil and Gas Wells
- Ontario Inventory of PCB Storage Sites
- Ministry Orders
- Occurrence Reporting Information System
- Pesticide Register
- Private Fuel Storage Tanks
- Ontario Regulation 347 Waste Receivers Summary
- Record of Site Condition
- Wastewater Discharger Registration Database
- Waste Disposal Sites MOE CA Inventory
- Waste Disposal Sites MOE 1991 Historical Approval Inventory

Water Well Information System

Private Databases:

- Anderson's Waste Disposal Sites
- Automobile Wrecking and Supplies
- Commercial Fuel Oil Tanks
- Chemical Register
- ERIS Historical Searches
- Canadian Mine Locations
- Oil and Gas Wells
- Canadian Pulp and Paper
- Retail Fuel Storage Tanks
- Scott's Manufacturing Directory
- Anderson's Storage Tanks

3.2.2 Database Findings Relevant to the Phase One ESA

The databases searched by ERIS contained the following information pertaining to the Site:

- Three (3) borehole records
- Eleven (11) Certificate of Approval records
- Six (6) Delisted fuel tanks
- One (1) Environmental and Activity Registry records
- Three (3) Environmental Registry records
- Eight (8) Environmental Compliance Approval records
- Five (5) List of TSSA Expired Facilities records
- Five (5) fuel storage tanks
- Thirty-eight (38) Ontario Regulation 347 Waste Generators Summary records
- One (1) TSSA Historic Incidents record
- One (1) Fuel Oil Spills and Leaks
- Three (3) Pesticide Register records
- Two (2) Private and Retail Storage Fuel Tanks
- Three (3) Scott's Manufacturing Directory records
- Three (3) Ontario Spills records
- Nine (9) Water Well Information System records

Relevant information from the ERIS report is summarized as follows:

Boreholes

No boreholes were listed on the subject property. Eight boreholes were recorded within 250 m of the subject property. Borehole records are summarized in the Table below:

Table 1: Borehole Records

Borehole ID	Location relative to site	Completion Depth (m bgs)	Depth to Bedrock (m bgs)	Static Water Level (m)
609650	138.2m North	26.2	3.7	N/A
609647	122.1m East Southeast	16.8	5.2	N/A
609646	244.4m West Southwest	6.1	N/A	N/A

Locations of the boreholes can be found in the ERIS report in Appendix A.

Certificates of Approval

Eleven Certificates of Approval records were found within 250m of the subject site. No records were found for the subject property. The records include the following

- Two records were listed under Toromont Industries Ltd., located at 5 Edgewater Street
 - One record was for a revised industrial air approval for a waste oil furnace in August 1995 (Certificate # 8-4013-95). Contaminates of concern were organic compounds, manganese, nickel, carbon monoxide, nitrogen oxide, sulphur dioxide, suspended particulate matter, arsenic, cadmium and copper.
 - One record was for an approved air certificate in November 2003 (Certificate # 9954-5DXHTJ)
- One record was listed under Pegasus Development Corporation, located at 9 Young Road and Foulis
 Crescent. The record is for an approved municipal and private sewage certificate in September 2000,
 which relates to the construction of a storm water management facility (Certificate # 5667-4N2SPM)
- Three records were listed under Taylor Developments, located at Terry Fox and Hazeldean Road
 - One record was for an approved municipal sewage certificate dated August 1988 (Certificate # 3-1533-88)
 - One record was for municipal and private sewage certificate in June 2002, which relates to the construction of storm sewers on Terry Fox Drive (Certificate # 1344-5ASRJK)
- Two records were listed under Allard's Paint & Body Shop, located at 33 Edgewater Street
 - One record was for a revoked or replaced air sewage certificate dated February 2014 (Certificate # 3565-5jkqv6)
 - One record was for an approved air certificate in March 2004, which relates to the (Certificate # 3447-5xbl97)

Two records were listed under Edgewater Center, located at 30 Edgewater Street

- o One record was for an approved municipal sewage certificate dated July 2002 (Certificate # 1326-4zljlv) for a stormwater facility. The other record is only for replacing manhole covers.
- One record was listed under 1374469 Ontario Inc. and located at Lot 30, Conc.12, 25 Edgewater Street. The record is for an approved industrial sewage certificate (certificate # 4177-57317m). It is for a stormwater management facility.

All located records can be found in Appendix B. Locations of the Certificate of Approval can be found in the ERIS report in Appendix A.

Delisted Fuel Tanks

Six Delisted Fuel Tank records were found within 250m of the subject site. No records were found for the subject property.

Two records are listed under Christopher Armstrong Enterprises Inc., located at 501 Hazelden Road and is for an expires Fuel storage facility and fuel storage pipping. Expiry date was January 1994.

Four records are listed under Crothers Ltd., located at 5 Edgewater Street and is for a private fuel storage facility and associated piping. No expiry date is given.

Locations of the Delisted Fuel Tank records can be found in the ERIS report in Appendix A.

Environmental Activity and Sector Registry

One Environmental Activity and Sector Registry (EASR) record was found within 250m of the subject site. No records were found for the subject property. The record is listed under Toromont Industries Ltd., located at 5 Edgewater Street and is for an approved air emissions EASR in August 2017 (Approval # R-010-7110218068).

All located records can be found in Appendix B. Locations of the Environmental Activity and Sector Registry records can be found in the ERIS report in Appendix A.

Environmental Registry

Three Environmental Registry (EBR) record was found within 250m of the subject site. No records were found for the subject property.

- One record was listed under Toromont Industries Ltd., located at 5 Edgewater Street. The record
 was for an instrument decision on an approval to discharge to the natural environment other than
 water (i.e Air) in March 2002 (Certificate #1536-586RG6)
- Two records were listed to Allard's Paint & Body Shop Ltd., located at 33 Edgewater Street. Both records are for an instrument decision on an approval to discharge to the natural environment other than water (i.e Air) in February 2003 (Certificate #5823-5crjyu)) and April 2004 (Certificate # 2760-5ndnjb).

All located records can be found in Appendix B. Locations of the Environmental Registry can be found in the ERIS report in Appendix A.

Environmental Compliance Approvals

Eight Environmental Compliance Approval records were found within 250m of the subject site. No records were found for the subject property.

- Two records were listed under Toromont Industries Ltd., located at 5 Edgewater Street
 - One record was for an approved air certificate in November 2003 (Certificate # 9954-5DXHTJ)
 - One record was for an approved industrial sewage works certificate in June 2017 (Certificate # 8595-ANDHRR)
- One record was listed under the City of Ottawa, located at Terry Fox and Hazeldean Road. The record
 is for an approved municipal and private sewage works certificate in June 2002, which relates to the
 construction of a storm water management facility (Certificate # 5809-5B2HCC)
- Two records were listed under Allard's Paint & Body Shop., located at 33 Edgewater Street
 - o One record was for an approved air certificate in March 2004 (Certificate # 3774-5xbl97) for a paint booth and associated appliances.
 - One record was revoked or replaced air certificate in February 2003 (Certificate # 3565-5jkqv6)
- Two records were listed under Actum Ltd., located at 30 Edgewater Street
 - One record was for an approved Municipal and Private Sewage Works certificate in July 2002 (Certificate # 2423-5cjgc5)
 - One record was for a revoked or replaced Municipal and Private Sewage Works certificate in July 2002 (Certificate # 1326-4|z|lv)
- One record was listed under 1374469 Ontario Inc., located at 25 Edgewater Street for an industrial sewage works (Certificate # 4177-57317m)

All located copies of above records can be found in Appendix B. Locations of the Environmental Compliance Approval can be found in the ERIS report in Appendix A.

List of TSSA Expired Facilities

Five TSSA expired facilities records were found within 250m of the subject site. No records were found for the subject property. The sixteen records relate to two addresses listed below;

• Three records were listed under Christopher Armstrong Enterprises Inc., located at 501 Hazelden Road.

- o All records are associated with a self-serve retail fuel facility with three gasoline fuel storage tanks and associated piping. Status of all records are expired since January 1997.
- Two records were listed under Geo W Crothers Ltd., located at 5 Edgewater Street.
 - o All records are associated with a self-serve private fuel facility with two gasoline fuel storage tanks and associated piping. Status of all records are expired since September 1990.

Due to the proximity of these fuel storage tank records to the Site, these records are considered to represent an environmental concern to the Site. Locations of the TSSA Expired Facilities records can be found in the ERIS report in Appendix A.

Fuel Storage Tank

Five Fuel Storage Tank records were found within 250 m of the subject property. No records were found for the Site.

Three records are listed under Christopher Armstrong Enterprises Inc., located at 501 Hazelden Road and is for three steel liquid fuel tanks installed in October 1989.

Two records are listed under Crothers Ltd., located at 5 Edgewater Street and is for two steel liquid fuel tanks installed September 1990.

Locations of the Delisted Fuel Tank records can be found in the ERIS report in Appendix A.

Ontario Regulation 347 Waste Generators Summary

Thirty-eight Ontario Regulation 347 Waste Generators were found within 250 m of the subject property. No records were found for the Site. The Thirty-eight waste generator records are associated with seven different businesses, with multiple years of approval. These records are summarized in Table below:

Table 2: Ontario Regulation 347 Waste Generators Summary Records

Company	Address	Waste Description (Approval Years)
Chiropractic Clinic	501-B Hazeldean	Photoprocessing Waste (1988,1989, 1992-1998)
	Road	
Abbotsford Moving	24 Edgewater	Aliphatic Solvents (1995-1998)
	Street	Waste Oils and Lubricants (1995-2008)
GTA's Finest Restoration	33 Edgewater	Oil Skimming & Sludges (2016)
Services	Street	
Johnson Controls	30 Edgewater	Aliphatic Solvents (2001-current)
	street	Waste Oils & Lubricants (2001- current)
		Organic Laboratory Chemicals (2010- current)
		Inorganic Laboratory Chemicals (2010- current)
		Detergents/soaps (2010- current)

Company	Address	Waste Description (Approval Years)
		Paint/pigment/coating residues (2010- current)
		Waste compressed gases (2010- current)
		Alkaline wastes – other metals (2016- current)
Rockwell Collins Canada	30 Edgewater	Polymeric Resins (2020-current)
Inc.	Street	Miscellaneous waste organic chemicals (2020-current)
		Waste compressed gasses including cylinders (2020-current)
Toromont Industries Inc	5 Edgewater	Petroleum Distillates (1993-current)
	Street	Oil Skimmings and Sludges (1993- current)
		Waste Oils and Lubricants (1993- current)
		Aromatic Solvents (1993- 2016)
		Aliphatic Solvents (1993- current)
		Light Fuels (1999- current)
		Organic Laboratory Chemicals (2000- current)
		Waste Compressed Gases (2016- current)
Crothers Limited		Petroleum Distillates (1986-1990, 1992-1998)
		Oil Skimmings and Sludges (1986-1990, 1992-1998)
		Waste Oils and Lubricants (1986-1990, 1992-1998)
		Aromatic Solvents (1990, 1992-1998)
		Aliphatic Solvents (1992-1998)
One Hour Photo	500 Hazeldean	Photoprocessing Waste (1994-2001)
	Road, Unit 3	

Due to their proximity to the Site, the records at 5 Edgewater Street are considered to have the potential to represent environmental liability for the subject property. Locations of the Ontario regulation 347 Waste Generator records can be found in the ERIS report in Appendix A.

TSSA Historic Incident

One TSSA historic incident was found within 250 m of the subject property. The record is located at 21 Young Road for a fuel oil leak. The incident occurred on September 26, 2008. Due to the separation distance and indicated no action require as part of the TSSA investigation, this record is not considered to represent environmental liability for the Site.

No TSSA Historic Incidents were found on the subject property.

Fuel Oil Spills and Leaks

One TSSA incident was found within 250m of the subject property. The record is located at 501 Hazeldean Road for a vapour release of natural gas. This was due to multiple leaks in piping on October 22, 2013. Due to the gaseous nature and separation distance, this record is not considered to represent environmental liability for the Site

No TSSA Historic Incidents were found on the subject property.

This record is not considered to represent environmental liability for the Site because of the gaseous nature of the contaminant. Locations of the TSSA Incidents can be found in the ERIS report in Appendix A.

Pesticide Register

Three Pesticide Register records were found on the subject property. Records are for the Cashway Building Center which previously occupied the Site.

These records are not considered to represent environmental liability for the Site as the records are for the retail of presides and not for the bulk storage or manufacturing.

No Pesticide Register records were found 250m of the subject property. Locations of the Pesticide Register records can be found in the ERIS report in Appendix A.

Private and Retail Storage Fuel Tanks

Two Private and Retail Fuel Storage Tank record was found within 250m of the subject property, a 4546 liter private fuel storage tank and a 4500 liter retail fuel storage tank at 5 Edgewater Street. These records are listed under Geo W Crothers Ltd. and Crothers Ltd. respectively. No expiry date or further information is provided. No records were found for on the subject property

These records are considered to represent a potential environmental concern to the Site because of their proximity to the Site and lack of up-to-date or confirmed information regarding their removal of the environmental condition of the property. Locations of the private and Retail Fuel Storage Tanks can be found in the ERIS report in Appendix A.

Scott's Manufacturing Directory

Three Scott's Manufacturing Directory records were found within 250m of the subject property. No records were found for the Site. These records are summarized in the Table below:

Table 3: Scott's Manufacturing Directory Records

Company	Address	Established	Plant Size (ft²)/ # Employees	Description
Kanata Upholstery	500 Hazeldean Road	1989	1200/4	Upholstered Household Furniture Manufacturing
Skywave Mobile Communication Inc	30 Edgewater Street, Suite 110	1999	-/40	Wireless communication equipment manufacturing
Espial Group Inc	30 Edgewater Street, Suite 114	-	-/-	Software publishers

This record is not considered to represent environmental liability for the subject property. Locations of the Scott's Manufacturing Directory records can be found in the ERIS report in Appendix A.

Ontario Spills

Three Ontario spill records were found within 250 m of the subject property. No records were found for the subject property. The Table below summarizes the spill records:

Table 4: Ontario Spill Records

Location	Contaminant	Incident	Impacts	Date
501 Hazeldean Road	Hydraulic Oil	Equipment leaked 20 L of oil to catch basin	No anticipated environmental impacts noted	29/05/2012
21 Young Road	Heating Oil	4-5 L of oil spilled due to equipment failure	No anticipated environmental impacts noted. Spill cleaned up.	26/09/2008
Hazeldean and Terry Fox	Gasoline	Spill to catch basin	cleaned	13/12/2019

Due to the limited quantity, separation distance, cross or downgradient location to the Site, and noted as cleaned, these records are not considered to represent environmental liability for the subject property. Locations of the Ontario Spill records can be found in the ERIS report in Appendix A.

Water Well Information System

Nine Water Well Information records found within 250m of the subject property. No records were found for the subject property. The Table below summarize the details of each well.

Table 5: Water Well Information System Records

Well ID	Completion Material	Depth to Bedrock (m bgs)	Bedrock Type	Well Depth (m bgs)	Well Use	Static Water Level (m bgs)	Clear/ Cloudy	Water Type
736158	Overburden	-	-	6.096	Monitoring well	-	-	-
1514168	Bedrock	9.75	Limestone	32	Domestic Water Supply	1.82	Clear	Fresh
1514897	Bedrock	0.91	Sandstone	25.91	Domestic Water Supply	9.14	Clear	Fresh

Well ID	Completion Material	Depth to Bedrock (m bgs)	Bedrock Type	Well Depth (m bgs)	Well Use	Static Water Level (m bgs)	Clear/ Cloudy	Water Type
1514055	Bedrock	9.75	Limestone	67.97	Industrial Water Supply	21.34	-	Fresh
1502987	Bedrock	5.18	Shale/ Sandstone	16.76	Domestic Water Supply	4.57	Clear	Fresh
1502990	Bedrock	3.66	Sandstone	26.21	Domestic Water Supply	7.92	Cloudy	Fresh
1502995	Bedrock	3.05	Sandstone	14.63	Public Water Supply	5.49	Clear	Fresh
1509894	Bedrock	1.22	Sandstone	37.80	Domestic Water Supply	12.19	Cloudy	Fresh
1502988	Bedrock	0	Sandstone	22.86	Domestic Water Supply	4.57	Clear	Fresh

Locations of the Water Well Information records can be found in the ERIS report in Appendix A.

3.2.3 MECP Freedom of Information and Index Review Requests

In order to identify any previous environmental reports concerning the Site, an MECP Freedom of Information (FOI) request and index review request was submitted for the Site on September 20, 2021. At time of writing MPCE has received no official response from MECP, responses take between one to two months to receive.

A copy of the MECP correspondence is provided in Appendix D.

3.2.4 TSSA Information Request

An FOI request was submitted to the Technical Standards and Safety Authority (TSSA). The TSSA request returned no records of fuel tanks on the subject property. TSSA FOI results indicated expired records for a self-serve private fuel outlet, with two liquid fuel storage tanks, at 5 Edgewater Street. A copy of the TSSA correspondence is provided in Appendix C.

3.2.5 Historic Land Use Inventory (HLUI) Request

A Historic Land Use Inventory (HLUI) request was submitted to the City of Ottawa to determine historic land uses for the Phase One Study Area. At the time of this report, the HLUI results have not yet been received. The HLUI request form is included in Appendix D.

3.2.6 MECP Instruments (PTTW)

A search for all available MECP Instruments, including Certificates of Authorization, Permits To Take Water, and other records, was completed as part of the ERIS report for the Site, discussed in previous sections. No records were identified which represented environmental concerns to the Site.

3.2.7 MECP Incident Reports

The ERIS report and the MECP FOI response discussed above did not identify any MECP incident reports with respect to the Site or surrounding properties.

3.2.8 MECP Brownfields Environmental Site Registry

The MECP Brownfields Environmental Site Registry was searched as part of the ERIS report, discussed in previous sections. No RSCs have been filed for the Site or immediately adjacent properties.

3.2.9 City of Ottawa Landfill Sites

The document titled 'Old Landfill Management Strategy – Phase 1 – Identification of Sites' prepared by Golder Associates, dated October 2004, was reviewed as part of this Phase One ESA.

This report provides an in-depth summary of former landfill sites within the City of Ottawa, as identified by a variety of research sources. The report did not identify any landfill sites in the vicinity of the Site.

3.2.10 Former City of Ottawa Industrial Sites

The report titled 'Mapping and Assessment of Former Industrial Sites, City of Ottawa', prepared by Intera Technologies Ltd., dated July 1988, was reviewed as part of this Phase One ESA. This document did not identify any environmental concerns in the vicinity of the Site.

4.0 PHYSICAL SETTING

4.1 Aerial Photographs and Satellite Images

Table 6 describes observations about current and historical land use for the Site and surrounding properties that were noted during review of aerial photographs of the area taken between 1932 and 2017, included in Appendix E. Current land uses are included on Figure 4.

Table 6: Current and Historical Land Use from Aerial Photographs and Satellite Images

Date	Source	Observations
1932	National Air Photo Library	Site is vacant and used as agricultural land. Surrounding land use is predominantly agricultural with associated residences. One such residence is located directly northwest of the Site. Hazelden Road is located to the south.
1945	National Air Photo Library	The Site and surrounding area remains relatively unchanged.
1958	National Air Photo Library	The Site and surrounding area remains relatively unchanged.
1968	National Air Photo Library	The Site remains relatively unchanged. Additional residences are present to the northwest of the site
1976	National Air Photo Library	The Site remains relatively unchanged. The heavy equipment garage is present southwest of the Site.
1983	National Air Photo Library	The Site has been developed into a materials storage yard for the Cashway Building Center. A commercial strip mall and retail fuel outlet are present to the northeast of the Site. Commercial buildings are present to the northwest of the Site and the heavy equipment garage is present to the southwest. The primary surrounding land use is residential.
1991	GeoOttawa	The Site and surrounding area remains relatively unchanged.
2002	GeoOttawa	The Site is vacant, and the present-day commercial building is on the southeast portion of the property (Tim Hortons). The retail fuel outlet the northeast has been removed. The heavy equipment garage and yard has expanded to the present-day orientation.
2011	GeoOttawa	The Site and surrounding area remains relatively unchanged.
2017	GeoOttawa	The Site and surrounding area remains relatively unchanged.

Based on the aerial photos two PCAs were identified in the surrounding area.

4.2 Topography

The elevation at the Site is approximately 101 m above sea level (m asl). The topography is generally flat (see Figure 4).

4.3 Hydrology

The Site occurs within the Carp River watershed. The Carp River is approximately 650m southwest of the Site.

4.4 Geology

4.4.1 Surficial Geology

Geological maps of the area classify the overburden at the Site as fine-textured glaciomarine deposits, consisting predominantly of silt and clay. (OGS, 2018).

4.4.2 Bedrock Geology

Geological maps of the area classify the bedrock at the Site as predominantly limestone, dolostone, shale, arkose and sandstone of the Ottawa Group (OGS, 2018).

4.5 Hydrogeology

Based on a review of site geology and topography, groundwater is likely to flow southwest toward the Carp River. Groundwater flow may be influenced by underground service trenches along Edgewater Street and Hazeldean Road.

4.6 Fill Materials

The Site visit and analysis of the aerial photos indicate the historical placement and/or grading of fill material at the site.

4.7 Water Bodies and Areas of Natural Significance

The closest permanent waterbody is the Carp River (located 0.65 km southwest of the Site at its closest point).

When completing a Phase One ESA, considerations are made for the following Areas of Natural Significance as defined by O.Reg. 153/04:

- Provincial Parks and conservation reserves
- Areas of Natural and Scientific Interest (ANSIs)
- Provincially Significant Wetlands (PSWs)
- Environmentally/ecologically sensitive/significant areas per the City of Ottawa Official Plan
- Areas designated by the Niagara Escarpment Plan
- Areas identified by MNRF as significant habitat of a threatened or endangered species or areas of habitat of a species classified under section 7 of the Endangered Species Act

- Areas designated by the Oak Ridges Moraine Conservation Plan
- Areas set apart under the Wilderness Areas Act

No areas of natural significance were observed within the Study Area.

4.8 Well Records

McIntosh Perry performed a well record search utilizing the ERIS Water Well Information System (WWIS) data (based on MECP GIS data). Seven well records were returned from this search. Details of the record are located in the Section 3.2.2.

5.0 INTERVIEWS

McIntosh Perry personnel conducted an interview with Chris McCluskey and Don Godbold, tenants of the property, to obtain information about the subject property pertaining to items of actual and/or potential environmental concern. Information collected during this interview was used to corroborate data from other sources, and is presented in Appendix E.

The information obtained from the interview is summarized as follows:

Potential Environmental	Interview Comments (Chris McCluskey)	Interview Comments (Don Godbold)		
Concerns	Tenant Since 2013	Tenant since 1996		
Accidents/Spills	Not that he is aware of	Not that he is aware of		
Previous Use of Site	Vacant land from at least 1998	Cashway Lumber Yard		
Adjacent Properties	Tim Hortons, Residential, Boone Plumbing	Tim Hortons/ Residential/ Industrial use – pluming showroom		
Fuel Handling/Storage	Not that he is aware of	Not that he is aware of		
Maintenance/Operational Areas	Not that he is aware of	Not that he is aware of		
Hazardous Materials Storage	Not that he is aware of	Not that he is aware of		
Salt Storage	Not that he is aware of	Not that he is aware of		
Fuel Storage Tanks	Not that he is aware of	Not that he is aware of		
Odours	Not that he is aware of	Not that he is aware of		
Potable Water	Not that he is aware of	Not that he is aware of		
Septic and Wastewater	Not that he is aware of	Not that he is aware of		
Discharges				
Pesticides	Not that he is aware of	Not that he is aware of		
Mould	Not that he is aware of	Not that he is aware of		
Heating and Cooling Systems	Not that he is aware of	Not that he is aware of		
Major Mechanical Equipment	Not that he is aware of	Not that he is aware of		
Waste Oils, Solvents, Batteries	Not that he is aware of	Not that he is aware of		
PCBs	Not that he is aware of	Not that he is aware of		
Asbestos	Not that he is aware of	Not that he is aware of		
Lead Paint	Not that he is aware of	Not that he is aware of		
ODS	Not that he is aware of	Not that he is aware of		
Electromagnetic Radiation	Not that he is aware of	Not that he is aware of		
UFFI	Not that he is aware of	Not that he is aware of		
Mercury	Not that he is aware of	Not that he is aware of		
Radon Gas	Not that he is aware of	Not that he is aware of		
Soil and Groundwater Conditions	Not that he is aware of	Not that he is aware of		
Wells	Not that he is aware of	Not that he is aware of		
Waste Disposal and Recycling	Not that he is aware of	Not that he is aware of		
Fill Material	Not that he is aware of	Not that he is aware of		
Floor Drains/OWS (Discharge Locations)	Not that he is aware of	Not that he is aware of		
Other				

Note that statements made by those interviewed were not made categorically and are limited to personal knowledge of, and experience with, the subject property. The significance of environmental concerns that have been identified by other methods was not reduced based on the interview statements.

The interviews with the above confirmed the Site was once a Cashway Building Centers lumber yard, which is considered a PCA.

6.0 SITE RECONNAISSANCE UPDATE

The objectives of the site reconnaissance were as follows:

- To identify potential environmental concerns associated with current and past uses of the Site;
- To identify Potentially Contaminating Activities (PCAs) on, in, or under the Site;
- To identify, as practical, current and past uses, activities, and PCAs in the vicinity of the Site; and
- To identify details of potential contaminant pathways on, in, or under the Site and potential environmental concerns and contaminants of potential concern.

McIntosh Perry had open and ready access to all exterior areas of the Site during the site visit.

6.1 General Requirements

McIntosh Perry conducted the Site reconnaissance on May 20, 2021 (from approximately 1:30pm to 2:30pm). Bradley Sutherland of McIntosh Perry inspected the entirety of the property and observed other properties in the Study Area from publicly accessible locations.

6.1.1 Qualifications of the Assessors

Field assessment for this report was undertaken by Bradley Sutherland, B.Sc. of McIntosh Perry. Bradley has successfully completed numerous Phase One ESAs for various clients in Ontario. Reporting was completed by Bradley Sutherland, B.Sc. and Dan Arnott, P.Eng. Dan is an Ontario licensed Professional Engineer and a Qualified Person (QP) under O.Reg. 153/04, as amended, and has completed numerous Phase One and Two ESAs across Ontario.

McIntosh Perry is licensed to practice engineering and geoscience in the Province of Ontario. McIntosh Perry holds Certificates of Authorization with the Professional Engineers of Ontario (PEO) and the Association of Professional Geoscientists of Ontario (APGO) and is a full member of the Consulting Engineers of Ontario (CEO).

6.1.2 Weather Conditions at Time of Inspection

Weather conditions at the time of the Site visit was sunny with a temperature of 25 degrees Celsius.

6.1.3 Property Occupancy/Use Status at Time of Inspection

The Site is currently vacant.

Land use in the Phase One ESA Study Area is shown on Figure 4.

6.1.4 Site Photographs

Photographs of the Site are included in Appendix G. A brief description is included with each photograph, including location and orientation where applicable.

6.2 Description of Investigations

The Phase One component of the current investigation is a preliminary environmental screening that aims to provide a qualitative assessment of the environmental condition of the site based on a review of available information pertaining to the Site, observations made during a Site visit, and information from interviews with people who have knowledge of the Site and its history.

The Phase One portion of the current investigation includes the following components:

- A review of available background information;
- Interviews with person(s) knowledgeable about the site;
- Site reconnaissance; and
- Freedom of Information requests (Ministry of the Environment, Conservation and Parks (MECP) and the Technical Standards and Safety Authority (TSSA))

6.2.1 Phase One Property

The property is vacant with three monitoring wells.

Site zoning is AM2 (Arterial Mainstreet Zone, Subzone 2) as described under section 185-186 of the City of Ottawa Zoning by-laws.

6.2.2 Phase One Study Area

The Study Area consists primarily of residential, commercial and light industrial properties.

6.3 Specific Observations at the Phase One Property

6.3.1 Structures and Other Improvements

The Site is currently vacant. No structures or other improvements are present.

6.3.2 Below Ground Structures

No evidence of below ground structures was observed at the Site.

6.3.3 Storage Tanks

No aboveground storage tanks (ASTs) or evidence of underground storage tanks (USTs) were observed.

6.3.4 Hazardous Materials

No hazardous materials were observed.

6.3.5 Potable and Non-Potable Water Sources

Three monitoring wells are on-site. They are located in the southeast, northwest and southwest portion of the property.

There are currently no buildings on the Site. The Site is located in a municipally-serviced area, and the restaurant to the south of the Site is serviced by the City of Ottawa water distribution system.

6.3.6 Underground Service Trenches

No underground service trenches were observed at the Site. However, storm drains, fire hydrants and a transformer were observed in the parking lot of the Tim Hortons to the southeast.

6.3.7 Exit and Entry Points

All exit and entry points to the Site were inspected. No concerns were identified.

6.3.8 Existing and Former Heating Systems

The Site is currently vacant. No heating systems were observed. No information was available about the heating system(s) associated with the former Cashway Building Centre.

6.3.9 Cooling Systems

The Site is currently vacant. No cooling systems were observed. No information was available about the cooling system(s) associated with the former Cashway Building Centre.

6.3.10 Drains, Pits, and Sumps

No drains, pits, or sumps were observed at the Site.

6.3.11 Unidentified Substances

No unidentified substances were observed at the Site.

6.3.12 Stains and/or Corrosion Near Drains, Pits, and Sumps

None observed.

6.3.13 Well Details

Three monitoring wells are on-site. They are located in the southeast, northwest and southwest portion of the property.

6.3.14 Details of Sewage Works

The Site visit did not indicate any evidence of private sewage works. The Site is located in a municipally-serviced area.

6.3.15 Ground Surface Details

The ground surface at the Site was covered in approximately 15 cm of snow at time of inspection. Snow was cleared in selected areas, and vegetation (grass) was observed under the snow in these areas.

6.3.16 Current and Former Railway Lines

The site inspection did not indicate the presence of current or former rail lines at the Site or on adjacent properties.

6.3.17 Staining to Soil, Vegetation, or Pavement

No staining was observed during the Site visit.

6.3.18 Stressed Vegetation

No stressed vegetation was observed during the Site visit.

6.3.19 Fill and Debris

No fill or debris were observed on-site.

6.3.20 Mould

Site is currently vacant. No mould was observed on exposed surfaces.

6.3.21 Potentially Contaminating Activities (PCAs) and Areas of Potential Environmental Concern (APECs)

No PCAs were observed on-site during the site visit on May 20, 2021.

6.4 Surrounding Properties

Surrounding land use in the vicinity of the Site generally consisted of the following:

- Northeast Commercial and residential
- Northwest Commercial
- Southwest Edgewater Street and light industrial
- Southeast Tim Hortons then Hazeldean Road followed by residential

One off-site PCA was observed during McIntosh Perry's site visit on May 20, 2021.

5 Edgewater Street – Toromont CAT – Heavy equipment repair and storage facility

The potential of these PCAs resulting in APECs for the Site is considered in Section 7.2.

7.0 REVIEW AND EVALUATION OF INFORMATION

The following sections provide a review, and evaluation and an interpretation of the information from the records review, interviews and site reconnaissance.

7.1 Current and Past Uses of Phase One Property

The following table summarizes the land use history of the subject Site:

Table 7: Current and Past Uses of the Phase One ESA Property

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.	
Prior to 1932	Not identified		Vacant		
1828-1861	Robert Young	Address not listed		No Information	
1861-1906	William Young and Adam Abbott	Address not listed			
1906-1930	W.R. Young				
1930-1946	Francis Young				
1946-1956	Gordon Young			Earliest air photo (1932) shows the Site as vacant farm land	
1956-1957	Irenus and Margaret Hix		Vacant		
1957-1960	Department of Highways	Agricultural			
1960-1968	Irenus and Margaret Hix				
1968-1972	Space Optic Ltd.				
1972-1974	Watts and Henderson Ltd.				
1974-1995	Gilbert and Mary Henderson	Commercial	Cashway Building Centre	Interview from former Phase I ESA indicated Cashway was built in 1976 and City directory indicated its presence until 1996. Present in aerial photos in 1983 and 1991. Chain of Title indicates Site was leased to Larkin Lumber Company Ltd. between 1977 and 1995.	
1995-2019	The TDL Group Inc. and Wendy's Restaurants of Canada Inc.	Vacant/ commercial	Site is vacant, southwestern adjacent property is	City directory and aerial phots show the Site as vacant with Tim Hortons on southern portion of property.	
Present	11143921 Canada Inc.		commercial		

7.2 Potentially Contaminating Activities

The following PCAs were identified at, on, or under the Site and properties within the Phase One Study Area:

	Table 8: Potentially Contaminating Activities					
No.	Potential Contaminating Activity (PCA)	Location of PCA	Proximity of PCA to Phase One ESA Property	Time Frame Associated with PCA	Information Source	Does the PCA warrant an area of potential environmental concern (APEC)
1	Item 28, Column A, Table 2, Schedule D, O.Reg. 153/04: Gasoline and Associated Products Storage in Fixed Tanks (on-site ASTs)	On-Site	On-Site	1970s- 1995	Interviews, previous report	YES – on-site PCA
2	No item under Column A, Table 2, Schedule D, O.Reg. 153/04: Building materials storage yard	On-Site	On-Site	1970s- 1995	Interviews, air photos, previous report	YES – on-site PCA
3a	Item 27, Column A, Table 2, Schedule D, O.Reg. 153/04: Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles (heavy equipment garage)	5 Edgewater Street	45 m southwest	1980s- present	Aerial photos, site visit, previous report, ERIS report	YES, based on proximity
3b	Item 28, Column A, Table 2, Schedule D, O.Reg. 153/04: Gasoline and Associated Products Storage in Fixed Tanks (AST records)	5 Edgewater Street	45 m southwest	1980s- present	ERIS report	YES, based on proximity
3c	No item under Column A, Table 2, Schedule D, O.Reg. 153/04: historical spill record (TCE)	5 Edgewater Street	45 m southwest	Unknown	Report by others	YES, based on proximity

	Table 8: Potentially Contaminating Activities					
No.	Potential Contaminating Activity (PCA)	Location of PCA	Proximity of PCA to Phase One ESA Property	Time Frame Associated with PCA	Information Source	Does the PCA warrant an area of potential environmental concern (APEC)
4	Item 28, Column A, Table 2, Schedule D, O.Reg. 153/04: Gasoline and Associated Products Storage in Fixed Tanks (former retail fuel outlet)	501 Hazeldean Road	150 m south	Prior to 1994	ERIS report, air photos	YES, based on proximity
5	No item under Column A, Table 2, Schedule D, O.Reg. 153/04: Spill of fuel oil from residential fuel storage tank	21 Young Road	80 m north	2008	ERIS report	YES, based on proximity

7.3 Areas of Potential Environmental Concern (APEC)

The above noted on-site PCAs are considered to result in APECs for the Site. Due to the limited information available for type of materials and operational procedures of the Cashway Building Centers stock yard, it is possible that the operations have had impacts to the soil and groundwater in the vicinity of the materials storage yard.

The above noted off-site PCAs are considered to represent APECs at the Site due to their proximity.

7.4 Phase One Conceptual Site Model

This Phase One Conceptual Site Model is prepared as part of a Phase One Environmental Site Assessment (Phase One ESA) for the Phase One Property identified in Section 1.1.1 of this report, addressed as 16 Edgewater Street, Kanata (Ottawa) Ontario. (hereinafter referred to as the "Phase One Property" or the "Site"). A Site Location Plan is presented on Figure 1 appended to this report.

Based on the records review, the Phase One Property appears to have been used as agricultural land until approximately 1976-1977, at which time it was first developed with a hardware and building supply store, Cashway Building Centres (considered commercial use). The Site was subsequently redeveloped in approximately 1995; the Phase One ESA property is currently vacant, and the adjacent property to the south (originally part of the hardware/building supply store property) was redeveloped with a Tim Horton's restaurant. It is our understanding that the Site is to be redeveloped with a residential building, and as such, a Record of Site Condition will be required.

The legal description of the Site is as follows:

Part Lot 30 Concession 12 Part 1 4R31503 City of Ottawa; (PIN 044980170)

Land use in the Site is predominantly residential and commercial, with some industrial (heavy equipment maintenance).

7.4.1 Areas Where Potentially Contaminating Activities Have Occurred

Potentially Contaminating Activities (PCAs) were identified for the Phase One ESA Property and surrounding properties within the Phase One Study Area based on records review, interviews and site reconnaissance, as part of this Phase One ESA, as summarized above in Table 8.

7.4.2 Contaminants of Potential Concern

The following contaminants of potential concern (COCs) are suspected and should be tested at the Phase One Property:

- Petroleum hydrocarbons Fractions 1 to 4 (PHCs): This parameter group consists of petroleum hydrocarbons of various carbon chain lengths commonly encountered in gasoline (PHC F1), diesel and furnace oil (PHC F2), and heavy oils and asphalts (PHC F3-F4). This parameter group was selected as COPCs for the Site due to the historic presence of ASTs at the Site, the historic presence of a retail fuel outlet at 501 Hazeldean Road, a record of a fuel oil spill at 21 Young Road, and ASTs and garage activities at 5 Edgewater Street.
- Volatile organic compounds (VOCs) including benzene, toluene, ethylbenzene, and xylenes (BTEX): This parameter group consists of soluble components in gasoline, diesel, and fuel oil, as well as various chlorinated solvents used in degreasing, dry cleaning, and industrial applications. VOCs were selected as COPCs for the Site due to the historic presence of ASTs at the Site, the historic presence of a retail fuel outlet at 501 Hazeldean Road, a record of a fuel oil spill at 21 Young Road, and ASTs and garage activities at 5 Edgewater Street, as well as the historic TCE spill record noted in a previous environmental report at 5 Edgewater Street.
- Polycyclic aromatic hydrocarbons (PAHs): This parameter group consists of various complex hydrocarbons associated with heavy oils as well as combustion byproducts, coal, etc. PAHs were selected as COPCs for the Site due to the historic use of the Site as a building materials storage yard and garage activities at 5 Edgewater Street.
- Metals and inorganic parameters (As, Sb, Se, B, B-HWS, Na, Hg, Cl-, CN, Cr-VI, pH, EC and SAR) were selected as COPCs for the Site based on the historic use of the Site as a building materials storage vard.

7.4.3 Potential for Underground Utilities to Affect Contaminant Distribution and Transport

In general, there is the potential for underground service trenches to serve as preferential contaminant transport pathways. Underground service trenches are interpreted to be present along Edgewater Street and

Hazeldean Road; however, it is unknown whether these trenches will act as preferential flowpaths enabling contaminant transport towards the Site, or will intercept off-site contamination away from the Site.

7.4.4 Geological and Hydrogeological Information

The Site occurs within the Carp River watershed. The Carp River is approximately 650m southwest of the Site.

Geological maps of the area classify the overburden at the Site as fine-textured glaciomarine deposits, consisting predominantly of silt and clay. (OGS, 2018).

Geological maps of the area classify the bedrock at the Site as predominantly limestone, dolostone, shale, arkose and sandstone of the Ottawa Group (OGS, 2018).

Based on a review of site geology and topography, groundwater is likely to flow southwest toward the Carp River. Groundwater flow may be influenced by underground service trenches along Edgewater Street and Hazeldean Road.

7.4.5 Uncertainty or Absence of Information

No uncertainty or absence of information noted in the Phase One ESA is considered to have the potential to affect the validity of this conceptual site model.

8.0 CONCLUSIONS

Two PCAs were identified at, on, or under the Site (source).

- Former above ground fuel storage tanks (Previous Phase I and II ESA report)
- Cashway Building Center material storage yard (Aerial Photos and Interviews)

Three off-site PCAs were identified in the Phase One ESA Study Area (source).

- 5 Edgewater Street
 - Heavy equipment garage and storage yard (Site visit)
 - Former private fuel outlet with fuel storage tanks (ERIS Eco Logs)
 - o Former Trichlorethylene spill (Former Phase I and II ESA report)
- 501 Hazeldean Road
 - o Former retail fuel outlet (Aerial photos and ERIS Eco Log)
- 21 Young Road
 - o Spill of heating oil (ERIS report)

The above noted on-site PCAs are considered to result in an APEC for the Site. Due to the limited information available for type of materials and operational procedures of the Cashway Building Center stock yard, it is possible that the operations have had impacts to the soil and groundwater in the vicinity of the materials storage yard.

The above noted Off-site PCA are areas of environmental concern that have the possibility of impacting on-site soil and groundwater conditions.

8.1 Is a Phase Two ESA Required?

McIntosh Perry completed a Phase Two ESA based on the above findings, which are the same as original Phase One ESA conclusions. The Phase Two ESA addressed the PCAs above. McIntosh Perry recommends resampling the wells to confirm the current groundwater conditions.

9.0 LIMITATIONS

This report has been prepared, and the work referred to in this report has been undertaken by, McIntosh Perry Consulting Engineers Ltd. for Chris McCluskey of the McCluskey Group. It is intended for the sole and exclusive use of Chris McCluskey of the McCluskey Group. The report may not be relied upon by any other person or entity without the express written consent of McIntosh Perry Consulting Engineers Ltd. (in the form of a Reliance Letter).

Any use which a third party makes of this report, or any reliance on decisions made based on it, without a Reliance Letter are the responsibility of such third parties. McIntosh Perry Consulting Engineers Ltd. accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report.

Some of the information presented in this report was provided through maps, air photographs, and environmental reports. While attempts were made, whenever possible, to obtain a minimum of two confirmatory sources of information, McIntosh Perry Consulting Engineers Ltd., has, in certain instances, been required to assume that the information provided is accurate.

The conclusions presented represent the best professional judgment of the assessor based on current environmental standards and on the site conditions observed during the site inspection on November 22, 2018. External areas of the properties were observed from 6 Edgewater Street and other publicly accessible locations. Due to the nature of the investigation and the limited data available, the assessor cannot warrant against undiscovered environmental liabilities.

Should additional information become available, McIntosh Perry Consulting Engineers Ltd. requests that this information be brought to our attention so that we may re-assess the conclusions presented herein.

We trust that this information is satisfactory for your present requirements. Should you have any questions or require additional information, please do not hesitate to contact the undersigned.

Respectfully submitted,

McIntosh Perry Consulting Engineers Ltd.

Bradley Sutherland B.Sc. Environmental Scientist



Dan Arnott, P.Eng., QP_{ESA} Geo-Environmental Engineer

10.0 REFERENCES

Canadian Standards Association (CSA), Z768-01: Phase I Environmental Site Assessment, CSA International, Toronto, 2001 (Updated 2003, Reaffirmed 2012).

ERIS, 2018. Site-Specific Search Report Results.

Mississippi Valley Conservation Authority (MVCA), 2018. RVCA Regulations Mapping - http://camaps.arcgis.com/apps/webappviewer/index.html?id=70831905961e470988262c7a703a56af

Natural Resources Canada (NRCAN), 2011. Geobase online mapping tool: Hydro Network GIS Data accessed through http://geobase.ca/geobase/en/viewer.jsp?group=nhn>.

Ontario Geologic Survey (OGS), 2017 GIS Data for bedrock and surficial geology stratigraphy.

Ontario Ministry of Environment, Conservation and Parks (MECP), Ontario Regulation (O.Reg.) 153/04; Records of Site Condition – Part XV.1 of the Act (i.e. The Environmental Protection Act), as amended.


Ontario Geological Survey (OGS), 2017 – Google EarthTM (website: http://www.mndmf.gov.on.ca/mines/ogs_earth_e.asp).


Jacques Whitford Environmental Ltd., 1995. 'Phase I & II Environmental Site Assessment Proposed Restaurant Development', 6 Edgewater Street, Kanata, Ontario.

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



FIGURES





Approximate Site Boundary

CLIENT:

CHRIS McCLUSKEY

PROJECT:
PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
16 EDGEWATER STREET, KANATA, ON

SITE LAYOUT

MCINTOSH PERRY 115 Walgreen Road, RR3, Carp, ON K0A1L0 Tel: 613-836-2184 Fax: 613-836-3742 www.mcintoshperry.com

Oct., 06, 2021 DA Checked By


PROJECT NO:CCO-22-0244


REFERENCE


GIS data provided by the Ontario Ministry of Natural Resources and Forestry, 2021.

2

FIGURE:







PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



APPENDIX A CHAIN OF TITLE



READ Abstracts Limited

331 Cooper Street, Suite 300, Ottawa, Ontario K2P 0A4 Email: search@readsearch.com

Tel.: 613-236-0664 Fax: 613-236-3677

ENVIRONMENTAL SEARCH

McIntosh Perry

Attn: Bradley Sutherland

BRIEF DESCRIPTION OF LAND:

16 Edgewater, Kanata Part of Lot 30, Concession 12, Goulbourn

PIN: 04498-0170

LAST REGISTERED OWNER: 11143921 Canada Inc.

CHAIN OF TITLE:

Patent dated Jul 5, 1828 From the Crown to Robert Young

Deed RO17349 registered Mar 12, 1861 From Robert Young to Adam Abbott

Deed RO17578 registered Apr 18, 1861 From Robert Young to William Young

Deed GB3660 registered Apr 19, 1894 From William Young to Adam Abbott

Deed GB5610 registered Apr 2, 1906 From Adam Abbott to W. R. Young

Deed GB7530 registered May 12, 1930 From W. R. Young to Francis Young

Deed GB9822 registered Sep 23, 1946 From Francis Young to Gordon Young Deed GB11612 registered Jul 16, 1956 From Gordon Young to Irenus and Margaret Hix

Expropriation CB11886 registered Jun 10, 1957 By Dept of Highways

Deed GB11894 registered Jun 17, 1957 From Her Majesty the Queen to Irenus and Margaret Hix

Deed GB13393 registered Jul 7, 1960 From Irenus and Margaret Hix to Irenus and Margaret Hix

Deed GB17370 registered Dec 11, 1968 From Irenus and Margaret Hix to Space Optic Ltd.

Deed CT161926 registered Oct 27, 1972 From Space Optic Ltd. to Watts and Henderson Ltd.

Deed CT197486 registered Aug 13, 1974 From Watts and Henderson Ltd. to Gilbert and Mary Henderson

Lease CT243290 registered Feb 2, 1977 To The Larkin Lumber Company Limited

Deed LT949495 registered Sep 18, 1995 From Gilbert and Mary Henderson to The TDL Group Inc.

Name Change OC2008809 registered Jun 29, 2018 From The TDL Group Inc. to The TDL Group Corp.

Deed OC2008923 registered Jun 29, 2018

From The TDL Group Corp. to The TDL Group Corp. and Wendy's Restaurants of Canada Inc.

Deed OC2074411 registered Jan 30, 2019

From The TDL Group Corp. and Wendy's Restaurants of Canada Inc. to 11143921 Canada Inc.

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



APPENDIX B CITY DIRECTORIES



Head Office: 80 Valleybrook Dr, Toronto, ON M3B 2S9
Physical Address: 38 Lesmill Rd, Toronto, ON M3B 2T5
Phone: 416-510-5204 • Fax: 416-510-5133
info@erisinfo.com • www.erisinfo.com

City Directory Information Source	
Vernon's Ottawa and Area Ontario City Directory	

PROJECT NUMBER: 20181121032	
Site Address:	6 Edgewater Street, Kanata, Ontario
Year: 2011	
Site Listing:	-Tim Hortons
Adjacent Properties:	
5 Edgewater Street	-Address Not Listed
20 Edgewater Street	-Nissan University
	-Boone Plumbing & Heating Supply Inc
	-Mondeau Bathroom & Kitchen
21 Edgewater Street	-Address Not Listed
24 Edgewater Street	-Abbotsford Moving & Storage Ltd

	-Abbotsford Holdings Inc
501 Hazeldean Road	-Kellyos Welcome Irish Pub & Resto
	-Beauty Systems Group Canada
	-Money Mart
	-Henry's
	-Wavelength
	-Three Bags Full
	-Women's World

PROJECT NUMBER: 20181121032	
Site Address:	6 Edgewater Street, Kanata, Ontario
Year: 2006-07	
Site Listing:	-Tim Hortons
Adjacent Properties:	
5 Edgewater Street	-Toromont Ind -Toromont Truck Service
20 Edgewater Street	-Club Excellence -Independent Learning Systems
	-Nissan University -Mondeau Bathroom & Kitchen

21 Edgewater Street	-Address Not Listed
24 Edgewater Street	-Abbotsford Limousine Service
	Abbotsford Moving & Storago
	-Abbotsford Moving & Storage
	-Abbotsford Transportation
501 Hazeldean Road	-Carvery The
	-Davis Grocery
	-Brig Pub The
	-Soprano's Pizza
	-Wavelength
	-Three Bags Full Consignment Shop
	Crook Pologo
	-Greek Palace
	-Women's World

PROJECT NUMBER: 20181121032	
Site Address:	6 Edgewater Street, Kanata, Ontario
Year: 2001-02	
Site Listing:	-Tim Hortons
Adjacent Properties:	
5 Edgewater Street	-Parts
	-Battlefield Equipment Rentals

20 Edgewater Street	-Atmos Corporation
21 Edgewater Street	-Address Not Listed
24 Edgewater Street	-Abbotsford Moving & Storage Ltd
	-Abbotsford Limousine Service
	-Abbotsford Transportation Systems
501 Hazeldean Road	-Davis Grocery
	-Big Pub The
	-Motor Vehicle License Issuers
	-Tom & Sons Donuts & More
	-Wavelength
	-Three Bags Full Consignment Shop
	-Joe's Pizza
	<u> </u>

PROJECT NUMBER: 20181121032	
Site Address:	6 Edgewater Street, Kanata, Ontario
Year: 1996-97	
Site Listing:	-Cashway Building Centres
Site Listing.	-West End Branch
Adjacent Properties:	

5 Edgewater Street	-Toromont Ind
	-Toromont Truck
20 Edgewater Street	-Learn Soft
21 Edgewater Street	-Address Not Listed
24 Edgewater Street	-Abbotsford Moving & Storage Ltd
	-Abbotsford Limousine Service
	-Abbotsford Transportation Systems
501 Hazeldean Road	-Davis Grocery
	-Paul's Roadhouse
	-Popeye Pizza
	-Motor Vehicle License Issuers
	-Running Stitch
	-Tom & Sons Donuts & More
	-Westar Sports
	-Three Bags Full Consignment Shop

PROJECT NUMBER: 20181121032	
Site Address:	6 Edgewater Street, Kanata, Ontario
Year: 1992	
Site Listing:	-Address Not Listed

Adjacent Properties:	
.,	
5 Edgewater Street	-Crothers Truck Service
20 Edgewater Street	-Calmos Systems
21 Edgewater Street	-Address Not Listed
24 Edgewater Street	-Abbotsford Moving & Storage Ltd
	-Abbotsford Limousine Service
	The solution of Emmoderning Continues
501 Hazeldean Road	-Popeye Pizza
	-Motor Vehicle License Issuers
	-Tom & Sons Donuts & More
	-Westar Sports
	-Westar Sports

⁻All listings for businesses were listed as they are in the city directory.

⁻Listings that are residential are listed as "residential" with the number of tenants. The name of the residential tenant is not listed in the above city directory

^{**}Kanata Ontario is listed from 1992-2011 within the City Directory Archives**

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



APPENDIX C ERIS REPORT



Project Property: 16 Edgewater RSC

16 Edgewater Street

Kanata ON K2L 1V8

Project No: CCO-22-0244

Report Type: Standard Report

Order No: 21062300392

McIntosh Perry Consulting Engineers Requested by:

Date Completed: June 28, 2021

Table of Contents

Table of Contents	2
Executive Summary	
Executive Summary: Report Summary	
Executive Summary: Site Report Summary - Project Property	6
Executive Summary: Site Report Summary - Surrounding Properties	7
Executive Summary: Summary By Data Source	
Map	29
Aerial	
Topographic Map	31
Detail Report	32
Unplottable Summary	100
Unplottable Report	103
Appendix: Database Descriptions	125
Definitions	134

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

_			
$\nu r \cap$	nortv	' Int∩rr	nation:
	DELLA	1111011	nauvn.

Project Property: 16 Edgewater RSC

16 Edgewater Street Kanata ON K2L 1V8

Order No: 21062300392

Project No: CCO-22-0244

Coordinates:

 Latitude:
 45.2955894

 Longitude:
 -75.8959327

 UTM Northing:
 5,016,177.88

 UTM Easting:
 427,750.84

UTM Zone: 18T

Elevation: 345 FT

105.11 M

Order Information:

 Order No:
 21062300392

 Date Requested:
 June 23, 2021

Requested by: McIntosh Perry Consulting Engineers

Report Type: Standard Report

Historical/Products:

Aerial Photographs Aerials - National Collection

Insurance Products Fire Insurance Maps/Inspection Reports/Site Plans

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Within 0.25 km	Total
AAGR	Abandoned Aggregate Inventory	Υ	0	0	0
AGR	Aggregate Inventory	Υ	0	0	0
AMIS	Abandoned Mine Information System	Υ	0	0	0
ANDR	Anderson's Waste Disposal Sites	Υ	0	0	0
AST	Aboveground Storage Tanks	Υ	0	0	0
AUWR	Automobile Wrecking & Supplies	Υ	0	0	0
BORE	Borehole	Υ	0	3	3
CA	Certificates of Approval	Υ	0	11	11
CDRY	Dry Cleaning Facilities	Υ	0	0	0
CFOT	Commercial Fuel Oil Tanks	Υ	0	0	0
CHEM	Chemical Manufacturers and Distributors	Υ	0	0	0
CHM	Chemical Register	Υ	0	0	0
CNG	Compressed Natural Gas Stations	Υ	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Υ	0	0	0
CONV	Compliance and Convictions	Υ	0	0	0
CPU	Certificates of Property Use	Υ	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	6	6
EASR	Environmental Activity and Sector Registry	Y	0	1	1
EBR	Environmental Registry	Y	0	3	3
ECA	Environmental Compliance Approval	Υ	0	8	8
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	0	8	8
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Υ	0	0	0
EPAR	Environmental Penalty Annual Report	Υ	0	0	0
EXP	List of Expired Fuels Safety Facilities	Υ	0	5	5
FCON	Federal Convictions	Υ	0	0	0
FCS	Contaminated Sites on Federal Land	Υ	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Υ	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	5	5
FSTH	Fuel Storage Tank - Historic	Y	0	0	0
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	38	38
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	1	1
IAFT	Indian & Northern Affairs Fuel Tanks	Υ	0	0	0

Database	Name	Searched	Project Property	Within 0.25 km	Total
INC	Fuel Oil Spills and Leaks	Υ	0	1	1
LIMO	Landfill Inventory Management Ontario	Υ	0	0	0
MINE	Canadian Mine Locations	Υ	0	0	0
MNR	Mineral Occurrences	Υ	0	0	0
NATE	National Analysis of Trends in Emergencies System	Υ	0	0	0
NCPL	(NATES) Non-Compliance Reports	Υ	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Υ	0	0	0
NDSP	National Defense & Canadian Forces Spills	Υ	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal	Υ	0	0	0
NEBI	Sites National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Υ	0	0	0
NEES	National Environmental Emergencies System (NEES)	Υ	0	0	0
NPCB	National PCB Inventory	Υ	0	0	0
NPRI	National Pollutant Release Inventory	Y	0	0	0
OGWE	Oil and Gas Wells	Υ	0	0	0
OOGW	Ontario Oil and Gas Wells	Υ	0	0	0
OPCB	Inventory of PCB Storage Sites	Υ	0	0	0
ORD	Orders	Υ	0	0	0
PAP	Canadian Pulp and Paper	Υ	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Υ	0	0	0
PES	Pesticide Register	Υ	0	3	3
PINC	Pipeline Incidents	Υ	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Υ	0	2	2
PTTW	Permit to Take Water	Υ	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Υ	0	0	0
RSC	Record of Site Condition	Υ	0	0	0
RST	Retail Fuel Storage Tanks	Υ	0	0	0
SCT	Scott's Manufacturing Directory	Υ	0	3	3
SPL	Ontario Spills	Υ	0	3	3
SRDS	Wastewater Discharger Registration Database	Υ	0	0	0
TANK	Anderson's Storage Tanks	Υ	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Υ	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Υ	0	0	0
WWIS	Water Well Information System	Y	0	9	9
		Total:	0	110	110

Executive Summary: Site Report Summary - Project Property

MapDBCompany/Site NameAddressDir/Dist (m)Elev diffPageKey(m)Number

No records found in the selected databases for the project property.

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	CA	TOROMONT INDUSTRIES LIMITED	5 EDGEWATER STREET KANATA CITY ON K2L 1V7	SSE/97.7	-1.62	<u>32</u>
1	PRT	GEO W CROTHERS LTD	5 EDGEWATER DR KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>32</u>
1	PRT	CROTHERS LTD	5 EDGEWATER DR KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>32</u>
1	EBR	Toromont Industries Ltd.	5 Edgewater Street Ottawa Ontario Ottawa ON	SSE/97.7	-1.62	<u>32</u>
1	GEN	CROTHERS LIMITED	5 EDGEWATER ST. KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>33</u>
1	GEN	CROTHERS LIMITED	5 EDGEWATER ST. KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>33</u>
1	GEN	CROTHERS(SEE & USE ON1767304) 11-220	5 EDGEWATER ST. KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>34</u>
1	GEN	CROTHERS LIMITED (SEE & USE ON1767304)	5 EDGEWATER STREET KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>34</u>
1	GEN	TOROMONT INDUSTRIES LTD.	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>34</u>
1	GEN	TOROMONT INDUSTRIES LTD.	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>35</u>
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>35</u>
1	CA	Toromont Industries Ltd.	5 Edgewater Street Ottawa ON	SSE/97.7	-1.62	<u>36</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	DTNK	CROTHERS LTD	5 EDGEWATER DR KANATA ON	SSE/97.7	-1.62	<u>36</u>
1	DTNK	GEO W CROTHERS LTD	5 EDGEWATER DR KANATA ON	SSE/97.7	-1.62	<u>37</u>
1	DTNK	CROTHERS LTD	5 EDGEWATER DR KANATA ON	SSE/97.7	-1.62	<u>37</u>
1	DTNK	GEO W CROTHERS LTD	5 EDGEWATER DR KANATA ON	SSE/97.7	-1.62	<u>37</u>
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>38</u>
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>38</u>
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>39</u>
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>39</u>
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON	SSE/97.7	-1.62	<u>40</u>
<u>1</u>	EXP	GEO W CROTHERS LTD	5 EDGEWATER DR KANATA K2L 1V7 ON CA ON	SSE/97.7	-1.62	<u>40</u>
1	EXP	CROTHERS LTD	5 EDGEWATER DR KANATA K2L 1V7 ON CA ON	SSE/97.7	-1.62	<u>41</u>
1	ECA	Toromont Industries Ltd.	5 Edgewater Street Ottawa ON L4K 1B7	SSE/97.7	-1.62	<u>41</u>
<u>1</u> .	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>41</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>42</u>
<u>1</u>	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>43</u>
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>43</u>
1	EASR	TOROMONT INDUSTRIES LTD./ INDUSTRIES TOROMONT LTEE	5 Edgewater DR Kanata ON K2L 1V7	SSE/97.7	-1.62	<u>44</u>
1	ECA	Toromont Industries Ltd.	5 Edgewater St Ottawa ON L4K 5E1	SSE/97.7	-1.62	<u>44</u>
1	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>44</u>
<u>1</u>	FST	CROTHERS LTD	5 EDGEWATER DR KANATA K2L 1V7 ON CA ON	SSE/97.7	-1.62	<u>45</u>
1	FST	GEO W CROTHERS LTD	5 EDGEWATER DR KANATA K2L 1V7 ON CA ON	SSE/97.7	-1.62	<u>45</u>
<u>1</u>	GEN	TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE/97.7	-1.62	<u>46</u>
<u>2</u> .	EHS		6 Edgewater Street Kanata ON K2L 1V8	E/106.4	1.04	<u>46</u>
<u>3</u>	GEN	ABBOTSFORD MOVING (OUT OF BUSINESS)	24 EDGEWATER STREET KANATA ON K2L 1V8	NNW/107.1	2.54	<u>46</u>
<u>3</u>	EHS		24 Edgewater Street Kanata ON K2L 1V8	NNW/107.1	2.54	<u>47</u>
<u>4</u> .	wwis		6 EDGEWATER ST lot 30 con 12 OTTAWA ON	E/127.1	2.50	<u>47</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7326158			
<u>5</u>	WWIS		lot 30 con 12 ON <i>Well ID:</i> 1514168	E/130.3	1.58	<u>49</u>
<u>6</u>	BORE		ON	WSW/150.6	-3.39	<u>53</u>
<u>7</u>	wwis		lot 30 con 12 ON Well ID: 1514897	ESE/156.8	0.77	<u>54</u>
<u>8</u>	PES	CANADA CASHWAY LUMBER COMPANY	6 EDGEWATER STREET HAZELDEAN ON	ESE/158.8	0.77	<u>57</u>
<u>8</u>	PES	CASHWAY BUILDING CENTRES	6 EDGEWATER STREET KANATA ON K2L 1V8	ESE/158.8	0.77	<u>58</u>
<u>8</u>	PES	CASHWAY BUILDING CENTRES	6 EDGEWATER STREET KANATA ON K2L1V8	ESE/158.8	0.77	<u>58</u>
<u>9</u> .	CA		Lot 30, Conc. 12, 25 Edgewater Street, Kanata Ottawa ON K2L 1V7	WNW/159.9	0.59	<u>58</u>
9	ECA	1374469 Ontario Inc.	Lot 30, Conc. 12, 25 Edgewater Street, Kanata Ottawa ON K2A 3X9	WNW/159.9	0.59	<u>59</u>
<u>10</u>	EHS		24 Edgewater St Ottawa ON K2L1V8	NW/164.2	1.77	<u>59</u>
<u>11</u>	SPL		21 Young Rd Ottawa ON	NNE/174.0	4.85	<u>59</u>
<u>11</u>	HINC		21 YOUNG ROAD OTTAWA ON	NNE/174.0	4.85	<u>60</u>
<u>12</u>	wwis		lot 30 con 12 ON <i>Well ID:</i> 1502990	NE/179.6	4.77	<u>60</u>
<u>13</u>	BORE		ON	NE/179.6	4.77	<u>63</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>14</u>	СА		9 Young Road, Foulis Crescent, Block 40, 4M-405 Kanata ON K2L 1V9	ENE/187.4	4.46	<u>64</u>
<u>15</u>	GEN	CHIROPRACTIC CLINIC	501B HAZELDEAN CENTRE KANATA ON K2L 1V6	E/191.3	2.46	<u>64</u>
<u>15</u>	GEN	CHIROPRACTIC (OUT OF BUSINESS) 07-179	501B HAZELDEAN CENTRE KANATA ON K2L 1V6	E/191.3	2.46	<u>65</u>
<u>15</u>	DTNK	CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA ON K2L 1V6	E/191.3	2.46	<u>65</u>
<u>15</u>	DTNK	CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA ON	E/191.3	2.46	<u>65</u>
<u>15</u>	SPL	Waste Services (CA) Inc.	501 Hazeldean Road Ottawa ON K2L 1V6	E/191.3	2.46	<u>65</u>
<u>15</u>	EXP	CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	E/191.3	2.46	<u>66</u>
<u>15</u>	EXP	CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	E/191.3	2.46	<u>66</u>
<u>15</u>	EXP	CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	E/191.3	2.46	<u>67</u>
<u>15</u>	INC		501 HAZELDEAN RD, KANATA ON	E/191.3	2.46	<u>67</u>
<u>15</u>	FST	CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	E/191.3	2.46	<u>68</u>
<u>15</u>	FST	CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	E/191.3	2.46	<u>68</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>15</u>	FST	CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	E/191.3	2.46	<u>69</u>
<u>16</u>	EHS		29 Edgewater St Ottawa ON K2L1V7	WNW/201.7	0.69	<u>69</u>
<u>17</u>	wwis		lot 30 con 12 ON <i>Well ID</i> : 1514055	E/212.5	2.77	<u>69</u>
<u>18</u>	EHS		30 Edgewater St Ottawa ON K2L1V8	NNW/216.4	3.69	<u>73</u>
<u>19</u>	wwis		lot 30 con 12 ON <i>Well ID:</i> 1509894	NNE/217.6	5.40	<u>74</u>
<u>20</u>	BORE		ON	ESE/223.0	0.46	<u>76</u>
<u>21</u>	wwis		lot 30 con 12 ON <i>Well ID</i> : 1502987	ESE/223.1	0.46	<u>77</u>
22	CA	TAYLOR DEVELOPMENTS	S.E. TERRY FOX DR. & HAZELDEAN KANATA CITY ON	S/225.3	-5.23	<u>80</u>
22	CA		Terry Fox Drive and Hazeldean Road Ottawa ON	S/225.3	-5.23	<u>80</u>
<u>22</u>	CA		Terry Fox Drive Hazeldean Road to Carp River Ottawa ON	S/225.3	-5.23	<u>81</u>
<u>22</u>	ECA	City of Ottawa	Terry Fox Drive and Hazeldean Road Ottawa ON K1P 1J1	S/225.3	-5.23	<u>81</u>
<u>23</u>	wwis		lot 30 con 12 ON <i>Well ID</i> : 1502988	NNE/229.6	5.74	<u>81</u>
<u>24</u>	SPL		Ottawa ON	S/233.5	-5.23	<u>84</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>25</u>	WWIS		lot 31 con 12 ON	NE/236.7	6.38	<u>84</u>
			Well ID: 1502995			
<u>26</u>	SCT	KANATA UPHOLSTERY	500 HAZELDEAN RD KANATA ON K2L 2B5	SE/237.8	-3.20	<u>87</u>
<u>26</u>	GEN	ONE HOUR MOTO PHOTO	500 HAZELDEAN ROAD, UNIT #3 KANATA ON	SE/237.8	-3.20	<u>87</u>
<u>26</u>	GEN	ONE HOUR MOTO PHOTO	500 HAZELDEAN ROAD, UNIT 3 KANATA ON	SE/237.8	-3.20	<u>87</u>
<u>27</u>	EBR	Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa Ontario K2L 1V7 Ottawa ON	WNW/242.0	0.68	<u>87</u>
<u>27</u>	EBR	Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa Ontario K2L 1V7 Ottawa ON	WNW/242.0	0.68	<u>88</u>
<u>27</u>	CA	Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa ON	WNW/242.0	0.68	<u>88</u>
<u>27</u>	CA	Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa ON	WNW/242.0	0.68	<u>89</u>
<u>27</u>	ECA	Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa ON K2L 1V7	WNW/242.0	0.68	<u>89</u>
<u>27</u>	ECA	Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa ON K2L 1V7	WNW/242.0	0.68	<u>89</u>
<u>27</u>	GEN	GTA'S Finest Restoration Services (ottawa) Inc.	33 Edgewater Street Ottawa ON K2L 1V7	WNW/242.0	0.68	<u>89</u>
<u>28</u>	CA		30 Edgewater St. Kanata ON K2L 1V8	NW/242.6	4.77	<u>90</u>
<u>28</u>	CA	Edgewater Centre	30 Edgewater Street Ottawa ON K2L 1V8	NW/242.6	4.77	<u>90</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW/242.6	4.77	<u>90</u>
28	SCT	Skywave Mobile Comm. Inc.	30 Edgewater St Suite 110 Kanata ON K2L 1V8	NW/242.6	4.77	<u>91</u>
<u>28</u>	EHS		30 Edgewater Street, Suite 106 Ottawa ON	NW/242.6	4.77	<u>91</u>
<u>28</u>	EHS		30 Edgewater Street Kanata ON K2L 1V8	NW/242.6	4.77	<u>91</u>
<u>28</u>	SCT	Espial Group Inc.	30 Edgewater St Suite 114 Kanata ON K2L 1V8	NW/242.6	4.77	<u>91</u>
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON	NW/242.6	4.77	<u>92</u>
<u>28</u>	EHS		30 Edgewater St Ottawa ON K2L 1V8	NW/242.6	4.77	92
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON	NW/242.6	4.77	92
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON	NW/242.6	4.77	<u>93</u>
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW/242.6	4.77	<u>93</u>
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON	NW/242.6	4.77	<u>94</u>
<u>28</u>	ECA	Actum Ltd.	30 Edgewater St. Kanata ON K2A 3X9	NW/242.6	4.77	<u>94</u>
<u>28</u>	ECA	Actum Ltd.	30 Edgewater Street Ottawa ON K2A 3X9	NW/242.6	4.77	<u>95</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW/242.6	4.77	<u>95</u>
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW/242.6	4.77	<u>96</u>
28	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW/242.6	4.77	<u>96</u>
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW/242.6	4.77	<u>97</u>
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW/242.6	4.77	<u>97</u>
<u>28</u>	GEN	Rockwell Collins Canada Inc	30 EDGEWATER ST SUITE 104 KANATA ON K2L 1V8	NW/242.6	4.77	<u>98</u>
<u>28</u>	GEN	Rockwell Collins Canada Inc	30 EDGEWATER ST SUITE 104 KANATA ON K2L 1V8	NW/242.6	4.77	98
<u>28</u>	GEN	JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW/242.6	4.77	<u>99</u>

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 3 BORE site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	Map Key
	ON	NE	179.63	<u>13</u>
	ON	ESE	223.05	<u>20</u>
Lower Elevation	Address ON	<u>Direction</u> WSW	<u>Distance (m)</u> 150.65	Map Key

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 11 CA site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	<u>Address</u>	Direction	Distance (m)	<u>Map Key</u>
	Lot 30, Conc. 12, 25 Edgewater Street, Kanata Ottawa ON K2L 1V7	WNW	159.92	9_
	9 Young Road, Foulis Crescent, Block 40, 4M-405 Kanata ON K2L 1V9	ENE	187.35	<u>14</u>
Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa ON	WNW	241.96	<u>27</u>
Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa ON	WNW	241.96	<u>27</u>

Equal/Higher Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	Map Key
	30 Edgewater St. Kanata ON K2L 1V8	NW	242.62	<u>28</u>
Edgewater Centre	30 Edgewater Street Ottawa ON K2L 1V8	NW	242.62	<u>28</u>
Lower Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	<u>Map Key</u>
Toromont Industries Ltd.	5 Edgewater Street Ottawa ON	SSE	97.73	1
TOROMONT INDUSTRIES LIMITED	5 EDGEWATER STREET KANATA CITY ON K2L 1V7	SSE	97.73	1
TAYLOR DEVELOPMENTS	S.E. TERRY FOX DR. & HAZELDEAN KANATA CITY ON	S	225.29	<u>22</u>
	Terry Fox Drive Hazeldean Road to Carp River Ottawa ON	S	225.29	<u>22</u>

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Jul 31, 2020 has found that there are 6 DTNK site(s) within approximately 0.25 kilometers of the project property.

225.29

22

Order No: 21062300392

Equal/Higher Elevation	<u>Address</u>	Direction	Distance (m)	Map Key
CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA ON K2L 1V6	E	191.26	<u>15</u>
CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA ON	Е	191.26	<u>15</u>

Terry Fox Drive and Hazeldean Road

Ottawa ON

Lower Elevation	<u>Address</u>	Direction	Distance (m)	Map Key
GEO W CROTHERS LTD	5 EDGEWATER DR KANATA ON	SSE	97.73	1
CROTHERS LTD	5 EDGEWATER DR KANATA ON	SSE	97.73	1
CROTHERS LTD	5 EDGEWATER DR KANATA ON	SSE	97.73	1
GEO W CROTHERS LTD	5 EDGEWATER DR KANATA ON	SSE	97.73	<u>1</u>

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011-May 31, 2021 has found that there are 1 EASR site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	<u>Address</u>	Direction	Distance (m)	<u>Map Key</u>
TOROMONT INDUSTRIES LTD./ INDUSTRIES TOROMONT LTEE	5 Edgewater DR Kanata ON K2L 1V7	SSE	97.73	<u>1</u>

EBR - Environmental Registry

A search of the EBR database, dated 1994-Apr 30, 2021 has found that there are 3 EBR site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation Allard's Paint & Body Shop Ltd.	Address 33 Edgewater Street Ottawa Ontario K2L 1V7 Ottawa ON	<u>Direction</u> WNW	<u>Distance (m)</u> 241.96	<u>Map Key</u> <u>27</u>
Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa Ontario K2L 1V7 Ottawa ON	WNW	241.96	<u>27</u>
Lower Elevation Toromont Industries Ltd.	Address 5 Edgewater Street Ottawa Ontario Ottawa ON	<u>Direction</u> SSE	<u>Distance (m)</u> 97.73	Map Key 1

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011- May 31, 2021 has found that there are 8 ECA site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation 1374469 Ontario Inc.	Address Lot 30, Conc. 12, 25 Edgewater Street, Kanata Ottawa ON K2A 3X9	<u>Direction</u> WNW	<u>Distance (m)</u> 159.92	Map Key 9
Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa ON K2L 1V7	WNW	241.96	<u>27</u>
Allard's Paint & Body Shop Ltd.	33 Edgewater Street Ottawa ON K2L 1V7	WNW	241.96	<u>27</u>
Actum Ltd.	30 Edgewater Street Ottawa ON K2A 3X9	NW	242.62	<u>28</u>
Actum Ltd.	30 Edgewater St. Kanata ON K2A 3X9	NW	242.62	<u>28</u>

Lower Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	Map Key
Toromont Industries Ltd.	5 Edgewater Street Ottawa ON L4K 1B7	SSE	97.73	1
Toromont Industries Ltd.	5 Edgewater St Ottawa ON L4K 5E1	SSE	97.73	<u>1</u>
City of Ottawa	Terry Fox Drive and Hazeldean Road Ottawa ON K1P 1J1	S	225.29	<u>22</u>

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Jan 31, 2021 has found that there are 8 EHS site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	<u>Address</u>	Direction	Distance (m)	<u>Map Key</u>
	6 Edgewater Street Kanata ON K2L 1V8	Е	106.39	2
	24 Edgewater Street Kanata ON K2L 1V8	NNW	107.09	<u>3</u>
	24 Edgewater St Ottawa ON K2L1V8	NW	164.19	<u>10</u>
	29 Edgewater St Ottawa ON K2L1V7	WNW	201.69	<u>16</u>
	30 Edgewater St Ottawa ON K2L1V8	NNW	216.38	<u>18</u>
	30 Edgewater St Ottawa ON K2L 1V8	NW	242.62	<u>28</u>
	30 Edgewater Street Kanata ON K2L 1V8	NW	242.62	<u>28</u>
	30 Edgewater Street, Suite 106 Ottawa ON	NW	242.62	<u>28</u>

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Jul 31, 2020 has found that there are 5 EXP site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	<u>Address</u>	Direction	Distance (m)	<u>Map Key</u>
CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	Е	191.26	<u>15</u>
CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	E	191.26	<u>15</u>

Equal/Higher Elevation	<u>Address</u>	Direction	Distance (m)	Map Key
CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	Е	191.26	<u>15</u>

Lower Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	Map Key
GEO W CROTHERS LTD	5 EDGEWATER DR KANATA K2L 1V7 ON CA ON	SSE	97.73	1
CROTHERS LTD	5 EDGEWATER DR KANATA K2L 1V7 ON CA ON	SSE	97.73	1

FST - Fuel Storage Tank

A search of the FST database, dated Jul 31, 2020 has found that there are 5 FST site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation CHRISTOPHER ARMSTRONG ENT. INC	Address 501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	<u>Direction</u> E	<u>Distance (m)</u> 191.26	<u>Map Key</u> <u>15</u>
CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	Е	191.26	<u>15</u>
CHRISTOPHER ARMSTRONG ENT. INC	501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA ON	Е	191.26	<u>15</u>

Lower Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	Map Key
CROTHERS LTD	5 EDGEWATER DR KANATA K2L 1V7 ON CA ON	SSE	97.73	1
GEO W CROTHERS LTD	5 EDGEWATER DR KANATA K2L 1V7 ON CA ON	SSE	97.73	1

Order No: 21062300392

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Apr 30, 2021 has found that there are 38 GEN site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation ABBOTSFORD MOVING (OUT OF		<u>Direction</u> NNW	<u>Distance (m)</u> 107.09	Map Key
BUSINESS)	KANATA ON K2L 1V8			
CHIROPRACTIC CLINIC	501B HAZELDEAN CENTRE KANATA ON K2L 1V6	E	191.26	<u>15</u>
CHIROPRACTIC (OUT OF BUSINESS) 07-179	501B HAZELDEAN CENTRE KANATA ON K2L 1V6	E	191.26	<u>15</u>
GTA'S Finest Restoration Services	33 Edgewater Street	WNW	241.96	27
(ottawa) Inc.	Ottawa ON K2L 1V7		211.00	<u>21</u>
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW	242.62	<u>28</u>
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON	NW	242.62	<u>28</u>
IOLINICON CONTROL C	20 EDOEWATED CHITE 400	NIA/	242.02	
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON	NW	242.62	<u>28</u>
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON	NW	242.62	<u>28</u>
	NANATA ON			
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW	242.62	<u>28</u>
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON	NW	242.62	<u>28</u>
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108	NW	242.62	28
	KANATA ON K2L 1V8			_

Equal/Higher Elevation	<u>Address</u>	Direction	Distance (m)	<u>Map Key</u>
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW	242.62	<u>28</u>
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW	242.62	28
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW	242.62	<u>28</u>
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW	242.62	28
JOHNSON CONTROLS	30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8	NW	242.62	28
Rockwell Collins Canada Inc	30 EDGEWATER ST SUITE 104 KANATA ON K2L 1V8	NW	242.62	28
Rockwell Collins Canada Inc	30 EDGEWATER ST SUITE 104 KANATA ON K2L 1V8	NW	242.62	<u>28</u>
Lower Elevation TOROMONT	Address 5 EDGEWATER DRIVE KANATA ON K2L 1V7	<u>Direction</u> SSE	<u>Distance (m)</u> 97.73	<u>Map Key</u> <u>1</u>
TOROMONT	5 EDGEWATER DRIVE KANATA ON	SSE	97.73	1
TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1
TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1

TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1
TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1
TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1
TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	<u>1</u>
CROTHERS LIMITED	5 EDGEWATER ST. KANATA ON K2L 1V7	SSE	97.73	1
CROTHERS LIMITED	5 EDGEWATER ST. KANATA ON K2L 1V7	SSE	97.73	1
CROTHERS(SEE & USE ON1767304) 11-220	5 EDGEWATER ST. KANATA ON K2L 1V7	SSE	97.73	1
CROTHERS LIMITED (SEE & USE ON1767304)	5 EDGEWATER STREET KANATA ON K2L 1V7	SSE	97.73	1
TOROMONT INDUSTRIES LTD.	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1
TOROMONT INDUSTRIES LTD.	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1
TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1
TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	<u>1</u>
TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	1

TOROMONT	5 EDGEWATER DRIVE KANATA ON K2L 1V7	SSE	97.73	<u>1</u>
ONE HOUR MOTO PHOTO	500 HAZELDEAN ROAD, UNIT #3 KANATA ON	SE	237.80	<u>26</u>
ONE HOUR MOTO PHOTO	500 HAZELDEAN ROAD, UNIT 3 KANATA ON	SE	237.80	<u>26</u>

HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 1 HINC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	Map Key
	21 YOUNG ROAD	NNE	173.97	<u>11</u>

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated Jul 31, 2020 has found that there are 1 INC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	<u>Map Key</u>
	501 HAZELDEAN RD, KANATA ON	E	191.26	<u>15</u>

PES - Pesticide Register

A search of the PES database, dated Oct 2011-May 31, 2021 has found that there are 3 PES site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	<u>Address</u>	Direction	Distance (m)	Map Key
CASHWAY BUILDING CENTRES	6 EDGEWATER STREET KANATA ON K2L 1V8	ESE	158.84	8
CANADA CASHWAY LUMBER COMPANY	6 EDGEWATER STREET HAZELDEAN ON	ESE	158.84	<u>8</u>

Equal/Higher Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	<u>Map Key</u>
CASHWAY BUILDING CENTRES	6 EDGEWATER STREET KANATA ON K2L1V8	ESE	158.84	<u>8</u>

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 2 PRT site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	<u>Address</u>	Direction	Distance (m)	Map Key
CROTHERS LTD	5 EDGEWATER DR KANATA ON K2L 1V7	SSE	97.73	1
GEO W CROTHERS LTD	5 EDGEWATER DR KANATA ON K2L 1V7	SSE	97.73	1

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 3 SCT site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation Skywave Mobile Comm. Inc.	Address 30 Edgewater St Suite 110 Kanata ON K2L 1V8	<u>Direction</u> NW	<u>Distance (m)</u> 242.62	<u>Map Key</u> <u>28</u>
Espial Group Inc.	30 Edgewater St Suite 114 Kanata ON K2L 1V8	NW	242.62	<u>28</u>
Lower Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	Map Key
KANATA UPHOLSTERY	500 HAZELDEAN RD KANATA ON K2L 2B5	SE	237.80	<u>26</u>

SPL - Ontario Spills

A search of the SPL database, dated 1988-Aug 2020 has found that there are 3 SPL site(s) within approximately 0.25 kilometers of the project property.


Equal/Higher Elevation	Address	<u>Direction</u>	Distance (m)	Map Key
	21 Young Rd Ottawa ON	NNE	173.97	<u>11</u>
Waste Services (CA) Inc.	501 Hazeldean Road Ottawa ON K2L 1V6	E	191.26	<u>15</u>
Lower Elevation	<u>Address</u>	Direction	Distance (m)	Map Key
	Ottawa ON	S	233.46	<u>24</u>

WWIS - Water Well Information System

A search of the WWIS database, dated Apr 30, 2021 has found that there are 9 WWIS site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address 6 EDGEWATER ST lot 30 con 12 OTTAWA ON Well ID: 7326158	<u>Direction</u> E	<u>Distance (m)</u> 127.10	Map Key 4
	lot 30 con 12 ON <i>Well ID</i> : 1514168	Е	130.30	<u>5</u>
	lot 30 con 12 ON	ESE	156.81	<u>7</u>
	Well ID: 1514897 lot 30 con 12 ON	NE	179.57	12
	Well ID: 1502990	_	040.54	
	lot 30 con 12 ON <i>Well ID:</i> 1514055	Е	212.51	<u>17</u>
	lot 30 con 12 ON <i>Well ID</i> : 1509894	NNE	217.61	<u>19</u>
	lot 30 con 12 ON	ESE	223.06	<u>21</u>


Equal/Higher Elevation	<u>Address</u>	<u>Direction</u>	Distance (m)	<u>Map Key</u>
	Well ID: 1502987			
	lot 30 con 12 ON	NNE	229.58	<u>23</u>
	Well ID: 1502988			
	lot 31 con 12 ON	NE	236.66	<u>25</u>
	Well ID: 1502995			




Map: 0.25 Kilometer Radius

Order Number: 21062300392

Address: 16 Edgewater Street, Kanata, ON



ERIS



Aerial Year: 2020

Source: ESRI World Imagery

Address: 16 Edgewater Street, Kanata, ON

Order Number: 21062300392



Topographic Map

Address: 16 Edgewater Street, ON

Source: ESRI World Topographic Map

Order Number: 21062300392



Detail Report

Мар Кеу	Numbe Record		Elev/Diff (m)	Site	DB
1	1 of 34	SSE/97.7	103.5 / -1.62	TOROMONT INDUSTRIES LIMITED 5 EDGEWATER STREET KANATA CITY ON K2L 1V7	CA
Certificate #	:	8-4013-95-			
Application	Year:	95			
Issue Date: Approval Ty	noi	8/16/1995 Industrial air			
Status:	μ e .	Revised			
Application	Туре:				
Client Name					
Client Addre	ess:				
Client City: Client Posta	l Code				
Project Desc		WASTE OIL FUR	NACE MODEL CB-5	5000	
Contaminan	ts:			se, Nickel, Carbon Monoxide, Nitrogen Oxides, Sulphur Die	oxide, Suspended
Emission Co	ontrol:	Particulate Matter	, Arsenic, Cadmium,	Copper	
Linission oc	niu Oi.				
1	2 of 34	SSE/97.7	103.5 / -1.62	GEO W CROTHERS LTD 5 EDGEWATER DR KANATA ON K2L 1V7	PRT
Location ID:		6723			
Type: Expiry Date:		private			
Capacity (L)		4546.00			
Licence #:		0001012622			
1	3 of 34	SSE/97.7	103.5 / -1.62	CROTHERS LTD 5 EDGEWATER DR KANATA ON K2L 1V7	PRT
Location ID:		6723			
Type:		retail			
Expiry Date:					
Capacity (L)	:	4500			
Licence #:		0001031533			
1	4 of 34	SSE/97.7	103.5 / -1.62	Toromont Industries Ltd. 5 Edgewater Street Ottawa Ontario Ottawa ON	EBR
				Decision Posted:	
FRR Pagistr	v No:	IA02F0312			
EBR Registr Ministry Ref		IA02E0312 1536-586RG6			
EBR Registr Ministry Ref Notice Type	No:			Exception Posted: Section:	
Ministry Ref Notice Type Notice Stage	No: : e:	1536-586RG6 Instrument Decision		Exception Posted: Section: Act 1:	
Ministry Ref Notice Type Notice Stage Notice Date:	No: : e:	1536-586RG6 Instrument Decision November 26, 2003		Exception Posted: Section: Act 1: Act 2:	
Ministry Ref Notice Type Notice Stage	No: : e:	1536-586RG6 Instrument Decision		Exception Posted: Section: Act 1:	

Number of Direction/ Elev/Diff Site DΒ Map Key Records Distance (m) (m)

Off Instrument Name:

Posted By: Company Name: Site Address:

Toromont Industries Ltd.

Location Other: Proponent Name:

Proponent Address: Comment Period:

3131 Highway 7 West, Vaughan Ontario, L4K 1B7

URL:

Site Location Details:

5 Edgewater Street Ottawa Ontario Ottawa

5 of 34 SSE/97.7 103.5 / -1.62 **CROTHERS LIMITED** 1

5 EDGEWATER ST. KANATA ON K2L 1V7

KANATA ON K2L 1V7

PO Box No:

Choice of Contact: Co Admin:

Phone No Admin:

Country:

Choice of Contact:

Phone No Admin:

Co Admin:

GEN

Order No: 21062300392

ON0063609 Generator No: PO Box No: Status: Country:

Approval Years:

86,87,88,89

Contam. Facility: MHSW Facility:

SIC Code: 3242

SIC Description: COMMERICAL TRAILER

Detail(s)

Waste Class: 213

PETROLEUM DISTILLATES Waste Class Desc:

Waste Class:

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

6 of 34 SSE/97.7 103.5 / -1.62 **CROTHERS LIMITED** 1 **GEN** 5 EDGEWATER ST.

ON0063609 Generator No:

Status: Approval Years:

90 Contam. Facility: MHSW Facility:

SIC Code: 3242

SIC Description: COMMERICAL TRAILER

Detail(s)

Waste Class:

AROMATIC SOLVENTS Waste Class Desc:

Waste Class:

Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251

Waste Class Desc: **OIL SKIMMINGS & SLUDGES**

Waste Class: 252

Number of Elev/Diff Site DΒ Map Key Direction/ Records Distance (m) (m) WASTE OILS & LUBRICANTS Waste Class Desc: 7 of 34 SSE/97.7 103.5 / -1.62 CROTHERS(SEE & USE ON1767304) 11-220 1 **GEN** 5 EDGEWATER ST. KANATA ON K2L 1V7 Generator No: ON0063609 PO Box No: Status: Country: Approval Years: 92,93,94,95,96,97 Choice of Contact: Contam. Facility: Co Admin: MHSW Facility: Phone No Admin: SIC Code: 3242 SIC Description: **COMMERICAL TRAILER** Detail(s) Waste Class: 211 AROMATIC SOLVENTS Waste Class Desc: Waste Class: 212 Waste Class Desc: ALIPHATIC SOLVENTS Waste Class: 213 PETROLEUM DISTILLATES Waste Class Desc: Waste Class: 251 Waste Class Desc: **OIL SKIMMINGS & SLUDGES** Waste Class: Waste Class Desc: WASTE OILS & LUBRICANTS CROTHERS LIMITED (SEE & USE ON1767304) 1 8 of 34 SSE/97.7 103.5 / -1.62 **GEN 5 EDGEWATER STREET** KANATA ON K2L 1V7 ON0063609 Generator No: PO Box No: Status: Country: Choice of Contact: Approval Years: 98 Contam. Facility: Co Admin: MHSW Facility: Phone No Admin: SIC Code: 3242 SIC Description: COMMERICAL TRAILER Detail(s) Waste Class: Waste Class Desc: OIL SKIMMINGS & SLUDGES Waste Class: AROMATIC SOLVENTS Waste Class Desc: Waste Class: Waste Class Desc: ALIPHATIC SOLVENTS Waste Class: 213 Waste Class Desc: PETROLEUM DISTILLATES

1 9 of 34 SSE/97.7 103.5 / -1.62 TOROMONT INDUSTRIES LTD. 5 EDGEWATER DRIVE

Order No: 21062300392

WASTE OILS & LUBRICANTS

252

Waste Class:

Waste Class Desc:

Direction/ Number of Elev/Diff Site DΒ Map Key

Records Distance (m) (m)

KANATA ON K2L 1V7

Choice of Contact:

PO Box No:

Country:

Co Admin: Phone No Admin:

Generator No: ON1767304 Status:

Approval Years:

93,94,95,96,97,98

Contam. Facility: MHSW Facility:

3242 SIC Code:

SIC Description:

COMMERICAL TRAILER

Detail(s)

Waste Class: 211

AROMATIC SOLVENTS Waste Class Desc:

Waste Class:

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213

PETROLEUM DISTILLATES Waste Class Desc:

Waste Class:

OIL SKIMMINGS & SLUDGES Waste Class Desc:

Waste Class:

Waste Class Desc: WASTE OILS & LUBRICANTS

1 10 of 34 SSE/97.7 103.5 / -1.62

TOROMONT INDUSTRIES LTD.__ **5 EDGEWATER DRIVE**

Choice of Contact:

Phone No Admin:

PO Box No:

Co Admin:

Country:

KANATA ON K2L 1V7

GEN

GEN

ON1767304 Generator No:

Status:

Approval Years:

Contam. Facility:

MHSW Facility:

SIC Code: 3242

SIC Description: **COMMERICAL TRAILER**

99

Detail(s)

Waste Class: 211

AROMATIC SOLVENTS Waste Class Desc:

Waste Class:

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class:

Waste Class Desc: PETROLEUM DISTILLATES

Waste Class:

LIGHT FUELS Waste Class Desc:

Waste Class:

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class:

Waste Class Desc: WASTE OILS & LUBRICANTS

1 11 of 34 SSE/97.7 103.5 / -1.62 **TOROMONT**

5 EDGEWATER DRIVE

KANATA ON K2L 1V7

Order No: 21062300392 erisinfo.com | Environmental Risk Information Services

Map Key Number of Direction/ Elev/Diff Site DΒ

PO Box No:

Choice of Contact:

Phone No Admin:

Toromont Industries Ltd.

5 Edgewater Street Ottawa ON

Country:

Co Admin:

Records Distance (m) (m)

Generator No: ON1767304

Status: Approval Years:

00,01,02,03,04,05,06,07,08

Contam. Facility: MHSW Facility:

3242 SIC Code:

SIC Description: **COMMERICAL TRAILER**

Detail(s)

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class:

Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212

ALIPHATIC SOLVENTS Waste Class Desc:

Waste Class:

PETROLEUM DISTILLATES Waste Class Desc:

Waste Class:

LIGHT FUELS Waste Class Desc:

Waste Class: 251

Waste Class Desc: **OIL SKIMMINGS & SLUDGES**

Waste Class:

Waste Class Desc: WASTE OILS & LUBRICANTS

12 of 34 SSE/97.7 103.5 / -1.62 1

9954-5DXHTJ Certificate #: Application Year: 2003 Issue Date: 11/24/2003

Approval Type: Air Status: Approved

Application Type: Client Name: Client Address: Client City:

Client Postal Code: **Project Description:** Contaminants: **Emission Control:**

> 13 of 34 SSE/97.7 103.5 / -1.62 **CROTHERS LTD DTNK 5 EDGEWATER DR**

> > KANATA ON

Delisted Expired Fuel Safety Facilities

1

Instance No: 9320532 Status: **EXPIRED** Instance ID: 380076 Instance Type: FS Facility CA

DB Map Key Number of Direction/ Elev/Diff Site Records Distance (m) (m) Fuels Safety Private Fuel Outlet - Self Serve Description: TSSA Program Area:

Maximum Hazard Rank: Facility Type:

Expired Date: Original Source:

EXP

Record Date: Up to Mar 2012

SSE/97.7 GEO W CROTHERS LTD 14 of 34 103.5 / -1.62 1 **DTNK** 5 EDGEWATER DR

KANATA ON

Delisted Expired Fuel Safety

Facilities

Instance No: 9251671 **EXPIRED** Status: Instance ID: 383059 FS Facility Instance Type:

Description: TSSA Program Area:

Maximum Hazard Rank:

Facility Type: Expired Date: Original Source:

EXP

Record Date: Up to Mar 2012

SSE/97.7 **CROTHERS LTD** 1 15 of 34 103.5 / -1.62 **DTNK 5 EDGEWATER DR**

KANATA ON

Fuels Safety Private Fuel Outlet - Self Serve

Delisted Expired Fuel Safety

Facilities

Instance No: 10797820 **EXPIRED** Status: Instance ID: 40550 Instance Type: FS Piping FS Piping Description:

TSSA Program Area: Maximum Hazard Rank:

Facility Type: Expired Date:

Original Source:

Record Date: Up to Mar 2012

16 of 34 SSE/97.7 103.5 / -1.62 GEO W CROTHERS LTD 1 **DTNK 5 EDGEWATER DR**

KANATA ON

Delisted Expired Fuel Safety

Facilities

10797803 Instance No: **EXPIRED** Status: Instance ID: 40731 Instance Type: FS Piping Description: FS Piping

Number of Direction/ Elev/Diff Site DΒ Map Key

TSSA Program Area: Maximum Hazard Rank:

Facility Type: Expired Date:

Original Source: **EXP**

Records

Record Date: Up to Mar 2012

1 17 of 34 SSE/97.7 103.5 / -1.62 **TOROMONT**

5 EDGEWATER DRIVE KANATA ON K2L 1V7

GEN

Order No: 21062300392

Generator No: ON1767304 PO Box No: Status:

Distance (m)

Country:

(m)

Approval Years: 2009 Choice of Contact: Contam. Facility: Co Admin: MHSW Facility: Phone No Admin:

SIC Code: 488490

SIC Description: Other Support Activities for Road Transportation

Detail(s)

Waste Class:

AROMATIC SOLVENTS Waste Class Desc:

Waste Class:

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class:

Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221

LIGHT FUELS Waste Class Desc:

Waste Class:

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class:

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

18 of 34 SSE/97.7 103.5 / -1.62 **TOROMONT** 1 **GEN**

5 EDGEWATER DRIVE KANATA ON K2L 1V7

Generator No: ON1767304 PO Box No: Country: Status:

2010 Choice of Contact: Approval Years: Contam. Facility: Co Admin: MHSW Facility: Phone No Admin:

SIC Code: 488490

SIC Description: Other Support Activities for Road Transportation

Detail(s)

Waste Class: 221

Waste Class Desc: LIGHT FUELS

251 Waste Class:

OIL SKIMMINGS & SLUDGES Waste Class Desc:

Waste Class: 211 Map Key Number of Direction/ Elev/Diff Site DB

Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 263

Records

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213

Waste Class Desc: PETROLEUM DISTILLATES

1 19 of 34 SSE/97.7 103.5 / -1.62 TOROMONT

Distance (m)

(m)

5 EDGEWATER DRIVE KANATA ON K2L 1V7 **GEN**

GEN

Order No: 21062300392

Generator No: ON1767304 PO Box No:

Status: Country: Approval Years: 2011 Choice of Contact:

Contam. Facility: Co Admin:

MHSW Facility: Phone No Admin:

SIC Code: 488490

SIC Description: Other Support Activities for Road Transportation

Detail(s)

Waste Class: 251

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213

Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 221

Waste Class Desc: LIGHT FUELS

Waste Class: 211

Waste Class Desc: AROMATIC SOLVENTS

1 20 of 34 SSE/97.7 103.5 / -1.62 TOROMONT

5 EDGEWATER DRIVE KANATA ON K2L 1V7

Generator No: ON1767304 PO Box No: Status: Country:

2012 Choice of Contact: Co Admin:

Contam. Facility: Co Admin: MHSW Facility: Phone No Admin:

SIC Code: 488490

SIC Description: Other Support Activities for Road Transportation

Detail(s)

Approval Years:

Number of Elev/Diff Site DΒ Map Key Direction/ Records Distance (m) (m)

Waste Class: 251

Waste Class Desc: **OIL SKIMMINGS & SLUDGES**

Waste Class:

Waste Class Desc: PETROLEUM DISTILLATES

Waste Class:

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class:

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 221

Waste Class Desc: LIGHT FUELS

Waste Class: 211

Waste Class Desc: AROMATIC SOLVENTS

1 21 of 34 SSE/97.7 103.5 / -1.62 **TOROMONT GEN 5 EDGEWATER DRIVE**

KANATA ON

Generator No: ON1767304 PO Box No: Status: Country:

Approval Years: 2013 Choice of Contact: Co Admin: Contam. Facility: MHSW Facility: Phone No Admin:

488490 SIC Code:

SIC Description: OTHER SUPPORT ACTIVITIES FOR ROAD TRANSPORTATION

Detail(s)

Waste Class: 213

Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252

WASTE OILS & LUBRICANTS Waste Class Desc:

Waste Class:

LIGHT FUELS Waste Class Desc:

Waste Class:

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class:

OIL SKIMMINGS & SLUDGES Waste Class Desc:

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 211

Waste Class Desc: AROMATIC SOLVENTS

GEO W CROTHERS LTD 22 of 34 SSE/97.7 103.5 / -1.62 1

5 EDGEWATER DR KANATA K2L 1V7 ON CA

EXP

Order No: 21062300392

ON

10797794 **NULL** Instance No: Model: **EXPIRED** Quantity: Status:

EΑ Instance ID: Unit of Measure:

Direction/ Elev/Diff Site DΒ Map Key Number of Records Distance (m) (m)

Piping Steel:

Piping Galvanized:

Tank Single Wall St:

Tank Underground:

Panam Venue Nm:

Panam Related:

Piping Underground:

NULL Instance Type: Fuel Type2: Instance Creation Dt: 1/10/1990 Fuel Type3: NULL

1/10/1990 Instance Install Dt:

Item:

Item Description: FS Liquid Fuel Tank FS LIQUID FUEL TANK Facility Type:

Overfill Prot Type: **NULL**

7/5/2009 1:21:07 AM Creation Date: Expired Date:

Manufacturer:

NULL

FS Liquid Fuel Tank Source: Description: UNDERGROUND TANK

Serial No: NULL Ulc Standard: **NULL**

Facility Location: 5 EDGEWATER DR KANATA K2L 1V7 ON CA

1 23 of 34 SSE/97.7 103.5 / -1.62 **CROTHERS LTD**

5 EDGEWATER DR KANATA K2L 1V7 ON CA

NULL

NULL

NULL

-75.89724

45.296406

EXP

ECA

GEN

NULL

NULL

ON

Fuel Type3:

Piping Steel: Piping Galvanized:

Tank Single Wall St:

Piping Underground:

Tank Underground:

Panam Venue Nm:

Panam Related:

Instance No: 10797811 Model: **NULL EXPIRED** Quantity: Status: 1 Instance ID: Unit of Measure: EΑ Instance Type: Fuel Type2: NULL

Instance Creation Dt: 9/6/1990 Instance Install Dt: 9/6/1990

Item: FS Liquid Fuel Tank

Facility Type:

Item Description: FS LIQUID FUEL TANK Overfill Prot Type: NULL

Creation Date: 7/5/2009 1:21:04 AM

Expired Date: Manufacturer: NULL

Source:

FS Liquid Fuel Tank Description: UNDERGROUND TANK

Serial No: **NULL** Ulc Standard: NULL

Facility Location: 5 EDGEWATER DR KANATA K2L 1V7 ON CA

24 of 34 SSE/97.7 103.5 / -1.62 Toromont Industries Ltd. 1

5 Edgewater Street Ottawa ON L4K 1B7

Longitude:

Geometry X:

Geometry Y:

Latitude:

Approval No: 9954-5DXHTJ Ottawa **MOE District:** Approval Date: 2003-11-24 City:

Approved Status: Record Type: **ECA** IDS Link Source:

SWP Area Name: Mississippi Valley Approval Type: **ECA-AIR** AIR

Project Type: Business Name: Toromont Industries Ltd. Address: 5 Edgewater Street

Full Address:

1

41

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1536-586RG6-14.pdf

25 of 34 SSE/97.7 103.5 / -1.62 **TOROMONT**

5 EDGEWATER DRIVE KANATA ON K2L 1V7

Map Key Number of Direction/ Elev/Diff Site DB

Records Distance (m) (m)

Generator No: ON1767304 PO Box No:

Status:Country:CanadaApproval Years:2016Choice of Contact:CO_OFFICIALContam. Facility:NoCo Admin:Steve CassidyMHSW Facility:NoPhone No Admin:613-836-5171 Ext.

SIC Code: 488490

SIC Description: OTHER SUPPORT ACTIVITIES FOR ROAD TRANSPORTATION

Detail(s)

Waste Class: 213

Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 22

Waste Class Desc: LIGHT FUELS

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 251

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 211

Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 331

Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

1 26 of 34 SSE/97.7 103.5/-1.62 TOROMONT GEN

5 EDGEWATER DRIVE KANATA ON K2L 1V7

Order No: 21062300392

PO Box No:

Generator No: ON1767304

Status:Country:CanadaApproval Years:2015Choice of Contact:CO_OFFICIALContam. Facility:NoCo Admin:Steve CassidyMHSW Facility:NoPhone No Admin:613-836-5171 Ext.

SIC Code: 488490

SIC Description: OTHER SUPPORT ACTIVITIES FOR ROAD TRANSPORTATION

Detail(s)

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 221

Waste Class Desc: LIGHT FUELS

Waste Class: 251

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 213

Waste Class Desc: PETROLEUM DISTILLATES

Number of Direction/ Elev/Diff Site DΒ Map Key Records Distance (m)

211 Waste Class:

Waste Class Desc: AROMATIC SOLVENTS

Waste Class:

Waste Class Desc: WASTE OILS & LUBRICANTS

1 27 of 34 SSE/97.7 103.5 / -1.62 **TOROMONT**

5 EDGEWATER DRIVE KANATA ON K2L 1V7

GEN

Order No: 21062300392

Generator No: ON1767304 PO Box No:

Status: Country:

Canada Approval Years: 2014 Choice of Contact: CO_OFFICIAL Contam. Facility: Co Admin: Steve Cassidy No MHSW Facility: 613-836-5171 Ext. No Phone No Admin:

488490 SIC Code:

SIC Description: OTHER SUPPORT ACTIVITIES FOR ROAD TRANSPORTATION

Detail(s)

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 211

AROMATIC SOLVENTS Waste Class Desc:

Waste Class:

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 213

Waste Class Desc: PETROLEUM DISTILLATES

Waste Class:

Waste Class Desc: **OIL SKIMMINGS & SLUDGES**

Waste Class:

Waste Class Desc: LIGHT FUELS

Waste Class: 212

ALIPHATIC SOLVENTS Waste Class Desc:

28 of 34 SSE/97.7 103.5 / -1.62 **TOROMONT** 1 GEN

5 EDGEWATER DRIVE KANATA ON K2L 1V7

PO Box No:

Generator No: ON1767304

Status: Registered Country: Canada As of Dec 2018 Choice of Contact:

Approval Years: Contam. Facility: MHSW Facility: SIC Code:

SIC Description:

Co Admin: Phone No Admin:

Detail(s)

Waste Class: 212 L

Waste Class Desc: Aliphatic solvents and residues

Waste Class: 221 I Light fuels Waste Class Desc:

Waste Class:

Waste Class Desc: Waste oils/sludges (petroleum based)

Number of Direction/ Elev/Diff Site DΒ Map Key Records Distance (m) (m)

Waste Class Desc: Waste crankcase oils and lubricants

252 L

Waste Class: 263 I

Waste Class:

Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I

Waste Class Desc: Waste compressed gases including cylinders

1 29 of 34 SSE/97.7 103.5 / -1.62 TOROMONT INDUSTRIES LTD./ INDUSTRIES **EASR**

TOROMONT LTEE 5 Edgewater DR Kanata ON K2L 1V7

Approval No: R-010-7110218068 SWP Area Name: Mississippi Valley

Status: REGISTERED **MOE District:** Ottawa 2017-08-23 Date: Municipality: Kanata Record Type: **EASR** Latitude: 45.29472222 Link Source: **MOFA** Longitude: -75.89444444

Air Emissions Geometry X: Project Type: Full Address: Geometry Y:

EASR-Air Emissions Approval Type:

Full PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2042133

30 of 34 SSE/97.7 103.5 / -1.62 Toromont Industries Ltd. 1

5 Edgewater St Ottawa ON L4K 5E1 **ECA**

GEN

Order No: 21062300392

8595-ANDHRR **MOE District:** Ottawa Approval No: City:

2017-06-30 Approval Date: Approved Status:

Longitude: -75.89724 Record Type: **ECA** Latitude: 45.296406 Link Source: **IDS** Geometry X: Mississippi Valley SWP Area Name: Geometry Y:

Approval Type: **ECA-INDUSTRIAL SEWAGE WORKS** INDUSTRIAL SEWAGE WORKS Project Type:

Business Name: Toromont Industries Ltd. Address: 5 Edgewater St

Full Address:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4554-ALSQQK-14.pdf

31 of 34 SSE/97.7 103.5 / -1.62 **TOROMONT** 1

5 EDGEWATER DRIVE KANATA ON K2L 1V7

Generator No: ON1767304 PO Box No: Registered Country: Canada Status:

Approval Years: As of Jul 2020 Choice of Contact: Co Admin: Contam. Facility: MHSW Facility: Phone No Admin: SIC Code:

SIC Description:

Detail(s)

Waste Class: 212 L

Waste Class Desc: Aliphatic solvents and residues

Waste Class: 331 I

Waste Class Desc: Waste compressed gases including cylinders

Number of Elev/Diff Site DΒ Map Key Direction/ Records Distance (m) (m)

Waste Class:

Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 252 L

Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 263 I

Waste Class Desc: Misc. waste organic chemicals

Waste Class: 221 I Waste Class Desc: Light fuels

32 of 34 SSE/97.7 103.5 / -1.62 **CROTHERS LTD** 1

5 EDGEWATER DR KANATA K2L 1V7 ON CA

Diesel

NULL

NULL

FST

FST

Order No: 21062300392

Manufacturer: Serial No:

Ulc Standard: Quantity:

Fuel Type:

Fuel Type2:

Fuel Type3:

Piping Steel:

Piping Galvanized:

Num Underground:

Panam Related:

Panam Venue:

Tanks Single Wall St: Piping Underground:

Unit of Measure:

10797811 Instance No:

Status: Cont Name: Instance Type:

Item: FS LIQUID FUEL TANK Item Description: FS Liquid Fuel Tank Liquid Fuel Single Wall UST

Tank Type: Install Date: 9/6/1990 1974

Install Year:

Years in Service:

Model: NULL Description:

4500 Capacity: Tank Material: Steel

Corrosion Protect: Overfill Protect:

Facility Type:

Facility Location:

Parent Facility Type:

Device Installed Location: 5 EDGEWATER DR KANATA K2L 1V7 ON CA

FS Liquid Fuel Tank

Fuel Storage Tank Details

CROTHERS LTD Owner Account Name:

33 of 34 SSE/97.7 103.5 / -1.62 **GEO W CROTHERS LTD** 1

5 EDGEWATER DR KANATA K2L 1V7 ON CA

Instance No: 10797794

Status: Cont Name: Instance Type:

FS LIQUID FUEL TANK Item: Item Description: FS Liquid Fuel Tank Liquid Fuel Single Wall UST Tank Type:

Install Date: 1/10/1990 Install Year: 1974

Years in Service:

Model: **NULL** Description:

Capacity: 4546 Tank Material: Steel

Corrosion Protect: Overfill Protect:

FS Liquid Fuel Tank Facility Type:

Manufacturer: Serial No: Ulc Standard: Quantity: Unit of Measure:

Fuel Type: Diesel NULL Fuel Type2: Fuel Type3: NULL

Piping Steel: Piping Galvanized: Tanks Single Wall St: Piping Underground: Num Underground: Panam Related: Panam Venue:

Map Key Number of Direction/ Elev/Diff Site DB

Parent Facility Type: Facility Location:

Device Installed Location: 5 EDGEWATER DR KANATA K2L 1V7 ON CA

Distance (m)

(m)

Fuel Storage Tank Details

Records

Owner Account Name: GEO W CROTHERS LTD

1 34 of 34 SSE/97.7 103.5 / -1.62 TOROMONT 5 EDGEWATER DRIVE GEN

KANATA ON K2L 1V7

Generator No: ON1767304 PO Box No:

Status: Registered Country: Canada

Approval Years:As of Apr 2021Choice of Contact:Contam. Facility:Co Admin:MHSW Facility:Phone No Admin:SIC Code:

Detail(s)

SIC Description:

Waste Class: 263 I

Waste Class Desc: Misc. waste organic chemicals

Waste Class: 212 l

Waste Class Desc: Aliphatic solvents and residues

Waste Class: 251 L

Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 252 L

Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 221 I
Waste Class Desc: Light fuels

Waste Class: 331 I

Waste Class Desc: Waste compressed gases including cylinders

2 1 of 1 E/106.4 106.1 / 1.04 6 Edgewater Street
Kanata ON K2L 1V8

Order No:20181121032Nearest Intersection:Status:CMunicipality:

 Report Type:
 Standard Report
 Client Prov/State:
 ON

 Report Date:
 27-NOV-18
 Search Radius (km):
 .25

 Date Received:
 21-NOV-18
 X:
 -75.894583

 Date Received:
 21-NOV-18
 X:
 -75.894583

 Previous Site Name:
 Y:
 45.295492

Lot/Building Size:

Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

3 1 of 2 NNW/107.1 107.6 / 2.54 ABBOTSFORD MOVING (OUT OF BUSINESS)
34 EDGEWATER STREET GEN

24 EDGEWATER STREET KANATA ON K2L 1V8

Order No: 21062300392

Generator No: ON2038700 PO Box No: Status: Country:

Approval Years: 95,96,97,98 Choice of Contact:
Contam. Facility: Co Admin:
MHSW Facility: Phone No Admin:

Number of Direction/ Elev/Diff Site DΒ Map Key

4561 SIC Code:

SIC Description: GEN. FREIGHT TRUCK.

Distance (m)

Detail(s)

Waste Class: 252

Records

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

2 of 2 NNW/107.1 107.6 / 2.54 3 24 Edgewater Street **EHS** Kanata ON K2L 1V8

Order No: 21011900019 Status: C

Report Type: Standard Report Report Date: 22-JAN-21 Date Received: 19-JAN-21

Previous Site Name: Lot/Building Size: Additional Info Ordered: Nearest Intersection: Municipality: Client Prov/State: ON Search Radius (km): .25

-75.8963069 X: 45.2965164 Y:

1 of 1 E/127.1 6 EDGEWATER ST lot 30 con 12 4 107.6 / 2.50 **WWIS** OTTAWA ON

Well ID: 7326158

Construction Date:

Primary Water Use: Test Hole Sec. Water Use: Monitoring Test Hole Final Well Status:

Water Type:

Casing Material: 7300215 Audit No: A182106 Tag:

Construction Method: Elevation (m): Elevation Reliability:

Depth to Bedrock: Well Depth:

Overburden/Bedrock: Pump Rate: Static Water Level: Flowing (Y/N): Flow Rate: Clear/Cloudy:

Data Entry Status:

Data Src:

1/11/2019 Date Received: Selected Flag: True

Abandonment Rec:

Contractor: 7323 Form Version:

Owner:

6 EDGEWATER ST Street Name:

Order No: 21062300392

County: **OTTAWA GOULBOURN TOWNSHIP**

Municipality: Site Info:

030 Lot: Concession: 12 CON

Concession Name: Easting NAD83: Northing NAD83:

UTM Reliability:

Zone:

https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/732\7326158.pdf PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2018/12/13 2018 Year Completed: Depth (m): 6.096

45.2958010288747 Latitude: Longitude: -75.894339762932 732\7326158.pdf Path:

Bore Hole Information

Bore Hole ID: 1007352723 Elevation: Map Key Number of Direction/ Elev/Diff Site DB
Records Distance (m) (m)

Elevrc:

East83:

North83:

Org CS:

UTMRC:

UTMRC Desc:

Location Method:

18 429876.00

5016200.00

margin of error: 30 m - 100 m

Order No: 21062300392

UTM83

Zone:

DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole:

Date Completed: 13-Dec-2018 00:00:00

Remarks:

Elevrc Desc:

Cluster Kind:

Location Source Date:

Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID: 1007511038

 Layer:
 1

 Color:
 6

 General Color:
 BROWN

 Mat1:
 01

 Most Common Material:
 FILL

 Mat2:
 11

 Mat2 Desc:
 GRAVEL

Mat3: Mat3 Desc:

Formation Top Depth: 0.0 Formation End Depth: 2.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 1007511039

 Layer:
 2

 Color:
 2

 General Color:
 GREY

 Mat1:
 05

 Most Common Material:
 CLAY

 Mat2:
 06

 Mat2 Desc:
 SILT

 Mat3:
 91

Mat3 Desc: WATER-BEARING

Formation Top Depth: 2.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment

Sealing Record

Plug ID: 1007511047

 Layer:
 1

 Plug From:
 0

 Plug To:
 9

 Plug Depth UOM:
 ft

Annular Space/Abandonment

Sealing Record

Plug ID: 1007511048

Map Key Number of Direction/ Elev/Diff Site DB Records Distance (m) (m)

 Layer:
 2

 Plug From:
 9

 Plug To:
 20

 Plug Depth UOM:
 ft

Method of Construction & Well

<u>Use</u>

Method Construction ID: 1007511046

Method Construction Code:6Method Construction:Boring

Other Method Construction:

Pipe Information

Pipe ID: 1007511037

Casing No:

Comment: Alt Name:

Construction Record - Screen

Screen ID: 1007511043

Layer: 1 Slot: 10 Screen Top Depth: 10 Screen End Depth: 20 Screen Material: 5 Screen Depth UOM: ft Screen Diameter UOM: inch Screen Diameter: 2.25

Water Details

Water ID: 1007511041

Layer: Kind Code: Kind:

Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1007511040

 Diameter:
 8.0

 Depth From:
 0.0

 Depth To:
 20.0

 Hole Depth UOM:
 ft

 Hole Diameter UOM:
 inch

##**5**

Well ID: 1514168
Construction Date:

1 of 1

Primary Water Use: Domestic Sec. Water Use: 0

Final Well Status: Water Supply

Water Type: Casing Material: Audit No: lot 30 con 12 ON

106.7 / 1.58

Data Entry Status: Data Src:

Date Received: 8/6/1974
Selected Flag: True

Abandonment Rec:

Contractor: 3658 Form Version: 1

Owner:

erisinfo.com | Environmental Risk Information Services

E/130.3

Order No: 21062300392

WWIS

5

Map Key Number of Direction/ Elev/Diff Site DB
Records Distance (m) (m)

Tag: Street Name:

Construction Method: County: OTTAWA

Elevation (m):Municipality:GOULBOURN TOWNSHIPElevation Reliability:Site Info:

 Depth to Bedrock:
 Lot:
 030

 Well Depth:
 Concession:
 12

 Overburden/Bedrock:
 Concession Name:
 CON.

 Overburden/Bedrock:
 Concession:
 12

 Pump Rate:
 Easting NAD83:

 Static Water Level:
 Northing NAD83:

Flowing (Y/N):
Flow Rate:
UTM Reliability:
Clear/Cloudy:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/151\1514168.pdf

Additional Detail(s) (Map)

 Well Completed Date:
 1974/05/14

 Year Completed:
 1974

 Depth (m):
 32.004

 Latitude:
 45.2954954759443

 Longitude:
 -75.8942762929642

 Path:
 151\1514168.pdf

Bore Hole Information

Bore Hole ID: 10036145 **Elevation:** 102.003547

 DP2BR:
 32.00
 Elevrc:

 Spatial Status:
 Zone:
 18

 Code OB:
 r
 East83:
 429880.60

 Code OB Desc:
 Bedrock
 North83:
 5016166.00

Code OB Desc: Bedrock North83: 5016166.00
Open Hole: Org CS:

 Cluster Kind:
 UTMRC:
 4

 Date Completed:
 14-May-1974 00:00:00
 UTMRC Desc:
 margin of error : 30 m - 100 m

Remarks: Location Method: p4

Elevrc Desc:

Location Source Date: Improvement Location

Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID: 931025490

 Layer:
 2

 Color:
 2

 General Color:
 GREY

 Mat1:
 11

 Most Common Material:
 GRAVEL

 Mat2:
 05

 Mat2 Desc:
 CLAY

 Mat3:
 13

Mat3 Desc:BOULDERSFormation Top Depth:22.0Formation End Depth:32.0Formation End Depth UOM:ft

Overburden and Bedrock

Materials Interval

Formation ID: 931025489

 Layer:
 1

 Color:
 6

 General Color:
 BROWN

 Mat1:
 05

 Most Common Material:
 CLAY

 Mat2:
 85

 Mat2 Desc:
 SOFT

Mat3:

Mat3 Desc:

Formation Top Depth: 0.0 Formation End Depth: 22.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

 Formation ID:
 931025491

 Layer:
 3

 Color:
 2

 General Color:
 GREY

 Mat1:
 15

Most Common Material: LIMESTONE

Mat2: 73 Mat2 Desc: HARD

Mat3: Mat3 Desc:

Formation Top Depth: 32.0 Formation End Depth: 105.0 Formation End Depth UOM: ft

Method of Construction & Well

<u>Use</u>

Method Construction ID: 961514168

Method Construction Code: 5

Method Construction: Air Percussion

Other Method Construction:

Pipe Information

Pipe ID: 10584715

Casing No: Comment: Alt Name:

Construction Record - Casing

Casing ID: 930063857

Layer: 2 Material: 4

Open Hole or Material: OPEN HOLE

Depth From:

Depth To:105Casing Diameter:6Casing Diameter UOM:inchCasing Depth UOM:ft

Construction Record - Casing

 Casing ID:
 930063856

 Layer:
 1

Material:

Open Hole or Material: STEEL

Depth From:
Depth To: 32
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991514168

Pump Set At:

Static Level:6.0Final Level After Pumping:70.0Recommended Pump Depth:70.0Pumping Rate:15.0

Flowing Rate:

Recommended Pump Rate: 5.0 Levels UOM: ft Rate UOM: **GPM** Water State After Test Code: 1 Water State After Test: **CLEAR** Pumping Test Method: Pumping Duration HR: 2 **Pumping Duration MIN:** 0 No Flowing:

Draw Down & Recovery

 Pump Test Detail ID:
 934099061

 Test Type:
 Draw Down

 Test Duration:
 15

 Test Level:
 70.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934899845

 Test Type:
 Draw Down

 Test Duration:
 60

 Test Level:
 70.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934381385

 Test Type:
 Draw Down

 Test Duration:
 30

 Test Level:
 70.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934642376

 Test Type:
 Draw Down

 Test Duration:
 45

 Test Level:
 70.0

 Test Level UOM:
 ft

Water Details

Order No: 21062300392

DB Map Key Number of Direction/ Elev/Diff Site Records Distance (m) (m) Water ID: 933469975 Layer: 2 Kind Code: **FRESH** Kind: Water Found Depth: 88.0 Water Found Depth UOM: ft Water Details Water ID: 933469976 Layer: 3 Kind Code: **FRESH** Kind: Water Found Depth: 102.0 Water Found Depth UOM: Water Details Water ID: 933469974 Layer: Kind Code: Kind: **FRESH** Water Found Depth: 63.0 Water Found Depth UOM: ft 6 1 of 1 WSW/150.6 101.7 / -3.39 **BORE** ON Borehole ID: 609646 Inclin FLG: No OGF ID: 215511262 SP Status: Initial Entry Status: Surv Elev: No Borehole Piezometer: No Type: Primary Name: Use: Completion Date: Municipality: Static Water Level: Lot: Primary Water Use: Township: Sec. Water Use: Latitude DD: 45.294894 Total Depth m: -999 Longitude DD: -75.897582 Depth Ref: **Ground Surface** UTM Zone: 18 Depth Elev: Easting: 429621 Drill Method: Northing: 5016102 Orig Ground Elev m: 102 Location Accuracy: Elev Reliabil Note: Accuracy: Not Applicable **DEM Ground Elev m:** 99.2 Concession: Location D: Survey D: Comments:

Borehole Geology Stratum

Geology Stratum ID: 218383715
Top Depth: 3.7
Bottom Depth: 6.1
Material Color:
Material 1: Bedrock

Material 1: Bedrock
Material 2: Sandstone
Material 3:

Material 3: Material 4:

Gsc Material Description:

Stratum Description: BEDROCK, SANDSTONE.

Mat Consistency: Material Moisture: Material Texture: Non Geo Mat Type: Geologic Formation: Geologic Group: Geologic Period: Depositional Gen:

Order No: 21062300392

Geology Stratum ID: 218383714 Mat Consistency: Top Depth: Material Moisture: 3.7 **Bottom Depth:** Material Texture:

Material Color: Non Geo Mat Type: Material 1: Gravel Geologic Formation: Geologic Group: Material 2: Material 3: Geologic Period: Material 4: Depositional Gen:

Gsc Material Description:

Stratum Description: GRAVEL.

Geology Stratum ID: 218383716 Mat Consistency: Top Depth: 6.1 Material Moisture: Bottom Depth: Material Texture: Material Color: Non Geo Mat Type: Material 1: **Bedrock**

Geologic Formation: Geologic Group: Material 2: Limestone Material 3: Geologic Period: Material 4 Depositional Gen:

Gsc Material Description:

BEDROCK, LIMESTONE. SEISMIC VELOCITY = 4600. BEDROCK. SEISMIC VELOCITY = 15000. BEDROCK. S Stratum Description:

**Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Data Survey Source Type: Source Appl: Spatial/Tabular

Source Orig: Geological Survey of Canada Source Iden: Source Date: Scale or Res: 1956-1972 Varies Confidence: Μ Horizontal: NAD27

Observatio: Verticalda: Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS) Source Details: File: OTTAWA1.txt RecordID: 021540 NTS_Sheet: 31G05D

Confiden 1: Reliable information but incomplete.

Source List

Horizontal Datum: NAD27 Source Identifier:

Source Type: Data Survey Vertical Datum: Mean Average Sea Level Source Date: 1956-1972 Universal Transverse Mercator Projection Name:

Scale or Resolution: Varies Source Name: Urban Geology Automated Information System (UGAIS)

Source Originators: Geological Survey of Canada

ESE/156.8 105.9 / 0.77 7 1 of 1 lot 30 con 12 **WWIS** ON

Order No: 21062300392

Well ID: 1514897 Data Entry Status:

Construction Date: Data Src:

9/11/1975 Primary Water Use: Domestic Date Received: Sec. Water Use: Selected Flag: True

Final Well Status: Water Supply Abandonment Rec: 1558 Contractor:

Water Type: Casing Material: Form Version: 1 Audit No: Owner:

Tag: Street Name:

OTTAWA Construction Method: County:

Elevation (m): Municipality: **GOULBOURN TOWNSHIP** Elevation Reliability: Site Info:

Depth to Bedrock: 030 Lot: Well Depth: Concession: 12 CON Overburden/Bedrock: Concession Name:

Easting NAD83: Pump Rate: Static Water Level: Northing NAD83:

Zone: Flowing (Y/N):

Flow Rate: UTM Reliability:

Clear/Cloudy: PDF URL (Map):

https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/151\1514897.pdf

Additional Detail(s) (Map)

Well Completed Date: 1975/08/07 Year Completed: 1975 Depth (m): 25.908

Latitude: 45.2950197547202 -75.8941030194984 Longitude: Path: 151\1514897.pdf

Bore Hole Information

10036864 101.094085 Bore Hole ID: Elevation:

DP2BR: 3.00 Elevro:

Spatial Status: Zone: 18

East83: Code OB: 429893.60 Code OB Desc: 5016113.00 Bedrock North83:

Open Hole: Org CS:

UTMRC: Cluster Kind: Date Completed: 07-Aug-1975 00:00:00 UTMRC Desc:

margin of error: 30 m - 100 m Location Method: Remarks:

Elevrc Desc:

Location Source Date:

Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID: 931027620

Layer: 6 Color: General Color: **BROWN** Mat1: 28 Most Common Material: SAND Mat2: 12 **STONES** Mat2 Desc: Mat3: 01 Mat3 Desc: FILL Formation Top Depth: 0.0 Formation End Depth: 3.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

931027621 Formation ID:

Layer: 2 Color: **GREY** General Color: Mat1: 18

SANDSTONE Most Common Material:

73 Mat2 Mat2 Desc: HARD

Mat3:

Mat3 Desc:

Formation Top Depth: 3.0 85.0 Formation End Depth: Formation End Depth UOM: ft

Method of Construction & Well

<u>Use</u>

Method Construction ID: 961514897

Method Construction Code:

Method Construction: Air Percussion

Other Method Construction:

Pipe Information

Pipe ID: 10585434 Casing No:

Comment: Alt Name:

Construction Record - Casing

Casing ID: 930065162

Layer: 1 Material:

STEEL Open Hole or Material:

Depth From: Depth To: 25 Casing Diameter: 6 Casing Diameter UOM: inch Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930065163

Layer: 2 Material:

Open Hole or Material: **OPEN HOLE**

Depth From:

Depth To: 85 Casing Diameter: 6 Casing Diameter UOM: inch Casing Depth UOM:

Results of Well Yield Testing

991514897 Pump Test ID:

Pump Set At:

30.0 Static Level: Final Level After Pumping: 60.0 Recommended Pump Depth: 65.0 Pumping Rate: 6.0 Flowing Rate:

Recommended Pump Rate: 5.0 Levels UOM: ft Rate UOM: GPM Water State After Test Code: Water State After Test: **CLEAR** Pumping Test Method: 1 Pumping Duration HR: 1 **Pumping Duration MIN:** 0 Flowing: No

Draw Down & Recovery

 Pump Test Detail ID:
 934384137

 Test Type:
 Draw Down

 Test Duration:
 30

 Test Level:
 60.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934645122

 Test Type:
 Draw Down

 Test Duration:
 45

 Test Level:
 60.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934893829

 Test Type:
 Draw Down

 Test Duration:
 60

 Test Level:
 60.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934100704

 Test Type:
 Draw Down

 Test Duration:
 15

 Test Level:
 60.0

 Test Level UOM:
 ft

Water Details

 Water ID:
 933470872

 Layer:
 1

 Kind Code:
 1

 Kind:
 FRESH

 Water Found Depth:
 83.0

 Water Found Depth UOM:
 ft

8 1 of 3 ESE/158.8 105.9 / 0.77 CANADA CASHWAY LUMBER COMPANY 6 EDGEWATER STREET

Operator Box:

Operator No:

Operator Type:

Operator Class:

HAZELDEAN ON

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type:

Vendor

Oper Area Code: Oper Phone No: Licence Type Code: Operator Ext: Licence Class: Operator Lot: Licence Control: Oper Concession: Operator Region: Latitude: Longitude: Operator District: Lot: **Operator County:** Concession: Op Municipality: Region: Post Office Box: District: MOE District:

PES

Number of Direction/ Elev/Diff Site DΒ Map Key Records Distance (m) (m) SWP Area Name: County: Trade Name: PDF Link: **CASHWAY BUILDING CENTRES** 8 2 of 3 ESE/158.8 105.9 / 0.77 **PES 6 EDGEWATER STREET** KANATA ON K2L 1V8 Detail Licence No: Operator Box: Licence No: Operator Class: Status: Operator No: Approval Date: Operator Type: Report Source: Oper Area Code: Licence Type: Vendor Oper Phone No: Licence Type Code: Operator Ext: Licence Class: Operator Lot: Licence Control: Oper Concession: Latitude: Operator Region: Longitude: Operator District: **Operator County:** Lot: Concession: Op Municipality: Post Office Box: Region: District: **MOE District:** SWP Area Name: County: Trade Name:

8 3 of 3 ESE/158.8 105.9 / 0.77 CASHWAY BUILDING CENTRES 6 EDGEWATER STREET PES

KANATA ON K2L1V8

Detail Licence No:Operator Box:Licence No:09733Operator Class:

Status: Operator No: Approval Date: Operator Type:

Report Source:Legacy Licenses (Excluding TS)Oper Area Code:613Licence Type:Retail Vendor Class 03Oper Phone No:8367787Licence Type Code:21Operator Ext:

Licence Class: 03 Operator Lot:
Licence Control: Oper Concession:
Latitude: Operator Region:
Longitude: Operator District:
Lot: Operator County:
Concession: Op Municipality:

Concession: Op Municipality:
Region: Post Office Box:
District: MOE District:
County: SWP Area Name:
Trade Name:

9 1 of 2 WNW/159.9 105.7 / 0.59 Lot 30, Conc. 12, 25 Edgewater Street, Kanata Ottawa ON K2L 1V7

Order No: 21062300392

Certificate #: 4177-573L7M

Application Year: 02
Issue Date: 5/6/02

Approval Type:Industrial sewageStatus:Approved

Application Type:New Certificate of ApprovalClient Name:1374469 Ontario Inc.

PDF Link:

PDF Link:

411 Roosevelt Avenue, Suite #102 Client Address:

Client City: Ottawa Client Postal Code: K2A 3X9

Project Description: This application is for approval to construct an on-site storm water management facility to service a single storey

building used for automotive repair and a five bay do-it-yourself car wash. The facility drains to a road side ditch

and the water shed is the Carp River.

Contaminants: **Emission Control:**

> 1374469 Ontario Inc. 2 of 2 WNW/159.9 105.7 / 0.59 9

Lot 30, Conc. 12, 25 Edgewater Street, Kanata

ECA

EHS

Ottawa ON K2A 3X9

4177-573L7M **MOE District:** Ottawa Approval No:

Approval Date: 2002-05-06 City:

Approved Longitude: Status: -75.89777 Record Type: **ECA** Latitude: 45.296238 **IDS** Link Source: Geometry X:

SWP Area Name: Mississippi Valley Geometry Y: Approval Type: ECA-INDUSTRIAL SEWAGE WORKS

Project Type: INDUSTRIAL SEWAGE WORKS **Business Name:** 1374469 Ontario Inc.

Address: Lot 30, Conc. 12, 25 Edgewater Street, Kanata

Full Address:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1149-56WSAG-14.pdf

NW/164.2 10 1 of 1 106.9 / 1.77 24 Edgewater St

Order No: 20160926147

Status:

Custom Report Report Type: Report Date: 30-SEP-16 26-SEP-16

Date Received: Previous Site Name:

Lot/Building Size: Additional Info Ordered: Nearest Intersection:

Ottawa ON K2L1V8

Municipality:

Client Prov/State: ON Search Radius (km): .25

-75.897352 Y: 45.296676

11 1 of 2 NNE/174.0 110.0 / 4.85 21 Young Rd SPL Ottawa ON

Ref No: 8566-7JUR9X Discharger Report: Material Group: Site No:

Incident Dt: Health/Env Conseq: Year: Client Type: Incident Cause: Sector Type: Other Discharges Incident Event: Agency Involved:

Contaminant Code: Nearest Watercourse:

OIL (PETROLEUM BASED, NOT SPECIFIED) Site Address: Contaminant Name:

Contaminant Limit 1: Site District Office: Contam Limit Freq 1: Site Postal Code:

Site Region: Contaminant UN No 1: Environment Impact: Not Anticipated Site Municipality: Ottawa Site Lot:

Nature of Impact: Other Impact(s) Receiving Medium: Site Conc: Receiving Env:

Northing: No Field Response Easting:

Dt MOE Arvl on Scn: Site Geo Ref Accu: MOE Reported Dt: 9/26/2008 Site Map Datum: **Dt Document Closed:** 10/4/2008 SAC Action Class:

Equipment Failure Incident Reason: Source Type:

erisinfo.com | Environmental Risk Information Services

TSSA - Fuel Safety Branch

Ottawa

MOE Response:

Direction/ Elev/Diff Site DΒ Map Key Number of

> Records Distance (m) (m)

Hazeldean Masonic Temple<UNOFFICIAL> Site Name:

Site County/District: Site Geo Ref Meth:

Incident Summary: 4-5 L heating oil spill-cleaned up

Contaminant Qty:

11 2 of 2 NNE/174.0 110.0 / 4.85 21 YOUNG ROAD **HINC** OTTAWA ON

External File Num: FS INC 0809-05692

Fuel Occurrence Type: Leak 9/26/2008 Date of Occurrence: Fuel Oil Fuel Type Involved:

Completed - No Action Required Status Desc: Job Type Desc: Incident/Near-Miss Occurrence (FS)

Oper. Type Involved: Commercial (e.g. restaurant, business unit, etc)

Service Interruptions: No Property Damage: No Fuel Life Cycle Stage:

Utilization Root Cause:

Reported Details: Hazeldean Masonic Temple

Liquid Fuel Fuel Category: Occurrence Type: Incident

Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.) Affiliation:

County Name: Ottawa

Approx. Quant. Rel: Nearby body of water: Enter Drainage Syst.: Approx. Quant. Unit: Environmental Impact:

> 12 1 of 1 NE/179.6 109.9 / 4.77 lot 30 con 12 **WWIS** ON

> > 10/27/1960

Order No: 21062300392

True

Well ID: 1502990 Data Entry Status: Construction Date: Data Src:

Primary Water Use: Date Received: Domestic

Sec. Water Use: Selected Flag:

Water Supply Final Well Status: Abandonment Rec: Water Type: Contractor: 3002 Form Version:

Casing Material: Audit No: Owner:

Tag: Street Name: **Construction Method:** County:

OTTAWA GOULBOURN TOWNSHIP Elevation (m): Municipality:

Elevation Reliability: Site Info: Depth to Bedrock: 030 Lot: Well Depth: Concession: 12

CON Overburden/Bedrock: Concession Name: Pump Rate: Easting NAD83:

Static Water Level: Northing NAD83: Flowing (Y/N): Zone:

Flow Rate: UTM Reliability: Clear/Cloudy:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1502990.pdf

Additional Detail(s) (Map)

1960/10/13 Well Completed Date: 1960 Year Completed:

Depth (m): 26.2128

 Latitude:
 45.2967195249255

 Longitude:
 -75.8942955341159

 Path:
 150\1502990.pdf

Bore Hole Information

Bore Hole ID: 10025033 **Elevation:** 105.856300

DP2BR: 12.00 Elevrc: Spatial Status: Zone:

 Code OB:
 r
 East83:
 429880.60

 Code OB Desc:
 Bedrock
 North83:
 5016302.00

Open Hole: Org CS:

 Cluster Kind:
 UTMRC:
 5

 Date Completed:
 13-Oct-1960 00:00:00
 UTMRC Desc:
 margin of error : 100 m - 300 m

Remarks: Location Method: p5
Elevrc Desc:

Location Source Date: Improvement Location Source: Improvement Location Method:

Improvement Location Method: Source Revision Comment: Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID: 930995733

Layer: 1 **Color:** 6

 General Color:
 BROWN

 Mat1:
 05

 Most Common Material:
 CLAY

 Mat2:
 12

 Mat2 Desc:
 STONES

Mat3: Mat3 Desc:

Formation Top Depth: 0.0 Formation End Depth: 12.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 930995734

Layer: 2

Color:

General Color:

Mat1: 18

Most Common Material: SANDSTONE

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

Formation Top Depth: 12.0 Formation End Depth: 86.0 Formation End Depth UOM: ft

Method of Construction & Well

<u>Use</u>

Method Construction ID: 961502990

Method Construction Code: 1

Order No: 21062300392

Method Construction:

Cable Tool

Other Method Construction:

Pipe Information

 Pipe ID:
 10573603

 Casing No:
 1

 Comment:
 1

Comment: Alt Name:

Construction Record - Casing

Casing ID: 930042848

Layer: 2 Material: 4

Open Hole or Material: OPEN HOLE

Depth From:
Depth To: 86
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930042847

Layer: 1
Material: 1
Open Hole or Material: STEEL

Depth From:

Depth To: 16
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502990

Pump Set At:

Static Level:26.0Final Level After Pumping:72.0Recommended Pump Depth:80.0Pumping Rate:5.0

Flowing Rate:

Recommended Pump Rate: 5.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2

Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HP: 1

Pumping Duration HR:1Pumping Duration MIN:0Flowing:No

Water Details

Water ID: 933455816

 Layer:
 3

 Kind Code:
 1

 Kind:
 FRESH

 Water Found Depth:
 82.0

 Water Found Depth UOM:
 ft

Water Details

 Water ID:
 933455815

 Layer:
 2

 Kind Code:
 1

 Kind:
 FRESH

 Water Found Depth:
 78.0

 Water Found Depth UOM:
 ft

Water Found Depth UOM:

Water Details

 Water ID:
 933455814

 Layer:
 1

 Kind Code:
 1

 Kind:
 FRESH

 Water Found Depth:
 48.0

 Water Found Depth UOM:
 ft

13 1 of 1 NE/179.6 109.9 / 4.77
ON
BORE

Lot:

Township:

Latitude DD:

UTM Zone:

Easting:

Northing:

Accuracy:

Longitude DD:

Location Accuracy:

Mat Consistency:

Material Moisture:

Non Geo Mat Type:

Geologic Formation:

Material Texture:

Geologic Group:

Geologic Period:

Depositional Gen:

45.29672

429881

5016302

Not Applicable

Order No: 21062300392

18

-75.894295

 Borehole ID:
 609650
 Inclin FLG:
 No

 OGF ID:
 215511266
 SP Status:
 Initial Entry

 Status:
 Surv Elev:
 No

 Type:
 Borehole
 Piezometer:
 No

Type:BoreholePiezometer:Use:Primary Name:Completion Date:OCT-1960Municipality:

Static Water Level:

Primary Water Use:
Sec. Water Use:
Total Depth m: 26.2

Depth Ref: Ground Surface

Depth Elev:
Drill Method:

Orig Ground Elev m: 112
Elev Reliabil Note:

DEM Ground Elev m: 105
Concession:
Location D:

Borehole Geology Stratum

Survey D: Comments:

 Geology Stratum ID:
 218383726

 Top Depth:
 0

 Bottom Depth:
 3.7

 Material Color:
 Brown

 Material 1:
 Clay

Material 2: Stones
Material 3:
Material 4:

Gsc Material Description:

Stratum Description: CLAY,STONES. BROWN.

 Geology Stratum ID:
 218383727

 Top Depth:
 3.7

 Bottom Depth:
 26.2

Material Color:

Material 1: Sandstone

Material 2: Material 3: Mat Consistency: Material Moisture: Material Texture: Non Geo Mat Type: Geologic Formation: Geologic Group: Geologic Period:

erisinfo.com | Environmental Risk Information Services

Direction/ Elev/Diff Site DΒ Map Key Number of

Records Distance (m) (m)

Material 4: Depositional Gen:

Gsc Material Description: SANDSTONE. 00078GRAVEL. BEDROCK, LIMESTONE. . BEDROCK. SEISMIC VELOCITY = 15000. BE **Note: Stratum Description:

Many records provided by the department have a truncated [Stratum Description] field.

<u>Source</u>

Data Survey Spatial/Tabular Source Type: Source Appl:

Source Orig: Geological Survey of Canada Source Iden: 1 Source Date: 1956-1972 Scale or Res: Varies Confidence: Horizontal: NAD27

Observatio: Verticalda: Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)

File: OTTAWA1.txt RecordID: 02158 NTS Sheet: Source Details: Confiden 1:

Source List

Source Identifier: Horizontal Datum: NAD27

Source Type: **Data Survey** Vertical Datum: Mean Average Sea Level 1956-1972 Universal Transverse Mercator Source Date: Projection Name:

Scale or Resolution: Varies

Source Name: Urban Geology Automated Information System (UGAIS)

Geological Survey of Canada Source Originators:

14 1 of 1 ENE/187.4 109.6 / 4.46 9 Young Road, Foulis Crescent, Block 40, 4M-

405

CA

GEN

Order No: 21062300392

Kanata ON K2L 1V9

5667-4N2SPM Certificate #:

Application Year: 00 Issue Date: 9/8/00

Municipal & Private sewage Approval Type: Status: Approved

Application Type:

New Certificate of Approval Pegasus Development Corporation Client Name:

Client Address: 1914 Merivale Rd. Client City: Nepean Client Postal Code: K2G 1E8

Project Description: This application is for the construction of a storm water management facility to serve the Young Road Development

Project.

Contaminants: **Emission Control:**

15

E/191.3 CHIROPRACTIC CLINIC 107.6 / 2.46 501B HAZELDEAN CENTRE

KANATA ON K2L 1V6

Generator No: ON1132500 PO Box No: Status: Country:

Approval Years: 88,89 Choice of Contact: Contam. Facility: Co Admin: Phone No Admin: MHSW Facility:

0000 SIC Code:

1 of 12

*** NOT DEFINED *** SIC Description:

Detail(s)

Waste Class:

Waste Class Desc: PHOTOPROCESSING WASTES

Мар Кеу	Number Records		Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>15</u>	2 of 12		E/191.3	107.6 / 2.46	CHIROPRACTIC (OUT OF BUSINESS) 07-179 501B HAZELDEAN CENTRE KANATA ON K2L 1V6	GEN
Generator No:		ON1132500			PO Box No:	
Status: Approval Years: Contam. Facility: MHSW Facility: SIC Code: SIC Description:		92,93,94,95,96,97,98			Country: Choice of Contact: Co Admin: Phone No Admin:	
		8661	CHIRO./OSTEOPA	THS		
<u>15</u>	3 of 12		E/191.3	107.6 / 2.46	CHRISTOPHER ARMSTRONG ENT. INC 501 HAZELDEAN RD HWY 7 KANATA ON K2L 1V6	DTNK
<u>Delisted Exp</u> <u>Facilities</u>	oired Fuel Sa	<u>afety</u>				
Instance No: Status: Instance ID:	atus:		9684225 EXPIRED			
Instance Type: Description: TSSA Program Area: Maximum Hazard Rank:			FS Facility			
Facility Type Expired Date Original Sou Record Date	e: irce:		1/24/1997 EXP Up to May 2013			
<u>15</u>	4 of 12		E/191.3	107.6 / 2.46	CHRISTOPHER ARMSTRONG ENT. INC 501 HAZELDEAN RD HWY 7 KANATA ON	DTNK
<u>Delisted Exp</u> <u>Facilities</u>	oired Fuel Sa	<u>afety</u>				
Instance No: Status: Instance ID: Instance Typ Description: TSSA Progra Maximum Ha	oe: am Area: azard Rank:		11325691 EXPIRED 77759 FS Piping FS Piping			
Facility Type Expired Date Original Sou Record Date	e: ırce:		EXP Up to Mar 2012			
<u>15</u>	5 of 12		E/191.3	107.6 / 2.46	Waste Services (CA) Inc. 501 Hazeldean Road Ottawa ON K2L 1V6	SPL
Ref No:		6648-81	JRJY7		Discharger Report:	
Site No: Incident Dt:		29-MAY	′-12		Material Group: Health/Env Conseq:	
Year: Incident Cause:		Pipe Or Hose Leak			Client Type: Sector Type: Motor Vehicle	

Order No: 21062300392

Elev/Diff DΒ Map Key Number of Direction/ Site Records Distance (m) (m)

Incident Event: Agency Involved: Contaminant Code: Nearest Watercourse:

HYDRAULIC OIL Contaminant Name: Site Address: 501 Hazeldean Road

Contaminant Limit 1: Site District Office: Contam Limit Freq 1: Site Postal Code: Contaminant UN No 1: Site Region:

Environment Impact: Not Anticipated Site Municipality: Ottawa Nature of Impact: Site Lot:

Receiving Medium: Sewage - Municipal/Private and Commercial Site Conc: Receiving Env: Northing: MOE Response: No Field Response Easting:

Dt MOE Arvl on Scn: Site Geo Ref Accu: 29-MAY-12 MOE Reported Dt: Site Map Datum:

Dt Document Closed: SAC Action Class: Primary Assessment of Spills

Incident Reason: Equipment/Vehicles Source Type: Site Name: 501 Hazeldean Road Parking Lot<UNOFFICIAL>

Site County/District: Site Geo Ref Meth:

Waste Services: 20L Hydraulic oil to CB Incident Summary:

Contaminant Qty:

15 6 of 12 E/191.3 107.6 / 2.46 CHRISTOPHER ARMSTRONG ENT. INC

501 HAZELDEAN RD HWY 7 KANATA K2L 1V6

NULL

NULL

EXP

EXP

Order No: 21062300392

ON CA ON

Panam Venue Nm:

Instance No: 10797939 NULL Model: **EXPIRED** Status: Quantity: 1

Instance ID: Unit of Measure: EΑ NULL Instance Type: Fuel Type2:

Instance Creation Dt: 10/2/1989 Fuel Type3: NULL Instance Install Dt: Piping Steel: 10/2/1989

Item: Piping Galvanized: Item Description: FS Liquid Fuel Tank Tank Single Wall St: FS LIQUID FUEL TANK Piping Underground: Facility Type:

Overfill Prot Type: NULL Tank Underground: 7/5/2009 1:21:01 AM Panam Related: NULL Creation Date:

Expired Date: Manufacturer: NULL

FS Liquid Fuel Tank Source:

11325655

Description: **NULL** NULL Serial No: Ulc Standard: **NULL**

Facility Location: 501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA

7 of 12 E/191.3 107.6 / 2.46 CHRISTOPHER ARMSTRONG ENT. INC 15 501 HAZELDEAN RD HWY 7 KANATA K2L 1V6

ON CA

Model:

ON

EXPIRED Status: Quantity: Instance ID: Unit of Measure: EΑ

NULL Instance Type: Fuel Type2: Instance Creation Dt: 10/2/1989 Fuel Type3: **NULL** Instance Install Dt: 10/2/1989 Piping Steel:

Item: Piping Galvanized: Tank Single Wall St: Item Description: FS Liquid Fuel Tank Facility Type: **FS LIQUID FUEL TANK** Piping Underground: Overfill Prot Type: Tank Underground: NULL

7/5/2009 1:24:43 AM Panam Related: **NULL** Creation Date: Panam Venue Nm: **NULL** Expired Date:

Instance No:

Number of Elev/Diff Site DΒ Map Key Direction/ Records Distance (m) (m)

NULL Manufacturer:

Source: FS Liquid Fuel Tank

Description: NULL Serial No: NULL Ulc Standard: **NULL**

501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA Facility Location:

8 of 12 E/191.3 CHRISTOPHER ARMSTRONG ENT. INC 15 107.6 / 2.46

501 HAZELDEAN RD HWY 7 KANATA K2L 1V6

EXP

Order No: 21062300392

ON CA ON

11325675 NULL Instance No: Model: **EXPIRED** Status: Quantity: Instance ID: Unit of Measure: EΑ

Instance Type: Fuel Type2: **NULL** Instance Creation Dt: 10/2/1989 Fuel Type3: **NULL**

Instance Install Dt: 10/2/1989 Piping Steel: Item: Piping Galvanized: Item Description: FS Liquid Fuel Tank Tank Single Wall St: Facility Type: **FS LIQUID FUEL TANK** Piping Underground: Tank Underground: Overfill Prot Type: NULL

Creation Date: 7/5/2009 1:24:46 AM Panam Related: NULL Panam Venue Nm: NULL

Expired Date: NULL

Manufacturer: FS Liquid Fuel Tank Source:

Description: NULL Serial No: NULL Ulc Standard: NULL

501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA Facility Location:

107.6 / 2.46 15 9 of 12 E/191.3 501 HAZELDEAN RD, KANATA INC

Incident No: 1266628 Any Health Impact: Unknown Incident ID: Any Enviro Impact: No Service Interrupted: Yes

Instance No: Was Prop Damaged: No Status Code:

Attribute Category: FS-Perform L1 Incident Insp Reside App. Type:

Context: Commer App. Type: Date of Occurrence: 2013/10/22 00:00:00 Indus App. Type: Time of Occurrence: NULL Institut App. Type:

Incident Created On: Venting Type: Instance Creation Dt: Vent Conn Mater: Instance Install Dt: Vent Chimney Mater: Occur Insp Start Date: 2013/10/22 00:00:00 Pipeline Type:

Approx Quant Rel: Pipeline Involved: Tank Capacity: Pipe Material: Fuels Occur Type: Vapour Release Depth Ground Cover: Fuel Type Involved: Natural Gas Regulator Location:

NULL **Enforcement Policy:** Regulator Type: **NULL** Operation Pressure: Prc Escalation Reg: Tank Material Type: Liquid Prop Make: Tank Storage Type: Liquid Prop Model: Tank Location Type: Liquid Prop Serial No:

Liquid Prop Notes: Pump Flow Rate Cap: Task No: 4688128 Equipment Type: Equipment Model: Notes: Drainage System: Serial No: Sub Surface Contam.: Cylinder Capacity:

Aff Prop Use Water: Cylinder Cap Units: Contam. Migrated: Cylinder Mat Type:

Elev/Diff Site DΒ Map Key Number of Direction/ Records Distance (m) (m)

Contact Natural Env: Near Body of Water:

Incident Location: 501 HAZELDEAN RD, KANATA - VAPOUR RELEASE

Occurence Narrative: Multiple ng piping leaks resulting in building evacuations. No Maintainence conducted by owner.

Operation Type Involved: Commercial (e.g. restaurant, business unit, etc)

Item:

Item Description:

Device Installed Location:

15 10 of 12 E/191.3 107.6 / 2.46 CHRISTOPHER ARMSTRONG ENT. INC

501 HAZELDEAN RD HWY 7 KANATA K2L 1V6

Gasoline

FST

FST

Order No: 21062300392

ON CA ON

Panam Related:

Panam Venue:

11325675 Instance No: Manufacturer:

Serial No: Status: Cont Name: Ulc Standard:

Quantity: FS LIQUID FUEL TANK Unit of Measure:

Item Description: FS Liquid Fuel Tank Fuel Type: Gasoline NULL Tank Type: Liquid Fuel Single Wall UST Fuel Type2: Install Date: 10/2/1989 Fuel Type3: NULL

Install Year: Piping Steel: 1974 Years in Service: Piping Galvanized:

NULL Model:

Tanks Single Wall St: Description: Piping Underground: Capacity: 30446 Num Underground:

Tank Material: Steel Corrosion Protect: Overfill Protect:

FS Liquid Fuel Tank Facility Type: Parent Facility Type:

Facility Location:

Instance Type:

Item:

501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA Device Installed Location:

Fuel Storage Tank Details

Owner Account Name: CHRISTOPHER ARMSTRONG ENT. INC

CHRISTOPHER ARMSTRONG ENT. INC 15 11 of 12 E/191.3 107.6 / 2.46

501 HAZELDEAN RD HWY 7 KANATA K2L 1V6

ON CA ON

Piping Galvanized:

Tanks Single Wall St:

Piping Underground:

Num Underground:

Panam Related:

Panam Venue:

10797939 Manufacturer: Instance No:

Status: Serial No: Cont Name: Ulc Standard: Quantity: Instance Type:

FS LIQUID FUEL TANK Unit of Measure: Item: Item Description: FS Liquid Fuel Tank Fuel Type:

Tank Type: Liquid Fuel Single Wall UST Fuel Type2: NULL Install Date: 10/2/1989 Fuel Type3: NULL Piping Steel:

Install Year: 1974

Years in Service:

NULL Model: Description:

Capacity: 30446 Tank Material: Steel

Corrosion Protect: Overfill Protect:

FS Liquid Fuel Tank Facility Type:

Parent Facility Type: Facility Location:

Device Installed Location: 501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA

Fuel Storage Tank Details

Owner Account Name: CHRISTOPHER ARMSTRONG ENT. INC

12 of 12 E/191.3 107.6 / 2.46 CHRISTOPHER ARMSTRONG ENT. INC 15

501 HAZELDEAN RD HWY 7 KANATA K2L 1V6

FST

Order No: 21062300392

ON CA ON

Piping Steel:

Piping Galvanized:

Instance No: 11325655 Manufacturer:

Status: Serial No: Ulc Standard: Cont Name:

Instance Type: Quantity: Item: **FS LIQUID FUEL TANK** Unit of Measure:

Item Description: FS Liquid Fuel Tank Fuel Type: Gasoline Liquid Fuel Single Wall UST NULL Tank Type: Fuel Type2: Install Date: 10/2/1989 Fuel Type3: NULL

Install Year: 1974 Years in Service:

Model: **NULL**

Tanks Single Wall St: Description: Piping Underground: Num Underground: Capacity: 30446 Panam Related: Tank Material: Steel Panam Venue:

Corrosion Protect: Overfill Protect: FS Liquid Fuel Tank Facility Type:

Parent Facility Type: Facility Location:

Device Installed Location: 501 HAZELDEAN RD HWY 7 KANATA K2L 1V6 ON CA

Fuel Storage Tank Details

Owner Account Name: CHRISTOPHER ARMSTRONG ENT. INC

1 of 1 WNW/201.7 105.8 / 0.69 29 Edgewater St 16 **EHS** Ottawa ON K2L1V7

Order No: 20150330048 Nearest Intersection: Status: С Municipality:

Report Type: Custom Report Client Prov/State: ON 02-APR-15 Report Date: Search Radius (km): .25 30-MAR-15 X: -75.89801 45.29666

Date Received: Y: Previous Site Name: Lot/Building Size: Additional Info Ordered:

17 1 of 1 E/212.5 107.9 / 2.77 lot 30 con 12 **WWIS** ON

1514055 Well ID: Data Entry Status:

Construction Date: Data Src:

7/2/1974 Date Received: Primary Water Use: Industrial Sec. Water Use: Selected Flag: True

Final Well Status: Water Supply Abandonment Rec: 2557 Water Type: Contractor:

Casing Material: Form Version: Audit No: Owner: Street Name: Taa:

Construction Method: County: **OTTAWA**

GOULBOURN TOWNSHIP Elevation (m): Municipality:

Elevation Reliability: Site Info: 030 Depth to Bedrock: Lot:

12 Well Depth: Concession: Overburden/Bedrock: Concession Name: CON

Easting NAD83: Pump Rate: Static Water Level: Northing NAD83: Flowing (Y/N): Zone:

Flow Rate: UTM Reliability: Clear/Cloudy:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/151\1514055.pdf

Additional Detail(s) (Map)

Well Completed Date: 1974/06/10 1974 Year Completed: 67.9704 Depth (m):

45.2960880842002 Latitude: Longitude: -75.8933163221515 151\1514055.pdf Path:

Bore Hole Information

Bore Hole ID: 10036037 Elevation: 103.712501

DP2BR: 28.00 Elevrc: Spatial Status: Zone:

18

Code OB: East83: 429956.60 Code OB Desc: North83: **Bedrock** 5016231.00

Open Hole: Org CS: Cluster Kind: UTMRC:

Date Completed: 10-Jun-1974 00:00:00 **UTMRC Desc:** margin of error: 30 m - 100 m

Order No: 21062300392

Remarks: Location Method: Elevrc Desc:

Location Source Date: Improvement Location Source:

Overburden and Bedrock

Improvement Location Method: Source Revision Comment: Supplier Comment:

Materials Interval

931025204 Formation ID:

3 Layer: Color: 2 General Color: **GREY** Mat1: 17 SHALE Most Common Material: Mat2: 85 Mat2 Desc: SOFT

Mat3: Mat3 Desc:

Formation Top Depth:

28.0 Formation End Depth: 32.0 Formation End Depth UOM:

Overburden and Bedrock

Materials Interval

Formation ID: 931025202

Layer:

 Color:
 6

 General Color:
 BROWN

 Mat1:
 11

 Most Common Material:
 GRAVEL

 Mat2:
 85

 Mat2 Desc:
 SOFT

Mat3: Mat3 Desc:

Formation Top Depth: 0.0 Formation End Depth: 4.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 931025203

 Layer:
 2

 Color:
 2

 General Color:
 GREY

 Mat1:
 05

 Most Common Material:
 CLAY

 Mat2:
 79

 Mat2 Desc:
 PACKED

Mat3: Mat3 Desc:

Formation Top Depth: 4.0
Formation End Depth: 28.0
Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 931025205

 Layer:
 4

 Color:
 8

 General Color:
 BLACK

 Mat1:
 15

Most Common Material: LIMESTONE

Mat2: 85
Mat2 Desc: SOFT

Mat3: Mat3 Desc:

Formation Top Depth: 32.0
Formation End Depth: 35.0
Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

 Formation ID:
 931025206

 Layer:
 5

 Color:
 8

 General Color:
 BLACK

Mat1: 15
Most Common Material: LIMESTONE

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

Formation Top Depth: 35.0 Formation End Depth: 223.0 Formation End Depth UOM: ft

Order No: 21062300392

Method of Construction & Well

<u>Use</u>

Method Construction ID: 961514055

Method Construction Code: 5

Method Construction: Air Percussion

Other Method Construction:

Pipe Information

Pipe ID: 10584607

Casing No: Comment: Alt Name:

Construction Record - Casing

Casing ID: 930063662

Layer: 1
Material: 1
Open Hole or Material: STEEL

Depth From:

Depth To:35Casing Diameter:6Casing Diameter UOM:inchCasing Depth UOM:ft

Construction Record - Casing

Casing ID: 930063663

Layer: 2 Material: 4

Open Hole or Material: OPEN HOLE

Depth From:

Depth To:223Casing Diameter:6Casing Diameter UOM:inchCasing Depth UOM:ft

Results of Well Yield Testing

Pump Test ID: 991514055

Pump Set At:
Static Level: 70.0
Final Level After Pumping: 160.0
Recommended Pump Depth: 190.0
Pumping Rate: 9.0

Flowing Rate:

Recommended Pump Rate: 5.0 **Levels UOM:** ft

Rate UOM: GPM

Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR:

Pumping Duration MIN:

Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934641885

1

 Test Type:
 Draw Down

 Test Duration:
 45

 Test Level:
 160.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934899772

 Test Type:
 Draw Down

 Test Duration:
 60

 Test Level:
 160.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934099818

 Test Type:
 Draw Down

 Test Duration:
 15

 Test Level:
 160.0

 Test Level UOM:
 ft

Draw Down & Recovery

 Pump Test Detail ID:
 934381310

 Test Type:
 Draw Down

 Test Duration:
 30

 Test Level:
 160.0

 Test Level UOM:
 ft

Water Details

 Water ID:
 933469839

 Layer:
 2

 Kind Code:
 1

 Kind:
 FRESH

 Water Found Ponth:
 168.0

Water Found Depth: 168.0 Water Found Depth UOM: 1

Water Details

Water ID: 933469838

 Layer:
 1

 Kind Code:
 1

 Kind:
 FRESH

 Water Found Depth:
 47.0

 Water Found Depth UOM:
 ft

Water Details

 Water ID:
 933469840

 Layer:
 3

 Kind Code:
 1

 Kind:
 FRESH

 Water Found Penth:
 190.0

Water Found Depth: 190.0
Water Found Depth UOM: ft

18 1 of 1 NNW/216.4 108.8 / 3.69 30 Edgewater St Ottawa ON K2L1V8

Order No: 20130717023 Nearest Intersection:

Status: С

Municipality: Ottawa Report Type: RSC Report (Urban) Client Prov/State: ON 26-JUL-13 Report Date: Search Radius (km): .3 17-JUL-13 -75.896988 Date Received: X:

Previous Site Name:

Lot/Building Size: 6 acres

Additional Info Ordered:

19 1 of 1 NNE/217.6 110.5 / 5.40 lot 30 con 12 **WWIS**

Y:

Well ID: 1509894

Construction Date:

Primary Water Use: Domestic Sec. Water Use:

Final Well Status: Water Supply

Water Type: Casing Material: Audit No: Tag:

Construction Method:

Elevation (m): Elevation Reliability: Depth to Bedrock: Well Depth:

Overburden/Bedrock:

Pump Rate: Static Water Level: Flowing (Y/N): Flow Rate: Clear/Cloudy:

ON

Data Entry Status: Data Src:

11/14/1968 Date Received: Selected Flag: True Abandonment Rec:

Contractor: 1503 Form Version: 1 Owner:

Street Name: County: **OTTAWA**

GOULBOURN TOWNSHIP Municipality:

45.297389

Site Info:

030 Lot: Concession: 12 Concession Name: CON

Easting NAD83: Northing NAD83: Zone: UTM Reliability:

https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1509894.pdf PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 1968/10/18 Year Completed: 1968 Depth (m): 37.7952

45.2974515602238 Latitude: Longitude: -75.8950722859196 Path: 150\1509894.pdf

Bore Hole Information

10031926 Bore Hole ID:

DP2BR: 4.00

Spatial Status: Code OB:

Code OB Desc: **Bedrock**

Open Hole:

Cluster Kind:

Date Completed: 18-Oct-1968 00:00:00

Remarks: Elevrc Desc:

Location Source Date:

Improvement Location Source: Improvement Location Method: **Source Revision Comment:** Supplier Comment:

Elevation: 109.848419

Elevrc:

Zone: 18

East83: 429820.60 North83: 5016384.00

Org CS:

UTMRC:

UTMRC Desc: margin of error: 30 m - 100 m

Location Method:

Overburden and Bedrock

Materials Interval

931013343 Formation ID:

Layer:

Color:

General Color:

18 Mat1:

Most Common Material: SANDSTONE

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

4.0 Formation Top Depth: Formation End Depth: 124.0 Formation End Depth UOM:

Overburden and Bedrock

Materials Interval

931013342 Formation ID:

Layer:

Color:

General Color:

Mat1: 01 FILL Most Common Material:

Mat2: Mat2 Desc:

Mat3: Mat3 Desc:

0.0 Formation Top Depth: Formation End Depth: 4.0 Formation End Depth UOM: ft

Method of Construction & Well

Method Construction ID: 961509894 Method Construction Code:

Method Construction: Cable Tool

Other Method Construction:

Pipe Information

10580496 Pipe ID:

Casing No:

Comment: Alt Name:

Construction Record - Casing

Casing ID: 930056482

Layer: Material:

STEEL Open Hole or Material:

Depth From:

Casing Depth UOM:

20 Depth To: Casing Diameter: 6 Casing Diameter UOM: inch

Construction Record - Casing

ft

Casing ID: 930056483

Layer: 2 Material:

Open Hole or Material: **OPEN HOLE**

Depth From:

Depth To: 124 Casing Diameter: 5 Casing Diameter UOM: inch Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991509894

Pump Set At:

Static Level: 40.0 Final Level After Pumping: 60.0 80.0 Recommended Pump Depth: Pumping Rate: 10.0 Flowing Rate: Recommended Pump Rate: 5.0 Levels UOM: ft **GPM** Rate UOM: Water State After Test Code: Water State After Test: **CLOUDY** Pumping Test Method: **Pumping Duration HR: Pumping Duration MIN:** 0 Flowing: No

Water Details

Water ID: 933464787 Layer: Kind Code: **FRESH** Kind: Water Found Depth: 122.0 Water Found Depth UOM:

105.6 / 0.46 **20** 1 of 1 ESE/223.0

BORE ON

609647 Borehole ID: OGF ID: 215511263

Status:

Borehole Type: Use: DEC-1956 Completion Date:

Static Water Level: Primary Water Use:

Sec. Water Use:

Total Depth m:

16.8

Depth Ref: **Ground Surface**

Depth Elev: Drill Method:

106 Orig Ground Elev m: Elev Reliabil Note:

101 DEM Ground Elev m:

Concession: Location D: Survey D: Comments:

Inclin FLG: No SP Status: Initial Entry Surv Elev: No Piezometer: No Primary Name: Municipality: Lot: Township:

Latitude DD: 45.294928 Longitude DD: -75.893247 UTM Zone: 18

Easting: 429961 Northing: 5016102

Location Accuracy:

Accuracy: Not Applicable Map Key Number of Direction/ Elev/Diff Site DB

Records Distance (m) (m)

Borehole Geology Stratum

Geology Stratum ID:218383719Mat Consistency:Top Depth:9.1Material Moisture:Bottom Depth:16.8Material Texture:Material Color:Non Geo Mat Type:

Material 1:SandstoneGeologic Formation:Material 2:Geologic Group:Material 3:Geologic Period:Material 4:Depositional Gen:

Gsc Material Description:

Stratum Description: SANDSTONE. 00055SEISMIC VELOCITY = 4600. BEDROCK. SEISMIC VELOCITY = 15000. BEDROCK. S

**Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218383718 Mat Consistency: Top Depth: 5.2 Material Moisture: Bottom Depth: 9.1 Material Texture: Material Color: Non Geo Mat Type: Material 1: Shale Geologic Formation: Material 2: Geologic Group:

Material 2:Geologic Group:Material 3:Geologic Period:Material 4:Depositional Gen:

Gsc Material Description:

Stratum Description: SHALE.

Geology Stratum ID:218383717Mat Consistency:Top Depth:0Material Moisture:Bottom Depth:5.2Material Texture:Material Color:Non Geo Mat Type:Material 1:BouldersGeologic Formation:Material 2:ClayGeologic Group:

Material 2:ClayGeologic Group:Material 3:SandGeologic Period:Material 4:Depositional Gen:

Gsc Material Description:

Stratum Description: BOULDERS,CLAY,SAND.

<u>Source</u>

Source Type: Data Survey Source Appl: Spatial/Tabular

Source Orig:Geological Survey of CanadaSource Iden:1Source Date:1956-1972Scale or Res:VariesConfidence:Horizontal:NAD27

Observatio: Verticalda: Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA1.txt RecordID: 02155 NTS_Sheet:

Confiden 1:

Source List

Source Identifier: 1 Horizontal Datum: NAD27

Source Type:Data SurveyVertical Datum:Mean Average Sea LevelSource Date:1956-1972Projection Name:Universal Transverse Mercator

Scale or Resolution: Varies

Source Name: Urban Geology Automated Information System (UGAIS)

Source Originators: Geological Survey of Canada

21 1 of 1 ESE/223.1 105.6 / 0.46 lot 30 con 12 WWIS

Order No: 21062300392

Well ID: 1502987 Data Entry Status:

Construction Date: Data Src:

Primary Water Use: Domestic Date Received: 1/22/1957

Selected Flag:

True

Order No: 21062300392

Sec. Water Use: 0

Final Well Status: Water Supply

Abandonment Rec: 3504 Water Type: Contractor: Casing Material: Form Version: 1 Audit No: Owner:

Street Name: Tag: County:

Construction Method: OTTAWA Municipality: **GOULBOURN TOWNSHIP** Elevation (m): Elevation Reliability: Site Info:

Depth to Bedrock: Lot: 030 Well Depth: Concession: 12 Overburden/Bedrock: Concession Name: CON

Pump Rate: Easting NAD83: Static Water Level: Northing NAD83:

Flowing (Y/N): Zone:

Flow Rate: UTM Reliability: Clear/Cloudy:

https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1502987.pdf PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 1956/12/13 1956 Year Completed: Depth (m): 16.764

45.2949274362645 Latitude: Longitude: -75.8932470839576 Path: 150\1502987.pdf

Bore Hole Information

Bore Hole ID: 10025030 101.249717 Elevation:

DP2BR: 17.00 Elevrc:

Spatial Status: Zone: 18 Code OB: East83: 429960.60

Bedrock Code OB Desc: North83: 5016102.00 Open Hole: Org CS:

Cluster Kind: UTMRC:

UTMRC Desc: Date Completed: 13-Dec-1956 00:00:00 margin of error: 100 m - 300 m Remarks: Location Method:

Elevrc Desc:

Location Source Date:

Improvement Location Source: Improvement Location Method: **Source Revision Comment:**

Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID: 930995728

Layer:

Color: General Color:

Mat1: 18

SANDSTONE

Most Common Material: Mat2:

Mat2 Desc: Mat3: Mat3 Desc:

Formation Top Depth: 30.0 Formation End Depth: 55.0 Formation End Depth UOM:

Overburden and Bedrock

Materials Interval

Formation ID: 930995727

Layer:

Color:

General Color:

Mat1: 17
Most Common Material: SHALE

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

Formation Top Depth: 17.0 Formation End Depth: 30.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 930995726

Layer: 1

Color:

General Color:

Mat1: 13

 Most Common Material:
 BOULDERS

 Mat2:
 05

 Mat2 Desc:
 CLAY

 Mat3:
 09

Mat3 Desc: MEDIUM SAND

Formation Top Depth: 0.0
Formation End Depth: 17.0
Formation End Depth UOM: ft

Method of Construction & Well

<u>Use</u>

Method Construction ID: 961502987

Method Construction Code: 1

Method Construction: Cable Tool

Other Method Construction:

Pipe Information

Pipe ID: 10573600

Casing No:

Comment: Alt Name:

Construction Record - Casing

Casing ID: 930042841

Layer: 1
Material: 1

Open Hole or Material: STEEL

Depth From:

Depth To:20Casing Diameter:5Casing Diameter UOM:inchCasing Depth UOM:ft

Order No: 21062300392

Construction Record - Casing

Casing ID: 930042842

Layer: 2 Material: 4

Open Hole or Material: OPEN HOLE

Depth From:

Depth To: 55
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502987

Pump Set At: Static Level: 15.0 Final Level After Pumping: 18.0

Recommended Pump Depth:

Pumping Rate: 6.0

Flowing Rate:

Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM

Water State After Test Code: 1
Water State After Test: CLEAR

Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933455811

Layer: 1
Kind Code: 1

Kind: FRESH
Water Found Depth: 55.0
Water Found Depth UOM: ft

22 1 of 4 S/225.3 99.9/-5.23

S.E. TERRY FOX DR. & HAZELDEAN KANATA CITY ON

99.9 / -5.23

Certificate #:3-1533-88-Application Year:88Issue Date:8/19/1988Approval Type:Municipal sewageStatus:Approved

Status: Application Type: Client Name: Client Address: Client City: Client Postal Code

Client Postal Code: Project Description: Contaminants: Emission Control:

> Terry Fox Drive and Hazeldean Road Ottawa ON

TAYLOR DEVELOPMENTS

CA

CA

Order No: 21062300392

2 of 4

S/225.3

22

5809-5B2HCC Certificate #:

Application Year: 02 Issue Date: 6/12/02

Approval Type: Municipal & Private sewage

Status: Approved

New Certificate of Approval Application Type:

Client Name: City of Ottawa

Client Address: 110 Laurier Avenue West

Client City: City of Ottawa K1P 1J1

Client Postal Code: Approval is sought for the construction of storm sewers on Terry Fox Drive. **Project Description:**

Contaminants: **Emission Control:**

22 3 of 4 S/225.3 99.9 / -5.23 Terry Fox Drive Hazeldean Road to Carp River Ottawa ON

Certificate #: 1344-5ASRJK

Application Year: 02 6/5/02 Issue Date:

Approval Type: Municipal & Private sewage

Approved Status:

Application Type: New Certificate of Approval

Client Name: City of Ottawa

Client Address: 110 Laurier Avenue West

Client City: City of Ottawa Client Postal Code: K1P 1J1

Project Description:

Approval is sought for the construction of storm sewers on Terry Fox Drive, Palladium to Carp River, City of Ottawa

Contaminants: **Emission Control:**

> 99.9 / -5.23 22 4 of 4 S/225.3 City of Ottawa **ECA**

Terry Fox Drive and Hazeldean Road

CA

Order No: 21062300392

Ottawa ON K1P 1J1

Approval No: 5809-5B2HCC Ottawa **MOE District:** Approval Date: 2002-06-12 City: Approved -75.9224 Status: Longitude: Record Type: **ECA** Latitude: 45.282

IDS Link Source: Geometry X: SWP Area Name: Mississippi Valley Geometry Y: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS Approval Type:

MUNICIPAL AND PRIVATE SEWAGE WORKS Project Type: **Business Name:** City of Ottawa

Address: Terry Fox Drive and Hazeldean Road

Full Address:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2808-5ANTEY-14.pdf

23 1 of 1 NNE/229.6 110.8 / 5.74 lot 30 con 12 **WWIS** ON

1502988 Well ID: Data Entry Status:

Data Src: Construction Date:

Primary Water Use: Domestic Date Received: 10/29/1957 Sec. Water Use: Selected Flag: True

Final Well Status: Water Supply Abandonment Rec: 4833 Water Type: Contractor:

Casing Material: Form Version: Audit No: Owner: Tag:

Street Name:

Construction Method: **OTTAWA** County:

Elevation (m): Municipality: **GOULBOURN TOWNSHIP** Elevation Reliability: Site Info:

030 Depth to Bedrock: Lot: Well Depth: Concession: 12 CON

Overburden/Bedrock: Concession Name: Pump Rate: Easting NAD83: Static Water Level: Northing NAD83:

Flowing (Y/N): Zone: Flow Rate: UTM Reliability:

Clear/Cloudy:

https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1502988.pdf PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 1957/08/02 Year Completed: 1957 Depth (m): 22.86

Latitude: 45.2976115674463 -75.8953298855595 Longitude: Path: 150\1502988.pdf

Bore Hole Information

Bore Hole ID: 10025031 Elevation: 110.437232 DP2BR: 0.00 Elevrc:

Spatial Status: Zone:

18

Code OB: East83: 429800.60 Code OB Desc: Bedrock North83: 5016402.00

Open Hole: Org CS: Cluster Kind: UTMRC:

Date Completed: 02-Aug-1957 00:00:00 **UTMRC Desc:** margin of error: 100 m - 300 m

Order No: 21062300392

Remarks: Location Method: р5 Elevrc Desc:

Location Source Date: Improvement Location Source:

Improvement Location Method: Source Revision Comment:

Supplier Comment:

Overburden and Bedrock

Materials Interval

930995729 Formation ID:

Layer:

Color: General Color:

Mat1: 18

SANDSTONE Most Common Material:

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

0.0 Formation Top Depth: Formation End Depth: 75.0 Formation End Depth UOM: ft

Method of Construction & Well

Method Construction ID: 961502988

Method Construction Code:

Method Construction: Cable Tool

Other Method Construction:

Pipe Information

Pipe ID: 10573601

Casing No: Comment: Alt Name:

Construction Record - Casing

Casing ID: 930042844

Layer: 2 Material:

Open Hole or Material: **OPEN HOLE**

Depth From: Depth To: 75 Casing Diameter: 4 Casing Diameter UOM: inch Casing Depth UOM:

Construction Record - Casing

930042843 Casing ID:

Layer: 1 Material: STEEL Open Hole or Material:

Depth From:

12 Depth To: Casing Diameter: 4 Casing Diameter UOM: inch Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502988

Pump Set At:

Static Level: 15.0 Final Level After Pumping: 15.0

Recommended Pump Depth:

Pumping Rate: 7.0

Flowing Rate:

Recommended Pump Rate:

Levels UOM: GPM Rate UOM: Water State After Test Code: **CLEAR** Water State After Test: Pumping Test Method:

Pumping Duration HR: 0 Pumping Duration MIN: 30 Flowing: No

Water Details

Water ID: 933455812

Layer: 1 Kind Code: **FRESH** Kind: Water Found Depth: 73.0 Water Found Depth UOM:

Number of Elev/Diff Site DΒ Map Key Direction/ Records Distance (m) (m)

S/233.5 99.9 / -5.23 24 1 of 1 SPL Ottawa ON

Miscellaneous Industrial

Order No: 21062300392

7123-BJTHYH Ref No: Discharger Report: Site No: Material Group:

Incident Dt: 2019/12/13 Health/Env Conseq: 0 - No Impact

Year: Client Type: Incident Cause: Sector Type:

Incident Event: Collision/Accident Agency Involved:

Contaminant Code: Nearest Watercourse:

Contaminant Name: **GASOLINE** Site Address: Site District Office: Contaminant Limit 1:

Ottawa Contam Limit Freq 1: Site Postal Code: n/a

1203 Contaminant UN No 1: Site Region: Eastern **Environment Impact:** Site Municipality: Ottawa

Nature of Impact: Site Lot: Receiving Medium: Site Conc:

5015944.99 Receiving Env: Land Northing: MOE Response: No Easting: 429767.26 Site Geo Ref Accu:

Dt MOE Arvl on Scn: **MOE** Reported Dt: 2019/12/13 Site Map Datum:

Land Spills Dt Document Closed: SAC Action Class: Incident Reason: Unknown / N/A Source Type: Motor Vehicle

Site Name: Hazeldean Rd and Terry Fox Rd, Kanata<UNOFFICIAL>

Site County/District: Site Geo Ref Meth:

Ottawa 311: MVA fluids spilled to CB; clng Incident Summary:

Contaminant Qty:

lot 31 con 12 1 of 1 NE/236.7 111.5 / 6.38 25 **WWIS**

1502995 Well ID: Data Entry Status:

Construction Date: Data Src: Primary Water Use: **Public** Date Received: 12/5/1961 Sec. Water Use: 0 Selected Flag: True

Final Well Status: Water Supply Abandonment Rec: 3503 Water Type: Contractor: Casing Material: Form Version: 1 Audit No: Owner:

Street Name: Tag:

Construction Method: County: **OTTAWA** Municipality: **GOULBOURN TOWNSHIP** Elevation (m):

Elevation Reliability: Site Info: Depth to Bedrock: Lot: 031

Well Depth: Concession: 12 Overburden/Bedrock: Concession Name: CON

Pump Rate: Easting NAD83: Static Water Level: Northing NAD83:

Flowing (Y/N): UTM Reliability: Flow Rate: Clear/Cloudy:

https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/150\1502995.pdf PDF URL (Map):

Zone:

Additional Detail(s) (Map)

1961/11/05 Well Completed Date: 1961 Year Completed: 14.6304 Depth (m):

Latitude: 45.2974385549511

-75.8944343779809 Longitude: Path: 150\1502995.pdf

Bore Hole Information

Bore Hole ID: 10025038 Elevation: 110.325904

DP2BR: 10.00 Elevrc:

Spatial Status: Zone: 18 Code OB: East83:

429870.60 Code OB Desc: Bedrock North83: 5016382.00

Open Hole: Org CS: Cluster Kind: UTMRC:

05-Nov-1961 00:00:00 UTMRC Desc: margin of error: 100 m - 300 m Date Completed:

Remarks: Location Method: Elevrc Desc:

Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: **Supplier Comment:**

Overburden and Bedrock **Materials Interval**

Formation ID: 930995744

Layer:

Color: General Color:

Mat1:

05 Most Common Material: CLAY 02 Mat2: **TOPSOIL** Mat2 Desc: Mat3: 12 Mat3 Desc: **STONES** Formation Top Depth: 0.0 Formation End Depth: 10.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 930995745

Layer:

Color:

General Color:

Mat1:

Most Common Material: SANDSTONE

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

10.0 Formation Top Depth: Formation End Depth: 48.0

Formation End Depth UOM: ft

Method of Construction & Well

<u>Use</u>

Method Construction ID: 961502995

Method Construction Code:

Method Construction: Cable Tool

Other Method Construction:

Order No: 21062300392

Pipe Information

 Pipe ID:
 10573608

 Casing No:
 1

Comment: Alt Name:

Construction Record - Casing

Casing ID: 930042858

Layer: 2 Material: 4

Open Hole or Material: OPEN HOLE

Depth From:

Depth To:48Casing Diameter:6Casing Diameter UOM:inchCasing Depth UOM:ft

Construction Record - Casing

Casing ID: 930042857

Layer: 1
Material: 1

Open Hole or Material: STEEL
Depth From:
Depth To: 12
Casing Diameter: 6

Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 991502995

Pump Set At:

Static Level:18.0Final Level After Pumping:29.0Recommended Pump Depth:40.0Pumping Rate:5.0

Flowing Rate:

Recommended Pump Rate: 5.0

Levels UOM: ft

Rate UOM:

Water State After Test Code:

Water State After Test:

Pumping Test Method:

Pumping Duration HR:

Pumping Duration MIN:

O

Flowing:

GPM

1

CLEAR

2

CLEAR

0

No

Water Details

Water ID: 933455822

 Layer:
 1

 Kind Code:
 1

 Kind:
 FRESH

 Water Found Depth:
 40.0

 Water Found Depth UOM:
 ft

Map Key	Numbe Record		Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>26</u>	1 of 3		SE/237.8	101.9/-3.20	KANATA UPHOLSTERY 500 HAZELDEAN RD KANATA ON K2L 2B5	SCT
Established: Plant Size (ft Employment	t²):		1989 1200 4			
Details Description: SIC/NAICS C			WOOD HOUSEHO	OLD FURNITURE,	UPHOLSTERED	
Description: SIC/NAICS C			Upholstered Hous 337121	ehold Furniture Ma	nufacturing	
<u>26</u>	2 of 3		SE/237.8	101.9/-3.20	ONE HOUR MOTO PHOTO 500 HAZELDEAN ROAD, UNIT #3 KANATA ON	GEN
Generator No	o:	ON1895	5402		PO Box No:	
Status: Approval Yea Contam. Fac MHSW Facili	ility:	94,95,90	6,97,98		Country: Choice of Contact: Co Admin: Phone No Admin:	
SIC Code: SIC Descript	tion:	6571	CAMERA/PHOTO	. SUPPLY		
<u>Detail(s)</u>						
Waste Class Waste Class			264 PHOTOPROCESS	SING WASTES		
<u>26</u>	3 of 3		SE/237.8	101.9 / -3.20	ONE HOUR MOTO PHOTO 500 HAZELDEAN ROAD, UNIT 3 KANATA ON	GEN
Generator No	o:	ON1895	5402		PO Box No:	
Status: Approval Yea Contam. Fac		99,00,0	1		Country: Choice of Contact: Co Admin:	
MHSW Facili SIC Code:		6571			Phone No Admin:	
SIC Descript	tion:	0071	CAMERA/PHOTO	. SUPPLY		
<u>Detail(s)</u>						
Waste Class Waste Class			264 PHOTOPROCESS	SING WASTES		
<u>27</u>	1 of 7		WNW/242.0	105.8 / 0.68	Allard's Paint & Body Shop Ltd. 33 Edgewater Street Ottawa Ontario K2L 1V7 Ottawa ON	EBR
EBR Registry Ministry Ref Notice Type: Notice Stage	No:	IA02E09 5823-50 Instrume			Decision Posted: Exception Posted: Section: Act 1:	
Notice Date: Proposal Da			y 20, 2003 07, 2002		Act 2: Site Location Map:	

Number of Direction/ Elev/Diff Site DΒ Map Key Records Distance (m) (m)

Year: 2002

Instrument Type:

(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)

Off Instrument Name:

Posted By: Company Name: Site Address:

Allard's Paint & Body Shop Ltd.

Location Other: Proponent Name: Proponent Address:

33 Edgewater Street, Ottawa Ontario, K2L 1V7

Comment Period:

URL:

Site Location Details:

33 Edgewater Street Ottawa Ontario K2L 1V7 Ottawa

27 2 of 7 WNW/242.0 105.8 / 0.68 Allard's Paint & Body Shop Ltd.

33 Edgewater Street Ottawa Ontario K2L 1V7

EBR

CA

Order No: 21062300392

Ottawa ON

Act 1:

Act 2:

EBR Registry No: IA03E0869 Decision Posted: Ministry Ref No: 2760-5NDNJB **Exception Posted:** Notice Type: Instrument Decision Section:

Notice Stage:

April 01, 2004 Notice Date:

Proposal Date: June 17, 2003 Site Location Map:

2003 Year:

Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)

Off Instrument Name:

Posted By:

Company Name: Allard's Paint & Body Shop Ltd.

Site Address: Location Other: Proponent Name:

33 Edgewater Street, Ottawa Ontario, K2L 1V7 Proponent Address:

Comment Period:

URL:

Site Location Details:

33 Edgewater Street Ottawa Ontario K2L 1V7 Ottawa

Allard's Paint & Body Shop Ltd. **27** 3 of 7 WNW/242.0 105.8 / 0.68

33 Edgewater Street

Ottawa ON

3565-5JKQV6 Certificate #: Application Year: 2003 Issue Date: 2/14/2003

Air Approval Type:

Status: Revoked and/or Replaced

Application Type: Client Name: Client Address: Client City: Client Postal Code: **Project Description:**

Contaminants: **Emission Control:**

Number of Direction/ Elev/Diff Site DΒ Map Key Records Distance (m) (m) 4 of 7 WNW/242.0 105.8 / 0.68 Allard's Paint & Body Shop Ltd. 27 CA 33 Edgewater Street Ottawa ON Certificate #: 3774-5XBL97 Application Year: 2004 Issue Date: 3/24/2004 Approval Type: Air Status: Approved Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: **Emission Control:** 5 of 7 WNW/242.0 105.8 / 0.68 Allard's Paint & Body Shop Ltd. **27 ECA** 33 Edgewater Street Ottawa ON K2L 1V7 **MOE District:** Approval No: 3565-5JKQV6 Ottawa Approval Date: 2003-02-14 City: Status: Revoked and/or Replaced Longitude: -75.89859 Record Type: **ECA** Latitude: 45.296867 **IDS** Link Source: Geometry X: SWP Area Name: Geometry Y: Mississippi Valley **ECA-AIR** Approval Type: Project Type: AIR **Business Name:** Allard's Paint & Body Shop Ltd. Address: 33 Edgewater Street Full Address: Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5823-5CRJYU-14.pdf 27 6 of 7 WNW/242.0 105.8 / 0.68 Allard's Paint & Body Shop Ltd. **ECA** 33 Edgewater Street Ottawa ON K2L 1V7 3774-5XBL97 Approval No: MOE District: Ottawa Approval Date: 2004-03-24 City: Status: Approved Longitude: -75.89859 45.296867 Latitude: **ECA** Record Type: IDS Link Source: Geometry X: SWP Area Name: Mississippi Valley Geometry Y: Approval Type: **ECA-AIR** Project Type: Allard's Paint & Body Shop Ltd. **Business Name:**

Address: 33 Edgewater Street

Full Address:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2760-5NDNJB-14.pdf

27 7 of 7 WNW/242.0 105.8 / 0.68 GTA'S Finest Restoration Services (ottawa) Inc.

33 Edgewater Street Ottawa ON K2L 1V7

Order No: 21062300392

Generator No: ON6495006 PO Box No:

Status: Country: Canada

Number of Direction/ Elev/Diff Site DΒ Map Key

CO_ADMIN 2016 Choice of Contact: Approval Years: Contam. Facility: No Co Admin: Veronique Benson 613-298-9215 Ext. MHSW Facility: No Phone No Admin:

(m)

Distance (m)

562910 REMEDIATION SERVICES SIC Description:

Detail(s)

SIC Code:

Waste Class: 251

Records

Waste Class Desc: OIL SKIMMINGS & SLUDGES

1 of 23 30 Edgewater St. 28 NW/242.6 109.9 / 4.77 CA Kanata ON K2L 1V8

1326-4LZJLV Certificate #: Application Year: 02 7/31/02 Issue Date:

Approval Type: Municipal & Private sewage Revoked and/or Replaced Status: New Certificate of Approval Application Type:

Client Name: Actum Ltd.

Client Address: 411 Roosevelt Ave., Unit 210

Ottawa Client City: K2A 3X9 Client Postal Code:

Project Description: Construction of a stormwater management facility for control of runoff for a 100 year storm. This will be achieved by

surface water retention ponding with controls in catchbasins.

Contaminants: **Emission Control:**

> 2 of 23 NW/242.6 109.9 / 4.77 **Edgewater Centre** 28 CA 30 Edgewater Street

Ottawa ON K2L 1V8

Certificate #: 2423-5CJGC5

Application Year: 02 Issue Date: 7/31/02

Approval Type: Municipal & Private sewage

Status: Approved Amended CofA Application Type: Client Name: Actum Ltd.

411 Roosevelt Avenue Client Address:

Client City: Ottawa Client Postal Code: K2A 3X9

Project Description: Change from orifice plates to ICDs in manhole.

Contaminants: **Emission Control:**

28 3 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS **GEN** 30 EDGEWATER, SUITE 108

KANATA ON K2L 1V8

Order No: 21062300392

Generator No: ON0554841 PO Box No: Country: Status:

Approval Years: 01,02,03,04,05,06,07,08 Choice of Contact: Contam. Facility: Co Admin: MHSW Facility: Phone No Admin:

SIC Code: 9959

SIC Description: OTHER SERV. TO BLDG.

Detail(s)

Map Key Number of Direction/ Elev/Diff Site DΒ Records Distance (m) (m) Waste Class: 212 ALIPHATIC SOLVENTS Waste Class Desc: Waste Class: WASTE OILS & LUBRICANTS Waste Class Desc: 28 4 of 23 NW/242.6 109.9 / 4.77 Skywave Mobile Comm. Inc. SCT 30 Edgewater St Suite 110 Kanata ON K2L 1V8 Established: 1999 Plant Size (ft2): Employment: 40 --Details--Description: Radio and Television Broadcasting and Wireless Communications Equipment Manufacturing SIC/NAICS Code: 334220 28 5 of 23 NW/242.6 109.9 / 4.77 30 Edgewater Street, Suite 106 **EHS** Ottawa ON Order No: 20050826018 Nearest Intersection: TERRY FOX ROAD / HAZELDEAN Status: Municipality: KANATA Client Prov/State: Report Type: Complete Report MI 9/7/2005 Report Date: Search Radius (km): 0.25 8/26/2005 -75.897637 Date Received: X: Previous Site Name: Y: 45.297431 Lot/Building Size: 5.5 acres, 3 buildings Additional Info Ordered: 28 6 of 23 NW/242.6 109.9 / 4.77 30 Edgewater Street **EHS** Kanata ON K2L 1V8 Nearest Intersection: Order No: 20060613011 Edgewater Street and Terry Fox Drive Status: С Municipality: Complete Report ON Report Type: Client Prov/State: 6/21/2006 Search Radius (km): 0.25 Report Date: Date Received: 6/13/2006 -75.897652 X: Y: Previous Site Name: 45.29729 Lot/Building Size: Additional Info Ordered: 28 7 of 23 NW/242.6 109.9 / 4.77 Espial Group Inc. SCT 30 Edgewater St Suite 114 Kanata ON K2L 1V8 Established: Plant Size (ft2): Employment:

Order No: 21062300392

--Details--

Description:

Software Publishers

SIC/NAICS Code: 511210

Description: Software Publishers

SIC/NAICS Code: 511210

Number of Direction/ Elev/Diff Site DΒ Map Key

Records Distance (m) (m)

Computer Systems Design and Related Services Description:

SIC/NAICS Code: 541510

28 8 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS

30 EDGEWATER, SUITE 108

GEN

GEN

Order No: 21062300392

KANATA ON

Choice of Contact:

Phone No Admin:

PO Box No:

Country:

Co Admin:

Generator No: ON0554841

Status: Approval Years:

2009

Contam. Facility: MHSW Facility:

SIC Code: 561210

Facilities Support Services SIC Description:

Detail(s)

Waste Class: 252

WASTE OILS & LUBRICANTS Waste Class Desc:

Waste Class:

ALIPHATIC SOLVENTS Waste Class Desc:

30 Edgewater St 28 9 of 23 NW/242.6 109.9 / 4.77 **EHS** Ottawa ON K2L 1V8

20120228024 Order No:

Status:

Site Report Report Type:

Report Date: 2/29/2012 2:07:33 PM 2/28/2012 2:04:51 PM Date Received:

Previous Site Name: Lot/Building Size: Additional Info Ordered: Nearest Intersection: Municipality:

DC Client Prov/State: Search Radius (km): 0.25

-75.897645 X: Y: 45.296953

28 10 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS 30 EDGEWATER, SUITE 108

KANATA ON

Choice of Contact:

Phone No Admin:

PO Box No:

Country:

Co Admin:

Generator No: ON0554841

Status:

Approval Years: 2010

Contam. Facility:

MHSW Facility:

SIC Code: 561210

SIC Description: **Facilities Support Services**

Detail(s)

Waste Class: 212

ALIPHATIC SOLVENTS Waste Class Desc:

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class:

Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 262

Waste Class Desc: **DETERGENTS/SOAPS**

Number of Elev/Diff Site DΒ Map Key Direction/ Records Distance (m) (m)

Waste Class: 145

PAINT/PIGMENT/COATING RESIDUES Waste Class Desc:

Waste Class:

WASTE OILS & LUBRICANTS Waste Class Desc:

Waste Class: 331

Waste Class Desc: WASTE COMPRESSED GASES

28 11 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS **GEN** 30 EDGEWATER, SUITE 108

KANATA ON

Choice of Contact:

Phone No Admin:

PO Box No: Country:

Co Admin:

ON0554841 Generator No:

Status:

Approval Years: 2011

Contam. Facility:

MHSW Facility:

SIC Code: 561210

SIC Description: **Facilities Support Services**

Detail(s)

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 262

Waste Class Desc: **DETERGENTS/SOAPS**

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class:

Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class:

WASTE COMPRESSED GASES Waste Class Desc:

Waste Class:

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

28 12 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS **GEN** 30 EDGEWATER, SUITE 108

KANATA ON K2L 1V8

Order No: 21062300392

Choice of Contact:

Phone No Admin:

PO Box No:

Country:

Co Admin:

Generator No: ON0554841

Status: Approval Years:

2012

Contam. Facility: MHSW Facility:

SIC Code: 561210

SIC Description: Facilities Support Services

Detail(s)

262 Waste Class:

DETERGENTS/SOAPS Waste Class Desc:

Waste Class: 212

Elev/Diff Site DΒ Map Key Number of Direction/ Records Distance (m)

(m)

ALIPHATIC SOLVENTS Waste Class Desc:

Waste Class: 148

Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 331

Waste Class Desc: WASTE COMPRESSED GASES

Waste Class:

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class:

WASTE OILS & LUBRICANTS Waste Class Desc:

Waste Class:

ORGANIC LABORATORY CHEMICALS Waste Class Desc:

28 13 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS **GEN** 30 EDGEWATER, SUITE 108

KANATA ON

Generator No: ON0554841 PO Box No: Status: Country:

Approval Years: 2013 Choice of Contact: Contam. Facility: Co Admin: MHSW Facility: Phone No Admin:

SIC Code: 561210

FACILITIES SUPPORT SERVICES SIC Description:

Detail(s)

Waste Class:

Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 331

WASTE COMPRESSED GASES Waste Class Desc:

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 145

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class:

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 262

DETERGENTS/SOAPS Waste Class Desc:

14 of 23 NW/242.6 109.9 / 4.77 28 Actum Ltd. **ECA** 30 Edgewater St.

Kanata ON K2A 3X9

Order No: 21062300392

Approval No: 1326-4LZJLV **MOE District:** Ottawa 2002-07-31 Approval Date: City:

Status: Revoked and/or Replaced Longitude: -75.89685 Record Type: **ECA** Latitude: 45.297447 **IDS** Link Source: Geometry X:

SWP Area Name: Mississippi Valley Geometry Y: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS Approval Type:

Number of Elev/Diff Site DΒ Map Key Direction/

Records Distance (m) (m)

MUNICIPAL AND PRIVATE SEWAGE WORKS Project Type:

Business Name: Actum Ltd. Address: 30 Edgewater St. Full Address:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3072-4LHSJG-14.pdf

28 15 of 23 NW/242.6 109.9 / 4.77 Actum Ltd. **ECA**

30 Edgewater Street Ottawa ON K2A 3X9

Order No: 21062300392

Approval No: 2423-5CJGC5 **MOE District:** Ottawa

2002-07-31 Approval Date: City:

Approved Status: Longitude: -75.89685 **ECA** Record Type: Latitude: 45.297447

IDS Link Source: Geometry X: SWP Area Name: Mississippi Valley Geometry Y: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS Approval Type: MUNICIPAL AND PRIVATE SEWAGE WORKS

Project Type: **Business Name:** Actum Ltd.

Address: 30 Edgewater Street Full Address:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9695-5AUNDT-14.pdf

28 16 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS **GEN**

30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8

ON0554841 Generator No: PO Box No:

Status: Country:

Canada 2016 Approval Years: Choice of Contact: CO_OFFICIAL

Contam. Facility: No Co Admin: MHSW Facility: No Phone No Admin:

561210 SIC Code: **FACILITIES SUPPORT SERVICES** SIC Description:

Detail(s)

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 122

Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class:

Waste Class Desc: WASTE COMPRESSED GASES

Waste Class:

Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 145

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 262

Waste Class Desc: **DETERGENTS/SOAPS**

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class:

Waste Class Desc: ALIPHATIC SOLVENTS

Elev/Diff Site DΒ Map Key Number of Direction/

Records Distance (m)

(m)

28 17 of 23

109.9 / 4.77 NW/242.6

JOHNSON CONTROLS 30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8

GEN

Order No: 21062300392

ON0554841 Generator No: PO Box No:

Status:

2015 Approval Years: Contam. Facility: No MHSW Facility: No

Country: Canada CO_OFFICIAL Choice of Contact: Co Admin: Veronica Drummond Phone No Admin: 613-831-6725 Ext.

561210 SIC Code:

FACILITIES SUPPORT SERVICES SIC Description:

Detail(s)

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class:

Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class:

PAINT/PIGMENT/COATING RESIDUES Waste Class Desc:

Waste Class: 262

Waste Class Desc: **DETERGENTS/SOAPS**

Waste Class: 331

Waste Class Desc: WASTE COMPRESSED GASES

Waste Class:

Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class:

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 263

ORGANIC LABORATORY CHEMICALS Waste Class Desc:

28 18 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS **GEN** 30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8

Generator No: ON0554841 PO Box No:

Status: Country:

Canada 2014 CO_OFFICIAL Approval Years: Choice of Contact: Contam. Facility: No Co Admin: Veronica Drummond MHSW Facility: No Phone No Admin: 613-831-6725 Ext.

SIC Code: 561210 **FACILITIES SUPPORT SERVICES** SIC Description:

Detail(s)

Waste Class: 252

WASTE OILS & LUBRICANTS Waste Class Desc:

Waste Class:

INORGANIC LABORATORY CHEMICALS Waste Class Desc:

Waste Class:

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 262 Map Key Number of Direction/ Elev/Diff Site DB

Records Distance (m) (

Waste Class: 212

Waste Class Desc:

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 331

Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 263

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

28 19 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS 30 EDGEWATER, SUITE 108

KANATA ON K2L 1V8

Generator No: ON0554841 PO Box No:

Status: Registered Country: Canada

Approval Years: As of Dec 2018 Choice of Contact:
Contam. Facility: Co Admin:
MHSW Facility: Phone No Admin:
SIC Code:

DETERGENTS/SOAPS

Detail(s)

SIC Description:

Waste Class: 122 C

Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145

Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C

Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 212 L

Waste Class Desc: Aliphatic solvents and residues

Waste Class: 252 L

Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 262 L

Waste Class Desc: Detergents and soaps

Waste Class: 263 l

Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I

Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 331 L

Waste Class Desc: Waste compressed gases including cylinders

28 20 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS
20 EDGENATED SUITE 100

30 EDGEWATER, SUITE 108 KANATA ON K2L 1V8

Canada

Order No: 21062300392

Generator No:ON0554841PO Box No:Status:RegisteredCountry:

 Status:
 Registered
 Country:

 Approval Years:
 As of Jul 2020
 Choice of Contact:

 Contam. Facility:
 Co Admin:

 MHSW Facility:
 Phone No Admin:

SIC Code: SIC Description: Map Key Number of Direction/ Elev/Diff Site DB

Detail(s)

Waste Class: 212 L

Records

Waste Class Desc: Aliphatic solvents and residues

Waste Class: 252 L

Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 331 I

Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 145 l

Waste Class Desc: Wastes from the use of pigments, coatings and paints

Distance (m)

(m)

Waste Class: 263 l

Waste Class Desc: Misc. waste organic chemicals

Waste Class: 122 C

Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 148 C

Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 262 L

Waste Class Desc: Detergents and soaps

Waste Class: 133 L

Waste Class Desc: Brine, chlor-alkali sludges

Waste Class: 331 L

Waste Class Desc: Waste compressed gases including cylinders

28 21 of 23 NW/242.6 109.9 / 4.77 Rockwell Collins Canada Inc

30 EDGEWATER ST SUITE 104

GEN

Order No: 21062300392

KANATA ON K2L 1V8

Generator No: ON3771071 PO Box No:

Status: Registered Country: Canada

Approval Years:As of Jul 2020Choice of Contact:Contam. Facility:Co Admin:MHSW Facility:Phone No Admin:

SIC Code: SIC Description:

Detail(s)

Waste Class: 232 L

Waste Class Desc: Polymeric resins

Waste Class: 263 l

Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I

Waste Class Desc: Waste compressed gases including cylinders

28 22 of 23 NW/242.6 109.9 / 4.77 Rockwell Collins Canada Inc 30 EDGEWATER ST SUITE 104 GEN

KANATA ON K2L 1V8

Generator No: ON3771071 PO Box No:

Status: Registered Country: Canada

Approval Years: As of Apr 2021 Choice of Contact:

Map Key Number of Direction/ Elev/Diff Site DB

Records Distance (m) (m)

Contam. Facility: Co Admin: MHSW Facility: Phone No Admin:

SIC Code: SIC Description:

Detail(s)

Waste Class: 263 l

Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I

Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 232 L

Waste Class Desc: Polymeric resins

28 23 of 23 NW/242.6 109.9 / 4.77 JOHNSON CONTROLS 30 EDGEWATER, SUITE 108

KANATA ON K2L 1V8

Order No: 21062300392

Generator No: ON0554841 PO Box No:

Status: Registered Country: Canada

Approval Years:As of Apr 2021Choice of Contact:Contam. Facility:Co Admin:MHSW Facility:Phone No Admin:

SIC Code: SIC Description:

Detail(s)

Waste Class: 145 I

Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L

Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 133 L

Waste Class Desc: Brine, chlor-alkali sludges

Waste Class: 331 I

Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 148 C

Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 331 l

Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 212 L

Waste Class Desc: Aliphatic solvents and residues

Waste Class: 262 L

Waste Class Desc: Detergents and soaps

Waste Class: 122 C

Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 263 l

Waste Class Desc: Misc. waste organic chemicals

Unplottable Summary

Total: 45 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA		Block 40, 4M-405, Foulis Crescent	Kanata ON	
CA	Terry Fox Drive Stormwater Management Facility at Realigned Richardson Side Road	Terry Fox Drive	Ottawa ON	
CA	R.M. OF OTTAWA-CARLETON, ENVIRONMENT & T	HAZELDEAN P.S. OVERFLOW MODS	KANATA CITY ON	
CA	CANADIAN TIRE REAL ESTATE LTD., GILPAUL	TERRY FOX DR.,GAS BAR SWM FAC.	KANATA CITY ON	
CA	CLARIDGE HOMES (KANATA) INC.	PT.LOT 30/CONC.XI (SWM)	KANATA CITY ON	
CA	CLARIDGE HOMES (KANATA) INC.	HAZELDEAN RD.,PT.LOT 30/CON.XI	KANATA CITY ON	
CA	PENEX HAZELDEAN LIMITED	HAZELDEAN ROAD (SWM)	KANATA CITY ON	
CA	KANATA RESEARCH PARK CORP.	TERRY FOX DR.,CROSS KEY, SWM	KANATA CITY ON	
CA		Terry Fox Drive	Kanata ON	
CA	MACDONALD REALESTATE LTD.	HAZELDEAN RD.	KANATA CITY ON	
CA	KANATA CITY	PT.LOT 3/CON.1, TERRY FOX DR.	KANATA CITY ON	
CA	KANATA RESEARCH PARK CORPORATION	TERRY FOX DR. KANATA N. BUS. P	KANATA CITY ON	
CA	GARFORD LTD. AND NOTLAW LTDTERRY FOX D	M.T.O. ACCES RD/TERRY FOX DR.	KANATA CITY ON	
CA	Westcreek Meadows - Phase 2B	Part of West Half of Lot 30, Concession 11	Kanata ON	
CA	KANATA CITY	KANATA COLISEUM EDGEWATER DR.	KANATA CITY ON	
CA	RICHGREEN REALTY CORP.	KANATA CORP.BUS.PK.TERRY FOX	KANATA CITY ON	
CA	TAYLOR DEVELOPMENTS	SHOPPING CEN., TERRY FOX DRIVE	KANATA CITY ON	

CA	KANATA CITY VALLEY-VU REALTY	FUTURE TERRY FOX DR.	KANATA CITY ON	
CA	CALMAR HOLDINGS (ONT) LTDPT. LOT 31	COPE DR.+STORMWATER MANAGEMENT	KANATA CITY ON	
CA	CALMAR HOLDINGS (ONT) LTDPT. LOT 31	COPE DR./SPALDING CRES.	KANATA CITY ON	
CA	R.M. OF OTTAWA-CARLETON- LOT 31, 31-PH. 2	EAGLESON RDCONC. 10 & 6	KANATA CITY ON	
CA	RICHGREEN REALTY CORPORATION	KANATA CORP.BUS.PK. TERRY FOX	KANATA CITY ON	
CA	KANATA CITY VALLEY-VU REALTY FORCEMAIN	FUTURE TERRY FOX DR. P.S.	KANATA CITY ON	
CA	MACDONALD REALESTATE LTD.	HAZELDEAN RD.	KANATA CITY ON	
CA	KANATA CITY	TERRY FOX DRIVE	KANATA CITY ON	
CA	KANATA CITY KANATA N. BUSINESS PARK	TERRY FOX DRIVE	KANATA CITY ON	
CA	TACO BELL OF CANADA	HAZELDEAN ROAD	KANATA CITY ON	
CA	Toromont Industries Ltd.		Ottawa ON	
CA		Block 40, 4M-405, Foulis Crescent	Kanata ON	
CA	CALMAR HOLDINGS (ONT) LTD. PT. LOT 31	COPE DR./SPALDING CRES.	KANATA CITY ON	
CA	Westcreek Meadows - Phase 2B	Part of West Half of Lot 30, Concession 11	Kanata ON	
CONV	Waste Services (CA) Inc		Ottawa ON	
EASR	288688 ONTARIO INC.	EDGEWATER STREET	KANATA ON	K2L 1V7
ECA	City of Ottawa	Terry Fox Dr Hazeldean Road to Carp River	Ottawa ON	K1P 1J1
ECA	City of Ottawa	Terry Fox Dr	Ottawa ON	K1P 1J1
EHS		Young St	Ottawa ON	
GEN	KANATA HYDRO-ELECTRIC COMMISSION	HAZELDEAN M.S., PT LOT 34 CONC. 6	KANATA ON	K2K 1X4
GEN	KANATA HYDRO-ELECTRIC COMMISSION 23-456	HAZELDEAN M.S., PT LOT 34 CONC. 6 C/O 100 MAPLEGROVE RD.	KANATA ON	K2K 1X4
PTTW	Richardson Ridge Inc.	Property of Richardson Ridge Inc. Terry Fox Drive (northeast of Huntsville Drive and between Richardson Side Road and Huntsville Drive), City of Ottawa	CITY OF OTTAWA ON	

S	SPL	Van's Industrial & Specialty Coatings <unofficial></unofficial>	Terry Fox Drive, Nepean	Ottawa ON
S	SPL	TOP OIL RESOURCES	TOP OIL RESOURCES HAZELDEAN ROAD, GOULBORN TWP. DIESEL FUEL OUTLET	OTTAWA-CARLETON R. M. ON
S	SPL	PUC	TERRY FOX DR PAD TRANSFORMER BY NEWBRIDGE COMM. LTD.	KANATA CITY ON
٧	VWIS		lot 31	ON
٧	VWIS		lot 31	ON
٧	VWIS		4129 CALBRENT lot 31	ON

Unplottable Report

Database:

CA

CA

Database:

Site: Block 40, 4M-405, Foulis Crescent Kanata ON

Application Year:

11/3/00 Issue Date:

Municipal & Private sewage Approval Type:

Status: Approved

New Certificate of Approval Application Type: Client Name: Pegasus Development Corporation

Client Address: 1914 Merivale Rd.

Client City: Nepean K2G 1E8 Client Postal Code:

Project Description: This application is for the installation of sanitary sewers on Foulis Crescemt located off Young Road in the City of

2836-4QPMGC

Contaminants: **Emission Control:**

Certificate #:

Site: Terry Fox Drive Stormwater Management Facility at Realigned Richardson Side Road Database:

Terry Fox Drive Ottawa ON

1044-5E9JWT Certificate #:

Application Year: 02 Issue Date: 9/27/02

Municipal & Private sewage Approval Type:

Approved Status:

Application Type: New Certificate of Approval

Client Name: City of Ottawa

Client Address: 110 Laurier Avenue West

City of Ottawa Client City: Client Postal Code: K1P 1J1

SWM Facility, quality and quantitay control with inlet and outlet sewers **Project Description:**

Contaminants: **Emission Control:**

Site: R.M. OF OTTAWA-CARLETON, ENVIRONMENT & T Database:

HAZELDEAN P.S. OVERFLOW MODS KANATA CITY ON

Certificate #: 3-1045-99-Application Year: 99

Issue Date: 10/14/1999 Municipal sewage Approval Type: Approved

Status: Application Type: Client Name: Client Address: Client City: Client Postal Code:

Project Description: Contaminants: **Emission Control:**

103

CANADIAN TIRE REAL ESTATE LTD., GILPAUL Site:

TERRY FOX DR., GAS BAR SWM FAC. KANATA CITY ON

3-0329-99-Certificate #:

Application Year:99Issue Date:7/26/1999Approval Type:Municipal sewageStatus:Cancelled

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: CLARIDGE HOMES (KANATA) INC.

PT.LOT 30/CONC.XI (SWM) KANATA CITY ON

Certificate #:3-1116-96-Application Year:96Issue Date:10/22/1996Approval Type:Municipal sewageStatus:Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants:

Emission Control:

Site: CLARIDGE HOMES (KANATA) INC.

HAZELDEAN RD.,PT.LOT 30/CON.XI KANATA CITY ON

Certificate #:3-0960-96-Application Year:96Issue Date:9/6/1996Approval Type:Municipal sewageStatus:Approved

Status: Application Type: Client Name: Client Address: Client City:

Client Postal Code: Project Description: Contaminants: Emission Control:

Site: PENEX HAZELDEAN LIMITED

HAZELDEAN ROAD (SWM) KANATA CITY ON

Certificate #: 3-0099-97Application Year: 97
Issue Date: 4/11/1997
Approval Type: Municipal sewage
Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code:

Client Postal Code: Project Description: Contaminants: Emission Control: Database:

Database:

Database: CA

Site: KANATA RESEARCH PARK CORP.

TERRY FOX DR., CROSS KEY, SWM KANATA CITY ON

Database: CA

Order No: 21062300392

Certificate #: 3-0087-96Application Year: 96
Issue Date: 4/1/1996
Approval Type: Municipal sewage
Status: Approved

Status: Application Type: Client Name: Client Address: Client City: Client Postal Code

Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site:
Terry Fox Drive Kanata ON
Database:
CA

-

 Certificate #:
 0854-4JBJN5

 Application Year:
 00

 Issue Date:
 4/13/00

Approval Type: Municipal & Private water Status: Approved

Application Type: New Certificate of Approval

Client Name: Corporation of the Regional Municipality of Ottawa-Carleton

Client Address: 111 Lisgar Street

Client City: Ottawa
Client Postal Code: K2P 2L7

Project Description: Extension of the watermain on Terry Fox Drive from Winchester Drive south to Michael Cowpland Drive, with a 400

mm diameter watermain.

Contaminants: Emission Control:

<u>Site:</u> MACDONALD REALESTATE LTD. Database: HAZELDEAN RD. KANATA CITY ON CA

Certificate #: 7-1305-86Application Year: 86
Issue Date: 11/4/1986
Approval Type: Municipal water
Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: KANATA CITY Database: PT.LOT 3/CON.1, TERRY FOX DR. KANATA CITY ON CA

Certificate #: 3-1095-94Application Year: 94
Issue Date: 10/4/1994
Approval Type: Municipal sewage
Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: KANATA RESEARCH PARK CORPORATION

TERRY FOX DR. KANATA N. BUS. P KANATA CITY ON

Database:

Certificate #: 7-0653-87Application Year: 87
Issue Date: 6/9/1987
Approval Type: Municipal water
Status: Approved
Application Type:

Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

<u>Site:</u> GARFORD LTD. AND NOTLAW LTD.-TERRY FOX D M.T.O. ACCES RD/TERRY FOX DR. KANATA CITY ON

Database:

Certificate #:7-0939-91-Application Year:91Issue Date:8/2/1991Approval Type:Municipal waterStatus:Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: Westcreek Meadows - Phase 2B

Part of West Half of Lot 30, Concession 11 Kanata ON

Database:

CA

Certificate #: 1686-4PZLMV

Application Year:00Issue Date:10/12/00

Approval Type: Municipal & Private sewage

Status: Approved

Application Type:New Certificate of ApprovalClient Name:Claridge Homes (Kanata) Inc.Client Address:210 Gladstone Avenue, Suite #2001

Client City: Ottawa
Client Postal Code: K2P 0Y6

Project Description: This application is for the installation of sanitary and storm sewers on Kincardine Drive to serve the Westcreek

Meadows, Phase 2B, subdivision.

Contaminants: Emission Control:

Site: KANATA CITY

KANATA COLISEUM EDGEWATER DR. KANATA CITY ON

Database:

Order No: 21062300392

Certificate #: 7-1652-89Application Year: 89
Issue Date: 10/3/1989
Approval Type: Municipal water

Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: RICHGREEN REALTY CORP.

KANATA CORP.BUS.PK.TERRY FOX KANATA CITY ON

Database:

Certificate #: 7-1358-89-Application Year: 89

Issue Date: 8/15/1989
Approval Type: Municipal water
Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants:

Emission Control:

Site: TAYLOR DEVELOPMENTS

SHOPPING CEN., TERRY FOX DRIVE KANATA CITY ON

Database:

Database:

CA

 Certificate #:
 7-1321-88

 Application Year:
 88

 Issue Date:
 8/19/1988

 Approval Type:
 Municipal water

 Status:
 Approved

Status:
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:

Emission Control:

Site: KANATA CITY VALLEY-VU REALTY

FUTURE TERRY FOX DR. KANATA CITY ON

Certificate #: 7-1420-86-Application Year: 86

Issue Date:12/17/1986Approval Type:Municipal waterStatus:Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants:

Emission Control:

Site: CALMAR HOLDINGS (ONT) LTD.-PT. LOT 31

COPE DR.+STORMWATER MANAGEMENT KANATA CITY ON

Database:

Certificate #:3-1216-90-Application Year:90Issue Date:7/24/1990Approval Type:Municipal sewageStatus:Approved

Status: Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description:

Contaminants: Emission Control:

<u>Site:</u> CALMAR HOLDINGS (ONT) LTD.-PT. LOT 31 COPE DR./SPALDING CRES. KANATA CITY ON

Database:

Certificate #:3-1217-90-Application Year:90Issue Date:7/6/1990Approval Type:Municipal sewageStatus:Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: R.M. OF OTTAWA-CARLETON-LOT 31, 31-PH. 2 EAGLESON RD.-CONC. 10 & 6 KANATA CITY ON Database:

Certificate #: 3-1030-90Application Year: 90
Issue Date: 6/8/1990
Approval Type: Municipal sewage
Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description:

Contaminants: Emission Control:

<u>Site:</u> RICHGREEN REALTY CORPORATION

KANATA CORP.BUS.PK. TERRY FOX KANATA CITY ON

Database:

Order No: 21062300392

 Certificate #:
 3-1634-89

 Application Year:
 89

 Issue Date:
 8/15/1989

 Approval Type:
 Municipal sewage

 Status:
 Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants:

Emission Control:

<u>Site:</u> KANATA CITY VALLEY-VU REALTY FORCEMAIN FUTURE TERRY FOX DR. P.S. KANATA CITY ON

Database:

Certificate #:3-1793-86-Application Year:86Issue Date:12/17/1986Approval Type:Municipal sewageStatus:Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: MACDONALD REALESTATE LTD.

HAZELDEAN RD. KANATA CITY ON

Certificate #:3-1645-86-Application Year:86Issue Date:11/4/1986Approval Type:Municipal sewageStatus:Approved

Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: KANATA CITY

TERRY FOX DRIVE KANATA CITY ON

Certificate #: 3-1806-87Application Year: 87
Issue Date: 10/5/1987
Approval Type: Municipal sewage
Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants:

Emission Control:

<u>Site:</u> KANATA CITY KANATA N. BUSINESS PARK TERRY FOX DRIVE KANATA CITY ON

 Certificate #:
 3-0786-87

 Application Year:
 87

 Issue Date:
 6/9/1987

 Approval Type:
 Municipal services

Approval Type: Municipal sewage Status: Approved

Application Type: Client Name: Client Address: Database: CA

Database:

Database: CA

Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: TACO BELL OF CANADA

HAZELDEAN ROAD KANATA CITY ON

Database: CA

Certificate #: 8-4092-94Application Year: 94
Issue Date: 7/15/1994
Approval Type: Industrial air
Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code:

Project Description: CONDENSATE & FRYER EXHAUST HOODS

Contaminants: Odour/Fumes Emission Control: Fabric Filters,

<u>Site:</u> Toromont Industries Ltd.

Ottawa ON

Database: CA

 Certificate #:
 8440-7H2L7X

 Application Year:
 2008

 Issue Date:
 8/8/2008

Approval Type: Industrial Sewage Works

Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code

Client Postal Code: Project Description: Contaminants: Emission Control:

Site:

Database:

Block 40, 4M-405, Foulis Crescent Kanata ON

Certificate #: 3022-4QPMPH
Application Year: 00

Issue Date: 11/3/00

Approval Type: Municipal & Private water

Status: Approved

Application Type: New Certificate of Approval Client Name: Pegasus Development Corporation

Client Address: 1914 Merivale Rd.

Client City: Nepean
Client Postal Code: K2G 1E8

Project Description: This application is for the installation of watermains on Foulis Crescent located off Young Road in the City of

Kanata.

Contaminants: Emission Control:

<u>Site:</u> CALMAR HOLDINGS (ONT) LTD. PT. LOT 31 COPE DR./SPALDING CRES. KANATA CITY ON

Database:

Order No: 21062300392

 Certificate #:
 7-0987-90

 Application Year:
 90

 Issue Date:
 7/6/1990

Approval Type: Municipal water Status: Approved

Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:

Site: Westcreek Meadows - Phase 2B

Part of West Half of Lot 30, Concession 11 Kanata ON

Database:

Certificate #: 2660-4PZM2T Application Year: 00

Issue Date: 10/12/00

Approval Type: Municipal & Private water

Status: Approved

Application Type:New Certificate of ApprovalClient Name:Claridge Homes (Kanata) Inc.Client Address:210 Gladstone Avenue, Suite #2001

Client City: Ottawa
Client Postal Code: K2P 0Y6

Project Description: This application is for the installation of watermains on Kincardine Drive to serve the Westcreek Meadows, Phase

Location:

Ministry District:

Region:

2B, subdivision.

Contaminants: Emission Control:

Site: Waste Services (CA) Inc

Ottawa ON

Database: CONV

Order No: 21062300392

File No: 112803 Crown Brief No:

Court Location: Publication City:

Publication Title:

Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description:

Santaro Development LLC has been fined \$10,000 plus a victim fine surcharge, and Waste Services (CA) Inc. has been fined \$7,500 plus a victim fine surcharge, after pleading guilty on November 13, 2008 to violations under the

Environmental Protection Act. Santaro Development LLC pleaded guilty to operating a Waste Management System without a Certificate of Approval, and Waste Services (CA) Inc. pleaded guilty to arranging for the use of equipment, namely transport trucks, for the handling and transportation of waste that was not part of a Waste Management System for which a Certificate of Approval had been issued. The companies were given 60 days to pay. The Court heard that Santaro Development LLC is a New York Based trucking company. Waste Services (CA) Inc. is an Ontario company that operates waste disposal sites, transfer facilities and waste management systems, including a facility in Ottawa. During a ministry surveillance program, Santaro trucks were observed crossing the border into Canada, picking up waste at the Waste Services facility in Ottawa, and crossing back into the United States to dispose of the waste. At the time, Santaro did not have an approval from the ministry for a Waste Management System, and Waste Services did not ensure that Santaro had the necessary approval prior to arranging for it to transport waste from its facility. Santaro Development LLC and Waste Services (CA) Inc. were

charged following an investigation by the Ministry of the Environment's Investigations and Enforcement Branch

Background:

URL:

Additional Details

Publication Date:

 Count:
 1

 Act:
 EPA

Regulation: Section:

Act/Regulation/Section: **EPA**

Date of Offence: Date of Conviction: Date Charged:

November 13, 2008

Charge Disposition: FINED, plus a victim fine surcharge

Fine: \$7,500

Synopsis:

288688 ONTARIO INC. Site:

EDGEWATER STREET KANATA ON K2L 1V7

Database:

R-001-4249478874 SWP Area Name: Approval No: Status: REGISTERED **MOE District:**

KANATA Date: 2012-10-26 Municipality:

EASR Latitude: Record Type: Link Source: **MOFA** Longitude: Project Type: Automotive Refinishing Facility Geometry X: Full Address: Geometry Y:

Approval Type: **EASR-Automotive Refinishing Facility**

Full PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2333

Site: City of Ottawa Database: **ECA** Terry Fox Dr Hazeldean Road to Carp River Ottawa ON K1P 1J1

1344-5ASRJK **MOE District:** Approval No: 2002-06-05 Approval Date: City: Status: Approved Longitude: Record Type: **ECA** Latitude: IDS Link Source: Geometry X: SWP Area Name: Geometry Y:

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS MUNICIPAL AND PRIVATE SEWAGE WORKS Project Type: **Business Name:** City of Ottawa

Address: Terry Fox Dr Hazeldean Road to Carp River

Full Address: Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6279-5ANTPG-14.pdf

Site: City of Ottawa Database: Terry Fox Dr Ottawa ON K1P 1J1 **ECA**

1044-5E9JWT **MOE District:** Approval No: Approval Date: 2002-09-27 City: Revoked and/or Replaced Longitude: Status: Record Type: **ECA** Latitude: Link Source: IDS Geometry X: SWP Area Name: Geometry Y:

ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS Approval Type: Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS

City of Ottawa **Business Name:** Address: Terry Fox Dr

Full Address: **Full PDF Link:** https://www.accessenvironment.ene.gov.on.ca/instruments/6019-59QSAT-14.pdf

Site: Database: Young St Ottawa ON **EHS**

20030828009 Nearest Intersection: Lorette & Champagne

Order No: С Status: Municipality:

Report Type: Complete Report Client Prov/State: ON Report Date: 9/8/03 Search Radius (km): 0.25 8/28/03 -75.714064 Date Received: X: Previous Site Name: Y: 45.401749

Site: KANATA HYDRO-ELECTRIC COMMISSION

HAZELDEAN M.S., PT LOT 34 CONC. 6 KANATA ON K2K 1X4

Database: GEN

Database: PTTW

Order No: 21062300392

 Generator No:
 ON0646403
 PO Box No:

 Status:
 Country:

Approval Years: 92,93,97,98 Choice of Contact:
Contam. Facility: Co Admin:
MHSW Facility: Phone No Admin:

SIC Code: 4911

SIC Description: ELECT. POWER SYS.

Detail(s)

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Site: KANATA HYDRO-ELECTRIC COMMISSION 23-456 Database: HAZELDEAN M.S., PT LOT 34 CONC. 6 C/O 100 MAPLEGROVE RD. KANATA ON K2K 1X4 GEN

Generator No: ON0646403 PO Box No:

Status: Country:

Approval Years: 94,95,96 Choice of Contact:
Contam. Facility: Co Admin:
MHSW Facility: Phone No Admin:

SIC Code: 4911

SIC Description: ELECT. POWER SYS.

Detail(s)

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251

Waste Class Desc: OIL SKIMMINGS & SLUDGES

<u>Site:</u> Richardson Ridge Inc.
Property of Richardson Ridge Inc. Terry Fox Drive (northeast of Huntsville Drive and between Richardson Side

Road and Huntsville Drive), City of Ottawa CITY OF OTTAWA ON

EBR Registry No:012-2859Decision Posted:Ministry Ref No:7488-9Q5HKYException Posted:

Notice Type:Instrument DecisionSection:Notice Stage:Act 1:Notice Date:May 06, 2015Act 2:

Proposal Date: October 22, 2014 Site Location Map:

Year: 2014

Instrument Type: (OWRA s. 34) - Permit to Take Water

Off Instrument Name:

Posted By:
Company Name: Richardson Ridge Inc.

Site Address: Location Other: Proponent Name:

Proponent Address: 1737 Woodward Drive, 2nd Floor, Ottawa Ontario, Canada K2C 0P9

Comment Period:

URL:

Site Location Details:

Site: Van's Industrial & Specialty Coatings<UNOFFICIAL>

Terry Fox Drive, Nepean Ottawa ON

Database: SPL

Database:

Ref No: 2438-6GNMTJ Discharger Report: 0

Site No: Material Group: Oil Incident Dt: 9/28/2005 Health/Env Conseq:

Year: Client Type:

Incident Cause: Other Transport Accident Sector Type: Other Motor Vehicle

Incident Event:

Contaminant Code:

Agency Involved:

Nearest Watercourse:

Contaminant Name: DIESEL FUEL Site Address:
Contaminant Limit 1: Site District Office:

Contaminant Limit 1: Site District Office:
Contam Limit Freq 1: Site Postal Code:

Site Postal Code: Site Region: Ottawa

Spills to Watercourses

Environment Impact: Not Anticipated Site Municipality: Ottawa Nature of Impact: Site Lot:

 Nature of Impact:
 Site Lot:

 Receiving Medium:
 Land & Water
 Site Conc:

 Receiving Env:
 Northing:

 MOE Response:
 Fasting:

MOE Response: Easting:
Dt MOE Arvl on Scn: Site Geo Ref Accu:

MOE Reported Dt: 9/28/2005 Site Map Datum:
Dt Document Closed: SAC Action Class:

Incident Reason: Adverse Road Condition - Road faults Source Type:

Site Name: East side of Terry Fox Drive, between March Road and Legget Drive<UNOFFICIAL>

Site County/District:
Site Geo Ref Meth:
Incident Summary:

Van's Cleaning, 40 L die

Incident Summary: Van's Cleaning, 40 L diesel to road, ditch, sewer Contaminant Qty:

Site: TOP OIL RESOURCES

TOP OIL RESOURCES HAZELDEAN ROAD, GOULBORN TWP. DIESEL FUEL OUTLET OTTAWA-CARLETON R.M.

ON

Contaminant UN No 1:

Ref No: 25861 Discharger Report:

Site No: Material Group:
Incident Dt: 9/25/1989 Health/Env Conseq:

Year: Client Type:
Incident Cause: UNDERGROUND TANK LEAK Sector Type:

Incident Event:Agency Involved:Contaminant Code:Nearest Watercourse:Contaminant Name:Site Address:Contaminant Limit 1:Site District Office:Contam Limit Freq 1:Site Postal Code:Contaminant UN No 1:Site Region:

Environment Impact: Site Municipality: 20000

Nature of Impact:
Receiving Medium:
Receiving Env:
MOE Response:

Site Lot:
Site Conc:
Northing:
MOE Response:

Easting:

MOE Response:Easting:MCCRDt MOE Arvl on Scn:Site Geo Ref Accu:

MOE Reported Dt: 9/28/1989 Site Map Datum:
Dt Document Closed: SAC Action Class:
Incident Reason: UNKNOWN Source Type:
Site Name:

Site County/District: Site Geo Ref Meth:

Incident Summary: TOP OIL RESOURCES- 7000 LTR DIESEL FUEL LEAK FROMUNDERGROUND TANK

Contaminant Qty:

PUC

TERRY FOX DR PAD TRANSFORMER BY NEWBRIDGE COMM. LTD. KANATA CITY ON

SPL

Database:

Order No: 21062300392

Site:

Ref No: 4874 Discharger Report:

Site No:Material Group:Incident Dt:6/7/1988Health/Env Conseq:

Year: Client Type: Incident Cause: COOLING SYSTEM LEAK Sector Type:

Incident Cause: Cooling State Health Sector Type: Incident Event: Agency Involved: Contaminant Code: Nearest Watercourse: Contaminant Name: Site Address:

Contaminant Name: Site Address:
Contaminant Limit 1: Site District Office:
Contam Limit Freq 1: Site Postal Code:
Contaminant UN No 1: Site Region:

Environment Impact: Site Municipality: 20103
Nature of Impact: Site Lot:

Receiving Medium:LANDSite Conc:Receiving Env:Northing:MOE Response:Easting:

Dt MOE Arvl on Scn:Site Geo Ref Accu:MOE Reported Dt:6/7/1988Site Map Datum:Dt Document Closed:SAC Action Class:

Incident Reason: FIRE/EXPLOSION Source Type:

Site Name: Site County/District:

Contaminant Qty:

Site Geo Ref Meth:
Incident Summary: KANATA HYDRO - 150 L MINERAL OIL (NO PCBS) TO GROUND.

Site:

lot 31 ON

Database:

WWIS

Well ID: 1534734 Data Entry Status:

Construction Date: Data Src: 1

Primary Water Use: Not Used Date Received: 6/10/2004
Sec. Water Use: Selected Flag: True

Sec. Water Use: Selected Flag: True
Final Well Status: Not A Well Abandonment Rec:

Water Type: Contractor: 6907

Casing Material:Form Version:2Audit No:265833Owner:

Tag: Street Name: Construction Method: County:

 Construction Method:
 County:
 OTTAWA

 Elevation (m):
 Municipality:
 OTTAWA CITY

 Elevation Reliability:
 Site Info:

Depth to Bedrock: Lot: 031

Well Depth: Concession:
Overburden/Bedrock: Concession Name:
Pump Rate: Easting NAD83:
Static Water Level: Northing NAD83:

Flowing (Y/N): Zone:

Flow Rate: UTM Reliability: Clear/Cloudy:

Bore Hole Information

Bore Hole ID: 11097509 Elevation: DP2BR: Elevro:

Spatial Status: Zone: 18

Code OB: 0 East83:
Code OB Desc: Overburden North83:
Open Hole: Org CS:

Cluster Kind: UTMRC: 9

Date Completed:31-May-2004 00:00:00UTMRC Desc:unknown UTMRemarks:Location Method:na

Order No: 21062300392

Elevrc Desc:

Location Source Date: Improvement Location Source:

Improvement Location Source: Improvement Location Method: Source Revision Comment:

Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID: 932942463

Layer:

Color:

General Color:

Mat1: 24

Most Common Material: PREV. DRILLED

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

Formation Top Depth: 0.0 Formation End Depth: 40.0 Formation End Depth UOM: ft

Method of Construction & Well

Use

Method Construction ID: 961534734

Method Construction Code:

Method Construction: Other Method

Other Method Construction:

Pipe Information

Pipe ID: 11101224

Casing No:

Comment: Alt Name:

Results of Well Yield Testing

Pump Test ID: 991534734

Pump Set At: Static Level: 8.0

Final Level After Pumping:

Recommended Pump Depth:

Pumping Rate:

Flowing Rate:

Recommended Pump Rate: Levels UOM:

Levels UOM: ft Rate UOM: GPM

Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN:

Flowing: No

Site:

lot 31 ON

Database:

WWIS

Order No: 21062300392

Well ID: 1528149 Data Entry Status:

Construction Date: Data Src:

Primary Water Use: Not Used Date Received: 8/30/1994

Sec. Water Use: Selected Flag: True

Final Well Status: Observation Wells Abandonment Rec:

Water Type: Contractor: 6844
Casing Material: Form Version: 1

 Audit No:
 149112
 Owner:

 Tag:
 Street Name:

 Construction Method:
 County:
 OTTAWA

 Elevation (m):
 Municipality:
 OTTAWA CITY

Elevation Reliability: Depth to Bedrock:

Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Flowing (Y/N): Flow Rate: Clear/Cloudy:

Site Info:

031 Lot:

Concession: Concession Name: Easting NAD83: Northing NAD83:

Zone:

UTM Reliability:

Bore Hole Information

Bore Hole ID: 10049688

DP2BR: Spatial Status:

Code OB:

Unknown type above a bedrock layer Code OB Desc:

Open Hole: Cluster Kind:

Date Completed: 27-Jul-1994 00:00:00

Remarks: Elevrc Desc:

Location Source Date:

Improvement Location Source: Improvement Location Method: Source Revision Comment:

Supplier Comment:

Overburden and Bedrock

Materials Interval

931068737 Formation ID:

Layer: Color: 8 General Color: **BLACK** Mat1: 00

Most Common Material: **UNKNOWN TYPE**

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

0.0 Formation Top Depth: Formation End Depth: 2.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 931068739

Layer: 3 Color:

BROWN General Color: Mat1: 05 Most Common Material: CLAY Mat2: 11 Mat2 Desc: **GRAVEL**

Mat3:

Mat3 Desc:

2.0 Formation Top Depth: 3.0 Formation End Depth: Formation End Depth UOM:

Overburden and Bedrock

Materials Interval

Formation ID: 931068740 Elevation:

Elevrc:

Zone: 18

East83: North83: Org CS:

> UTMRC: 9

UTMRC Desc: unknown UTM

Location Method: na **Layer:** 4 **Color:** 6

General Color: BROWN **Mat1:** 08

Most Common Material: FINE SAND

Mat2: 11 Mat2 Desc: GRAVEL

Mat3: Mat3 Desc:

Formation Top Depth: 3.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 931068738

 Layer:
 2

 Color:
 2

 General Color:
 GREY

 Mat1:
 21

 Most Common Material:
 GRANITE

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

Formation Top Depth: 2.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

 Formation ID:
 931068741

 Layer:
 5

 Color:
 2

 General Color:
 GREY

 Mat1:
 05

 Most Common Material:
 CLAY

 Mat2:
 74

Mat2 Desc: LAYERED

Mat3:

Mat3 Desc:

Formation Top Depth: 4.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment

Sealing Record

Plug ID: 933113003

 Layer:
 1

 Plug From:
 3

 Plug To:
 7

 Plug Depth UOM:
 ft

Annular Space/Abandonment

Sealing Record

Plug ID: 933113005

 Layer:
 3

 Plug From:
 9

 Plug To:
 20

 Plug Depth UOM:
 ft

Annular Space/Abandonment

Sealing Record

933113004 Plug ID:

2 7 Layer: Plug From: Plug To: 9 Plug Depth UOM: ft

Method of Construction & Well

<u>Use</u>

Method Construction ID: 961528149 **Method Construction Code:** Method Construction: **Boring**

Other Method Construction:

Pipe Information

Pipe ID: 10598258

Casing No:

Comment: Alt Name:

Construction Record - Casing

Casing ID: 930086839

Layer: Material:

PLASTIC Open Hole or Material: Depth From:

Depth To: 20 Casing Diameter: 2 Casing Diameter UOM: inch Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933326495

Layer: 010 Slot: Screen Top Depth: 10 20 Screen End Depth:

Screen Material:

Screen Depth UOM: ft Screen Diameter UOM: inch Screen Diameter: 2

Site: Database: 4129 CALBRENT lot 31 ON

Order No: 21062300392

Well ID: 1536505 Data Entry Status:

Construction Date:

Data Src: Primary Water Use: Domestic Date Received: 8/1/2006 Sec. Water Use: Selected Flag: True Final Well Status: Water Supply Abandonment Rec: Contractor: 4006

Water Type:

Casing Material: Form Version: 3

Audit No: Z22643 Owner:

4129 CALBRENT Tag: A022383 Street Name: **Construction Method:** County: **OTTAWA** Elevation (m): Municipality: 15000

Elevation Reliability: Site Info: PL;AN #4M-1127 Depth to Bedrock: Lot: 031

Well Depth: Concession: Overburden/Bedrock: Concession Name: Pump Rate: Easting NAD83:

Static Water Level: Flowing (Y/N): Flow Rate: Clear/Cloudy: Northing NAD83: Zone:

UTM Reliability:

Bore Hole Information

 Bore Hole ID:
 11550571

 DP2BR:
 12.00

Spatial Status:

Code OB:

Code OB Desc: Bedrock
Open Hole:

Cluster Kind:

Date Completed: 22-Dec-2004 00:00:00

Remarks: Elevrc Desc:

Location Source Date:

Improvement Location Source: Improvement Location Method: Source Revision Comment:

Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID: 933063112

Layer: 1
Color: 6
General Color: BB

 General Color:
 BROWN

 Mat1:
 28

 Most Common Material:
 SAND

 Mat2:
 12

 Mat2 Desc:
 STONES

Mat3: Mat3 Desc:

Formation Top Depth: 0.0 Formation End Depth: 12.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID: 933063114

 Layer:
 3

 Color:
 2

 General Color:
 GREY

 Mat1:
 15

Most Common Material: LIMESTONE

Mat2: Mat2 Desc: Mat3: Mat3 Desc:

Formation Top Depth: 18.0 Formation End Depth: 120.0 Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

 Formation ID:
 933063113

 Layer:
 2

 Color:
 2

 General Color:
 GREY

 Mat1:
 15

Most Common Material: LIMESTONE

Elevation: Elevrc: Zone: East83:

North83:

UTMRC: 9

UTMRC Desc: unknown UTM

Order No: 21062300392

Location Method: na

Mat2: 7

Mat2 Desc: FRACTURED

Mat3: Mat3 Desc:

Formation Top Depth: 12.0 Formation End Depth: 18.0 Formation End Depth UOM: ft

Annular Space/Abandonment

Sealing Record

Plug ID: 933298383

 Layer:
 1

 Plug From:
 40

 Plug To:
 0

 Plug Depth UOM:
 ft

Method of Construction & Well

<u>Use</u>

Method Construction ID: 961536505

Method Construction Code: 4

Method Construction: Rotary (Air)

Other Method Construction:

Pipe Information

Pipe ID: 11560178

Casing No:

Comment: Alt Name:

Construction Record - Casing

Casing ID: 930883490

Layer: 1
Material: 1

Open Hole or Material:STEELDepth From:-2Depth To:40Casing Diameter:6Casing Diameter UOM:inchCasing Depth UOM:ft

Construction Record - Casing

Casing ID: 930883491

Layer: 2

Material:

Open Hole or Material:

Depth From: Depth To:

Casing Diameter:6Casing Diameter UOM:inchCasing Depth UOM:ft

Construction Record - Casing

Casing ID: 930883492

Layer: 3 Material: 4

Open Hole or Material: OPEN HOLE

Depth From: 40 **Depth To:** 120

Casing Diameter:

Casing Diameter UOM: inch Casing Depth UOM: ft

Results of Well Yield Testing

 Pump Test ID:
 11569550

 Pump Set At:
 20.0

Static Level: 6.800000190734863

Final Level After Pumping: 11.0
Recommended Pump Depth: 20.0
Pumping Rate: 30.0
Flowing Rate:

Recommended Pump Rate: 30.0 Levels UOM: ft Rate UOM: GPM

Water State After Test Code: Water State After Test: Pumping Test Method:

Pumping Duration HR: 2 **Pumping Duration MIN:** 0

Flowing:

Draw Down & Recovery

Pump Test Detail ID:11645999Test Type:Draw Down

Test Duration: 20

Test Level: 9.300000190734863

Test Level UOM:

Draw Down & Recovery

Pump Test Detail ID:11645993Test Type:Draw Down

Test Duration:

Test Level: 7.300000190734863

2

Test Level UOM:

Draw Down & Recovery

Pump Test Detail ID:11645992Test Type:Draw Down

Test Duration:

Test Level: 6.900000095367432

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:11646000Test Type:Draw Down

Test Duration: 25

Test Level: 9.699999809265137

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:11646001Test Type:Draw Down

Test Duration: 30

Test Level: 10.300000190734863

Test Level UOM:

Draw Down & Recovery

Pump Test Detail ID:11645995Test Type:Draw Down

Test Duration: 4

Test Level: 8.199999809265137

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 11646004
Test Type: Draw Down

Test Duration: 60
Test Level: 11.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:11645998Test Type:Draw Down

Test Duration: 15

Test Level: 8.899999618530273

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:11645994Test Type:Draw Down

Test Duration: 3

Test Level: 7.800000190734863

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:11645996Test Type:Draw Down

Test Duration: 5

Test Level: 8.399999618530273

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:11645997Test Type:Draw Down

Test Duration: 10

Test Level: 8.699999809265137

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:11646002Test Type:Draw Down

Test Duration: 40

Test Level: 10.600000381469727

Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:11646003Test Type:Draw Down

Test Duration: 50

Test Level: 10.899999618530273

Test Level UOM: ft

Water Details

Order No: 21062300392

Water ID: 934078357

Layer: 1 Kind Code: 1

Kind: FRESH
Water Found Depth: 32.0
Water Found Depth UOM: ft

Hole Diameter

 Hole ID:
 11681301

 Diameter:
 150.0

 Depth From:
 120.0

 Depth To:
 0.0

 Hole Depth UOM:
 ft

 Hole Diameter UOM:
 cm

Order No: 21062300392

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. **Note:** Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.

Abandoned Aggregate Inventory:

Provincial

AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory:

Provincial AGR

The Ontario Ministry of Natural Resources maintains a database of all active pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Sep 2020

Abandoned Mine Information System:

Provincial

AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Oct 2018

Anderson's Waste Disposal Sites:

Private

ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks:

Provincial

AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies:

Private

AUWR

Order No: 21062300392

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Dec 31, 2020

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval:

Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2018

Commercial Fuel Oil Tanks:

Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.

Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Jul 31, 2020

Chemical Manufacturers and Distributors:

Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

<u>Chemical Register:</u> Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Dec 31, 2020

Compressed Natural Gas Stations:

Private

CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Apr 2021

Inventory of Coal Gasification Plants and Coal Tar Sites:

Provincial

COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions:

Provincial

CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Nov 2020

Certificates of Property Use:

Provincial

CPU

Order No: 21062300392

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994-Apr 30, 2021

Drill Hole Database:

Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Sep 2020

Delisted Fuel Tanks:

Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Jul 31, 2020

Environmental Activity and Sector Registry:

Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-May 31, 2021

Environmental Registry:

Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994-Apr 30, 2021

Environmental Compliance Approval:

Provincial

FCA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011- May 31, 2021

Environmental Effects Monitoring:

Federal

EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches:

Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Jan 31, 2021

Environmental Issues Inventory System:

Federal

EIIS

Order No: 21062300392

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event:

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Dec 31, 2016

Environmental Penalty Annual Report:

Provincial

Provincial

EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2020

List of Expired Fuels Safety Facilities:

Provincial

EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.

Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Jul 31, 2020

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land:

Federal

ECS.

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Apr 2021

Fisheries & Oceans Fuel Tanks:

Federal

FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS):

Federal

FRST

Order No: 21062300392

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: May 31, 2018

For Formical FST Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.

Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are

not verified for accuracy or completeness. Government Publication Date: Jul 31, 2020

Fuel Storage Tank - Historic:

Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary:

Provincial

GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Apr 30, 2021

Greenhouse Gas Emissions from Large Facilities:

Federal

GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2019

TSSA Historic Incidents:

Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks:

Federal

IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks:

Provincial

NC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Jul 31, 2020

Landfill Inventory Management Ontario:

Provincial

LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Feb 28, 2019

Canadian Mine Locations:

Private

MINE

Order No: 21062300392

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences:

Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Dec 2020

National Analysis of Trends in Emergencies System (NATES):

Federal

NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports:

Provincial

NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2019

National Defense & Canadian Forces Fuel Tanks:

Federal

NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills:

Federal

NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites:

Federal

NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents:

Federal

NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Mar 31, 2021

National Energy Board Wells:

Federal

NEBP

Order No: 21062300392

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES):

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory:

Federal NPRI

Federal

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Feb 28, 2021

Ontario Oil and Gas Wells:

Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Jun 2020

Inventory of PCB Storage Sites:

Provincial

OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994-Apr 30, 2021

<u>Canadian Pulp and Paper:</u> Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks:

Federal

PCFT

Order No: 21062300392

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005

Pesticide Register:

Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011-May 31, 2021

Provincial PINC Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 31, 2020

Private and Retail Fuel Storage Tanks:

Provincial

PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water:

Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994-Apr 30, 2021

Ontario Regulation 347 Waste Receivers Summary:

Provincial

REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2018

Record of Site Condition:

Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.

RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-May 2021

Retail Fuel Storage Tanks:

Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Dec 31, 2020

Scott's Manufacturing Directory:

Private

SCT

Order No: 21062300392

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills:

Provincial SPL

List of spills and incidents made available the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Aug 2020

Wastewater Discharger Registration Database:

Information under this heading is combination of the following 2 programs. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment maintained a database of all direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation; Mining; Petroleum Refining; Organic Chemicals; Inorganic Chemicals; Pulp & Paper; Metal Casting; Iron & Steel; and Quarries. All sampling information is now collected and stored within the Sample Result Data Store (SRDS).

Government Publication Date: 1990-Dec 31, 2018

Anderson's Storage Tanks:

Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks:

Federal TCFT

Provincial

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Dec 2020

Variances for Abandonment of Underground Storage Tanks:

Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.

Records are not verified for accuracy or completeness.

Government Publication Date: Jul 31, 2020

Waste Disposal Sites - MOE CA Inventory:

Provincial v

WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-May 31, 2021

Waste Disposal Sites - MOE 1991 Historical Approval Inventory:

Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System:

Provincial

WWIS

Order No: 21062300392

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Apr 30, 2021

Definitions

<u>Database Descriptions:</u> This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

<u>Detail Report</u>: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

<u>Distance:</u> The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

<u>Direction</u>: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

<u>Elevation:</u> The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

<u>Map Key:</u> The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

<u>Unplottables:</u> These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

Order No: 21062300392

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



APPENDIX D CORRESPONDENCE

McINTOSH PERRY

September 21, 2021 Ministry of the Environment, Conservation and Parks Freedom of Information Office 40 St. Clair Avenue West, 12th Floor Toronto, ON M4V 1M2

Re: Freedom of Information Request (FOI)

Civic Address: 6 Edgewater Street, Kanata, Ontario

Legal Description:

Parts Concession 12, Part of Lot 30, RP5R-2711; Part 1 Less RP4R-13349 Part; 1 Save & Except RP5R-6120

Part 3

Dear Sir/Madam,

Please find enclosed a freedom of information request pertaining to the above-noted site. A credit card payment form for the Freedom of Information Request fee is enclosed. The property is identified by the municipal address above. Please mail or fax our office any information regarding this site.

If you have any further questions, please do not hesitate to contact the undersigned.

Yours Truly,

Dan Arnott, P.Eng. (613) 714-4589

d.arnott@mcintoshperry.com

CP-17-0635 - MECP Freedom of Information Request .docx

Ministry of the Environment Freedom of Information and Protection of Privacy Office 40 St. Clair Avenue West, 12th Floor Toronto, ON M4V 1M2 Tel: 416-314-4075



Tel: 416-314-4075 Fax: 416-314-4285

Use this form to request records that are in the Ministry's files on environmental concerns related to properties. Please refer to the guide on the completion and use of this form. Our fax no. is 416- 314-4285.

Requester Data		For Mini	stry l	Jse Only	
Name, Title, Company Name and Mailing Address of Requester		FOI Request No.		Date Request Received	
			Fee Paid		
			☐ CHQ ☐ VISA/N	1C/AN1	EX CASH/MONEY
Email Address:			ORDER	IC/AIVII	EX CASI //VIONET
- -	Varia Drain et/	Circulations of Dominator		- NG	D = 0WD = W0D
Tel:	Your Project/ Reference No.	Signature of Requester	□ CNR □ ER	□ NC	DR □ SWR □ WCR
Fax:	1.0.0.0.00		□ IEB □ EAA	□ EM	IR □ SCB □ SDW
Request Para	meters				
•		wnship (Municipal address mand	datory for cities, towns o	r regior	ns)
·					•
Present Property Own	ner(s) and Date(s) of Ownershi	p			
Previous Property Ow	vner(s) and Date(s) of Ownersh	nip			
Present/Previous Ter	nant(s) (if annlicable)				
T TOOCHUT TOVIOUS TO	ant(o) (ii applicable)				
Search Paran	neters				Specify Year(s)
		00 retrieval cost. There is	no quarantee that re	ecords	Requested
	request will be located.				Nequesteu
Environmental	concerns (General co	rrespondence, occurrence	reports, abatement)		
Orders					
Spills					
Investigations/prosecutions > Owner and tenant information must be provided					
	itor number/classes		•		
Certificates of Approval ▶ Proponent information must be provided and Certificates of Approval number(s) (if					nnroval number(s) (if
		d manually. Search fees in ex			
		supporting documents are a			ou, doponum.g on the
				SD	Specify Year(s) Requested
Air - emissions					
Renewable Er	nerav				
Water - mains, treatment, ground level, standpipes & elevated storage,					
pumping stations (local & booster)					
Sewage - sanitary, storm, treatment, stormwater, leachate & leachate					
treatment & sewage pump stations					
Waste water - industrial discharge					
,					
Waste sites - disposal, landfill sites, transfer stations, processing sites, incinerator sites					
Waste		on-hazardous & hazardo	us wasta mohilo	1	
	9 ,		นง พลงเษ, ทาบมทิษ		
systems waste processing units, PCB destruction					

MCINTOSH PERRY

September 21, 2021

Historic Land Use Inventory (HLUI) Office City of Ottawa 110 Laurier Avenue West Ottawa, Ontario K1P 1J1

Re: Authorization Letter, Historic Land Use Inventory (HLUI Search), 16 Edgewater Street, Ottawa, ON

McIntosh Perry has been retained by 11143921 Canada Inc. to complete a Phase One Environmental Site Assessment at the property addressed as 16 Edgewater Street, Ottawa, Ontario.

With this letter, the property owners authorize the City of Ottawa and other regulatory bodies to release, to McIntosh Perry Consulting Engineers Ltd., information requested for the purpose of completing a Phase One Environmental Site Assessment at the above-noted property.

Name of Property Owners: <u>11143921 Ontario Inc</u>

Property Owners Representatives: Chris Mccluskey, President

Signature of Property Owner or Representative:

Date: September 21, 2021

Chris M'Clurky

	Office Use Only	
Application Number:	Ward Number:	Application Received: (dd/mm/yyyy):
Client Service Centre Staff:		Fee Received: \$



Historic Land Use Inventory

Application Form

Notice of Public Record

All information and materials required in support of your application shall be made available to the public, as indicated by Section 1.0.1 of *The Planning Act*, R.S.O. 1990, C.P.13.

Municipal Freedom of Information and Protection Act

Personal information on this form is collected under the authority the *Planning Act*, RSO 1990, c. P. 13 and will be used to process this application. Questions about this collection may be directed by mail to Manager, Business Support Services, Planning Infrastructure and Economic Development Department, 110 Laurier Avenue West, Ottawa, K1P 1J1, or by phone at (613) 580-2424, ext. 24075

Background Information			
*Site Address or Location:	16 Edgewater Street		
	* Mandatory Field		
Applicant/Agent I	nformation:		
Name:	Dan Arnott, McIntosh Perry		
Mailing Address:	115 Walgreen Road, Carp, ON K0A	1L0	
Telephone:	(613) 714-4589	Email Address:	d.arnott@mcintoshperry.com
Registered Proper	rty Owner Information:	Same as abo	ve
Name:	Chris McCluskey		
Mailing Address:	6 Edgewater Street, Ottawa, ON K2	PL 1V8	
Telephone:	613.627.0611 ext. 702	Email Address:	chris@mccluskeygroup.ca

Page 1 of 3 January 1, 2021

	Site Details	
and PIN:	ort Lot 30 Concession 12 Part 1 4R31503 City of Ottawa; (PIN 044980170)	
	m Lot depth: m Lot area: m² ea: (irregular lot) m² eave Full Municipal Services: • Yes No	
	Required Fees	
	o visit the Historic Land Use Inventory website s must be paid in full at the time of application submission.	
Planning Fee	\$128.0	0

Submittal Requirements

The following are required to be submitted with this application:

- 1. Consent to Disclose Information: Consultants and other third parties may make requests for information on behalf of an individual or corporation. However, if the requester is not the owner of the property, the requester must provide the City of Ottawa with a 'consent to disclose information' letter, signed by the property owner. This will authorize the City of Ottawa to release any relevant information about the property or its owner(s) to the requester. Consent for disclosure is required in the event that personal information or proprietary company information is found concerning the property and its owner. All consents must clearly indicate the name of the property owner as well as the name of the requester, and must be signed and dated.
- 2. Disclaimer: Requesters must read and understand the conditions included in the attached disclaimer and submit a signed disclaimer to the City of Ottawa's Planning, Infrastructure and Economic Development Department. This disclaimer is related to the Historic Land Use Inventory and must be received by the City of Ottawa, signed and dated by the requestor, before the process can begin.
- 3. A site plan or key plan of the property, its location and particular features.
- 4. Any significant dates or time frames that you would like researched.

Page 2 of 3 January 1, 2021

Disclaimer For use with HLUI Database

CITY OF OTTAWA ("the City") is the owner of the Historical Land Use Inventory ("HLUI"), a database of information on the type and location of land uses within the geographic area of Ottawa, which had or have the potential to cause contamination in soil, groundwater or surface water.

The City, in providing information from the HLUI, to McIntosh Perry,	("the Requester") does so only under the following	
conditions and understanding:		

- The HLUI may contain erroneous information given that such records and sources of information may be flawed. Changes in
 municipal addresses over time may have introduced error in such records and sources of information. The City is not responsible
 for any errors or omissions in the HLUI and reserves the right to change and update the HLUI without further notice. The City
 does not, however, make any commitment to update the HLUI. Accordingly, all information from the HLUI is provided on an "as
 is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in
 responding to the request.
- 2. City staff will perform a search of the HLUI based on the information given by the Requester. City staff will make every effort to be accurate, however, the City does not provide an assurance, guarantee, warranty, representation (express or implied), as to the availability, accuracy, completeness or currency of information which will be provided to the Requester. The HLUI in no way confirms the presence or absence of contamination or pollution of any kind. The information provided by the City to the Requester is provided on the assumption that it will not be relied upon by any person whatsoever. The City denies all liability to any such persons attempting to rely on any information provided from the HLUI database.
- 3. The City, its employees, servants, agents, boards, officials or contractors take no responsibility for any actions, claims, losses, liability, judgments, demands, expenses, costs, damages or harm suffered by any person whatsoever including negligence in compiling or disseminating information in the HLUI.
- 4. Copyright is reserved to the City.
- 5. Any use of the information provided from the HLUI which a third party makes, or any reliance on or decisions to be based on it, are the responsibilities of such third parties. The City, its employees, servants, agents, boards, officials or contractors accept no responsibility for any damages, if any, suffered by a third party as a result of decisions made as a result of an information search of the HLUI.
- 6. Any use of this service by the Requestor indicates an acknowledgement, acceptance and limits of this disclaimer.
- 7. All information collected under this request and all records provided in response to this request are subject to the provisions of the Municipal Freedom of Information and Protection of Privacy Act, R.S.O. 1990, c. M.56, as amended.

Signed: 16-Mar-21	
Dated (dd/mm/yyyy): 16/03/2021	
Per: Dan Arnott	
(Please print name)	
Title: Manager, Geo-Env.	
Company: McIntosh Perry	

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



APPENDIX E AERIAL PHOTOGRAPHS











AIR PHOTO DIVISION - ENERGY, MINES & RESOURCES - CANADIAN GOVT. COPYRI



Year: 1976

Source: City of Ottawa Map Scale: 1: 10000

Comments:














PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



APPENDIX F
INTERVIEW RECORDS

Phase I ESA Interviews

Interviewer (MPCE) Bradley	Sutherland MPCE Project No. CP-17-0635
Interviewee Chris	McCluskey
Relationship to Subject Prope	rty Tenant Time Associated with Property: 2913 - Present Date Property was developed:
Potential Item of Concern	Interview Comments
Accidents/Spills	Not that I am ance
Previous Use of Site	Vacant land from at Wast 1998
Adjacent Properties	Nim Gorbons, Residential,
Fuel Handling/Storage	Prin Gorbons, Residential, Boone Plumbing Wet that I am aware
Maintenance/ Operational Areas	
Hazardous Materials Storage	
Salt Storage	To the second se

Potential Item of Concern	Interview Comments
Fuel Storage Tanks	Not that I am awar
Odours	
Potable Water	
Septic and Wastewater	
Discharges	
Pesticides	
Mould .	
Heating and Cooling Systems	
Major Mechanical Equipment	
Waste Oils, Solvents,	
Batteries	
PCBs	
Asbestos	
Lead Paint	
	V



Potential Item of Concern	Interview Comments
ODS	Not Mut I am away
Electromagnetic Radiation	
UFFI .	
Mercury	
Radon Gas	
Soil and Groundwater Conditions	
Wells	
Waste Disposal and Recycling	
Fill Material	
cloor Drains/OWS (discharge ocations)	
Other	
ا و	

Future use of property:

Indishial Showroom / Office

McIntosh Perry Consulting Engineers Ltd.

Page <u>3</u> of 3

Page <u>1</u> of 3

Phase I ESA Interviews

Interviewer (MPCE) Bradley	Sutherland MPCE Project No. CP-17-0635
Interviewee Don	bolbold
Relationship to Subject Proper	
Date Nov 23, 2018	Date Property was developed:
Potential Item of Concern	Interview Comments
Accidents/Spills	Not that I am aware
Previous Use of Site	Cashway Lumber yord
Adjacent Properties	Tim Horkons / Pesidential/ Industrial use-Plumbing show room
Fuel Handling/Storage	20(Marian ask 1/00/2/20)
Maintenance/ Operational Areas	
Hazardous Materials Storage	
Salt Storage	

McIntosh Perry Consulting Engineers Ltd.

Potential	Interview Comments
Item of Concern	
Fuel Storage Tanks	Not Mut I am and
Odours	
Potable Water	
Septic and Wastewater	
Discharges	
Pesticides	
Mould	
Heating and Cooling Systems	
Major Mechanical Equipment	
54 20	
Waste Oils, Solvents, Batteries	
PCBs	
Asbestos	
Lead Paint	
	V



DDS Moth that I am aware Electromagnetic Radiation UFFI Mercury Radon Gas Soil and Groundwater Conditions Wells Waste Disposal and Recycling Fill Material Floor Drains/OWS (discharge locations)	Potential Item of Concern	Interview Comments
Electromagnetic Radiation UFFI Mercury Radon Gas Soil and Groundwater Conditions Wells Waste Disposal and Recycling Fill Material Floor Drains/OWS (discharge pocations)	ODS	Not that I am aware
Mercury Radon Gas Soil and Groundwater Conditions Wells Waste Disposal and Recycling Fill Material Floor Drains/OWS (discharge pocations)	Electromagnetic Radiation	
Radon Gas Soil and Groundwater Conditions Wells Waste Disposal and Recycling Fill Material Floor Drains/OWS (discharge occations)	UFFI	
Soil and Groundwater Conditions Wells Waste Disposal and Recycling Fill Material Floor Drains/OWS (discharge ocations)	Mercury	
Wells Waste Disposal and Recycling Fill Material Floor Drains/OWS (discharge pocations)	Radon Gas	
Waste Disposal and Recycling Fill Material Floor Drains/OWS (discharge pocations)		
Waste Disposal and Recycling Fill Material Floor Drains/OWS (discharge ocations)	Wells	
Floor Drains/OWS (discharge occations)	Waste Disposal and Recycling	
ocations)	Fill Material	
Other		
	Other	

McIntosh Perry Consulting Engineers Ltd.

Page <u>3</u> of 3

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 16 EDGEWATER STREET, KANATA, ON



APPENDIX G SITE PHOTOGRAPHS



Photo 1: Exterior of Site, facing northwest from Tim Hortons parking lot.



Photo 2: Exterior of Site, facing southeast from northwest property boundary.



Photo 3: Waste disposal area for Tim Hortons, at southeast corner of the Site



Photo 4: Heavy equipment garage and storage yard, facing southwest from southwest property boundary



Photo 5: Heavy equipment garage and storage yard, facing southwest from Edgewater Street



Photo 6: Tim Horton's restaurant and parking lot, facing southeast from site.